
IP-87 Error code 93 (pg 1 of 2)

EC-93: Carousel Lock Arm not locked






2 Troubleshooting IP-87: Error code 93 2 - 229 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Contents Manual Contents CD Main Screen

Index

IP-87 (pg 2 of 2)



2 Troubleshooting IP-87: Error code 93 2 - 230 LCx® Analyzer Service Manual (Text P/N 47278-102)