PL-4: OPTICS (pg 1 of 3)

Item	RR	Part No.	Description
1	4.1	3-47228-01	Optics Assy
2		3-04820-01	Ribbon Cable #4,
			MEIA Optics to
			Analog Bd
3		3-04551-01	HV Connector Cable
			Assy
4	4.4	3-04708-01	Lamp Power Supply,
			Feedback Control
5	4.5	3-31009-01	PMT HV Power
			Supply
6	4.6	3-47071-01	Carousel Lock
			Sensor Cable
			(Cuvette Sensor)

Item	RR	Part No.	Description	
11	4.11	LN 9A42-41	Lamp, MEIA	
			Mercury Low	
			Pressure	
12		3-31915-01	Bearing Center Pin	
13		47047-102	Sensor Bracket	
			Assy	
			(Bracket, #6, #14)	
14	4.14	3-04572-01	Remote Air	
			Thermistor Assy	
15		3-79229-01	Cable Analog Bd	
			to MEIA Lamp	
			Supply	

PL-4 screws/washers table on next page.

3 Parts Lists PL-4: Optics 3 - 14 LCx® Analyzer Service Manual (Text P/N 47278-102)

Block/board	PL-4
diagrams	illustration

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

PL-4: Optics (pg 2 of 3)


Item	Part No.	Description
S1	31158-102	Screw, PHP 6-32 x .375
S2	14494-110	Screw, PHP 6-32 x .625
S3	14494-105	Screw, PHP 6-32 x .312
S4	14494-208	Screw, PHP 8-32 x .500

3	Parts Lists	PL-4: Optics	3 - 15
	LCx® Analyzer Service Manual (Text P/N 47278-102)	-	

Block/board	PL-4
diagrams	illustration

Chapter Contents	Manual Contents	CD Main Screen	Index
Contents	Contents	Ocicen	

PL-4: Optics (pg 3 of 3)



3 Parts Lists PL-4: Optics 3 - 16 LCx® Analyzer Service Manual (Text P/N 47278-102)

PL-4 parts list	d
--------------------	---