
IP-3 Analyzer operates too slowly (pg 1 of 2)






IP3-1.vsd

2 Troubleshooting IP-3: Analyzer operates too slowly 2 - 38 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Contents	Manual Contents	CD Main Screen	Index
Contents	Contents	Scieen	

IP-3 (pg 2 of 2)



IP3-2.vsd

2 - 39

Troubleshooting LCx[®] Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-3: Analyzer operates too slowly