	- IAM	E: T.VAGHDEVI PRAVEEN WARRY WOOMPHV COMOR
	1 000	. (13) . (170) [170]
	SIGN	VATURE: Playlidevic: LAB-2 EDGJ
	a.	Derive a Stepper Motor interface to 910 tate the motori
_		in Clockwise by N steps. Introduce suitable delay
در		between successive steps.
		# include < Stdio.h>
		#include < Aleg51.h>
		charxdata port at 0xe803;
1		charxdata porta at oxe 800; charidata acc at ox30;
-		delay C) // DELAY BETWEEN THE ROTATION OF THE STEPPER
ER		MOTOR
\dashv		int i;
+		for (j=0; j < 800; j++)
		\{\frac{2}{2}\tag{7}
		2-3
		void main ()
	ASIA	\{\begin{align*} \text{\left} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
		POYE = 0x80; //CONFIGURE ALL THE PORT OF 8255' AS
3		DUTPUT PORT
		While (1)
		c .
		acc = 0x88;
		porta: acc;
1		delay (); acc= Ox44;
+		porta= acc;
+		delay ();
+		acc = 0 × 22;
1		porta = acc;
1		
1		acc = DXII;
1		porta = acc; delay co;
		32