

Property Risk Engineering Report

Survey date 2024-03-15 · Elena Brooks, CSP

Insured:	ABC Manufacturing	Survey date:	2024-03-15
Engineer:	Elena Brooks, CSP	Scope:	COPE, fire protection, natural hazard, re

LOCATION 1 — DAYTON PLANT

Address:	4410 Foundry St, Dayton, OH		
Construction:	Masonry non-combustible (ISO 4)		1998
Stories:	1	Floor area (sq ft):	186,000
Roof covering:	TPO membrane	Roof year (verified):	2014
Occupancy observed:	Light manufacturing	Sprinkler protection:	100% of area
Fire alarm:	Central station	Public protection class:	3

The Dayton Plant facility is a 1-story masonry non-combustible building of approximately 186,000 sq ft built in 1998. Housekeeping was observed to be generally good. The building is fully protected by automatic sprinklers supplied from the municipal main; the system was last tested within 12 months.

LOCATION 2 — TAMPA ASSEMBLY & DC

Address:	1880 Harbor Point Dr, Tampa, FL		
Construction:	Masonry non-combustible (ISO 4)		2006
Stories:	1	Floor area (sq ft):	142,000
Roof covering:	TPO membrane	Roof year (verified):	2019
Occupancy observed:	Light manufacturing	Sprinkler protection:	100% of area
Fire alarm:	Central station	Public protection class:	2

The Tampa Assembly & DC facility is a 1-story masonry non-combustible building of approximately 142,000 sq ft built in 2006. Housekeeping was observed to be generally good. The building is fully protected by automatic sprinklers supplied from the municipal main; the system was last tested within 12 months.

RECOMMENDATIONS

Rec #	Loc	Category	Recommendation	Priority	Target date
R-121	2	Wind mitigation	Upgrade roof-to-wall anchorage on east elevation; secure rooftop HVAC...	Medium	2026-03-31
R-098	1	Housekeeping	Remove combustible pallet storage from within 10 ft of building	Low	2024-09-30

Elena Brooks, CSP · Northgate Risk Engineering · 2024-03-15