

Notice of Fire Protection System Impairment

Issued 2026-08-06

Premises:	Pinecrest Plaza, 1043 Beacon Hill Rd, Charlotte, NC
System:	Automatic sprinkler — anchor building riser
Impairment:	System shut off; water supply valve closed during vacant-unit renovation
Date observed:	2026-08-06
Owner notified:	Yes — property manager
Expected restoration:	Unknown

NFPA 25 impairment procedures were not followed: no fire watch, no notification to the insurer. The owner is directed to restore the system.

SAMPLE