
Nonparametric shared-stress comparison
20 vs 80 mm
Split check
Jute
0.0
0.2
0.4
0.6
0.8
1.0
Complete-data reliability