MENU

23 Shares



(https://pinshape.com/blog/how-to-generate-a-3d-printed-mold-for-an-object/)

How to generate a 3D printable mold for an object! (https://pinshape.com/blog/how-to-generate-a-3d-printed-mold-for-anobject/)



24 Comments (https://pinshape.com/blog/how-to-generate-a-3d-printed-mold-for-anobject/#disqus_thread)



We were lucky enough to have Dan Steele (https://pinshape.com/users/11828-dansteele) write a post on generating a 3D printed mold for an object! He has done quite a few of these, and you can download his molds from Pinshape. But if you want to create your own, read on for Dan's tutorial!

Introduction

I'm going to walk through the process of taking a cool character model and turning it into a mold, then casting copies from the mold.

Making a 3D printed mold can be a very easy process for some models. For instance, Robber Rex (https://pinshape.com/items/4075-3d-printed-robber-rex) was already Manifold, had no internal structures, and was low-poly so it took about 2 minutes to generate a mold w __1 ith the reference script. You can find the mold I created for it here (https://pinshape.com/items/4996-3d-printed-robber-rex-mold).

You can find the script that I ran against the original model with the parameters I used already filled in here

(https://drive.google.com/file/d/0B1w4gcTOEq2QczZFNjVqSV8zZTA/view?usp=sharing).

Bunny with an attitude was quite a bit more work. This cool model was designed by Tanya Wiesner.

This tutorial documents how I turned this model into a mold. The exact same steps should be able to convert all but the most broken models into molds.

Making a mold and casting can be broken into three distinct parts:

- Prepping and cleaning up the model
- Making the mold
- Casting parts


Preparing and cleaning up your model

The three requirements for a model capable of generating a mold are:

- Manifoldness A model must be manifold in order to turn it into a mold. For a
 model to be manifold, it must make up a volume that could exist in the real world.
 The most common cause of non-manifoldness are "holes" in a mesh. If the mesh
 isn't "water tight" and there is no clear inside and outside volume, a model is not
 manifold.
- No internal structures Often when models are created, they are made by jamming
 multiple other models together. If these models aren't stitched together properly
 with their internal structures removed, then we need to fix this before we attempt
 to make the mold.
- Low-Poly To use OpenSCAD to create a model, the poly count on the model must be less than 20,000. While this number may sound low for most objects, a higher poly count doesn't get you any more detail anyway.


23 Shares

(http://meshlab.sourceforge.net/). Meshlab is a full-featured tool but I mostly use it for reducing polycounts. Start Meshlab up and load your STL by clicking on File->Import Mesh...



(https://blog-assets.pinshape.com/blog/wp-

content/uploads/2015/05/02134534/mold-1.png) Next take a look at the face count. It's circled in red in the above picture. Right now it's at almost 1 million. I want to reduce it down to well under 100K for the first part of our process.



(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134528/mold-2.png)Click on:

23 Shares

Filters->Remeshing, Simplification, and Reconstruction->Quadratic Edge Collapse Decimation

Set the number of faces to something that still looks reasonable when you hit "Apply" but is below 100K (I chose 60K). Hit "Apply".

Your Model is now decimated down to a workable number of faces. If you skip this step, some of the software used in later steps won't load the model, or will crash when you try.


Step 2. Is it manifold?

Now we need to verify our model's manifoldness. Quadratic Edge Decimation generally produces good-looking results but frequently breaks manifoldness. The attitude bunny I'm using was manifold before the decimation, but now is not. Here's how you tell:

Click Render->Show Non-Manif Edges

then

Click Render->Show Non-Manif Vertices



(https://blog-assets.pinshape.com/blog/wp-

content/uploads/2015/05/02134519/mold-3.png) Notice in the above example we now have 60,000 faces in the bottom center. Also up in the top left hand corner we also have two boxes that should have a total of 4 zeros if everything is manifold. But I have a 1 and a 4. To fix this click:

Filter->Cleaning and Repairing-> Remove Duplicate Faces

Filter->Cleaning and Repairing-> Remove Duplicate Vertex

Filter->Cleaning and Repairing-> Remove Faces from Non Manif Edges

Once that's done export your mesh as an STL even if it still isn't perfectly manifold.


23 Shares

If after selecting all of the above your model still isn't manifold, you'll have to load it in Netfabb Basic (also free) and attempt automatic repair from there (http://www.netfabb.com/downloadcenter.php?basic=1).

If Netfabb basic won't fix it you may need to reduce the polycount further and repair it by hand in Sketchup. This is tedious and not for the faint of heart.

Speaking of Sketchup, it's a great tool for taking a look inside our mesh to see how the insides look. It's free and you can download it here (http://www.sketchup.com/).

You'll need to install an STL importer/exporter. There's one available in the Sketchup plugin library. Once you've done that, you'll be able to import your model and have a look. I highlighted the back of my model, then right-clicked and selected hide. Here's a peek at the insides:




(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134503/mold-4.png)If you look carefully you'll notice two things: the spheres up in the head structure and the overlap in the legs. These internal structures need to be eliminated to make the model properly manifold.

Step 3. Get rid of internal structures

This used to be a long and tedious process but now there's an easy and free solution. Autodesk's Meshmixer tool is free and can take care of this for us. Download it here (http://www.123dapp.com/meshmixer).

Load Meshmixer and choose import to import the latest version of your mold.

23 Shares



(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134457/mold-5.png)

Click Edit->Make Solid

You'll need to make some adjustments here to make things come out right. Adjust the values of "Solid Accuracy" and "Mesh Dens 1 ity" upwards until your model looks nice and clean when you hit "Update". Once you're happy with the results hit "Accept". Now go to File->Export and export it as an STL. This will produce an amazingly large file (mine was 1.9GB and a couple million polys). You'll need to bring this back into MeshLab and decimate it down to less than 20,000 polys (I used 11,000). Follow the steps above to clean up any final manifold errors.

Making the mold

For the next part you'll need to download OpenSCAD. It is another free modeling tool and you can find it here (http://www.openscad.org/).

You'll also need my mold generation scad which can be found here (https://drive.google.com/file/d/0B1w4gcTOEq2QYjhkYWZmT18xQUE/view?usp=sharing).

Put the Mold Generator script in the same directory as your model and load the script in OpenSCAD. The code window will look something like this:

```
Original Author

Parametric two-port mold generator
Author: Joson Nebb

Mebsite: http://jason-webb.info

Modified by

Chasse (rocketboy on thingiverse)

Changed one of the keys to a cube so mold can't be put together backwards. Center poor hole option for plaster.

A parametric two-port mold generator that constructs two-port molds with registration marks based on STL files.

// Model parameters
model_Trieneme - "obecli.stl";
model_roate = [796,99];
model_toole = -9;
// Mod parameters
mold_wight = 47;
// Mod parameters
mold_wight = 47;
// Measured along Z axis
mold_beight = 47;
// Measured along Z axis
mold_spacing = 3;
// Measured along Z axis
mold_spacing = 3;
// Measured along Z axis
mold_spacing = 3;
// Space between mold holves
rounded_corners = true;
// Kounded the corners to lessen warping
edge_radius = 8;
// Key parameters (registration marks)
key_size = 3;
key_fettle = 6.4;
// Size difference between keys and corresponding holes
key_sprin = 7;
// Distance from outside edge of mold
// Pour hole parameters
pour_hole = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //0 for folse 1 for true.
location = 0; //
```

(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134444/mold-6.png)

You'll need to change model_filename to the name of your STL. You can hit F5 to render a view of what the script will do right now. If you are very lucky it will be perfect right away, but chances are it won't be. Note that this script creates a negative of your model and pushes it into two halves of your mold. A negative space is difficult to see and position so there is a small change you can make to the script to see the model you are trying to place in the mold halves.

```
Bottom half of the mold
module bottom_half() {
    // Create the mold form with negative keys
   difference() {
        // Create the basic mold form by subtracting the STL from a cube half it's size
        difference() {
           difference() {
//
                    roundedBox([mold_width, mold_height, mold_depth], edge_radius, true);
                    cube(size = [mold_width, mold_height, mold_depth], center = true);
               scale(model_scale)
                    translate(model_translate)
                      rotate(model_rotate)
                            import(model_filename);
11
            if (pour_hole) {
                translate(model_translate)
                   translate([mold_depth,0,0])
                        cylinder(h = mold_depth*2, r1 = mold_depth*2, r2 = mold_depth, center = true);
```

content/uploads/2015/05/02134431/mold-7.png) Notice the six '//' I added on the left-hand side. Add those and hit F5 and all of a sudden you will see your model in the preview. You can now move the model around and put it halfway into the right-hand side of your mold. You move your model around by tweaking these variables


```
23
Shares
```

16

(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134418/mold-8.png)


For model_rotate and model_translate the 3 variables are X, Y, and Z respectively. model_scale is a multiplier applied to the size of your original model.

Adjust the mold_width, height and depth as needed so that your model sits nicely in the middle of your mold. Don't forget to hit F5 after you make an adjustment to see the effect. When you have all the variables set right, your preview should look something like this:



(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134408/mold-9.png)

Once it looks right, you'll need to remove the 6 '//' comment markings we added above and hit F5 again. It should now look like this:




23 Shares

16

(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134356/mold-10.png)

Your last step is to do a full render and export the STL. To do a render hit F6. This will take much longer than when you hit F5. Once the render is done, the model in the preview will look much clearer:



(https://blog-assets.pinshape.com/blog/wp-content/uploads/2015/05/02134347/mold-11.png)

You can now select File->Export and Export as an STL.

Casting with Oogoo


The original instructions for making 1 Oogoo can be found here (http://www.instructables.com/id/How-To-Make-Your-Own-Sugru-Substitute/).

I've got a couple of tips for using Oogoo so that it will work well with these molds.

- Add essential oils. Just add a few drops of vanilla (or whatever other odour strikes your fancy) essential oil to the silicon before adding the corn starch. It will replace the yucky vinegar smell much quicker.
- Add a bit of oil-based paint even if you don't care about color. The extra oil from the paint and essential oil makes the Oogoo a bit thinner and delays the curing process a bit.

Here are my steps to making the mold:

- 1. Add the essential oils into the silicon and stir in the paint
- 2. Stir until paint is mixed evenly
- 3. Mix in corn starch. Add the same amount of cornstarch as silicon by volume. I did this one teaspoon at a time, stirring until it was well blended.
- 4. Smoosh the Oogoo into the mold. Add more than you think you'd need.



Leave your mess sitting around on the counter so you can poke at the leftover Oogoo every once in a while. When it's hard and rubbery, the stuff in your mold will be as well. Pull the mold apart carefully and enjoy your new minion. Make a thousand. Start an army....take over the world!

We'd love to hear from you!

Questions? Comments? Leave them for Dan below!

Related







(https://pinshape.com/blog/to/https://pinshape.com/blog/lowhttps://pinshape.com/blog/what-

10-most-popular-3dprinting-articles-of-2015-

on-pinshape/)

Top 10 Most Popular 3D Printing Articles of 2015 on

Pinshape!

cost-injection-moldingusing-3d-printing/)

Low-Cost Injection Molding

Using 3D Printing

cost-injection-molding-

is-3d-printing/)

What is 3D Printing?

(https://pinshape.com/blog/what-

is-3d-printing/) (https://pinshape.com/blog/lowJuly 14, 2015 In "Guides"

(https://pinshape.com/blog/topusing-3d-printing/)

10-most-popular-3d-

printing-articles-of-2015-on-

pinshape/) January 4, 2016 In "Industry News" November 2, 2017 In "Pinshape News"

23 Shares

3D Print (https://pinshape.com/blog/tag/3d-print/)
3d printing guide (https://pinshape.com/blog/tag/3d-printing-guide/)
guide (https://pinshape.com/blog/tag/guide/)
tutorial (https://pinshape.com/blog/tag/tutorial/)

23 Shares

16

PINSHAPE

(HTTPS://PINSHAPE.COM/BLOG/AUTHOR/LETMETELLYOUABOUT3DPRINTING/)

Pinshape is a 3D printing community and marketplace where makers from all over the world can find and share their next great 3D print and help each other get the best results from their 3D printers.

24 Comments Pinshape Blog			● Login →
			Sort by Best 🔻
	Join the discussi	on	
	LOG IN WITH	OR SIGN UP WITH DISQUS ?	
		Name	

Andrew Patton • 10 months ago

Any advice would be appreciated. I get an error at Rendering... Also can't find Line:326.

Rendering Polygon Mesh using CGAL...

ERROR: CGAL error in CGAL_Nef_polyhedron3(): CGAL ERROR: assertion violation! Expr: e->incident_sface() != SFace_const_handle() File: /opt/mxe/usr/x86_64-w64-

mingw32.static/include/CGAL/Nef_S2/SM_const_decorator.h Line: 326

Reply • Share >

Andrew Patton → Andrew Patton • 10 months ago

Fixed. Took awhile but I had to repair my model with multiple programs.

∧ V • Reply • Share >

Gabriel Martins Raphael • a year ago

cool.. doesn't work. when press f6 the mold get only the outside block surface.. and don't the model negative.

Ultra Force • 3 years ago

Then you can use your two part mold to rotational cast it hollow with a RotoMAAK

SEARCH

search.. S

23 Shares

16

PINSHAPE

Pinshape is a 3D printing community and marketplace where makers from all over the world can find and share their next great 3D print and help each other get the best results from their 3D printers.

NEWSLETTER

Sign up now to get the best 3D printing news & coolest new designs each week!

Your email address

Sign up

FOLLOW US!

(http:///fape/lockepit/hethpa/dy/ijpjlalite/glas/had/si.ors/psig/ts/Pinpseb/ap/ep)inshape3d/)

POPULAR POSTS



5 Interesting 3D Printer Controller Boards to Check Out!

(https://pinshape.com/blog/3-interesting-3d-printer-controller-boards/)



FDM vs SLA: How does 3D Printing Technology Work? (https://pinshape.com/blog/fdm-vs-sla-how-does-3d-printer-tech-work/)

Low-Cost Injection Molding Using 3D Printing (https://pinshape.com/blog/low-cost-injection-molding-using-3d-printing/)

23 Shares


16

Learn How To 3D Print With

Nylon —

How to 3D Print with Nylon

(https://pinshape.com/blog/how-to-3d-print-with-nylon/)



4 Things You Need to Know About 3D Printing Resolution (https://pinshape.com/blog/4-thingsyou-need-to-know-about-3d-printing-resolution/)

RECENT POSTS



Pinshape Featured Designs - December 15th (https://pinshape.com/blog/pinshape-featured-designs-december-15th/)



Announcing the Create to Educate Lesson Plan Contest Winners!

(https://pinshape.com/blog/announcing-create-educate-lesson-plan-contest-winners/)



Pinshape Featured Designs - December 8th (https://pinshape.com/blog/pinshape-featured-designs-december-8th/)

 $\label{lem:pinshape} \textbf{Pinshape's Official 2017 Holiday Gift Guide (https://pinshape.com/blog/pinshapes-official-2017-holiday-gift-guide/)} \\$





Pinshape Featured Designs - December 1st (https://pinshape.com/blog/pinshape-featureddesigns-december-1st/)

(https://pinshape.com/blog/3d-(https://pinshape. timelapseprintingfortuesdaysboneheadscharitywith-(http://**(lakteb///wither///withma/pi)julihangs//www.cipinsk/lephines**kra**pe)**pinshape3d/) skull/) miniworld/)

© pinshape inc. 2017

23 Shares