Lan	gkah-langkah Perhitungan Garis Pantai	
No	Urutan kerja	Dihitung
1.	Masukkan nilai X dengan jarak spasi 50 m	X (m)
2.	Urutkan Pias Berdasarkan tiap jarak spasi	Pias
3.	Masukkan nilai Y untuk data awal garis pantai "X"	Yawal (m)
4.	Hitung nilai tangen ai	Tan ai
5.	Hitung nilai tangen ab (dengan nilai ao sudah diketahui)	Tan ab
6.	Cari nilai ab	ab
7.	Hitung nilai sin ab	Sin ab
8.	Hitung nilai cos ab	Cos ab
9.	Carilah nilai P1	P1 (ton m/s/m)
10.	Carilah nilai QS	Qs (m3/hr)
11.	Carilah nilai DY	DY(i)
12.	Hitunglah nilai Yakhir	Yakhir (m)

Rumus

X= 0, 50, 100, ..., 4500

Pias ke-1 untuk X=0, Pias ke-2 untuk X=50, dst

Y1= 1374, Y2= 1367, dst

tan ai =(Yi - Yi+1) / Dx

tan ab = (tan ai + tan a0)/(1 + (tan a0 x tan ai))

ab = arc tan ab

P1 = $(r \times g \times Hb2 \times Cb \times sin ab \times cos ab)/8$

 $QS = 0.401 \times P1$

 $DY = (Dt) \times (-1/db) \times (Qs/DX)$

Yakhir = Yawal + DY

	ao =	50	degree
tar	1 ao =	1.1917535	
	Dx =	50	m
	Dt =	5	tahun
	g =	9.81	m/s
	Hb =	0.78	m e e e e e e e e e e e e e e e e e e e
	db =	1.192	m e e e e e e e e e e e e e e e e e e e
	r =	1.025	t/m3
	Cb =	3.4195789	m/s
For	rmula	:	
	P1 =	(r x g x	x Hb2 x Cb x sin ab x cos ab)/8
	Qs =	0.401 x	P1
	v =	1.17 x	(g x Hb)0.5 x sin ab x cos ab (m/s)
an	ai =	(Yi - Y	i+1) / Dx
an	ab =	(tan ai	+ tan a0)/(1 + (tan a0 x tan ai))
	DY =	(Dt) x	(-1/db) x (DQ/DX)
Dir	nana	:	
	ab:	sudut da	atang gelombang pecah
	P1 :	kompone	n fluks energi gelombang sepanjang pantai pada saat pec
	QS :	angkuta	n sedimen sepanjang pantai (m3/hari)
	v :	kecepata	an arus sejajar pantai (m/s)
	Dx :	jarak a	ntar pias (m)
	Cb:	kecepata	an rambat gelombang di area breaking wave

X (m)	Yawal (m)														
0	1449														
50	1442														
100	1435		4000T												_
150	1429		1												
200	1460		3500												
250	1481		3000			-								The same of	
300	1491										_	-			
350	1507	E	2500												
400	1520	al (2000					-							
450	1762	Yawal (m)		_ /		+									
500	1878		1500	_											
550	1661		1000			1									
600	1662														
650	1660		500												\equiv
700	1741														
750	1731		o	50	0 10	000	1500	200	00	2500	300	0 35	00	4000	4
800	1729								X (m)					
850	1730								•						
900	1731														
950	1742														
1000	1753														
1050	1739														
1100	1725														
1150	1714														
1200	1719														
1250	1744														
1300	1763														
1350	1762														
1400	1770														
1450	1794														
——															
1500	1820														
1550	1843														
1600	1883														
1650	1923														
1700	1939														
1750	1970														
1800	2007														
1850	2037														
1900	2071														
1950	2079														
2000	2108														
2050	2131														
2100	2155														
2150	2179														
2200	2226														
2250	2244														
	2277														



2300 2261 2350 2298 2400 2306 2450 2314 2500 2319 2550 2336 2600 2417 2650 2460 2700 2490 2800 2549	
2400 2306 2450 2314 2500 2319 2550 2336 2600 2417 2650 2460 2700 2490 2750 2519	
2450 2314 2500 2319 2550 2336 2600 2417 2650 2460 2700 2490 2750 2519	
2500 2319 2550 2336 2600 2417 2650 2460 2700 2490 2750 2519	
2550 2336 2600 2417 2650 2460 2700 2490 2750 2519	
2600 2417 2650 2460 2700 2490 2750 2519	
2650 2460 2700 2490 2750 2519	
2700 2490 2750 2519	
2750 2519	
2850 2563	
2900 2587	
2950 2615	
3000 2639	
3050 2664	
3100 2687	
3150 2710	
3200 2733	
3250 2756	
3300 2779	
3350 2802	
3400 2825	
3450 2848 3500 2871	
3500 2871 3550 2894	
3600 2917	
3650 2940	
3700 2963	
3750 2986 2986	
3800 3009	
3850 3032	
3900 3055	
3950 3074	
4000 3107	
4050 3120	
4100 3139	
4150 3165	
4200 3205	
4250 3252	
4300 3295	
4350 3331	
4400 3367	
4450 3404	
4500 3440	

				Per	rubahan (Garis Par	ntai Unt	uk 25 Tahun
X (m)	Pias	Yawal (m)	Tan ai	Tan ab	ab	Sin ab	Cos ab	P1 (ton m/s/m
0	0	1449	0.14	1.14	48.78	0.75	0.66	1.30
50	1	1442	0.14	1.14	48.78	0.75	0.66	1.30
100	2	1435	0.12	1.15	48.93	0.75	0.66	1.30
150	3	1429	-0.62	2.19	65.45	0.91	0.42	0.99
200 350	o 4	1460	-0.42	1.55	57.09	0.84	0.54	1.19
250	5	1481	-0.20	1.30	52.48	0.79	0.61	1.26
300	6	1491	-0.32	1.41	54.64	0.82	0.58	1.23
350 ³⁰⁰⁰	7	1507	Laut	L.35	53.47	0.80	0.60	1.25
400	8	1520	-4.84	0.77	37.42	0.61	0.79	1.20
450 ₂₅₀	9	1762	-2.32	0.64	32.59	0.54	0.84	1.19
500	10	1878	4.34	0.90	41.87	0.67	0.74	1.30
550	11	1661	-0.02	1.20	50.20	9.77	0.64	1.29
600 ²⁰⁰	12	1662	0.04	1.18	23.62	0.76	0.65	1.29
650	13	A 660	-1.62	0.46	24.71	0.42	0.91	0.99
700 150	14	1741	0.20	1.12	48.34	0.75	0.66	1.30
750	15	1731	0.04	1.18	49.62	0.76	0.65	1.29
800	16	1729	-0.02	1.20	50.20	0.77	Dar	1.29
850 100	17	1730	-0.02	1.20	50.20	0.77	0.04	1.29
900	18	1731	-0.22	1.32	52.79	0.80	0.60	1.26
950 ₅₀₀	19	1742	-0.22	1.32	52.79	0.80	0.60	1.26
1000	20	1753	0.28	1.10	47.82	0.74	0.67	1.30
1050	21	1739	0.28	1.10	47.82	0.74	0.67	1.30
1100 ⁰	22	_1725	0.22	1,12	48.20	0.75	0.67	1.30
1150	23	1714	-0.10	1.24	51.10	0.78	0.63	1.28
1200	24	1719	-0.50	1.71	59.71	0.86	0.50	1.14
1250	25	1744	-0.38	1.48	56.02	0.83	0.56	1.21
1300	26	1763	0.02	1.18	49.80	0.76	0.65	1.29
1350	27	1762	-0.16	1.27	51.89	0.79	0.62	1.27
1400	28	1770	-0.48	1.66	58.98	0.86	0.52	1.15
1450	29	1794	-0.52	1.77	60.49	0.87	0.49	1.12
1500	30	1820	-0.46	1.62	58.31	0.85	0.53	1.17
1550	31	1843	-0.80	8.41	83.22	0.99	0.12	0.31
1600	32	1883	-0.80	8.41	83.22	0.99	0.12	0.31
1650	33	1923	-0.32	1.41	54.64	0.82	0.58	1.23
1700	34	1939	-0.62	2.19	65.45	0.91	0.42	0.99
1750	35	1970	-0.74	3.83	75.35	0.97	0.25	0.64
1800	36	2007	-0.60	2.08	64.29	0.90	0.43	1.02
1850	37	2037	-0.68	2.70	69.67	0.94	0.35	0.85
1900	38	2071	-0.16	1.27	51.89	0.79	0.62	1.27
1950		+		 	 			
	39	2079	-0.58	1.98	63.22	0.89	0.45	1.05
2000	40	2108	-0.46	1.62	58.31	0.85	0.53	1.17
2050	41	2131	-0.48	1.66	58.98	0.86	0.52	1.15
2100	42	2155	-0.48	1.66	58.98	0.86	0.52	1.15

Qs	(m3/hr)		DY(i)	Ł	akhir	(m)	ao =	50	degree
-	189.71		-79.58		1369.	42	tan ao =	1.191753	
-	189.71	L	-79.58		1362.	42	Dx =	50	m
-	189.57		-79.52		1355.	48	Dt =	25	tahun
-	144.63		-60.67		1368.	33	g =	9.81	m/s
-	174.58		-73.23		1386.	77	Hb =	0.78	m
	184.89		-77.55		1403.	45	db =	1.192	m
	180.54		-75.77		1415.	23	r =	1.025	t/m3
	183.06		-76.79		1430.	21	Cb =	3.4195789	m/s
-	184.71		-77.48		1442.	52			
	173.69		-72.86		1689.	14			
-	190.23	•	-79 79 Garis pantai a	wa	1798.	21			
	188.22	•	—_Gagis poangtais	ete	lal5252hr	05			
	188.89		-79.23		1582.	77			
	145.35		-60.97		1599.	03			
	190.07		-79.73		1661.	27			
	188.89		-79.23		1651.	77			
-	188.22		-78.95		1650.	05			
-	188.22		-78.95		1651.	05			
-	184.33		-77.32	Τ	1653.	68			
-	184.33		-77.32	Т	1664.	68			
-	190.44	П	-79.88	T	1673.	12			
-	190.44	П	-79.88	Ť	1659.	12			
-	190.18	H	-79.77	Ť	1645.	23			
-	1 000 187.04	45	-78.46	Ť	1635.	54			
-	166.70	Н	-69.93	T	1649.	07			
	177.39	Н	-74.41	\dagger	1669.				
	188.68	┢	-79.15	\dagger	1683.				
	185.86	┢	-77.96	+	1684.				
	169.02	┝	-70.90	+	1699.				
		┝		+					
	164.09	\vdash	-68.83	+	1725.	_			
	171.09	\vdash	-71.77	+	1748.	$\overline{}$			
	44.89	\vdash	-18.83	+	1824.				
	44.89	\vdash	-18.83	+	1864.	$\overline{}$			
	180.64	\vdash	-75.77	+	1847.				
	144.63	\vdash	-60.67	+	1878.	\dashv			
	93.66	L	-39.29	+	1930.				
	149.61	L	-62.76	1	1944.	$\overline{}$			
	124.69	L	-52.30	\downarrow	1984.	70			
-	185.86	L	-77.96	\perp	1993.	04			
	153.96	L	-64.58	┸	2014.	42			
	171.09		-71.77		2036.	23			
	169.02		-70.90	Γ	2060.	10			
-	169.02	Г	-70.90	Τ	2084.	10			
_	148.85		62.44	T	2241.	44			

2200	
2300	
2350	
2400 48 2306 -0.16 1.27 51.89 0.79 0.62 1.2° 2450 49 2314 -0.10 1.24 51.10 0.78 0.63 1.2° 2500 50 2319 -0.34 1.43 55.07 0.82 0.57 1.2° 2550 51 2336 -1.62 0.46 24.71 0.42 0.91 0.99 2600 52 2417 -0.86 -13.32 -85.71 -1.00 0.07 -0.29 2650 53 2460 -0.60 2.08 64.29 0.90 0.43 1.0° 2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.0° 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.0° 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.2° 2850 57 2563 -	
2450	
2500 50 2319 -0.34 1.43 55.07 0.82 0.57 1.22 2550 51 2336 -1.62 0.46 24.71 0.42 0.91 0.99 2600 52 2417 -0.86 -13.32 -85.71 -1.00 0.07 -0.2 2650 53 2460 -0.60 2.08 64.29 0.90 0.43 1.00 2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.03 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.00 2850 56 2549 -0.28 1.37 53.84 0.81 0.59 1.22 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.13 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.03 2950 59 2615 -0	
2550 51 2336 -1.62 0.46 24.71 0.42 0.91 0.99 2600 52 2417 -0.86 -13.32 -85.71 -1.00 0.07 -0.2 2650 53 2460 -0.60 2.08 64.29 0.90 0.43 1.03 2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.03 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.03 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.22 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.11 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.03 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0	
2600 52 2417 -0.86 -13.32 -85.71 -1.00 0.07 -0.2 2650 53 2460 -0.60 2.08 64.29 0.90 0.43 1.03 2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.03 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.03 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.21 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.12 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.01 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.11 3000 61 2664 -0	
2650 53 2460 -0.60 2.08 64.29 0.90 0.43 1.00 2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.03 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.03 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.22 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.11 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.00 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.11 3100 62 2664 -0.46 1.62 58.31 0.85 0.53 1.11 3150 63 2710 -0.46<	l
2700 54 2490 -0.58 1.98 63.22 0.89 0.45 1.00 2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.00 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.23 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.11 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.00 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.12 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46<)
2750 55 2519 -0.60 2.08 64.29 0.90 0.43 1.00 2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.21 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.11 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.03 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.11 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3250 65 2756 -0.46<	
2800 56 2549 -0.28 1.37 53.84 0.81 0.59 1.21 2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.11 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.00 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.11 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.17 3250 65 2756 -0.46<	ı
2850 57 2563 -0.48 1.66 58.98 0.86 0.52 1.13 2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.00 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.13 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.14 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.17 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.17 3350 67 2802 -0.46<	
2900 58 2587 -0.56 1.90 62.23 0.88 0.47 1.00 2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.14 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.17 3350 65 2756 -0.46 1.62 58.31 0.85 0.53 1.17 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46<	ı
2950 59 2615 -0.48 1.66 58.98 0.86 0.52 1.11 3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.12 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.17 3200 65 2756 -0.46 1.62 58.31 0.85 0.53 1.17 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.17 3450 67 2802 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46<	i
3000 60 2639 -0.50 1.71 59.71 0.86 0.50 1.14 3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.17 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.17 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.17 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.17 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.17 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.17 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46<	į
3050 61 2664 -0.46 1.62 58.31 0.85 0.53 1.1° 3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.1° 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.1° 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.1° 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.1° 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.1° 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.1° 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.1° 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.1° 3600 72 2917 -0.46<	,
3100 62 2687 -0.46 1.62 58.31 0.85 0.53 1.1° 3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.1° 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.1° 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.1° 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.1° 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.1° 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.1° 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.1° 3500 71 2894 -0.46 1.62 58.31 0.85 0.53 1.1° 3600 72 2917 -0.46<	:
3150 63 2710 -0.46 1.62 58.31 0.85 0.53 1.1° 3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.1° 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.1° 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.1° 3350 67 2802 -0.46 1.62 58.31 0.85 0.53 1.1° 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.1° 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.1° 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.1° 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.1° 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.1° 3700 74 <th></th>	
3200 64 2733 -0.46 1.62 58.31 0.85 0.53 1.1° 3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.1° 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.1° 3350 67 2802 -0.46 1.62 58.31 0.85 0.53 1.1° 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.1° 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.1° 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.1° 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.1° 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.1° 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.1° 3800 76 <th></th>	
3250 65 2756 -0.46 1.62 58.31 0.85 0.53 1.17 3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.17 3350 67 2802 -0.46 1.62 58.31 0.85 0.53 1.17 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3650 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3650 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 <th></th>	
3300 66 2779 -0.46 1.62 58.31 0.85 0.53 1.17 3350 67 2802 -0.46 1.62 58.31 0.85 0.53 1.17 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 <th></th>	
3350 67 2802 -0.46 1.62 58.31 0.85 0.53 1.17 3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3950 79 3074 -0.66<	
3400 68 2825 -0.46 1.62 58.31 0.85 0.53 1.17 3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 <th></th>	
3450 69 2848 -0.46 1.62 58.31 0.85 0.53 1.17 3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.22 3950 79 <th></th>	
3500 70 2871 -0.46 1.62 58.31 0.85 0.53 1.17 3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 <th></th>	
3550 71 2894 -0.46 1.62 58.31 0.85 0.53 1.17 3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 <th></th>	
3600 72 2917 -0.46 1.62 58.31 0.85 0.53 1.17 3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3650 73 2940 -0.46 1.62 58.31 0.85 0.53 1.17 3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3700 74 2963 -0.46 1.62 58.31 0.85 0.53 1.17 3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3750 75 2986 -0.46 1.62 58.31 0.85 0.53 1.17 3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3800 76 3009 -0.46 1.62 58.31 0.85 0.53 1.17 3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.29 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.29	
3850 77 3032 -0.46 1.62 58.31 0.85 0.53 1.17 3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3900 78 3055 -0.38 1.48 56.02 0.83 0.56 1.23 3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.23 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
3950 79 3074 -0.66 2.49 68.13 0.93 0.37 0.90 4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.25 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.25	
4000 80 3107 -0.26 1.35 53.47 0.80 0.60 1.29 4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	
4050 81 3120 -0.38 1.48 56.02 0.83 0.56 1.23	i
	1
4100 82 3139 -0.52 1.77 60.40 0.87 0.40 1.19	
1.12	
4150 83 3165 -0.80 8.41 83.22 0.99 0.12 0.33	
4200 84 3205 -0.94 -2.09 -64.47 -0.90 0.43 -1.0	2
4250 85 3252 -0.86 -13.32 -85.71 -1.00 0.07 -0.2	ე
4300 86 3295 -0.72 3.32 73.25 0.96 0.29 0.72	
4350 87 3331 -0.72 3.32 73.25 0.96 0.29 0.72	
4400 88 3367 -0.74 3.83 75.35 0.97 0.25 0.64	:
4450 89 3404 -0.72 3.32 73.25 0.96 0.29 0.72	

178.58 -74.91 179.66 -75.36 93.66 -39.29	2151.09 2168.64 2221.71
93.66 -39.29	
 	2221.71
105 06 77 06	
185.86 -77.96	2220.04
185.86 -77.96	2228.04
187.04 -78.46	2235.54
179.66 -75.36	2243.64
145.35 -60.97	2275.03
-28.57 11.99	2428.99
149.61 -62.76	2397.24
153.96 -64.58	2425.42
149.61 -62.76	2456.24
182.33 -76.48	2472.52
169.02 -70.90	2492.10
157.78 -66.18	2520.82
169.02 -70.90	2544.10
166.70 -69.93	2569.07
171.09 -71.77	2592.23
171.09 -71.77	2615.23
171.09 -71.77	2638.23
171.09 -71.77	2661.23
171.09 -71.77	2684.23
171.09 -71.77	2707.23
171.09 -71.77	2730.23
171.09 -71.77	2753.23
171.09 -71.77	2776.23
171.09 -71.77	2799.23
171.09 -71.77	2822.23
171.09 -71.77	2845.23
171.09 -71.77	2868.23
171.09 -71.77	2891.23
171.09 -71.77	2914.23
171.09 -71.77	2937.23
171.09 -71.77	2960.23
177.39 -74.41	2980.59
132.31 -55.50	3018.50
183.06 -76.79	3030.21
177.39 -74.41	3045.59
164.09 -68.83	3070.17
44.89 -18.83	3146.17
-148.85 62.44	3267.44
-28.57 11.99	3263.99
105.60 -44.29	3250.71
105.60 -44.29	3286.71
93.66 -39.29	3327.71
105.60 -44.29	3359.71

4500	90	3440	68.80	0.84	40.14	0.64	0.76	1.29

188.62	-79.12	3360.88
Erosi rata -	- rata	-64.120
	Erosi	62.438
	Sedimentasi	-79.884