

HP Point of Sale (POS) Peripherals Configuration Guide – Barcode Scanner Default / Tab Barcodes

Document Version 3.23 November 2010 © Copyright 2007-2010 Hewlett-Packard Development Company, L.P. The information contained herein is subject to change without notice.

Microsoft, MS-DOS, Windows, WEPOS, POSReady and Windows NT are trademarks of Microsoft Corporation in the U.S. and other countries.

The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

HP Point of Sale (POS) Peripherals Configuration Guide – Barcode Scanner Default / Tab Barcodes Document Version 3.23.0003

November 2010

HP USB Barcode Scanner

Scan the following bar code to put the scanner back to factory default setting:



Set All Defaults

If a tab is required after a bar code is scanned, scan the following bar codes to program the scanner for this option:

