



Comms




12C CONNECTOR

UART CONNECTOR



CANBUS CONNECTORS




Sheet: /Comms/ File: comms.kicad_sch


Title:

 Size: A4
 Date:
 Rev:


 KiCad E.D.A. kicad 7.0.10
 Id: 2/6



Debug



POWER SUPPLY TESTPOINTS CANBUS TESTPOINTS






Sheet: /Debug/ File: debug.kicad_sch

| Title | : |
|-------|---|
| | |

| Size: A4 | Date: | Rev: |
|----------------|--------------|---------|
| KiCad E.D.A. k | kicad 7.0.10 | ld: 4/6 |



I/O CONNECTOR J16 --Conn_01x07_Pin --J17 = 1 Conn_01x02_Pin = 2 GND J18 - 1 Conn_01x02_Pin - 2 GND +12V J19 <u>1</u> Conn_01x02_Pin <u>2</u> Sheet: /IO/ File: io.kicad_sch Title: Size: A4 Date: KiCad E.D.A. kicad 7.0.10 **Rev:** Id: 6/6