

Printer-A200 Diagnostic & Troubleshooting Guide

Product: Industrial Printer | Model: Printer-A200 | Document Type: TROUBLESHOOTING

1. Error Code P101 - Filament Jam / Feed Error

Description: Extruder stepper motor detects high backpressure or filament runout sensor triggers.

- Corrective Action: 1. Pause print job. 2. Heat nozzle to 230°C. 3. Use 0.4 mm acupuncture needle to clear nozzle tip orifice. 4. Reload filament.

2. Error Code P205 - Bed Thermal Runaway

Description: Heated bed thermistor signal drops unexpectedly during heating cycle.

- Corrective Action: Inspect bed heater thermistor wiring harness connector under heated bed plate.