```
ADD AL, OTH
DIGIT:
ADD AL, 30H; 30H
MOV RES, AL
AND BL, OFH ; BL = OAH
CMP BL, OAH
 JC DIGIT1
 ADD BL, 07H; BL = OA + O7H
 DIGIT1:
 ADD BL, 30H; BL = OA + O7 + 30 OA + 37 = 41H
MOV RES+1, BL
 MOV AH, DOH ; CLEAR THE SCREEN
 MOV AL, O3H
 INT LOH
 MOV AH, OZH ; SET THE CURSOR POSITION
 MOV BH, OOH
 MOV DH, OCH ; ROW NUMBER
 MOV DL, 28H; COLUM NUMBER.
  MOV REST2, $'; $ HERE INDICATES END
                     OF THE RESULT STRING
```

LEADX, RES

CALL DISP; RES VALUE WILL BE PRINTED ON THE SCREEN

MOV AH, 4CH

DISP PROC NEAR MOV AH, DQH INT 21H RET DISP ENDP

END.