























## Ω **Rev:** Id: 26/40 3.30 File: Magnetotorquer Driver2.kicad\_sch File: Magnetotorquer Driver3.kicad\_sch File: TEMPERATURE.kicad\_sch Sheet: /ADCS/ File: ADCS.kicad\_sch **Title:** TEMPERATURE SENSOR Driver2 Magnetotorquer Driver3 νε.ε> Size: A3 KiCad E.D.A. DI2C1\_SDA DMAG\_CURR\_2 DMAG\_STBY\_2 DMAG\_DIR\_2 DMAG\_PWM\_2 DMAG\_FAULT\_2 DMAG\_EN\_2 OMAG\_PWM\_3 -OMAG\_CURR\_3 -OMAG\_EN\_3 -OMAG\_FAULT\_3 -OMAG\_STBY\_3 -OMAG\_DIR\_3 Magnetotorquer Transceiever.kicad\_sch MAG\_CURR\_2C MAG\_STBY\_2D MAG\_DIR\_2D MAG\_PWM\_2D MAG\_FAULT\_2C MAG\_PWM\_3C MAG\_CURR\_3C MAG\_EN\_3C MAG\_STBY\_3C MAG\_STBY\_3C CAN Transciever ♦CAN H ♦CAN L >CAN\_VCC ∴ ♦ F D C A N 1\_TX FDCAN1\_RX⇔ FDCAN1\_TX⇔ νε.ε> ->νε.ε M\_TNI< □M\_TNI Sensor.kicad Sch DRDY\_MD INECTOR ISCT<sup>™</sup>2D∀� ⟨ISC1\_SDA⟩ (ISGI ZCE) SCT<sup>−</sup>SCF DD\A\_1TNI J16 Conn\_02x10\_Counte ADCS CON Sensor A STNI DEN AVG DEN\_A/GD 3.34 ΛG ADCS DAUGHTER File: (ISCT\_SDA) ISCT<sup>™</sup>SD∀ d N D (ISCT\_SCF) ISCT<sup>−</sup>2CF♦ CAN\_VCCD CAN H♦ CAN L♦ GNDD 5∨ XA\_STAA2U< ♦XA\_STAA2U XT\_STAA2U ≎XT\_STЯA≳U ENABLED D5 LED File: Switch.kicad\_sch ΛG ]Vout\_switch νε.ε> ⊳νε.ε Б195 ТКорш untitled OPBS $\Diamond$ CND DPC0 DPC1 DPB0 PBSC PC6C File: ESC Connector.kicad\_sch H3 MountingHole H4 MountingHole Mounting Holes File: Magnetotorquer Driver1.kicad\_sch File: BOOST Converter.kicad\_sch PCOC PC1C PBOC PB5C JP2 Jumper\_3\_Bridged12 JOutput\_8V Vout\_switch⊂ Magnetotorquer Driver1 BOOST Converter H2 MountingHole H1 MountingHole 0 0



























