



The .gov means it's official.

Federal government websites often end in .gov or .mil. Before sharing sensitive information, make sure you're on a federal government site.



The site is secure.

The **https://** ensures that you are connecting to the official website and that any information you provide is encrypted and transmitted securely.



Occupational Safety and Health Administration

[CONTACT US](#) | [FAQ](#) | [A TO Z INDEX](#) | [LANGUAGES](#)



Menu

[OSHA](#) [STANDARDS](#) [ENFORCEMENT](#) [TOPICS](#) [HELP AND RESOURCES](#) [NEWS](#) [CONTACT US](#) [FAQ](#) [A TO Z INDEX](#) [LANGUAGES](#)

[Return to Accident Search Results](#)

Accident Report Detail

Accident Summary Nr: 173962.015 - Employee sustains fatal burns in compressor station explosio

Accident Summary Nr: 173962.015 -- Report ID: 0855610 -- Event Date: 01/30/2025

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1801292.015	01/31/2025		211130	Eog Resources, Inc

Abstract: At 12:45 p.m. on January 30, 2025, Employee #1 was working on a malfunctioning compressor unit at an oil and gas compressor station site when an equipment-related explosion occurred. The blast caused a fire and multiple burns, resulting in fatal injuries.

Keywords: Burn, Compressor, Explosion, Explosives, Fire

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1801292.015	58	M	Fatality		Supervisors, production occupations

Accident Summary Nr: 173635.015 - Employee is killed when struck by tree in motor vehicle acci

Accident Summary Nr: 173635.015 -- Report ID: 0627100 -- Event Date: 01/19/2025

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1798725.015	01/21/2025		211120	Mission Creek Employee Co., Llc

Abstract: At 9:00 a.m. on January 19, 2025, Employee #1 was driving a work truck on an access road while checking production on oil and gas wells. The employee accelerated and struck a pine tree off the side of the road. An automated accident alert was sent to the sheriff, and deputies searched but did not locate the accident. At approximately 2:30 p.m., a neighbor found the accident site and called 911. Employee #1 was found alive but unresponsive. It is presumed that Employee #1 later died from a heart attack. The employee was 75 years old. The incident is not covered by OSHA.

Keywords: Cardiovasc Disease, Cardiovasc System, Heart, Heart Attack, Motor Vehicle, Struck Against, Struck By, Traffic Accident, Tree, Unconsciousness, Unresponsive, Vehicle

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1798725.015	75	M	Fatality		Quality Assurance Inspector

Accident Summary Nr: 172070.015 - Employee dies from head trauma when struck by high pressure

Accident Summary Nr: 172070.015 -- Report ID: 0627510 -- Event Date: 11/20/2024

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1789632.015	11/20/2024		211120	Mewbourne Oil Company

Abstract: At 5:00 p.m. on November 20, 2024, an employee working for an oil company was performing maintenance on a 2-phase separator vessel. The vessel was undergoing clearance testing of the system maintenance was performed due to a paraffin buildup. The employee was working by the tank battery venting the pressure out of the vessel. The employee vented pressure out through a pipe that hung down from the vessel with an L-bend at the bottom. When the employee vented the pressure out of the pipe, it caused the pipe to rotate around its point of axis. As the pipe was on the downward swing, it struck the employee who was standing in the path of rotation in the head. The employee died from skull fractures and other head trauma including fractures, contusions and a concussion.

Keywords: Abrasion, Concussion, Contusion, Fracture, Head, High Pressure, High Pressure Pipe, Maintenance, Metal, Metal Pipe, Pipe, Pressure Vessel, Rotating Parts, Skull, Struck By, Testing, Unsecured, Vent, Venting, Vessel--Container

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1789632.015	23	M	Fatality	

Accident Summary Nr: 170054.015 - Employee is killed when struck by rod during WLV pressure te

Accident Summary Nr: 170054.015 -- Report ID: 1032100 -- Event Date: 06/30/2023

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1680855.015	07/02/2023		211120	Halliburton

Abstract: At 4:15 p.m. on June 30, 2024, Employee #1, a maintenance technician, was assisting with WLV pressure testing when a rod was ejected from the WLV system. The rod struck Employee #1 in the head, causing a fatal injury. Emergency services were called, but the employee died from the injuries.

Keywords: Drill Rod, Flying Object, Head, Struck By, Traumatic Brain Injury

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1680855.015	27	M	Fatality	

Accident Summary Nr: 155471.015 - Employee is killed when struck by high pressure pipe

Accident Summary Nr: 155471.015 -- Report ID: 0626600 -- Event Date: 12/05/2022

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1638173.015	12/06/2022		211130	Brammer Engineering, Inc.

Abstract: At 7:40 p.m. on December 5, 2022, an employee was working with a crew of coworkers preparing to remove a Christmas tree and install a blowout preventer on a gas well. The crew was working on a mobile pumping station that was hooked up to the Christmas tree which this was used to relieve the pressure in the well. The crew connected approximately 50 feet of 2-inch pipe from the pumping station to the Christmas tree. When they opened the valve on the Christmas tree, the pipe ruptured at the pumping station causing it to swing wildly back and forth. The pipe was rated for 5,000 pounds and the estimated well pressure was 2,500 pounds. A coworker (an independent contractor) and the employee were killed. Three coworkers were struck by the pipe and hospitalized. They have since been released. The crews were working two 12-hour shifts with five man crews and both companies were out of the same State.

Keywords: Blunt force, Blunt force trauma, Flying Object, Gas Well, Gas Well Drilling, High Pressure, High Pressure Pipe, Lost Control, Misjudgment, Misjudgment of Hazardous Situation, Pipe, Pipeline, Pump, Pumping Station, Removal, Rupture, Struck By, Valve, Well

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1638173.015	69	M	Fatality	

Accident Summary Nr: 144195.015 - Gas well worker is struck by damaged valve, needs stitches

Accident Summary Nr: 144195.015 -- Report ID: 0625700 -- Event Date: 02/24/2022

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1581172.015	03/03/2022		211130	Texas Petroleum Investment Co.

Abstract: At 6:10 p.m. on February 24, 2022, an employee was working as a production operator for a firm that extracted crude petroleum and natural gas. He was flowing a gas well. An ice plug formed in the line upstream. The blockage caused pressure downstream to drop. The employee began bleeding off the line downstream. This pressure difference between upstream and downstream caused the ice plug to release. The ice plug headed downstream. It struck the ball valve that had been used to bleed the line. The ball valve was blown off. It struck the employee in his right bicep. He suffered a laceration. He went to the hospital, where he received stitches. He was hospitalized overnight for observation.

Keywords: Arm, Compressed By, Flying Object, Gas Well, Gas Well Drilling, Laceration, Pressure, Pressure Release, Struck By, Valve, Well

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1581172.015	32	M	Hospitalized injury	

Accident Summary Nr: 142641.015 - Employee is found dead of natural causes behind retail count

Accident Summary Nr: 142641.015 -- Report ID: 0950631 -- Event Date: 01/09/2022

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1571913.015	01/11/2022		211120	Chevron Corporation

Abstract: At 1:41 p.m. on January 9, 2022, police found the employee, who was a retail cashier at a gas station, sitting on a chair dead behind the counter. The coroner reported no trauma. The employee died due to heart failure.

Keywords: Cardiac Arrest, Cashier, Natural Causes, Retail Clerk, Retail Store

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1571913.015	34	M	Fatality		Cashiers

Accident Summary Nr: 142900.015 - Employee with COVID-19 infection is hospitalized

Accident Summary Nr: 142900.015 -- Report ID: 0950673 -- Event Date: 12/24/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1573436.015	01/19/2022		211120	Chevron U.S.A. Inc.

Abstract: On December 24, 2021, an employee who worked as a Production Operator for an Oil Fields Operations Company was hospitalized with COVID-19. The employee's duties included spending much of his time the field working alone. The employee was tested for COVID-19 and received a positive test result at which time he was quarantined. At 3:11 p.m. on December 25, 2021, the employee's spouse notified the employer that he had been admitted to the hospital due to COVID-19 complications earlier that day. There was already an ongoing inspection at the location for prior COVID-19 hospitalizations. The employer conducted contact tracing and from statements they collected they determined that the employee likely contracted the virus from a family member. The employer was found to have an effective COVID-19 Prevention Program in place.

Keywords: Infectious Disease

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1573436.015	38	M	Hospitalized injury	

Accident Summary Nr: 142416.015 - Two employees with COVID-19 infections are hospitalized

Accident Summary Nr: 142416.015 -- Report ID: 0950673 -- Event Date: 11/19/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1569772.015	12/21/2021		211120	Chevron U.S.A. Inc.

Abstract: Employee #1 and Employee #2 are both production operators who spend the majority of their time out in the field working alone. Prior to the hospitalizations, both employees were quarantined at their homes due to positive COVID-19 test results. Employee #1 and Employee #2 were both hospitalized on 11/19/2021 due to COVID-19 complications. Both employees recovered from their infections.

Keywords: Infectious Disease

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1569772.015	36	M	Hospitalized injury	
2	1569772.015	39	M	Hospitalized injury	

Accident Summary Nr: 142076.015 - Employee with COVID-19 infection dies

Accident Summary Nr: 142076.015 -- Report ID: 0830300 -- Event Date: 11/04/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1566717.015	12/03/2021		211130	Valence Natural Gas Solution

Abstract: An employee was working for a natural gas extraction company when he contracted COVID-19 and subsequently died from his infection at 1:00 p.m. on November 4, 2021.

Keywords: Infectious Disease

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1566717.015	30	M	Fatality		Equipment Operator: Heavy

Accident Summary Nr: 139044.015 - Employee lighting burner on treater unit burns face when fla

Accident Summary Nr: 139044.015 -- Report ID: 0830300 -- Event Date: 09/01/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1552618.015	09/09/2021		211120	William Herbert Hunt Trust Estate

Abstract: At 4:00 p.m. on September 1, 2021, an employee working for a crude petroleum extraction contractor was working near Oilwell Hall 3-161-98H. The employee was attempting to light the burner on the treater unit. A flash fire occurred striking the employee. The employee was hospitalized to treat facial burns.

Keywords: Burn, Burner, Face, Fire, Flammable Liquid, Flammable Vapors, Flash, Flashback, Gas, Ignite, Ignition, Inadequate Maint, Inspecting, Inspection, Insufficient Supervision, Lighting, Misjudgment, Misjudgment of Hazardous Situation, Open Flame, PPE, PPE Hazard Assessment, Petroleum, Protective Clothing, Unsafe Position, Vapor, Wellhead

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1552618.015	32	M	Hospitalized injury	

Accident Summary Nr: 138340.015 - Employee cuts fingertip while operating pump jack, later amp

Accident Summary Nr: 138340.015 -- Report ID: 0729700 -- Event Date: 08/18/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1548893.015	08/20/2021		211130	River Rock Operating, Llc

Abstract: At 9:30 a.m. on August 18, 2021, an employee working for a natural gas extraction operator was operating an Alten D16 Pump Jack. The employee was applying the brake to the belt and pulley system to stop the pump jack head in the down position. The brake was broken so the employee attached bailing wire to brake arm before applying the brake. The brake failed so the employee tried to stop the pump jack by applying pressure to the belt with his right hand. The belt continued to run from the motor to the gear box pulling the employee's hand toward the pulley. The employee pulled his hand away and removed his glove at which time he noticed his pinky fingertip was missing at the nail bed. The employee received medical treatment without hospitalization requiring amputation of the finger to the first knuckle.

Keywords: Amputated, Amputation, Belt, Brake, Brake failure, Caught Between, Defect, Defective, Defective Equipment, Finger, Fingertip, Laceration, Lack of Work Procedures, Lockout, Lockout/Tagout, Machine Guarding, Machine operator, Misjudgment, Misjudgment of Hazardous Situation, Natural Gas, Partial Amputation, Pinch Point, Pinched, Pulled In, Pulley, Pump, Surgical Amputation, Traumatic Amputation, Wrong Equipment

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1548893.015	40	M	Non Hospitalized injury	

Accident Summary Nr: 137249.015 - Employee lacerates face and abdomen when struck by rolling l

Accident Summary Nr: 137249.015 -- Report ID: 0336000 -- Event Date: 07/10/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name

1542381.015	07/16/2021		211130	Kinder Morgan, Inc.
-------------	------------	--	--------	---------------------

Abstract: At 1:00 p.m. on July 10, 2021, an employee working as a mechanic for an energy infrastructure company was guiding a coworker operating a forklift. They were setting a compressor cylinder onto wooden bracing when the compressor rolled when set down. The compressor struck the employee pushing him into another compressor cylinder that was already in storage. The employee was hospitalized to treat a laceration to his groin/abdomen and above his left eye.

Keywords: Abdomen, Bracing, Compressor, Cylinder, Equipment Operator, Eye, Face, Forklift, Groin, Guide, Industrial Truck, Laceration, Loading, Material Handling, Powered Industrial Vehicle, Rolled, Spotter , Spotting, Struck By, Unsafe Position, Unsecured, Unstable Load

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1542381.015	53	M	Hospitalized injury		Specified mechanics and repairers

Accident Summary Nr: 139893.015 - Two employees are burned by ignited gasoline vapors

Accident Summary Nr: 139893.015 -- Report ID: 0418800 -- Event Date: 05/05/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1556451.015	10/06/2021		211120	Jf Acquisition, Inc.

Abstract: At 3:00 p.m. on May 5, 2021, two employees were tasked with emptying a containment sump for 87 octane gasoline at a gas station. They were using a cordless power drill pump to extract the remaining fuel from the sump. However, the drill caused gasoline vapors to ignite, resulting in flash burns to both employees. The employees sustained burns to their faces and arms. Emergency services were called, and both employees were transported to the hospital for admission and treatment.

Keywords: Arm, Burn, Chemical Burn, Face, Flash, Gas, Pump, Vapor

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1556451.015	35	M	Hospitalized injury	
2	1556451.015	35	M	Hospitalized injury	

Accident Summary Nr: 133624.015 - Employee sustains 3rd degree burns from flash fire

Accident Summary Nr: 133624.015 -- Report ID: 0627700 -- Event Date: 02/17/2021

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1516735.015	02/23/2021		211112	Oneok Field Services Company, L.L.C.

Abstract: At 6:15 p.m. on February 17, 2021, employees were attempting to start an adjacent compression machine at a manufacturing facility. During this process, the already running compression machine had excess gas flow into the drain system, causing a flash fire. The employees sustained 3rd degree burns as a result of the fire. Emergency services responded to the incident, and the employees were transported to the hospital for admission and treatment.

Keywords: Automatic Machine, Burn, Fire, Flash, Gas

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1516735.015	30	M	Hospitalized injury	

Accident Summary Nr: 131984.015 - Employee is killed when struck by falling equipment

Accident Summary Nr: 131984.015 -- Report ID: 0627510 -- Event Date: 12/23/2020

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1508011.015	12/23/2020		211111	Endeavor Energy Resources, Lp

Abstract: At approximately 7:15 a.m. on December 23, 2020, an employee was waiting for the equipment to be brought to him for inspection. A gun fell out of a lubricator that was suspended by a crane. The gun hit the ground vertically then toppled over and hit the employee on the head. The employee was killed.

Keywords: Crane, Equipment Failure, Falling Object, Head, Lubricating, Struck By

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1508011.015	24	M	Fatality		Construction Laborer

Accident Summary Nr: 130875.015 - Employee is killed after being pinned beneath ATV

Accident Summary Nr: 130875.015 -- Report ID: 0316400 -- Event Date: 11/02/2020

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1500819.015	11/04/2020		211112	Pillar Energy Llc

Abstract: at 1:30 p.m. on November 2, 2020, an employee had been driving a 2006 Honda Ranger ATV Hurricane while returning from changing a gas meter chart. The employee was found on ground with ATV on top of his chest. He had died from asphyxia after being crushed by the vehicle.

Keywords: ATV, Asphyxiated, Chest, Crushed, Driver, Head, Lack of oxygen, Motor Vehicle, PPE, Pinned, Powered Industrial Vehicle, Run Over, Struck By, Vehicle

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1500819.015	65	M	Fatality	

Accident Summary Nr: 129462.015 - Employee suffers electric shock when contacting electrical o

Accident Summary Nr: 129462.015 -- Report ID: 0626700 -- Event Date: 09/09/2020

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1492552.015	09/10/2020		211111	Energy Transfer Operating, L.P.

Abstract: At 2:15 p.m. on September 9, 2020, Employee #1 opened a floor section of a modular building/trailer to visually inspect a structural board under the flooring that was sagging. As Employee #1 looked inside the floor opening with a flashlight, he made contact with an electrical outlet and was shocked. The outlet was powering a submersible pump. No visual deficiencies were identified with the outlet. Employee #1 was hospitalized to treat an electric shock.

Keywords: Contact, Electric Shock, Floor Opening, Mobile Home, Outlet

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury	Occupation
1	1492552.015	49	M	Hospitalized injury		Electricians

Accident Summary Nr: 128989.015 - Two employees are electrocuted from overhead powerline and a

Accident Summary Nr: 128989.015 -- Report ID: 0653510 -- Event Date: 03/04/2020

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1469807.015	03/05/2020		211111	Concho Recsources

Abstract: At 2:15 p.m. on March 4, 2020, Employee #1 and Employee #2 were relocating tank battery vent piping from storage area to reattachment location. They extended the forklift forks which contacted an overhead powerline. Employee #1 and Employee #2 were killed by the electrical shock.

Keywords: Contact, Electric Shock, Electrocuted, Forklift, Forks, Overhead Power Line, Power Lines, Powered Industrial Vehicle

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1469807.015	24	M	Fatality	
2	1469807.015	29	M	Fatality	

Accident Summary Nr: 122931.015 - Employee suffers spinal fracture when struck by falling tree

Accident Summary Nr: 122931.015 -- Report ID: 0317500 -- Event Date: 01/02/2020

Inspection Nr	Date Opened	SIC	NAICS	Establishment Name
1453774.015	01/03/2020		211111	Dominion Energy Transmission, Inc.

Abstract: At 10:00 a.m. on January 2, 2020, an employee in his late 20s was working for a firm that constructed and operated natural gas pipelines. He and a coworker were at a storage well. There was a group of dead ash trees near the storage well that represented a hazard to employees accessing the storage well. The two employees were removing the dead ash trees. They were using a chain saw and a Bobcat E35 excavator. The employee was operating a chain saw. The employee's coworker was operating a Bobcat E35 excavator. Depending on the tree, they would either fell it manually or push it over with the excavator. The excavator was not equipped with a falling object protection structure (FOPS), even though the manufacturer recommended that a FOPS be used in a situation where there was a chance of falling objects. Once the tree was lying on the ground, it would be cut up with the chain saw, regardless of how it got there. At the time of the incident, the employee's coworker was using the excavator to push over a dead ash tree that the two were felling. The tree being pushed got caught up in a nearby dead ash tree. The dead ash tree fell over and struck the employee as he was walking away. The employee was struck in the head. He suffered a spinal fracture. His back was broken from the T2 through T11 vertebrae, as well as a laceration. The broken back required surgery. He was hospitalized.

Keywords: Back, Broken Bone, Chain Saw, Excavator, Falling Object, Fracture, Gas Well, Head, Laceration, Lodged Tree, Natural Gas, Nerve damage, Pipeline, Pushing, ROPS, Spine, Struck By, Tree, Tree Felling, Vertebra

Employee Details

Employee #	Inspection Nr	Age	Sex	Degree of Injury	Nature of Injury
1	1453774.015	29	M	Hospitalized injury	



U.S. DEPARTMENT OF LABOR

Occupational Safety and Health
Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 1-800-321-OSHA
1-800-321-6742
www.osha.gov

FEDERAL GOVERNMENT

[White House](#)

[Disaster Recovery Assistance](#)

DisasterAssistance.gov

USA.gov

[No Fear Act Data](#)

[U.S. Office of Special Counsel](#)

OCCUPATIONAL SAFETY & HEALTH

[Frequently Asked Questions](#)

[A - Z Index](#)

[Freedom of Information Act - OSHA](#)

[Read the OSHA Newsletter](#)

[Subscribe to the OSHA Newsletter](#)

[OSHA Publications](#)

[Office of Inspector General](#)

ABOUT THE SITE

[Freedom of Information Act](#)

[Disclaimers](#)

[Plug-Ins Used on DOL.gov](#)

[Accessibility Statement](#)

[Privacy & Security Statement](#)

[Important Website Notices](#)

[Site Map](#)

Connect With DOL

