### **Chapter 6 Exercises**

6.1	Add a TP700 Comfort Panel to the Project and configure the PLC Connection	າ2
6.1.1	Add a TP700 Comfort to the Project	3
1)	Add a new TP700Comfort to the project.	3
6.1.2	Define the HMI Connection between the HMI and the S7-1500 PLC	4
1)	Define the data connection between the TP700 and the S7-1500 PLC	4

# 6.1 Add an TP700 to the Project and configure the PLC Connection



## 6.1 Add a TP700 Comfort Panel to the Project and configure the PLC Connection

#### **Description**

Add a TP700 Comfort Panel to the project and configure the data connection to the S7-1500.

#### **Objectives**

- 1. Add a TP700 to the Project
- 2. Configure the Data connection to the PLC.


#### **Prerequisites**

The following prerequisites must be completed before this exercise is started:

 Chapter 5 exercises have been completed, OR the Chapter 6 Seed Project Archive has been retrieved and is open for editing.

#### 6.1.1 Add a TP700 Comfort to the Project.


- 1) Add a new TP700Comfort to the project.
  - 1. With your project open in the Project view, double click on the "Add new device" in the Project tree.
  - 2. In the "Add new device" dialog, select HMI, then select the device TP700 Comfort.
  - 3. Accept the default name "HMI\_1"
  - 4. Note the panel version is version 13.0.1.0
  - 5. Make sure the "Start device wizard" is NOT checked.
  - 6. Click "OK".




7. After a brief delay, the object is added and the default screen, Screen\_1, is opened for editing.

#### 6.1.2 Define the HMI Connection between the HMI and the S7-1500 PLC.

- 1) Define the data connection between the TP700 and the S7-1500 PLC.
  - 1. Open the Devices and networks editor.
  - 2. Select the Network view.
  - 3. Select the Profinet port of the HMI device shown in green.
  - 4. In the Inspector window, change the port's Ethernet address to 192.168.0.7.
  - 5. Back in the editor Work area, select the button labeled "Connections" at the top left of the window.
  - 6. Using the pull down right next to the Connections button, make sure "HMI connection" is selected.
  - 7. In the main window, drag the Profinet port *of the HMI* and drop it on the S7-1500's Profinet IO port. The software will define a connection and highlight it as shown below:



8. Select the highlighted connection. In the Inspector window, change the name of the connection to read "S7-1500 Connection"



9. Save your project.

This Completes the Chapter 6 Exercises.