VEHICLE DAMAGE ASSESSMENT REPORT

AI-Assisted Automatic Insurance Appraisal System

Document No	VD-20261013-231207	**Issue Date**	13.10.2026 23:12
Policy No	POL-2026-004521	**Report Type**	Automated Preliminary Assessment

1. VEHICLE DETAILS

Plate	34 ABC 123	**Make**	BMW
Model	5 Series	**Model Year**	2016
VIN	WBA5A7C50FD000000	**Colour**	White

2. DETECTED DAMAGE

#	Part	Damage Type	Area (%)	Confidence (%)	Status
1	Hood	Dent	14.75	65.3	Probable
2	Front Light	Crack	1.43	29.2	Uncertain

Summary: 2 damage instance(s) detected. Affected parts: Front Light, Hood. Damage types: Crack, Dent. Total damaged area: 16.19%.

3. VISUAL ANALYSIS



Colour key: Scratch | Dent | Crack

4. SYSTEM INFORMATION

Part Detection Model	YOLOv11m-seg (Carparts-Seg)

Damage Detection Model	YOLOv11l-seg (v6, fp32)
Damage Model mAP@50	0.7238
Inference Time	~9 ms/image
Image Resolution	640 x 640 px

IMPORTANT NOTICE: This report was generated automatically by an AI-based image analysis system and constitutes a preliminary assessment. The final damage assessment, repair scope and settlement amount are determined by a qualified claims adjuster. System outputs should be used for reference only, to accelerate the adjuster workflow. Image quality, viewing angle and lighting conditions may affect detection accuracy.