




DIMENSION AND CONVERSIONS		
	mm	in
R1	100	3.94
R2	250	9.84

NOTE:

 REFER TO DIAGRAM 004.

 ANGLE VALUE = 30°.

N_SR_530011_1_6CJM000A_01_01

Figure 002 / 53-00-11-283-004 (SHEET 1) - Pitot Probes and Total Air Temperature Probes - Definition of Areas