




DIMENSIONS AND CONVERSIONS	
mm	in
0.5	0.02
1	0.039
1.5	0.059
2.5	0.098
50	1.969
100	3.937
200	7.874
250	9.843

NOTE:
REFER TO FIGURE 002 TO DETERMINE ON WHICH
AREA THIS DIAGRAM APPLIES.

N_SR_530011_1_6CLM000A_01_01

Diagram 004 / 53-00-11-283-004 (SHEET 1) - Pitot Probes and Total Air Temperature Probes - Limitation Data