Ex.No.-1.1-Design and Draft the given 2D Sketches in modelling software

AIM:


Tosketch the given drawing with dimensions using fusion 360 tool.

REQUIREMENTS:

1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommend 2 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE:

1. Open new file and then select sketch icon.
2. Select the plane for sketching.
3. Use sketching features (line, circle, arc, rectangle, polygon, etc.,) to draw the given sketch
4. Click finish Sketch when the drawing is complete



5. Use sketch modifying features such as (cut, trim, mirror, move, etc.,) to edit and modify the sketch as required..




6. The dimensions of the sketch are successfully measured using the Inspect-Measure tool, and the sketch is verified for dimensional accuracy.




7. After completing all the required sketching and modifications, click the Finish Sketch option to finalize the sketch and exit the sketching environment.




8. The completed sketch is successfully transferred to the Drawing environment and prepared according to the ISO standard.





CREATE DRAWING
Drawing Type
Automatic
Manual
Contents
Destination
Drawing
Create New
Base Document
Standard
ISO
Units
mm
Sheet Size
A3
Width
420mm
Height
297mm
Orientation
Sheet Count
1
OK
Cancel

SKETCH:



OUTPUT:



Result:

Thus, the given sketch was successfully created,modified,measured, and finalizer using Autodesk Fusion 360. The final drawing was prepared with the required dimensions and arranged according to the ISO standard.