Safety Precautions

- Always Call Mark-out Service Before Digging
- Be Aware for Smell of Gas
- No smoking if gas smell is present