Name - Vedika Dalmia USN-1BM19CS187 Program-2

Drive a stepper motor interface ito rotate the motor in clockwise by N steps Introduce suitable delay b/w successive steps. # include (stdio.h) # include (reg 51.h) charxdata port_at_0xe803; charxdata porta_at_0xe800; charidata ace - at - 0x30; delay() unt j for (j=0; j(800; j++) void main () port = 0 x 80; while (1) acc = 0 × 88; porta = acc; delay (); acc = 0 x44 porta = acc; delay (). acc = 0x22; borta = acc, delay (); acc = 0x11; borta = acc; delay ().