CYT2B75CADES 程序下载说明

CYT2B75CADES 程序下载说明


- 1、更换jlink USB驱动
- 2、配置脚本文件
- 3、程序下载


1、更换jlink USB驱动

运行zadig-2.5.exe

Name	Date modified	Туре	Size
AutoFlashUtil_1.0.0.277	2021/7/1 11:13	File folder	
test test	2021/7/29 14:35	File folder	
🕏 AutoFlashUtil_1.0.0.277.zip	2021/6/25 16:00	ZIP 压缩文件	6,235 KB
Cypress_Auto_Flash_Utility_Us	2021/6/25 16:11	PDF File	2,557 KB
Program.bat	2021/7/28 17:18	Windows Bat	1 KB
Readme.txt	2021/6/25 16:29	Text Document	4 KB
RAR test.rar	2021/7/29 14:34	RAR 压缩文件	45 KB
TVII_Program_Test - Copy.bat	2021/7/29 14:34	Windows Bat	1 KB
■ TVII_Program_Test bat	2021/7/29 14:34	Windows Bat	1 KB
🗷 zadig-2.5.exe	2020/4/13 15:50	Application	5,037 KB
■	2021/7/29 14:36	PNG File	117 KB


把jlink接到电脑端,选择菜单上Options->List All Devices,设备下拉列表选择jlink







更新USB驱动为libusbK(v3.0.7.0),选择后单击Replace Driver按钮,耐心等待安装完成

备注:中途杀毒软件提示权限问题,请选择允许执行







2、配置脚本文件

修改TVII_Program_Test.bat 脚本中程序路径

备注:程序路径根据实际存放位置来填写,路径不含中文

```
Elle Edit Farmat Mew Help

SET CTP_PATH=C:\Program Files (x86)\Cypress\Cypress Auto Flash Utility 1.0

::CM4 HEX programming
call "%CYP_PATH%/bin/openocd.exe" -s "%CYP_PATH%/scripts" -f interface/jlink.cfg -c "transport select swd" -f target/traveo2_lm_0A.cfg -c "program D:/test/cm4.hex 0x0 verify exit"
```

3、程序下载

直接双击运行脚本,下载完成后回车关闭窗口

```
D:\YW687\A6W\工具\AutoFlashUtility\AutoFlashUtility>call "C:\Program Files (x86)\Cypress\Cypress Auto Flash Utility 1.0/bin/openocd.exe" -s "C:\Program Files (x86)\Cypress\Cypress Auto Flash Utility 1.0/scripts" -f interface/jlink.cfg -c "transport select swd" -f target/traveo2_1m_0A.cfg -c "program D:/test/cm4.hex 0x0 verify exit" Open On-Chip Debugger 0.10.0+dev-1.0.0.277 (2019-10-11-11:05)
```

```
Licensed under GNU GPL v2
For bug reports, read
       http://openocd.org/doc/doxygen/bugs.html
***********
** traveo2_1m_0A.cfg file is deprecated, please use traveo2_1m_a0.cfg
***********
adapter speed: 1000 kHz
** Test Mode acquire not supported by selected adapter
cortex_m reset_config sysresetreq
adapter_nsrst_delay: 100
Info: J-Link ARM-OB STM32 compiled Aug 22 2012 19:52:04
Info: Hardware version: 7.00
Info : VTarget = 3.300 V
Info : clock speed 1000 kHz
info : SWD DPIDR 0x6ba02477
Info : traveo2.cpu.cm0: hardware has 4 breakpoints, 2 watchpoints
**********
** Use overriden Main Flash size, kb: 1088
** Use overriden Work Flash size, kb: 96
** Silicon: 0xE3DA, Family: 0x101, Rev.: 0x23 (B2)
** Detected Device: CYT2B75CAE
** Flash Boot version 3.1.0.515
** Chip Protection: NORMAL
***********
Info: traveo2.cpu.cm4: hardware has 6 breakpoints, 4 watchpoints
Info : traveo2.cpu.cm4: external reset detected
Info : Listening on port 3333 for gdb connections
Info : Listening on port 3334 for gdb connections
info : SWD DPIDR 0x6ba02477
target halted due to debug-request, current mode: Thread
xPSR: 0x61000000 pc: 0x000000f8 msp: 0x0801f800
** traveo2.cpu.cm4: Ran after reset and before halt...
target halted due to debug-request, current mode: Thread
xPSR: 0x01000000 pc: 0x000001bc msp: 0x0801f800
** Programming Started **
auto erase enabled
Info: Padding image section 0 at 0x1008360c with 500 bytes (bank write end
alignment)
Warn: Adding extra erase range, 0x10083800 .. 0x10087fff
[100%] [################## [ Erasing
[100%] [################### [ Programming ]
wrote 14336 bytes from file D:/test/cm4.hex in 0.721071s (19.416 KiB/s)
** Programming Finished **
** Verify Started **
verified 13836 bytes in 0.066821s (202.208 KiB/s)
** Verified OK **
shutdown command invoked
D:\YW687\A6W\工具\AutoFlashUtility\AutoFlashUtility>PAUSE
Press any key to continue . . .
```

```
C:\WINDOWS\system32\cmd.ex
 Open On-Chip Debugger 0.10.0+dev-1.0.0.277 (2019-10-11-11:05)
Licensed under GNU GPL v2
  For bug reports, read
http://openocd.org/doc/doxygen/bugs.html
  ** traveo2_1m_0A.cfg file is deprecated, please use traveo2_1m_a0.cfg
  adapter speed: 1000 kHz
** Test Mode acquire not supported by selected adapter
 ** Test Mode acquire not supported by selected adapter cortex_m reset_config sysresetreq adapter_nsrst_delay: 100
Info : J-Link ARM-OB STM32 compiled Aug 22 2012 19:52:04
Info : Hardware version: 7.00
Info : VTarget = 3.300 V
Info : clock speed 1000 kHz
Info : SWD DPIDR 0x6ba02477
Info : traveo2.cpu.cm0: hardware has 4 breakpoints, 2 watchpoints
 ***********

** Use overriden Main Flash size, kb: 1088

** Use overriden Work Flash size, kb: 96

** Silicon: 0xE3DA, Family: 0x101, Rev.: 0x23 (B2)

** Detected Device: CYT2B75CAE

** Flash Boot version 3.1.0.515

** Chip Protection: NORMAL
** Programming Finished **

** Verify Started **

verified 13836 bytes in 0.066821s (202.208 KiB/s)

** Verified OK **
  ):\YW687\A6W\工具\AutoFlashUtility\AutoFlashUtility>PAUSE
```