

Lesson 1 Hurdle Tool Assembly

The assembly steps are as follow:

 Place white hurdle accessory at the end of the blue hurdle accessory, as the figure shown below:



2) Install the white one on the the blue one with M3*20 flat head self-tapping screw, as the figure shown below:



3) Install the other white hurdle accessory according to the same method, as the figure shown below:

