## 1

## GATE 2022 BM.38

## EE23BTECH11010 - VENKATESH BANDAWAR\*

**Question:** An input x(t) is applied to a system with a frequency transfer function given by  $H(j\omega)$ as shown below. The magnitude and phase response of the transfer function are shown below. If  $y(t_d) = 0$ for x(t) = u(t), the time  $t_d(>0)$  is.

(Gate 2022 BM.38)




Fig. 1: Graph of y(t)

## **Solution:**

Parameter	Description
x(t) = u(t)	Input signal
y(t)	Output signal
$X(j\omega)$	Fourier Transform of $x(t)$
$Y(j\omega)$	Fourier Transform of $y(t)$
$H(j\omega) = \frac{Y(j\omega)}{X(j\omega)}$	Transfer function

TABLE I: Input Parameters Table

from graph 2

$$\angle H(j\omega) = -2\tan^{-1}\left(\frac{\omega}{a}\right) \tag{1}$$

(2)

At 
$$\omega = 10^4$$
,  $\angle H(j\omega) = -\frac{\pi}{2}$   
 $\implies a = 10^4$ 

$$\angle H(j\omega) = \tan^{-1}\left(\frac{-\omega}{a}\right) - \tan^{-1}\left(\frac{\omega}{a}\right)$$
 (3)

$$H(j\omega) = \frac{e^{j\tan^{-1}\left(\frac{-\omega}{a}\right)}}{e^{j\tan^{-1}\left(\frac{\omega}{a}\right)}} \tag{4}$$

$$=\frac{a-j\omega}{a+j\omega}\tag{5}$$




Fig. 2: Phase of H(f)

Substitute  $j\omega = s$ 

$$u(t) \stackrel{\mathcal{L}}{\longleftrightarrow} \frac{1}{s} \tag{6}$$

$$Y(s) = \frac{1}{s} \frac{a-s}{a+s}$$
(7)  
=  $\frac{1}{s} - \frac{2}{a+s}$  (8)

$$=\frac{1}{s} - \frac{2}{a+s} \tag{8}$$

$$\frac{1}{s} \stackrel{\mathcal{L}^{-1}}{\longleftrightarrow} u(t) \tag{9}$$

$$\frac{1}{a+s} \stackrel{\mathcal{L}^{-1}}{\longleftrightarrow} e^{-at} u(t) \tag{10}$$

$$y(t) = (1 - 2e^{-at})u(t)$$
 (11)

$$y(t_d) = 0 (12)$$

$$t_d = 100 \ln 2\mu s \tag{13}$$

