

FileResetAssemblerDebugHelp

Registers

A02

BC0204

DE0300

HL0000

PSW0000

PC421E

SPFFFF

Int-Reg00

Flag

S1

Z0

AC0

P0

C1

Decimal - Hex Conversion

DecimalHex

00

To HexTo Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

Load me at

1LDA3070

2MOV B,A

3LDA3071

4MOV C,A

5MVI D,00

6LOOP: MOV A,B

7CMP C

8JC EXIT

9SUB C

10MOV B,A

11INR D

12JMP LOOP

13EXIT: MOV A,D

14STA 3072

15MOV A,B

16STA 3073

17HLT

DataStackKeyPadMemoryI/O Ports

Start3070OK

Address (Hex)AddressData

0BFE307014

0BFF30714

0C0030723

0C0130732

0C0230740

0C0330750

0C0430760

0C0530770

0C0630780

0C0730790

0C0830800

0C0930810

0C0A30820

0C0B30830

Line NoAssembler Message

0Program assembled successfully

Simulator Title