

File Edit View Assembly Debug Help

Registers

Register	Value
A	05
BC	05 00
DE	00 00
HL	1F 42
PSW	00 00
PC	42 0E
SP	FF FF
Int-Reg	00

Flag

Flag	Status
S	0
Z	0
AC	0
P	0
C	0

Load me at

```

1 LXI H, 8000
2 MOV A, M
3 INX H
4 MOV B, M
5 CMP B
6 JC SMALL
7 MOV A, B
8
9 SMALL: INX H
10 MOV M, A
11 HLT
        
```

Decimal - Hex Conversion

Decimal Hex

I/O Ports

Memory

Data
Stack
KeyPad
Memory

Start

Address (Hex)	Address	Data
1F40	8000	12
1F41	8001	5
1F42	8002	5
1F43	8003	0
1F44	8004	0
1F45	8005	0
1F46	8006	0
1F47	8007	0
1F48	8008	0
1F49	8009	0
1F4A	8010	0
1F4B	8011	0
1F4C	8012	0
1F4D	8013	0
1F4E	8014	0
1F4F	8015	0

Line No
Assembler Message

0
Program assembled successfully