

DebugHelp

Flag

S0

Z1

AC0

P1

C0

rtion

tex

o Dec

ue

y

Load me at

1LDA 2500H

2MOV B,A; B = number

3

4MVI C,01H; C = 1

5

6LOOP: MOV A,C

7MOV D,A

8

9MOV A,B

10MOV E,A

11

12MVI A,00H

13MOV C,A

14

15MULT: ADD D

16DCR E

17JNZ MULT

18

19MOV C,A

20DCR B

21JNZ LOOP

22

23MOV A,C

24STA 2501H

25

26HLT

DataStackKeyPadMemoryI/O Ports

Start2500OK

Address (Hex)	Address	Data
09C4	2500	4
09C5	2501	24
09C6	2502	0
09C7	2503	0
09C8	2504	0
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0
09CD	2509	0
09CE	2510	0
09CF	2511	0
09D0	2512	0
09D1	2513	0
09D2	2514	0
09D3	2515	0

Line No	Assembler Message
0	Program assembled successfully