

FileEditViewHelp

ResetAssemblerDebugHelp

Registers

A03

BC0306

DE0000

HL080E

PSW0000

PC4210

SPFFFF

st-Reg00

Flag

S0

Z1

AC0

P1

C0

Decimal - Hex Convertnon

Decimal

Hex

0

0

To Hex

To Dec

I/O Ports

-

+

00

Update Port Value

Memory

-

+

00

Update Memory

Load me at

1LDA 2001

2MOV B,A

3LDA 2002

4MOV C,A

5STA 2003

6MOV A,B

7STA 2004

8HLT

9

DataStackKeyPadMemory

Start2001

Address (Hex)AddressData

07D120013

07D220026

07D320036

07D420043

07D520050

07D620060

07D720070

07D820080

07D920090

07DA20100

07DB20110

07DC20120

07DD20130

07DE20140

07DF20150

07E020160

Line NoAssembler Message

0Program assembled successfully