

FileResetAssemblerDebugHelp

Registers

A01

BC1300

DE0000

HL0000

PSW0000

PC420C

SPFFFF

Int-Reg00

Flag

S0

Z0

AC0

P0

C0

Decimal - Hex Conversion

Decimal

Hex

00

00

To Hex

To Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

Load me at

1LDA2050

2MOV B,A

3LDA2051

4SUB B

5STA2052

6HLT

DataStackKeyPadMemoryI/O Ports

Start2050OK

Address (Hex)	Address	Data
0802	2050	19
0803	2051	20
0804	2052	1
0805	2053	0
0806	2054	0
0807	2055	0
0808	2056	0
0809	2057	0
080A	2058	0
080B	2059	0
080C	2060	0
080D	2061	0
080E	2062	0
080F	2063	0

Line NoAssembler Message

0Program assembled successfully

Simulator: Idle

32°C

FNG

10:57 AM