

FileResetAssemblerDebugHelp

Registers

A	0A	S	0
BC	00 00	Z	1
DE	00 00	AC	0
HL	09 C9	P	1
PSW	00 00	C	0
PC	42 15		
SP	FF FF		
Int-Reg	00		

Flag

S	0
Z	1
AC	0
P	1
C	0

Load me at

1 LXI H, 2500

2 MOV C, M

3 INX H

4 MOV A, M

5 DCR C

6 LOOP: INX H

7 CMP M

8 JC NEXT

9 MOV A, M

10 NEXT: DCR C

11 JNZ LOOP

12 STA 2600

13 HLT

Decimal - Hex Conversion

DecimalHex

00

To HexTo Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

DataStackKeyPadMemoryI/O Ports

Start2600OK

Address (Hex)	Address	Data
0A28	2600	10
0A29	2601	0
0A2A	2602	0
0A2B	2603	0
0A2C	2604	0
0A2D	2605	0
0A2E	2606	0
0A2F	2607	0
0A30	2608	0
0A31	2609	0
0A32	2610	0
0A33	2611	0
0A34	2612	0
0A35	2613	0

Line NoAssembler Message

0Program assembled successfully

Simulator: Idle