```
JBR04-P04 | None | None
PREPARED BY | None | CPL | QTM PKR | =G71 | QTM PACKER M/ELMT | =E2+0.515 | CASING COLLAR (m) | 701.21 - 7'
DATE | None | 22/05/2024 | None | None
CLIENT | None | TOTALENERGIES | CASING SHOE | 758.69 | FLOAT SHOE | =F12 | RAT HOLE | =C7-F12 | None | None
FIELD / WELL NAME | None | JOBI RII / JBRO4-P04 | None | None
RIG TYPE / NAME | None | LAND / ZPEB 1501 | TUBULAR DATA: | None 
TOTAL DEPTH | None | 1550 | 2-3/8 4.6# TSH W511 MAKEUP LOSS (m) | 0.057658 | TORQUE (FT.LB) | 550 | 700 | 1000 | Non
DEVIATION | None | 90.480 @ 1300.99m | 4-1/2" 12.6# HSM2 MAKEUP LOSS (m) | 0.8184 | TORQUE (FT.LB) | 4200 | 4650 | 5
DLS | None | 7.45°/30 m @ 252.97m | None | None | TORQUE (FT.LB) | None | None | None | None | None
None | No
ASSY # | ITEM | DESCRIPTION | LENGTH (m) w/o MUL (0.0818) | CUM
                                                                                                                                                                                                                                                                                                                                                                                                         LENGTH (m) | BOTTOM■DEPTH (m) | TOP■DE
1 | WASHDOWN ASSEMBLY | SINGLE VALVE WASH DOWN SHOE, with 2F-3R, Plunger F type DPFV, Cast iron 4.5 12.6# HS
None | None | PUP JOINT , 4.5 12.6 # HSM2-PREMIUM | 2.985 | =E12+D13 | =G13+D13 | =F14 | None | None | None | None
None | None | PBR.2.688 BORE ID, 4FT OAL 4.5 12.6 HSM2-PREMIUM, BOX X PIN 4140(80), | 1.15 | =E13+D14 | =G14+D14 | =
None | None | PUP JOINT , 4.5 12.6 # HSM2-PREMIUM | 1.494 | =E14+D15 | =G15+D15 | =F16 | None | None | None | None
2 | Screen 1 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.629161 | =E15+D16 | =G16+D16 | =F17 | None |
3 | Screen 2 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.796161 | =E16+D17 | =G17+D17 | =F18 | None | None | None
4 | Screen 3 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.778160999999999 | =E17+D18 | =G18+D18 | =F19 | Non
5 | Screen 4 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.801160999999999 | =E18+D19 | =G19+D19 | =F20 | None 
6 | Screen 5 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.801160999999999 | =E19+D20 | =G20+D20 | =F21 | Non
```

```
7 | Screen 6 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.812161 | =E20+D21 | =G21+D21 | =F22 | None | 
8 | Screen 7 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.723161 | =E21+D22 | =G22+D22 | =F23 | None |
9 | Screen 8 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.589160999999999 | =E22+D23 | =G23+D23 | =F24 | None 
 10 | Screen 9 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.800161 | =E23+D24 | =G24+D24 | =F25 | None | None |
 11 | Screen 10 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.805161 | =E24+D25 | =G25+D25 | =F26 | None 
 12 | Screen 11 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.822161 | =E25+D26 | =G26+D26 | =F27 | None | None
13 | Screen 12 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.821161 | =E26+D27 | =G27+D27 | =F28 | None 
 14 | Screen 13 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.648161 | =E27+D28 | =G28+D28 | =F29 | None | None
 15 | Screen 14 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.585161 | =E28+D29 | =G29+D29 | =F30 | None 
 16 | Screen 15 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.736161 | =E29+D30 | =G30+D30 | =F31 | None | None
17 | Screen 16 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.817160999999999 | =E30+D31 | =G31+D31 | =F32 | None | None
 18 | Screen 17 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.808161 | =E31+D32 | =G32+D32 | =F33 | None | None
 19 | Screen 18 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.800161 | =E32+D33 | =G33+D33 | =F34 | None 
20 | Screen 19 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.819161 | =E33+D34 | =G34+D34 | =F35 | None | None
21 | Screen 20 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.810160999999999 | =E34+D35 | =G35+D35 | =F36 | None | None
22 | Screen 21 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.817160999999999 | =E35+D36 | =G36+D36 | =F37 | N
23 | Screen 22 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.798161 | =E36+D37 | =G37+D37 | =F38 | None 
24 | Screen 23 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.544160999999999 | =E37+D38 | =G38+D38 | =F39 | N
 25 | Screen 24 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.806161 | =E38+D39 | =G39+D39 | =F40 | Shale Interval 1050m - 1
 26 | Screen 25 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.798161 | =E39+D40 | =G40+D40 | =F41 | Shale Interva
```

```
27 | Screen 26 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.806161 | =E40+D41 | =G41+D41 | =F42 | Shale Interval 1050m - 1
28 | Screen 27 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.783161 | =E41+D42 | =G42+D42 | =F43 | None | None
29 | Screen 28 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.568161 | =E42+D43 | =G43+D43 | =F44 | None 
30 | Screen 29 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.816161 | =E43+D44 | =G44+D44 | =F45 | None | None
31 | Screen 30 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.798161 | =E44+D45 | =G45+D45 | =F46 | None 
32 | Screen 31 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.765160999999999 | =E45+D46 | =G46+D46 | =F47 | N
33 | Screen 32 | SCREEN 4-1/2" 12.6# HSM2 BOX x PIN | 11.804160999999999 | =E46+D47 | =G47+D47 | =F48 | None | None
34 | Screen 33 | SCREEN W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.514161 | =E47+D48 | =G48+D48 | =F49 | None | None
35 | Blank pipe 1 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.806161 | =E48+D49 | =G49+D49 | =F50 | None | None
36 | Blank pipe 2 | BLANK
                                                                                         4-1/2" 12.6# HSM2 BOX x PIN | 11.809161 | =E49+D50 | =G50+D50 | =F51 | None | None |
37 | Blank pipe 3 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.814161 | =E50+D51 | =G51+D51 | =F52 | None | None
38 | Blank pipe 4 | BLANK
                                                                                         4-1/2" 12.6# HSM2 BOX x PIN | 11.807160999999999 | =E51+D52 | =G52+D52 | =F53 | No
39 | Blank pipe 5 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.80416099999999 | =E52+D53 | =G53+D53 | =F54 | N
40 | Blank pipe 6 | BLANK
                                                                                         4-1/2" 12.6# HSM2 BOX x PIN | 11.818161 | =E53+D54 | =G54+D54 | =F55 | None | None |
41 | Blank pipe 7 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.80716099999999 | =E54+D55 | =G55+D55 | =F56 | N
42 | Blank pipe 8 | BLANK
                                                                                         4-1/2" 12.6# HSM2 BOX x PIN | 11.692160999999999 | =E55+D56 | =G56+D56 | =F57 | No
43 | Blank pipe 9 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.808161 | =E56+D57 | =G57+D57 | =F58 | None | None
44 | Blank pipe 10 | BLANK
                                                                                         4-1/2" 12.6# HSM2 BOX x PIN | 11.815161 | =E57+D58 | =G58+D58 | =F59 | None | None
45 | Blank pipe 11 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.812161 | =E58+D59 | =G59+D59 | =F60 | None | None
46 | Blank pipe 12 | BLANK
                                                                                          4-1/2" 12.6# HSM2 BOX x PIN | 11.813161 | =E59+D60 | =G60+D60 | =F61 | None | None
```

```
47 | Blank pipe 13 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.748161 | =E60+D61 | =G61+D61 | =F62 | None | None
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.813161 | =E61+D62 | =G62+D62 | =F63 | None | None
48 | Blank pipe 14 | BLANK
49 | Blank pipe 15 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.804160999999999 | =E62+D63 | =G63+D63 | =F64 | 1
51 | Swell Packer | SWELL PACKER | 11.476161 | =E63+D64 | =G64+D64 | =F65 | None | None | None | None
50 | Blank pipe 16 | BLANK
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.813161 | =E64+D65 | =G65+D65 | =F66 | None | None
52 | Blank pipe 17 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.80716099999999 | =E65+D66 | =G66+D66 | =F67 | 1
53 | Blank pipe 18 | BLANK
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.813161 | =E66+D67 | =G67+D67 | =F68 | None | None
54 | Blank pipe 19 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.818161 | =E67+D68 | =G68+D68 | =F69 | None | None
55 | Blank pipe 20 | BLANK
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.812161 | =E68+D69 | =G69+D69 | =F70 | None | None
56 | Blank pipe 21 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.810160999999999 | =E69+D70 | =G70+D70 | =F71 | 1
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.811161 | =E70+D71 | =G71+D71 | =F72 | None | None
57 | Blank pipe 22 | BLANK
58 | Blank pipe 23 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.813161 | =E71+D72 | =G72+D72 | =F73 | None | None
59 | Blank pipe 24 | BLANK
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.726161 | =E72+D73 | =G73+D73 | =F74 | None | None
60 | Blank pipe 25 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.726161 | =E73+D74 | =G74+D74 | =F75 | None | None
61 | Blank pipe 26 | BLANK
                                  4-1/2" 12.6# HSM2 BOX x PIN | 11.812161 | =E74+D75 | =G75+D75 | =F76 | None | None
62 | Blank pipe 27 | BLANK W/CTRLZ 4-1/2" 12.6# HSM2 BOX x PIN | 11.58316099999999 | =E75+D76 | =G76+D76 | =F77 | 1
67 | MFIV ASSEMBLY | PUP JOINT, 4-1/2" 12.6PPF HSM2-PREMIUM | 1.485161 | =E76+D77 | =G77+D77 | =F78 | None | None
None | None | CROSSOVER, 13CR(80), 18IN LONG, 4.5 IN 12.6 JFE BEAR BOX X 4.5 IN 12.6 HYEM HSM-2 PIN | 0.375 | =E77
None | None | 7 MFIV-II 3X, 5.500 X 2.940 (13CR X 13CR) (TOTAL GQCP) (HNBR) | 3.196 | =E78+D79 | =G79+D79 | =F80 | No
None | None | CROSSOVER, 18" OAL, 4-1/2" 12.6PPF HSM2-PREMIUM BOX X 4-1/2", 12.6PPF JFE BEAR PIN, 13CR(80) | 0.3
```

```
None | None | PUP JOINT, 4-1/2" 12.6PPF HSM2-PREMIUM (2M) | 1.982 | =E80+D81 | =G81+D81 | =F82 | None | None | None
68 | None | None | 1.381161 | =E81+D82 | =G82+D82 | =F83 | None | None | None | None
None | None | CROSSOVER - 4.937-6 STUB ACME BOX x 4-1/2" 12.6PPF HSM2-PREMIUM PIN, 13CR(80) | 0.376 | =E82+D83
None | None | 5.560 X 4.000 X 123 SBE, 13CR (80), 4.937-6 STUB ACME BOX X PIN | 3.118 | =E83+D84 | =G84+D84 | =F85 | 1
None | None | 5.560 X 4.000 X 123 SBE, 13CR (80), 4.937-6 STUB ACME BOX X PIN | 3.118 | =E84+D85 | =G85+D85 | =F86 | 1
None | None | 7-5/8 X 4.000 QUANTUM (24-29.7), 13CR (80),17-4 (105), NITRILE(90), 4.937-6 STUB ACME | 1.541 | =E85+D86
None | None | 7, 7-5/8 X 4.000 QUANTUM MAX TYPE III SERVICE TOOL, NPS, 4140(125), VITON (ABOVE PACKER ONLY) | 2
None | None | HANDLING PUP JOINT 3.5 IN 15.5 IF BOX X IF PIN | 1.732 | =E87+D88 | =G87 | =F88-D88 | None | None | None
None | None | CROSSOVER,4 IN 14 PPF NOV XT 39 BOX X 3.5 IN 15.5 PPF IF PIN | 0.308 | =E88+D89 | =G88 | =F89-D89 | No
77 | 72 | Drill Pipe 4" 14# $135 XT39 | 9.738 | =E89+D90 | =G89 | =F90-D90 | None | None | None | None
78 | None | None | 9.72 | =E90+D91 | =G90 | =F91-D91 | None | None | None | None
79 | None | HYDROSOLVE SWIVEL | 4.67 | =E91+D92 | =G91 | =F92-D92 | None | None | None | None
80 | 71 | Drill Pipe 4" 14# $135 XT39 | 9.726 | =E92+D93 | =G92 | =F93-D93 | None | None | None | None
81 | None | None | 9.719 | =E93+D94 | =G93 | =F94-D94 | None | None | None | None
82 | 70 | Drill Pipe 4" 14# S135 XT39 | 9.742 | =E94+D95 | =G94 | =F95-D95 | None | None | None | None
83 | None | None | 9.733 | =E95+D96 | =G95 | =F96-D96 | None | None | None | None
```

- 84 | 26 | HWDP 4" 14# S135 XT39 | 9.286 | =E96+D97 | =G96 | =F97-D97 | None | N
- 86 | 25 | HWDP 4" 14# S135 XT39 | 9.369 | =E98+D99 | =G98 | =F99-D99 | None | None | None | None
- 87 | None | None | 9.4 | =E99+D100 | =G99 | =F100-D100 | None | None | None | None

```
88 | 24 | HWDP 4" 14# S135 XT39 | 9.421 | =E100+D101 | =G100 | =F101-D101 | None | None | None | None
89 | None | None | 9.41 | =E101+D102 | =G101 | =F102-D102 | None | None | None | None
90 | 23 | HWDP 4" 14# S135 XT39 | 9.407 | =E102+D103 | =G102 | =F103-D103 | None | None | None | None
91 | None | None | 9.416 | =E103+D104 | =G103 | =F104-D104 | None | None | None | None
92 | 22 | HWDP 4" 14# S135 XT39 | 9.397 | =E104+D105 | =G104 | =F105-D105 | None | None | None | None
93 | None | None | 9.412 | =E105+D106 | =G105 | =F106-D106 | None | None | None | None
94 | 21 | HWDP 4" 14# S135 XT39 | 9.404 | =E106+D107 | =G106 | =F107-D107 | None | None | None | None
95 | None | None | 9.355 | =E107+D108 | =G107 | =F108-D108 | None | None | None | None
96 | 20 | HWDP 4" 14# S135 XT39 | 9.405 | =E108+D109 | =G108 | =F109-D109 | None | None | None | None
97 | None | None | 9.392 | =E109+D110 | =G109 | =F110-D110 | None | None | None | None
98 | 19 | HWDP 4" 14# S135 XT39 | 9.41 | =E110+D111 | =G110 | =F111-D111 | None | None | None | None
99 | None | None | 9.408 | =E111+D112 | =G111 | =F112-D112 | None | None | None | None
100 | 18 | HWDP 4" 14# S135 XT39 | 9.41 | =E112+D113 | =G112 | =F113-D113 | None | None | None | None
101 | None | None | 9.427 | =E113+D114 | =G113 | =F114-D114 | None | None | None | None
102 | 17 | HWDP 4" 14# S135 XT39 | 9.407 | =E114+D115 | =G114 | =F115-D115 | None | None | None | None
103 | None | None | 9.433 | =E115+D116 | =G115 | =F116-D116 | None | None | None | None
104 | 16 | HWDP 4" 14# S135 XT39 | 9.374 | =E116+D117 | =G116 | =F117-D117 | None | None | None | None
105 | None | None | 9.419 | =E117+D118 | =G117 | =F118-D118 | None | None | None | None
106 | 15 | HWDP 4" 14# S135 XT39 | 9.445 | =E118+D119 | =G118 | =F119-D119 | None | None | None | None
```

107 | None | None | 9.413 | =E119+D120 | =G119 | =F120-D120 | None | None | None | None

```
108 | 14 | HWDP 4" 14# S135 XT39 | 9.439 | =E120+D121 | =G120 | =F121-D121 | None | None | None | None
109 | None | None | 9.441 | =E121+D122 | =G121 | =F122-D122 | None | None | None | None
110 | 13 | HWDP 4" 14# S135 XT39 | 9.428 | =E122+D123 | =G122 | =F123-D123 | None | None | None | None
111 | None | None | 9.412 | =E123+D124 | =G123 | =F124-D124 | None | None | None | None
112 | 12 | HWDP 4" 14# S135 XT39 | 9.397 | =E124+D125 | =G124 | =F125-D125 | None | None | None | None
113 | None | None | 9.41 | =E125+D126 | =G125 | =F126-D126 | None | None | None | None
114 | 11 | HWDP 4" 14# S135 XT39 | 9.35 | =E126+D127 | =G126 | =F127-D127 | None | None | None | None
115 | None | None | 9.422 | =E127+D128 | =G127 | =F128-D128 | None | None | None | None
116 | 10 | HWDP 4" 14# S135 XT39 | 9.437 | =E128+D129 | =G128 | =F129-D129 | None | None | None | None
117 | None | None | 9.412 | =E129+D130 | =G129 | =F130-D130 | None | None | None | None
118 | 9 | HWDP 4" 14# S135 XT39 | 9.402 | =E130+D131 | =G130 | =F131-D131 | None | None | None | None
119 | None | None | 9.394 | =E131+D132 | =G131 | =F132-D132 | None | None | None | None
120 | 8 | HWDP 4" 14# S135 XT39 | 9.413 | =E132+D133 | =G132 | =F133-D133 | None | None | None | None
121 | None | None | 9.409 | =E133+D134 | =G133 | =F134-D134 | None | None | None | None
122 | 7 | HWDP 4" 14# S135 XT39 | 9.42 | =E134+D135 | =G134 | =F135-D135 | None | None | None | None
123 | None | None | 9.421 | =E135+D136 | =G135 | =F136-D136 | None | None | None | None
124 | 6 | HWDP 4" 14# S135 XT39 | 9.437 | =E136+D137 | =G136 | =F137-D137 | None | None | None | None
125 | None | None | 9.397 | =E137+D138 | =G137 | =F138-D138 | None | None | None | None
126 | 5 | HWDP 4" 14# S135 XT39 | 9.344 | =E138+D139 | =G138 | =F139-D139 | None | None | None | None
```

127 | None | None | 9.414 | =E139+D140 | =G139 | =F140-D140 | None | None | None | None

```
128 | 4 | HWDP 4" 14# S135 XT39 | 9.414 | =E140+D141 | =G140 | =F141-D141 | None | None | None | None
129 | None | None | 9.403 | =E141+D142 | =G141 | =F142-D142 | None | None | None | None
130 | 3 | HWDP 4" 14# S135 XT39 | 9.412 | =E142+D143 | =G142 | =F143-D143 | None | None | None | None
131 | None | None | 9.425 | =E143+D144 | =G143 | =F144-D144 | None | None | None | None
132 | 9 | SHWDP 4" 14# S135 XT39 | 9.449 | =E144+D145 | =G144 | =F145-D145 | None | None | None | None
133 | None | None | 9.406 | =E145+D146 | =G145 | =F146-D146 | None | None | None | None
134 | 8 | SHWDP 4" 14# S135 XT39 | 9.36 | =E146+D147 | =G146 | =F147-D147 | None | None | None | None
135 | None | None | 9.397 | =E147+D148 | =G147 | =F148-D148 | None | None | None | None
136 | 7 | SHWDP 4" 14# S135 XT39 | 9.408 | =E148+D149 | =G148 | =F149-D149 | None | None | None | None
137 | None | None | 9.448 | =E149+D150 | =G149 | =F150-D150 | None | None | None | None
138 | 6 | SHWDP 4" 14# S135 XT39 | 9.37 | =E150+D151 | =G150 | =F151-D151 | None | None | None | None
139 | None | None | 9.409 | =E151+D152 | =G151 | =F152-D152 | None | None | None | None
140 | 5 | SHWDP 4" 14# S135 XT39 | 9.447 | =E152+D153 | =G152 | =F153-D153 | None | None | None | None
141 | None | None | 9.347 | =E153+D154 | =G153 | =F154-D154 | None | None | None | None
142 | 4 | SHWDP 4" 14# S135 XT39 | 9.444 | =E154+D155 | =G154 | =F155-D155 | None | None | None | None
143 | None | None | 9.443 | =E155+D156 | =G155 | =F156-D156 | None | None | None | None
144 | 3 | SHWDP 4" 14# S135 XT39 | 9.45 | =E156+D157 | =G156 | =F157-D157 | None | None | None | None
145 | None | None | 9.415 | =E157+D158 | =G157 | =F158-D158 | None | None | None | None
146 | 2 | SHWDP 4" 14# S135 XT39 | 9.405 | =E158+D159 | =G158 | =F159-D159 | None | None | None | None
```

147 | None | None | 9.347 | =E159+D160 | =G159 | =F160-D160 | None | None | None | None

- 148 | 1 | SHWDP 4" 14# S135 XT39 | 9.438 | =E160+D161 | =G160 | =F161-D161 | None | None | None
- 149 | None | None | 9.42 | =E161+D162 | =G161 | =F162-D162 | None | None | None | None
- 150 | 69 | Drill Pipe 4" 14# S135 XT39 | 9.71 | =E162+D163 | =G162 | =F163-D163 | None | None | None | None
- 151 | None | None | 9.739 | =E163+D164 | =G163 | =F164-D164 | None | None | None | None
- 152 | None | Single 4" 14# S135 XT40 | 9.7 | =E164+D165 | =G164 | =F165-D165 | None | None | None | None

None | None