

## 9535 E COUNTY LINE RD

CENTENNIAL CO 80112

PROPERTY TYPE

Merchandising 2212

Com...

YEAR BUILT

-

BUILDING AREA

129,605 SF

ROOF SQUARES

1,296

PARCEL ID

207534323002

Image unavailable

### OVERALL ROOF CONDITION SCORE

**74** /100  
FAIR

### RISK LEVEL

**MODERATE**



### ROOF INFORMATION

|                  |                                  |
|------------------|----------------------------------|
| ROOF TYPE        | Low-slope membrane               |
| ROOF SYSTEM      | Unknown membrane                 |
| POSSIBLE TYPES   | -                                |
| VISIBLE CONCERNS | None prominent from aerial image |
| ROOF AGE EST.    | Unknown                          |
| ROOF AREA        | 129,605 SF                       |
| ROOF PITCH       | Low slope                        |
| CONFIDENCE       | Pending AI                       |

### SELECTED AERIAL IMAGE - ARAPAHOE COUNTY AERIALS AS OF 03/01/2024

#### ROOF CONDITION BREAKDOWN

|                     |                        |        |
|---------------------|------------------------|--------|
| Membrane Condition  | <div><div></div></div> | 74/100 |
| Ponding             | <div><div></div></div> | 62/100 |
| Flashing & Seals    | <div><div></div></div> | 66/100 |
| Penetrations        | <div><div></div></div> | 72/100 |
| Overall Maintenance | <div><div></div></div> | 74/100 |

#### AERIAL ROOF OBSERVATIONS

- Aerial imagery is available, but AI analysis was not run for this report.
- Large low-slope roof area should be reviewed for membrane wear, drainage, staining, and penetration condition.
- Use the selected aerial image as the primary visual reference for field validation.

#### BUILDING CHARACTERISTICS

|                   |              |
|-------------------|--------------|
| LAND AREA         | 34.39 acres  |
| STORIES           | -            |
| CONSTRUCTION TYPE | Commercial   |
| TAX DISTRICT      | -            |
| LAND VALUE        | \$29,980,160 |

#### REPORT SUMMARY

This preliminary report was generated from parcel/building data and aerial imagery. AI roof observations were not requested or no API key was available, so condition values are conservative placeholders for layout and workflow validation.

##### Recommendation:

Run AI image analysis and perform field inspection before final assessment.

#### ROOF REPLACEMENT COST ESTIMATE

| TOTAL PROJECT COST | COST COMPONENT              | COST               |
|--------------------|-----------------------------|--------------------|
| <b>\$3,390,791</b> | Tear Off & Disposal         | \$412,792          |
|                    | Roof Membrane               | \$825,584          |
|                    | Insulation                  | \$501,247          |
|                    | Flashing/Edging             | \$324,337          |
|                    | Labor                       | \$884,554          |
|                    | <b>Replacement Subtotal</b> | <b>\$2,948,514</b> |
|                    | <b>Contingency (15%)</b>    | <b>\$442,277</b>   |
|                    | <b>Total Project Cost</b>   | <b>\$3,390,791</b> |

This replacement cost is an estimate derived from aerial imagery, public property records, and commercial roofing cost models. It is intended for budgeting purposes only and should not be considered a contractor quote or engineering assessment.

#### ROOF OVERLAY COST ESTIMATE

| TOTAL PROJECT COST | COST COMPONENT            | COST               |
|--------------------|---------------------------|--------------------|
| <b>\$1,318,731</b> | <b>Overlay Subtotal</b>   | <b>\$1,198,846</b> |
|                    | <b>Contingency (10%)</b>  | <b>\$119,885</b>   |
|                    | <b>Total Project Cost</b> | <b>\$1,318,731</b> |

This overlay cost is an estimate derived from aerial imagery, public property records, and commercial roofing cost models. It is intended for budgeting purposes only and should not be considered a contractor quote or engineering assessment.