

4902 E SMITH RD

DENVER CO 80216

PROPERTY TYPE
INDUSTRIAL-WAREHOUSE 398: WAREHOU...

YEAR BUILT
1973

BUILDING AREA
29,295 SF

ROOF SQUARES
293

PARCEL ID
0119400256000



OVERALL ROOF CONDITION SCORE

61 /100
FAIR

RISK LEVEL

MODERATE



ROOF INFORMATION

ROOF TYPE	Low-slope commercial roof
ROOF SYSTEM	Primary: Single-ply membrane roof, likely white TPO/PVC or coated membrane; Secondary: PVC or Coated Roof
VISIBLE CONCERNS	dark staining/color variation; possible ponding; many penetrations/units
ROOF AGE EST.	Approximate roof age unknown; building date 1973 suggests the roof may be a later replacement rather than original
ROOF AREA	29,295 SF
ROOF PITCH	Low-slope / near-flat
CONFIDENCE	74%

SELECTED AERIAL IMAGE - DENVER GIS AS OF 03/11/2018 - 03/17/2018

ROOF CONDITION BREAKDOWN

Membrane Condition		60/100
Ponding		56/100
Flashing & Seals		58/100
Penetrations		54/100
Overall Maintenance		59/100

AERIAL ROOF OBSERVATIONS

1. The dominant roof field appears to be a white reflective low-slope membrane roof.
2. Visible seam lines and rooftop patches/objects indicate a commercial membrane assembly with multiple penetrations.
3. Localized dark staining/discoloration is present in several areas of the roof surface.
4. No obvious tree overhang or heavy debris accumulation is visible in the aerial image.
5. The roof appears serviceable from aerial view, but the visible staining and penetrations elevate leak risk.

BUILDING CHARACTERISTICS

LAND AREA	1.66 acres
STORIES	-
CONSTRUCTION TYPE	398: WAREHOUSE
TAX DISTRICT	DENV
LAND VALUE	\$1,085,900

REPORT SUMMARY

Aerial imagery dated 03/11/2018 - 03/17/2018 shows a low-slope commercial roof with a bright white membrane or coated membrane surface and multiple visible penetrations. The roof is generally reflective and appears serviceable, but several dark stained/discolored areas and irregular patches suggest possible ponding, localized moisture retention, prior repairs, or leak potential. Flashing and seal risk is elevated by the number of rooftop details. Because the image is 201

Recommendation:

Recommend a qualified commercial roof-coating contractor perform an onsite inspection, moisture testing where warranted, confirmation of the existing system and warranty eligibility, required repairs/preparation, and a reliable project-price proposal. Based on aerial evidence, the roof appears to be a candidate for evaluation of silicone roof restoration if the substrate is sound and dry enough for restoration; a properly designed silicone system can reduce tear-off waste, cost, and disruption, create a seamless monolithic white reflective cool-roof surface, withstand ponding water when properly designed and installed, improve resistance to UV exposure and hail, and may qualify for a manufacturer warranty of up to 20 years. If onsite investigation finds widespread moisture, failed insulation, structural/deck deterioration, or an incompatible substrate, then overlay or replacement evaluation is more appropriate.

ROOF REPAIR OPTIONS

Roof Replacement Cost Estimate

TOTAL PROJECT COST	COST SUMMARY
\$825,387	Replacement Subtotal \$717,728
\$24.50 / SF	Contingency (15%) \$107,659
	Total Project Cost \$825,387

Roof Overlay Cost Estimate

TOTAL PROJECT COST	COST SUMMARY
\$314,189	Overlay Subtotal \$285,626
\$9.75 / SF	Contingency (10%) \$28,563
	Total Project Cost \$314,189

Roof Coating Estimate

TOTAL PROJECT COST	WARRANTY TERM	BUDGETARY COST RANGE
\$102,532 - \$175,770	10 Year Warranty	\$102,532 - \$117,180
\$3.50 - \$6.00 / SF	15 Year Warranty	\$131,828 - \$146,475
	20 Year Warranty	\$161,122 - \$175,770

Cost estimates are derived from publicly available information and proprietary commercial roofing analysis models and are intended for preliminary budgeting and planning purposes only. Roof-area measurements do not include the vertical surface area of parapet walls. They should not be considered a contractor quote, engineering assessment, or guarantee of actual project costs. Estimates do not include additional repairs or unforeseen conditions that may be identified during an on-site inspection.