

GHL SYSTEMS PHILIPPINES, INC.
6F One Corporate Plaza, 845 Arnaiz Avenue, Legaspi Village 1224 Makati City, | Philippines

ACTIVITY REPORT

	Helpdesk T	el# 7449445									01074	127	⁷ 5		
Merchant Name	CALTEX GULANG Clie					ent PayMaya Philippines				Con	rol / SR # 01179784				
Address	VD PUROK		Date Visited		8/17/20 10:08 am			GHL	. Area	s	South Luzon				
PAGKAKAISA GULANG-GULANG LUCENA QUEZON , Philippines					Time Arriv	ved	ed 10:08 am			Time	e Started	10	0:10 a	m	
Contact Person	• •		Time Completed		10:23 am			Time Departure			10:23 am				
TERMINAL PROF	ILE					REQU	JEST TY	/PE	Insta	allation Re	quest				
Application Name				Par	tner Merc	hant ID (I	ant ID (MID)		Terminal ID (TID)						
DEVICE APPLICA	ATION & C	OMMUNICA	ATION DET	AILS											
CURRENT APP VERSION			NEW APP VER	RSION				Receipt C							
Site Telephone Number			Telephone Prov	vider				ı		<u>. I</u>					
Primary Dialing Number				IP				ort	1	ip Enable	\Box	Yes	\Box	No	
Secondary Dialing Number			Secondary HOS	ST IP		P	Port		Γip Adjust	匸	Yes		No		
Last Four Digit Validation Yes		☐ No	Manual Entry E	nable	Yes	Yes No			-Authorization (for hotels)					No	
PROBLEM REPORTED Hardware			е	PROBLEM FO			UND Hardware,								
connection,Checked thermal papers *printed details				Resolution: Ch Chip Reader,T							5 rolls of				
PARTICULARS			MERCHANT ORIENTATION			TEST TRANSACTION									
Fixed wiring connections Re-initialized terminal Checked paramaters, TID/MID Tested EMV / Chip Reader Tested Magnetic Stripe Printed telium, & system configuration Printed hardware configuration No Problem Found			Sale V EMV C Chip C Detail A Reprin Receip Loyalty Provid Negati	ert Port & Any	Settle Insta Settle Debi	Settle Installment Sale, Void, Settle Debit Sale, Bal Inq Loyalty Earn, Redem, Bal Inq EPurse, Reload, Sale, Void, Settle				Success Rate: Process Time: Success Rate: Process Time:					
Negation beisternen			ACTU	REP	REPLACEMENT S/N (i			y)	REASON						
PAX ADVINOR OF THE CONTROL OF THE CO)13052											
REMARKS Phone line Actual terminal serial is invalid.							CSE REPOR			ORT Working					
Recharge/Reinsert battery							RE			JLE ON					
Reprint hardware configuration Replace territing prime that the above equipment(s) and its accessories, are in correct order & in good working condition Replace Sim Card							GHL SYSTEMS PHILIPPINES INC.								
Replace batter	\Rightarrow			Signat	Signature		Mes								
Merchant Name	Solve through thone Merchant Name Genevieve Etrish Mar			0		Representative		re	Joren-PB Habal		ag				
Contact Number 0427175968		Position	Cashier		Contac	Contact Number		91774	3009	Position CSE					