

## Hazard Assessment Form

Name:

Date: 12-01-2025

Department: Stud Planer

Workstation: Planer Slowdown Belt #1

Task: **Planer Slowdown Belt #1**

Description: Employees will stop Planer outfeed belt, slowdown belts, and slowdown brushes. Use a pike pole or picaroon from the catwalk to straighten or increase the space between the boards. If the condition cannot be fixed using a tool the machine will be locked out and fixed by hand.

### Hazards

- Splinters
- Back strain
- Bending and stooping
- Twisting

### Chemicals

- N/A

### PPE

- Safety Glasses
- Gloves
- Hearing Protection

Are there valves to isolate? Yes  No

Are there lockout tagout procedures to follow? Yes  No

Are there confined spaces present? Yes  No

What is the noise level? 94 decibels

Other: