

Hazard Assessment Form

Name:

Date: 12-01-2025

Department: Stud Planer

Workstation: Accumulation #3

Task: **Accumulation #3 Upset Condition**

Description: Employees will stop the chains, use a pike pole or picaroon from the catwalk to straighten or increase the space between the boards. If the condition cannot be fixed using a tool shut down the outfeed and follow lock out tagout procedures to fix the problem by hand.

Hazards

- Splinters
- Back strain
- Bending and stooping
- Twisting

Chemicals

- N/A

PPE

- Safety Glasses
- Gloves
- Hearing Protection

Are there valves to isolate? Yes No

Are there lockout tagout procedures to follow? Yes No

Are there confined spaces present? Yes No

What is the noise level? 94 decibels

Other: