

| Hazard Assessment Form | |
|---|---|
| Name: | Date: 12-01-2025 |
| Department: Stud Planer | Workstation: Planer Tier Separator Transfer |
| Task: Planer Tier Separator Transfer Upset Condition | |
| Description: Employees will stop the chains, use a pike pole or picaroon from the catwalk to straighten or increase the space between the boards. If the condition cannot be fixed using a tool the machine will be locked out and fixed by hand. | |
| Hazards <ul style="list-style-type: none">• Splinters• Back strain• Bending and stooping• Twisting | |
| Chemicals <ul style="list-style-type: none">• N/A | |
| PPE <ul style="list-style-type: none">• Safety Glasses• Gloves• Hearing Protection | |
| Are there valves to isolate? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | |
| Are there lockout tagout procedures to follow? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | |
| Are there confined spaces present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | |
| What is the noise level? 94 decibels | |
| Other: | |