

## Hazard Assessment Form

Name:	Date: 12-01-2025
Department: Stud Planer	Workstation: Planer Infeed #2
Task: <b>Planer Infeed #2 Upset Condition</b>	
Description: Employees will stop the chains, use a pike pole or picaroon from the catwalk to straighten or increase the space between the boards. If the condition cannot be fixed using a tool the machine will be locked out and fixed by hand.	
<b>Hazards</b> <ul style="list-style-type: none"><li>• Splinters</li><li>• Back strain</li><li>• Bending and stooping</li><li>• Twisting</li></ul>	
<b>Chemicals</b> <ul style="list-style-type: none"><li>• N/A</li></ul>	
<b>PPE</b> <ul style="list-style-type: none"><li>• Safety Glasses</li><li>• Gloves</li><li>• Hearing Protection</li></ul>	
Are there valves to isolate? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Are there lockout tagout procedures to follow? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Are there confined spaces present? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
What is the noise level? 94 decibels	
Other:	