

## Hazard Assessment Form

Name:

Date: 12-01-2025

Department: Stud Planer

Workstation: Planer Floor Chains

Task: **Planer Floor Chains Upset Condition**

Description: Employee will use pike pole to remove boards that are causing loads to go sideways. The employee must lock out and tagout floor chains and engage bin arm lock.

### Hazards

- Splinters
- Back strain
- Bending and stooping
- Twisting

### Chemicals

- N/A

### PPE

- Safety Glasses
- Gloves
- Hearing Protection

Are there valves to isolate? Yes  No

Are there lockout tagout procedures to follow? Yes  No

Are there confined spaces present? Yes  No

What is the noise level? 94 decibels

Other: