## Sparse Elements distribution Cluster 0 PE1 PE2 PE3 PE4 PE5 PE6 PE7

g,0

u,0

f,o

r,0

h,0

v,0

i.0

w,0

k,0

x,0

Cycle 0

Cycle 1

**a**,0

**C**,0

0,0

e,0

q,0


## Dense Elements distribution Cluster 0

5,7

8,10

9,11

u,14



PF2 PE3 PE4 PE5 PE6 PE7

4,6