



Microcontroller




ANAREF – Silicon bug CHIP003–161
VDDANA as the DAC Reference non-functional.

RESET – Silicon bug HIP003–159
Internal pull-up non-functional.


Power




Button



USB




PWR_FLAG → +5V
PWR_FLAG →
PWR_FLAG → Shield




Source connected to a legacy device port.
The CC pins are pulled-down to GND
Rd (5.1 kΩ ± 20%) to indicate that
VBUS should be supplied by the host.

Orientation Sensor



Accelerometer + Gyroscope + Sensor Hub



Magnetometer

Mechanical / Production

V2 ICON101
axis ICON102
Revision INFO101
1 2 INFO102

SWB101
Button-bottom
H101 2mm
H102 2mm
FID101
FID102
FID103

V2 axis
Versio Duo 1/1
Orientation Sensor 2026-08-20