



Microcontroller




ANAREF - Silicon bug CHIP003-161
VDDANA as the DAC Reference non-functional.

RESET - Silicon bug HIP003-159
Internal pull-up non-functional.


Power




Button



USB




PWR_FLAG ◇ → +5V
PWR_FLAG ◇ → Shield
PWR_FLAG ◇ → Shield




Source connected to a legacy device port.

The CC pins are pulled-down to GND
Rd (5.1 kΩ ± 20%) to indicate that
VBUS should be supplied by the host.

Orientation Sensor



Accelerometer + Gyroscope + Sensor Hub



Magnetometer

Mechanical / Production

V2
ICON101
axis
ICON102
Revision
INFO101
1 2 3 4
INFO102

SWB101
Button-bottom
H101 2mm
H102 2mm
FID101
FID102
FID103

V2 axis
Versio Duo
Orientation Sensor
axis
1/1
2026-01-14 (2026-05-19)