



Microcontroller




Revision 2





ANAREF - Silicon bug CHIP003-161
VDDANA as the DAC Reference non-functional.

RESET - Silicon bug HIP003-159
Internal pull-up non-functional.


Power +3V3




Button



USB




PWR_FLAG ◇ → +5V
PWR_FLAG ◇ →
PWR_FLAG ◇ → Shield




Source connected to a legacy device port.

The CC pins are pulled-down to GND
Rd (5.1 kΩ ± 20%) to indicate that
VBUS should be supplied by the host.

DMX Out



MIDI In



Mechanical / Production

ICON102

V2

ICON104

dmx

INFO102

Revision

SWB101

Button-bottom

INFO101

1 2 3 4

H101
2mm

H102
2mm

H103
2mm

H104
2mm

ICON101

ICON103


FID101


FID102

FID103

V2 dmx
Versio Duo
MIDI to DMX Bridge

Revision: 2026-01-06
Id: 1/4
Sheet: Root
Updated: 2026-03-14





MIDI In

Revision: 3
Id: 3/4
Sheet: MIDI In
Updated: 2025-09-19

