




1. Baseplate onto the board [1, 2]




2. Screws into the board [3]



3. Servos into the posts [4]




4. Servo screws and nuts [5, 6]



5. Servo pinions [7, 8]




6. Mounting plate on the hinge [9]




7. Hinge screws and nuts [10, 11]




8. Stepper [12, 13]




9. Stepper pinion [14]




10. Tap-collar base [6, 15-18]




11. Auger over the plate [19]




12. Front bracket on the tube [20]




13. Tap collar on the tube [21]




14. Auger onto the plate [19-21]




15. Rear bracket on the tube [20]




16. Bracket screws and clamps [5, 6, 22]




17. Tap-collar clamp [6, 22]



18. Solenoid [23, 24]



19. Auger cap [25]



Numbers in brackets are the item numbers in Fig. S1.