

OWNER: Z MAGIC CARPET, LLC		OPERATOR: HOMEGROWN MUSIC		
ADDRESS: 101 GARDNER PARK		ADDRESS: 200 PARKADE COURT		
PEACHTREE CITY GA 30269		PEACHTREE CITY GA 30269		
OFFICE: 4049413480		OFFICE:		
FAX:		FAX:		
ANALYST: STEPHEN CHEN		+1-514-636-2195 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL: SCHEN@CAMPSYSTEMS.COM		+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

AIRCRAFT	SERIAL/REGNO: 9175/N117TP	MODEL: BD-700-1A10	MANUFACTURER: BOMBARDIER AVIATION		
CERTIFICATION DATE: 07-OCT-2005		LAST ACTUALS:			
		8918.6	A/C HRS	as of 19-JUN-2026	
		4707	AFL	as of 19-JUN-2026	
		9672	APH	as of 19-JUN-2026	
		8394	APS	as of 19-JUN-2026	

APU	SERIAL / PART: P-299/WE3800714-1		MODEL:	RE220 (GX)		MANUFACTURER: HONEYWELL	
INSTALLED ON: 07-OCT-2005			LAST ACTUALS:				
0	APU HRS	0 A/C HRS	9672	APU HRS	as of 19-JUN-2026		
0	APUS		8394	APUS	as of 19-JUN-2026		

ENGINE NO. 1	SERIAL / PART: 12471/BR710	MODEL: BR700-710A2-20 (CIMMS)	MANUFACTURER: ROLLS-ROYCE DERBY PLC		
INSTALLED ON: 07-OCT-2005		LAST ACTUALS:			
0	ENG. HRS	0	A/C HRS		
0	ENC	8918.6	ENG. HRS	as of 19-JUN-2026	
		4707	ENC	as of 19-JUN-2026	

ENGINE NO. 2	SERIAL / PART: 12472/BR710		MODEL:	BR700-710A2-20 (CIMMS)		MANUFACTURER: ROLLS-ROYCE DERBY PLC	
INSTALLED ON: 07-OCT-2005			LAST ACTUALS:				
0	ENG. HRS	0 A/C HRS	8918.6	ENG. HRS	as of 19-JUN-2026		
0	ENC		4707	ENC	as of 19-JUN-2026		

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
112219-MRIP-MRBR	REVIEW AIRCRAFT ANNUAL UTILIZATION (HOURS) FOR PROGRAM SELECTION (MRIP OR MRBR) PER TLMC AND MPD REV 17							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
AC76-160609	APU - REVIEW RE220 (GX) CMM REV 6							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	APUS								
PROC. REF: RCF AC76PROC. REF: RCF AC76									
CAMP CODE CHANGE - NOTIFICATION LETTER- NAR	REVIEW AND ACKNOWLEDGE THIS NOTIFICATION LETTER AND RETURNING IT TO CAMP (NO APPROVAL REQ. OPERATORS)							Service	ATA:00
	MOS/MSC		-						
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
EC76-160515	NO. 1 ENGINE - REVIEW BR700-710A2-20 TLM REV 54							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC76PROC. REF: RCF EC76									
EC76-160515	NO. 2 ENGINE - REVIEW BR700-710A2-20 TLM REV 54							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC76PROC. REF: RCF EC76									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
EC76-220707		NO. 1 ENGINE - REVIEW BR700-710A2-20 EMM REV 70						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC76PROC. REF: RCF EC76									
EC76-220707		NO. 2 ENGINE - REVIEW BR700-710A2-20 EMM REV 70						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC76PROC. REF: RCF EC76									
GXRS-160729		REVIEW BOMBARDIER GLOBAL EXPRESS XRS - TLMC REV. 14, DATED JULY 29/2016						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-160729 (MPD)		REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 14, DATED JULY 29/2016						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-171113		REVIEW TLMC BD-700-1A10 TIME LIMITS/MAINTENANCE CHECKS REV 15						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
GXRS-171206-TR-5-2-11 REVIEW TLMC _TEMPORARY REVISION NO. 5-2-11 DATED DEC 06/2017									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-180503-MPD ^S REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 16, DATED MAY 03/2018									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-180503-TLMC REVIEW BOMBARDIER GLOBAL EXPRESS XRS TLMC REV 16 DATED MAY 03/2018									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-180504-TR5-2-12 REVIEW BOMBARDIER GLOBAL EXPRESS XRS TR5-2-12 DATED MAY 04/2018									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-191122 (MPD) REVIEW GLOBAL EXPRESS XRS MPD REV 17 DATED NOV 22 2019									Service ATA:00
	MOS/MSC	07-Oct-05	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF GXRSPROC. REF: RCF GXRS									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
GXRS-191122 (TLMC)		REVIEW TIME LIMITS / MAINTENANCE CHECKS - GLOBAL EXPRESS XRS (TLMC), REVISION 17, DATED NOV. 22ND, 2019						Service	ATA:00
	MOS/MSC	07-Oct-05	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-200817-MPD		REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 18, DATED AUG 17/2020						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-200817-TLMC		REVIEW BOMBARDIER GLOBAL EXPRESS XRS - TLMC REV. 18, DATED AUG 17/2020						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-200911-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM FOR TLMC REV 18 AND MPD REV 18, DATED AUG 17/2020						Service	ATA:00
	MOS/MSC	07-Oct-05	-					REQUIREMENT CHANGE FORMS	
	HRS	0							
	AFL	0							
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-201209-TR		REVIEW BOMBARDIER GLOBAL EXPRESS XRS TLMC TR 5-2-13 DATED 09 DEC. 2020						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
GXRS-210519-MPD		REVIEW GLOBAL XRS MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 19 DATED MAY 19, 2021						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-210519-TLMC		GLOBAL XRS TIME LIMITS/MAINTENANCE CHECKS (TLMC) REVISION 19 DATED MAY 19, 2021						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-220817		REVIEW GLOBAL EXPRESS XRS TIME LIMITS/MAINTENANCE CHECKS TR 5-2-14 AND MAINTENANCE PLANNING DOCUMENT TR-83 DATED AUG 17, 2022						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF 00PROC. REF: RCF 00									
GXRS-230331-TRS		REVIEW GLOBAL EXPRESS XRS TIME LIMITS/MAINTENANCE CHECKS (TLMC) TR 5-2-15 AND MAINTENANCE PLANNING DOCUMENT (MPD) TR-84 DATED MAR 31, 2023						Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF -PROC. REF: RCF -									
ATA 01 - LIMITATIONS									
01-CUS-002 ^U		FAA AIRCRAFT RE-REGISTRATION						Service	ATA:01
	MOS/MSC	07-Nov-23	DUE		31-Dec-28 (M)		920 d	CUSTOMER CODE	
	HRS	8080.9							
	AFL	4296							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE11682	HRS	8252.8		TSN 0					
WC#: 72.225	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE11357	HRS	8252.8		TSN 0					
WC#: 72.270	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE11356	HRS	8252.8		TSN 0					
WC#: 72.275	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE11359	HRS	8252.8		TSN 0					
WC#: 72.280	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE11692	HRS	8252.8		TSN 0					
WC#: 72.285	ENC	4411	10000	TSN 0	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113608	HRS	8252.8		TSN 0					
WC#: 72.290	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116835	HRS	8252.8		TSN 0					
WC#: 72.295	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113604	HRS	8252.8		TSN 0					
WC#: 72.300	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113709	HRS	8252.8		TSN 0					
WC#: 72.305	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116849	HRS	8252.8		TSN 0					
WC#: 72.310	ENC	4411	10000	TSN 0	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113605	HRS	8252.8		TSN 0					
WC#: 72.315	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113705	HRS	8252.8		TSN 0					
WC#: 72.230	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116949	HRS	8252.8		TSN 0					
WC#: 72.320	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116818	HRS	8252.8		TSN 0					
WC#: 72.325	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116955	HRS	8252.8		TSN 0					
WC#: 72.330	ENC	4411	10000	TSN 0	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113523	HRS	8252.8		TSN 0					
WC#: 72.335	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113615	HRS	8252.8		TSN 0					
WC#: 72.340	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113613	HRS	8252.8		TSN 0					
WC#: 72.235	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116969	HRS	8252.8		TSN 0					
WC#: 72.240	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116867	HRS	8252.8		TSN 0					
WC#: 72.245	ENC	4411	10000	TSN 0	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116905	HRS	8252.8		TSN 0					
WC#: 72.250	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116942	HRS	8252.8		TSN 0					
WC#: 72.255	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE113568	HRS	8252.8		TSN 0					
WC#: 72.260	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	01-Jun-24		TSN 2				LIFE LIMIT	
SN:202542RGE116394	HRS	8252.8		TSN 0					
WC#: 72.265	ENC	4411	10000	TSN 0	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117011	HRS	8641.1		TSN 388.3					
WC#: 72.225	ENC	4580	10000	TSN 169	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117001	HRS	8641.1		TSN 388.3					
WC#: 72.270	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116516	HRS	8641.1		TSN 388.3					
WC#: 72.275	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116994	HRS	8641.1		TSN 388.3					
WC#: 72.280	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117000	HRS	8641.1		TSN 388.3					
WC#: 72.285	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116976	HRS	8641.1		TSN 388.3					
WC#: 72.290	ENC	4580	10000	TSN 169	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117007	HRS	8641.1		TSN 388.3					
WC#: 72.295	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116996	HRS	8641.1		TSN 388.3					
WC#: 72.300	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117002	HRS	8641.1		TSN 388.3					
WC#: 72.305	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117003	HRS	8641.1		TSN 388.3					
WC#: 72.310	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116887	HRS	8641.1		TSN 388.3					
WC#: 72.315	ENC	4580	10000	TSN 169	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE11652	HRS	8641.1		TSN 388.3					
WC#: 72.230	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116890	HRS	8641.1		TSN 388.3					
WC#: 72.320	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116982	HRS	8641.1		TSN 388.3					
WC#: 72.325	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116999	HRS	8641.1		TSN 388.3					
WC#: 72.330	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117004	HRS	8641.1		TSN 388.3					
WC#: 72.335	ENC	4580	10000	TSN 169	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117012	HRS	8641.1		TSN 388.3					
WC#: 72.340	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116723	HRS	8641.1		TSN 388.3					
WC#: 72.235	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116983	HRS	8641.1		TSN 388.3					
WC#: 72.240	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116948	HRS	8641.1		TSN 388.3					
WC#: 72.245	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE117025	HRS	8641.1		TSN 388.3					
WC#: 72.250	ENC	4580	10000	TSN 169	(14411) 14411		9704		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116958	HRS	8641.1		TSN 388.3					
WC#: 72.255	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116973	HRS	8641.1		TSN 388.3					
WC#: 72.260	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-003	NO. 2 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS	26-Feb-25		TSN 10				LIFE LIMIT	
SN:202542RGE116817	HRS	8641.1		TSN 388.3					
WC#: 72.265	ENC	4580	10000	TSN 169	(14411) 14411		9704		
05-00-03-870-004	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 27				LIFE LIMIT	
SN:200027LRE59867	HRS	8641.1		TSN 866.5					
WC#: 72.100	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 27				LIFE LIMIT	
SN:200027LRE59866	HRS	8641.1		TSN 866.5					
WC#: 72.145	ENC	4580	9700	TSN 446	(13834) 13834		9127		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35117	HRS	0		TSN 0					
WC#: 72.150	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 46				LIFE LIMIT	
SN:200027LRE56573	HRS	8641.1		TSN 866.5					
WC#: 72.155	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 46				LIFE LIMIT	
SN:200027LRE56583	HRS	8641.1		TSN 866.5					
WC#: 72.160	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 46				LIFE LIMIT	
SN:200027LRE56570	HRS	8641.1		TSN 866.5					
WC#: 72.165	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35111	HRS	8641.1		TSN 8641.1					
WC#: 72.170	ENC	4580	6300	TSN 4580	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004		NO. 1 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35086	HRS	0		TSN 0					
WC#: 72.175	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 27				LIFE LIMIT	
SN:200027LRE59868	HRS	8641.1		TSN 866.5					
WC#: 72.180	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004		NO. 1 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35327	HRS	0		TSN 0					
WC#: 72.185	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35116	HRS	0		TSN 0					
WC#: 72.190	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 26				LIFE LIMIT	
SN:200027LRE60116	HRS	8641.1		TSN 866.5					
WC#: 72.105	ENC	4580	9700	TSN 446	(13834) 13834		9127		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 27				LIFE LIMIT	
SN:200027LRE56571	HRS	8641.1		TSN 866.5					
WC#: 72.195	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 25				LIFE LIMIT	
SN:200027LRE60418	HRS	8641.1		TSN 866.5					
WC#: 72.200	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 46				LIFE LIMIT	
SN:200027LRE56575	HRS	8641.1		TSN 866.5					
WC#: 72.205	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35188	HRS	8641.1		TSN 8641.1					
WC#: 72.210	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25						LIFE LIMIT	
SN:200027LRE60426	HRS	8641.1							
WC#: 72.215	ENC	4580	9700	TSN 4580	(9700) 9700		4993		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004		NO. 1 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35082	HRS	0		TSN 0					
WC#: 72.110	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35084	HRS	0		TSN 0					
WC#: 72.115	ENC	0	6300	TSN 0	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 46				LIFE LIMIT	
SN:200027LRE56574	HRS	8641.1		TSN 866.5					
WC#: 72.120	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004		NO. 1 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25						LIFE LIMIT	
SN:HLAH35119	HRS	8641.1							
WC#: 72.125	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 1 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:HLAH35121	HRS	0		TSN 0					
WC#: 72.130	ENC	0	6300	TSN 0	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 27				LIFE LIMIT	
SN:200027LRE59869	HRS	8641.1		TSN 866.5					
WC#: 72.135	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 26				LIFE LIMIT	
SN:200027LRE60086	HRS	8641.1		TSN 866.5					
WC#: 72.140	ENC	4580	9700	TSN 446	(13834) 13834		9127		
05-00-03-870-004	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34992	HRS	8641.1		TSN 8641.1					
WC#: 72.100	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 30				LIFE LIMIT	
SN:200027LRE56576	HRS	8641.1		TSN 873					
WC#: 72.145	ENC	4580	9700	TSN 450	(13830) 13830		9123		
05-00-03-870-004	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34990	HRS	8641.1		TSN 8641.1					
WC#: 72.150	ENC	4580	6300	TSN 4580	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004		NO. 2 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 30				LIFE LIMIT	
SN:200027LRE56584	HRS	8641.1		TSN 873					
WC#: 72.155	ENC	4580	6300	TSN 450	(10430) 10430		5723		
05-00-03-870-004		NO. 2 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34988	HRS	8641.1		TSN 8641.1					
WC#: 72.160	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25						LIFE LIMIT	
SN:HLAH35063	HRS	8641.1							
WC#: 72.165	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35020	HRS	8641.1		TSN 8641.1					
WC#: 72.170	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34994	HRS	8641.1		TSN 8641.1					
WC#: 72.175	ENC	4580	6300	TSN 4580	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004		NO. 2 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35037	HRS	8641.1		TSN 8641.1					
WC#: 72.180	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35017	HRS	8641.1		TSN 8641.1					
WC#: 72.185	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34981	HRS	8641.1		TSN 8641.1					
WC#: 72.190	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004		NO. 2 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 268				LIFE LIMIT	
SN:GLAH02213	HRS	8641.1		TSN 6183.2					
WC#: 72.105	ENC	4580	6300	TSN 3295	(7585) 7585		2878		
05-00-03-870-004		NO. 2 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER						Component	ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35000	HRS	8641.1		TSN 8641.1					
WC#: 72.195	ENC	4580	6300	TSN 4580	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35050	HRS	8641.1		TSN 8641.1					
WC#: 72.200	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 30				LIFE LIMIT	
SN:200027LRE56580	HRS	8641.1		TSN 873					
WC#: 72.205	ENC	4580	9700	TSN 450	(13830) 13830		9123		
05-00-03-870-004	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35060	HRS	8641.1		TSN 8641.1					
WC#: 72.210	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS	26-Feb-25		TSN 30				LIFE LIMIT	
SN:200027LRE56579	HRS	8641.1		TSN 873					
WC#: 72.215	ENC	4580	9700	TSN 450	(13830) 13830		9123		
05-00-03-870-004	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 159				LIFE LIMIT	
SN:HLAH102454	HRS	8641.1		TSN 873					
WC#: 72.110	ENC	4580	6300	TSN 450	(10430) 10430		5723		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35021	HRS	8641.1		TSN 8641.1					
WC#: 72.115	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH34997	HRS	8641.1		TSN 8641.1					
WC#: 72.120	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35023	HRS	8641.1		TSN 8641.1					
WC#: 72.125	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35045	HRS	8641.1		TSN 8641.1					
WC#: 72.130	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-004	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35014	HRS	8641.1		TSN 8641.1					
WC#: 72.135	ENC	4580	6300	TSN 4580	(6300) 6300		1593		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS	26-Feb-25		TSN 232				LIFE LIMIT	
SN:HLAH35012	HRS	8641.1		TSN 8641.1					
WC#: 72.140	ENC	4580	6300	TSN 4580	(6300) 6300		1593		
05-00-03-870-005	NO. 1 ENGINE - INTERMEDIATE CASE								Component ATA:05
PN:BRR22752	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:00714	HRS	0		TSN 0					
WC#: 72.350	ENC	0	20000	TSN 0	(20000) 20000	20000	15293		
05-00-03-870-005	NO. 2 ENGINE - INTERMEDIATE CASE								Component ATA:05
PN:BRR22752	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:00708	HRS	0		TSN 0					
WC#: 72.350	ENC	0	20000	TSN 0	(20000) 20000	20000	15293		
05-00-03-870-006	NO. 1 ENGINE - REAR BEARING SUPPORT STRUCTURE								Component ATA:05
PN:BRR23504	MOS/MSC	07-Oct-05	O/C						
SN:00824	HRS	0							
WC#: 72.355	ENC	0							
05-00-03-870-006	NO. 2 ENGINE - REAR BEARING SUPPORT STRUCTURE								Component ATA:05
PN:BRR23504	MOS/MSC	07-Oct-05	O/C						
SN:00827	HRS	0							
WC#: 72.355	ENC	0							
05-00-03-870-007	NO. 1 ENGINE - NO. 4 STUB SHAFT								Component ATA:05
PN:BRR24545	MOS/MSC	07-Oct-05	O/C						
SN:279	HRS	0							
WC#: 72.465	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-007		NO. 2 ENGINE - NO. 4 STUB SHAFT						Component	ATA:05
PN:BRR24545	MOS/MSC	07-Oct-05	O/C						
SN:288	HRS	0							
WC#: 72.465	ENC	0							
05-00-04-870-001		NO. 1 ENGINE - NOSE CONE FAIRING						Component	ATA:05
PN:BRR24368	MOS/MSC	07-Oct-05	O/C						
SN:BA81470	HRS	0							
WC#: 72.420	ENC	0							
05-00-04-870-001		NO. 2 ENGINE - NOSE CONE FAIRING						Component	ATA:05
PN:BRR24368	MOS/MSC	07-Oct-05	O/C						
SN:BA81456	HRS	0							
WC#: 72.420	ENC	0							
05-00-04-870-002		NO. 1 ENGINE - NO. 1 STAGE 4 AIR PIPE						Component	ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.430	ENC	0		TSN 0					
05-00-04-870-002		NO. 1 ENGINE - NO. 2 STAGE 4 AIR PIPE						Component	ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.435	ENC	0		TSN 0					
05-00-04-870-002		NO. 1 ENGINE - NO. 3 STAGE 4 AIR PIPE						Component	ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.440	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-04-870-002	NO. 1 ENGINE - NO. 4 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.445	ENC	0		TSN 0					
05-00-04-870-002	NO. 2 ENGINE - NO. 1 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.430	ENC	0		TSN 0					
05-00-04-870-002	NO. 2 ENGINE - NO. 2 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.435	ENC	0		TSN 0					
05-00-04-870-002	NO. 2 ENGINE - NO. 3 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.440	ENC	0		TSN 0					
05-00-04-870-002	NO. 2 ENGINE - NO. 4 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.445	ENC	0		TSN 0					
05-000-1000H	1000 HOUR CHECK								Package ATA:05
	MOS	14-Aug-25						RECOMMENDED	
	HRS	8645	1000 (+50/-50)	Adj 50	9695	9745	776.4 (+50)		
	AFL	4582							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									

PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-000-1500H		1500 HOUR CHECK						Package	ATA:05
	MOS	16-Jun-24						RECOMMENDED	
	HRS	8280.9	1500 (+50/-50)	Adj 50	9830.9	9880.9	912.3 (+50)		
	AFL	4430							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:5
05-000-1800L		1800L CHECK						Package	ATA:05
	MOS	24-Jun-20							
	HRS	6911.6							
	AFL	3586	1800 (+50/-50)	Adj 14	5400	5450	693 (+50)		
PROC. REF: MPD SECTION 2.3.1PROC. REF: MPD SECTION 2.3.1									PKG:74
05-000-2250H		2250 HOUR CHECK						Package	ATA:05
	MOS	24-Jun-20						RECOMMENDED	
	HRS	6911.6	2250 (+50/-50)	Adj 50	9211.6	9261.6	293 (+50)		
	AFL	3586							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:6
05-000-3000H		3000 HOUR CHECK						Package	ATA:05
	MOS	14-Aug-25						RECOMMENDED	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
	AFL	4582							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:8
05-000-3750L		3750L CHECK						Package	ATA:05
	MOS	24-Jun-20							
	HRS	6911.6							
	AFL	3586	3750 (+50/-50)		7336	7386	2629 (+50)		
PROC. REF: MPD SECTION 2.3.1PROC. REF: MPD SECTION 2.3.1									PKG:75

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-000-4500H		4500 HOUR CHECK						Package	ATA:05
	MOS	14-Aug-25						RECOMMENDED	
	HRS	8645	4500 (+50/-50)	Adj 50	13195	13245	4276.4 (+50)		
	AFL	4582							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:10
05-000-450L		450L CHECK						Package	ATA:05
	MOS	14-Aug-25							
	HRS	8645							
	AFL	4582	450 (+50/-50)	Adj 50	5082	5132	375 (+50)		
PROC. REF: MPD SECTION 2.3.1PROC. REF: MPD SECTION 2.3.1									PKG:58
05-000-500H		500 HOUR CHECK						Package	ATA:05
	MOS	13-Nov-24						RECOMMENDED	
	HRS	8623.4	500 (+50/-50)	Adj -10	9113.4	9163.4	194.8 (+50)		
	AFL	4570							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:2
05-000-7500L		7500L CHECK						Package	ATA:05
	MOS								
	HRS								
	AFL	0	7500 (+50/-50)		7500	7550	2793 (+50)		
PROC. REF: GENERIC NO REF, MPD SECTION 2.3.1PROC. REF: GENERIC NO REF, MPD SECTION 2.3.1									PKG:76
05-000-750H		750 HOUR CHECK						Package	ATA:05
	MOS	01-Jun-24						RECOMMENDED	
	HRS	8251.3	750 (+50/-50)	Adj 50	9051.3	9101.3	132.7 (+50)		
	AFL	4407							
PROC. REF: MPD SECTION 2.1.1PROC. REF: MPD SECTION 2.1.1									PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-000-900L		900L CHECK							Package ATA:05
	MOS	14-Feb-23							
	HRS	7761.3							
	AFL	4124	900 (+50/-50)	Adj 50	5074	5124	367 (+50)		
PROC. REF: MPD SECTION 2.3.1PROC. REF: MPD SECTION 2.3.1									PKG:60
05-001-120M		120 MONTH CHECK							Package ATA:05
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 21d	04-Sep-35	04-Dec-35	3358 d (+91)	RECOMMENDED	
	HRS	8645							
	AFL	4582							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:38
05-001-15M		15 MONTH CHECK							Package ATA:05
	MOS	14-Aug-25	15 (+3m/-3m)	Adj 20d	04-Dec-26	04-Mar-27	162 d (+90)	RECOMMENDED	
	HRS	8645							
	AFL	4582							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:31
05-001-180M		180 MONTH CHECK							Package ATA:05
	MOS	25-Jun-20	180 (+3m/-3m)	Adj 92d	25-Sep-35	25-Dec-35	3379 d (+91)	RECOMMENDED	
	HRS	6911.6							
	AFL	3586							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:52
05-001-240M/120M		240 MONTH (T)/120 MONTH (R) CHECK							Package ATA:05
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 54d	07-Oct-35	07-Jan-36	3391 d (+92)		
	HRS	8645							
	AFL	4582							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:56

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-001-30M		30 MONTH CHECK						Package	ATA:05
	MOS	14-Aug-25	30 (+3m/-3m)	Adj 19d	04-Mar-28	04-Jun-28	618 d (+92)	RECOMMENDED	
	HRS	8645							
	AFL	4582							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:32
05-001-60M		60 MONTH CHECK						Package	ATA:05
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 19d	02-Sep-30	02-Dec-30	1530 d (+91)	RECOMMENDED	
	HRS	8645							
	AFL	4582							
PROC. REF: MPD SECTION 2.2.1PROC. REF: MPD SECTION 2.2.1									PKG:34
05-10-01-870-002		NO. 1 ENGINE - LP COMPRESSOR (FAN) DISC						Component	ATA:05
PN:KH22509	MOS	14-Aug-25		TSN 0				LIFE LIMIT	
SN:RRSU02231B	HRS	8646.2		TSN 0					
WC#: 72.220	ENC	4583	4800	TSN 0	(9383) 9383	9383	4676		
05-10-01-870-002		NO. 2 ENGINE - LP COMPRESSOR (FAN) DISC						Component	ATA:05
PN:KH22509	MOS	14-Aug-25		TSN 0				LIFE LIMIT	
SN:RRSU02456A	HRS	8646.2		TSN 0					
WC#: 72.220	ENC	4583	4800	TSN 0	(9383) 9383	9383	4676		
05-10-01-870-003		NO. 1 ENGINE - FAN SHAFT						Component	ATA:05
PN:BRR23914	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:CL17962	HRS	0		TSN 0					
WC#: 72.345	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-003		NO. 2 ENGINE - FAN SHAFT						Component	ATA:05
PN:BRR23914	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:CL17964	HRS	0		TSN 0					
WC#: 72.345	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-01-870-004		NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK						Component	ATA:05
PN:BRR24382	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:1956	HRS	0		TSN 0					
WC#: 72.405	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		
05-10-01-870-004		NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK						Component	ATA:05
PN:BRR24382	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:1959	HRS	0		TSN 0					
WC#: 72.405	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		
05-10-01-870-005		NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK						Component	ATA:05
PN:BRR24357	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:3092	HRS	0		TSN 0					
WC#: 72.410	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		
05-10-01-870-005		NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK						Component	ATA:05
PN:BRR24357	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:3095	HRS	0		TSN 0					
WC#: 72.410	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-006		NO. 1 ENGINE - CURVIC RING						Component	ATA:05
PN:BRH20340	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6169	HRS	0		TSN 0					
WC#: 72.450	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		
05-10-01-870-006		NO. 2 ENGINE - CURVIC RING						Component	ATA:05
PN:BRR20340	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6167	HRS	0		TSN 0					
WC#: 72.450	ENC	0	15000	TSN 0	(15000) 15000	15000	10293		
05-10-01-870-007		NO. 1 ENGINE - HP TURBINE ROTOR STAGE 1 DISK						Component	ATA:05
PN:BRR23952	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:LDRQA00374	HRS	0		TSN 0					
WC#: 72.455	ENC	0	6200	TSN 0	(6200) 6200	6200	1493		
05-10-01-870-007		NO. 2 ENGINE - HP TURBINE ROTOR STAGE 1 DISK						Component	ATA:05
PN:BRR23952	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:LDRQA00375	HRS	0		TSN 0					
WC#: 72.455	ENC	0	6200	TSN 0	(6200) 6200	6200	1493		
05-10-01-870-008		NO. 1 ENGINE - HP TURBINE ROTOR STAGE 2 DISK						Component	ATA:05
PN:BRR22008	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:LDRQA00431	HRS	0		TSN 0					
WC#: 72.460	ENC	0	10500	TSN 0	(10500) 10500	10500	5793		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-008		NO. 2 ENGINE - HP TURBINE ROTOR STAGE 2 DISK						Component	ATA:05
PN:BRR22008	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:LDRQA00306	HRS	0		TSN 0					
WC#: 72.460	ENC	0	10500	TSN 0	(10500) 10500	10500	5793		
05-10-01-870-009		NO. 1 ENGINE - LP TURBINE ROTOR STAGE 1 DISK						Component	ATA:05
PN:BRR15535	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6183	HRS	0		TSN 0					
WC#: 72.470	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-01-870-009		NO. 2 ENGINE - LP TURBINE ROTOR STAGE 1 DISK						Component	ATA:05
PN:BRR15535	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6185	HRS	0		TSN 0					
WC#: 72.470	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-01-870-010		NO. 1 ENGINE - LP TURBINE ROTOR STAGE 2 DISK						Component	ATA:05
PN:BRR11896	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6183	HRS	0		TSN 0					
WC#: 72.475	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-01-870-010		NO. 2 ENGINE - LP TURBINE ROTOR STAGE 2 DISK						Component	ATA:05
PN:BRR11896	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:6173	HRS	0		TSN 0					
WC#: 72.475	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-011		NO. 1 ENGINE - LP TURBINE ROTOR SHAFT						Component	ATA:05
PN:BRR19612	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:SBAN685	HRS	0		TSN 0					
WC#: 72.485	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-01-870-011		NO. 2 ENGINE - LP TURBINE ROTOR SHAFT						Component	ATA:05
PN:BRR19612	MOS	07-Oct-05		TSN 0				LIFE LIMIT	
SN:SBAN684	HRS	0		TSN 0					
WC#: 72.485	ENC	0	25000	TSN 0	(25000) 25000	25000	20293		
05-10-05-870-001		NO. 1 ENGINE - FUEL PUMP VESPEL COUPLING						Component	ATA:05
PN:39504901	MOS	08-Jul-20		TSN 0					
SN:NSN	HRS	6911.6	5000	TSN 0	(11911.6) 11911.6		2993		
	ENC	3586		TSN 0					
05-10-05-870-001		NO. 2 ENGINE - FUEL PUMP VESPEL COUPLING						Component	ATA:05
PN:39504901	MOS	31-May-24		TSN 6					
SN:N/A	HRS	8252.8	5000	TSN 0	(13252.8) 13252.8		4334.2		
	ENC	4411		TSN 0					
05-10-05-CA		AIRCRAFT LIMIT OF VALIDITY (LOV) (AWL)						Service	ATA:05
	MOS	EFF						AIRWORTHINESS	
	HRS	EFF	58000		58000 *		49081.4		
	AFL	EFF	15000		15000 *		10293		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
1000APU		APU - 1000 HOURS APU						Package	ATA:05
	MOS	14-Aug-25							
	HRS	9615	1000 (+50/-50)	Adj 50	10665	10715	993 (+50)		
	APUS	8333							
									PKG:1000
1500APU		APU - 1500 HOUR APU						Package	ATA:05
	MOS	31-May-24							
	HRS	9293	1500 (+50/-50)		10793	10843	1121 (+50)		
	APUS	8017							
									PKG:1500
750APU		APU - 750 HOUR APU						Package	ATA:05
	MOS	16-May-24						RECOMMENDED	
	HRS	9274	750 (+50/-50)		10024	10074	352 (+50)		
	APUS	8001							
									PKG:750
BR710-05-10-01-870-002		NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK						Service	ATA:05
PN:KH22509	MOS/MSC	14-Aug-25	N/A						
SN:RRSU02231B	HRS	8646.2							
WC#: 72.505	ENC	4583							
BR710-05-10-01-870-002		NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK						Service	ATA:05
PN:KH22509	MOS/MSC	14-Aug-25	N/A						
SN:RRSU02456A	HRS	8646.2							
WC#: 72.505	ENC	4583							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 11 - PLACARDS AND MARKINGS									
11-30-50-601	U ^S	GENERAL VISUAL INSPECTION OF CABIN PLACARDS-INTERNAL						Service	ATA:11
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
11-30-60-601	U ^S	GENERAL VISUAL INSPECTION OF CABIN PLACARDS MODIFICATION - INTERNAL						Service	ATA:11
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
ATA 21 - AIR CONDITIONING									
21-21-00-201	S	OPERATIONAL TEST OF THE RECIRC SWITCH						Service	ATA:21
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 21.005	AFL	4582							
PKG:4									
PROC. REF: AMM 21-21-00-710-802PROC. REF: AMM 21-21-00-710-802									
21-21-05-900-801-01	LH TRIM DUCT							Component	ATA:21
PN:GG438-2066-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00566	HRS	0		TSN 0					
WC#: 21.075	AFL	0		TSN 0					
PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801									
21-21-05-900-801-02	RH TRIM DUCT							Component	ATA:21
PN:GG438-2066-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00568	HRS	0		TSN 0					
WC#: 21.075	AFL	0		TSN 0					
PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801									
21-21-05-900-801-03	CENTER TRIM DUCT							Component	ATA:21
PN:GG438-2066-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00567	HRS	0		TSN 0					
WC#: 21.075	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801

21-21-05-900-803-01	MIX MANIFOLD							Component	ATA:21
PN:GG431-2027-9	MOS/MSC	27-Apr-15	O/C	TSN 0					
SN:00837	HRS	4228.4		TSN 0					
WC#: 21.080	AFL	2192		TSN 0					
PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801PROC. REF: AMM 21-21-05-000-801, AMM 21-21-05-400-801									

21-21-09-900-801-01	LH (MIX MANIFOLD) TEMPERATURE SENSOR							Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04596	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-09-000-801, AMM 21-21-09-400-801PROC. REF: AMM 21-21-09-000-801, AMM 21-21-09-400-801									

21-21-09-900-801-02	RH (MIX MANIFOLD) TEMPERATURE SENSOR							Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04476	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-09-000-801, AMM 21-21-09-400-801PROC. REF: AMM 21-21-09-000-801, AMM 21-21-09-400-801									

21-21-17-201 ^S	OPERATIONAL TEST OF THE BULKHEAD CHECK VALVES							Service	ATA:21
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 21.010	AFL	4582							
PROC. REF: AMM 21-21-17-710-801PROC. REF: AMM 21-21-17-710-801									
									PKG:8

21-21-17-900-801-01	LH BULKHEAD CHECK VALVE							Component	ATA:21
PN:GG436-2029-1	MOS/MSC	05-May-15	O/C	TSN 1					
SN:03087	HRS	4228.4		TSN 0					
WC#: 21.085	AFL	2192		TSN 0					
PROC. REF: AMM 21-21-17-000-801, AMM 21-21-17-400-801PROC. REF: AMM 21-21-17-000-801, AMM 21-21-17-400-801									

21-21-17-900-801-02	RH BULKHEAD CHECK VALVE							Component	ATA:21
PN:GG436-2029-1	MOS/MSC	05-May-15	O/C	TSN 1					
SN:03088	HRS	4228.4		TSN 0					
WC#: 21.085	AFL	2192		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
PROC. REF: AMM 21-21-17-000-801, AMM 21-21-17-400-801PROC. REF: AMM 21-21-17-000-801, AMM 21-21-17-400-801									
21-21-21-900-801-01		LH RECIRCULATION FAN						Component	ATA:21
PN:GG433-2030-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0491	HRS	0	TSN 0						
WC#: 21.090	AFL	0	TSN 0						
PROC. REF: AMM 21-21-21-000-801, AMM 21-21-21-400-801PROC. REF: AMM 21-21-21-000-801, AMM 21-21-21-400-801									
21-21-21-900-801-02		RH RECIRCULATION FAN						Component	ATA:21
PN:GG433-2030-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0505	HRS	0	TSN 0						
WC#: 21.090	AFL	0	TSN 0						
PROC. REF: AMM 21-21-21-000-801, AMM 21-21-21-400-801PROC. REF: AMM 21-21-21-000-801, AMM 21-21-21-400-801									
21-21-25-201 ^S		DISCARD THE RECIRCULATION FILTERS						Service	ATA:21
	MOS	14-Aug-25	1000 (+50/-50)						
	HRS	8645							
WC#: 21.015	AFL	4582							
PKG:4									
PROC. REF: AMM 21-21-25-961-801PROC. REF: AMM 21-21-25-961-801									
21-21-25-900-801-01		LH RECIRCULATION FILTER						Component	ATA:21
PN:GG431-2031-1	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:12211	HRS	8645	TSN 0						
WC#: 21.095	AFL	4582	TSN 0						
PROC. REF: AMM 21-21-25-000-801, AMM 21-21-25-400-801PROC. REF: AMM 21-21-25-000-801, AMM 21-21-25-400-801									
21-21-25-900-801-02		RH RECIRCULATION FILTER						Component	ATA:21
PN:GG431-2031-1	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:12214	HRS	8645	TSN 0						
WC#: 21.095	AFL	4582	TSN 0						
PROC. REF: AMM 21-21-25-000-801, AMM 21-21-25-400-801PROC. REF: AMM 21-21-25-000-801, AMM 21-21-25-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-21-50-BDL-9001	U S	RESTORE THE CABIN AIR CONDITIONING FILTERS							Service ATA:21
	MOS	14-Aug-25						STLMC	
	HRS	8645	1000						
	AFL	4582							
PKG:4									
21-31-00-101		OPERATIONAL TEST OF THE EMERGENCY DEPRESSURIZATION FUNCTION (CMR**)							Service ATA:21
	MOS	07-Jun-24						CMR	
	HRS	8259.5	1500 (+50/-50)	Adj 50	9809.5	9859.5	890.9 (+50)		
WC#: 21.020	AFL	4418							
PKG:5									
PROC. REF: AMM 21-31-00-710-803PROC. REF: AMM 21-31-00-710-803									
21-31-00-103		FUNCTIONAL TEST OF THE CABIN-PRESSURE LEAKAGE RATE (CMR**)							Service ATA:21
	MOS	14-Aug-25	120 (+3m/-3m)	Adj -129d	07-Apr-35	07-Jul-35	3208 d (+91)	CMR	
	HRS	8645							
WC#: 21.030	AFL	4582							
PKG:38									
PROC. REF: AMM 21-31-00-720-804PROC. REF: AMM 21-31-00-720-804									
21-31-00-201	S	OPERATIONAL TEST OF THE MANUAL MODE							Service ATA:21
	MOS	27-May-20						MRB	
	HRS	6911.6	2250 (+50/-50)						
WC#: 21.035	AFL	3586							
PKG:6									
PROC. REF: AMM 21-31-00-710-802PROC. REF: AMM 21-31-00-710-802									
21-31-00-203	S	OPERATIONAL TEST OF THE DITCHING FUNCTION							Service ATA:21
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 21.040	AFL	4582							
PKG:8									
PROC. REF: AMM 21-31-00-710-804PROC. REF: AMM 21-31-00-710-804									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
21-31-01-900-801-01		LH CABIN PRESSURE CONTROLLER							Component	ATA:21
PN:GG546-3001-11	MOS/MSC	07-Sep-24	O/C	TSN 227						
SN:0520	HRS	8479.2		TSN 8479.2						
WC#: 21.100	AFL	4499		TSN 4499						
PROC. REF: AMM 21-31-01-000-801, AMM 21-31-01-400-801PROC. REF: AMM 21-31-01-000-801, AMM 21-31-01-400-801										
21-31-01-900-801-02		RH CABIN PRESSURE CONTROLLER							Component	ATA:21
PN:GG546-3001-11	MOS/MSC	07-Sep-24	O/C							
SN:264	HRS	8479.2		TSN 9443.8, TSR 8353.8						
WC#: 21.100	AFL	4499								
PROC. REF: AMM 21-31-01-000-801, AMM 21-31-01-400-801PROC. REF: AMM 21-31-01-000-801, AMM 21-31-01-400-801										
21-31-05-900-801-01		FWD OUTFLOW VALVE							Component	ATA:21
PN:GG435-3002-21	MOS/MSC	07-Sep-24	O/C	TSN 139, TSR 7						
SN:01302	HRS	8479.2		TSR 0						
WC#: 21.105	AFL	4499		TSR 0						
PROC. REF: AMM 21-31-05-000-801, AMM 21-31-05-400-801PROC. REF: AMM 21-31-05-000-801, AMM 21-31-05-400-801										
21-31-05-900-801-02		AFT OUTFLOW VALVE							Component	ATA:21
PN:GG435-3002-21	MOS/MSC	03-Apr-19	O/C							
SN:00275	HRS	6412.5		TSN 6650.7						
WC#: 21.105	AFL	3300		TSN 3745						
PROC. REF: AMM 21-31-05-000-801, AMM 21-31-05-400-801PROC. REF: AMM 21-31-05-000-801, AMM 21-31-05-400-801										
21-31-09-101		FUNCTIONAL TEST OF THE SAFETY VALVES (CMR*)							Service	ATA:21
	MOS	14-Aug-25		CMR						
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)			
WC#: 21.045	AFL	4582								
PKG:8										
PROC. REF: AMM 21-31-09-720-801PROC. REF: AMM 21-31-09-720-801										
21-31-09-900-801-01		LH SAFETY VALVE							Component	ATA:21
PN:GG435-3006-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:00150	HRS	0		TSN 0						
WC#: 21.110	AFL	0		TSN 0						
PROC. REF: AMM 21-31-09-000-801, AMM 21-31-09-400-801PROC. REF: AMM 21-31-09-000-801, AMM 21-31-09-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-31-09-900-801-02		RH SAFETY VALVE						Component	ATA:21
PN:GG435-3006-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00174	HRS	0		TSN 0					
WC#: 21.110	AFL	0		TSN 0					
PROC. REF: AMM 21-31-09-000-801, AMM 21-31-09-400-801PROC. REF: AMM 21-31-09-000-801, AMM 21-31-09-400-801									
21-31-11-201 ^S		DISCARD THE SAFETY VALVE FILTERS						Service	ATA:21
	MOS	14-Aug-25							
	HRS	8645	3000 (+50/-50)						
WC#: 21.050	AFL	4582							
PROC. REF: AMM 21-31-11-961-801PROC. REF: AMM 21-31-11-961-801									
21-51-01-900-801-01		LH VENTURI FLOW SENSOR						Component	ATA:21
PN:GG431-2058-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:501	HRS	0		TSN 0					
WC#: 21.130	AFL	0		TSN 0					
PROC. REF: AMM 21-51-01-000-801, AMM 21-51-01-400-801PROC. REF: AMM 21-51-01-000-801, AMM 21-51-01-400-801									
21-51-01-900-801-02		RH VENTURI FLOW SENSOR						Component	ATA:21
PN:GG431-2058-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:502	HRS	0		TSN 0					
WC#: 21.130	AFL	0		TSN 0					
PROC. REF: AMM 21-51-01-000-801, AMM 21-51-01-400-801PROC. REF: AMM 21-51-01-000-801, AMM 21-51-01-400-801									
21-51-05-900-801-01		LH BLEED FILTER						Component	ATA:21
PN:GG431-2002-3	MOS/MSC	23-Jul-20	O/C	TSN 11					
SN:2046	HRS	6911.6		TSN 0					
WC#: 21.135	AFL	3586		TSN 0					
PROC. REF: AMM 21-51-05-000-801, AMM 21-51-05-400-801PROC. REF: AMM 21-51-05-000-801, AMM 21-51-05-400-801									
21-51-05-900-801-02		RH BLEED FILTER						Component	ATA:21
PN:GG431-2002-3	MOS/MSC	20-Mar-18	O/C	TSN 5					
SN:1839	HRS	5807.9		TSN 0					
WC#: 21.135	AFL	3006		TSN 0					
PROC. REF: AMM 21-51-05-000-801, AMM 21-51-05-400-801PROC. REF: AMM 21-51-05-000-801, AMM 21-51-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-51-09-201	^S	RESTORATION OF THE LH OZONE CONVERTER							Service ATA:21
PN:GG431-2001-3	MOS								
SN:6986	HRS		3000 (+50/-50)						
WC#: 21.055	AFL								
PROC. REF: AMM 21-51-09-615-801PROC. REF: AMM 21-51-09-615-801									
21-51-09-201	^S	RESTORATION OF THE RH OZONE CONVERTER							Service ATA:21
PN:GG431-2001-3	MOS								
SN:7567	HRS		3000 (+50/-50)						
	AFL								
PROC. REF: AMM 21-51-09-615-801PROC. REF: AMM 21-51-09-615-801									
21-51-09-900-801-01		LH OZONE CONVERTER							Component ATA:21
PN:GG431-2001-3	MOS/MSC	14-Aug-25	O/C						
SN:6986	HRS	8645							
WC#: 21.140	AFL	4582							
PROC. REF: CMM 21-51-12, AMM 21-51-09-000-801, AMM 21-51-09-400-801PROC. REF: CMM 21-51-12, AMM 21-51-09-000-801, AMM 21-51-09-400-801									
21-51-09-900-801-02		RH OZONE CONVERTER							Component ATA:21
PN:GG431-2001-3	MOS/MSC	14-Aug-25	O/C						
SN:7567	HRS	8645							
WC#: 21.140	AFL	4582							
PROC. REF: CMM 21-51-12, AMM 21-51-09-000-801, AMM 21-51-09-400-801PROC. REF: CMM 21-51-12, AMM 21-51-09-000-801, AMM 21-51-09-400-801									
21-51-13-900-801-01		LH PACK INLET FLOW SENSOR							Component ATA:21
PN:GG436-2003-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1230	HRS	0		TSN 0					
WC#: 21.145	AFL	0		TSN 0					
PROC. REF: AMM 21-51-13-000-801, AMM 21-51-13-400-801PROC. REF: AMM 21-51-13-000-801, AMM 21-51-13-400-801									
21-51-13-900-801-02		RH PACK INLET FLOW SENSOR							Component ATA:21
PN:GG436-2003-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1077	HRS	0		TSN 0					
WC#: 21.145	AFL	0		TSN 0					
PROC. REF: AMM 21-51-13-000-801, AMM 21-51-13-400-801PROC. REF: AMM 21-51-13-000-801, AMM 21-51-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-51-17-900-801-01		LH PACK INLET PRESSURE SENSOR						Component	ATA:21
PN:GG436-2004-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1300	HRS	0		TSN 0					
WC#: 21.150	AFL	0		TSN 0					
PROC. REF: AMM 21-51-17-000-801, AMM 21-51-17-400-801PROC. REF: AMM 21-51-17-000-801, AMM 21-51-17-400-801									
21-51-17-900-801-02		RH PACK INLET PRESSURE SENSOR						Component	ATA:21
PN:GG436-2004-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1113	HRS	0		TSN 0					
WC#: 21.150	AFL	0		TSN 0					
PROC. REF: AMM 21-51-17-000-801, AMM 21-51-17-400-801PROC. REF: AMM 21-51-17-000-801, AMM 21-51-17-400-801									
21-51-21-900-801-01		LH PACK INLET TEMPERATURE (INLET) SENSOR						Component	ATA:21
PN:GG436-2005-3	MOS/MSC	01-Apr-13	O/C	TSN 0					
SN:10725R	HRS	3053.8		TSN 0					
	AFL	1617		TSN 0					
PROC. REF: AMM 21-51-21-000-801, AMM 21-51-21-400-801PROC. REF: AMM 21-51-21-000-801, AMM 21-51-21-400-801									
21-51-21-900-801-02		RH PACK INLET TEMPERATURE (INLET) SENSOR						Component	ATA:21
PN:GG436-2005-3	MOS/MSC	08-Jul-16	O/C	TSN 0					
SN:13980R	HRS	4894.5		TSN 0					
	AFL	2540		TSN 0					
PROC. REF: AMM 21-51-21-000-801, AMM 21-51-21-400-801PROC. REF: AMM 21-51-21-000-801, AMM 21-51-21-400-801									
21-51-25-900-802-01		LH SUPPLY DUCT						Component	ATA:21
PN:GG468-4042-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0212	HRS	0		TSN 0					
WC#: 21.155	AFL	0		TSN 0					
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-51-25-900-802-02		RH SUPPLY DUCT						Component	ATA:21
PN:GG468-4042-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0211	HRS	0		TSN 0					
WC#: 21.155	AFL	0		TSN 0					
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-51-25-900-803-01		LH SUPPLY DUCT ASSY						Component	ATA:21
PN:GG438-2050-3	MOS/MSC	31-Oct-08	O/C						
SN:0415	HRS	928.2							
WC#: 21.160	AFL	503							
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-51-25-900-803-02		RH SUPPLY DUCT ASSY						Component	ATA:21
PN:GG468-4056-3	MOS/MSC	19-Dec-19	O/C	TSN 0					
SN:1068	HRS			TSN 0					
WC#: 21.160	AFL			TSN 0					
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-51-25-900-804-01		LH SENSE LINE- TUBE ASSY						Component	ATA:21
PN:GD438-1405-5	MOS/MSC	15-Aug-16	O/C	TSN 0					
SN:J/LN155255	HRS			TSN 0					
WC#: 21.165	AFL			TSN 0					
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-51-25-900-805-01		LH FLOW CONTROL VALVE						Component	ATA:21
PN:GG436-2006-11	MOS/MSC	04-May-23	O/C						
SN:00260	HRS	7808.8							
WC#: 21.170	AFL	4157							
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-51-25-900-805-02		RH FLOW CONTROL VALVE						Component	ATA:21
PN:GG436-2006-11	MOS/MSC	30-Nov-09	O/C	TSN 82, TSR 1					
SN:00439	HRS	1382		TSN 1631, TSR 0					
WC#: 21.170	AFL	775		TSR 0					
PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: AMM 21-51-25-000-801, AMM 21-51-25-400-801									
21-52-00-101		OPERATIONAL TEST OF THE MANUAL MODE OF THE AIR CONDITIONING SYSTEM (CMR**)						Service	ATA:21
	MOS	16-Jun-24						CMR	
	HRS	8280.9	1500 (+50/-50)	Adj 50	9830.9	9880.9	912.3 (+50)		
WC#: 21.060	AFL	4430							
PROC. REF: AMM 21-52-00-710-802PROC. REF: AMM 21-52-00-710-802									
PKG:5									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-52-01-900-801-01		LH COOLING PACK						Component	ATA:21
PN:GG431-2007-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0509	HRS	0		TSN 0					
WC#: 21.175	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
21-52-01-900-801-02		RH COOLING PACK						Component	ATA:21
PN:GG431-2007-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0510	HRS	0		TSN 0					
WC#: 21.175	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
21-52-01-900-802-01		LH PLENUM						Component	ATA:21
PN:GG431-2008-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01252	HRS	0		TSN 0					
WC#: 21.180	AFL	0		TSN 0					
PROC. REF: AMM 21-52-01-000-801, AMM 21-52-01-400-801PROC. REF: AMM 21-52-01-000-801, AMM 21-52-01-400-801									
21-52-01-900-802-02		RH PLENUM						Component	ATA:21
PN:GG431-2008-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01274	HRS	0		TSN 0					
WC#: 21.180	AFL	0		TSN 0					
PROC. REF: AMM 21-52-01-000-801, AMM 21-52-01-400-801PROC. REF: AMM 21-52-01-000-801, AMM 21-52-01-400-801									
21-52-05-900-801-01		LH DUAL HEAT EXCHANGER						Component	ATA:21
PN:GG474-2009-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50248	HRS	0		TSN 0					
WC#: 21.185	AFL	0		TSN 0					
PROC. REF: AMM 21-52-05-000-801, AMM 21-52-05-400-801PROC. REF: AMM 21-52-05-000-801, AMM 21-52-05-400-801									
21-52-05-900-801-02		RH DUAL HEAT EXCHANGER						Component	ATA:21
PN:GG474-2009-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50249	HRS	0		TSN 0					
WC#: 21.185	AFL	0		TSN 0					
PROC. REF: AMM 21-52-05-000-801, AMM 21-52-05-400-801PROC. REF: AMM 21-52-05-000-801, AMM 21-52-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
21-52-09-900-801-01		LH AIR CYCLE MACHINE ACM							Component	ATA:21
PN:GG431-2010-3	MOS/MSC	31-Jul-20	O/C	TSN 160, TSR 3						
SN:00634	HRS	6914.3	TSN 4614.1, TSR 0							
WC#: 21.190	AFL	3588	TSN 1535, TSR 0							
PROC. REF: AMM 21-52-09-000-801, AMM 21-52-09-400-801PROC. REF: AMM 21-52-09-000-801, AMM 21-52-09-400-801										
21-52-09-900-801-02		RH AIR CYCLE MACHINE ACM							Component	ATA:21
PN:GG431-2010-3	MOS/MSC	12-Jun-23	O/C	TSN 133, TSR 0						
SN:01159	HRS	7864.7	TSR 0							
WC#: 21.190	AFL	4198	TSR 0							
PROC. REF: AMM 21-52-09-000-801, AMM 21-52-09-400-801PROC. REF: AMM 21-52-09-000-801, AMM 21-52-09-400-801										
21-52-13-900-801-01		LH PACK INLET TEMPERATURE (DISCHARGE) SENSOR							Component	ATA:21
PN:GG436-2005-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:03038R	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-52-13-000-801, AMM 21-52-13-400-801PROC. REF: AMM 21-52-13-000-801, AMM 21-52-13-400-801										
21-52-13-900-801-02		RH PACK INLET TEMPERATURE (DISCHARGE) SENSOR							Component	ATA:21
PN:GG436-2005-3	MOS/MSC	11-Sep-16	O/C	TSN 0						
SN:13589R	HRS	4998.3	TSN 0							
	AFL	2569	TSN 0							
PROC. REF: AMM 21-52-13-000-801, AMM 21-52-13-400-801PROC. REF: AMM 21-52-13-000-801, AMM 21-52-13-400-801										
21-52-17-900-801-01		LH COMPRESSOR PNEUMATIC OVERHEAT SENSOR							Component	ATA:21
PN:GG436-2012-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:00503	HRS	0	TSN 0							
WC#: 21.195	AFL	0	TSN 0							
PROC. REF: AMM 21-52-17-000-801, AMM 21-52-17-400-801PROC. REF: AMM 21-52-17-000-801, AMM 21-52-17-400-801										
21-52-17-900-801-02		RH COMPRESSOR PNEUMATIC OVERHEAT SENSOR							Component	ATA:21
PN:GG436-2012-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:00496	HRS	0	TSN 0							
WC#: 21.195	AFL	0	TSN 0							
PROC. REF: AMM 21-52-17-000-801, AMM 21-52-17-400-801PROC. REF: AMM 21-52-17-000-801, AMM 21-52-17-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-52-21-900-801-01		LH REHEATER CONDENSER						Component	ATA:21
PN:GG474-2053-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00925	HRS	0		TSN 0					
WC#: 21.200	AFL	0		TSN 0					
PROC. REF: AMM 21-52-21-000-801, AMM 21-52-21-400-801PROC. REF: AMM 21-52-21-000-801, AMM 21-52-21-400-801									
21-52-21-900-801-02		RH REHEATER CONDENSER						Component	ATA:21
PN:GG474-2053-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00923	HRS	0		TSN 0					
WC#: 21.200	AFL	0		TSN 0					
PROC. REF: AMM 21-52-21-000-801, AMM 21-52-21-400-801PROC. REF: AMM 21-52-21-000-801, AMM 21-52-21-400-801									
21-52-25-900-801-01		LH (PACK) TEMPERATURE SENSOR						Component	ATA:21
PN:GG436-2015-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04401	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-52-25-000-801, AMM 21-52-25-400-801PROC. REF: AMM 21-52-25-000-801, AMM 21-52-25-400-801									
21-52-25-900-801-02		RH (PACK) TEMPERATURE SENSOR						Component	ATA:21
PN:GG436-2015-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04400	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-52-25-000-801, AMM 21-52-25-400-801PROC. REF: AMM 21-52-25-000-801, AMM 21-52-25-400-801									
21-52-29-900-801-01		LH WATER EXTRACTOR						Component	ATA:21
PN:GG431-2016-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00802	HRS	0		TSN 0					
WC#: 21.205	AFL	0		TSN 0					
PROC. REF: AMM 21-52-29-000-801, AMM 21-52-29-400-801PROC. REF: AMM 21-52-29-000-801, AMM 21-52-29-400-801									
21-52-29-900-801-02		RH WATER EXTRACTOR						Component	ATA:21
PN:GG431-2016-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00803	HRS	0		TSN 0					
WC#: 21.205	AFL	0		TSN 0					
PROC. REF: AMM 21-52-29-000-801, AMM 21-52-29-400-801PROC. REF: AMM 21-52-29-000-801, AMM 21-52-29-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-52-33-900-801-01 LH TEMPERATURE CONTROL VALVE								Component	ATA:21
PN:GG436-2017-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01081	HRS	0		TSN 0					
WC#: 21.210	AFL	0		TSN 0					
PROC. REF: AMM 21-52-33-000-801, AMM 21-52-33-400-801PROC. REF: AMM 21-52-33-000-801, AMM 21-52-33-400-801									
21-52-33-900-801-02 RH TEMPERATURE CONTROL VALVE								Component	ATA:21
PN:GG436-2017-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01083	HRS	0		TSN 0					
WC#: 21.210	AFL	0		TSN 0					
PROC. REF: AMM 21-52-33-000-801, AMM 21-52-33-400-801PROC. REF: AMM 21-52-33-000-801, AMM 21-52-33-400-801									
21-52-37-900-801-01 LH (PACK DISCHARGE) TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04539	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-52-37-000-801, AMM 21-52-37-400-801PROC. REF: AMM 21-52-37-000-801, AMM 21-52-37-400-801									
21-52-37-900-801-02 RH (PACK DISCHARGE) TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04207	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-52-37-000-801, AMM 21-52-37-400-801PROC. REF: AMM 21-52-37-000-801, AMM 21-52-37-400-801									
21-52-41-900-801-01 LH ANTI-ICING PRESSURE SENSOR								Component	ATA:21
PN:GG436-2033-1	MOS/MSC	05-May-23	O/C	TSN 33					
SN:11749	HRS	7808.8		TSN 0					
WC#: 21.215	AFL	4157		TSN 0					
PROC. REF: AMM 21-52-41-000-801, AMM 21-52-41-400-801PROC. REF: AMM 21-52-41-000-801, AMM 21-52-41-400-801									
21-52-41-900-801-02 RH ANTI-ICING PRESSURE SENSOR								Component	ATA:21
PN:GG436-2033-1	MOS/MSC	17-Jan-13	O/C	TSN 1					
SN:10251	HRS	2979.4		TSN 0					
WC#: 21.215	AFL	1554		TSN 0					
PROC. REF: AMM 21-52-41-000-801, AMM 21-52-41-400-801PROC. REF: AMM 21-52-41-000-801, AMM 21-52-41-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-52-49-900-801-01		LH PACK DISCHARGE DUCT						Component	ATA:21
PN:GG438-2050-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0279	HRS	0		TSN 0					
WC#: 21.220	AFL	0		TSN 0					
PROC. REF: AMM 21-52-49-000-801, AMM 21-52-49-400-801PROC. REF: AMM 21-52-49-000-801, AMM 21-52-49-400-801									
21-52-53-900-801-01		RH PACK DISCHARGE DUCT						Component	ATA:21
PN:GG438-2049-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0274	HRS	0		TSN 0					
WC#: 21.220	AFL	0		TSN 0					
PROC. REF: AMM 21-52-53-000-801, AMM 21-52-53-400-801PROC. REF: AMM 21-52-53-000-801, AMM 21-52-53-400-801									
21-53-01-900-801-01		LH WATER SPRAYER						Component	ATA:21
PN:GG431-2022-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01419	HRS	0		TSN 0					
WC#: 21.230	AFL	0		TSN 0					
PROC. REF: AMM 21-53-01-000-801, AMM 21-53-01-400-801PROC. REF: AMM 21-53-01-000-801, AMM 21-53-01-400-801									
21-53-01-900-801-02		RH WATER SPRAYER						Component	ATA:21
PN:GG431-2022-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01420	HRS	0		TSN 0					
WC#: 21.230	AFL	0		TSN 0					
PROC. REF: AMM 21-53-01-000-801, AMM 21-53-01-400-801PROC. REF: AMM 21-53-01-000-801, AMM 21-53-01-400-801									
21-53-05-101		OPERATIONAL TEST OF THE RAM AIR VALVE (CMR**)						Service	ATA:21
	MOS	06-Jun-24						CMR	
	HRS	8259.5	1500 (+50/-50)	Adj 50	9809.5	9859.5	890.9 (+50)		
WC#: 21.065	AFL	4418							
PROC. REF: AMM 21-53-05-710-801PROC. REF: AMM 21-53-05-710-801									
21-53-05-900-801-01		EMERGENCY RAM AIR VALVE						Component	ATA:21
PN:GG436-2048-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00918	HRS	0		TSN 0					
WC#: 21.235	AFL	0		TSN 0					
PROC. REF: AMM 21-53-05-000-801, AMM 21-53-05-400-801PROC. REF: AMM 21-53-05-000-801, AMM 21-53-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-53-09-900-801-01		LH RAM AIR FLEXIBLE DUCT						Component	ATA:21
PN:GG438-2056-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:290-42996	HRS	0		TSN 0					
WC#: 21.225	AFL	0		TSN 0					
PROC. REF: AMM 21-53-09-000-801, AMM 21-53-09-400-801PROC. REF: AMM 21-53-09-000-801, AMM 21-53-09-400-801									
21-53-09-900-801-02		RH RAM AIR FLEXIBLE DUCT						Component	ATA:21
PN:GG438-2056-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:261-35157	HRS	0		TSN 0					
WC#: 21.225	AFL	0		TSN 0					
PROC. REF: AMM 21-53-09-000-801, AMM 21-53-09-400-801PROC. REF: AMM 21-53-09-000-801, AMM 21-53-09-400-801									
21-53-17-900-801-01		LH MAIN HEAT EXCHANGER DIFFUSER						Component	ATA:21
PN:GG438-2057-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:325-46611	HRS	0		TSN 0					
WC#: 21.240	AFL	0		TSN 0					
PROC. REF: AMM 21-53-17-000-801, AMM 21-53-17-400-801PROC. REF: AMM 21-53-17-000-801, AMM 21-53-17-400-801									
21-53-17-900-801-02		RH MAIN HEAT EXCHANGER DIFFUSER						Component	ATA:21
PN:GG438-2057-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:324-45574	HRS	0		TSN 0					
WC#: 21.240	AFL	0		TSN 0					
PROC. REF: AMM 21-53-17-000-801, AMM 21-53-17-400-801PROC. REF: AMM 21-53-17-000-801, AMM 21-53-17-400-801									
21-53-21-900-801-01		SPLITTER RAM AIR DUCT						Component	ATA:21
PN:GG438-2055-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0249	HRS	0		TSN 0					
WC#: 21.245	AFL	0		TSN 0					
PROC. REF: AMM 21-53-21-000-801, AMM 21-53-21-400-801PROC. REF: AMM 21-53-21-000-801, AMM 21-53-21-400-801									
21-53-33-900-801-01		RAM-AIR CHECK VALVE						Component	ATA:21
PN:GG436-2068-3	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:01392	HRS	8645		TSN 0					
WC#: 21.065	AFL	4582		TSN 0					
PROC. REF: AMM 21-53-33-000-801, AMM 21-53-33-400-801PROC. REF: AMM 21-53-33-000-801, AMM 21-53-33-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-53-33-900-801-02		RAM-AIR INTAKE						Component	ATA:21
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.250	AFL	0		TSN 0					
PROC. REF: AMM 21-53-33-000-801, AMM 21-53-33-400-801PROC. REF: AMM 21-53-33-000-801, AMM 21-53-33-400-801									
21-54-01-900-802-01		NO. 1 COOLING IRS FAN						Component	ATA:21
PN:26012423-105	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6054	HRS	0		TSN 0					
WC#: 21.255	AFL	0		TSN 0					
PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802									
21-54-01-900-802-02		NO. 2 COOLING IRS FAN						Component	ATA:21
PN:26012423-105	MOS/MSC	21-May-14	O/C	TSN 6					
SN:11117	HRS	3646.4		TSN 0					
WC#: 21.255	AFL	1928		TSN 0					
PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802									
21-54-01-900-802-03		NO. 3 COOLING IRS FAN						Component	ATA:21
PN:26012423-105	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6333 / 6133	HRS	0		TSN 0					
WC#: 21.255	AFL	0		TSN 0					
PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802PROC. REF: AMM 21-54-01-000-802, AMM 21-54-01-400-802									
21-54-37-900-801-01		NO. 1 AVIONICS EXHAUST FAN						Component	ATA:21
PN:GG433-2047-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0449	HRS	0		TSN 0					
WC#: 21.260	AFL	0		TSN 0					
PROC. REF: AMM 21-54-37-000-801, AMM 21-54-37-400-801PROC. REF: AMM 21-54-37-000-801, AMM 21-54-37-400-801									
21-54-37-900-801-02		NO. 2 AVIONICS EXHAUST FAN						Component	ATA:21
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.260	AFL	0		TSN 0					
PROC. REF: AMM 21-54-37-000-801, AMM 21-54-37-400-801PROC. REF: AMM 21-54-37-000-801, AMM 21-54-37-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-54-41-900-801-01		AVIONICS EXHAUST-FAN CONVERTER						Component	ATA:21
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.265	AFL	0		TSN 0					
PROC. REF: AMM 21-54-41-000-801, AMM 21-54-41-400-801PROC. REF: AMM 21-54-41-000-801, AMM 21-54-41-400-801									
21-60-00-101		OPERATIONAL TEST OF THE AUXILIARY PRESSURIZATION FUNCTION (CMR**)						Service	ATA:21
	MOS	16-Jun-24						CMR	
	HRS	8280.9	1500 (+50/-50)	Adj 50	9830.9	9880.9	912.3 (+50)		
WC#: 21.070	AFL	4430							
PROC. REF: AMM 21-60-00-710-802PROC. REF: AMM 21-60-00-710-802									
21-60-01-900-801-01		EMERGENCY CHECK VALVE						Component	ATA:21
PN:GG436-2035-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00298	HRS	0		TSN 0					
WC#: 21.270	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01-000-801, AMM 21-60-01-400-801PROC. REF: AMM 21-60-01-000-801, AMM 21-60-01-400-801									
21-60-05-900-801-01		LH TRIM AIR CHECK VALVE						Component	ATA:21
PN:GG436-2036-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00528	HRS	0		TSN 0					
WC#: 21.275	AFL	0		TSN 0					
PROC. REF: AMM 21-60-05-000-801, AMM 21-60-05-400-801PROC. REF: AMM 21-60-05-000-801, AMM 21-60-05-400-801									
21-60-05-900-801-02		RH TRIM AIR CHECK VALVE						Component	ATA:21
PN:GG436-2036-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00529	HRS	0		TSN 0					
WC#: 21.275	AFL	0		TSN 0					
PROC. REF: AMM 21-60-05-000-801, AMM 21-60-05-400-801PROC. REF: AMM 21-60-05-000-801, AMM 21-60-05-400-801									
21-60-09-900-801-01		LH HOT AIR SHUT-OFF VALVE						Component	ATA:21
PN:GG436-2037-5	MOS/MSC	02-Jan-13	O/C						
SN:00410	HRS	2958.4		TSN 0					
WC#: 21.280	AFL	1545		TSN 0					
PROC. REF: AMM 21-60-09-000-801, AMM 21-60-09-400-801PROC. REF: AMM 21-60-09-000-801, AMM 21-60-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 21 - AIR CONDITIONING										
21-60-09-900-801-02		RH HOT AIR SHUT-OFF VALVE							Component	ATA:21
PN:GG436-2037-5	MOS/MSC	19-Feb-19	O/C	TSR 1						
SN:01233	HRS	6352.1	TSN 6108.1, TSR 0							
WC#: 21.280	AFL	3273	TSN 2632, TSR 0							
PROC. REF: AMM 21-60-09-000-801, AMM 21-60-09-400-801PROC. REF: AMM 21-60-09-000-801, AMM 21-60-09-400-801										
21-60-13-900-801-01		LH TRIM AIR VALVE							Component	ATA:21
PN:GG436-2038-5	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:00673	HRS	0	TSN 0							
WC#: 21.285	AFL	0	TSN 0							
PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801										
21-60-13-900-801-02		RH TRIM AIR VALVE							Component	ATA:21
PN:GG436-2038-7	MOS/MSC	10-Jan-18	O/C	TSR 6						
SN:01347	HRS	5739.2	TSN 3032, TSR 0							
WC#: 21.285	AFL	2959	TSN 2639, TSR 0							
PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801										
21-60-13-900-801-03		CENTER TRIM AIR VALVE							Component	ATA:21
PN:GG436-2038-7	MOS/MSC	18-Dec-19	O/C							
SN:02126	HRS	6767.7								
WC#: 21.285	AFL	3497								
PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801PROC. REF: AMM 21-60-13-000-801, AMM 21-60-13-400-801										
21-60-17-900-801-01		LH (DUCT AFT CABIN) TEMPERATURE SENSOR							Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:04545	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801										
21-60-17-900-801-02		RH (DUCT FWD CABIN) TEMPERATURE SENSOR							Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:03860	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
21-60-17-900-801-03 CENTER (DUCT FLT COMPARTMENT) TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2015-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04598	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801PROC. REF: AMM 21-60-17-000-801, AMM 21-60-17-400-801									
21-60-21-900-801-01 LH AIR CONDITIONING SYSTEM CONTROLLER								Component	ATA:21
PN:GG5462040-15	MOS/MSC	18-Jul-23	O/C	TSR 32					
SN:01435	HRS	7923.9		TSR 0					
WC#: 21.290	AFL	4211		TSR 0					
PROC. REF: AMM 21-60-21-000-801, AMM 21-60-21-400-801PROC. REF: AMM 21-60-21-000-801, AMM 21-60-21-400-801									
21-60-21-900-801-02 RH AIR CONDITIONING SYSTEM CONTROLLER								Component	ATA:21
PN:GG546-2040-11	MOS/MSC	02-May-23	O/C						
SN:00514	HRS	7808.8							
WC#: 21.290	AFL	4157							
PROC. REF: AMM 21-60-21-000-801, AMM 21-60-21-400-801PROC. REF: AMM 21-60-21-000-801, AMM 21-60-21-400-801									
21-60-25-900-801-01 AFT VENTILATED TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2041-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:02082	HRS	0		TSN 0					
WC#: 21.295	AFL	0		TSN 0					
PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801									
21-60-25-900-801-02 LH VENTILATED TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2041-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:01854	HRS	0		TSN 0					
WC#: 21.295	AFL	0		TSN 0					
PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801									
21-60-25-900-801-03 FWD VENTILATED TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2041-3	MOS/MSC	06-Dec-17	O/C	TSN 0					
SN:08940	HRS	5684.7		TSN 0					
WC#: 21.295	AFL	2924		TSN 0					
PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801PROC. REF: AMM 21-60-25-000-801, AMM 21-60-25-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

215410-701	U	AVIONICS COOLING DUCT						Component	ATA:21
PN:GS438-0034-5	MOS/MSC	04-Nov-09	O/C	TSN 0					
SN:397	HRS	1347.2		TSN 0					
	AFL	746		TSN 0					

ATA 22 - AUTO FLIGHT

22-11-01-900-801-01		GUIDANCE PANEL						Component	ATA:22
PN:7022010-905	MOS/MSC	06-Jan-19	O/C						
SN:08100896	HRS	6299.7							
WC#: 22.005	AFL	3238							
PROC. REF: AMM 22-11-01-000-801, AMM 22-11-01-400-801PROC. REF: AMM 22-11-01-000-801, AMM 22-11-01-400-801									

22-12-01-900-801-01		AILERON PARALLEL SERVO						Component	ATA:22
PN:4015373-823	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04094187	HRS	0		TSN 0					
WC#: 22.010	AFL	0		TSN 0					
PROC. REF: AMM 22-12-01-000-801, AMM 22-12-01-400-801PROC. REF: AMM 22-12-01-000-801, AMM 22-12-01-400-801									

22-12-05-900-801-01		LEFT MLG WHEEL WELL AILERON SERVO BRACKET						Component	ATA:22
PN:4015374-813	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04093924	HRS	0		TSN 0					
WC#: 22.015	AFL	0		TSN 0					
PROC. REF: AMM 22-12-05-000-801, AMM 22-12-05-400-801PROC. REF: AMM 22-12-05-000-801, AMM 22-12-05-400-801									

22-12-09-900-801-01		ELEVATOR PARALLEL SERVO						Component	ATA:22
PN:4015373-834	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04124090	HRS	0		TSN 0					
WC#: 22.020	AFL	0		TSN 0					
PROC. REF: AMM 22-12-09-000-801, AMM 22-12-09-400-801PROC. REF: AMM 22-12-09-000-801, AMM 22-12-09-400-801									

22-12-13-900-801-01		FS1076.0 WL203.8 ELEVATOR SERVO BRACKET						Component	ATA:22
PN:4015374-906	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:02053832	HRS	0		TSN 0					
WC#: 22.025	AFL	0		TSN 0					
PROC. REF: AMM 22-12-13-000-801, AMM 22-12-13-400-801PROC. REF: AMM 22-12-13-000-801, AMM 22-12-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
23-11-01-900-801-01	NO. 1 VHF COMMUNICATION RECEIVER								Component ATA:23
PN:7510733-666	MOS/MSC	26-Feb-25	O/C						
SN:0903CS13	HRS	8641.1							
WC#: 23.020	AFL	4580							
PROC. REF: AMM 23-11-01-000-801, AMM 23-11-01-400-801PROC. REF: AMM 23-11-01-000-801, AMM 23-11-01-400-801									
23-11-01-900-801-02	NO. 2 VHF COMMUNICATION RECEIVER								Component ATA:23
PN:7510733-666	MOS/MSC	29-Apr-21	O/C						
SN:01066630	HRS								
WC#: 23.020	AFL								
PROC. REF: AMM 23-11-01-000-801, AMM 23-11-01-400-801PROC. REF: AMM 23-11-01-000-801, AMM 23-11-01-400-801									
23-11-05-900-801-01	NO. 1 COMM VHF TOP ANTENNA								Component ATA:23
PN:S65-8280-10	MOS/MSC	20-May-14	O/C	TSN 8					
SN:310-25869	HRS	3646.4		TSN 0					
WC#: 23.025	AFL	1928		TSN 0					
PROC. REF: AMM 23-11-05-000-801, AMM 23-11-05-400-801PROC. REF: AMM 23-11-05-000-801, AMM 23-11-05-400-801									
23-11-05-900-801-02	NO. 2 COMM VHF BOTTOM ANTENNA								Component ATA:23
PN:S65-8280-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0339	HRS	0		TSN 0					
WC#: 23.025	AFL	0		TSN 0					
PROC. REF: AMM 23-11-05-000-801, AMM 23-11-05-400-801PROC. REF: AMM 23-11-05-000-801, AMM 23-11-05-400-801									
23-11-CA-200	RECERTIFY NO. 1 VHF COMMUNICATION RECEIVER PER 14 CFR 91.413								Service ATA:23
PN:7510733-666	MOS	14-Apr-25	24	14-Apr-27		293 d		FAA	
SN:0903CS13	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
23-11-CA-200	RECERTIFY NO. 2 VHF COMMUNICATION RECEIVER PER 14 CFR 91.413								Service ATA:23
PN:7510733-666	MOS	14-Apr-25	24	14-Apr-27		293 d		FAA	
SN:01066630	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
23-12-01-900-801-01		LH HF (HF9031A) RECEIVER						Component	ATA:23
PN:822-0101-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1997	HRS	0		TSN 0					
WC#: 23.030	AFL	0		TSN 0					
PROC. REF: AMM 23-12-01-000-801, AMM 23-12-01-400-801PROC. REF: AMM 23-12-01-000-801, AMM 23-12-01-400-801									
23-12-01-900-801-02		RH HF (HF9031A) RECEIVER						Component	ATA:23
PN:822-0101-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2027	HRS	0		TSN 0					
WC#: 23.030	AFL	0		TSN 0					
PROC. REF: AMM 23-12-01-000-801, AMM 23-12-01-400-801PROC. REF: AMM 23-12-01-000-801, AMM 23-12-01-400-801									
23-12-05-900-801-01		NO. 1 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER						Component	ATA:23
PN:685-0350-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5751	HRS	0		TSN 0					
WC#: 23.035	AFL	0		TSN 0					
PROC. REF: AMM 23-12-05-000-801, AMM 23-12-05-400-801PROC. REF: AMM 23-12-05-000-801, AMM 23-12-05-400-801									
23-12-05-900-801-02		NO. 2 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER						Component	ATA:23
PN:685-0350-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5752	HRS	0		TSN 0					
WC#: 23.035	AFL	0		TSN 0					
PROC. REF: AMM 23-12-05-000-801, AMM 23-12-05-400-801PROC. REF: AMM 23-12-05-000-801, AMM 23-12-05-400-801									
23-22-01-900-801-01		SELCAL DECODER						Component	ATA:23
PN:1200008-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:4442	HRS	0		TSN 0					
WC#: 23.040	AFL	0		TSN 0					
PROC. REF: AMM 23-22-01-000-801, AMM 23-22-01-400-801PROC. REF: AMM 23-22-01-000-801, AMM 23-22-01-400-801									
23-51-05-900-801-01		NO. 1 AUDIO CONTROL PANEL						Component	ATA:23
PN:7511001-981	MOS/MSC	23-Apr-14	O/C	TSR 0					
SN:01066815	HRS	3630.5		TSR 0					
WC#: 23.045	AFL	1915		TSR 0					
PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 23 - COMMUNICATIONS										
23-51-05-900-801-02		NO. 2 AUDIO CONTROL PANEL							Component	ATA:23
PN:7511001-981	MOS/MSC	13-Oct-23	O/C	TSR 46						
SN:02067990	HRS	8057.9	TSR 1085.1							
WC#: 23.045	AFL	4281	TSR 649							
PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801										
23-51-05-900-801-03		NO. 3 AUDIO CONTROL PANEL							Component	ATA:23
PN:7511001-981	MOS/MSC	13-Oct-23	O/C							
SN:02108574	HRS	8057.9								
WC#: 23.045	AFL	4281								
PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801PROC. REF: AMM 23-51-05-000-801, AMM 23-51-05-400-801										
23-61-01-201 ^S		FUNCTIONAL TEST OF THE STATIC DISCHARGERS							Service	ATA:23
	MOS	14-Aug-25	60 (+3m/-3m)	MRB						
	HRS	8645								
WC#: 23.010	AFL	4582								
PKG:34										
PROC. REF: AMM 23-61-01-720-801PROC. REF: AMM 23-61-01-720-801										
23-71-00-201		OPERATIONAL TEST OF THE VOICE RECORDER SYSTEM							Service	ATA:23
	MOS	14-Aug-25	MRB							
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)			
WC#: 23.015	AFL	4582								
PKG:8										
PROC. REF: AMM 23-71-00-710-801PROC. REF: AMM 23-71-00-710-801										
23-71-01-900-801-01		(CVR) COCKPIT VOICE RECORDER							Component	ATA:23
PN:980-6032-040	MOS/MSC	07-May-12	O/C							
SN:CVR-01509	HRS	2616.8								
WC#: 23.050	AFL	1382								
PROC. REF: AMM 23-71-01-000-801, AMM 23-71-01-400-801PROC. REF: AMM 23-71-01-000-801, AMM 23-71-01-400-801										
23-71-05-900-801-01		CVR - CONTROL PANEL							Component	ATA:23
PN:980-6117-001	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:CVRCCP-02544	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 23-71-05-000-801, AMM 23-71-05-400-801PROC. REF: AMM 23-71-05-000-801, AMM 23-71-05-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
23-71-09-900-801-01		MICROPHONE						Component	ATA:23
PN:980-6113-001	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:03415	HRS	0		TSN 0					
WC#: 23.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
23-71-13-201		RESTORATION OF THE RECORDER INDEPENDENT POWER SUPPLY (RIPS)						Service	ATA:23
PN:PN	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 23-71-13-840-801PROC. REF: AMM 23-71-13-840-801									
23-71-17-900-801-01		IMPACT SWITCH						Component	ATA:23
PN:370-0145-003	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7041	HRS	0		TSN 0					
WC#: 23.060	AFL	0		TSN 0					
PROC. REF: AMM 23-71-17-000-801, AMM 23-71-17-400-801PROC. REF: AMM 23-71-17-000-801, AMM 23-71-17-400-801									
23-71-21-201		DISCARD OF THE COCKPIT- VOICE-RECORDER (CVR) UNDERWATER-LOCATING- DEVICE (ULD) BATTERY						Service	ATA:23
PN:DK120/90	MOS/MSC	04-Oct-23	DUE		01-May-30 (M)		1406 d	MRB	
SN:AT188211	HRS	8049.4							
WC#: 23.065	AFL	4271							
PROC. REF: AMM 23-71-21-960-802PROC. REF: AMM 23-71-21-960-802									
23-71-21-202		OPERATIONAL TEST OF THE COCKPIT-VOICE−RECORDER (CVR) UNDERWATER-LOCATING DEVICE (ULD)						Service	ATA:23
PN:DK120/90	MOS	14-Aug-25	30 (+3m/-3m)	Adj 3	14-May-28	14-Aug-28	689 d (+92)	MRB	
SN:AT188211	HRS	8645							
WC#: 23.065	AFL	4582							
PROC. REF: AMM 23-71-21-710-801PROC. REF: AMM 23-71-21-710-801									PKG:32
23-71-21-900-801-01		CVR (ULB) UNDERWATER LOCATOR BEACON						Component	ATA:23
PN:DK120/90	MOS/MSC	04-Oct-23	O/C	TSN 6					
SN:AT188211	HRS	8049.4		TSN 0					
WC#: 23.065	AFL	4271		TSN 0					
PROC. REF: AMM 23-71-21-000-801, AMM 23-71-21-400-801PROC. REF: AMM 23-71-21-000-801, AMM 23-71-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
23-81-01-900-802-01	LH RADIO MANAGEMENT UNIT							Component	ATA:23
PN:7013270-977	MOS/MSC	20-May-14	O/C						
SN:01073264	HRS	3646.4							
WC#: 23.070	AFL	1928							
PROC. REF: AMM 23-81-01-000-802, AMM 23-81-01-400-802PROC. REF: AMM 23-81-01-000-802, AMM 23-81-01-400-802									
23-81-01-900-802-02	RH RADIO MANAGEMENT UNIT							Component	ATA:23
PN:7013270-977	MOS/MSC	20-May-14	O/C						
SN:98071135	HRS	3646.4							
WC#: 23.070	AFL	1928							
PROC. REF: AMM 23-81-01-000-802, AMM 23-81-01-400-802PROC. REF: AMM 23-81-01-000-802, AMM 23-81-01-400-802									
23-CUS-001 ^U	RENEW RADIO STATION LICENSE							Service	ATA:23
	MOS	12-May-26	120		12-May-36		3609 d		
	HRS	8870							
	AFL	4687							
231101-701 ^U	NO. 3 VHF COMMUNICATION RECEIVER							Component	ATA:23
PN:7510700-833	MOS/MSC	13-Nov-25	O/C						
SN:0810C236	HRS	8740.5							
	AFL	4614							
231105-701 ^U	ANTENNA							Component	ATA:23
PN:S65-8280-10	MOS/MSC	07-Oct-05	O/C						
SN:310-13766	HRS	0							
	AFL	0							
231299-701 ^U	SDR#1 PAX/CREW NETWORK							Component	ATA:23
PN:1233-F-2191-10	MOS/MSC	22-Feb-22	O/C						
SN:1223	HRS	7373.2							
	AFL	3892							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231300-701 ^U		SDR 2 VIP # NETWORK						Component	ATA:23
PN:1233-F-2191-10	MOS/MSC	26-Mar-22	O/C						
SN:564	HRS	7407.2							
	AFL	3910							
231301-701 ^U		LNA ASSY DIPLEXER						Component	ATA:23
PN:1242-A-0006	MOS/MSC	14-Jul-16	O/C						
SN:579	HRS	4894.5							
	AFL	2540							
231303-701 ^U		AMT-700 ANTENNA ASSEMBLY						Component	ATA:23
PN:1428-A-0010-02	MOS/MSC	21-Nov-22	O/C		TSR 0				
SN:144	HRS	7677.8			TSN 2185.9, TSR 0				
	AFL	4076			TSN 1311, TSR 0				
231304-701 ^U		SATELLITE RECEIVER/TRANSMITTER						Component	ATA:23
PN:822-1785-001	MOS/MSC	29-Sep-25	O/C						
SN:147105	HRS	8654.87							
	AFL	4580							
231312-701 ^U		IRRIDIUM COM ANTENNA						Component	ATA:23
PN:500644	MOS/MSC	07-Oct-05	O/C						
SN:4240	HRS	0							
	AFL	0							
231317-701 ^U		HIGH SPEED TRANSCEIVER						Component	ATA:23
PN:822-2232-020	MOS/MSC	06-Sep-12	O/C						
SN:16Y8VK	HRS	2842.3							
	AFL	1467							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231317-702 ^U		HIGH SPEED TRANSCEIVER						Component	ATA:23
PN:822-2232-020	MOS/MSC	02-Aug-16	O/C	TSN 0					
SN:16PPPX	HRS	4938.3		TSN 0					
	AFL	2552		TSN 0					
231318-701 ^U		WEATHER XM RECEIVER						Component	ATA:23
PN:4092743-901	MOS/MSC	07-May-08	O/C						
SN:32596670	HRS	658.8							
	AFL	394							
231319-701 ^U		VGA SPLITTER						Component	ATA:23
PN:990-5700-001	MOS/MSC	07-Oct-05	O/C						
SN:06010024192	HRS	0							
	AFL	0							
231401-701 ^U		ATG FWD DUAL DIRECTIONAL ANTENNA						Component	ATA:23
PN:P35500	MOS/MSC	23-Jun-20	O/C						
SN:3550002699	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231401-702 ^U		ATG AFT DUAL DIRECTIONAL ANTENNA						Component	ATA:23
PN:P35500	MOS/MSC	23-Jun-20	O/C						
SN:3550002856	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231402-701 ^U		F.S.426 GOGO TERRESTRIAL MODEM ANTENNA						Component	ATA:23
PN:P18350-001	MOS/MSC	23-Jun-20	O/C						
SN:1835004414	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231402-702 ^U		F.S.500 GOGO TERRESTRIAL MODEM ANTENNA						Component	ATA:23
PN:P18350-001	MOS/MSC	23-Jun-20	O/C						
SN:1835004310	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231403-701 ^U		GOGO L5 TRANSCEIVER						Component	ATA:23
PN:P34110-002	MOS/MSC	12-Dec-23	O/C						
SN:3411002001406	HRS	8117.4							
	AFL	4317							
231404-701 ^U		L5 CONFIGURATION MODULE						Component	ATA:23
PN:P14126	MOS/MSC	23-Jun-20	O/C						
SN:1412618052	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231405-701 ^U		F.S.482 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110661	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231405-702 ^U		F.S.489 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110698	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231405-703 ^U		F.S.495 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110698	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231405-704 ^U		F.S.559.65 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110684	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231405-705 ^U		F.S.569 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110691	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231405-706 ^U		F.S.582 GOGO WIFI ANTENNA						Component	ATA:23
PN:P16917-001	MOS/MSC	23-Jun-20	O/C						
SN:1691700110701	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					
231500-701 ^U		AEROCOM 3000 CTU UNIT						Component	ATA:23
PN:350000-10-010200	MOS/MSC	24-Sep-11	O/C	TSR 0					
SN:AE3K-337	HRS	2364		TSR 0					
	AFL	1233		TSR 0					
231501-702 ^U		IRIDIUM COMM ICS 200 UNIT						Component	ATA:23
PN:500617-2	MOS/MSC	24-Mar-14	O/C						
SN:5903	HRS	3595							
	AFL	1889							
232100-701 ^U		COCKPIT PRINTER						Component	ATA:23
PN:G-624E-P-7.0-G	MOS/MSC	04-Feb-10	O/C						
SN:401200601011	HRS	1427.4							
	AFL	807							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
232301-701 ^U		AIRBORNE DATA LINK (ADLU) UNIT						Component	ATA:23
PN:8400021-03	MOS/MSC	20-May-26	O/C						
SN:10578	HRS	8875.1							
	AFL	4690							
237000-701 ^U		NO. 1 VIDEO ENCODING EQUIPMENT						Component	ATA:23
PN:1308525-100	MOS/MSC	22-Sep-11	O/C						
SN:35TLM	HRS	2364							
	AFL	1233							
237000-702 ^U		NO. 2 VIDEO ENCODING EQUIPMENT						Component	ATA:23
PN:1308525-100	MOS/MSC	07-Oct-05	O/C						
SN:1HYPC	HRS	0							
	AFL	0							
237000-703 ^U		NO. 3 VIDEO ENCODING EQUIPMENT						Component	ATA:23
PN:1308525-100	MOS/MSC	07-Oct-05	O/C						
SN:1HYRK	HRS	0							
	AFL	0							
238101-003 ^U		A25 RMU PANEL						Component	ATA:23
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.075	AFL	0		TSN 0					
238101-004 ^U		A26 RMU PANEL						Component	ATA:23
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.075	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

239020-701	U	XM RADIO ANTENNA SATELLITE						Component	ATA:23
PN:822-2030-001	MOS/MSC	26-Feb-25	O/C	TSN 20					
SN:4TCV2V	HRS	8641.1		TSN 0					
	AFL	4580		TSN 0					

239020-702	U	XM RADIO RECEIVER SATELLITE						Component	ATA:23
PN:XMR400-01	MOS/MSC	11-Sep-11	O/C	TSR 3					
SN:804000472	HRS	2342.5		TSR 0					
	AFL	1225		TSR 0					

239602-701	U	18" HIGH CABINET DISPLAY EQUIPMENT						Component	ATA:23
PN:ALD-1801D	MOS/MSC	02-Nov-06	O/C						
SN:AK0045	HRS	36.5							
	AFL	14							

ATA 24 - ELECTRICAL POWER

24-00-00-301	S	OPERATIONAL TEST (CYCLING) OF THERMAL CIRCUIT BREAKERS						Service	ATA:24
	MOS	14-Aug-25	15 (+3m/-3m)					OPTIONAL	
	HRS	8645							
	AFL	4582							

PKG:31

PROC. REF: AMM 24-00-00-710-802PROC. REF: AMM 24-00-00-710-802

24-00-50-601	U S	OPERATIONAL TEST OF THE CABIN POWER SHUT-OFF SWITCH						Service	ATA:24
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							

PKG:31

24-12-00-900-801-01		NO. 1 VFG OIL PIPE				Component	ATA:24
PN:BRR20625	MOS/MSC	07-Oct-05	O/C	TSN 0			
SN:NOT SERIALIZE	HRS	0		TSN 0			
WC#: 24.035	AFL	0		TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-12-00-900-801-02	NO. 2 VFG OIL PIPE								Component ATA:24
PN:BRR22218	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT SERIALIZE	HRS	0		TSN 0					
WC#: 24.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
24-21-01-201 S	DETAILED INSPECTION OF THE VARIABLE FREQUENCYGENERATOR (VFG) OIL SUPPLY								Service ATA:24
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 24.005	AFL	4582							
PROC. REF: AMM 24-12-00-220-801PROC. REF: AMM 24-12-00-220-801									
24-21-01-900-801-01	NO. 1 (LH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component ATA:24
PN:GL511-1103-9	MOS/MSC	27-Mar-18	O/C	TSR 5					
SN:4114	HRS	5837.3		TSN 910, TSR 0					
WC#: 24.040	AFL	3015		TSN 885, TSR 0					
PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801									
24-21-01-900-801-02	NO. 2 (LH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component ATA:24
PN:GL511-1103-11	MOS/MSC	14-Aug-25	O/C	TSR 0					
SN:6343	HRS	8645		TSR 0					
WC#: 24.040	AFL	4582		TSR 0					
PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801									
24-21-01-900-801-03	NO. 3 (RH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component ATA:24
PN:GL511-1103-9	MOS/MSC	20-Oct-17	O/C	TSN 41					
SN:6190	HRS	5650.6		TSN 2004.2					
WC#: 24.040	AFL	2898		TSN 970					
PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801									
24-21-01-900-801-04	NO. 4 (RH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component ATA:24
PN:GL511-1103-9	MOS/MSC	20-Oct-17	O/C	TSN 43					
SN:6115	HRS	5650.6		TSN 2004.2					
WC#: 24.040	AFL	2898		TSN 970					
PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801PROC. REF: AMM 24-21-01-000-801, AMM 24-21-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 24 - ELECTRICAL POWER										
24-22-01-900-801-01		NO.5 APU AC (40/45 KVA) GENERATOR							Component	ATA:24
PN:GL511-1204-5	MOS/MSC	21-Oct-23	O/C	TSR 2						
SN:2505	HRS	8064.2	TSN 1862.3, TSR 0							
WC#: 24.045	AFL	4287	TSN 962, TSR 0							
PROC. REF: AMM 24-22-01-000-801, AMM 24-22-01-400-801PROC. REF: AMM 24-22-01-000-801, AMM 24-22-01-400-801										
24-23-01-101		OPERATIONAL TEST OF THE RAM AIR TURBINE (RAT) (CMR*)							Service	ATA:24
	MOS	17-Aug-25	24 (+3m/-3m)	Adj -101d	08-May-27	08-Aug-27	317 d (+92)	CMR		
	HRS	8646.2								
WC#: 24.015	AFL	4583								
PROC. REF: AMM 24-23-01-710-801PROC. REF: AMM 24-23-01-710-801										
24-23-01-102		FUNCTIONAL TEST RAM AIR TURBINE (RAT) HEATER (CMR*)							Service	ATA:24
PN:GL456-1101-7	MOS	14-Aug-25	24 (+3m/-3m)	Adj -98d	08-May-27	08-Aug-27	317 d (+92)	CMR		
SN:162	HRS	8645								
WC#: 24.015	AFL	4582								
PROC. REF: AMM 24-23-33-720-804PROC. REF: AMM 24-23-33-720-804										
24-23-01-900-801-01		RAM AIR TURBINE							Component	ATA:24
PN:GL456-1101-7	MOS/MSC	11-Sep-07	O/C							
SN:162	HRS	431.5								
WC#: 24.015	AFL	233								
PROC. REF: CMM 24-23-01, AMM 24-23-01-000-801, AMM 24-23-01-400-801PROC. REF: CMM 24-23-01, AMM 24-23-01-000-801, AMM 24-23-01-400-801										
24-23-05-900-801-01		GENERATOR- RAT CONTROL							Component	ATA:24
PN:GL456-1201-9	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0279	HRS	0	TSN 0							
WC#: 24.050	AFL	0	TSN 0							
PROC. REF: AMM 24-23-05-000-801, AMM 24-23-05-400-801PROC. REF: AMM 24-23-05-000-801, AMM 24-23-05-400-801										
24-23-09-900-801-01		DEPLOY RAT ACTUATOR							Component	ATA:24
PN:GL456-1301-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0275	HRS	0	TSN 0							
WC#: 24.055	AFL	0	TSN 0							
PROC. REF: AMM 24-23-09-000-801, AMM 24-23-09-400-801PROC. REF: AMM 24-23-09-000-801, AMM 24-23-09-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-23-13-900-801-01 RAT MANUAL RELEASE CABLE								Component	ATA:24
PN:GL456-1401-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0201	HRS	0		TSN 0					
WC#: 24.060	AFL	0		TSN 0					
PROC. REF: AMM 24-23-13-000-801, AMM 24-23-13-400-801PROC. REF: AMM 24-23-13-000-801, AMM 24-23-13-400-801									
24-23-17-900-801-01 DOOR RAT LINK								Component	ATA:24
PN:GL456-1501-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0295	HRS	0		TSN 0					
WC#: 24.065	AFL	0		TSN 0					
PROC. REF: AMM 24-23-17-000-801, AMM 24-23-17-400-801PROC. REF: AMM 24-23-17-000-801, AMM 24-23-17-400-801									
24-23-21-900-801-01 RAT RETRACTION PUMP								Component	ATA:24
PN:GL456-1701-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:C0204	HRS	0		TSN 0					
WC#: 24.070	AFL	0		TSN 0					
PROC. REF: AMM 24-23-21-000-801, AMM 24-23-21-400-801PROC. REF: AMM 24-23-21-000-801, AMM 24-23-21-400-801									
24-23-25-900-801-01 RAT UPLOCK								Component	ATA:24
PN:GL456-1601-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0273	HRS	0		TSN 0					
WC#: 24.075	AFL	0		TSN 0					
PROC. REF: AMM 24-23-25-000-801, AMM 24-23-25-400-801PROC. REF: AMM 24-23-25-000-801, AMM 24-23-25-400-801									
24-24-01-900-801-01 NO.1 LH ENGINE GENERATOR CONTROL UNIT GCU								Component	ATA:24
PN:GL511-3104-1	MOS/MSC	29-Apr-19	O/C	TSR 1					
SN:2044	HRS	6451.1		TSR 0					
WC#: 24.080	AFL	3322		TSR 0					
Special Properties: TRACKED ITEM									
PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801									
24-24-01-900-801-02 NO.2 LH ENGINE GENERATOR CONTROL UNIT GCU								Component	ATA:24
PN:GL511-3104-1	MOS/MSC	21-Oct-23	O/C						
SN:1056	HRS	8064.2							
WC#: 24.080	AFL	4287							
PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-24-01-900-801-03		NO.3 RH ENGINE GENERATOR CONTROL UNIT GCU						Component	ATA:24
PN:GL511-3104-1	MOS/MSC	21-Oct-23	O/C						
SN:1431	HRS	8064.2							
WC#: 24.085	AFL	4287							
PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801									
24-24-01-900-801-04		NO.4 RH ENGINE GENERATOR CONTROL UNIT GCU						Component	ATA:24
PN:GL511-3104-1	MOS/MSC	11-Feb-09	O/C						
SN:1431	HRS	1028.8							
WC#: 24.085	AFL	571							
PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801									
24-24-01-900-801-05		NO.5 APU GENERATOR CONTROL UNIT GCU						Component	ATA:24
PN:GL511-3104-1	MOS/MSC	21-Oct-23	O/C						
SN:1355	HRS	8064.2							
WC#: 24.090	AFL	4287							
PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801PROC. REF: AMM 24-24-01-000-801, AMM 24-24-01-400-801									
24-25-00-201		DISCARD OF THE NO. 1 (LH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER						Service	ATA:24
	MOS	17-Aug-25							
	HRS	8646.2	3000 (+50/-50)	Adj 50	11696.2	11746.2	2777.6 (+50)		
	AFL	4583							
PROC. REF: AMM 24-12-03-961-801PROC. REF: AMM 24-12-03-961-801									
24-25-00-201		DISCARD OF THE NO. 2 (LH INBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER						Service	ATA:24
	MOS	14-Aug-25							
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
	AFL	4582							
PROC. REF: AMM 24-12-03-961-801PROC. REF: AMM 24-12-03-961-801									
24-25-00-201		DISCARD OF THE NO. 3 (RH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER						Service	ATA:24
	MOS	17-Aug-25							
	HRS	8646.2	3000 (+50/-50)	Adj 50	11696.2	11746.2	2777.6 (+50)		
	AFL	4583							
PROC. REF: AMM 24-12-03-961-801PROC. REF: AMM 24-12-03-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-31-01-900-801-04		NO. 4 TRANSFORMER RECTIFIER UNIT TRU						Component	ATA:24
PN:GL511-2102-1	MOS/MSC	15-Mar-11	O/C						
SN:B1858	HRS	2052.9							
WC#: 24.095	AFL	1112							
PROC. REF: AMM 24-31-01-000-801, AMM 24-31-01-400-801PROC. REF: AMM 24-31-01-000-801, AMM 24-31-01-400-801									
24-32-01-203		RESTORATION OF THE AVIONICS BATTERY						Service	ATA:24
PN:GL511-2201-3	MOS	15-May-26	8 (+10%/-10%)		15-Jan-27	08-Feb-27	204 d (+24)	MRB	
SN:107612	HRS	8871.6							
WC#: 24.100	AFL	4688							
PROC. REF: BULLETINS , AMM 24-32-01-610-802PROC. REF: BULLETINS , AMM 24-32-01-610-802									
24-32-01-900-801-01		AVIONICS BATTERY						Component	ATA:24
PN:GL511-2201-3	MOS/MSC	15-May-26	O/C	TSO 0					
SN:107612	HRS	8871.6		TSO 0					
WC#: 24.100	AFL	4688		TSO 0					
PROC. REF: AMM 24-32-01-000-801, AMM 24-32-01-400-801PROC. REF: AMM 24-32-01-000-801, AMM 24-32-01-400-801									
24-32-05-900-801-01		AVIONIC BAY BATTERY CHARGER						Component	ATA:24
PN:GL511-2401-9	MOS/MSC	09-Sep-08	O/C	TSR 2					
SN:E687	HRS	894.9		TSN 20, TSR 0					
WC#: 24.105	AFL	484		TSN 6, TSR 0					
PROC. REF: CMM 24-32-01, AMM 24-32-05-000-801, AMM 24-32-05-400-801PROC. REF: CMM 24-32-01, AMM 24-32-05-000-801, AMM 24-32-05-400-801									
24-32-05-900-801-02		APU BATTERY CHARGER						Component	ATA:24
PN:GL511-2401-9	MOS/MSC	07-Oct-05	O/C						
SN:D514	HRS	0							
WC#: 24.110	AFL	0							
PROC. REF: CMM 24-32-01, AMM 24-32-05-000-801, AMM 24-32-05-400-801PROC. REF: CMM 24-32-01, AMM 24-32-05-000-801, AMM 24-32-05-400-801									
24-32-09-203		RESTORATION OF THE APU BATTERY						Service	ATA:24
PN:GL511-2301-5	MOS	15-May-26	8 (+10%/-10%)	Adj 16d	31-Jan-27	24-Feb-27	220 d (+24)	MRB	
SN:100702	HRS	8871.6							
WC#: 24.010	AFL	4688							
PROC. REF: BULLETINS , AMM 24-32-09-610-802PROC. REF: BULLETINS , AMM 24-32-09-610-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-32-09-900-801-01 APU BATTERY								Component	ATA:24
PN:GL511-2301-5	MOS/MSC	15-May-26	O/C	TSO 0					
SN:100702	HRS	8871.6		TSO 0					
WC#: 24.010	AFL	4688		TSO 0					
PROC. REF: AMM 24-32-09-000-801, AMM 24-32-09-400-801PROC. REF: AMM 24-32-09-000-801, AMM 24-32-09-400-801									
24-41-01-900-801-01 CTA CURRENT TRANSFORMER								Component	ATA:24
PN:GL516-1101-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1463	HRS	0		TSN 0					
WC#: 24.115	AFL	0		TSN 0					
PROC. REF: AMM 24-41-01-000-801, AMM 24-41-01-400-801PROC. REF: AMM 24-41-01-000-801, AMM 24-41-01-400-801									
24-51-17-900-801-01 AC TO DC CONVERTER								Component	ATA:24
PN:1707580B	MOS/MSC	15-Oct-24	O/C	TSR 4					
SN:PR2012090019	HRS	8551.1		TSR 0					
WC#: 24.120	AFL	4538		TSR 0					
PROC. REF: AMM 24-51-17-000-801, AMM 24-51-17-400-801PROC. REF: AMM 24-51-17-000-801, AMM 24-51-17-400-801									
24-51-21-900-801-01 EPQM CARD								Component	ATA:24
PN:770563B	MOS/MSC	20-Nov-08	O/C	TSR 3					
SN:12990014	HRS	939.1		TSR 0					
WC#: 24.125	AFL	512		TSR 0					
PROC. REF: AMM 24-51-21-000-801, AMM 24-51-21-400-801PROC. REF: AMM 24-51-21-000-801, AMM 24-51-21-400-801									
24-51-37-900-801-01 K2 ACPC ZC-SERIES CONTACTOR								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.130	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-02 K3 ACPC ZC-SERIES CONTACTOR								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.135	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-51-37-900-801-03		K5 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.140	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-04		K7 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.145	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-05		K8 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.150	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-06		K10 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.155	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-07		K11 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.160	AFL	0		TSN 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									
24-51-37-900-801-08		K13 ACPC ZC-SERIES CONTACTOR						Component	ATA:24
PN:5911739-1	MOS/MSC	24-Nov-18	O/C	TSR 96					
SN:01994	HRS	6202.9		TSR 0					
WC#: 24.165	AFL	3186		TSR 0					
PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801PROC. REF: AMM 24-51-37-000-801, AMM 24-51-37-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-51-41-900-801-01		K4 CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.170	AFL	0		TSN 0					
PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801									
24-51-41-900-801-02		K6 CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.175	AFL	0		TSN 0					
PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801									
24-51-41-900-801-03		K9 CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.180	AFL	0		TSN 0					
PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801									
24-51-41-900-801-04		K12 CONTACTOR						Component	ATA:24
PN:1714139	MOS/MSC	24-Feb-15	O/C	TSN 0					
SN:03744	HRS	4146.2		TSN 0					
WC#: 24.185	AFL	2162		TSN 0					
PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801									
24-51-41-900-801-05		K1 CONTACTOR						Component	ATA:24
PN:5911747-1	MOS/MSC	11-Feb-08	O/C						
SN:00222	HRS	569.9							
WC#: 24.190	AFL	328							
PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801PROC. REF: AMM 24-51-41-000-801, AMM 24-51-41-400-801									
24-51-53-900-801-01		AC POWER CENTER						Component	ATA:24
PN:GL512-1101-17	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0402	HRS	0		TSN 0					
WC#: 24.195	AFL	0		TSN 0					
PROC. REF: CMM 24-51-02, AMM 24-51-53-000-801, AMM 24-51-53-400-801PROC. REF: CMM 24-51-02, AMM 24-51-53-000-801, AMM 24-51-53-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-52-01-900-801-01 CIRCUIT BREAKER PANEL								Component	ATA:24
PN:GL513-1101-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0374	HRS	0		TSN 0					
WC#: 24.200	AFL	0		TSN 0					
PROC. REF: AMM 24-52-01-000-801, AMM 24-52-01-400-801PROC. REF: AMM 24-52-01-000-801, AMM 24-52-01-400-801									
24-52-05-900-801-01 CCBP H-SERIES CONTACTOR								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.205	AFL	0		TSN 0					
PROC. REF: AMM 24-52-05-000-801, AMM 24-52-05-400-801PROC. REF: AMM 24-52-05-000-801, AMM 24-52-05-400-801									
24-61-00-900-801-01 DCPC DC POWER CENTER								Component	ATA:24
PN:770703C	MOS/MSC	07-Apr-16	O/C	TSR 96					
SN:0405	HRS	4778.2		TSR 3905.8					
WC#: 24.210	AFL	2479		TSR 2007					
PROC. REF: AMM 24-61-00-000-801, AMM 24-61-00-400-801PROC. REF: AMM 24-61-00-000-801, AMM 24-61-00-400-801									
24-61-00-900-801-02 DCPC DC POWER CENTER								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.210	AFL	0		TSN 0					
PROC. REF: AMM 24-61-00-000-801, AMM 24-61-00-400-801PROC. REF: AMM 24-61-00-000-801, AMM 24-61-00-400-801									
24-61-09-900-801-01 NO. 1 DCPC CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.215	AFL	0		TSN 0					
PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801									
24-61-09-900-801-02 NO. 2 DCPC CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.215	AFL	0		TSN 0					
PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-61-09-900-801-03 NO. 3 DCPC CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.215	AFL	0		TSN 0					
PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801PROC. REF: AMM 24-61-09-000-801, AMM 24-61-09-400-801									
24-61-13-900-801-01 NO. 1 DCPC DCPQM CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.220	AFL	0		TSN 0					
PROC. REF: AMM 24-61-13-000-801, AMM 24-61-13-400-801PROC. REF: AMM 24-61-13-000-801, AMM 24-61-13-400-801									
24-61-13-900-801-02 NO. 2 DCPC DCPQM CARD								Component	ATA:24
PN:772243B	MOS/MSC	14-Mar-11	O/C						
SN:12990015	HRS	2052.9							
WC#: 24.220	AFL	1112							
PROC. REF: AMM 24-61-13-000-801, AMM 24-61-13-400-801PROC. REF: AMM 24-61-13-000-801, AMM 24-61-13-400-801									
24-61-33-900-801-01 DCPC BATTERY/RAT IF CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.225	AFL	0		TSN 0					
PROC. REF: AMM 24-61-33-000-801, AMM 24-61-33-400-801PROC. REF: AMM 24-61-33-000-801, AMM 24-61-33-400-801									
24-61-37-900-801-01 DCPC SPDA FEEDER CARD								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.230	AFL	0		TSN 0					
PROC. REF: AMM 24-61-37-000-801, AMM 24-61-37-400-801PROC. REF: AMM 24-61-37-000-801, AMM 24-61-37-400-801									
24-61-53-900-801-01 K1 DCPC L-SERIES CONTACTOR								Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.235	AFL	0		TSN 0					
PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-61-53-900-801-02		K2 DCPC L-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.240	AFL	0		TSN 0					
PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801									
24-61-53-900-801-03		K3 DCPC L-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.245	AFL	0		TSN 0					
PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801									
24-61-53-900-801-04		K4 DCPC L-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.250	AFL	0		TSN 0					
PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801									
24-61-53-900-801-05		K5 DCPC L-SERIES CONTACTOR						Component	ATA:24
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.255	AFL	0		TSN 0					
PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801PROC. REF: AMM 24-61-53-000-801, AMM 24-61-53-400-801									
24-62-01-900-801-01		NO. 1 SPDA SECONDARY POWER DISTRIBUTION						Component	ATA:24
PN:GL512-3201-13	MOS/MSC	15-Apr-19	O/C						
SN:1187	HRS	6418.9							
WC#: 24.260	AFL	3306							
PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801									
24-62-01-900-801-02		NO. 2 SPDA SECONDARY POWER DISTRIBUTION						Component	ATA:24
PN:GL512-3201-13	MOS/MSC	08-Feb-08	O/C						
SN:1187	HRS	569.9							
WC#: 24.260	AFL	328							
PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
24-62-01-900-801-03	NO. 3 SPDA SECONDARY POWER DISTRIBUTION							Component	ATA:24
PN:GL512-3201-13	MOS/MSC	15-Apr-19	O/C						
SN:0759	HRS	6418.9							
WC#: 24.260	AFL	3306							
PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801									
24-62-01-900-801-04	NO. 4 SPDA SECONDARY POWER DISTRIBUTION							Component	ATA:24
PN:GL512-3201-13	MOS/MSC	07-Oct-05	O/C						
SN:1131	HRS	0							
WC#: 24.260	AFL	0							
PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801PROC. REF: AMM 24-62-01-000-801, AMM 24-62-01-400-801									
24-62-05-900-801-01	APU START (ASCA) CONTACTOR							Component	ATA:24
PN:GL512-3301-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0442	HRS	0		TSN 0					
WC#: 24.265	AFL	0		TSN 0					
PROC. REF: AMM 24-62-05-000-801, AMM 24-62-05-400-801PROC. REF: AMM 24-62-05-000-801, AMM 24-62-05-400-801									
24-64-00-201 ^S	OPERATIONAL TEST OF THE DC OVERRIDE SYSTEM							Service	ATA:24
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500 (+50/-50)						
	AFL	4570							
PROC. REF: AMM 24-64-00-710-801PROC. REF: AMM 24-64-00-710-801									
24-70-01-900-801-01	LH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT							Component	ATA:24
PN:GL542-3101-13	MOS/MSC	11-May-16	O/C	TSR 3					
SN:1617	HRS	4817.9		TSN 3684, TSR 0					
WC#: 24.270	AFL	2507		TSN 920, TSR 0					
PROC. REF: AMM 24-70-01-000-801, AMM 24-70-01-400-801PROC. REF: AMM 24-70-01-000-801, AMM 24-70-01-400-801									
24-70-01-900-801-02	RH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT							Component	ATA:24
PN:GL542-3101-19	MOS/MSC	22-Oct-07	O/C	TSR 2					
SN:1088	HRS	464.9		TSR 0					
WC#: 24.270	AFL	261		TSR 0					
PROC. REF: AMM 24-70-01-000-801, AMM 24-70-01-400-801PROC. REF: AMM 24-70-01-000-801, AMM 24-70-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
241202-001	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50043001-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50043-1036	HRS	0		TSN 0					
WC#: 24.005	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
241202-001	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50043001-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50043-1030	HRS	0		TSN 0					
WC#: 24.005	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
241202-002	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50042001-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50043-1035	HRS	0		TSN 0					
WC#: 24.005	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
241202-002	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50042001-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50042-1031	HRS	0		TSN 0					
WC#: 24.005	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242407-701 ^U	CONVERTER								Component ATA:24
PN:933612-02	MOS/MSC	07-Oct-05	O/C						
SN:649	HRS	0							
	AFL	0							
242600-701 ^U	DC TO DC POWER CONVERTER CONVERTER								Component ATA:24
PN:LT-46C	MOS/MSC	07-Oct-05	O/C						
SN:491	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
245113-701	U	#1 ACPC SECONDARY LOGIC CARD							Component ATA:24
PN:77277005A	MOS/MSC	11-Nov-23	O/C						
SN:PR03050011	HRS	8083.7							
	AFL	4298							
245113-702	U	#2 ACPC SECONDARY LOGIC CARD							Component ATA:24
PN:772705A	MOS/MSC	11-Nov-23	O/C						
SN:PR03050008	HRS	8083.7							
	AFL	4298							
245113-703	U	#3 ACPC SECONDARY LOGIC CARD							Component ATA:24
PN:1707918	MOS/MSC	11-Nov-23	O/C	TSN 32					
SN:2020090019	HRS	8083.7		TSN 0					
	AFL	4298		TSN 0					
245113-704	U	#4 ACPC SECONDARY LOGIC CARD							Component ATA:24
PN:1707918	MOS/MSC	11-Nov-23	O/C						
SN:PR20011060010	HRS	8083.7							
	AFL	4298							
245113-721	U	L SERIES CONTACTOR K20 1B HYDRAULIC PUMP							Component ATA:24
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
245113-722	U	L SERIES CONTACTOR K17 2B HYDRAULIC PUMP							Component ATA:24
PN:L-B3N-014	MOS/MSC	12-Nov-23	O/C						
SN:03840	HRS	8083.7							
	AFL	4298							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
245113-723	L SERIES CONTACTOR K24 3A HYDRAULIC PUMP								Component ATA:24
PN:5911738-1	MOS/MSC	22-May-21	O/C	TSN 93					
SN:02572	HRS	7110.4		TSN 0					
	AFL	3729		TSN 0					
245113-724	L SERIES CONTACTOR K14 3B HYDRAULIC PUMP								Component ATA:24
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
245129-702	AC BUS #2 FEED K18								Component ATA:24
PN:5911737-1	MOS/MSC	12-Nov-23	O/C	TSN 199					
SN:N/A	HRS	8083.7		TSN 0					
	AFL	4298		TSN 0					
245133-703	K20 ACPC L SERIES CONTACTOR								Component ATA:24
PN:5911738-1	MOS/MSC	29-Aug-09	O/C	TSN 0					
SN:01757	HRS	1289.6		TSN 0					
	AFL	705		TSN 0					
247010-701	DC POWER DISTRIBUTION EQUIP #1 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	31-Jan-11	O/C	TSN 0					
SN:10101689A	HRS	1983.6		TSN 0					
	AFL	1077		TSN 0					
247010-702	DC POWER DISTRIBUTION EQUIP #2 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	31-Jan-11	O/C	TSN 0					
SN:10101688A	HRS	1983.6		TSN 0					
	AFL	1077		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
247010-703 ^U		DC POWER DISTRIBUTION EQUIP #3 UNIT						Component	ATA:24
PN:10718B01E01	MOS/MSC	05-Jul-23	O/C						
SN:08021035A	HRS	7893.5							
	AFL	4207							
247010-704 ^U		DC POWER DISTRIBUTION EQUIP #4 UNIT						Component	ATA:24
PN:10718B01E01	MOS/MSC	14-Aug-25	O/C	TSR 0					
SN:06030271B	HRS	8645		TSR 0					
	AFL	4582		TSR 0					
247010-705 ^U		DC POWER DISTRIBUTION EQUIP #5 UNIT						Component	ATA:24
PN:10718B01E01	MOS/MSC	20-May-24	O/C	TSR 1					
SN:11011759AB	HRS	8251.1		TSR 0					
	AFL	4407		TSR 0					
247010-706 ^U		DCPDE #6 (DC POWER DISTRIBUTION EQUIP) UNIT						Component	ATA:24
PN:10718B01E01	MOS/MSC	10-May-12	O/C						
SN:11122158C	HRS	2616.8							
	AFL	1382							
247011-701 ^U		DCPDE TRIP SETTING MOD.#1 UNIT						Component	ATA:24
PN:10720B01E00	MOS/MSC	08-Mar-10	O/C						
SN:06020254	HRS	1483.4		TSN 1483.4					
	AFL	836		TSN 836					
247011-702 ^U		DCPDE TRIP SETTING MOD.#2 UNIT						Component	ATA:24
PN:10720B01E00	MOS/MSC	08-Mar-10	O/C	TSN 0					
SN:09071355	HRS	1483.4		TSN 0					
	AFL	836		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
247011-703 ^U		DCPDE TRIP SETTING MOD.#3 UNIT						Component	ATA:24
PN:10720B01E00	MOS/MSC	05-Jul-23	O/C	TSN 0					
SN:22115707	HRS	7893.5		TSN 0					
	AFL	4207		TSN 0					
247011-704 ^U		DCPDE TRIP SETTING MOD.#4 UNIT						Component	ATA:24
PN:10720B01E00	MOS/MSC	16-Feb-11	O/C						
SN:06020259	HRS	1999.4							
	AFL	1085							
247011-705 ^U		DCPDE TRIP SETTING MOD.#5 UNIT						Component	ATA:24
PN:10720B01E00	MOS/MSC	26-Sep-23	O/C	TSN 0					
SN:23025813	HRS	8034.4		TSN 0					
	AFL	4262		TSN 0					
247011-706 ^U		DCPDE TRIP SETTING MOD.#6 UNIT						Component	ATA:24
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
247012-701 ^U		AC POWER DISTRIBUTION EQUIPMENT #1 UNIT						Component	ATA:24
PN:10719B01E01	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:25025263DA	HRS	8645		TSN 0					
	AFL	4582		TSN 0					
247012-702 ^U		AC POWER DISTRIBUTION EQUIPMENT #2 UNIT						Component	ATA:24
PN:10719B01E01	MOS/MSC	18-Sep-19	O/C	TSR 12					
SN:10111808CD	HRS	6664		TSR 0					
	AFL	3428		TSR 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
247012-703 ^U		AC POWER DISTRIBUTION EQUIPMENT #3 UNIT						Component	ATA:24
PN:10719B01E01	MOS/MSC	07-Sep-16	O/C						
SN:10051643CD	HRS	4992.6							
	AFL	2567							
247012-704 ^U		AC POWER DISTRIBUTION EQUIPMENT #4 UNIT						Component	ATA:24
PN:10719B01E01	MOS/MSC	07-Nov-12	O/C						
SN:08010986CD	HRS	2912							
	AFL	1515							
247012-705 ^U		AC POWER DISTRIBUTION EQUIPMENT #5 UNIT						Component	ATA:24
PN:10719B01E01	MOS/MSC	27-Feb-16	O/C						
SN:09011236CD	HRS	4718.4							
	AFL	2447							
247013-701 ^U		ACPDE TRIP SETTING MOD #1 UNIT						Component	ATA:24
PN:10722B01E00	MOS/MSC	31-Jan-11	O/C	TSN 0					
SN:10051388	HRS	1983.6		TSN 0					
	AFL	1077		TSN 0					
247013-702 ^U		ACPDE TRIP SETTING MOD #2 UNIT						Component	ATA:24
PN:10722B01E00	MOS/MSC	18-Sep-19	O/C						
SN:09101245	HRS	6664							
	AFL	3428							
247013-703 ^U		ACPDE TRIP SETTING MOD #3 UNIT						Component	ATA:24
PN:10722B01E00	MOS/MSC	07-Sep-16	O/C	TSN 0					
SN:12102204	HRS	4992.6		TSN 0					
	AFL	2567		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
247013-704 ^U		ACPDE TRIP SETTING MOD #4 UNIT						Component	ATA:24
PN:10722B01E00	MOS/MSC	07-Oct-05	O/C						
SN:05040146	HRS	0							
	AFL	0							
247013-705 ^U		ACPDE TRIP SETTING MOD #5 UNIT						Component	ATA:24
PN:10722B01E00	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
247101-701 ^U		NO.1 (RDE-6000) RELAY DRIVE EQUIPMENT						Component	ATA:24
PN:2052-1-10	MOS/MSC	07-Oct-05	O/C						
SN:206030084	HRS	0							
	AFL	0							
247101-702 ^U		NO.2 (RDE-6000) RELAY DRIVE EQUIPMENT						Component	ATA:24
PN:2052-1-10	MOS/MSC	07-Oct-05	O/C						
SN:206030085	HRS	0							
	AFL	0							
247101-703 ^U		NO.3 (RDE-6000) RELAY DRIVE EQUIPMENT						Component	ATA:24
PN:2052-1-10	MOS/MSC	13-Nov-12	O/C	TSR 3					
SN:207040043	HRS	2912.2		TSR 0					
	AFL	1516		TSR 0					
247101-704 ^U		NO.4 (RDE-6000) RELAY DRIVE EQUIPMENT						Component	ATA:24
PN:2052-1-10	MOS/MSC	07-Oct-05	O/C						
SN:206030089	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
247101-705 ^U	NO.5 (RDE-6000) RELAY DRIVE EQUIPMENT								Component ATA:24
PN:2052-1-10	MOS/MSC	07-Oct-05	O/C						
SN:206030083	HRS	0							
	AFL	0							
258065-706 ^U	NO.3 RH FACING AFT SEAT								Component ATA:24
PN:2524.526.01 (6125B)	MOS/MSC	08-Dec-06	O/C						
SN:050907-06	HRS	88.9							
	AFL	44							
ATA 25 - EQUIPMENT/FURNISHINGS									
25-00-KMLEX-9001 ^U	PERFORM VISUAL INSPECTION OF TAMBOUR DOOR PLACARD: A) ENSURE THAT LEGIBLE "NO STOWAGE" PLACARD IS INSTALLED ON THE GALLEY TAMBOUR DOOR IN THE SINK AREA								Service ATA:25
	MOS	14-Aug-25	15		14-Nov-26		142 d		
	HRS	8645							
	AFL	4582							
									PKG:31
25-00-KMLEX-9002 ^{U S}	PERFORM VISUAL INSPECTION OF GALLEY FLOOR ATTACHMENTS COVERS INSTALLATION A) CHECK FOR SECURITY OF MOUNTING B) CHECK CONDITION COVERS, REPLACE IF EVIDENCE OF DAMAGE IS FOUND								Service ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
25-00-KMLEX-9003 ^U	PERFORM VISUAL INSPECTION OF VANITY PRESSURE MAT OVERRIDE VALVE PLACARD: A) ENSURE THAT FOLLOWING LEGIBLE PLACARD IS INSTALLED NEXT TO EACH VANITY PRESSURE OVERRIDE VALVE.: BAS67038563-101								Service ATA:25
	MOS/MSC		N/A					STLMC	
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-01-52-602	U	DISCARD PADDLE LATCH STRIKERS						Service	ATA:25
	MOS							STLMC	
	HRS	0							
	AFL	0	6000		6000		1293		
25-11-00-900-801-01		PILOT SEAT						Component	ATA:25
PN:GC721-0001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0214	HRS	0		TSN 0					
WC#: 25.015	AFL	0		TSN 0					
PROC. REF: AMM 25-11-00-000-801, AMM 25-11-00-400-801PROC. REF: AMM 25-11-00-000-801, AMM 25-11-00-400-801									
25-11-00-900-801-02		COPILOT SEAT						Component	ATA:25
PN:GC721-0001-10	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0162	HRS	0		TSN 0					
WC#: 25.015	AFL	0		TSN 0					
PROC. REF: AMM 25-11-00-000-801, AMM 25-11-00-400-801PROC. REF: AMM 25-11-00-000-801, AMM 25-11-00-400-801									
25-11-05-201	S	OPERATIONAL TEST OF THE INERTIA REELS AND THE INERTIA REELS CONTROL						Service	ATA:25
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 25.005	AFL	4582							
PROC. REF: AMM 25-11-05-710-801PROC. REF: AMM 25-11-05-710-801									
25-11-09-201	S	GENERAL VISUAL INSPECTION OF THE SAFETY STRAPS						Service	ATA:25
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 25.010	AFL	4582							
PROC. REF: AMM 25-11-09-210-801PROC. REF: AMM 25-11-09-210-801									
25-13-01-900-801-01		LH PILOT FLOOR MAT HEATER						Component	ATA:25
PN:GG434-2042-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:455	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-13-01-900-801-02		RH PILOT FLOOR MAT HEATER						Component	ATA:25
PN:GG434-2042-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:522	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801									
25-13-01-900-801-03		LH COPILOT FLOOR MAT HEATER						Component	ATA:25
PN:GG434-2042-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:543	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801									
25-13-01-900-801-04		RH COPILOT FLOOR MAT HEATER						Component	ATA:25
PN:GG434-2042-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:543	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801PROC. REF: AMM 25-13-01-000-801, AMM 25-13-01-400-801									
25-13-50-601 ^{U S}		OPERATIONAL TEST OF JUMPSEAT INERTIA REELS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
25-13-50-602 ^{U S}		GENERAL VISUAL INSPECTION OF JUMPSEAT SAFETY STRAPS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
25-13-50-603 ^{U S}		OPERATIONAL TEST OF THE JUMPSEAT TRACKING AND LOCKING MECHANISMS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-21-00-601	^{U S}	DETAILED INSPECTION OF PASSENGER SEATS (INCLUDING DIVANS) FOR ATTACHMENT AND LOCKING						Service	ATA:25
	MOS	14-Aug-25	30					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:32
25-21-00-602	^{U S}	DETAILED INSPECTION OF PASSENGER SEATS RESTRAINTS						Service	ATA:25
	MOS	14-Aug-25	30					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:32
25-21-00-603	^{U S}	OPERATIONAL CHECK OF PASSENGER SEAT INERTIA REELS (INCLUDING DIVANS)						Service	ATA:25
	MOS	14-Aug-25	30					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:32
25-23-50-601	^{U S}	OPERATIONAL TEST OF CABIN DOOR ELECTRIC LATCH SYSTEM						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
25-30-50-601	^{U S}	GENERAL VISUAL INSPECTION OF GALLEY WASTE CONTAINER						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-30-50-602	U S	GENERAL VISUAL INSPECTION OF GALLEY APPLIANCES						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
25-30-50-604	U S	DETAILED INSPECTION OF THE GALLEY CHILLER AIR FILTER						Service	ATA:25
	MOS	13-Nov-24						STLMC	
	HRS	8623.4	500						
	AFL	4570							
									PKG:2
25-30-90-601	U S	GENERAL VISUAL INSPECTION OF GALLEY FLOOR ATTACHMENT POINT COVERS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
25-40-50-601	U S	GENERAL VISUAL INSPECTION OF LAVATORY WASTE CONTAINER						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
25-60-00-201		RESTORATION OF THE CREW LIFE VESTS						Service	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	DUE		01-Feb-33 (M)		2413 d	MRB	
SN:L5716645	HRS	8469.9							
	AFL	4493							
Expiry Date: : 01-Feb-33									
PROC. REF: AMM 25-60-00-840-802PROC. REF: AMM 25-60-00-840-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-00-201	RESTORATION OF THE CREW LIFE VESTS								Service ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	DUE		01-Feb-33 (M)		2413 d	MRB	
SN:L5716642	HRS	8469.9							
	AFL	4493							
Expiry Date: : 01-Feb-33									
PROC. REF: AMM 25-60-00-840-802PROC. REF: AMM 25-60-00-840-802									
25-60-00-202	RESTORATION OF THE CREW PROTECTIVE BREATHING EQUIPMENT								Service ATA:25
PN:MR10037N	MOS/MSC	01-May-26	DUE		30-Nov-35 (M)		3445 d	MRB	
SN:E2512164	HRS	8864.7							
	AFL	4682							
Expiry Date: : 30-Nov-35									
PROC. REF: AMM 25-60-00-840-801PROC. REF: AMM 25-60-00-840-801									
25-60-00-203	DISCARD OF THE CREW PROTECTIVE BREATHING EQUIPMENT								Service ATA:25
PN:MR10037N	MOS/MSC	01-May-26	N/A						
SN:E2512164	HRS	8864.7							
	AFL	4682							
PROC. REF: AMM 25-60-00-960-801PROC. REF: AMM 25-60-00-960-801									
25-60-00-208 ^S	DETAILED INSPECTION OF THE CREW LIFE VESTS								Service ATA:25
PN:63600-569	MOS	14-Aug-25						MRB	
SN:L5716645	HRS	8645	1000 (+50/-50)						
	AFL	4582							
PKG:4									
PROC. REF: AMM 25-60-00-220-801PROC. REF: AMM 25-60-00-220-801									
25-60-00-208 ^S	DETAILED INSPECTION OF THE CREW LIFE VESTS								Service ATA:25
PN:63600-569	MOS	14-Aug-25						MRB	
SN:L5716642	HRS	8645	1000 (+50/-50)						
	AFL	4582							
PKG:4									
PROC. REF: AMM 25-60-00-220-801PROC. REF: AMM 25-60-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

25-60-00-209	^S	DETAILED INSPECTION OF THE CREW PROTECTIVE BREATHING EQUIPMENT (PBE)						Service	ATA:25
PN:MR10037N	MOS	01-May-26						MRB	
SN:E2512164	HRS	8864.7	1000 (+50/-50)						
	AFL	4682							
PROC. REF: AMM 25-60-00-220-802PROC. REF: AMM 25-60-00-220-802									PKG:4

25-60-00-210		RESTORATION OF THE CREW FLASHLIGHTS - COPILOT FLASHLIGHT						Service	ATA:25
	MOS/MSC	30-Sep-18	N/A						
	HRS	6194							
	AFL	3180							
PROC. REF: CMM 25-60-02, AMM 25-60-00-840-803PROC. REF: CMM 25-60-02, AMM 25-60-00-840-803									

25-60-00-210		RESTORATION OF THE CREW FLASHLIGHTS - PILOT FLASHLIGHT						Service	ATA:25
	MOS/MSC	30-Sep-18	N/A						
	HRS	6194							
	AFL	3180							
PROC. REF: CMM 25-60-02, AMM 25-60-00-840-803PROC. REF: CMM 25-60-02, AMM 25-60-00-840-803									

25-60-00-601	^{U S}	DETAILED INSPECTION OF THE DITCHING LINES						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31

25-60-00-602	^{U S}	DETAILED INSPECTION OF THE LIFE VESTS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31

25-60-00-604	^{U S}	DETAILED INSPECTION OF THE LIFE RAFTS						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

25-60-00-607	U S	DETAILED INSPECTION OF THE SMOKE HOODS (SEE SMOKE HOODS)						Service	ATA:25
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31

25-60-00-900-801-01	PILOT LIFE VEST							Component	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	O/C	TSN 19					
SN:L5716645	HRS	8469.9		TSN 0					
	AFL	4493		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

25-60-00-900-801-02	COPILOT LIFE VEST							Component	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	O/C	TSN 19					
SN:L5716642	HRS	8469.9		TSN 0					
	AFL	4493		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

25-60-00-900-802-01	FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - PBE							Component	ATA:25
PN:MR10037N	MOS/MSC	01-May-26	H/T	TSN 0					
SN:E2512164	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					
PROC. REF: CMM 25-2499-200PROC. REF: CMM 25-2499-200									

25-60-01-900-801-01	PILOT FLASHLIGHT							Component	ATA:25
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-60-01-000-801, AMM 25-60-01-400-801PROC. REF: AMM 25-60-01-000-801, AMM 25-60-01-400-801									

25-60-01-900-801-02	COPILOT FLASHLIGHT							Component	ATA:25
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

PROC. REF: AMM 25-60-01-000-801, AMM 25-60-01-400-801PROC. REF: AMM 25-60-01-000-801, AMM 25-60-01-400-801

25-60-01-900-801-07 PILOT FLASHLIGHT BATTERY									Component	ATA:25
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REFPROC. REF: AMM NO REF										

25-60-01-900-801-08 COPILOT FLASHLIGHT BATTERY									Component	ATA:25
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM NO REFPROC. REF: AMM NO REF										

25-61-00-201 OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM									Service	ATA:25
PN:453-5004	MOS	14-Aug-25	12 (+10%/-10%)	14-Aug-26	20-Sep-26	50 d (+37)	MRB			
SN:12399	HRS	8645								
WC#: 25.020	AFL	4582								
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801										

25-61-01-201 DISCARD OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY									Service	ATA:25
PN:452-0133	MOS/MSC	10-Nov-23	DUE	28-Feb-29 (M)		979 d	MRB			
SN:1004342-025	HRS	8080.9								
WC#: 25.020	AFL	4296								
PROC. REF: AMM 25-61-01-961-801PROC. REF: AMM 25-61-01-961-801										

25-61-01-900-801-01 EMERGENCY LOCATOR TRANSMITTER									Component	ATA:25
PN:453-5004	MOS/MSC	10-Nov-23	O/C	TSO 0						
SN:12399	HRS	8080.9		TSO 0						
WC#: 25.020	AFL	4296		TSO 0						
PROC. REF: AMM 25-61-01-000-801, AMM 25-61-01-400-801PROC. REF: AMM 25-61-01-000-801, AMM 25-61-01-400-801										

25-61-01-900-802-01 ELT BATTERY									Component	ATA:25
PN:452-0133	MOS/MSC	10-Nov-23	O/C	TSN 0						
SN:1004342-025	HRS	8080.9		TSN 0						
	AFL	4296		TSN 0						
PROC. REF: AMM 25-61-01-000-802, AMM 25-61-01-400-802PROC. REF: AMM 25-61-01-000-802, AMM 25-61-01-400-802										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25-61-05-900-801-01		ELT ANTENNA						Component	ATA:25
PN:110-328-01	MOS/MSC	09-Jul-15	O/C	TSN 0					
SN:9781-01	HRS	4270.4		TSN 0					
WC#: 25.025	AFL	2220		TSN 0					
PROC. REF: AMM 25-61-05-000-801, AMM 25-61-05-400-801PROC. REF: AMM 25-61-05-000-801, AMM 25-61-05-400-801									
25-61-17-900-801-01		L/H ELT NAV INTERFACE UNIT						Component	ATA:25
PN:453-6500	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:02577	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-61-17-000-801, AMM 25-61-17-400-801PROC. REF: AMM 25-61-17-000-801, AMM 25-61-17-400-801									
25-CUS-25-00 ^U		APU HOUR METER						Component	ATA:25
PN:WE3876284-2	MOS/MSC	07-Oct-24	O/C	TSN 0					
SN:N/A	HRS	8543.1		TSN 0					
	AFL	4531		TSN 0					
251010-701 ^U		PILOT SEAT OUTBD HYDRO-LOCK HEIGHT ADJUSTMENT ACTUATOR						Component	ATA:25
PN:871544-405	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
251010-702 ^U		PILOT SEAT INBD HYDRO-LOCK HEIGHT ADJUSTMENT ACTUATOR						Component	ATA:25
PN:871544-405	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
251010-703 ^U		COPILOT SEAT INBD HYDRO-LOCK HEIGHT ADJUSTMENT ACTUATOR						Component	ATA:25
PN:871544-401	MOS/MSC	10-Feb-23	O/C	TSN 3					
SN:22-17423M1-0027	HRS	7761.3		TSN 0					
	AFL	4124		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
251010-704 ^U		COPILOT SEAT OUTBD HYDRO-LOCK HEIGHT ADJUSTMENT ACTUATOR						Component	ATA:25
PN:871544-401	MOS/MSC	10-Feb-23	O/C	TSN 3					
SN:22-17424M1-0005	HRS	7761.3		TSN 0					
	AFL	4124		TSN 0					
252002-701 ^U		PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS						Component	ATA:25
PN:107STC-191	MOS/MSC	21-Nov-24	O/C	TSO 6					
SN:0032Q07P	HRS	8628.8		TSO 376.9					
	AFL	4574		TSO 165					
252002-701A ^U		CHECK PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS - BLOWER AND BATTERY (PERIODIC INSPECTION)						Service	ATA:25
PN:107STC-191	DAYS	01-May-26	90	30-Jul-26		35 d		STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0032Q07P	HRS	8864.7							
	AFL	4682							
252002-701B ^U		RETURN PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR BIENNIAL INSPECTION						Service	ATA:25
PN:107STC-191	MOS	20-May-24	24	27-Jul-26 (M)		32 d		STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0032Q07P	HRS								
	AFL								
252002-701C ^U		RETURN PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR OVERHAUL						Service	ATA:25
PN:107STC-191	MOS	27-May-16	120	27-Jul-26 (M)		32 d		STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0032Q07P	HRS	4832.5							
	AFL	2518							
252002-702 ^U		COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS						Component	ATA:25
PN:107STC-192	MOS/MSC	25-May-24	O/C	TSO 0					
SN:0033Q07P	HRS	8251.9		TSO 0					
	AFL	4409		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252002-702A ^U		CHECK COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS - BLOWER AND BATTERY (PERIODIC INSPECTION)						Service	ATA:25
PN:107STC-192	DAYS	01-May-26	90		30-Jul-26		35 d	STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0033Q07P	HRS	8864.7							
	AFL	4682							
252002-702B ^U		RETURN COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR BIENNIAL INSPECTION						Service	ATA:25
PN:107STC-192	MOS	20-May-24	24		27-Jul-26 (M)		32 d	STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0033Q07P	HRS								
	AFL								
252002-702C ^U		RETURN COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR OVERHAUL						Service	ATA:25
PN:107STC-192	MOS	30-Dec-25	120		30-Dec-35		3475 d	STC-SUPPLEMENTAL TYPE CERTIFICATE	
SN:0033Q07P	HRS	8766.8							
	AFL	4630							
256001-701 ^U		SMOKE HOOD FRONT AFT FACING LEFT CHAIR FLT STA#431						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C						
SN:R2202499	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-701A ^U		RESTORE SMOKE HOOD FRONT AFT FACING LEFT CHAIR FLT STA#431 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202499	HRS	8049.4							
	AFL	4271							
256001-702 ^U		SMOKE HOOD FRONT AFT FACING RIGHT CHAIR FLT STA#431						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202327	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256001-702A ^U		RESTORE SMOKE HOOD FRONT AFT FACING RIGHT CHAIR FLT STA#431 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202327	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-703 ^U		SMOKE HOOD FWD FACING LEFT CHAIR FLT STA#501						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202478	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-703A ^U		RESTORE SMOKE HOOD FWD FACING LEFT CHAIR FLT STA#501 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202478	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-704 ^U		SMOKE HOOD FWD FACING RIGHT CHAIR FLT STA#491						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202482	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-704A ^U		RESTORE SMOKE HOOD FWD FACING RIGHT CHAIR FLT STA#491 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202482	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-705 ^U		SMOKE HOOD AFT FACING RIGHT CHAIR FLT STA#534						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202539	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256001-705A ^U		RESTORE SMOKE HOOD AFT FACING RIGHT CHAIR FLT STA#534 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202539	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-706 ^U		SMOKE HOOD FWD FACING RIGHT CHAIR FLT STA#598						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202343	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-706A ^U		RESTORE SMOKE HOOD FWD FACING RIGHT CHAIR FLT STA#598 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202343	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-707 ^U		SMOKE HOOD AFT FACING LEFT AFT CHAIR FLT STA#665						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202340	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-707A ^U		RESTORE SMOKE HOOD AFT FACING LEFT AFT CHAIR FLT STA#665 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202340	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-708 ^U		SMOKE HOOD FWD FACING LEFT AFT CHAIR STA#736						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2203481	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256001-708A ^U		RESTORE SMOKE HOOD FWD FACING LEFT AFT CHAIR STA#736 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2203481	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-709 ^U		SMOKE HOOD #1 LOW CABINET FLT STA#632						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202352	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-709A ^U		RESTORE SMOKE HOOD #1 LOW CABINET FLT STA#632 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202352	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-710 ^U		SMOKE HOOD #2 LOW CABINET FLT STA#632						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202350	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-710A ^U		RESTORE SMOKE HOOD #2 LOW CABINET FLT STA#632 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202350	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-711 ^U		SMOKE HOOD #3 LOW CABINET FLT STA#632						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202370	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256001-711A ^U		RESTORE SMOKE HOOD #3 LOW CABINET FLT STA#632 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202370	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-712 ^U		SMOKE HOOD #1 RIGHT AFT 16G DIVAN FWD DOOR FLT STA #676						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202379	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-712A ^U		RESTORE SMOKE HOOD #1 RIGHT AFT 16G DIVAN FWD DOOR FLT STA #676 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202379	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-713 ^U		SMOKE HOOD #2 RIGHT AFT 16G DIVAN FWD DOOR FLT STA #676						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202515	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-713A ^U		RESTORE SMOKE HOOD #2 RIGHT AFT 16G DIVAN FWD DOOR FLT STA #676 (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202515	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-714 ^U		SMOKE HOOD #1 RIGHT AFT 16G DIVAN AFT DOOR FLT STA#730						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R2202498	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256001-714A ^U RESTORE SMOKE HOOD #1 RIGHT AFT 16G DIVAN AFT DOOR FLT STA#730 (25-60-00-608) Service ATA:25									
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R2202498	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256001-715 ^U SMOKE HOOD #2 RIGHT AFT 16G DIVAN AFT DOOR FLT STA#730 Component ATA:25									
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C	TSN 0					
SN:R220254	HRS	8049.4		TSN 0					
	AFL	4271		TSN 0					
256001-715A ^U RESTORE SMOKE HOOD #2 RIGHT AFT 16G DIVAN AFT DOOR FLT STA#730 (25-60-00-608) Service ATA:25									
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	STLMC	
SN:R220254	HRS	8049.4							
	AFL	4271							
Expiry Date: : 01-Sep-32									
256002-701 ^U PILOT SMOKE HOOD Component ATA:25									
PN:MR-10010N	MOS/MSC	19-Aug-20	O/C	TSN 16					
SN:R1900442	HRS	6930.7		TSN 0					
	AFL	3600		TSN 0					
256002-701A ^U RESTORE PILOT SMOKE HOOD (25-60-00-608) Service ATA:25									
PN:MR-10010N	MOS/MSC	19-Aug-20	DUE		01-Sep-29 (M)		1164 d	STLMC	
SN:R1900442	HRS	6930.7							
	AFL	3600							
256002-702 ^U COPILOT SMOKE HOOD Component ATA:25									
PN:MR-10010N	MOS/MSC	19-Aug-20	O/C	TSN 16					
SN:R1900830	HRS	6930.7		TSN 0					
	AFL	3600		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256002-702A	U	RESTORE COPILOT SMOKE HOOD (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	19-Aug-20	DUE		01-Sep-29 (M)		1164 d	STLMC	
SN:R1900830	HRS	6930.7							
	AFL	3600							
256002-703	U	JUMP SEAT SMOKE HOOD						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C					CUSTOMER CODE	
SN:R2202498	HRS	8049.4							
	AFL	4271							
256002-703A	U	RESTORE JUMPSEAT SMOKE HOOD (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	VENDOR RECOMMENDATION	
SN:R2202498	HRS	8049.4							
	AFL	4271							
256002-704	U	FORWARD CREW REST SMOKE HOOD						Component	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	O/C					CUSTOMER CODE	
SN:R2202529	HRS	8049.4							
	AFL	4271							
256002-704A	U	RESTORE FORWARD CREW REST SMOKE HOOD (25-60-00-608)						Service	ATA:25
PN:MR-10010N	MOS/MSC	04-Oct-23	DUE		01-Sep-32 (M)		2260 d	VENDOR RECOMMENDATION	
SN:R2202529	HRS	8049.4							
	AFL	4271							
256040-701	U	JUMP SEAT LIFE VEST						Component	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	O/C	TSN 19					
SN:L5716648	HRS	8469.9		TSN 0					
	AFL	4493		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256040-701A ^U		RESTORATION JUMP SEAT LIFE VEST (25-60-00-603)						Service	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	DUE		01-Feb-33 (M)		2413 d	STLMC	
SN:L5716648	HRS	8469.9							
	AFL	4493							
Special Properties: TRACKED ITEM			Expiry Date: : 01-Feb-33						
256040-702A ^U		RESTORATION CREW REST FWD LIFE VEST (25-60-00-603)						Service	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	DUE		01-Feb-33 (M)		2413 d	STLMC	
SN:L5716646	HRS	8469.9							
	AFL	4493							
Special Properties: TRACKED ITEM			Expiry Date: : 01-Feb-33						
256040-703 ^U		CREW REST AFT LIFE VEST						Component	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	O/C	TSN 19					
SN:L5716649	HRS	8469.9		TSN 0					
	AFL	4493		TSN 0					
256040-703A ^U		RESTORATION CREW REST AFT LIFE VEST (25-60-00-603)						Service	ATA:25
PN:63600-569	MOS/MSC	03-Sep-24	DUE		01-Feb-33 (M)		2413 d	STLMC	
SN:L5716649	HRS	8469.9							
	AFL	4493							
			Expiry Date: : 01-Feb-33						
256041-701 ^U		LEFT STA #431.4 LIFE VEST						Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0					
SN:26041600011	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					
256041-701A ^U		RESTORATION LEFT STA #431.4 LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC	
SN:26041600011	HRS	8864.7							
	AFL	4682							
			Expiry Date: : 20-Jan-36						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

256041-702 ^U		LEFT STA #501.6 LIFE VEST						Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0					
SN:26041600040	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					

256041-702A ^U		RESTORATION LEFT STA #501.6 LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE	20-Jan-36 (M)		3496 d	STLMC		
SN:26041600040	HRS	8864.7							
	AFL	4682							
Expiry Date: : 20-Jan-36									

256041-703 ^U		LEFT STA #534.6 OUTBD CLUB LIFE VEST						Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0					
SN:26041600041	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					

256041-703A ^U		RESTORATION LEFT STA #534.6 OUTBD CLUB LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE	20-Jan-36 (M)		3496 d	STLMC		
SN:26041600041	HRS	8864.7							
	AFL	4682							
Expiry Date: : 20-Jan-36									

256041-704 ^U		LEFT STA #534.6 INBD CLUB LIFE VEST						Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0					
SN:26041600039	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT / FURNISHINGS										
256041-704A ^U		RESTORATION LEFT STA #534.6 INBD CLUB LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600039	HRS	8864.7								
	AFL	4682								
			Expiry Date: : 20-Jan-36							
256041-705 ^U		RIGHT STA #491.1 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0						
SN:26041600050	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-705A ^U		RESTORATION RIGHT STA #491.1 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600050	HRS	8864.7								
	AFL	4682								
			Expiry Date: : 20-Jan-36							
256041-706 ^U		LEFT STA #763.3 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0						
SN:26041600029	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-706A ^U		RESTORATION LEFT STA #763.3 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600029	HRS	8864.7								
	AFL	4682								
Special Properties: TRACKED ITEM			Expiry Date: : 20-Jan-36							
256041-707 ^U		RIGHT STA #431.4 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0						
SN:26041600042	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256041-707A ^U		RESTORATION RIGHT STA #431.4 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600042	HRS	8864.7								
	AFL	4682								
Special Properties: TRACKED ITEM			Expiry Date: : 20-Jan-36							
256041-708 ^U		RIGHT STA #534.8 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0						
SN:26041600030	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-708A ^U		RESTORATION RIGHT STA #534.8 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600030	HRS	8864.7								
	AFL	4682								
Special Properties: TRACKED ITEM			Expiry Date: : 20-Jan-36							
256041-709 ^U		RIGHT STA #598.6 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0						
SN:26041600038	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-709A ^U		RESTORATION RIGHT STA #598.6 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600038	HRS	8864.7								
	AFL	4682								
			Expiry Date: : 20-Jan-36							
256041-710 ^U		RIGHT STA #703.5 DIVAN MIDDLE LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0						
SN:26041600017	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT / FURNISHINGS									
256041-710A ^U		RESTORATION RIGHT STA #703.5 DIVAN MIDDLE LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC	
SN:26041600017	HRS	8864.7							
	AFL	4682							
			Expiry Date: : 20-Jan-36						
256041-711 ^U		RIGHT STA #730.8 DIVAN AFT LIFE VEST						Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0					
SN:26041600016	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					
256041-711A ^U		RESTORATION RIGHT STA #730.8 DIVAN AFT LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC	
SN:26041600016	HRS	8864.7							
	AFL	4682							
			Expiry Date: : 20-Jan-36						
256041-712 ^U		RIGHT STA #676.1 DIVAN FWD LIFE VEST						Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0					
SN:26041600031	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					
256041-712A ^U		RESTORATION RIGHT STA #676.1 DIVAN FWD LIFE VEST (25-60-00-603)						Service	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC	
SN:26041600031	HRS	8864.7							
	AFL	4682							
Special Properties: TRACKED ITEM			Expiry Date: : 20-Jan-36						
256041-715 ^U		LEFT STA #599.3 OUTBD CLUB LIFE VEST						Component	ATA:25
PN:P01074-201	MOS / MSC	01-May-26	O / C	TSN 0					
SN:26041600010	HRS	8864.7		TSN 0					
	AFL	4682		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 25 - EQUIPMENT/FURNISHINGS										
256041-715A ^U		RESTORATION LEFT STA #599.3 OUTBD CLUB LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600010	HRS	8864.7								
	AFL	4682								
Special Properties: TRACKED ITEM			Expiry Date: : 20-Jan-36							
256041-716 ^U		LEFT STA #599.3 INBD LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0						
SN:2604160003	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-716A ^U		RESTORATION LEFT STA #599.3 INBD LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:2604160003	HRS	8864.7								
	AFL	4682								
			Expiry Date: : 20-Jan-36							
256041-718 ^U		LEFT STA #665.4 LIFE VEST							Component	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	O/C	TSN 0						
SN:26041600009	HRS	8864.7		TSN 0						
	AFL	4682		TSN 0						
256041-718A ^U		RESTORATION LEFT STA #665.4 LIFE VEST (25-60-00-603)							Service	ATA:25
PN:P01074-201	MOS/MSC	01-May-26	DUE		20-Jan-36 (M)		3496 d	STLMC		
SN:26041600009	HRS	8864.7								
	AFL	4682								
			Expiry Date: : 20-Jan-36							
256083-701 ^U		FWD CLOSET EMERGENCY FIRST AID KIT							Component	ATA:25
PN:500097	MOS/MSC	19-Jun-26	O/C	TSN 0	31-Dec-26 (M)		189 d			
SN:121225003	HRS	8918.6		TSN 0						
	AFL	4707		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256083-701A ^U		DETAILED INSPECTION FWD CLOSET EMERGENCY FIRST AID KIT (25-60-00-606) (DO NOT OPEN IF SEALED)						Service	ATA:25
PN:500097	MOS	19-Jun-26	12		19-Jun-27		359 d	STLMC	
SN:121225003	HRS	8918.6							
	AFL	4707							
256083-702 ^U		ENTERTAINMENT CABINET EMERGENCY FIRST AID KIT						Component	ATA:25
PN:500097	MOS/MSC	19-Jun-26	O/C	TSN 0	31-Dec-26 (M)		189 d		
SN:121525005	HRS	8918.6		TSN 0					
	AFL	4707		TSN 0					
256083-702A ^U		DETAILED INSPECTION ENTERTAINMENT CABINET EMERGENCY FIRST AID KIT (25-60-00-606) (DO NOT OPEN IF SEALED)						Service	ATA:25
PN:500097	MOS	19-Jun-26	12		19-Jun-27		359 d	STLMC	
SN:121525005	HRS	8918.6							
	AFL	4707							
256083-703 ^U		AFT BAGGAGE COMPARTMENT EMERGENCY FIRST AID KIT						Component	ATA:25
PN:500097	MOS/MSC	19-Jun-26	O/C	TSN 0	31-Dec-26 (M)		189 d		
SN:121525013	HRS	8918.6		TSN 0					
	AFL	4707		TSN 0					
256083-703A ^U		DETAILED INSPECTION AFT BAGGAGE COMPARTMENT EMERGENCY FIRST AID KIT (25-60-00-606) (DO NOT OPEN IF SEALED)						Service	ATA:25
PN:500097	MOS	19-Jun-26	12		19-Jun-27		359 d	STLMC	
SN:121525013	HRS	8918.6							
	AFL	4707							
256101-701C ^U		RENEW EMERGENCY LOCATOR TRANSMITTER BEACON REGISTRATION						Service	ATA:25
PN:453-5004	MOS	30-Dec-25	24		30-Dec-27		553 d	CUSTOMER CODE	
SN:12399	HRS	8766.8							
	AFL	4630							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256123-9104 ^U		FORWARD CREW REST SHADE						Component	ATA:25
PN:ATG-WS-5124-C051	MOS/MSC	19-Oct-23	O/C	TSR 0					
SN:0231-206	HRS	8061.2		TSR 0					
	AFL	4284		TSR 0					
258052-701 ^U		GALLEY 10.4" LCD MONITOR-						Component	ATA:25
PN:1308520-100	MOS/MSC	15-Apr-19	O/C	TSO 0					
SN:2DX6J	HRS	6418.9		TSO 0					
	AFL	3306		TSO 0					
258055-701 ^U		21.3" (AFT WARDROBE) MONITOR-						Component	ATA:25
PN:866-0022-002	MOS/MSC	15-Apr-19	O/C	TSR 1					
SN:DL0080	HRS	6418.8		TSR 0					
	AFL	3306		TSR 0					
258065-701 ^U		3-PLACE DIVAN (AFT RH) SEAT						Component	ATA:25
PN:GM25280573-1	MOS/MSC	07-Oct-05	O/C						
SN:97925/97926	HRS	0							
	AFL	0							
258065-702 ^U		NO.1 LH SINGLE SEAT						Component	ATA:25
PN:GM25210621-1	MOS/MSC	16-Aug-22	O/C						
SN:050907-01	HRS	7609.7							
	AFL	4027							
258065-703 ^U		NO.2 LH SINGLE SEAT						Component	ATA:25
PN:GM25210621-3	MOS/MSC	16-Aug-22	O/C						
SN:050907-04	HRS	7609.7							
	AFL	4027							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
258065-704 ^U		NO.3 LH SINGLE SEAT						Component	ATA:25
PN:GM25210621-5	MOS/MSC	07-Oct-05	O/C						
SN:050907-09	HRS	0							
	AFL	0							
258065-705 ^U		NO.5 LH FACING AFT SEAT						Component	ATA:25
PN:2524.526.01 (4174A)	MOS/MSC	08-Dec-06	O/C						
SN:050907-02	HRS	88.9							
	AFL	44							
258065-707 ^U		NO.6 LH FWD FACING SEAT						Component	ATA:25
PN:2524.526.01 (4134B)	MOS/MSC	08-Dec-06	O/C						
SN:050907-08	HRS	88.9							
	AFL	44							
258065-708 ^U		NO.1 RH SINGLE SEAT						Component	ATA:25
PN:2524.526.01 (4174B)	MOS/MSC	08-Dec-06	O/C						
SN:050907-03	HRS	88.9							
	AFL	44							
258065-709 ^U		NO.2 RH SINGLE SEAT						Component	ATA:25
PN:2524.526.01 (6124A)	MOS/MSC	08-Dec-06	O/C						
SN:050907-05	HRS	88.9							
	AFL	44							
258065-710 ^U		NO.4 LH SINGLE SEAT						Component	ATA:25
PN:GM25210621-7	MOS/MSC	07-Oct-05	O/C						
SN:050907-10	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
258065-711 ^U	NO.4 RH FACING FWD SEAT								Component ATA:25
PN:2524.526.01 (6126A)	MOS/MSC	08-Dec-06	O/C						
SN:050907-07	HRS	88.9							
	AFL	44							
258084-701 ^U	DEFIBRILLATOR								Component ATA:25
PN:HEARTSTART FRX	MOS/MSC	18-Dec-24	O/C						
SN:BILL-01920	HRS	8641.1							
	AFL	4580							
258084-701A ^U	FUNCTIONAL TEST OF DEFIBRILLATOR AND CHECK BATTERY AND PADS EXPIRATION DATE								Service ATA:25
PN:HEARTSTART FRX	MOS	14-Aug-25	12		14-Aug-26		50 d	CUSTOMER CODE	
SN:BILL-01920	HRS	8645							
	AFL	4582							
258088-701 ^U	PRINTER SERVER								Component ATA:25
PN:J7942A	MOS/MSC	07-Jun-09	O/C						
SN:N/A	HRS	1120.3		TSN 0					
	AFL	641		TSN 0					
259055-701 ^U	CONFIGURATION ALDU MODULE								Component ATA:25
PN:2243262-1	MOS/MSC	07-Oct-05	O/C						
SN:158	HRS	0							
	AFL	0							
259336-701 ^U	LOW CABINET LIFE RAFT								Component ATA:25
PN:1320-FAUL-630-1-108	MOS/MSC	11-Jun-26	O/C	TSN 243, TSO 36					
SN:13UL-00599	HRS	8899.2		TSN 8868.1, TSO 1005.7					
	AFL	4698		TSN 4687, TSO 491					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259336-701B	U	RESTORE LOW CABINET LIFE RAFT (25-60-00-605)						Service	ATA:25
PN:1320-FAUL-630-1-108	MOS	11-Jun-26	36		11-Jun-29		1082 d	STLMC	
SN:13UL-00599	HRS	8899.2							
	AFL	4698							
259336-701C	U	REPLACE LOW CABINET LIFE RAFT ELT BATTERY						Service	ATA:25
PN:1320-FAUL-630-1-108	MOS/MSC	11-Jun-26	DUE		30-Apr-31 (M)		1770 d		
SN:13UL-00599	HRS	8899.2							
	AFL	4698							
Expiry Date: : 30-Apr-31									
259336-701D	U	RENEW LOW CABINET LIFE RAFT BEACON REGISTRATION						Service	ATA:25
PN:1320-FAUL-630-1-108	MOS	11-Jun-26	24		11-Jun-28		717 d	CUSTOMER CODE	
SN:13UL-00599	HRS	8899.2							
	AFL	4698							
259336-702	U	DIVAN LIFE RAFT						Component	ATA:25
PN:1320-FAUL-630-1-136	MOS/MSC	20-May-26	O/C	TSN 242, TSO 0					
SN:13UL-00600	HRS	8875.1		TSN 6880.5, TSO 0					
	AFL	4690		TSN 3575, TSO 0					
259336-702B	U	RESTORE DIVAN LIFE RAFT (25-60-00-605)						Service	ATA:25
PN:1320-FAUL-630-1-136	MOS	20-May-26	36		20-May-29		1060 d	STLMC	
SN:13UL-00600	HRS	8875.1							
	AFL	4690							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259336-702C ^U		REPLACE DIVAN LIFE RAFT ELT BATTERY						Service	ATA:25
PN:1320-FAUL-630-1-136	MOS/MSC	20-May-26	DUE		30-Apr-31 (M)		1770 d		
SN:13UL-00600	HRS	8875.1							
	AFL	4690							
Expiry Date: : 30-Apr-31									
259336-702D ^U		RENEW DIVAN LIFE RAFT BEACON REGISTRATION						Service	ATA:25
PN:1320-FAUL-630-1-136	MOS	30-Dec-25	24		30-Dec-27		553 d	CUSTOMER CODE	
SN:13UL-00600	HRS	8766.8							
	AFL	4630							
259407-701 ^U		PA AMPLIFIER						Component	ATA:25
PN:251-003	MOS/MSC	07-Oct-05	O/C						
SN:1379	HRS	0							
	AFL	0							
259513-701 ^U		JUMP SEAT						Component	ATA:25
PN:1513000-1	MOS/MSC	07-Oct-05	O/C						
SN:30298	HRS	0							
	AFL	0							
259522-701 ^U		CHILLER						Component	ATA:25
PN:319-4	MOS/MSC	20-Feb-18	O/C	TSO 1					
SN:514	HRS	5778.8		TSO 0					
	AFL	2995		TSO 0					
259573-701 ^U		CONTROL DISPLAY UNIT						Component	ATA:25
PN:100-0106-01	MOS/MSC	07-Oct-05	O/C						
SN:0625	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259574-701	U	MOTION DETECTOR						Component	ATA:25
PN:100-0401-11	MOS/MSC	07-Oct-05	O/C						
SN:3163	HRS	0							
	AFL	0							
259574-702	U	MOTION DETECTOR						Component	ATA:25
PN:100-0401-11	MOS/MSC	07-Oct-05	O/C						
SN:3162	HRS	0							
	AFL	0							
259574-703	U	MOTION DETECTOR						Component	ATA:25
PN:100-0401-11	MOS/MSC	07-Oct-05	O/C						
SN:3164	HRS	0							
	AFL	0							
259576-701	U	KEYLESS ENTRY MODULE						Component	ATA:25
PN:100-0651-01	MOS/MSC	07-Oct-05	O/C						
SN:0631	HRS	0							
	AFL	0							
259577-701	U	COCKPIT HANDSET						Component	ATA:25
PN:744000-10-10	MOS/MSC	22-Oct-08	O/C						
SN:0308-4222	HRS	927.8							
	AFL	501							
259578-701	U	AFT WARDROBE CORDLESS BASE STATION						Component	ATA:25
PN:500092-230	MOS/MSC	07-Oct-05	O/C						
SN:240610	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259578-708 ^U	CRADLE UNIT							Component	ATA:25
PN:500095-120	MOS/MSC	07-Oct-05	O/C						
SN:2603B001	HRS	0							
	AFL	0							
259579-703 ^U	CRADLE UNIT							Component	ATA:25
PN:500095-120	MOS/MSC	07-Oct-05	O/C						
SN:2603B007	HRS	0							
	AFL	0							
259579-704 ^U	CRADLE UNIT							Component	ATA:25
PN:500095-120	MOS/MSC	07-Oct-05	O/C						
SN:2603B006	HRS	0							
	AFL	0							
259580-701 ^U	CORDLESS BASE STATION							Component	ATA:25
PN:500092-230	MOS/MSC	07-Oct-05	O/C						
SN:2409136	HRS	0							
	AFL	0							
259580-702 ^U	CORDLESS - AFT WARDROBE BASE STATION							Component	ATA:25
PN:500092-230	MOS/MSC	07-Oct-05	O/C						
SN:240610	HRS	0							
	AFL	0							
259580-703 ^U	R/H FED LEDGE HANDSET BASE STATION							Component	ATA:25
PN:500092-230	MOS/MSC	07-Oct-05	O/C						
SN:2601C005	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259587-701 ^U		LIGHT SENSOR ANTENNA						Component	ATA:25
PN:7014062-901	MOS/MSC	07-Oct-05	O/C						
SN:05080769	HRS	0							
	AFL	0							
259590-701 ^U		OVEN						Component	ATA:25
PN:400-1317-01-L	MOS/MSC	26-Feb-25	O/C	TSR 0					
SN:14-02-53613	HRS	8641.1		TSR 0					
	AFL	4580		TSR 0					
259592-701 ^U		MICROWAVE OVEN						Component	ATA:25
PN:400-2577-01	MOS/MSC	24-Jul-24	O/C	TSR 63					
SN:06-09-39622	HRS	8405.8		TSR 0					
	AFL	4466		TSR 0					
259595-701 ^U		OVEN CONTROLLER						Component	ATA:25
PN:400-1962-01	MOS/MSC	07-Oct-05	O/C						
SN:06-03-38677	HRS	0							
	AFL	0							
259601-701 ^U		DVD/CD PLAYER						Component	ATA:25
PN:866-0025-001	MOS/MSC	26-Feb-25	O/C						
SN:004960	HRS	8641.1							
	AFL	4580							
259601-702 ^U		DVD/CD PLAYER						Component	ATA:25
PN:866-0025-001	MOS/MSC	21-Oct-21	O/C	TSR 1					
SN:004982	HRS	7245.9		TSR 0					
	AFL	3804		TSR 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259601-703 ^U		AIRPLAY DUAL DISC CD/DVD/MP3 PLAYER						Component	ATA:25
PN:866-0025-001	MOS/MSC	29-Jul-20	O/C	TSN 138, TSR 5					
SN:004674	HRS	6914.3		TSR 0					
	AFL	3588		TSR 0					
259601-704 ^U		DVD/CD PLAYER						Component	ATA:25
PN:866-0025-001	MOS/MSC	19-Dec-10	O/C						
SN:004620	HRS	1891.9							
	AFL	1025							
259643-701 ^U		FREQUENCY (AFT) CONVERTER						Component	ATA:25
PN:1-002-0102-1943	MOS/MSC	18-Aug-13	O/C	TSN 85					
SN:HT000647	HRS	3322.5		TSN 3322.5					
	AFL	1730		TSN 1730					
259643-702 ^U		FREQUENCY (FWD) CONVERTER						Component	ATA:25
PN:1-002-0102-1943	MOS/MSC	18-Aug-13	O/C	TSN 0					
SN:HT000563	HRS	3322.5		TSN 0					
	AFL	1730		TSN 0					
259645-701 ^U		VIDEO CONTROL UNIT						Component	ATA:25
PN:100-2415-01	MOS/MSC	07-Oct-05	O/C						
SN:1376	HRS	0							
	AFL	0							
259698-701 ^U		NETWORK PRINTER						Component	ATA:25
PN:6540	MOS/MSC	07-Oct-05	O/C						
SN:MY4AD3P3HX	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259716-701 ^U		AFT CABIN LEFT LAST POSITION WINDOW SHADE ASSY						Component	ATA:25
PN:ATG-WS-5122	MOS/MSC	30-Jul-13	O/C						
SN:0231-110	HRS	3296							
	AFL	1714							
259716-702 ^U		RH NO. 6 WINDOW SHADE						Component	ATA:25
PN:ATG-WS-5122	MOS/MSC	04-Jun-15	O/C						
SN:0231-122	HRS	4228.4							
	AFL	2192							
259716-703 ^U		SHADE ASSY, WINDOW,BOTTOM						Component	ATA:25
PN:ATG-WS-5122	MOS/MSC	26-Jun-22	O/C						
SN:0231-103	HRS	7535.3							
	AFL	3992							
259716-704 ^U		CABIN NO. 4 CABIN RIGHT SIDE SHADE ASSY						Component	ATA:25
PN:ATG-WS-5122	MOS/MSC	18-Aug-23	-						
SN:0231-109	HRS	7971.4							
	AFL	4227							
259716-705 ^U		EMERGENCY EXIT SHADE ASSY						Component	ATA:25
PN:ATG-WS-5123-C051	MOS/MSC	11-May-24	O/C					CUSTOMER CODE	
SN:0231-501	HRS	8234.2							
	AFL	4393							
259716-706 ^U		LEFT CABIN SHADE AT CLUB TABLE AFT FACING CHAIR						Component	ATA:25
PN:ATG-WS-5122-C051	MOS/MSC	19-Apr-24	O/C					CUSTOMER CODE	
SN:0231-111	HRS	8219.3							
	AFL	4386							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259716-708 ^U		#8 WINDOW SHADE						Component	ATA:25
PN:ATG-WS-5122	MOS/MSC	20-Mar-26	O/C						
SN:0231-108	HRS	8870							
	AFL	4687							
259716-711 ^U		#11 WINDOW SHADE						Component	ATA:25
PN:ATG-WS-5124	MOS/MSC	25-Jul-17	O/C						
SN:0231-130	HRS	5494.9							
	AFL	2818							
259716-721 ^U		AFT CREW REST WINDOW SHADE						Component	ATA:25
PN:ATG-WS-5124	MOS/MSC	17-Oct-23	O/C	TSR 0					
SN:0231-207	HRS	8061.2		TSR 0					
	AFL	4284		TSR 0					
259717-701 ^U		COFFEE MACHINE						Component	ATA:25
PN:PN	MOS/MSC	07-Sep-19	O/C						
SN:NOT INSTALLED	HRS	6656.5							
	AFL	3425							
259830-701 ^U		FWD EXHAUST VANITY FAN						Component	ATA:25
PN:011836	MOS/MSC	07-Oct-05	O/C						
SN:I05376134	HRS	0							
	AFL	0							
259830-701 ^U		GALLEY 1 EXHAUST FAN						Component	ATA:25
PN:011835	MOS/MSC	07-Oct-05	O/C						
SN:I05450115	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259830-701	L/H GALLEY EXHAUST VANITY FAN							Component	ATA:25
PN:011836	MOS/MSC	07-Oct-05	O/C						
SN:I05250494	HRS	0							
	AFL	0							
259830-702	AFT EXHAUST VANITY FAN							Component	ATA:25
PN:011836	MOS/MSC	07-Oct-05	O/C						
SN:I05081180	HRS	0							
	AFL	0							
259832-701	WASTE DRAIN (AFT) VALVE							Component	ATA:25
PN:2651-357-5	MOS/MSC	07-Oct-05	O/C						
SN:020008	HRS	0							
	AFL	0							
259836-701	WASTE TUBE (HR551B) HEATER							Component	ATA:25
PN:4E3527-2	MOS/MSC	03-Nov-09	O/C						
SN:0124	HRS	1347.2							
	AFL	746							
259846-701	AUDIO-ENTERTAINEMENT AMPLIFIER							Component	ATA:25
PN:3600-1-2	MOS/MSC	07-Oct-05	O/C						
SN:205480201	HRS	0							
	AFL	0							
259846-702	STEREO AUDIO - 3 CHANNEL AMPLIFIER							Component	ATA:25
PN:3500-1-1	MOS/MSC	29-Apr-21	O/C						
SN:205380071	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259899-701 ^U		MONITOR 21.3" EHTERNET MONITOR-						Component	ATA:25
PN:866-0022-001	MOS/MSC	07-Oct-05	O/C						
SN:CU0020	HRS	0							
	AFL	0							
259899-702 ^U		MONITOR 21.3" EHTERNET MONITOR-						Component	ATA:25
PN:866-0022-002	MOS/MSC	11-Aug-09	O/C	TSN 1					
SN:DL0091	HRS	1268.1		TSN 0					
	AFL	690		TSN 0					
259900-701 ^U		AVIONIC BAY ELECTRONIC INTERFACE BOX						Component	ATA:25
PN:5E2651-8	MOS/MSC	07-Oct-05	O/C						
SN:U0015	HRS	0							
	AFL	0							
259920-701 ^U		VIDEO AMPLIFIER						Component	ATA:25
PN:VA-401-1	MOS/MSC	28-Apr-08	O/C						
SN:100700988	HRS	658.8							
	AFL	394							
259925-705 ^U		GALLEY PLUG-IN TSE UNIT						Component	ATA:25
PN:1308520-100	MOS/MSC	16-May-20	O/C	TSO 11					
SN:3NK1R	HRS	6899.3		TSO 0					
	AFL	3578		TSO 0					
259925-706 ^U		CABIN SEAT #1 TOUCH SCREEN EQUIPMENT (TSE) UNIT						Component	ATA:25
PN:1308521-100	MOS/MSC	12-Jan-22	O/C	TSO 2					
SN:3JP8Y	HRS	7344.9		TSO 0					
	AFL	3869		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259925-707 ^U		#2 CABIN CHAIR TSE						Component	ATA:25
PN:1308521-100	MOS/MSC	26-Feb-25	O/C	TSO 81				CUSTOMER CODE	
SN:1J0YD	HRS	8641.1		TSO 0					
	AFL	4580		TSO 0					
259930-701 ^U		HIGH SPEED TRANSMIT (HCM) MODULE						Component	ATA:25
PN:822-2248-001	MOS/MSC	17-Nov-12	O/C	TSR 21					
SN:16Y8LH	HRS	2919.5		TSR 0					
	AFL	1523		TSR 0					
259941-702 ^U		PRINTER SERVER						Component	ATA:25
PN:ADI23900-000	MOS/MSC	07-Oct-05	O/C						
SN:023	HRS	0							
	AFL	0							
259950-701 ^U		CABIN SEAT 01 SWITCH PANEL						Component	ATA:25
PN:2601-1-34-T17PA	MOS/MSC	10-Aug-17	O/C	TSR 0					
SN:2PLWR	HRS	5519.6		TSR 0					
	AFL	2826		TSR 0					
259950-702 ^U		CABIN SEAT 02 SWITCH PANEL						Component	ATA:25
PN:2501-2-657-T17PA	MOS/MSC	26-Nov-24	O/C						
SN:3KYFT	HRS	8608.5							
	AFL	4561							
259950-705 ^U		CABIN SEAT 05 SWITCH PANEL						Component	ATA:25
PN:2601-1-35-T17PA	MOS/MSC	24-Sep-07	O/C						
SN:2PM6H	HRS	447							
	AFL	249							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259950-706 ^U		CABIN SEAT 06 SWITCH PANEL						Component	ATA:25
PN:2601-1-34-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PLWN		HRS	447						
		AFL	249						
259950-707 ^U		CABIN SEAT 07 SWITCH PANEL						Component	ATA:25
PN:2501-2-661-T17PA		MOS/MS	18-May-11	O/C					
SN:3KYFW		HRS	2157.3						
		AFL	1140						
259950-708 ^U		CABIN SEAT 08 SWITCH PANEL						Component	ATA:25
PN:2601-1-35-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PM6C		HRS	447						
		AFL	249						
259950-711 ^U		CABIN SEAT 11 SWITCH PANEL						Component	ATA:25
PN:2601-1-35-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PM6F		HRS	447						
		AFL	249						
259950-712 ^U		CABIN SEAT 12 SWITCH PANEL						Component	ATA:25
PN:2601-1-34-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PLWW		HRS	447						
		AFL	249						
259950-713 ^U		CABIN SEAT 13 SWITCH PANEL						Component	ATA:25
PN:2601-1-34-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PLWX		HRS	447						
		AFL	249						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259950-714 ^U		CABIN SEAT 14 SWITCH PANEL						Component	ATA:25
PN:2501-2-657T17PAMOS/MS		26-Feb-25	O/C	TSR 2					
SN:3KYFY		HRS	8641.1	TSR 0					
		AFL	4580	TSR 0					
259950-717 ^U		CABIN SEAT 17 SWITCH PANEL						Component	ATA:25
PN:2501-2-659-T17PA		MOS/MS	18-May-11	O/C					
SN:3KYFT		HRS	2157.3						
		AFL	1140						
259950-718 ^U		CABIN SEAT 18 SWITCH PANEL						Component	ATA:25
PN:2501-2-658-T1PA		MOS/MS	01-Oct-10	O/C					
SN:3KYFP		HRS	1768.8						
		AFL	966						
259950-719 ^U		CABIN SEAT 19 SWITCH PANEL						Component	ATA:25
PN:2601-1-37-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PLWY		HRS	447						
		AFL	249						
259950-721 ^U		CABIN SEAT 21 SWITCH PANEL						Component	ATA:25
PN:2601-1-36-T17PA		MOS/MS	24-Sep-07	O/C					
SN:2PLPB		HRS	447						
		AFL	249						
259950-723 ^U		CABIN SEAT 23 SWITCH PANEL						Component	ATA:25
PN:2601-1-35-T17PA		MOS/MS	23-Jan-14	O/C					
SN:2PM6B		HRS	3488.7						
		AFL	1835						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259950-724 ^U		CABIN SEAT 24 SWITCH PANEL						Component	ATA:25
PN:2601-1-34-T17PA	MOS/MSC	24-Sep-07	O/C						
SN:2PLWV	HRS	447							
	AFL	249							
259960-701 ^U		LH#1 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-002	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:35923	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
259960-702 ^U		LH#2 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-001	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:34180	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
259960-707 ^U		LH#7 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-002	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:35926	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
259960-708 ^U		LH#8 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-001	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:31631	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
259961-702 ^U		RH#2 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-002	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:35924	HRS	927.8		TSN 0					
	AFL	501		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
259961-703	U	RH#3 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-001	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:34179	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
259961-704	U	RH#4 MONITOR ARM ASSEMBLY						Component	ATA:25
PN:866-0133-002	MOS/MSC	22-Oct-08	O/C						
SN:35925	HRS	927.8							
	AFL	501							
259990-701	U	CABIN PRINTER						Component	ATA:25
PN:CQ809A	MOS/MSC	17-May-12	O/C						
SN:CN1A1C20HJ05Q	HRS	2616.8							
R	AFL	1382							
259995-701	U	ATG-5000 TRANSCEIVER						Component	ATA:25
PN:PN	MOS/MSC	30-Oct-20	O/C						
SN:NOT INSTALLED	HRS	6972.8							
	AFL	3632							
259997-701	U	FORWARD ANTENNA						Component	ATA:25
PN:PN	MOS/MSC	30-Oct-20	O/C						
SN:NOT INSTALLED	HRS	6972.8							
	AFL	3632							
259998-701	U	AFT ANTENNA						Component	ATA:25
PN:PN	MOS/MSC	30-Oct-20	O/C						
SN:NOT INSTALLED	HRS	6972.8							
	AFL	3632							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
256040-702 ^U CREW REST FWD LIFE VEST								Component	ATA:26
PN:63600-569	MOS/MSC	03-Sep-24	O/C	TSN 19					
SN:L5716646	HRS	8469.9		TSN 0					
	AFL	4493		TSN 0					
26-10-01-201 ^S OPERATIONAL TEST OF THE FIRE-DETECTION-AND- EXTINGUISHING (FIDEEX) CONTROL-CIRCUITS, ARM AND DISCHARGE CIRCUITS									
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 26.005	AFL	4582							
PROC. REF: AMM 26-10-01-710-802PROC. REF: AMM 26-10-01-710-802									PKG:34
26-10-01-900-801-01 FS987 ALARM FIDEEX CONTROL UNIT								Component	ATA:26
PN:GK774-0021-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0215	HRS	0		TSN 0					
WC#: 26.045	AFL	0		TSN 0					
PROC. REF: AMM 26-10-01-000-801, AMM 26-10-01-400-801PROC. REF: AMM 26-10-01-000-801, AMM 26-10-01-400-801									
26-12-00-201 ^S FUNCTIONAL TEST OF THE APU FIRE DETECTION SYSTEM								Service	ATA:26
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 26.010	AFL	4582							
PROC. REF: AMM 26-12-00-720-801PROC. REF: AMM 26-12-00-720-801									PKG:32
26-12-01-900-801-01 EDUCTOR LOOP A SENSING ELEMENT								Component	ATA:26
PN:GK774-0024-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT REQ	HRS	0		TSN 0					
WC#: 26.050	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01-000-801, AMM 26-12-01-400-801PROC. REF: AMM 26-12-01-000-801, AMM 26-12-01-400-801									
26-12-01-900-801-02 EDUCTOR LOOP B SENSING ELEMENT								Component	ATA:26
PN:GK774-0024-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT REQ	HRS	0		TSN 0					
WC#: 26.050	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01-000-801, AMM 26-12-01-400-801PROC. REF: AMM 26-12-01-000-801, AMM 26-12-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-12-05-900-801-01 RIGHT HATCH LOOP A SENSING ELEMENT								Component	ATA:26
PN:GK774-0025-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT REQ	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-12-05-000-801, AMM 26-12-05-400-801PROC. REF: AMM 26-12-05-000-801, AMM 26-12-05-400-801									
26-12-05-900-801-02 RIGHT HATCH LOOP B SENSING ELEMENT								Component	ATA:26
PN:GK774-0025-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT REQ	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-12-05-000-801, AMM 26-12-05-400-801PROC. REF: AMM 26-12-05-000-801, AMM 26-12-05-400-801									
26-12-09-900-801-01 LEFT STRUT LOOP A SENSING ELEMENT								Component	ATA:26
PN:GK774-0027-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0190	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-12-09-000-801, AMM 26-12-09-400-801PROC. REF: AMM 26-12-09-000-801, AMM 26-12-09-400-801									
26-12-09-900-801-02 LEFT STRUT LOOP B SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-12-09-000-801, AMM 26-12-09-400-801PROC. REF: AMM 26-12-09-000-801, AMM 26-12-09-400-801									
26-13-00-201 ^S FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM								Service	ATA:26
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 26.015	AFL	4582							
PROC. REF: AMM 26-13-00-720-801PROC. REF: AMM 26-13-00-720-801									
26-13-01-900-801-01 LEFT MLG WHEEL WELL SENSING ELEMENT								Component	ATA:26
PN:GK774-0023-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:LOT9706S/N005	HRS	0		TSN 0					
WC#: 26.060	AFL	0		TSN 0					
PROC. REF: AMM 26-13-01-000-801, AMM 26-13-01-400-801PROC. REF: AMM 26-13-01-000-801, AMM 26-13-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-13-01-900-801-02 RIGHT MLG WHEEL WELL SENSING ELEMENT								Component	ATA:26
PN:GK774-0023-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:LOT9706S/N006	HRS	0		TSN 0					
WC#: 26.060	AFL	0		TSN 0					
PROC. REF: AMM 26-13-01-000-801, AMM 26-13-01-400-801PROC. REF: AMM 26-13-01-000-801, AMM 26-13-01-400-801									
26-21-00-201 GENERAL VISUAL INSPECTION OF THE SINGLE-PATH DISCHARGE LINES								Service	ATA:26
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 26.020	AFL	4582							
PKG:8									
PROC. REF: AMM 26-21-00-210-801PROC. REF: AMM 26-21-00-210-801									
26-21-01-201 FUNCTIONAL TEST (HYDROSTATIC TEST) NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Service	ATA:26
PN:GK774-0020-3	MOS	19-Apr-21	120		19-Apr-31		1759 d	MRB	
SN:0037BD	HRS								
WC#: 26.065	AFL								
HydroCheck Date: : 19-Apr-21									
PROC. REF: AMM 26-21-01-790-801PROC. REF: AMM 26-21-01-790-801									
26-21-01-201 FUNCTIONAL TEST (HYDROSTATIC TEST) NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Service	ATA:26
PN:GK774-0020-3	MOS	17-Apr-21	120		17-Apr-31		1757 d	MRB	
SN:0249BD	HRS								
WC#: 26.070	AFL								
HydroCheck Date: : 17-Apr-21									
PROC. REF: AMM 26-21-01-790-801PROC. REF: AMM 26-21-01-790-801									
26-21-01-202 FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH								Service	ATA:26
PN:GK774-0020-3	MOS	19-Apr-21	120 (+3m/-3m)		19-Apr-31	19-Jul-31	1759 d (+91)	MRB	
SN:0037BD	HRS								
	AFL								
PROC. REF: AMM 26-21-01-720-801PROC. REF: AMM 26-21-01-720-801									
26-21-01-202 FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH								Service	ATA:26
PN:GK774-0020-3	MOS	17-Apr-21	120 (+3m/-3m)		17-Apr-31	17-Jul-31	1757 d (+91)	MRB	
SN:0249BD	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
PROC. REF: AMM 26-21-01-720-801PROC. REF: AMM 26-21-01-720-801									
26-21-01-203	FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT								Service ATA:26
PN:GK774-0020-3	MOS	14-Aug-25	60 (+3m/-3m)		14-Aug-30	14-Nov-30	1511 d (+92)	MRB	
SN:0037BD	HRS	8645							
	AFL	4582							
PROC. REF: AMM 26-21-01-720-802PROC. REF: AMM 26-21-01-720-802									
26-21-01-203	FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT								Service ATA:26
PN:GK774-0020-3	MOS	14-Aug-25	60 (+3m/-3m)		14-Aug-30	14-Nov-30	1511 d (+92)	MRB	
SN:0249BD	HRS	8645							
	AFL	4582							
PROC. REF: AMM 26-21-01-720-802PROC. REF: AMM 26-21-01-720-802									
26-21-01-900-801-01	NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Component ATA:26
PN:GK774-0020-3	MOS/MSC	05-May-21	O/C	TSO 1					
SN:0037BD	HRS	7094.7		TSO 0					
WC#: 26.065	AFL	3718		TSO 0					
PROC. REF: CMM 26-21-65, AMM 26-21-01-000-801, AMM 26-21-01-400-801PROC. REF: CMM 26-21-65, AMM 26-21-01-000-801, AMM 26-21-01-400-801									
26-21-01-900-801-02	NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Component ATA:26
PN:GK774-0020-3	MOS/MSC	05-May-21	O/C	TSO 1					
SN:0249BD	HRS	7094.7		TSO 0					
WC#: 26.070	AFL	3718		TSO 0					
PROC. REF: CMM 26-21-65, AMM 26-21-01-000-801, AMM 26-21-01-400-801PROC. REF: CMM 26-21-65, AMM 26-21-01-000-801, AMM 26-21-01-400-801									
26-21-05-201	DISCARD OF APU FWD THE DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	26-Feb-25	120		01-Nov-34		3051 d	LIFE LIMIT	
SN:AGZ3449	HRS	8641.1							
	AFL	4580							
Manufacture Date:: 01-Nov-24									
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-05-201	DISCARD OF THE APU AFT DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	26-Feb-25	120		01-Mar-33		2441 d	LIFE LIMIT	
SN:AGL5864	HRS	8641.1							
	AFL	4580							
Manufacture Date:: 01-Mar-23									
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									
26-21-05-201	DISCARD OF THE ENG. 1 AFT DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	01-Nov-24	120		01-Nov-34		3051 d	LIFE LIMIT	
SN:AGZ3445	HRS								
	AFL								
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									
26-21-05-201	DISCARD OF THE ENG. 1 FWD DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	26-Feb-25	120		01-Oct-34		3020 d	LIFE LIMIT	
SN:AGY5613	HRS	8641.1							
	AFL	4580							
Manufacture Date:: 01-Oct-24									
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									
26-21-05-201	DISCARD OF THE ENG. 2 AFT DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	26-Feb-25	120		01-Nov-34		3051 d	LIFE LIMIT	
SN:AGZ3444	HRS	8641.1							
	AFL	4580							
Manufacture Date:: 01-Nov-24									
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									
26-21-05-201	DISCARD OF THE ENG. 2 FWD DISCHARGE CARTRIDGE								Service ATA:26
PN:446518-1	MOS	26-Feb-25	120		01-Nov-34		3051 d	LIFE LIMIT	
SN:AGZ3457	HRS	8641.1							
	AFL	4580							
Manufacture Date:: 01-Nov-24									
PROC. REF: AMM 26-21-05-961-801PROC. REF: AMM 26-21-05-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-05-900-801-01		ENG. 1 FWD DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 4					
SN:AGY5613	HRS	8641.1		TSN 0					
WC#: 26.075	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									
26-21-05-900-801-02		ENG. 1 AFT DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 3					
SN:AGZ3445	HRS	8641.1		TSN 0					
WC#: 26.075	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									
26-21-05-900-801-03		ENG. 2 FWD DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 3					
SN:AGZ3457	HRS	8641.1		TSN 0					
WC#: 26.080	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									
26-21-05-900-801-04		ENG. 2 AFT DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 3					
SN:AGZ3444	HRS	8641.1		TSN 0					
WC#: 26.080	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									
26-21-05-900-801-05		APU FWD DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 3					
SN:AGZ3449	HRS	8641.1		TSN 0					
WC#: 26.085	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									
26-21-05-900-801-06		APU AFT DISCHARGE CARTRIDGE						Component	ATA:26
PN:446518-1	MOS/MSC	26-Feb-25	H/T	TSN 23					
SN:AGL5864	HRS	8641.1		TSN 0					
WC#: 26.085	AFL	4580		TSN 0					
PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801PROC. REF: AMM 26-21-05-000-801, AMM 26-21-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
26-21-13-201		OPERATIONAL TEST OF THE ENGINE FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS							Service ATA:26
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)		11645	11695	2726.4 (+50)		
WC#: 26.030	AFL	4582							
PROC. REF: AMM 26-21-13-710-811PROC. REF: AMM 26-21-13-710-811									PKG:8
26-21-13-202		OPERATIONAL TEST OF THE APU FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS							Service ATA:26
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 26.035	AFL	4582							
PROC. REF: AMM 26-21-13-710-812PROC. REF: AMM 26-21-13-710-812									PKG:8
26-21-13-900-801-01		FIRE S/O ENGINE LH HANDLE							Component ATA:26
PN:GC774-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:184	HRS	0		TSN 0					
WC#: 26.090	AFL	0		TSN 0					
PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801									
26-21-13-900-801-02		FIRE S/O ENGINE RH HANDLE							Component ATA:26
PN:GC774-0001-17	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:182	HRS	0		TSN 0					
WC#: 26.090	AFL	0		TSN 0					
PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801									
26-21-13-900-801-03		FIRE S/O ENGINE APU HANDLE							Component ATA:26
PN:GC774-0001-15	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:186	HRS	0		TSN 0					
WC#: 26.090	AFL	0		TSN 0					
PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801PROC. REF: AMM 26-21-13-000-801, AMM 26-21-13-400-801									
26-21-45-201 ^S		OPERATIONAL TEST OF THE DISCHARGE CHECK VALVES							Service ATA:26
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 26.040	AFL	4582							
									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
PROC. REF: AMM 26-21-45-710-801PROC. REF: AMM 26-21-45-710-801									
26-23-00-201		FUNCTIONAL TEST OF THE FLIGHT COMPARTMENT EXTINGUISHER (WEIGHT TEST)						Service	ATA:26
PN:30H673	MOS	14-Aug-25	15 (+3m/-3m)		14-Nov-26	14-Feb-27	142 d (+92)	MRB	
SN:H-92102063	HRS	8645							
	AFL	4582							
PROC. REF: AMM 26-23-01-720-801PROC. REF: AMM 26-23-01-720-801									
26-23-01-900-801-01		FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:30H673	MOS/MSC	27-Mar-24	O/C	TSN 6					
SN:H-92102063	HRS	8205.4		TSN 0					
	AFL	4378		TSN 0					
PROC. REF: AMM 26-23-01-000-801, AMM 26-23-01-400-801PROC. REF: AMM 26-23-01-000-801, AMM 26-23-01-400-801									
26-23-CA-200		PERFORM FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE 6YRS MAINTENANCE REQUIREMENTS AS PER NFPA-10						Service	ATA:26
PN:30H673	MOS	01-Sep-23	72		01-Sep-29		1164 d	CUSTOMER OPTION	
SN:H-92102063	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
261117-001		NO. 1 ENGINE - FIRE CORE WIRE						Component	ATA:26
PN:473899	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0348	HRS	0		TSN 0					
	ENC	0		TSN 0					
261117-001		NO. 2 ENGINE - FIRE CORE WIRE						Component	ATA:26
PN:473899	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0347	HRS	0		TSN 0					
	ENC	0		TSN 0					
261401-701 ^U		FWD VANITY SMOKE DETECTOR						Component	ATA:26
PN:473597-1	MOS/MSC	07-Oct-05	O/C						
SN:2117	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261401-702 ^U		AFT VANITY SMOKE DETECTOR						Component	ATA:26
PN:473597-1	MOS/MSC	07-Oct-05	O/C						
SN:2043	HRS	0							
	AFL	0							
261401-704 ^U		BAGGAGE SMOKE DETECTOR						Component	ATA:26
PN:473597-1	MOS/MSC	07-Feb-23	O/C	TSN 0					
SN:SAA1679	HRS	7757.5		TSN 0					
	AFL	4122		TSN 0					
261407-706 ^U		AFT AVIONICS BAY SMOKE DETECTOR						Component	ATA:26
PN:473597-1	MOS/MSC	14-Mar-18	O/C	TSN 11					
SN:SAA0463	HRS	5790		TSN 0					
	AFL	3001		TSN 0					
262150-701 ^U		(FWD ARMREST C/R) FIRE EXTINGUISHER						Component	ATA:26
PN:BA21741GSR-5	MOS/MSC	14-Aug-25	O/C	TSN 7					
SN:132493	HRS	8645		TSN 0					
	AFL	4582		TSN 0					
262150-701A ^U		DETAILED INSPECTION (FWD ARMREST C/R) FIRE EXTINGUISHER (26-21-50-601)						Service	ATA:26
PN:BA21741GSR-5	MOS	14-Aug-25	12	14-Aug-26		50 d	STLMC		
SN:132493	HRS	8645							
	AFL	4582							
262150-701B ^U		RESTORE (FWD ARMREST C/R) FIRE EXTINGUISHER (26-21-50-602)						Service	ATA:26
PN:BA21741GSR-5	MOS	01-Jan-25	120	01-Jan-35		3112 d	STLMC		
SN:132493	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262150-702 ^U		(AFT END DIVAN ARMREST) FIRE EXTINGUISHER						Component	ATA:26
PN:BA21741GSR-2	MOS/MSC	14-Aug-25	O/C	TSN 6					
SN:133729	HRS	8645		TSN 0					
	AFL	4582		TSN 0					
262150-702A ^U		DETAILED INSPECTION (AFT END DIVAN ARMREST) FIRE EXTINGUISHER (26-21-50-601)						Service	ATA:26
PN:BA21741GSR-2	MOS	14-Aug-25	12		14-Aug-26		50 d	STLMC	
SN:133729	HRS	8645							
	AFL	4582							
262150-702B ^U		RESTORE (AFT END DIVAN ARMREST) FIRE EXTINGUISHER (26-21-50-602)						Service	ATA:26
PN:BA21741GSR-2	MOS	01-Feb-25	120		01-Feb-35		3143 d	STLMC	
SN:133729	HRS								
	AFL								
262150-703 ^U		(FS 420) FIRE EXTINGUISHER						Component	ATA:26
PN:BA21741GSR-5	MOS/MSC	28-Mar-22	O/C	TSN 12					
SN:119911	HRS	7407.2		TSN 295.7					
	AFL	3910		TSN 179					
262150-703A ^U		DETAILED INSPECTION (FS 420) FIRE EXTINGUISHER (26-21-50-601)						Service	ATA:26
PN:BA21741GSR-5	MOS	14-Aug-25	12		14-Aug-26		50 d	STLMC	
SN:119911	HRS	8645							
	AFL	4582							
262150-703B ^U		RESTORE (FS 420) FIRE EXTINGUISHER (26-21-50-602)						Service	ATA:26
PN:BA21741GSR-5	MOS	09-Mar-21	120		09-Mar-31		1718 d	STLMC	
SN:119911	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

262150-704	U	(4.1 KG) (AFT WARDROBE) FIRE EXTINGUISHER						Component	ATA:26
PN:466090	MOS/MSC	28-Mar-22	O/C	TSN 54					
SN:D00726586	HRS	7407.2		TSN 1678.1					
	AFL	3910		TSN 959					

262150-704A	U	DETAILED INSPECTION (4.1 KG) (AFT WARDROBE) FIRE EXTINGUISHER (26-21-50-601)						Service	ATA:26
PN:466090	MOS	14-Aug-25	12	14-Aug-26		50 d	STLMC		
SN:D00726586	HRS	8645							
	AFL	4582							

262150-704B	U	RESTORE (4.1 KG) (AFT WARDROBE) FIRE EXTINGUISHER (26-21-50-602)						Service	ATA:26
PN:466090	MOS	01-Apr-17	144	01-Apr-29		1011 d	STLMC		
SN:D00726586	HRS								
	AFL								

ATA 27 - FLIGHT CONTROLS

27-00-00-201	S	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE FORWARD AVIONICS COMPARTMENT FS202.75 TO FS280.00						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 27.005	AFL	4582							
PROC. REF: AMM 27-00-00-220-802PROC. REF: AMM 27-00-00-220-802									PKG:34

27-00-00-202	S	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT FS280.00 TO FS557.00						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 27.010	AFL	4582							
PROC. REF: AMM 27-00-00-220-803PROC. REF: AMM 27-00-00-220-803									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10

Serial: 9175

RegNo: N117TP

HRS: 8918.6

AFL: 4707

As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-00-00-203	^S	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MID- LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00						Service	ATA:27
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.015	AFL	4582							
PROC. REF: AMM 27-00-00-220-804PROC. REF: AMM 27-00-00-220-804									PKG:38
27-00-00-204	^S	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL AND MID WING-TO-FUSELAGE FAIRING						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.020	AFL	4582							
PROC. REF: AMM 27-10-00-220-801PROC. REF: AMM 27-10-00-220-801									PKG:34
27-00-00-205	^S	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE FLIGHT COMPARTMENT FS202.75 TO FS280.00						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.025	AFL	4582							
PROC. REF: AMM 27-10-00-220-802PROC. REF: AMM 27-10-00-220-802									PKG:34
27-00-00-206	^S	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MID AND OUTBOARD WING BOX, WS178.00 TO WS536.50						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.030	AFL	4582							
PROC. REF: AMM 27-10-00-220-803PROC. REF: AMM 27-10-00-220-803									PKG:34
27-00-00-207	^S	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD WING TRAILING EDGE, WS47.62 TO WS178.00						Service	ATA:27
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.035	AFL	4582							
PROC. REF: AMM 27-10-00-220-804PROC. REF: AMM 27-10-00-220-804									PKG:32

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-00-00-208	^S	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT POWER DISTRIBUTION/ECS COMPARTMENT, FS781.00 TO FS861.00						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.040	AFL	4582							
PROC. REF: AMM 27-00-00-220-807PROC. REF: AMM 27-00-00-220-807									PKG:34
27-00-00-209	^S	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT, FS861.00 TO FS987.55						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.045	AFL	4582							
PROC. REF: AMM 27-00-00-220-808PROC. REF: AMM 27-00-00-220-808									PKG:34
27-00-00-210	^S	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION, FS987.55 TO REAR SPAR						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.050	AFL	4582							
PROC. REF: AMM 27-00-00-220-809PROC. REF: AMM 27-00-00-220-809									PKG:34
27-00-00-211	^S	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STABILIZER, FRONT SPAR TO REAR SPAR						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.055	AFL	4582							
PROC. REF: AMM 27-30-00-220-801PROC. REF: AMM 27-30-00-220-801									PKG:34
27-00-00-212	^S	OPERATIONAL TEST OF THE AILERON, ELEVATOR AND RUDDER CONTROL POWER-CONTROL UNITS (PCU)						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 27.060	AFL	4582							
PROC. REF: AMM 27-00-00-710-801PROC. REF: AMM 27-00-00-710-801									PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-10-00-201 ^S		LUBRICATION OF THE AILERON POWER-CONTROL UNIT (PCU) TOGGLE-LINK SLOTTED BEARINGS						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 12-22-00-640-838PROC. REF: AMM 12-22-00-640-838									
27-11-01-900-801-01		PILOT CONTROL WHEEL						Component	ATA:27
PN:GC415-1100-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0037	HRS	0		TSN 0					
WC#: 27.410	AFL	0		TSN 0					
PROC. REF: AMM 27-11-01-000-801, AMM 27-11-01-400-801PROC. REF: AMM 27-11-01-000-801, AMM 27-11-01-400-801									
27-11-01-900-801-02		COPILOT CONTROL WHEEL						Component	ATA:27
PN:GC415-1100-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0029	HRS	0		TSN 0					
WC#: 27.410	AFL	0		TSN 0					
PROC. REF: AMM 27-11-01-000-801, AMM 27-11-01-400-801PROC. REF: AMM 27-11-01-000-801, AMM 27-11-01-400-801									
27-11-05-201		FUNCTIONAL TEST OF THE ROLL DISCONNECT MECHANISM						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.065	AFL	4582							
PROC. REF: AMM 27-11-05-720-801PROC. REF: AMM 27-11-05-720-801									
27-11-05-202 ^S		OPERATIONAL TEST OF THE ROLL DISCONNECT MECHANISM						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 27.070	AFL	4582							
PROC. REF: AMM 27-11-05-710-801PROC. REF: AMM 27-11-05-710-801									
27-11-05-900-801-01		ROLL DISCONNECT ASSEMBLY						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.215	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

27-11-13-900-801-01		LH ROLL SPOILER TRANSDUCER						Component	ATA:27
PN:GT415-6006-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00051	HRS	0		TSN 0					
WC#: 27.220	AFL	0		TSN 0					
PROC. REF: AMM 27-11-13-000-801, AMM 27-11-13-400-801, AMM 27-11-13-720-801, AMM 27-11-13-820-801PROC. REF: AMM 27-11-13-000-801, AMM 27-11-13-400-801, AMM 27-11-13-720-801, AMM 27-11-13-820-801									

27-11-13-900-801-02		RH ROLL SPOILER TRANSDUCER						Component	ATA:27
PN:GT415-6006-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00050	HRS	0		TSN 0					
WC#: 27.220	AFL	0		TSN 0					
PROC. REF: AMM 27-11-13-000-801, AMM 27-11-13-400-801, AMM 27-11-13-720-801, AMM 27-11-13-820-801PROC. REF: AMM 27-11-13-000-801, AMM 27-11-13-400-801, AMM 27-11-13-720-801, AMM 27-11-13-820-801									

27-11-13-900-802-01		AILERON TORQUE TUBE						Component	ATA:27
PN:GC413-1200	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6250269	HRS	0		TSN 0					
WC#: 27.225	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-11-17-900-801-01		LH TENSION AILERON REGULATOR						Component	ATA:27
PN:GC415-1600-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR090	HRS	0		TSN 0					
WC#: 27.235	AFL	0		TSN 0					
PROC. REF: AMM 27-11-17-000-801, AMM 27-11-17-400-801PROC. REF: AMM 27-11-17-000-801, AMM 27-11-17-400-801									

27-11-17-900-801-02		RH TENSION AILERON REGULATOR						Component	ATA:27
PN:GC415-1600-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR088	HRS	0		TSN 0					
WC#: 27.235	AFL	0		TSN 0					
PROC. REF: AMM 27-11-17-000-801, AMM 27-11-17-400-801PROC. REF: AMM 27-11-17-000-801, AMM 27-11-17-400-801									

27-11-21-900-801-01		LEFT AILERON POSITION TRANSDUCER						Component	ATA:27
PN:GT415-0200-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0178	HRS	0		TSN 0					
WC#: 27.240	AFL	0		TSN 0					
PROC. REF: AMM 27-11-21-000-801, AMM 27-11-21-400-801PROC. REF: AMM 27-11-21-000-801, AMM 27-11-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-11-21-900-801-02		RIGHT AILERON POSITION TRANSDUCER						Component	ATA:27
PN:GT415-0200-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0179	HRS	0		TSN 0					
WC#: 27.240	AFL	0		TSN 0					
PROC. REF: AMM 27-11-21-000-801, AMM 27-11-21-400-801PROC. REF: AMM 27-11-21-000-801, AMM 27-11-21-400-801									
27-11-25-101		FUNCTIONAL TEST OF THE AILERON POWER-CONTROL UNIT (PCU) (CMR*)						Service	ATA:27
	MOS	09-May-24						CMR	
	HRS	8239.9	1500		9739.9		821.3		
WC#: 27.080	AFL	4398							
PKG:5									
PROC. REF: AMM 27-11-25-720-801PROC. REF: AMM 27-11-25-720-801									
27-11-25-102		FUNCTIONAL TEST OF THE AILERON PCU BUNGEE (CMR**)						Service	ATA:27
	MOS	14-Aug-25						CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.085	AFL	4582							
PKG:8									
PROC. REF: AMM 27-11-25-720-802PROC. REF: AMM 27-11-25-720-802									
27-11-25-900-801-01		NO. 1 AILERON PCU						Component	ATA:27
PN:GT411-1700-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0737	HRS	0		TSN 0					
WC#: 27.245	AFL	0		TSN 0					
PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801									
27-11-25-900-801-02		NO. 2 AILERON PCU						Component	ATA:27
PN:GT411-1700-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0653	HRS	0		TSN 0					
WC#: 27.245	AFL	0		TSN 0					
PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801									
27-11-25-900-801-03		NO. 3 AILERON PCU						Component	ATA:27
PN:GT411-1700-9	MOS/MSC	07-May-11	O/C						
SN:1001	HRS	2157.3		TSN 342					
WC#: 27.245	AFL	1140		TSN 186					
PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
27-11-25-900-801-04		NO. 4 AILERON PCU							Component	ATA:27
PN:GT411-1700-7	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0658	HRS	0		TSN 0						
WC#: 27.245	AFL	0		TSN 0						
PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801										
27-11-35-101		FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FLIGHT COMPARTMENT CABLES (CMR**)							Service	ATA:27
	MOS	14-Aug-25	30 (+3m/-3m)	Adj 25d	10-Mar-28	10-Jun-28	624 d (+92)	CMR		
	HRS	8645								
	AFL	4582								
PROC. REF: AMM 27-11-35-720-801PROC. REF: AMM 27-11-35-720-801										
27-11-35-102		FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FUSELAGE CABLES (CMR**)							Service	ATA:27
	MOS	14-Aug-25	30 (+3m/-3m)	Adj 25d	10-Mar-28	10-Jun-28	624 d (+92)	CMR		
	HRS	8645								
	AFL	4582								
PROC. REF: AMM 27-11-35-720-802PROC. REF: AMM 27-11-35-720-802										
27-11-35-103		DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL (POST SB 700-27-086 PART I OR PART J OR PART K OR PART L OR PART M OR PART N OR PART O OR PART P) (CMR**)							Service	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
PROC. REF: AMM 27-11-35-220-801PROC. REF: AMM 27-11-35-220-801										
27-11-35-104		DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE WING TRAILING EDGE, AT THE INNER, MID AND OUTER FLAP AREAS (POST SB 700-27-086 PART M OR PART N OR PART O OR PART P) (CMR**)							Service	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
PROC. REF: AMM 27-11-35-220-802PROC. REF: AMM 27-11-35-220-802										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-11-35-201		FUNCTIONAL TEST OF THE AILERON CABLE TENSION - WING CABLES							Service ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 27d	10-Sep-30	10-Dec-30	1538 d (+91)	MRB	
	HRS	8645							
	AFL	4582							
									PKG:34
PROC. REF: AMM 27-11-35-720-803PROC. REF: AMM 27-11-35-720-803									

27-12-05-900-801-01		AILERON-MLG WHEEL WELL TRIM ACTUATOR							Component ATA:27
PN:GT412-1500-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1637	HRS	0		TSN 0					
WC#: 27.250	AFL	0		TSN 0					
PROC. REF: AMM 27-12-05-000-801, AMM 27-12-05-400-801PROC. REF: AMM 27-12-05-000-801, AMM 27-12-05-400-801									

27-20-00-201 ^S		LUBRICATION OF THE RUDDER POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS							Service ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
									PKG:34
PROC. REF: AMM 12-22-00-640-839PROC. REF: AMM 12-22-00-640-839									

27-21-00-201 ^S		GENERAL VISUAL INSPECTION OF THE SINGLE-RUDDER CONTROL-PATH AND PCU LINKAGE CENTERING-SPRINGS							Service ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	4500 (+50/-50)						
WC#: 27.090	AFL	4582							
									PKG:10
PROC. REF: AMM 27-21-00-210-802PROC. REF: AMM 27-21-00-210-802									

27-21-00-900-803-01		RUDDER							Component ATA:27
PN:GS268-0001-3	MOS/MSC	03-Nov-06	O/C						
SN:B123SR6	HRS	36.5							
WC#: 27.290	AFL	14							
PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801									

27-21-01-900-802-01		RUDDER LINEAR FEEL UNIT							Component ATA:27
PN:GC415-2360-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR191	HRS	0		TSN 0					
WC#: 27.255	AFL	0		TSN 0					
PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801, AMM 27-21-01-000-802, AMM 27-21-01-400-802PROC. REF: AMM 27-11-25-000-801, AMM 27-11-25-400-801, AMM 27-21-01-000-802, AMM 27-21-01-400-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

27-21-05-201	^S	OPERATIONAL TEST OF THE RUDDER LOAD LIMITER						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	4500 (+50/-50)						
WC# : 27.095	AFL	4582							
									PKG:10
PROC. REF: AMM 27-21-05-710-801PROC. REF: AMM 27-21-05-710-801									

27-21-05-900-801-01	RUDDER LIMITER							Component	ATA:27
PN:GC415-2400-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR190	HRS	0		TSN 0					
WC# : 27.265	AFL	0		TSN 0					
PROC. REF: AMM 27-21-05-000-801, AMM 27-21-05-400-801PROC. REF: AMM 27-21-05-000-801, AMM 27-21-05-400-801									

27-21-05-900-801-02	RUDDER LIMITER UNIT							Component	ATA:27
PN:GC413-2600-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PMF4818105	HRS	0		TSN 0					
WC# : 27.305	AFL	0		TSN 0					
PROC. REF: AMM 27-21-05-000-801, AMM 27-21-05-400-801PROC. REF: AMM 27-21-05-000-801, AMM 27-21-05-400-801									

27-21-05-900-802-01	LH LINEAR YAW DAMPER ACTUATOR ASSEMBLY							Component	ATA:27
PN:7002800-804	MOS/MSC	11-Apr-18	O/C	TSR 10					
SN:96030799	HRS	5907		TSR 0					
WC# : 27.270	AFL	3034		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-21-05-900-802-02	RH LINEAR YAW DAMPER ACTUATOR ASSEMBLY							Component	ATA:27
PN:GC415-2565-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PMF5660543-002	HRS	0		TSN 0					
WC# : 27.270	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-21-09-101	OPERATIONAL TEST OF THE RUDDER POWER-CONTROL UNIT (PCU) INPUT LIMITERS (CMR**)							Service	ATA:27
	MOS	14-Aug-25						CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC# : 27.100	AFL	4582							
									PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

PROC. REF: AMM 27-21-09-710-801PROC. REF: AMM 27-21-09-710-801

27-21-09-900-801-01		NO. 1 LOAD LIMITER			Component	ATA:27
PN:GC415-2790-3	MOS/MSC	07-Oct-05	O/C	TSN 0		
SN:FR581	HRS	0		TSN 0		
WC#: 27.275	AFL	0		TSN 0		
PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801						

27-21-09-900-801-02		NO. 2 LOAD LIMITER			Component	ATA:27
PN:GC415-2790-3	MOS/MSC	07-Oct-05	O/C	TSN 0		
SN:FR567	HRS	0		TSN 0		
WC#: 27.275	AFL	0		TSN 0		
PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801						

27-21-09-900-801-03		NO. 3 LOAD LIMITER			Component	ATA:27
PN:GC415-2790-3	MOS/MSC	07-Oct-05	O/C	TSN 0		
SN:FR577	HRS	0		TSN 0		
WC#: 27.275	AFL	0		TSN 0		
PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801PROC. REF: AMM 27-21-09-000-801, AMM 27-21-09-400-801						

27-21-13-101	FUNCTIONAL TEST OF THE RUDDER POWER-CONTROL UNITS (PCU) (CMR**)						Service	ATA:27
	MOS	14-Aug-25					CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)	
WC#: 27.105	AFL	4582						
								PKG:8
PROC. REF: AMM 27-21-13-720-801PROC. REF: AMM 27-21-13-720-801								

27-21-17-900-801-01	RUDDER POSITION TRANSDUCER				Component	ATA:27
PN:GT415-0200-5	MOS/MSC	26-Feb-25	O/C	TSN 7		
SN:MY867	HRS	8641.1		TSN 0		
WC#: 27.280	AFL	4580		TSN 0		
PROC. REF: AMM 27-21-17-000-801, AMM 27-21-17-400-801PROC. REF: AMM 27-21-17-000-801, AMM 27-21-17-400-801						

27-21-21-900-801-01		NO. 1 RUDDER PCU			Component	ATA:27
PN:GT411-2800-5	MOS/MSC	03-Apr-09	O/C			
SN:0066	HRS	1083.1		TSN 2722		
WC#: 27.285	AFL	606		TSN 890		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801

27-21-21-900-801-02	NO. 2 RUDDER PCU								Component ATA:27
PN:GT411-2800-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0540	HRS	0		TSN 0					
WC#: 27.285	AFL	0		TSN 0					
PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801									

27-21-21-900-801-03	NO. 3 RUDDER PCU								Component ATA:27
PN:GT411-2800-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0541	HRS	0		TSN 0					
WC#: 27.285	AFL	0		TSN 0					
PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801PROC. REF: AMM 27-21-13-000-801, AMM 27-21-13-400-801									

27-21-25-900-801-01	LOB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:GC415-0030-33	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6470	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-21-25-900-801-02	LIB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:GC415-0030-33	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6474	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-21-25-900-801-03	RIB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:GC415-0030-33	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6469	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-21-25-900-801-04	ROB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:GC415-0030-33	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6468	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-21-27-101		FUNCTIONAL TEST OF THE RUDDER CABLE TENSION (CMR**)						Service	ATA:27
	MOS	14-Aug-25	30 (+3m/-3m)	Adj 25d	10-Mar-28	10-Jun-28	624 d (+92)	CMR	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 27-21-27-720-801PROC. REF: AMM 27-21-27-720-801									PKG:32

27-22-05-900-801-01		RUDDER FS1047, WL54 TRIM ACTUATOR						Component	ATA:27
PN:GT412-2550-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1135	HRS	0		TSN 0					
WC#: 27.295	AFL	0		TSN 0					
PROC. REF: AMM 27-22-05-000-801, AMM 27-22-05-400-801PROC. REF: AMM 27-22-05-000-801, AMM 27-22-05-400-801									

27-23-00-201 ^S		VISUAL CHECK OF THE RUDDER TRAVEL-LIMITING SYSTEM						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	4500 (+50/-50)						
WC#: 27.110	AFL	4582							
PROC. REF: AMM 27-23-00-210-801PROC. REF: AMM 27-23-00-210-801									PKG:10

27-23-01-900-801-01		LEFT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR						Component	ATA:27
PN:GT412-1500-5	MOS/MSC	17-Oct-22	O/C	TSR 15					
SN:AJ0904	HRS	7657.8		TSR 0					
WC#: 27.300	AFL	4061		TSR 0					
PROC. REF: AMM 27-23-01-000-801, AMM 27-23-01-400-801PROC. REF: AMM 27-23-01-000-801, AMM 27-23-01-400-801									

27-23-01-900-801-02		RIGHT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR						Component	ATA:27
PN:GT412-1500-3	MOS/MSC	16-Nov-22	O/C	TSN 205					
SN:1717	HRS	7677.8		TSN 7677.8					
WC#: 27.300	AFL	4076		TSN 4076					
PROC. REF: AMM 27-23-01-000-801, AMM 27-23-01-400-801PROC. REF: AMM 27-23-01-000-801, AMM 27-23-01-400-801									

27-23-09-900-801-01		LH RUDDER POSITION TRANSDUCER						Component	ATA:27
PN:GT415-2950-1	MOS/MSC	13-Oct-22	O/C	TSN 1					
SN:3667	HRS	7654		TSN 0					
WC#: 27.310	AFL	4057		TSN 0					
PROC. REF: AMM 27-23-09-000-801, AMM 27-23-09-400-801PROC. REF: AMM 27-23-09-000-801, AMM 27-23-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

27-23-09-900-801-02		RH RUDDER POSITION TRANSDUCER						Component	ATA:27
PN:GT415-2950-1	MOS/MSC	24-Jun-12	O/C	TSN 8					
SN:2271	HRS	2676.3		TSN 0					
WC#: 27.310	AFL	1421		TSN 0					
PROC. REF: AMM 27-23-09-000-801, AMM 27-23-09-400-801PROC. REF: AMM 27-23-09-000-801, AMM 27-23-09-400-801									

27-30-00-201 ^S		LUBRICATION OF THE ELEVATOR POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 12-22-00-640-840PROC. REF: AMM 12-22-00-640-840									
									PKG:34

27-31-00-900-801-01		LH FORWARD QUADRANT						Component	ATA:27
PN:GC413-3300-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6250323-001	HRS	0		TSN 0					
WC#: 27.315	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-31-00-900-801-02		RH FORWARD QUADRANT						Component	ATA:27
PN:GC413-3350-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5313583	HRS	0		TSN 0					
WC#: 27.315	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-31-05-201		FUNCTIONAL TEST OF THE PITCH DISCONNECT MECHANISM						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.115	AFL	4582							
									PKG:8
PROC. REF: AMM 27-31-05-720-801PROC. REF: AMM 27-31-05-720-801									

27-31-05-202 ^S		OPERATIONAL TEST OF THE PITCH DISCONNECT MECHANISM						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 27.120	AFL	4582							
									PKG:4
PROC. REF: AMM 27-31-05-710-801PROC. REF: AMM 27-31-05-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

27-31-05-900-801-01		PITCH DISCONNECT						Component	ATA:27
PN:GC415-3250-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5643391	HRS	0		TSN 0					
WC#: 27.325	AFL	0		TSN 0					
PROC. REF: AMM 27-31-05-000-801, AMM 27-31-05-400-801PROC. REF: AMM 27-31-05-000-801, AMM 27-31-05-400-801									

27-31-09-900-801-01		LH ASSEMBLY COLUMN						Component	ATA:27
PN:GC415-3149-5/18	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6537433	HRS	0		TSN 0					
WC#: 27.320	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-31-09-900-801-02		RH ASSEMBLY COLUMN						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.320	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

27-31-09-900-802-01		PITCH LOCK SOLENOID						Component	ATA:27
PN:GC415-3230-1	MOS/MSC	21-Nov-22	O/C	TSN 1					
SN:1682	HRS	7679		TSN 0					
WC#: 27.330	AFL	4078		TSN 0					
PROC. REF: AMM 27-31-09-000-802, AMM 27-31-09-400-802PROC. REF: AMM 27-31-09-000-802, AMM 27-31-09-400-802									

27-31-13-900-801-01		LEFT ELEVATOR LOAD LIMITER						Component	ATA:27
PN:GC415-3550-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR395	HRS	0		TSN 0					
WC#: 27.340	AFL	0		TSN 0					
PROC. REF: AMM 27-31-13-000-801, AMM 27-31-13-400-801PROC. REF: AMM 27-31-13-000-801, AMM 27-31-13-400-801									

27-31-13-900-801-02		RIGHT ELEVATOR LOAD LIMITER						Component	ATA:27
PN:GC415-3550-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR402	HRS	0		TSN 0					
WC#: 27.340	AFL	0		TSN 0					
PROC. REF: AMM 27-31-13-000-801, AMM 27-31-13-400-801PROC. REF: AMM 27-31-13-000-801, AMM 27-31-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-31-13-900-802-01		LH ELEVATOR CONTROL ROD						Component	ATA:27
PN:GC415-0030-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6938	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-31-13-900-802-02		RH ELEVATOR CONTROL ROD						Component	ATA:27
PN:GC415-0030-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TY6942	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-31-17-201		OPERATIONAL TEST OF THE ELEVATOR POWER-CONTROL UNIT (PCU) LOAD LIMITERS						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.125	AFL	4582							
PROC. REF: AMM 27-31-17-710-801PROC. REF: AMM 27-31-17-710-801									
27-31-17-900-801-01		NO. 1 LOAD LIMITER						Component	ATA:27
PN:GC415-3790-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR731	HRS	0		TSN 0					
WC#: 27.345	AFL	0		TSN 0					
PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801									
27-31-17-900-801-02		NO. 2 LOAD LIMITER						Component	ATA:27
PN:GC415-3790-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR733	HRS	0		TSN 0					
WC#: 27.345	AFL	0		TSN 0					
PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801									
27-31-17-900-801-03		NO. 3 LOAD LIMITER						Component	ATA:27
PN:GC415-3790-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR730	HRS	0		TSN 0					
WC#: 27.345	AFL	0		TSN 0					
PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-31-17-900-801-04		NO. 4 LOAD LIMITER						Component	ATA:27
PN:GC415-3790-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR766	HRS	0		TSN 0					
WC#: 27.345	AFL	0		TSN 0					
PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801PROC. REF: AMM 27-31-17-000-801, AMM 27-31-17-400-801									
27-31-19-101		DETAILED INSPECTION OF THE BEARING IN THE ELEVATOR TORQUE TUBE ASSEMBLY (CMR**)						Service	ATA:27
	MOS	07-Oct-05	60 (+3m/-3m)	04-Feb-28 (M)	04-May-28	589 d (+90)	AIRWORTHINESS		
	HRS	0							
	AFL	0							
PROC. REF: AMM 27-31-19-220-801PROC. REF: AMM 27-31-19-220-801									
27-31-21-101		FUNCTIONAL TEST OF THE ELEVATOR POWER-CONTROL UNITS (PCU) (CMR*)						Service	ATA:27
	MOS	08-May-24					CMR		
	HRS	8239.9	1500	9739.9		821.3			
WC#: 27.130	AFL	4398							
PROC. REF: AMM 27-31-21-720-801PROC. REF: AMM 27-31-21-720-801									
27-31-21-900-801-01		NO. 1 ELEVATOR PCU						Component	ATA:27
PN:GT411-3800-7	MOS/MSC	07-Oct-05	O/C	TSR 0					
SN:0739	HRS	0		TSR 0					
WC#: 27.350	AFL	0		TSR 0					
PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801									
27-31-21-900-801-02		NO. 2 ELEVATOR PCU						Component	ATA:27
PN:GT411-3800-7	MOS/MSC	09-May-24	O/C	TSR 1					
SN:2050	HRS	8239.9		TSR 0					
WC#: 27.350	AFL	4398		TSR 0					
PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801									
27-31-21-900-801-03		NO. 3 ELEVATOR PCU						Component	ATA:27
PN:376100-1009	MOS/MSC	12-Jan-15	O/C						
SN:0487	HRS	4061.4							
WC#: 27.350	AFL	2108							
PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-31-21-900-801-04		NO. 4 ELEVATOR PCU						Component	ATA:27
PN:GT411-3800-9	MOS/MSC	08-Aug-20	O/C	TSR 1					
SN:0744	HRS	6919.5		TSR 0					
WC#: 27.350	AFL	3592		TSR 0					
PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801PROC. REF: AMM 27-31-21-000-801, AMM 27-31-21-400-801									
27-31-25-900-801-01		LEFT ELEVATOR POSITION TRANSDUCER						Component	ATA:27
PN:GT415-0200-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SN111	HRS	0		TSN 0					
WC#: 27.355	AFL	0		TSN 0					
PROC. REF: AMM 27-31-25-000-801, AMM 27-31-25-400-801PROC. REF: AMM 27-31-25-000-801, AMM 27-31-25-400-801									
27-31-25-900-801-02		RIGHT ELEVATOR POSITION TRANSDUCER						Component	ATA:27
PN:GT415-0200-5	MOS/MSC	09-Sep-11	O/C	TSN 0					
SN:V3129	HRS	2332.1		TSN 0					
WC#: 27.355	AFL	1215		TSN 0					
PROC. REF: AMM 27-31-25-000-801, AMM 27-31-25-400-801PROC. REF: AMM 27-31-25-000-801, AMM 27-31-25-400-801									
27-31-29-900-801-01		LH ELEVATOR						Component	ATA:27
PN:GS278-0001-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B177	HRS	0		TSN 0					
WC#: 27.360	AFL	0		TSN 0					
PROC. REF: AMM 27-31-29-000-801, AMM 27-31-29-400-801PROC. REF: AMM 27-31-29-000-801, AMM 27-31-29-400-801									
27-31-29-900-801-02		RH ELEVATOR						Component	ATA:27
PN:GS278-0001-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B174	HRS	0		TSN 0					
WC#: 27.360	AFL	0		TSN 0					
PROC. REF: AMM 27-31-29-000-801, AMM 27-31-29-400-801PROC. REF: AMM 27-31-29-000-801, AMM 27-31-29-400-801									
27-31-33-900-803-01		LH ELEVATOR TENSION REGULATOR						Component	ATA:27
PN:GC415-3305-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR236	HRS	0		TSN 0					
WC#: 27.365	AFL	0		TSN 0					
PROC. REF: AMM 27-31-33-000-801, AMM 27-31-33-400-801PROC. REF: AMM 27-31-33-000-801, AMM 27-31-33-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-31-33-900-803-02		RH ELEVATOR TENSION REGULATOR						Component	ATA:27
PN:GC415-3305-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR239	HRS	0		TSN 0					
WC#: 27.365	AFL	0		TSN 0					
PROC. REF: AMM 27-31-33-000-801, AMM 27-31-33-400-801PROC. REF: AMM 27-31-33-000-801, AMM 27-31-33-400-801									
27-31-35-201		FUNCTIONAL TEST OF THE ELEVATOR CABLE TENSION						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 27d	10-Sep-30	10-Dec-30	1538 d (+91)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 27-31-35-720-801PROC. REF: AMM 27-31-35-720-801									
27-32-01-900-801-01		RIGHT FORWARD STALL PROTECTION COMPUTER						Component	ATA:27
PN:GH582-3001-9	MOS/MSC	07-Oct-05	O/C						
SN:227	HRS	0							
WC#: 27.370	AFL	0							
PROC. REF: AMM 27-32-01-000-801, AMM 27-32-01-400-801PROC. REF: AMM 27-32-01-000-801, AMM 27-32-01-400-801									
27-32-05-900-801-01		PILOT STICK SHAKER						Component	ATA:27
PN:GH582-3003-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:515	HRS	0		TSN 0					
WC#: 27.375	AFL	0		TSN 0					
PROC. REF: AMM 27-32-05-000-801, AMM 27-32-05-400-801PROC. REF: AMM 27-32-05-000-801, AMM 27-32-05-400-801									
27-32-05-900-801-02		COPILOT STICK SHAKER						Component	ATA:27
PN:GH582-3003-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:518	HRS	0		TSN 0					
WC#: 27.375	AFL	0		TSN 0					
PROC. REF: AMM 27-32-05-000-801, AMM 27-32-05-400-801PROC. REF: AMM 27-32-05-000-801, AMM 27-32-05-400-801									
27-32-09-900-801-01		LH AOA SENSOR						Component	ATA:27
PN:GH582-3002-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:392	HRS	0		TSN 0					
WC#: 27.380	AFL	0		TSN 0					
PROC. REF: AMM 27-32-09-000-801, AMM 27-32-09-400-801PROC. REF: AMM 27-32-09-000-801, AMM 27-32-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-32-09-900-801-02		RH AOA SENSOR						Component	ATA:27
PN:GH582-3002-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:389	HRS	0		TSN 0					
WC#: 27.380	AFL	0		TSN 0					
PROC. REF: AMM 27-32-09-000-801, AMM 27-32-09-400-801PROC. REF: AMM 27-32-09-000-801, AMM 27-32-09-400-801									
27-32-13-900-801-01		MACH TRANSDUCER						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.385	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-32-17-900-801-01		LH STICK PUSHER ACTUATOR						Component	ATA:27
PN:GH582-3005-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1449	HRS	0		TSN 0					
WC#: 27.390	AFL	0		TSN 0					
PROC. REF: AMM 27-32-17-000-801, AMM 27-32-17-400-801PROC. REF: AMM 27-32-17-000-801, AMM 27-32-17-400-801									
27-32-17-900-801-02		RH STICK PUSHER ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.390	AFL	0		TSN 0					
PROC. REF: AMM 27-32-17-000-801, AMM 27-32-17-400-801PROC. REF: AMM 27-32-17-000-801, AMM 27-32-17-400-801									
27-32-21-900-801-01		ASSY CAPSTAN						Component	ATA:27
PN:GH582-3006-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1722	HRS	0		TSN 0					
WC#: 27.395	AFL	0		TSN 0					
PROC. REF: AMM 27-32-21-000-801, AMM 27-32-21-400-801PROC. REF: AMM 27-32-21-000-801, AMM 27-32-21-400-801									
27-33-01-900-801-01		LH PITCH WHEEL SIMULATOR						Component	ATA:27
PN:GC415-3490-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:365	HRS	0		TSN 0					
WC#: 27.400	AFL	0		TSN 0					
PROC. REF: AMM 27-33-01-000-801, AMM 27-33-01-400-801PROC. REF: AMM 27-33-01-000-801, AMM 27-33-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-33-01-900-801-02		RH PITCH WHEEL SIMULATOR						Component	ATA:27
PN:GC415-3490-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:366	HRS	0		TSN 0					
WC#: 27.400	AFL	0		TSN 0					
PROC. REF: AMM 27-33-01-000-801, AMM 27-33-01-400-801PROC. REF: AMM 27-33-01-000-801, AMM 27-33-01-400-801									
27-33-05-900-801-01		LEFT PITCH FEEL TRIM ACTUATOR						Component	ATA:27
PN:GT412-1500-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1737	HRS	0		TSN 0					
WC#: 27.405	AFL	0		TSN 0					
PROC. REF: AMM 27-33-05-000-801, AMM 27-33-05-400-801PROC. REF: AMM 27-33-05-000-801, AMM 27-33-05-400-801									
27-33-05-900-801-02		RIGHT PITCH FEEL TRIM ACTUATOR						Component	ATA:27
PN:GT412-1500-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1717	HRS	0		TSN 0					
WC#: 27.405	AFL	0		TSN 0					
PROC. REF: AMM 27-33-05-000-801, AMM 27-33-05-400-801PROC. REF: AMM 27-33-05-000-801, AMM 27-33-05-400-801									
27-41-00-201		LUBRICATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR						Service	ATA:27
	MOS	14-Aug-25	15 (+3m/-3m)	Adj 3	14-Feb-27	14-May-27	234 d (+89)		
	HRS	8645	500 (+50/-50)	Adj 50	9195	9245	276.4 (+50)		
	AFL	4582							
PROC. REF: AMM 12-22-00-640-812PROC. REF: AMM 12-22-00-640-812									
27-41-00-202 ^S		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR						Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.135	AFL	4582							
PROC. REF: AMM 27-41-09-220-802PROC. REF: AMM 27-41-09-220-802									
27-41-09-101		SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (EXCLUDING AIRCRAFT ATTACHMENT PINS) (AWL*)						Service	ATA:27
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 27.140	AFL	0	T:7500		7500		2793		
PKG:76									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

PROC. REF: AMM 27-41-09-280-801PROC. REF: AMM 27-41-09-280-801

27-41-09-103	DETAILED INSPECTION OF THE PITCH TRIM ACTUATOR (CMR*)							Service	ATA:27
	MOS	13-Nov-24						CMR	
	HRS	8623.4	500		9123.4		204.8		
WC#: 27.145	AFL	4570							

PROC. REF: AMM 27-41-09-220-801PROC. REF: AMM 27-41-09-220-801

PKG:2

27-41-09-104	DISCARD THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-3							Service	ATA:27
PN:GT412-4001-7	MOS/MSC	15-Jun-17	O/C						
SN:0097B	HRS	5428.8							
	AFL	2792							

PROC. REF: AMM 27-41-09-961-801PROC. REF: AMM 27-41-09-961-801

27-41-09-105	DISCARD THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-5/7							Service	ATA:27
PN:GT412-4001-7	MOS/MSC	15-Jun-17	O/C						
SN:0097B	HRS	5428.8		TAC 5672.7					
	AFL	2792		TAC 2147					

PROC. REF: AMM 27-41-09-961-801PROC. REF: AMM 27-41-09-961-801

27-41-09-106	RESTORATION OF THE PITCH TRIM ACTUATOR (GEAR HOUSINGREPLACEMENT), PART NO. GT412-4001-5 (AWL*)							Service	ATA:27
PN:GT412-4001-7	MOS/MSC	12-May-14	N/A						
SN:0097B	HRS	3646.4							
WC#: 27.150	AFL	1928							

PROC. REF: AMM 27-41-29-610-801PROC. REF: AMM 27-41-29-610-801

27-41-09-107	RESTORATION OF THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-7 (AWL*)							Service	ATA:27
PN:GT412-4001-7	MOS	15-Jun-17						RESTORE	
SN:0097B	HRS	5428.8							
	AFL	2792	7500	TAC 2147	8145		3438		

PROC. REF: AMM 27-41-09-840-801PROC. REF: AMM 27-41-09-840-801

27-41-09-900-801-01	PITCH TRIM ACTUATOR							Component	ATA:27
PN:GT412-4001-7	MOS/MSC	15-Jun-17	O/C	TSR 4					
SN:0097B	HRS	5428.8		TSN 5672.7, TSR 0					
WC#: 27.145	AFL	2792		TSN 2147, TSR 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
PROC. REF: AMM 27-41-09-000-801, AMM 27-41-09-400-801PROC. REF: AMM 27-41-09-000-801, AMM 27-41-09-400-801									
27-41-17-900-801-01	DRIVE UNIT - HORIZONTAL STAB MOTOR							Component	ATA:27
PN:GT415-4002-11	MOS/MSC	22-Sep-25	O/C						
SN:2157	HRS	8645.87							
WC#: 27.415	AFL	4580							
PROC. REF: AMM 27-41-17-000-801, AMM 27-41-17-400-801PROC. REF: AMM 27-41-17-000-801, AMM 27-41-17-400-801									
27-50-00-201 ^S	LUBRICATION OF THE FLAP DRIVE TORQUE-TUBE SPLINES							Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.155	AFL	4582							
PKG:34									
PROC. REF: AMM 12-22-00-640-827PROC. REF: AMM 12-22-00-640-827									
27-50-00-202 ^S	LUBRICATION OF THE SLAT DRIVE TORQUE-TUBE SPLINES							Service	ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.160	AFL	4582							
PKG:34									
PROC. REF: AMM 12-22-00-640-828PROC. REF: AMM 12-22-00-640-828									
27-50-00-203	LUBRICATION OF THE FLAP ACTUATOR BALLSCREWS AND BALLNUTS							Service	ATA:27
	MOS	14-Aug-25	15 (+3m/-3m)	Adj 3	14-Feb-27	14-May-27	234 d (+89)	MRB	
	HRS	8645							
WC#: 27.165	AFL	4582							
PKG:31									
PROC. REF: AMM 12-22-00-640-829PROC. REF: AMM 12-22-00-640-829									
27-50-00-204	LUBRICATION OF THE SLAT ACTUATOR BALLSCREWS							Service	ATA:27
	MOS	14-Aug-25	15 (+3m/-3m)	Adj 3	14-Feb-27	14-May-27	234 d (+89)	MRB	
	HRS	8645							
WC#: 27.170	AFL	4582							
PKG:31									
PROC. REF: AMM 12-22-00-640-830PROC. REF: AMM 12-22-00-640-830									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-50-00-205		LUBRICATION OF THE FLAP ROLLERS							Service ATA:27
	MOS	06-Jun-24						MRB	
	HRS	8259.5	1500 (+50/-50)		9759.5	9809.5	840.9 (+50)		
WC#: 27.175	AFL	4418							
PROC. REF: AMM 12-22-00-640-831PROC. REF: AMM 12-22-00-640-831									
27-50-00-206 ^S		LUBRICATION OF THE SLAT ROLLERS							Service ATA:27
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 27.180	AFL	4582							
PROC. REF: AMM 12-22-00-640-832PROC. REF: AMM 12-22-00-640-832									
27-50-00-207 ^S		LUBRICATION OF THE FLAP SKEW SENSOR NO. 1 (A/C 9001 AND SUBS) AND FLAP SKEW SENSORS NO. 2, 3 AND 4 (A/C 9002 TO 9126 AND 9128 TO 9178, PRE SB 700-27-049)							Service ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 27.185	AFL	4582	450 (+50/-50)						
PROC. REF: AMM 12-22-00-640-835PROC. REF: AMM 12-22-00-640-835									
27-51-01-900-801-01		FLAP/SLAT LEVER							Component ATA:27
PN:GT415-5600-5	MOS/MSC	19-Nov-06	O/C	TSN 1					
SN:EO225	HRS	80.6		TSN 0					
WC#: 27.420	AFL	36		TSN 0					
PROC. REF: AMM 27-51-01-000-801, AMM 27-51-01-400-801PROC. REF: AMM 27-51-01-000-801, AMM 27-51-01-400-801									
27-51-05-900-801-01		LH SFCU FAN							Component ATA:27
PN:GT415-5903-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:104317029	HRS	0		TSN 0					
WC#: 27.425	AFL	0		TSN 0					
PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801									
27-51-05-900-801-02		RH SFCU FAN							Component ATA:27
PN:GT415-5903-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:104317039	HRS	0		TSN 0					
WC#: 27.425	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 27 - FLIGHT CONTROLS										
PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801										
27-51-05-900-802-01		LH FLAP/SLAT CONTROL UNIT							Component	ATA:27
PN:GT415-5900-17	MOS/MSC	30-Apr-18	O/C	TSR 1						
SN:1283	HRS	5932.5	TSR 962							
WC#: 27.430	AFL	3052	TSR 326							
PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801										
27-51-05-900-802-02		RH FLAP/SLAT CONTROL UNIT							Component	ATA:27
PN:GT415-5900-19	MOS/MSC	25-Jan-18	O/C	TSR 7						
SN:2004	HRS	5751.8	TSR 0							
WC#: 27.430	AFL	2972	TSR 0							
PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801PROC. REF: AMM 27-51-05-000-801, AMM 27-51-05-400-801										
27-52-01-900-801-01		LEFT MLG WHEEL WELL FLAP TORQUE TUBE							Component	ATA:27
PN:GT415-5201-3	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:2521	HRS	0	TSN 0							
WC#: 27.435	AFL	0	TSN 0							
PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801										
27-52-01-900-801-02		LIB FLAP TORQUE TUBE							Component	ATA:27
PN:GT415-5201-7	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:2552	HRS	0	TSN 0							
WC#: 27.440	AFL	0	TSN 0							
PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801										
27-52-01-900-801-03		RIB FLAP TORQUE TUBE							Component	ATA:27
PN:GT415-5201-7	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:2557	HRS	0	TSN 0							
WC#: 27.440	AFL	0	TSN 0							
PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801PROC. REF: AMM 27-52-01-000-801, AMM 27-52-01-400-801										
27-52-09-900-801-01		LEFT NO.1 FLAP ACTUATOR GEARBOX							Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
WC#: 27.445	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-801-02		LEFT NO.2 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.445	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-801-03		LEFT NO.3 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.445	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-801-04		LEFT NO.4 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:GT412-5011-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2562	HRS	0		TSN 0					
WC#: 27.445	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-801-05		RIGHT NO.1 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-801-06		RIGHT NO.2 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-801-07		RIGHT NO.3 FLAP ACTUATOR GEARBOX						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-801-08 RIGHT NO.4 FLAP ACTUATOR GEARBOX								Component	ATA:27
PN:GT412-5011-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2560	HRS	0		TSN 0					
WC#: 27.450	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-09-900-802-01 LH NO.1 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5002-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0411	HRS	0		TSN 0					
WC#: 27.455	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-02 RH NO.1 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5002-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0408	HRS	0		TSN 0					
WC#: 27.460	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-03 LH NO.2 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5005-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0252	HRS	0		TSN 0					
WC#: 27.465	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-04 RH NO.2 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5004-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0259	HRS	0		TSN 0					
WC#: 27.470	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-05 LH NO.3 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5006-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:394	HRS	0		TSN 0					
WC#: 27.475	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-802-06 RH NO.3 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5006-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0390	HRS	0		TSN 0					
WC#: 27.480	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-07 LH NO.4 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5008-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0400	HRS	0		TSN 0					
WC#: 27.485	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-09-900-802-08 RH NO.4 FLAP ACTUATOR ASSEMBLY								Component	ATA:27
PN:GT412-5008-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0403	HRS	0		TSN 0					
WC#: 27.490	AFL	0		TSN 0					
PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801PROC. REF: AMM 27-52-09-000-801, AMM 27-52-09-400-801									
27-52-13-900-801-01 FLAP LH WS131.500 T/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5101-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2534	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-52-13-900-801-02 FLAP LH WS199.000 T/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5101-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2535	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-52-13-900-801-03 FLAP RH WS131.500 T/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5101-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2536	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-13-900-801-04 FLAP RH WS199.000 T/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5101-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2537	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-52-21-900-801-01 LH INBOARD FLAP								Component	ATA:27
PN:GM148-1001-33	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0175	HRS	0		TSN 0					
WC#: 57.720	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-21-900-801-02 RH INBOARD FLAP								Component	ATA:27
PN:GM148-1001-34	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0173	HRS	0		TSN 0					
WC#: 57.720	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-25-900-801-01 LH MIDDLE FLAP								Component	ATA:27
PN:GM148-1002-29	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0174	HRS	0		TSN 0					
WC#: 57.715	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-25-900-801-02 RH MIDDLE FLAP								Component	ATA:27
PN:GM148-1002-30	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0174	HRS	0		TSN 0					
WC#: 57.715	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-29-900-801-01 LH OUTBOARD FLAP								Component	ATA:27
PN:GM148-1003-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0176	HRS	0		TSN 0					
WC#: 57.710	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-29-900-801-02		RH OUTBOARD FLAP						Component	ATA:27
PN:GM148-1003-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0174	HRS	0		TSN 0					
WC#: 57.710	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-52-41-900-801-01		LH ELECTRICAL SLAT/FLAP PDU MOTOR						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.575	AFL	0		TSN 0					
PROC. REF: AMM 27-52-41-000-801, AMM 27-52-41-400-801, AMM 27-53-37-000-801, AMM 27-53-37-400-801PROC. REF: AMM 27-52-41-000-801, AMM 27-52-41-400-801, AMM 27-53-37-000-801, AMM 27-53-37-400-801									
27-52-41-900-801-02		RH ELECTRICAL SLAT/FLAP PDU MOTOR						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.575	AFL	0		TSN 0					
PROC. REF: AMM 27-52-41-000-801, AMM 27-52-41-400-801, AMM 27-53-37-000-801, AMM 27-53-37-400-801PROC. REF: AMM 27-52-41-000-801, AMM 27-52-41-400-801, AMM 27-53-37-000-801, AMM 27-53-37-400-801									
27-52-49-900-801-01		LEFT FLAP (FLAP/SLAT) RESOLVER						Component	ATA:27
PN:GT415-5300-5	MOS/MSC	12-Mar-23	O/C	TSN 0					
SN:C4770	HRS	7773.2		TSN 0					
WC#: 27.495	AFL	4132		TSN 0					
PROC. REF: AMM 27-53-41-820-801, AMM 27-52-49-000-801, AMM 27-52-49-400-801PROC. REF: AMM 27-53-41-820-801, AMM 27-52-49-000-801, AMM 27-52-49-400-801									
27-52-49-900-801-02		RIGHT FLAP (FLAP/SLAT) RESOLVER						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.495	AFL	0		TSN 0					
PROC. REF: AMM 27-53-41-820-801, AMM 27-52-49-000-801, AMM 27-52-49-400-801PROC. REF: AMM 27-53-41-820-801, AMM 27-52-49-000-801, AMM 27-52-49-400-801									
27-52-53-900-801-01		LEFT FLAP ASSYMETRY BRAKE						Component	ATA:27
PN:GT415-5500-3	MOS/MSC	06-Oct-15	O/C	TSR 14					
SN:0789	HRS	4471.1		TSR 0					
WC#: 27.500	AFL	2321		TSR 0					
PROC. REF: AMM 27-52-53-000-801, AMM 27-52-53-400-801PROC. REF: AMM 27-52-53-000-801, AMM 27-52-53-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-52-53-900-801-02		RIGHT FLAP ASSYMETRY BRAKE						Component	ATA:27
PN:GT415-5500-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0755	HRS	0		TSN 0					
WC#: 27.500	AFL	0		TSN 0					
PROC. REF: AMM 27-52-53-000-801, AMM 27-52-53-400-801PROC. REF: AMM 27-52-53-000-801, AMM 27-52-53-400-801									
27-52-57-101		DETAILED INSPECTION OF THE FLAP ROLLERS (CMR*)						Service	ATA:27
	MOS	14-Aug-25						CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.190	AFL	4582							
PROC. REF: AMM 27-52-57-220-801PROC. REF: AMM 27-52-57-220-801									
27-53-01-900-801-01		LH SLAT NO. 3 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5200-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2548	HRS	0		TSN 0					
WC#: 27.505	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									
27-53-01-900-801-02		RIGHT SLAT NO. 3 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5200-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2549	HRS	0		TSN 0					
WC#: 27.505	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									
27-53-01-900-801-03		LEFT SLAT NO.1 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5207-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2549	HRS	0		TSN 0					
WC#: 27.510	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									
27-53-01-900-801-04		RIGHT SLAT NO. 1 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5207-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2550	HRS	0		TSN 0					
WC#: 27.510	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-01-900-801-05		LH SLAT NO. 4 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5200-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2566	HRS	0		TSN 0					
WC#: 27.515	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									
27-53-01-900-801-06		RIGHT SLAT NO. 4 SLAT TORQUE TUBE						Component	ATA:27
PN:GT415-5200-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2567	HRS	0		TSN 0					
WC#: 27.515	AFL	0		TSN 0					
PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801PROC. REF: AMM 27-53-01-000-801, AMM 27-53-01-400-801									
27-53-09-101		FUNCTIONAL TEST OF THE SLAT SYSTEM ACTUATORS (CMR**)						Service	ATA:27
	MOS	14-Aug-25						CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 27.195	AFL	4582							
PROC. REF: AMM 27-53-09-720-804PROC. REF: AMM 27-53-09-720-804									
27-53-09-900-803-01		LEFT NO.1 SLAT ACTUATOR						Component	ATA:27
PN:GT412-5601-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0389	HRS	0		TSN 0					
WC#: 27.520	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-02		RIGHT NO. 1 SLAT ACTUATOR						Component	ATA:27
PN:GT412-5601-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0390	HRS	0		TSN 0					
WC#: 27.520	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-03		LEFT NO.2 SLAT ACTUATOR						Component	ATA:27
PN:GT412-5602-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0388	HRS	0		TSN 0					
WC#: 27.525	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-04 RIGHT NO. 2 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5602-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0390	HRS	0		TSN 0					
WC#: 27.525	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-05 LEFT NO.3 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5603-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0402	HRS	0		TSN 0					
WC#: 27.530	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-06 RIGHT NO. 3 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5603-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0403	HRS	0		TSN 0					
WC#: 27.530	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-07 LEFT NO.4 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5604-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0387	HRS	0		TSN 0					
WC#: 27.535	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-08 RIGHT NO. 4 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5604-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0401	HRS	0		TSN 0					
WC#: 27.535	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-09 LEFT NO.5 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5605-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0408	HRS	0		TSN 0					
WC#: 27.540	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-10 RIGHT NO. 5 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5605-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0413	HRS	0		TSN 0					
WC#: 27.540	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-11 LEFT NO.6 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5606-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0398	HRS	0		TSN 0					
WC#: 27.545	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-12 RIGHT NO. 6 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5606-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0399	HRS	0		TSN 0					
WC#: 27.545	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-13 LEFT NO.7 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5607-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0410	HRS	0		TSN 0					
WC#: 27.550	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-14 RIGHT NO. 7 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5607-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0411	HRS	0		TSN 0					
WC#: 27.550	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-09-900-803-15 LEFT NO.8 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5609-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0253	HRS	0		TSN 0					
WC#: 27.555	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-16		RIGHT NO. 8 SLAT ACTUATOR						Component	ATA:27
PN:GT412-5608-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:02536/06/05	HRS	0		TSN 0					
WC#: 27.555	AFL	0		TSN 0					
PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801PROC. REF: AMM 27-53-09-000-801, AMM 27-53-09-400-801									
27-53-13-900-801-01		FLAP LH WS163.416 T/E DRIVE SHAFT RETAIN BEARING						Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2847	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-53-13-900-801-02		FLAP LH WS250.000 T/E DRIVE SHAFT RETAIN BEARING						Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2846	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-53-13-900-801-03		FLAP LH WS420.911 T/E DRIVE SHAFT RETAIN BEARING						Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2845	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-53-13-900-801-04		FLAP RH WS163.416 T/E DRIVE SHAFT RETAIN BEARING						Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2848	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-53-13-900-801-05		FLAP RH WS250.000 T/E DRIVE SHAFT RETAIN BEARING						Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2849	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-13-900-801-06 FLAP RH WS420.911 T/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2850	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801PROC. REF: AMM 27-52-13-000-801, AMM 27-52-13-400-801									
27-53-13-900-801-07 SLAT LH WS92.954 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2839	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									
27-53-13-900-801-08 SLAT LH WS265.000 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2840	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									
27-53-13-900-801-09 SLAT LH WS391.000 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2841	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									
27-53-13-900-801-10 SLAT RH WS92.954 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2842	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									
27-53-13-900-801-11 SLAT RH WS265.000 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2843	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-13-900-801-12 SLAT RH WS391.000 L/E DRIVE SHAFT RETAIN BEARING								Component	ATA:27
PN:GT415-5100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2844	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801PROC. REF: AMM 27-53-13-000-801, AMM 27-53-13-400-801									
27-53-17-900-801-01 LH NO.1 SLAT								Component	ATA:27
PN:GM128-1011-19	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0008	HRS	0		TSN 0					
WC#: 27.560	AFL	0		TSN 0					
PROC. REF: AMM 27-53-17-000-801, AMM 27-53-17-400-801PROC. REF: AMM 27-53-17-000-801, AMM 27-53-17-400-801									
27-53-17-900-801-02 RH NO.1 SLAT								Component	ATA:27
PN:GM128-1011-20	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0007	HRS	0		TSN 0					
WC#: 27.560	AFL	0		TSN 0					
PROC. REF: AMM 27-53-17-000-801, AMM 27-53-17-400-801PROC. REF: AMM 27-53-17-000-801, AMM 27-53-17-400-801									
27-53-21-900-801-01 LH NO.2 SLAT								Component	ATA:27
PN:GM128-1012-15	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0009	HRS	0		TSN 0					
WC#: 27.565	AFL	0		TSN 0					
PROC. REF: AMM 27-53-21-000-801, AMM 27-53-21-400-801PROC. REF: AMM 27-53-21-000-801, AMM 27-53-21-400-801									
27-53-21-900-801-02 RH NO.2 SLAT								Component	ATA:27
PN:GM128-1012-16	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0011	HRS	0		TSN 0					
WC#: 27.565	AFL	0		TSN 0					
PROC. REF: AMM 27-53-21-000-801, AMM 27-53-21-400-801PROC. REF: AMM 27-53-21-000-801, AMM 27-53-21-400-801									
27-53-25-900-801-01 LH NO.3 SLAT								Component	ATA:27
PN:GM128-1013-15	MOS/MSC	08-Nov-06	O/C	TSN 0					
SN:SB0058	HRS	36.5		TSN 0					
WC#: 27.570	AFL	14		TSN 0					
PROC. REF: AMM 27-53-25-000-801, AMM 27-53-25-400-801PROC. REF: AMM 27-53-25-000-801, AMM 27-53-25-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-25-900-801-02		RH NO.3 SLAT						Component	ATA:27
PN:GM128-1013-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0007	HRS	0		TSN 0					
WC#: 27.570	AFL	0		TSN 0					
PROC. REF: AMM 27-53-25-000-801, AMM 27-53-25-400-801PROC. REF: AMM 27-53-25-000-801, AMM 27-53-25-400-801									
27-53-29-900-801-01		LH NO.4 SLAT						Component	ATA:27
PN:GM128-1014-21	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0008	HRS	0		TSN 0					
WC#: 27.580	AFL	0		TSN 0					
PROC. REF: AMM 27-53-29-000-801, AMM 27-53-29-400-801PROC. REF: AMM 27-53-29-000-801, AMM 27-53-29-400-801									
27-53-29-900-801-02		RH NO.4 SLAT						Component	ATA:27
PN:GM128-1014-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB0014	HRS	0		TSN 0					
WC#: 27.580	AFL	0		TSN 0					
PROC. REF: AMM 27-53-29-000-801, AMM 27-53-29-400-801PROC. REF: AMM 27-53-29-000-801, AMM 27-53-29-400-801									
27-53-33-900-801-01		SLAT FLAP/SLAT PDU						Component	ATA:27
PN:GT415-5001-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0409	HRS	0		TSN 0					
WC#: 27.585	AFL	0		TSN 0					
PROC. REF: AMM 27-53-33-000-801, AMM 27-53-33-400-801PROC. REF: AMM 27-53-33-000-801, AMM 27-53-33-400-801									
27-53-33-900-801-02		FLAP FLAP/SLAT PDU						Component	ATA:27
PN:GT415-5001-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0410	HRS	0		TSN 0					
WC#: 27.590	AFL	0		TSN 0					
PROC. REF: AMM 27-53-33-000-801, AMM 27-53-33-400-801PROC. REF: AMM 27-53-33-000-801, AMM 27-53-33-400-801									
27-53-41-900-801-01		LEFT SLAT (FLAP/SLAT) RESOLVER						Component	ATA:27
PN:GT415-5300-3	MOS/MSC	20-Aug-08	O/C	TSR 9					
SN:B0467	HRS	858.7		TSO 0, TSR 0					
WC#: 27.595	AFL	465		TSR 0					
PROC. REF: AMM 27-53-41-820-801, AMM 27-53-41-000-801, AMM 27-53-41-400-801PROC. REF: AMM 27-53-41-820-801, AMM 27-53-41-000-801, AMM 27-53-41-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-53-41-900-801-02		RIGHT SLAT (FLAP/SLAT) RESOLVER						Component	ATA:27
PN:GT415-5300-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0887 / 0855	HRS	0		TSN 0					
WC#: 27.595	AFL	0		TSN 0					
PROC. REF: AMM 27-53-41-820-801, AMM 27-53-41-000-801, AMM 27-53-41-400-801PROC. REF: AMM 27-53-41-820-801, AMM 27-53-41-000-801, AMM 27-53-41-400-801									
27-53-45-900-801-01		LEFT SLAT ASSYMETRY BRAKE						Component	ATA:27
PN:GT415-5500-3	MOS/MSC	14-Jun-09	O/C	TSR 3					
SN:0844	HRS	1132		TSR 0					
WC#: 27.600	AFL	649		TSR 0					
PROC. REF: AMM 27-53-45-000-801, AMM 27-53-45-400-801PROC. REF: AMM 27-53-45-000-801, AMM 27-53-45-400-801									
27-53-45-900-801-02		RIGHT SLAT ASSYMETRY BRAKE						Component	ATA:27
PN:GT415-5500-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0724	HRS	0		TSN 0					
WC#: 27.600	AFL	0		TSN 0					
PROC. REF: AMM 27-53-45-000-801, AMM 27-53-45-400-801PROC. REF: AMM 27-53-45-000-801, AMM 27-53-45-400-801									
27-60-00-101		OPERATIONAL TEST OF THE SPOILER POWER-CONTROL UNITS (PCU) (CMR**)						Service	ATA:27
	MOS	22-May-24						CMR	
	HRS	8251.1	1500 (+50/-50)	Adj 50	9801.1	9851.1	882.5 (+50)		
WC#: 27.200	AFL	4407							
PROC. REF: AMM 27-60-00-710-801PROC. REF: AMM 27-60-00-710-801									
27-61-01-900-801-01		FLIGHT SPOILER CONTROL LEVER (FS235 WL89 LBL2)						Component	ATA:27
PN:GT415-6004-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:FR194	HRS	0		TSN 0					
WC#: 27.605	AFL	0		TSN 0					
PROC. REF: AMM 27-61-01-000-801, AMM 27-61-01-400-801PROC. REF: AMM 27-61-01-000-801, AMM 27-61-01-400-801									
27-61-05-201 ^S		OPERATIONAL TEST OF THE FLIGHT-CONTROL UNIT (FCU) BACK-UP MODULES						Service	ATA:27
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 27.205	AFL	4582							
PROC. REF: AMM 27-61-05-710-801PROC. REF: AMM 27-61-05-710-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-61-05-900-801-01	NO. 1 FLIGHT CONTROL UNIT FCU								Component ATA:27
PN:GT415-0100-9	MOS/MSC	11-Jun-23	O/C	TSR 1					
SN:890	HRS	7862		TSR 0					
WC#: 27.610	AFL	4196		TSR 0					
PROC. REF: AMM 27-61-05-000-801, AMM 27-61-05-400-801PROC. REF: AMM 27-61-05-000-801, AMM 27-61-05-400-801									
27-61-05-900-801-02	NO. 2 FLIGHT CONTROL UNIT FCU								Component ATA:27
PN:GT415-0100-9	MOS/MSC	11-Jun-23	O/C						
SN:429	HRS	7862							
WC#: 27.610	AFL	4196							
PROC. REF: AMM 27-61-05-000-801, AMM 27-61-05-400-801PROC. REF: AMM 27-61-05-000-801, AMM 27-61-05-400-801									
27-61-17-101	OPERATIONAL TEST OF THE GROUND LIFT DUMPING								Service ATA:27
	MOS/MSC	20-Mar-18	O/C						
	HRS	5807.9							
WC#: 27.210	AFL	3006							
PROC. REF: AMM 27-61-00-710-802PROC. REF: AMM 27-61-00-710-802									
27-62-01-900-801-01	LOB MULTIFUNCTION SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1473A	HRS	0		TSN 0					
WC#: 27.615	AFL	0		TSN 0					
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-02	LOB MULTIFUNCTION FLIGHT SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1490A	HRS	0		TSN 0					
WC#: 27.620	AFL	0		TSN 0					
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-03	LIB MULTIFUNCTION SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1483A	HRS	0		TSN 0					
WC#: 27.625	AFL	0		TSN 0					
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-62-01-900-801-04		LIB MULTIFUNCTION FLIGHT SPOILER PCU						Component	ATA:27
PN:376300-1009	MOS/MSC	12-Jan-15	O/C	TSR 0					
SN:2163C	HRS	4061.4	TSR 0						
WC#: 27.630	AFL	2108	TSR 0						
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-05		RIB MULTIFUNCTION SPOILER PCU						Component	ATA:27
PN:GT411-6001-9	MOS/MSC	19-May-15	O/C	TSR 2					
SN:1488C	HRS	4228.4	TSR 0						
WC#: 27.635	AFL	2192	TSR 0						
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-06		RIB MULTIFUNCTION FLIGHT SPOILER PCU						Component	ATA:27
PN:GT411-6001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1539A	HRS	0	TSN 0						
WC#: 27.640	AFL	0	TSN 0						
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-07		ROB MULTIFUNCTION SPOILER PCU						Component	ATA:27
PN:GT411-6001-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1484A	HRS	0	TSN 0						
WC#: 27.645	AFL	0	TSN 0						
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-01-900-801-08		ROB MULTIFUNCTION FLIGHT SPOILER PCU						Component	ATA:27
PN:GT411-6001-9	MOS/MSC	20-Jun-15	O/C	TSR 1					
SN:1812C	HRS	4251.3	TSR 0						
WC#: 27.650	AFL	2213	TSR 0						
PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801PROC. REF: AMM 27-62-01-000-801, AMM 27-62-01-400-801									
27-62-09-900-801-01		LOB FLIGHT SPOILER						Component	ATA:27
PN:GM168-1500-1	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0176	HRS	7751.1	TSN 7751.1						
WC#: 27.655	AFL	4121	TSN 4121						
PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-62-09-900-801-02		LIB FLIGHT SPOILER						Component	ATA:27
PN:GM168-1400-1	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0176	HRS	7751.1		TSN 7751.1					
WC#: 27.660	AFL	4121		TSN 4121					
PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801									
27-62-09-900-801-03		RIB FLIGHT SPOILER						Component	ATA:27
PN:GM168-1400-2	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0177	HRS	7751.1		TSN 7751.1					
WC#: 27.665	AFL	4121		TSN 4121					
PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801									
27-62-09-900-801-04		ROB FLIGHT SPOILER						Component	ATA:27
PN:GM168-1500-2	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0176	HRS	7751.1		TSN 7751.1					
WC#: 27.670	AFL	4121		TSN 4121					
PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801PROC. REF: AMM 27-62-09-000-801, AMM 27-62-09-400-801									
27-63-01-900-801-01		INBOARD SELECTOR, GROUND SPOILER VALVE						Component	ATA:27
PN:GT411-6003-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0398	HRS	0		TSN 0					
WC#: 27.675	AFL	0		TSN 0					
PROC. REF: AMM 27-63-01-000-801, AMM 27-63-01-400-801PROC. REF: AMM 27-63-01-000-801, AMM 27-63-01-400-801									
27-63-01-900-801-02		OUTBOARD SELECTOR, GROUND SPOILER VALVE						Component	ATA:27
PN:GT411-6003-3	MOS/MSC	27-Jul-10	O/C	TSN 0					
SN:0442	HRS	1674.6		TSN 0					
WC#: 27.680	AFL	916		TSN 0					
PROC. REF: AMM 27-63-01-000-801, AMM 27-63-01-400-801PROC. REF: AMM 27-63-01-000-801, AMM 27-63-01-400-801									
27-63-05-900-801-01		LOB GROUND SPOILER ACTUATOR						Component	ATA:27
PN:GT411-6002-3	MOS/MSC	29-Apr-15	O/C	TSR 2					
SN:0901	HRS	4228.4		TSN 2916, TSR 0					
WC#: 27.685	AFL	2192		TSN 1296, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
27-63-05-900-801-02		LIB GROUND SPOILER ACTUATOR						Component	ATA:27
PN:GT411-6002-3	MOS/MSC	11-May-11	O/C						
SN:1482	HRS	2157.3		TSN 383					
WC#: 27.690	AFL	1140		TSN 132					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-63-05-900-801-03		RIB GROUND SPOILER ACTUATOR						Component	ATA:27
PN:GT411-6002-3	MOS/MSC	29-Apr-15	O/C	TSR 3					
SN:2156	HRS	4228.4		TSR 0					
WC#: 27.695	AFL	2192		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
27-63-05-900-801-04		ROB GROUND SPOILER ACTUATOR						Component	ATA:27
PN:GT411-6002-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0731	HRS	0		TSN 0					
WC#: 27.670	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272105-001 ^U		AFT FUSELAGE RUDDER TRIM ACTUATOR						Component	ATA:27
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.260	AFL	0		TSN 0					
275001-708 ^U		RH#4 FLAP SKEW SENSOR						Component	ATA:27
PN:GT415-5702-5	MOS/MSC	08-Nov-12	O/C						
SN:3371	HRS	2912							
	AFL	1515							
ATA 28 - FUEL									
28-10-00-201		DETAILED INSPECTION OF THE VENT TUBING VAPOR-BARRIER COATING						Service	ATA:28
	MOS	28-Apr-15	180 (+3m/-3m)	28-Apr-30	28-Jul-30	1403 d (+91)	MRB		
	HRS	4228.4							
WC#: 28.005	AFL	2192							
PROC. REF: AMM 28-10-00-220-801PROC. REF: AMM 28-10-00-220-801									

PKG:52

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-10-00-202	S	DETAILED INSPECTION OF THE CENTER-TANK VAPOR-BARRIER COATING						Service	ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 28.010	AFL	4582							
PKG:38									
PROC. REF: AMM 28-10-00-220-802PROC. REF: AMM 28-10-00-220-802									
28-11-00-201	S	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL SURFACES						Service	ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 28.015	AFL	4582							
PKG:4									
PROC. REF: AMM 28-11-00-210-802PROC. REF: AMM 28-11-00-210-802									
28-11-00-202	S	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL COMPONENTS						Service	ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 28.020	AFL	4582							
PKG:4									
PROC. REF: AMM 28-11-00-210-803PROC. REF: AMM 28-11-00-210-803									
28-11-01-900-801-01	LH LOWER PANEL, WING ACCESS DOOR							Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.085	AFL	0		TSN 0					
PROC. REF: AMM 28-11-01-000-801, AMM 28-11-01-400-801PROC. REF: AMM 28-11-01-000-801, AMM 28-11-01-400-801									
28-11-01-900-801-02	RH LOWER PANEL, WING ACCESS DOOR							Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.085	AFL	0		TSN 0					
PROC. REF: AMM 28-11-01-000-801, AMM 28-11-01-400-801PROC. REF: AMM 28-11-01-000-801, AMM 28-11-01-400-801									
28-11-05-201	S	DETAILED INSPECTION OF THE WATER DRAIN VALVES						Service	ATA:28
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 28.025	AFL	4582							
PKG:34									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 28 - FUEL										
PROC. REF: AMM 28-11-05-220-801PROC. REF: AMM 28-11-05-220-801										
28-11-05-900-801-01		LH WATER DRAIN (BL42.0 FSTA 640.4) VALVE							Component	ATA:28
PN:GP422-1107-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0776	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801										
28-11-05-900-801-02		LH WATER DRAIN (WS52.5 LWR STR #10 - #11) VALVE							Component	ATA:28
PN:GP422-1107-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0774	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801										
28-11-05-900-801-03		RH WATER DRAIN (BL42.0 FSTA 634.00) VALVE							Component	ATA:28
PN:GP422-1107-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0775	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801										
28-11-05-900-801-04		RH WATER DRAIN (WS52.5 LWR STR #10- #11) VALVE							Component	ATA:28
PN:GP422-1107-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0773	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801PROC. REF: AMM 28-11-05-000-801, AMM 28-11-05-400-801										
28-11-09-900-801-01		LH WING TANK PRESSURE RELIEF VALVE							Component	ATA:28
PN:GP422-1109-1	MOS/MSC	26-Feb-25	O/C	TSN 10						
SN:3203	HRS	8641.1	TSN 0							
WC#: 28.090	AFL	4580	TSN 0							
PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801										
28-11-09-900-801-02		RH WING TANK PRESSURE RELIEF VALVE							Component	ATA:28
PN:GP422-1109-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:0547	HRS	0	TSN 0							
WC#: 28.090	AFL	0	TSN 0							
PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-11-09-900-801-03 CENTER TANK PRESSURE RELIEF VALVE								Component	ATA:28
PN:GP422-1109-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0530	HRS	0		TSN 0					
WC#: 28.095	AFL	0		TSN 0					
PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801PROC. REF: AMM 28-11-09-000-801, AMM 28-11-09-400-801									
28-11-25-900-801-01 LEFT GRAVITY FILL CAP								Component	ATA:28
PN:457-826-2-1	MOS/MSC	04-Jun-18	O/C	TSN 0					
SN:N/A	HRS	5987.6		TSN 0					
WC#: 28.100	AFL	3077		TSN 0					
PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801									
28-11-25-900-801-02 RIGHT FORWARD GRAVITY FILL CAP								Component	ATA:28
PN:457-826-2-1	MOS/MSC	16-Jun-17	O/C	TSN 0					
SN:NA	HRS	5430.6		TSN 0					
WC#: 28.100	AFL	2794		TSN 0					
PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801									
28-11-25-900-801-03 RIGHT AFT GRAVITY FILL CAP								Component	ATA:28
PN:457-826-2-1	MOS/MSC	11-Jun-18	O/C	TSN 0					
SN:N/A	HRS	5992.5		TSN 0					
WC#: 28.100	AFL	3083		TSN 0					
PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801PROC. REF: AMM 28-11-25-000-801, AMM 28-11-25-400-801									
28-11-29-900-801-01 LH WING TANK GRAVITY FILL ADAPTER								Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.105	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-11-29-900-801-02 CENTER TANK GRAVITY FILL ADAPTER								Component	ATA:28
PN:457-826-2-1	MOS/MSC	11-Jun-18	O/C	TSN 0					
SN:N/A	HRS	5592.5		TSN 0					
WC#: 28.105	AFL	3083		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-12-00-201		S	GENERAL VISUAL INSPECTION OF THE AFT FUEL-TANK DRAIN-MAST					Service	ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#:	28.030	AFL	4582						
PROC. REF: AMM 28-12-00-210-801PROC. REF: AMM 28-12-00-210-801									
28-12-00-202		S	FUNCTIONAL TEST OF THE AFT FUEL-TANK COMPARTMENT					Service	ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#:	28.035	AFL	4582						
PROC. REF: AMM 28-12-00-720-801PROC. REF: AMM 28-12-00-720-801									
28-12-05-900-801-01			AFT DRAIN TANK VALVE					Component	ATA:28
PN:GP422-1102-1	MOS/MSC	27-May-15	O/C						
SN:0565	HRS	4228.4							
WC#:	28.110	AFL	2192						
PROC. REF: AMM 28-12-05-000-801, AMM 28-12-05-400-801PROC. REF: AMM 28-12-05-000-801, AMM 28-12-05-400-801									
28-12-09-900-801-01			AFT TANK PRESSURE RELIEF VALVE					Component	ATA:28
PN:GP422-1105-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0164	HRS	0		TSN 0					
WC#:	28.115	AFL	0	TSN 0					
PROC. REF: AMM 28-12-09-000-801, AMM 28-12-09-400-801PROC. REF: AMM 28-12-09-000-801, AMM 28-12-09-400-801									
28-12-13-900-801-01			LH FLEXIBLE, AUXILIARY TANK FUEL CELL					Component	ATA:28
PN:GD421-0101-9	MOS/MSC	26-Jun-22	O/C	TSN 8					
SN:T011686	HRS	7535.3		TSN 0					
WC#:	28.125	AFL	3992	TSN 0					
PROC. REF: AMM 28-12-13-000-801, AMM 28-12-13-400-801PROC. REF: AMM 28-12-13-000-801, AMM 28-12-13-400-801									
28-12-13-900-801-02			RH FLEXIBLE, AUXILIARY TANK FUEL CELL					Component	ATA:28
PN:GD421-0101-8	MOS/MSC	26-Jun-22	O/C	TSN 7					
SN:T011702	HRS	7535.3		TSN 0					
WC#:	28.125	AFL	3992	TSN 0					
PROC. REF: AMM 28-12-13-000-801, AMM 28-12-13-400-801PROC. REF: AMM 28-12-13-000-801, AMM 28-12-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-13-00-201	^S	FUNCTIONAL TEST OF THE FUEL VENT TUBING							Service ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 28.040	AFL	4582							
PROC. REF: AMM 28-13-00-720-801PROC. REF: AMM 28-13-00-720-801									
28-13-00-202	^S	OPERATIONAL TEST OF THE VENT SYSTEM							Service ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 28.045	AFL	4582							
PROC. REF: AMM 28-13-00-710-801PROC. REF: AMM 28-13-00-710-801									
28-13-05-900-801-01		LH SURGE BOX							Component ATA:28
PN:GC426-0101-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5219	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-13-05-900-801-02		RH SURGE BOX							Component ATA:28
PN:GC426-0101-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7012	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-20-01-900-801-01		FUEL CONTROL PANEL							Component ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.150	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01-000-801, AMM 28-20-01-400-801PROC. REF: AMM 28-20-01-000-801, AMM 28-20-01-400-801									
28-21-00-201	^S	FUNCTIONAL TEST OF THE FUEL-FEED TUBING SHROUDS							Service ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 28.050	AFL	4582							
PROC. REF: AMM 28-21-00-720-801PROC. REF: AMM 28-21-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 28 - FUEL

28-21-00-202 ^S		VISUAL CHECK OF THE SHROUD DRAINS						Service	ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 28.055	AFL	4582							
PROC. REF: AMM 28-21-00-210-801PROC. REF: AMM 28-21-00-210-801									PKG:4

28-21-01-900-801-01		LEFT FORWARD AC BOOST PUMP CARTRIDGE						Component	ATA:28
PN:GP422-1401-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5BA57	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801									

28-21-01-900-801-02		RIGHT FORWARD AC BOOST PUMP CARTRIDGE						Component	ATA:28
PN:GP422-1401-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:12AY108	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801									

28-21-01-900-801-03		LEFT AFT AC BOOST PUMP CARTRIDGE						Component	ATA:28
PN:GP422-1401-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5BA59	HRS	0		TSN 0					
WC#: 28.160	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801									

28-21-01-900-801-04		RIGHT AFT AC BOOST PUMP CARTRIDGE						Component	ATA:28
PN:GP422-1401-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5BA58	HRS	0		TSN 0					
WC#: 28.160	AFL	0		TSN 0					
PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801PROC. REF: AMM 28-21-01-000-801, AMM 28-21-01-400-801									

28-21-05-900-801-01		LEFT FORWARD AC BOOST PUMP CANISTER						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.165	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-05-900-801-02		LEFT AFT AC BOOST PUMP CANISTER						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.170	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801									
28-21-05-900-801-03		RIGHT FORWARD AC BOOST PUMP CANNISTER						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.165	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801									
28-21-05-900-801-04		RIGHT AFT AC BOOST PUMP CANNISTER						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.170	AFL	0		TSN 0					
PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801PROC. REF: AMM 28-21-05-000-801, AMM 28-21-05-400-801									
28-21-09-900-801-01		LOB PRESSURE SWITCH						Component	ATA:28
PN:GP422-1306-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1456	HRS	0		TSN 0					
WC#: 28.175	AFL	0		TSN 0					
PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801									
28-21-09-900-801-02		LIB PRESSURE SWITCH						Component	ATA:28
PN:GP422-1306-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1455	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801									
28-21-09-900-801-03		RIB PRESSURE SWITCH						Component	ATA:28
PN:GP422-1306-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1458	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-09-900-801-04	ROB PRESSURE SWITCH							Component	ATA:28
PN:GP422-1306-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1457	HRS	0		TSN 0					
WC#: 28.175	AFL	0		TSN 0					
PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801PROC. REF: AMM 28-21-09-000-801, AMM 28-21-09-400-801									
28-21-13-900-801-01	LH DC AUXILIARY PUMP ASSY							Component	ATA:28
PN:GP422-1414-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:4BA24	HRS	0		TSN 0					
WC#: 28.185	AFL	0		TSN 0					
PROC. REF: AMM 28-21-13-000-801, AMM 28-21-13-400-801PROC. REF: AMM 28-21-13-000-801, AMM 28-21-13-400-801									
28-21-13-900-801-02	RH DC AUXILIARY PUMP ASSY							Component	ATA:28
PN:GP422-1414-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5BA32	HRS	0		TSN 0					
WC#: 28.185	AFL	0		TSN 0					
PROC. REF: AMM 28-21-13-000-801, AMM 28-21-13-400-801PROC. REF: AMM 28-21-13-000-801, AMM 28-21-13-400-801									
28-21-25-900-801-01	LH EJECTOR VENT SCAVENGE PUMP							Component	ATA:28
PN:GP422-1408-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0400	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
PROC. REF: AMM 28-21-25-000-801, AMM 28-21-25-400-801PROC. REF: AMM 28-21-25-000-801, AMM 28-21-25-400-801									
28-21-25-900-801-02	RH EJECTOR VENT SCAVENGE PUMP							Component	ATA:28
PN:GP422-1408-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0398	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
PROC. REF: AMM 28-21-25-000-801, AMM 28-21-25-400-801PROC. REF: AMM 28-21-25-000-801, AMM 28-21-25-400-801									
28-21-29-201 ^S	OPERATIONAL (INTERNAL LEAK) TEST OF THE ENGINE FEED SHUTOFF-VALVES							Service	ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 28.060	AFL	4582							
PROC. REF: AMM 28-21-29-710-802PROC. REF: AMM 28-21-29-710-802									
PKG:8									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-29-900-801-01		LEFT ENGINE FEED SHUTOFF VALVE						Component	ATA:28
PN:GP422-1404-17	MOS/MSC	20-Mar-18	O/C	TSR 8					
SN:1204	HRS	5807.9		TSN 2777, TSR 0					
WC#: 28.200	AFL	3006		TSR 0					
PROC. REF: AMM 28-21-29-000-801, AMM 28-21-29-400-801PROC. REF: AMM 28-21-29-000-801, AMM 28-21-29-400-801									
28-21-29-900-801-02		RIGHT ENGINE FEED SHUTOFF VALVE						Component	ATA:28
PN:GP422-1403-1	MOS/MSC	20-Mar-18	O/C	TSR 6					
SN:0234	HRS	5807.9		TSN 5087, TSR 0					
WC#: 28.200	AFL	3006		TSR 0					
PROC. REF: AMM 28-21-29-000-801, AMM 28-21-29-400-801PROC. REF: AMM 28-21-29-000-801, AMM 28-21-29-400-801									
28-21-33-900-801-01		LH ENGINE FEED SOV ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.195	AFL	0		TSN 0					
PROC. REF: AMM 28-21-33-000-801, AMM 28-21-33-400-801PROC. REF: AMM 28-21-33-000-801, AMM 28-21-33-400-801									
28-21-33-900-801-02		RH ENGINE FEED SOV ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.195	AFL	0		TSN 0					
PROC. REF: AMM 28-21-33-000-801, AMM 28-21-33-400-801PROC. REF: AMM 28-21-33-000-801, AMM 28-21-33-400-801									
28-21-37-900-801-01		APU BODY VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.205	AFL	0		TSN 0					
PROC. REF: AMM 28-21-37-000-801, AMM 28-21-37-400-801PROC. REF: AMM 28-21-37-000-801, AMM 28-21-37-400-801									
28-21-41-900-801-01		APU SHUT-OFF VALVE ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.140	AFL	0		TSN 0					
PROC. REF: AMM 28-21-41-000-801, AMM 28-21-41-400-801PROC. REF: AMM 28-21-41-000-801, AMM 28-21-41-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-45-900-801-01		LH SHUTOFF CROSSFEED VALVE						Component	ATA:28
PN:GP422-1412-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0571	HRS	0		TSN 0					
WC#: 28.210	AFL	0		TSN 0					
PROC. REF: AMM 28-21-45-000-801, AMM 28-21-45-400-801PROC. REF: AMM 28-21-45-000-801, AMM 28-21-45-400-801									
28-21-45-900-801-02		RH SHUTOFF CROSSFEED VALVE						Component	ATA:28
PN:GP422-1412-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0572	HRS	0		TSN 0					
WC#: 28.210	AFL	0		TSN 0					
PROC. REF: AMM 28-21-45-000-801, AMM 28-21-45-400-801PROC. REF: AMM 28-21-45-000-801, AMM 28-21-45-400-801									
28-21-53-900-801-01		LH CHECK FEED VALVE						Component	ATA:28
PN:GP422-1410-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0777	HRS	0		TSN 0					
WC#: 28.215	AFL	0		TSN 0					
PROC. REF: AMM 28-21-53-000-801, AMM 28-21-53-400-801PROC. REF: AMM 28-21-53-000-801, AMM 28-21-53-400-801									
28-21-53-900-801-02		RH CHECK FEED VALVE						Component	ATA:28
PN:GP422-1410-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0790	HRS	0		TSN 0					
WC#: 28.215	AFL	0		TSN 0					
PROC. REF: AMM 28-21-53-000-801, AMM 28-21-53-400-801PROC. REF: AMM 28-21-53-000-801, AMM 28-21-53-400-801									
28-21-57-900-801-01		LEFT CHECK FEED VALVE						Component	ATA:28
PN:GP422-1410-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0787	HRS	0		TSN 0					
WC#: 28.220	AFL	0		TSN 0					
PROC. REF: AMM 28-21-57-000-801, AMM 28-21-57-400-801PROC. REF: AMM 28-21-57-000-801, AMM 28-21-57-400-801									
28-21-57-900-801-02		RIGHT CHECK FEED VALVE						Component	ATA:28
PN:GP422-1410-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0788	HRS	0		TSN 0					
WC#: 28.220	AFL	0		TSN 0					
PROC. REF: AMM 28-21-57-000-801, AMM 28-21-57-400-801PROC. REF: AMM 28-21-57-000-801, AMM 28-21-57-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-21-61-900-801-01	LH CHECK DC AUX PUMP VALVE								Component ATA:28
PN:GP422-1305-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0624	HRS	0		TSN 0					
WC#: 28.225	AFL	0		TSN 0					
PROC. REF: AMM 28-21-61-000-801, AMM 28-21-61-400-801PROC. REF: AMM 28-21-61-000-801, AMM 28-21-61-400-801									
28-21-61-900-801-02	RH CHECK DC AUX PUMP VALVE								Component ATA:28
PN:GP422-1305-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0625	HRS	0		TSN 0					
WC#: 28.225	AFL	0		TSN 0					
PROC. REF: AMM 28-21-61-000-801, AMM 28-21-61-400-801PROC. REF: AMM 28-21-61-000-801, AMM 28-21-61-400-801									
28-22-00-201	OPERATIONAL TEST OF THE AFT-TANK MANUAL-TRANSFER SYSTEM								Service ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 28.065	AFL	4582							
PROC. REF: AMM 28-22-00-710-803PROC. REF: AMM 28-22-00-710-803									PKG:8
28-22-00-202	OPERATIONAL TEST OF THE WING TO WING MANUAL-TRANSFER SYSTEM								Service ATA:28
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 28.070	AFL	4582							
PROC. REF: AMM 28-22-00-710-801PROC. REF: AMM 28-22-00-710-801									PKG:8
28-22-01-900-801-01	LH SHUTOFF WING TRANSFER VALVE								Component ATA:28
PN:GP422-1304-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0370	HRS	0		TSN 0					
WC#: 28.230	AFL	0		TSN 0					
PROC. REF: AMM 28-22-01-000-801, AMM 28-22-01-400-801PROC. REF: AMM 28-22-01-000-801, AMM 28-22-01-400-801									
28-22-01-900-801-02	RH SHUTOFF WING TRANSFER VALVE								Component ATA:28
PN:GP422-1304-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0369	HRS	0		TSN 0					
WC#: 28.230	AFL	0		TSN 0					
PROC. REF: AMM 28-22-01-000-801, AMM 28-22-01-400-801PROC. REF: AMM 28-22-01-000-801, AMM 28-22-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-22-09-900-801-01		LH CENTER TRANSFER PUMP CARTRIDGE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNK	HRS	0		TSN 0					
WC#: 28.235	AFL	0		TSN 0					
PROC. REF: AMM 28-22-09-000-801, AMM 28-22-09-400-801PROC. REF: AMM 28-22-09-000-801, AMM 28-22-09-400-801									
28-22-09-900-801-02		RH CENTER TRANSFER PUMP CARTRIDGE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNK	HRS	0		TSN 0					
WC#: 28.235	AFL	0		TSN 0					
PROC. REF: AMM 28-22-09-000-801, AMM 28-22-09-400-801PROC. REF: AMM 28-22-09-000-801, AMM 28-22-09-400-801									
28-22-13-900-801-01		LH CENTER TRANSFER PUMP ASSEMBLY						Component	ATA:28
PN:GP422-1307-11	MOS/MSC	17-Apr-15	O/C	TSN 13					
SN:2BK71	HRS	4228.38		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-22-13-900-801-02		RH CENTER TRANSFER PUMP ASSEMBLY						Component	ATA:28
PN:GP422-1307-11	MOS/MSC	17-Apr-15	O/C	TSN 13					
SN:2BK72	HRS	4228.38		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-22-13-900-802-01		LH CENTER TRANSFER PUMP CANISTER						Component	ATA:28
PN:GP422-1307-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:11AW6	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-22-13-000-801, AMM 28-22-13-400-801PROC. REF: AMM 28-22-13-000-801, AMM 28-22-13-400-801									
28-22-13-900-802-02		RH CENTER TRANSFER PUMP CANISTER						Component	ATA:28
PN:GP422-1307-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:10AW1	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-22-13-000-801, AMM 28-22-13-400-801PROC. REF: AMM 28-22-13-000-801, AMM 28-22-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-22-21-900-801-01		LH CHECK CENTER TANK TRANSFER VALVE						Component	ATA:28
PN:GP422-1405-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1824	HRS	0		TSN 0					
WC#: 28.240	AFL	0		TSN 0					
PROC. REF: AMM 28-22-21-000-801, AMM 28-22-21-400-801PROC. REF: AMM 28-22-21-000-801, AMM 28-22-21-400-801									
28-22-21-900-801-02		RH CHECK CENTER TANK TRANSFER VALVE						Component	ATA:28
PN:GP422-1405-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1825	HRS	0		TSN 0					
WC#: 28.240	AFL	0		TSN 0					
PROC. REF: AMM 28-22-21-000-801, AMM 28-22-21-400-801PROC. REF: AMM 28-22-21-000-801, AMM 28-22-21-400-801									
28-22-25-900-801-01		LH AFT TANK TRANSFER PUMP ASSEMBLY						Component	ATA:28
PN:GP422-1302-17	MOS/MSC	16-Apr-12	O/C	TSO 8					
SN:10AW14	HRS	2603.4		TSO 0					
WC#: 28.120	AFL	1373		TSO 0					
PROC. REF: AMM 28-22-25-000-801, AMM 28-22-25-400-801PROC. REF: AMM 28-22-25-000-801, AMM 28-22-25-400-801									
28-22-25-900-801-02		RH AFT TANK TRANSFER PUMP ASSEMBLY						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.120	AFL	0		TSN 0					
PROC. REF: AMM 28-22-25-000-801, AMM 28-22-25-400-801PROC. REF: AMM 28-22-25-000-801, AMM 28-22-25-400-801									
28-22-37-900-801-01		AFT SHUT-OFF VALVE ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.145	AFL	0		TSN 0					
PROC. REF: AMM 28-22-37-000-801, AMM 28-22-37-400-801PROC. REF: AMM 28-22-37-000-801, AMM 28-22-37-400-801									
28-22-41-900-801-01		LOB FUEL CHECK VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.245	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-22-41-900-801-02		LIB FUEL CHECK VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.250	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-22-41-900-801-03		RIB FUEL CHECK VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.250	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-22-41-900-801-04		ROB FUEL CHECK VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.245	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-23-01-900-801-01		EXTERNAL REFUEL/DEFUEL PANEL						Component	ATA:28
PN:GP541-1102-1	MOS/MSC	02-Jun-26	O/C						
SN:1298	HRS	8887.7							
WC#: 28.255	AFL	4694							
PROC. REF: AMM 28-23-01-000-801, AMM 28-23-01-400-801PROC. REF: AMM 28-23-01-000-801, AMM 28-23-01-400-801									
28-23-05-900-801-02		RH REFUEL ADAPTOR CAP						Component	ATA:28
PN:GP425-1103-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0188	HRS	0		TSN 0					
WC#: 28.260	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05-000-801, AMM 28-23-05-400-801PROC. REF: AMM 28-23-05-000-801, AMM 28-23-05-400-801									
28-23-05-900-802-01		REFUEL/DE-FUEL ADAPTOR						Component	ATA:28
PN:GP425-1102-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:28226	HRS	0		TSN 0					
WC#: 28.265	AFL	0		TSN 0					
PROC. REF: AMM 28-23-05-000-801, AMM 28-23-05-400-801PROC. REF: AMM 28-23-05-000-801, AMM 28-23-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-23-13-900-801-01 LEFT TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component	ATA:28
PN:GP425-1101-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0652	HRS	0		TSN 0					
WC#: 28.270	AFL	0		TSN 0					
PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801									
28-23-13-900-801-02 CENTER TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component	ATA:28
PN:GP425-1101-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0655	HRS	0		TSN 0					
WC#: 28.270	AFL	0		TSN 0					
PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801									
28-23-13-900-801-03 RIGHT TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component	ATA:28
PN:GP425-1101-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0654	HRS	0		TSN 0					
WC#: 28.270	AFL	0		TSN 0					
PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801PROC. REF: AMM 28-23-13-000-801, AMM 28-23-13-400-801									
28-23-17-900-801-01 LH CHECK REFUEL VALVE								Component	ATA:28
PN:GP422-1111-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0373	HRS	0		TSN 0					
WC#: 28.275	AFL	0		TSN 0					
PROC. REF: AMM 28-23-17-000-801, AMM 28-23-17-400-801PROC. REF: AMM 28-23-17-000-801, AMM 28-23-17-400-801									
28-23-17-900-801-02 RH CHECK REFUEL VALVE								Component	ATA:28
PN:GP422-1111-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0381	HRS	0		TSN 0					
WC#: 28.275	AFL	0		TSN 0					
PROC. REF: AMM 28-23-17-000-801, AMM 28-23-17-400-801PROC. REF: AMM 28-23-17-000-801, AMM 28-23-17-400-801									
28-23-21-900-801-01 CHECK REFUEL/DEFUEL VALVE								Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.280	AFL	0		TSN 0					
PROC. REF: AMM 28-23-21-000-801, AMM 28-23-21-400-801PROC. REF: AMM 28-23-21-000-801, AMM 28-23-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-23-25-900-801-01		LH SHUTOFF DEFUEL VALVE						Component	ATA:28
PN:GP422-1412-4	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:AA24657	HRS	0		TSN 0					
WC#: 28.285	AFL	0		TSN 0					
PROC. REF: AMM 28-23-25-000-801, AMM 28-23-25-400-801PROC. REF: AMM 28-23-25-000-801, AMM 28-23-25-400-801									
28-23-25-900-801-02		RH SHUTOFF DEFUEL VALVE						Component	ATA:28
PN:GP422-1412-4	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:AA23515	HRS	0		TSN 0					
WC#: 28.285	AFL	0		TSN 0					
PROC. REF: AMM 28-23-25-000-801, AMM 28-23-25-400-801PROC. REF: AMM 28-23-25-000-801, AMM 28-23-25-400-801									
28-23-29-900-801-01		LH SHUT-OFF VALVE ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.135	AFL	0		TSN 0					
PROC. REF: AMM 28-23-29-000-801, AMM 28-23-29-400-801PROC. REF: AMM 28-23-29-000-801, AMM 28-23-29-400-801									
28-23-29-900-801-02		RH SHUT-OFF VALVE ACTUATOR						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.135	AFL	0		TSN 0					
PROC. REF: AMM 28-23-29-000-801, AMM 28-23-29-400-801PROC. REF: AMM 28-23-29-000-801, AMM 28-23-29-400-801									
28-23-33-900-801-01		AFT TANK REFUEL SHUTOFF VALVE						Component	ATA:28
PN:GP422-1412-15	MOS/MSC	22-Jan-20	O/C	TSR 40					
SN:AA426824	HRS	6819.5		TSN 887, TSR 0					
WC#: 28.290	AFL	3520		TSN 452, TSR 0					
PROC. REF: AMM 28-23-33-000-801, AMM 28-23-33-400-801PROC. REF: AMM 28-23-33-000-801, AMM 28-23-33-400-801									
28-24-00-201 ^S		OPERATIONAL TEST OF THE FUEL RETURN TO TANK (FRTT) CHECK VALVES POST SB 700-28-034 AND A/C 9111 AND SUBS						Service	ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 28.075	AFL	4582							
PROC. REF: AMM 28-26-00-710-802PROC. REF: AMM 28-26-00-710-802									
PKG:38									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10

Serial: 9175

RegNo: N117TP

HRS: 8918.6

AFL: 4707

As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-27-05-900-801-01		LH EJECTOR PUMP VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.295	AFL	0		TSN 0					
PROC. REF: AMM 28-27-05-000-801, AMM 28-27-05-400-801PROC. REF: AMM 28-27-05-000-801, AMM 28-27-05-400-801									
28-27-05-900-801-02		RH EJECTOR PUMP VALVE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.295	AFL	0		TSN 0					
PROC. REF: AMM 28-27-05-000-801, AMM 28-27-05-400-801PROC. REF: AMM 28-27-05-000-801, AMM 28-27-05-400-801									
28-41-00-101		FUNCTIONAL TEST OF THE TEMPERATURE SENSORS (CMR**)						Service	ATA:28
	MOS	14-Aug-25	120 (+3m/-3m)	Adj -130d	06-Apr-35	06-Jul-35	3207 d (+91)	CMR	
	HRS	8645							
WC#: 28.080	AFL	4582							
									PKG:38
PROC. REF: AMM 28-41-25-720-801PROC. REF: AMM 28-41-25-720-801									
28-41-01-900-801-01		RIGHT MAIN AVIONIC BAY FMQG COMPUTER						Component	ATA:28
PN:GP546-1501-13	MOS/MSC	26-Feb-25	O/C						
SN:0356	HRS	8641.1							
WC#: 28.300	AFL	4580							
PROC. REF: AMM 28-41-01-000-801, AMM 28-41-01-400-801PROC. REF: AMM 28-41-01-000-801, AMM 28-41-01-400-801									
28-41-09-900-801-01		LH (L 36.17 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0303	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-02		RH (L 36.17 IN) FUEL PROBE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-03		LH (L 35.88 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1514-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0375	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-04		RH (L 35.88 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1514-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0386	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-05		LH (L 27.81 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0362	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-06		RH (L 27.81 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0363	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-07		LH (L 17.51 IN) FUEL PROBE						Component	ATA:28
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-08		RH (L 17.51 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0304	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-09		LH (L 28.85 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0373	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-10		RH (L 28.85 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0374	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-11		LH (L 30.77 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-4	MOS/MSC	20-Aug-15	O/C	TSN 38					
SN:1097	HRS	4381.6		TSN 0					
	AFL	2263		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-12		RH (L 30.77 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-4	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0370	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-13		LH (L 20.16 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0357	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-14		RH (L 20.16 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-15		LH (L 18.38 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-6	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0356	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-16		RH (L 18.38 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-6	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0357	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-17		LH (L 17.51 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0364	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-18		RH (L 17.51 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0366	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-19		LH (L 14.65 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0356	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-20		RH (L 14.65 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0357	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-21		LH (L 9.63 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0357	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-22		RH (L 9.63 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-23		LH (L 9.33 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-10	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0396	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-24		RH (L 9.33 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-10	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0397	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-25		LH (L 8.98 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0373	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-26		RH (L 8.98 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0374	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-27		LH (L 8.12 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-12	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0362	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-28		RH (L 8.12 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-12	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0363	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-29		LH (L 6.53 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0366	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-30		RH (L 6.53 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-13	MOS/MSC	07-Oct-05	O/C						
SN:0367	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-31		LH (L 7.61 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0371	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-32		RH (L 7.61 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0372	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
28-41-09-900-801-33		LH (L 21.67 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-15	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0357	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-09-900-801-34		RH (L 21.67 IN) FUEL PROBE						Component	ATA:28
PN:GP422-1501-15	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0358	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
28-41-21-900-801-01		DENSIOMETER ENCLOSURE						Component	ATA:28
PN:2950025-103	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0220	HRS	0		TSN 0					
WC#: 28.305	AFL	0		TSN 0					
PROC. REF: AMM 28-41-21-000-801, AMM 28-41-21-400-801PROC. REF: AMM 28-41-21-000-801, AMM 28-41-21-400-801									
28-41-21-900-802-01		FUEL DENSIOMETER						Component	ATA:28
PN:GP422-1512-1	MOS/MSC	20-Aug-15	O/C	TSR 5					
SN:0037	HRS	4381.6		TSR 0					
WC#: 28.310	AFL	2263		TSR 0					
PROC. REF: AMM 28-41-21-000-801, AMM 28-41-21-400-801PROC. REF: AMM 28-41-21-000-801, AMM 28-41-21-400-801									
284102-701 ^U		AUX TANK L/H FUEL PROBE						Component	ATA:28
PN:GP422-1514-5	MOS/MSC	06-Oct-09	O/C						
SN:0289	HRS	1338.1							
	AFL	735							
284102-702 ^U		AUX TANK R/H FUEL PROBE						Component	ATA:28
PN:GP422-1514-5	MOS/MSC	06-Oct-09	O/C						
SN:0026	HRS	1338.1							
	AFL	735							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-12-00-201	^S	VISUAL CHECK OF THE NO. 1 AND NO. 2 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS						Service	ATA:29
	MOS	14-Aug-25							
	HRS	8645	1000 (+50/-50)						
WC#: 29.005	AFL	4582							
PROC. REF: AMM 29-12-00-210-802PROC. REF: AMM 29-12-00-210-802									
29-12-01-900-801-01	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:GX472-0010-1	MOS/MSC	30-Sep-13	O/C	TSR 1					
SN:K0110	HRS	3379.8		TSR 0					
WC#: 29.035	AFL	1769		TSR 0					
PROC. REF: AMM 29-12-01-000-801, AMM 29-12-01-400-801PROC. REF: AMM 29-12-01-000-801, AMM 29-12-01-400-801									
29-12-01-900-801-02	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP							Component	ATA:29
PN:GX472-0010-1	MOS/MSC	02-May-20	O/C	TSR 1					
SN:K0989	HRS	6887.8		TSR 0					
WC#: 29.035	AFL	3568		TSR 0					
PROC. REF: AMM 29-12-01-000-801, AMM 29-12-01-400-801PROC. REF: AMM 29-12-01-000-801, AMM 29-12-01-400-801									
29-12-05-900-801-01	1B AC MOTOR PUMP							Component	ATA:29
PN:GX472-0020-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0734	HRS	0		TSN 0					
WC#: 29.040	AFL	0		TSN 0					
PROC. REF: AMM 29-12-05-000-801, AMM 29-12-05-400-801PROC. REF: AMM 29-12-05-000-801, AMM 29-12-05-400-801									
29-12-05-900-801-02	2B AC MOTOR PUMP							Component	ATA:29
PN:GX472-0020-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0754	HRS	0		TSN 0					
WC#: 29.045	AFL	0		TSN 0					
PROC. REF: AMM 29-12-05-000-801, AMM 29-12-05-400-801PROC. REF: AMM 29-12-05-000-801, AMM 29-12-05-400-801									
29-12-09-900-801-01	NO. 1 MANIFOLD FILTER							Component	ATA:29
PN:GX476-0010-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0555	HRS	0		TSN 0					
WC#: 29.085	AFL	0		TSN 0					
PROC. REF: AMM 29-12-09-000-801, AMM 29-12-09-400-801PROC. REF: AMM 29-12-09-000-801, AMM 29-12-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-12-09-900-801-02		NO. 2 MANIFOLD FILTER						Component	ATA:29
PN:GX476-0010-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0575	HRS	0		TSN 0					
WC#: 29.085	AFL	0		TSN 0					
PROC. REF: AMM 29-12-09-000-801, AMM 29-12-09-400-801PROC. REF: AMM 29-12-09-000-801, AMM 29-12-09-400-801									
29-12-25-900-801-01		NO. 1 HYDRAULIC RESERVOIR						Component	ATA:29
PN:GX471-0010-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0190	HRS	0		TSN 0					
WC#: 29.060	AFL	0		TSN 0					
PROC. REF: AMM 29-12-25-000-801, AMM 29-12-25-400-801PROC. REF: AMM 29-12-25-000-801, AMM 29-12-25-400-801									
29-12-25-900-801-02		NO. 2 HYDRAULIC RESERVOIR						Component	ATA:29
PN:GX471-0012-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0193	HRS	0		TSN 0					
WC#: 29.060	AFL	0		TSN 0					
PROC. REF: AMM 29-12-25-000-801, AMM 29-12-25-400-801PROC. REF: AMM 29-12-25-000-801, AMM 29-12-25-400-801									
29-12-33-101		OPERATIONAL TEST OF THE FIREWALL HYDRAULIC SHUTOFF-VALVES (CMR**)						Service	ATA:29
	MOS	30-May-24						CMR	
	HRS	8252.8	1500		9752.8		834.2		
WC#: 29.010	AFL	4411							
PROC. REF: AMM 29-12-33-710-801PROC. REF: AMM 29-12-33-710-801									
29-12-33-900-801-01		NO. 1 S/O FIREWALL VALVE						Component	ATA:29
PN:GX473-0010-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TA0803	HRS	0		TSN 0					
WC#: 29.065	AFL	0		TSN 0					
PROC. REF: AMM 29-12-33-000-801, AMM 29-12-33-400-801PROC. REF: AMM 29-12-33-000-801, AMM 29-12-33-400-801									
29-12-33-900-801-02		NO. 2 S/O FIREWALL VALVE						Component	ATA:29
PN:GX473-0010-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:TA0795	HRS	0		TSN 0					
WC#: 29.065	AFL	0		TSN 0					
PROC. REF: AMM 29-12-33-000-801, AMM 29-12-33-400-801PROC. REF: AMM 29-12-33-000-801, AMM 29-12-33-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-12-33-900-802-01		NO. 1 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY						Component	ATA:29
PN:GX473-0126-1	MOS/MSC	05-May-14	O/C	TSN 3					
SN:TA4525	HRS	3646.4		TSN 0					
	AFL	1928		TSN 0					
PROC. REF: AMM 29-12-33-000-802, AMM 29-12-33-400-802PROC. REF: AMM 29-12-33-000-802, AMM 29-12-33-400-802									
29-12-33-900-802-02		NO. 2 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY						Component	ATA:29
PN:GX473-0126-1	MOS/MSC	08-Feb-19	O/C	TSN 10					
SN:TA5858	HRS	6336.1		TSN 0					
	AFL	3260		TSN 0					
PROC. REF: AMM 29-12-33-000-802, AMM 29-12-33-400-802PROC. REF: AMM 29-12-33-000-802, AMM 29-12-33-400-802									
29-12-37-900-801-01		LH PRIORITY VALVE						Component	ATA:29
PN:GX473-0060-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0391	HRS	0		TSN 0					
WC#: 29.070	AFL	0		TSN 0					
PROC. REF: AMM 29-12-37-000-801, AMM 29-12-37-400-801PROC. REF: AMM 29-12-37-000-801, AMM 29-12-37-400-801									
29-12-37-900-801-02		RH PRIORITY VALVE						Component	ATA:29
PN:GX473-0060-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0392	HRS	0		TSN 0					
WC#: 29.070	AFL	0		TSN 0					
PROC. REF: AMM 29-12-37-000-801, AMM 29-12-37-400-801PROC. REF: AMM 29-12-37-000-801, AMM 29-12-37-400-801									
29-12-41-900-801-01		NO. 1 HEAT EXCHANGER						Component	ATA:29
PN:GX474-0010-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:3261	HRS	0		TSN 0					
WC#: 29.105	AFL	0		TSN 0					
PROC. REF: AMM 29-12-41-000-801, AMM 29-12-41-400-801PROC. REF: AMM 29-12-41-000-801, AMM 29-12-41-400-801									
29-12-41-900-801-02		NO. 2 HEAT EXCHANGER						Component	ATA:29
PN:GX474-0010-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:3258	HRS	0		TSN 0					
WC#: 29.105	AFL	0		TSN 0					
PROC. REF: AMM 29-12-41-000-801, AMM 29-12-41-400-801PROC. REF: AMM 29-12-41-000-801, AMM 29-12-41-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-12-45-900-801-01	NO. 1 HEAT EXCHANGER BYPASS VALVE								Component ATA:29
PN:GX473-0105-7	MOS/MSC	30-Jul-24	O/C	TSO 5					
SN:PN4359	HRS	8410.2		TSO 0					
WC#: 29.075	AFL	4470		TSO 0					
PROC. REF: AMM 29-12-45-000-801, AMM 29-12-45-400-801PROC. REF: AMM 29-12-45-000-801, AMM 29-12-45-400-801									
29-12-45-900-801-02	NO. 2 HEAT EXCHANGER BYPASS VALVE								Component ATA:29
PN:GX473-0105-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NG1836	HRS	0		TSN 0					
WC#: 29.075	AFL	0		TSN 0					
PROC. REF: AMM 29-12-45-000-801, AMM 29-12-45-400-801PROC. REF: AMM 29-12-45-000-801, AMM 29-12-45-400-801									
29-12-61-900-801-01	LH CHECK VALVE								Component ATA:29
PN:GX473-0125-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0589	HRS	0		TSN 0					
WC#: 29.080	AFL	0		TSN 0					
PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801									
29-12-61-900-801-02	RH CHECK VALVE								Component ATA:29
PN:GX473-0125-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0558	HRS	0		TSN 0					
WC#: 29.080	AFL	0		TSN 0					
PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801									
29-12-61-900-801-03	CENTER CHECK VALVE								Component ATA:29
PN:GX473-0125-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0579	HRS	0		TSN 0					
WC#: 29.080	AFL	0		TSN 0					
PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801PROC. REF: AMM 29-12-61-000-801, AMM 29-12-61-400-801									
29-13-00-101	OPERATIONAL (INTERNAL LEAK) TEST OF THE NO. 3 HYDRAULIC SYSTEM (CMR*)								Service ATA:29
	MOS	05-Jun-24						CMR	
	HRS	8259.5	1500 (+50/-50)	Adj 50	9809.5	9859.5	890.9 (+50)		
WC#: 29.015	AFL	4418							
PROC. REF: AMM 29-13-00-790-802PROC. REF: AMM 29-13-00-790-802									
PKG:5									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-13-00-201	^S	VISUAL CHECK OF THE NO. 3 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS						Service	ATA:29
	MOS	14-Aug-25							
	HRS	8645	1000 (+50/-50)						
WC#: 29.020	AFL	4582							
PROC. REF: AMM 29-13-00-210-802PROC. REF: AMM 29-13-00-210-802									
29-13-01-900-801-01	3A	AC MOTOR PUMP						Component	ATA:29
PN:GX472-0020-9	MOS/MSC	22-May-21	O/C	TSR 1					
SN:2207	HRS	7110.4		TSN 2735, TSR 0					
WC#: 29.050	AFL	3729		TSN 919, TSR 0					
PROC. REF: AMM 29-13-01-000-801, AMM 29-13-01-400-801PROC. REF: AMM 29-13-01-000-801, AMM 29-13-01-400-801									
29-13-01-900-801-02	3B	AC MOTOR PUMP						Component	ATA:29
PN:GX472-0020-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0747	HRS	0		TSN 0					
WC#: 29.055	AFL	0		TSN 0					
PROC. REF: AMM 29-13-01-000-801, AMM 29-13-01-400-801PROC. REF: AMM 29-13-01-000-801, AMM 29-13-01-400-801									
29-13-05-900-801-01	NO. 3	MANIFOLD FILTER						Component	ATA:29
PN:GX476-0010-5	MOS/MSC	08-Nov-17	O/C						
SN:1392	HRS	5661.8							
WC#: 29.085	AFL	2903							
PROC. REF: AMM 29-13-05-000-801, AMM 29-13-05-400-801PROC. REF: AMM 29-13-05-000-801, AMM 29-13-05-400-801									
29-13-21-201	^S	FUNCTIONAL TEST OF THE NO. 3 HYDRAULIC SYSTEM ACCUMULATOR						Service	ATA:29
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 29.025	AFL	4582							
PROC. REF: AMM 29-13-21-720-801PROC. REF: AMM 29-13-21-720-801									
29-13-21-900-801-01	NO. 3	SYSTEM HYDRAULIC ACCUMULATOR						Component	ATA:29
PN:GX473-0100-7	MOS/MSC	17-Apr-15	O/C	TSN 1					
SN:60190-2050	HRS	4228.4		TSN 0					
WC#: 29.090	AFL	2192		TSN 0					
PROC. REF: AMM 29-13-21-000-801, AMM 29-13-21-400-801PROC. REF: AMM 29-13-21-000-801, AMM 29-13-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-13-29-900-801-01		NO. 3 HYDRAULIC RESERVOIR						Component	ATA:29
PN:GX471-0011-9	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0197	HRS	0		TSN 0					
WC#: 29.095	AFL	0		TSN 0					
PROC. REF: AMM 29-13-29-000-801, AMM 29-13-29-400-801PROC. REF: AMM 29-13-29-000-801, AMM 29-13-29-400-801									
29-13-33-900-801-01		RELIEF/BLEED VALVE						Component	ATA:29
PN:GX473-0120-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:PN0199	HRS	0		TSN 0					
WC#: 29.100	AFL	0		TSN 0					
PROC. REF: AMM 29-13-33-000-801, AMM 29-13-33-400-801PROC. REF: AMM 29-13-33-000-801, AMM 29-13-33-400-801									
29-13-37-900-801-01		NO. 3 HEAT EXCHANGER						Component	ATA:29
PN:GX474-0010-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:3241	HRS	0		TSN 0					
WC#: 29.105	AFL	0		TSN 0					
PROC. REF: AMM 29-13-37-000-801, AMM 29-13-37-400-801PROC. REF: AMM 29-13-37-000-801, AMM 29-13-37-400-801									
29-13-41-900-801-01		NO. 3 HEAT EXCHANGER BYPASS VALVE						Component	ATA:29
PN:GX473-0105-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NG1838	HRS	0		TSN 0					
WC#: 29.075	AFL	0		TSN 0					
PROC. REF: AMM 29-13-41-000-801, AMM 29-13-41-400-801PROC. REF: AMM 29-13-41-000-801, AMM 29-13-41-400-801									
29-13-49-900-801-01		NO. 1 CHECK IN LINE VALVE						Component	ATA:29
PN:GX473-0056-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:CR0193	HRS	0		TSN 0					
WC#: 29.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
29-13-57-900-801-01		MANIFOLD VALVE						Component	ATA:29
PN:GX473-0115-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:CR0209	HRS	0		TSN 0					
WC#: 29.115	AFL	0		TSN 0					
PROC. REF: AMM 29-13-57-000-801, AMM 29-13-57-400-801PROC. REF: AMM 29-13-57-000-801, AMM 29-13-57-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-14-00-201	FUNCTIONAL TEST OF THE RAM AIR TURBINE (RAT) HYDRAULIC FLUID-HEATING SYSTEM								Service ATA:29
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 29.030	AFL	4582							
PROC. REF: AMM 29-14-00-720-801PROC. REF: AMM 29-14-00-720-801									
29-14-01-900-801-01	NO. 1 CHECK RESTRICTOR VALVE								Component ATA:29
PN:GX473-0035-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0581	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801									
29-14-01-900-801-02	NO. 2 CHECK RESTRICTOR VALVE								Component ATA:29
PN:GX473-0035-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0582	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801									
29-14-01-900-801-03	NO. 3 CHECK RESTRICTOR VALVE								Component ATA:29
PN:GX473-0035-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0583	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801PROC. REF: AMM 29-14-01-000-801, AMM 29-14-01-400-801									
29-31-01-900-801-01	NO. 1 PRESSURE TRANSDUCER								Component ATA:29
PN:GX473-0030-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KK0553	HRS	0		TSN 0					
WC#: 29.125	AFL	0		TSN 0					
PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801									
29-31-01-900-801-02	NO. 2 PRESSURE TRANSDUCER								Component ATA:29
PN:GX473-0030-1	MOS/MSC	21-Sep-20	O/C	TSN 13					
SN:KK2853	HRS	6965.5		TSN 0					
WC#: 29.125	AFL	3626		TSN 0					
PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-31-01-900-801-03 NO. 3 PRESSURE TRANSDUCER								Component	ATA:29
PN:GX473-0030-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KK0594	HRS	0		TSN 0					
WC#: 29.125	AFL	0		TSN 0					
PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801PROC. REF: AMM 29-31-01-000-801, AMM 29-31-01-400-801									
29-31-05-900-801-01 1A PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1038	HRS	0		TSN 0					
WC#: 29.130	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									
29-31-05-900-801-02 1B PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1162	HRS	0		TSN 0					
WC#: 29.130	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									
29-31-05-900-801-03 2A PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1206	HRS	0		TSN 0					
WC#: 29.135	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									
29-31-05-900-801-04 2B PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1208	HRS	0		TSN 0					
WC#: 29.135	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									
29-31-05-900-801-05 NO. 3A PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1163	HRS	0		TSN 0					
WC#: 29.140	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
29-31-05-900-801-06 NO. 3B PRESSURE SWITCH								Component	ATA:29
PN:GX473-0020-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ET1047	HRS	0		TSN 0					
WC#: 29.140	AFL	0		TSN 0					
PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801PROC. REF: AMM 29-31-05-000-801, AMM 29-31-05-400-801									
29-33-01-900-801-01 NO. 1 TEMPERATURE TRANSDUCER								Component	ATA:29
PN:GX473-0040-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RA1309	HRS	0		TSN 0					
WC#: 29.145	AFL	0		TSN 0					
PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801									
29-33-01-900-801-02 NO. 2 TEMPERATURE TRANSDUCER								Component	ATA:29
PN:GX473-0040-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RA1318	HRS	0		TSN 0					
WC#: 29.145	AFL	0		TSN 0					
PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801									
29-33-01-900-801-03 NO. 3 TEMPERATURE TRANSDUCER								Component	ATA:29
PN:GX473-0040-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RA1326	HRS	0		TSN 0					
WC#: 29.145	AFL	0		TSN 0					
PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801PROC. REF: AMM 29-33-01-000-801, AMM 29-33-01-400-801									
ATA 30 - ICE AND RAIN PROTECTION									
30-11-01-900-801-01 LH MODULATING VALVE								Component	ATA:30
PN:GG436-4001-11	MOS/MSC	02-Jul-16	O/C						
SN:01221	HRS	4266.2							
WC#: 30.025	AFL	2217							
PROC. REF: AMM 30-11-01-000-801, AMM 30-11-01-400-801PROC. REF: AMM 30-11-01-000-801, AMM 30-11-01-400-801									
30-11-01-900-801-02 RH MODULATING VALVE								Component	ATA:30
PN:GG436-4001-11	MOS/MSC	16-Jan-14	O/C	TSR 7					
SN:00839	HRS	3484.3		TSR 0					
WC#: 30.025	AFL	1830		TSR 0					
PROC. REF: AMM 30-11-01-000-801, AMM 30-11-01-400-801PROC. REF: AMM 30-11-01-000-801, AMM 30-11-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-11-05-900-801-01		LEFT SLAT NO. 4 TEMPERATURE SENSOR						Component	ATA:30
PN:GG436-4078-1	MOS/MSC	08-Feb-12	O/C	TSN 0					
SN:0464	HRS	2527.8		TSN 0					
WC#: 30.030	AFL	1319		TSN 0					
PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801									
30-11-05-900-801-02		RIGHT SLAT NO. 4 TEMPERATURE SENSOR						Component	ATA:30
PN:GG436-4078-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0752	HRS	0		TSN 0					
WC#: 30.030	AFL	0		TSN 0					
PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801									
30-11-05-900-801-03		LH WAI TEMPERATURE SENSOR						Component	ATA:30
PN:GG436-4003-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0752	HRS	0		TSN 0					
WC#: 30.035	AFL	0		TSN 0					
PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801									
30-11-05-900-801-04		RH WAI TEMPERATURE SENSOR						Component	ATA:30
PN:GG436-4003-1	MOS/MSC	20-Jan-07	O/C	TSN 12					
SN:1040	HRS	171.7		TSN 0					
WC#: 30.035	AFL	94		TSN 0					
PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801PROC. REF: AMM 30-11-05-000-801, AMM 30-11-05-400-801									
30-11-09-202 ^S		OPERATIONAL TEST OF THE WING XBLEED SYSTEM						Service	ATA:30
	MOS	26-May-20						MRB	
	HRS	6911.6	2250 (+50/-50)						
WC#: 30.005	AFL	3586							
PROC. REF: AMM 30-11-00-710-802PROC. REF: AMM 30-11-00-710-802									
30-11-09-900-801-01		WAI ISOLATION VALVE						Component	ATA:30
PN:GG436-4004-9	MOS/MSC	26-Feb-25	O/C	TSN 150, TSR 3					
SN:01372	HRS	8641.1		TSN 3316.5, TSR 0					
WC#: 30.040	AFL	4580		TSN 1017, TSR 0					
PROC. REF: AMM 30-11-09-000-801, AMM 30-11-09-400-801PROC. REF: AMM 30-11-09-000-801, AMM 30-11-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-12-05-101		DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (LH), PART NO. GG468-4022-3 (S/N 0001, 0002, 0023, 0029, 0044, 0045, 0048 AND 0056) (AWL*)						Service	ATA:30
PN:GG468-4022-3	MOS/MSC		N/A						
SN:0187	HRS	0							
	AFL	0							
PROC. REF: AMM 30-12-05-961-801PROC. REF: AMM 30-12-05-961-801									
30-12-05-102		DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (LH), PART NO. GG468-4022-3 (SERIAL NUMBERS NOT COVERED BY TASK 30-12-05-101*) (AWL*)						Service	ATA:30
PN:GG468-4022-3	MOS							LIFE LIMIT	
SN:0187	HRS	0	15000		15000 (M)		6081.4		
	AFL	0							
PROC. REF: AMM 30-12-05-961-801PROC. REF: AMM 30-12-05-961-801									
30-12-05-103		DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (RH), PART NO. GG468-4022-4 (S/N 0001, 0002, 0003, 0031, 0038, 0047, 0049, 0056, 0057, 0058 AND 0061) (AWL*)						Service	ATA:30
PN:GG468-4022-4	MOS/MSC		N/A						
SN:0206	HRS	0							
	AFL	0							
PROC. REF: AMM 30-12-05-961-801PROC. REF: AMM 30-12-05-961-801									
30-12-05-104		DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (RH), PART NO. GG468-4022-4 (SERIAL NUMBERS NOT COVERED BY TASK 30-12-05-103*) (AWL*)						Service	ATA:30
PN:GG468-4022-4	MOS							LIFE LIMIT	
SN:0206	HRS	0	15000		15000		6081.4		
	AFL	0							
PROC. REF: AMM 30-12-05-961-801PROC. REF: AMM 30-12-05-961-801									
30-12-05-900-801-01		LH SLAT NO. 1 TELESCOPIC, A/I SUPPLY LH DUCT						Component	ATA:30
PN:GG468-4022-3	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:0187	HRS	0		TSN 0					
WC#: 30.045	AFL	0		TSN 0					
PROC. REF: AMM 30-12-05-000-801, AMM 30-12-05-400-801PROC. REF: AMM 30-12-05-000-801, AMM 30-12-05-400-801									
30-12-05-900-801-02		RH SLAT NO. 1 TELESCOPIC, A/I SUPPLY RH DUCT						Component	ATA:30
PN:GG468-4022-4	MOS/MSC	07-Oct-05	H/T						
SN:0206	HRS	0							
WC#: 30.045	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 30 - ICE AND RAIN PROTECTION

PROC. REF: AMM 30-12-05-000-801, AMM 30-12-05-400-801PROC. REF: AMM 30-12-05-000-801, AMM 30-12-05-400-801

30-12-09-900-801-01	NO. 1 COUPLING COVER							Component	ATA:30
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

30-12-09-900-801-02	NO. 2 COUPLING COVER							Component	ATA:30
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

30-12-09-900-801-03	NO. 3 COUPLING COVER							Component	ATA:30
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

30-12-09-900-801-04	NO. 4 COUPLING COVER							Component	ATA:30
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

30-12-09-900-801-05	NO. 5 COUPLING COVER							Component	ATA:30
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

30-12-09-900-801-06	ANTI-ICE SUPPLY CENTER WING TO FUSE FAIRING DUCT							Component	ATA:30
PN:GG468-4033-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0122	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-12-13-101		DISCARD THE LH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO.GG468-4025-1 (AWL*)						Service	ATA:30
PN:GG468-4025-1	MOS							LIFE LIMIT	
SN:0514	HRS	0	15000		15000		6081.4		
	AFL	0							
PROC. REF: AMM 30-12-13-961-801PROC. REF: AMM 30-12-13-961-801									
30-12-13-101		DISCARD THE RH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO.GG468-4025-1 (AWL*)						Service	ATA:30
PN:GG468-4025-1	MOS							LIFE LIMIT	
SN:0491	HRS	0	15000		15000		6081.4		
	AFL	0							
PROC. REF: AMM 30-12-13-961-801PROC. REF: AMM 30-12-13-961-801									
30-12-13-900-801-01		LH FLEXIBLE JOINT						Component	ATA:30
PN:GG468-4025-1	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:0514	HRS	0		TSN 0					
WC#: 30.075	AFL	0		TSN 0					
PROC. REF: AMM 30-12-13-000-801, AMM 30-12-13-400-801PROC. REF: AMM 30-12-13-000-801, AMM 30-12-13-400-801									
30-12-13-900-801-02		RH FLEXIBLE JOINT						Component	ATA:30
PN:GG468-4025-1	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:0491	HRS	0		TSN 0					
WC#: 30.075	AFL	0		TSN 0					
PROC. REF: AMM 30-12-13-000-801, AMM 30-12-13-400-801PROC. REF: AMM 30-12-13-000-801, AMM 30-12-13-400-801									
30-21-01-900-801-01		LH ENGINE NOSE COWL ANTI-ICE VALVE						Component	ATA:30
PN:510-0020-5	MOS/MSC	06-Feb-15	O/C						
SN:D0246	HRS	4132.3		TSN 4132.3					
WC#: 30.080	AFL	2144		TSN 2144					
PROC. REF: AMM 30-21-01-000-801, AMM 30-21-01-400-801PROC. REF: AMM 30-21-01-000-801, AMM 30-21-01-400-801									
30-21-01-900-801-02		RH ENGINE NOSE COWL ANTI-ICE VALVE						Component	ATA:30
PN:510-0020-7	MOS/MSC	14-Jan-16	O/C						
SN:D1303B	HRS	4649.2							
WC#: 30.080	AFL	2416							
PROC. REF: AMM 30-21-01-000-801, AMM 30-21-01-400-801PROC. REF: AMM 30-21-01-000-801, AMM 30-21-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-21-05-201	GENERAL VISUAL INSPECTION OF THE COWL ANTI-ICING-VALVE DUCTS								Service ATA:30
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 30.010	AFL	4582							
PROC. REF: AMM 30-21-05-210-802PROC. REF: AMM 30-21-05-210-802									
30-31-01-900-801-01	NO. 1 HEATER/BRAKE TEMPERATURE MONITOR								Component ATA:30
PN:GH569-0017-1	MOS/MSC	14-May-19	O/C	TSR 5					
SN:1439	HRS	6477.6		TSR 0					
WC#: 30.085	AFL	3345		TSR 0					
PROC. REF: AMM 30-31-01-000-801, AMM 30-31-01-400-801PROC. REF: AMM 30-31-01-000-801, AMM 30-31-01-400-801									
30-31-01-900-801-02	NO. 2 HEATER/BRAKE TEMPERATURE MONITOR								Component ATA:30
PN:GH569-0017-1	MOS/MSC	14-May-19	O/C						
SN:566	HRS	6477.6							
WC#: 30.085	AFL	3345							
PROC. REF: AMM 30-31-01-000-801, AMM 30-31-01-400-801PROC. REF: AMM 30-31-01-000-801, AMM 30-31-01-400-801									
30-41-00-202	FUNCTIONAL TEST OF THE WINDSHIELD RAIN-REPELLANT LAYER								Service ATA:30
	MOS	01-May-26	12 (+10%/-10%)	Adj -65d	25-Feb-27	31-Mar-27	245 d (+34)		
	HRS	8864.7	750 (+50/-50)	Adj 50	9664.7	9714.7	746.1 (+50)		
WC#: 30.015	AFL	4682							
PROC. REF: AMM 30-40-00-720-801PROC. REF: AMM 30-40-00-720-801									
30-41-00-301	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL								Service ATA:30
	MOS	30-Dec-25	15 (+3m/-3m)	Adj -24d	06-Mar-27	06-Jun-27	254 d (+92)	OPTIONAL	
	HRS	8766.8	750 (+50/-50)	Adj 50	9566.8	9616.8	648.2 (+50)		
	AFL	4630							
PROC. REF: AMM 56-10-01-220-801PROC. REF: AMM 56-10-01-220-801									
30-41-01-900-801-01	LH WINDSHIELD TEMPERATURE CONTROLLER								Component ATA:30
PN:GC584-1001-4	MOS/MSC	20-Jun-24	O/C	TSN 278, TSR 1					
SN:0342	HRS	8286.1		TSR 0					
WC#: 30.090	AFL	4433		TSR 0					
PROC. REF: AMM 30-41-01-000-801, AMM 30-41-01-400-801PROC. REF: AMM 30-41-01-000-801, AMM 30-41-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
30-41-01-900-801-02		RH WINDSHIELD TEMPERATURE CONTROLLER						Component	ATA:30
PN:GC584-1001-4	MOS/MSC	03-Oct-19	O/C						
SN:0603	HRS	6684.7		TSN 4044.5, TSR 0					
WC#: 30.090	AFL	3441		TSR 0					
PROC. REF: AMM 30-41-01-000-801, AMM 30-41-01-400-801PROC. REF: AMM 30-41-01-000-801, AMM 30-41-01-400-801									
30-81-01-201		OPERATIONAL TEST OF THE ICE DETECTORS						Service	ATA:30
	MOS	05-Jun-24						MRB	
	HRS	8259.5	1500 (+50/-50)	9759.5	9809.5	840.9 (+50)			
WC#: 30.020	AFL	4418							
PROC. REF: AMM 30-81-01-710-801PROC. REF: AMM 30-81-01-710-801									
30-81-01-900-801-01		LH ICE DETECTOR						Component	ATA:30
PN:GG436-4006-7	MOS/MSC	07-Sep-12	O/C						
SN:01150	HRS	2844.4							
WC#: 30.095	AFL	1471							
PROC. REF: AMM 30-81-01-000-801, AMM 30-81-01-400-801PROC. REF: AMM 30-81-01-000-801, AMM 30-81-01-400-801									
30-81-01-900-801-02		RH ICE DETECTOR						Component	ATA:30
PN:GG436-4006-9	MOS/MSC	07-Sep-12	O/C						
SN:21236	HRS	2844.4							
WC#: 30.095	AFL	1471							
PROC. REF: AMM 30-81-01-000-801, AMM 30-81-01-400-801PROC. REF: AMM 30-81-01-000-801, AMM 30-81-01-400-801									
301107-701 ^U		EVS HEATER CONTROLLER						Component	ATA:30
PN:GC584-1002-1	MOS/MSC	07-Oct-05	O/C						
SN:733623IN00117	HRS	0							
	AFL	0							
301108-701 ^U		EVS (IR) WINDOW						Component	ATA:30
PN:GT546-0001-7	MOS/MSC	18-Dec-17	O/C	TSN 0					
SN:16470575	HRS	5716.4		TSN 0					
	AFL	2942		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301213-702 ^U RH WING #2 STAT FLEX JOINT								Component	ATA:30
PN:GG468-4026-1	MOS/MSC	22-Oct-08	O/C	TSN 22					
SN:0577	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
302094-001 ^U ILSD INTERIOR LIGHTING DIRECTOR								Component	ATA:30
PN:8ES455611-10	MOS/MSC	04-Oct-23	O/C						
SN:2002781	HRS	8049.4							
	AFL	4271							
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-21-01-900-801-01 LH DIGITAL CLOCK								Component	ATA:31
PN:4190-030	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:148	HRS	0		TSN 0					
WC#: 31.035	AFL	0		TSN 0					
PROC. REF: AMM 31-21-01-000-801, AMM 31-21-01-400-801PROC. REF: AMM 31-21-01-000-801, AMM 31-21-01-400-801									
31-21-01-900-801-02 RH DIGITAL CLOCK								Component	ATA:31
PN:APE4190-030	MOS/MSC	27-May-13	O/C	TSN 64					
SN:425	HRS	3152.6		TSN 0					
WC#: 31.035	AFL	1664		TSN 0					
PROC. REF: AMM 31-21-01-000-801, AMM 31-21-01-400-801PROC. REF: AMM 31-21-01-000-801, AMM 31-21-01-400-801									
31-31-00-201 ^S OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (CONTROL COLUMN AND RUDDER PEDAL PARAMETERS)								Service	ATA:31
	MOS	14-Aug-25						MRB	
	HRS	8645	4500 (+50/-50)						
WC#: 31.005	AFL	4582							
PROC. REF: AMM 31-31-00-710-802PROC. REF: AMM 31-31-00-710-802									
31-31-00-203 FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) FORCE SENSORS (POST SB 700-31-020)								Service	ATA:31
	MOS/MSC		N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 31-31-00-720-801PROC. REF: AMM 31-31-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-31-01-900-801-01 (FDR) FLIGHT DATA RECORDER								Component	ATA:31
PN:980-4700-041	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SSFDR-11187	HRS	0		TSN 0					
WC#: 31.040	AFL	0		TSN 0					
PROC. REF: AMM 31-31-01-000-801, AMM 31-31-01-400-801PROC. REF: AMM 31-31-01-000-801, AMM 31-31-01-400-801									
31-31-05-900-801-01 ACCELEROMETER								Component	ATA:31
PN:971-4193-001	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:10764	HRS	0		TSN 0					
WC#: 31.045	AFL	0		TSN 0					
PROC. REF: AMM 31-31-05-000-801, AMM 31-31-05-400-801PROC. REF: AMM 31-31-05-000-801, AMM 31-31-05-400-801									
31-31-09-201 OPERATIONAL TEST OF THE FLIGHT-DATA-RECORDER (FDR) UNDERWATER-LOCATING-DEVICE (ULD)								Service	ATA:31
PN:DK120/90	MOS	14-Aug-25	30 (+3m/-3m)	Adj 3	14-May-28	14-Aug-28	689 d (+92)	MRB	
SN:AT176491	HRS	8645							
	AFL	4582							
PROC. REF: AMM 31-31-09-710-802PROC. REF: AMM 31-31-09-710-802									
31-31-09-202 DISCARD OF THE FLIGHT-DATA-RECORDER (FDR) UNDERWATER-LOCATING-DEVICE (ULD) BATTERY								Service	ATA:31
PN:DK120/90	MOS/MSC	25-Apr-22	DUE		01-Feb-29 (M)		952 d	MRB	
SN:AT176491	HRS	7430							
WC#: 31.050	AFL	3926							
PROC. REF: AMM 31-31-09-961-801PROC. REF: AMM 31-31-09-961-801									
31-31-09-900-801-01 FDR (ULB) UNDERWATER LOCATOR BEACON								Component	ATA:31
PN:DK120/90	MOS/MSC	25-Apr-22	O/C	TSN 4					
SN:AT176491	HRS	7430		TSN 0					
WC#: 31.050	AFL	3926		TSN 0					
PROC. REF: AMM 31-31-09-000-801, AMM 31-31-09-400-801PROC. REF: AMM 31-31-09-000-801, AMM 31-31-09-400-801									
31-33-00-301 DOWNLOAD OF THE QUICK ACCESS RECORDER (POST SB 700-31-026)								Service	ATA:31
	MOS	14-Aug-25						MPD	
	HRS	8645	300 (+10%/-10%)	Adj 30	8975	9005	56.4 (+30)		
	AFL	4582							
PROC. REF: AMM 31-33-00-970-801PROC. REF: AMM 31-33-00-970-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-41-01-900-801-01		NO.1 INTEGRATED AVIONICS COMPUTER						Component	ATA:31
PN:7017300-61014	MOS/MSC	22-Oct-20	O/C						
SN:99071455	HRS	6972.8							
WC#: 31.055	AFL	3672							
PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801									
31-41-01-900-801-02		NO.2 INTEGRATED AVIONICS COMPUTER						Component	ATA:31
PN:7017300-61014	MOS/MSC	14-Aug-25	O/C	TSR 0					
SN:96080647	HRS	8645		TSR 0					
WC#: 31.055	AFL	4582		TSR 0					
PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801									
31-41-01-900-801-03		NO.3 INTEGRATED AVIONICS COMPUTER						Component	ATA:31
PN:7017300-61014	MOS/MSC	23-Oct-21	O/C						
SN:10081924	HRS	7262							
WC#: 31.055	AFL	3812							
PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801PROC. REF: AMM 31-41-01-000-801, AMM 31-41-01-400-801									
31-41-05-900-801-01		NO. 1 CONFIGURATION IAC MODULE						Component	ATA:31
PN:7014940-902	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04126634	HRS	0		TSN 0					
WC#: 31.060	AFL	0		TSN 0					
PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801									
31-41-05-900-801-02		NO. 2 CONFIGURATION IAC MODULE						Component	ATA:31
PN:7014940-902	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05026689	HRS	0		TSN 0					
WC#: 31.060	AFL	0		TSN 0					
PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801									
31-41-05-900-801-03		NO. 3 CONFIGURATION IAC MODULE						Component	ATA:31
PN:7014940-902	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05016651	HRS	0		TSN 0					
WC#: 31.060	AFL	0		TSN 0					
PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801PROC. REF: AMM 31-41-05-000-801, AMM 31-41-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-42-01-900-801-01		NO. 1 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:10604B03M09	MOS/MSC	02-Jun-22	O/C	TSR 18						
SN:06051457	HRS	7492.7	TSR 0							
WC#: 31.065	AFL	3968	TSR 0							
PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801										
31-42-01-900-801-02		NO. 2 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:10604B03M09	MOS/MSC	16-Jun-17	O/C							
SN:05041312	HRS	5430.6								
WC#: 31.065	AFL	2794								
PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801										
31-42-01-900-801-03		NO. 3 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:10604B03M09	MOS/MSC	02-Jun-22	O/C	TSR 0						
SN:06051457	HRS	7492.7	TSR 0							
WC#: 31.065	AFL	3968	TSR 0							
PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801										
31-42-01-900-801-04		NO. 4 DATA ACQUISITION (DAU) UNIT							Component	ATA:31
PN:10604B03M09	MOS/MSC	16-Jun-17	O/C							
SN:05041309	HRS	5430.6								
WC#: 31.065	AFL	2794								
PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801PROC. REF: AMM 31-42-01-000-801, AMM 31-42-01-400-801										
31-43-01-900-801-01		FWD POWER LAMP DRIVER							Component	ATA:31
PN:LT45D	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:1260	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
31-43-01-900-801-02		AFT POWER LAMP DRIVER							Component	ATA:31
PN:LT45D	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:1259	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-43-01-900-801-03	R/H POWER LAMP DRIVER								Component ATA:31
PN:LT45D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1266	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
31-44-01-900-801-01	LH ISOLATION COUPLER								Component ATA:31
PN:5008500-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:13980	HRS	0		TSN 0					
WC#: 31.070	AFL	0		TSN 0					
PROC. REF: AMM 31-44-01-000-801, AMM 31-44-01-400-801PROC. REF: AMM 31-44-01-000-801, AMM 31-44-01-400-801									
31-44-01-900-801-02	RH ISOLATION COUPLER								Component ATA:31
PN:5008500-002	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:12544	HRS	0		TSN 0					
WC#: 31.070	AFL	0		TSN 0					
PROC. REF: AMM 31-44-01-000-801, AMM 31-44-01-400-801PROC. REF: AMM 31-44-01-000-801, AMM 31-44-01-400-801									
31-61-00-201 ^S	OPERATIONAL TEST OF THE EICAS DISPLAY REVERSION								Service ATA:31
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 31.015	AFL	4582							
PROC. REF: AMM 31-61-00-710-803PROC. REF: AMM 31-61-00-710-803									
31-61-00-202 ^S	OPERATIONAL TEST OF THE PRIMARY FLIGHT DISPLAY REVERSION								Service ATA:31
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 31.020	AFL	4582							
PROC. REF: AMM 31-61-00-710-802PROC. REF: AMM 31-61-00-710-802									
31-61-00-203 ^S	OPERATIONAL TEST OF THE IRS REVERSION								Service ATA:31
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 31.025	AFL	4582							
PROC. REF: AMM 31-61-00-710-805PROC. REF: AMM 31-61-00-710-805									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

31-61-00-204 ^S		OPERATIONAL TEST OF THE ADC REVERSION						Service	ATA:31
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 31.030	AFL	4582							
									PKG:32
PROC. REF: AMM 31-61-00-710-806PROC. REF: AMM 31-61-00-710-806									

31-61-01-900-801-01		PILOT PFD DISPLAY UNIT						Component	ATA:31
PN:K9321062A11	MOS/MSC	10-Jul-20	O/C						
SN:2890022292	HRS	6911.6							
WC#: 31.075	AFL	3586							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									

31-61-01-900-801-02		PILOT MFD DISPLAY UNIT						Component	ATA:31
PN:K9321062A11	MOS/MSC	10-Jul-20	O/C						
SN:2890022294	HRS	6911.6							
WC#: 31.075	AFL	3586							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									

31-61-01-900-801-03		PILOT EICAS DISPLAY UNIT						Component	ATA:31
PN:K9321062A11	MOS/MSC	20-Nov-23	O/C						
SN:2890022348	HRS	8092.2							
WC#: 31.075	AFL	4307							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									

31-61-01-900-801-04		COPILOT EICAS DISPLAY UNIT						Component	ATA:31
PN:K9321062A11	MOS/MSC	20-Nov-23	O/C						
SN:2890022295	HRS	8092.2							
WC#: 31.080	AFL	4307							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									

31-61-01-900-801-05		COPILOT MFD DISPLAY UNIT						Component	ATA:31
PN:K9321062A11	MOS/MSC	10-Jul-20	O/C						
SN:2890022349	HRS	6911.6							
WC#: 31.080	AFL	3586							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-61-01-900-801-06 COPILOT PFD DISPLAY UNIT								Component	ATA:31
PN:K9321062A11	MOS/MSC	10-Jul-20	O/C						
SN:2890022350	HRS	6911.6							
WC#: 31.080	AFL	3586							
PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801PROC. REF: AMM 31-61-01-000-801, AMM 31-61-01-400-801									
31-61-05-900-801-01 LH PANEL- PFD CONTROLLER CONTROL								Component	ATA:31
PN:7022012-905	MOS/MSC	26-Apr-07	O/C	TSR 1					
SN:98090275	HRS	262.6		TSR 0					
WC#: 31.085	AFL	156		TSR 0					
PROC. REF: AMM 31-61-05-000-801, AMM 31-61-05-400-801PROC. REF: AMM 31-61-05-000-801, AMM 31-61-05-400-801									
31-61-05-900-801-02 RH PANEL- PFD CONTROLLER CONTROL								Component	ATA:31
PN:7022012-905	MOS/MSC	26-Apr-07	O/C	TSR 1					
SN:01090468	HRS	262.6		TSR 0					
WC#: 31.085	AFL	156		TSR 0					
PROC. REF: AMM 31-61-05-000-801, AMM 31-61-05-400-801PROC. REF: AMM 31-61-05-000-801, AMM 31-61-05-400-801									
31-61-09-900-801-01 LH MFD CONTROLLER								Component	ATA:31
PN:7016683-943	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04111605	HRS	0		TSN 0					
WC#: 31.090	AFL	0		TSN 0					
PROC. REF: AMM 31-61-09-000-801, AMM 31-61-09-400-801PROC. REF: AMM 31-61-09-000-801, AMM 31-61-09-400-801									
31-61-09-900-801-02 RH MFD CONTROLLER								Component	ATA:31
PN:7016683-943	MOS/MSC	10-May-23	O/C						
SN:06011911	HRS	7822.4		TSR 0					
WC#: 31.090	AFL	4167		TSR 0					
PROC. REF: AMM 31-61-09-000-801, AMM 31-61-09-400-801PROC. REF: AMM 31-61-09-000-801, AMM 31-61-09-400-801									
31-61-13-900-801-01 EICAS (EC-900) CONTROLLER								Component	ATA:31
PN:7022014-903	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05020313	HRS	0		TSN 0					
WC#: 31.095	AFL	0		TSN 0					
PROC. REF: AMM 31-61-13-000-801, AMM 31-61-13-400-801PROC. REF: AMM 31-61-13-000-801, AMM 31-61-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-61-17-900-801-01 PANEL - REVERSION CONTROLLER CONTROL								Component	ATA:31
PN:7022016-905	MOS/MSC	03-Sep-18	O/C	TSR 1					
SN:09060581	HRS	6142.3		TSR 0					
WC#: 31.100	AFL	3151		TSR 0					
PROC. REF: AMM 31-61-17-000-801, AMM 31-61-17-400-801PROC. REF: AMM 31-61-17-000-801, AMM 31-61-17-400-801									
311002-701 ^U CMZ-01 VIDEO CAMERA UNIT								Component	ATA:31
PN:100-1053-02	MOS/MSC	07-Oct-05	O/C						
SN:0575	HRS	0							
	AFL	0							
311003-701 ^U QUAD VIDEO CAMERA UNIT								Component	ATA:31
PN:100-1078-01	MOS/MSC	07-Oct-05	O/C						
SN:1027	HRS	0							
	AFL	0							
311010-701 ^U COMM UNIT (SECURAPLANE SYSTEM) POWER SUPPLY								Component	ATA:31
PN:100-0850-01	MOS/MSC	07-Oct-05	O/C						
SN:0214	HRS	0							
	AFL	0							
311011-701 ^U CAMERA UNIT VERTICAL FIN (CMX-01-2) CAMERA								Component	ATA:31
PN:100-1054-02	MOS/MSC	07-Oct-05	O/C						
SN:1272	HRS	0							
	AFL	0							
313301-701 ^U QUICK ACCESS RECORDER								Component	ATA:31
PN:804-0105	MOS/MSC	18-May-10	O/C						
SN:17295	HRS	1594.8		TSN 0					
	AFL	882		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-10-00-201	S	RESTORATION LH MLG ASSEMBLY GEAR						Service	ATA:32
PN:GW318-1001-3	MOS	14-Aug-25	240 (+3m/-3m)					MRB	
SN:DCL465/05	HRS	8645							
WC#: 32.280	AFL	4582							
PROC. REF: AMM 32-11-00-615-801PROC. REF: AMM 32-11-00-615-801									
32-10-00-201	S	RESTORATION RH MLG ASSEMBLY GEAR						Service	ATA:32
PN:GW318-1001-4	MOS	14-Aug-25	240 (+3m/-3m)					MRB	
SN:DCL464/05	HRS	8645							
WC#: 32.285	AFL	4582							
PROC. REF: AMM 32-11-00-615-801PROC. REF: AMM 32-11-00-615-801									
32-10-00-202	S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PIN						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.005	AFL	4582							
PROC. REF: AMM 32-10-00-220-802PROC. REF: AMM 32-10-00-220-802									
32-10-00-203	S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.010	AFL	4582							
PROC. REF: AMM 32-10-00-220-803PROC. REF: AMM 32-10-00-220-803									
32-10-00-204	S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK-STRUT ASSEMBLY (INTERNAL)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.015	AFL	4582							
PROC. REF: AMM 32-11-01-280-801PROC. REF: AMM 32-11-01-280-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-10-00-206	^S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PINS						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.020	AFL	4582							
PROC. REF: AMM 32-10-00-280-802PROC. REF: AMM 32-10-00-280-802									
32-10-00-207	^S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.025	AFL	4582							
PROC. REF: AMM 32-10-00-280-803PROC. REF: AMM 32-10-00-280-803									
32-10-00-208	^S	DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.030	AFL	4582							
PROC. REF: AMM 32-10-00-220-805PROC. REF: AMM 32-10-00-220-805									
32-10-00-209	^S	SPECIAL DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.035	AFL	4582							
PROC. REF: AMM 32-10-00-280-804PROC. REF: AMM 32-10-00-280-804									
32-10-00-210	^S	DETAILED INSPECTION OF THE SHOCK STRUT ASSEMBLY (INTERNAL)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.040	AFL	4582							
PROC. REF: AMM 32-11-01-220-804PROC. REF: AMM 32-11-01-220-804									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-10-00-211	^S	DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.045	AFL	4582							
PROC. REF: AMM 32-11-17-220-801PROC. REF: AMM 32-11-17-220-801									PKG:38
32-10-00-212	^S	SPECIAL DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.050	AFL	4582							
PROC. REF: AMM 32-11-17-280-801PROC. REF: AMM 32-11-17-280-801									PKG:56
32-10-00-213	^S	DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.055	AFL	4582							
PROC. REF: AMM 32-32-01-220-801PROC. REF: AMM 32-32-01-220-801									PKG:38
32-10-00-214	^S	SPECIAL DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.060	AFL	4582							
PROC. REF: AMM 32-32-01-280-801PROC. REF: AMM 32-32-01-280-801									PKG:56
32-11-00-201		LUBRICATION OF THE MAIN LANDING GEAR (MLG) AND COMPONENTS							Service ATA:32
	MOS	12-May-26						MRB	
	HRS	8870	250 (+10%/-10%)	Adj 25	9145	9170	226.4 (+25)		
WC#: 32.065	AFL	4687							
PROC. REF: AMM 12-22-00-640-802PROC. REF: AMM 12-22-00-640-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-00-900-801-01		LH MLG PINTLE PIN						Component	ATA:32
PN:21112-101	MOS/MSC	29-Apr-15	H/T						
SN:EXC1309	HRS	4228.4							
WC#: 32.270	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801									
32-11-00-900-801-02		RH MLG PINTLE PIN						Component	ATA:32
PN:21112-102	MOS/MSC	29-Apr-15	H/T						
SN:EXC1318	HRS	4228.4							
WC#: 32.270	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801									
32-11-00-900-801-03		LH CROSS PINTLE PIN						Component	ATA:32
PN:21116-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC0486	HRS	4228.4							
WC#: 32.275	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801									
32-11-00-900-801-04		RH CROSS PINTLE PIN						Component	ATA:32
PN:21116-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC0478	HRS	4228.4							
WC#: 32.275	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: AMM 32-11-00-000-801, AMM 32-11-00-400-801									
32-11-00-900-803-01		LH MLG ASSEMBLY GEAR						Component	ATA:32
PN:GW318-1001-3	MOS/MSC	30-Apr-15	O/C	TSR 0					
SN:DCL465/05	HRS	4228.4		TSR 0					
WC#: 32.280	AFL	2192		TSR 0					
PROC. REF: CMM 32-10-11, AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: CMM 32-10-11, AMM 32-11-00-000-801, AMM 32-11-00-400-801									
32-11-00-900-803-02		RH MLG ASSEMBLY GEAR						Component	ATA:32
PN:GW318-1001-4	MOS/MSC	29-Apr-15	O/C	TSR 0					
SN:DCL464/05	HRS	4228.4		TSR 0					
WC#: 32.285	AFL	2192		TSR 0					
PROC. REF: CMM 32-10-11, AMM 32-11-00-000-801, AMM 32-11-00-400-801PROC. REF: CMM 32-10-11, AMM 32-11-00-000-801, AMM 32-11-00-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-01-101	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21115 (AWL*)								Service ATA:32
	MOS/MSC		N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-101	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21115 (AWL*)								Service ATA:32
	MOS/MSC		N/A						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-102	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1 (AWL*)								Service ATA:32
PN:21274-1	MOS	29-Apr-15						LIFE LIMIT	
SN:CPS0416	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-01-961-802PROC. REF: AMM 32-11-01-961-802									
32-11-01-102	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1 (AWL*)								Service ATA:32
PN:21274-1	MOS	29-Apr-15						LIFE LIMIT	
SN:CPS0407	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-01-961-802PROC. REF: AMM 32-11-01-961-802									
32-11-01-103	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER, PART NO. 21206 AND 21209 (AWL*)								Service ATA:32
PN:21208-109	MOS	29-Apr-15						LIFE LIMIT	
SN:DCL315	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-01-961-803PROC. REF: AMM 32-11-01-961-803									
32-11-01-103	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUTCYLINDER, PART NO. 21206 AND 21209 (AWL*)								Service ATA:32
PN:21208-109	MOS	29-Apr-15						LIFE LIMIT	
SN:DCL314	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-01-961-803PROC. REF: AMM 32-11-01-961-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-01-104	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON, PART NO. 21216 AND 21218 (AWL*)								Service ATA:32
PN:21217-107	MOS	29-Apr-15						LIFE LIMIT	
SN:DCL369	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-01-961-804PROC. REF: AMM 32-11-01-961-804									
32-11-01-104	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON, PART NO. 21216 AND 21218 (AWL*)								Service ATA:32
PN:21217-107	MOS	29-Apr-15						LIFE LIMIT	
SN:DCL368	HRS	4228.4							
	AFL	2192	15000		17192		12485		
PROC. REF: AMM 32-11-01-961-804PROC. REF: AMM 32-11-01-961-804									
32-11-01-105	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21194-1 (AWL*)								Service ATA:32
PN:21194-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC0546	HRS	4228.4							
	AFL	2192	10999	TAC 2192	10999		6292		
PROC. REF: AMM 32-11-01-961-801PROC. REF: AMM 32-11-01-961-801									
32-11-01-105	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21194-1 (AWL*)								Service ATA:32
PN:21194-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC0567	HRS	4228.4							
	AFL	2192	10999	TAC 2192	10999		6292		
PROC. REF: AMM 32-11-01-961-801PROC. REF: AMM 32-11-01-961-801									
32-11-01-201 ^S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT EXTENSION								Service ATA:32
	MOS	01-Jun-24						MRB	
	HRS	8251.3	750 (+50/-50)						
WC#: 32.070	AFL	4407							
PROC. REF: AMM 32-11-01-220-801PROC. REF: AMM 32-11-01-220-801									
32-11-01-900-801-01	LEFT HAND MLG SHOCK STRUT ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.295	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-01-900-801-02 RIGHT HAND MLG SHOCK STRUT ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.295	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-802-01 LH MLG SHOCK STRUT								Component	ATA:32
PN:21200-113	MOS/MSC	29-Apr-15	O/C						
SN:DCL535/05/06	HRS	4228.4							
WC#: 32.290	AFL	2192							
PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801									
32-11-01-900-802-02 RH MLG SHOCK STRUT								Component	ATA:32
PN:21200-113	MOS/MSC	29-Apr-15	O/C						
SN:DCL536/05/06	HRS	4228.4							
WC#: 32.290	AFL	2192							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-803-01 LH MLG TRAILING ARM / SHOCK STRUT PIN								Component	ATA:32
PN:21194-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC0546	HRS	4228.4							
WC#: 32.300	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-803-02 RH MLG TRAILING ARM / SHOCK STRUT PIN								Component	ATA:32
PN:21194-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC0567	HRS	4228.4							
WC#: 32.300	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801									
32-11-01-900-804-01 LH MLG UPPER PIN								Component	ATA:32
PN:21274-1	MOS/MSC	29-Apr-15	H/T						
SN:CPS0416	HRS	4228.4							
WC#: 32.305	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-01-900-804-02		RH MLG UPPER PIN						Component	ATA:32
PN:21274-1	MOS/MSC	29-Apr-15	H/T						
SN:CPS0407	HRS	4228.4							
WC#: 32.305	AFL	2192			TSN 2192				
PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801PROC. REF: AMM 32-11-01-000-801, AMM 32-11-01-400-801									
32-11-01-900-805-01		LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON						Component	ATA:32
PN:21217-107	MOS/MSC	29-Apr-15	H/T						
SN:DCL369	HRS	4228.4							
	AFL	2192			TSN 2192				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-805-02		RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON						Component	ATA:32
PN:21217-107	MOS/MSC	29-Apr-15	H/T						
SN:DCL368	HRS	4228.4							
	AFL	2192			TSN 2192				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-806-01		LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER						Component	ATA:32
PN:21208-109	MOS/MSC	29-Apr-15	H/T						
SN:DCL315	HRS	4228.4							
	AFL	2192			TSN 2192				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-806-02		RH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER						Component	ATA:32
PN:21208-109	MOS/MSC	29-Apr-15	H/T						
SN:DCL314	HRS	4228.4							
	AFL	2192			TSN 2192				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-807-01		LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON ASSY						Component	ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C		TSN 0				
SN:UNKNOWN	HRS	4228.4			TSN 0				
	AFL	2192			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-01-900-807-02 RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON ASSY								Component	ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0					
SN:UNKNOWN	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-808-01 LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER ASSY								Component	ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0					
SN:UNKNOWN	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-01-900-808-02 RH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER ASSY								Component	ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0					
SN:UNKNOWN	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-09-101 DISCARD THE LEFT HAND MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE, PART NO. 21410 (AWL*)								Service	ATA:32
PN:21410-103	MOS	07-May-15						LIFE LIMIT	
SN:H0168	HRS	4228.4		TAC 3305					
	AFL	2192	15000	TAC 1025	16167		11460		
PROC. REF: AMM 32-11-09-961-801PROC. REF: AMM 32-11-09-961-801									
32-11-09-101 DISCARD THE RIGHT HAND MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE, PART NO. 21410 (AWL*)								Service	ATA:32
PN:21410-103	MOS	27-May-15						LIFE LIMIT	
SN:H0163	HRS	4228.4		TAC 3305					
	AFL	2192	15000	TAC 1025	16167		11460		
PROC. REF: AMM 32-11-09-961-801PROC. REF: AMM 32-11-09-961-801									
32-11-09-102 DISCARD THE LH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO.21114 (AWL*)								Service	ATA:32
PN:21114-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1283	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-09-961-802PROC. REF: AMM 32-11-09-961-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-09-102 DISCARD THE RH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO.21114 (AWL*)									Service ATA:32
PN:21114-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1285	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-09-961-802PROC. REF: AMM 32-11-09-961-802									
32-11-09-900-801-01 LEFT HAND MLG TRAILING ARM ASSEMBLY									Component ATA:32
PN:21410-103	MOS/MSC	07-May-15	H/T						
SN:H0168	HRS	4228.4		TSN 3305					
WC#: 32.310	AFL	2192		TSN 1025					
PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801									
32-11-09-900-801-02 RIGHT HAND MLG TRAILING ARM ASSEMBLY									Component ATA:32
PN:21410-103	MOS/MSC	27-May-15	H/T						
SN:H0163	HRS	4228.4		TSN 3305					
WC#: 32.310	AFL	2192		TSN 1025					
PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801									
32-11-09-900-801-03 LH MLG HINGE PIN									Component ATA:32
PN:21114-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC1283	HRS	4228.4							
WC#: 32.315	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801									
32-11-09-900-801-04 RH MLG HINGE PIN									Component ATA:32
PN:21114-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC1285	HRS	4228.4							
WC#: 32.315	AFL	2192		TSN 2192					
PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801PROC. REF: AMM 32-11-09-000-801, AMM 32-11-09-400-801									
32-11-13-900-801-01 LOB MLG HARNESS ASSY									Component ATA:32
PN:21802-105	MOS/MSC	29-Apr-15	O/C						
SN:187	HRS	4228.4							
WC#: 32.320	AFL	2192							
PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-13-900-801-02		LIB MLG HARNESS ASSY						Component	ATA:32
PN:21801-105	MOS/MSC	29-Apr-15	O/C						
SN:191	HRS	4228.4							
WC#: 32.320	AFL	2192							
PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801									
32-11-13-900-801-03		RIB MLG HARNESS ASSY						Component	ATA:32
PN:21803-105	MOS/MSC	29-Apr-15	O/C						
SN:186	HRS	4228.4							
WC#: 32.325	AFL	2192							
PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801									
32-11-13-900-801-04		ROB MLG HARNESS ASSY						Component	ATA:32
PN:21804-105	MOS/MSC	29-Apr-15	O/C						
SN:189	HRS	4228.4							
WC#: 32.325	AFL	2192							
PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801PROC. REF: CMM 32-60-03, AMM 32-11-13-000-801, AMM 32-11-13-400-801									
32-11-17-101		DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAYLOWER-PIN, PART NO. 21113 (AWL*)						Service	ATA:32
PN:21113-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1270	HRS	4228.4							
	AFL	2192	11168	TAC 2192	11168		6461		
PROC. REF: AMM 32-11-17-961-801PROC. REF: AMM 32-11-17-961-801									
32-11-17-101		DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAYLOWER-PIN, PART NO. 21113 (AWL*)						Service	ATA:32
PN:21113-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1302	HRS	4228.4							
	AFL	2192	11168	TAC 2192	11168		6461		
PROC. REF: AMM 32-11-17-961-801PROC. REF: AMM 32-11-17-961-801									
32-11-17-102		DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE RODEND, PART NO. 21510 (AWL*)						Service	ATA:32
PN:21510-3	MOS	27-May-15						LIFE LIMIT	
SN:05-23	HRS	4228.4							
	AFL	2192	8683	TAC 2192	8683		3976		
PROC. REF: AMM 32-11-17-961-802PROC. REF: AMM 32-11-17-961-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-17-102		DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE RODEND, PART NO. 21510 (AWL*)						Service	ATA:32
PN:21510-3	MOS	27-May-15						LIFE LIMIT	
SN:05-19	HRS	4228.4							
	AFL	2192	8683	TAC 2192	8683		3976		
PROC. REF: AMM 32-11-17-961-802PROC. REF: AMM 32-11-17-961-802									
32-11-17-103		DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON,PART NO. 21512 (AWL*)						Service	ATA:32
PN:21512-2	MOS	26-May-15						LIFE LIMIT	
SN:1422	HRS	4228.4							
	AFL	2192	8683	TAC 2192	8683		3976		
PROC. REF: AMM 32-11-17-961-803PROC. REF: AMM 32-11-17-961-803									
32-11-17-103		DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON,PART NO. 21512 (AWL*)						Service	ATA:32
PN:21512-2	MOS	26-May-15						LIFE LIMIT	
SN:1423	HRS	4228.4							
	AFL	2192	8683		10875		6168		
PROC. REF: AMM 32-11-17-961-803PROC. REF: AMM 32-11-17-961-803									
32-11-17-104		DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER, PART NO. 21521 (AWL*)						Service	ATA:32
PN:21521-1	MOS	26-May-15						LIFE LIMIT	
SN:DAY1978	HRS	4228.4							
	AFL	2192	8683		10875		6168		
PROC. REF: AMM 32-11-17-961-804PROC. REF: AMM 32-11-17-961-804									
32-11-17-104		DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER, PART NO. 21521 (AWL*)						Service	ATA:32
PN:21521-1	MOS	27-May-15						LIFE LIMIT	
SN:DAY626	HRS	4228.4							
	AFL	2192	8683	TAC 2192	8683		3976		
PROC. REF: AMM 32-11-17-961-804PROC. REF: AMM 32-11-17-961-804									
32-11-17-106		DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725 (AWL*)						Service	ATA:32
PN:PN	MOS	07-Oct-05		TAC 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TAC 0					
	AFL	0	25000	TAC 0	25000		20293		
PROC. REF: AMM 32-11-17-961-805PROC. REF: AMM 32-11-17-961-805									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-17-106	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725 (AWL*)								Service ATA:32
PN:PN	MOS	07-Oct-05		TAC 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TAC 0					
	AFL	0	25000	TAC 0	25000		20293		
PROC. REF: AMM 32-11-17-961-805PROC. REF: AMM 32-11-17-961-805									
32-11-17-900-801-01	LH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END								Component ATA:32
PN:21510-3	MOS/MSC	27-May-15	H/T						
SN:05-23	HRS	4228.4							
	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-801-02	RH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END								Component ATA:32
PN:21510-3	MOS/MSC	27-May-15	H/T						
SN:05-19	HRS	4228.4							
	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-801-03	LH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON								Component ATA:32
PN:21512-2	MOS/MSC	26-May-15	H/T						
SN:1422	HRS	4228.4							
	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-801-04	RH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON								Component ATA:32
PN:21512-2	MOS/MSC	26-May-15	H/T	TSN 0					
SN:1423	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-801-05	LH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER								Component ATA:32
PN:21521-1	MOS/MSC	26-May-15	H/T	TSN 0					
SN:DAY1978	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-17-900-801-06 RH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER								Component	ATA:32
PN:21521-1	MOS/MSC	27-May-15	H/T						
SN:DAY626	HRS	4228.4							
	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-802-01 LH MLG SIDE BRACE ACTUATOR								Component	ATA:32
PN:GW312-2001-9	MOS/MSC	27-May-15	O/C						
SN:00381	HRS	4228.4							
WC#: 32.330	AFL	2192							
PROC. REF: CMM 32-30-23, AMM 32-11-17-000-801, AMM 32-11-17-400-801PROC. REF: CMM 32-30-23, AMM 32-11-17-000-801, AMM 32-11-17-400-801									
32-11-17-900-802-02 RH MLG SIDE BRACE ACTUATOR								Component	ATA:32
PN:GW312-2001-9	MOS/MSC	27-May-15	O/C						
SN:00380	HRS	4228.4							
WC#: 32.330	AFL	2192							
PROC. REF: CMM 32-30-23, AMM 32-11-17-000-801, AMM 32-11-17-400-801PROC. REF: CMM 32-30-23, AMM 32-11-17-000-801, AMM 32-11-17-400-801									
32-11-17-900-805-01 LH MLG SIDE-STAY UPPER PIN ASSY								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-17-900-805-02 RH MLG SIDE-STAY UPPER PIN ASSY								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-11-29-101 DISCARD THE LEFT HAND MAIN LANDING GEAR (MLG) MAIN FITTING, PART NO. 21310 (AWL*)								Service	ATA:32
PN:21310-105	MOS	29-Apr-15						LIFE LIMIT	
SN:WHM133	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-29-961-801PROC. REF: AMM 32-11-29-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-11-29-101	DISCARD THE RIGHT HAND MAIN LANDING GEAR (MLG) MAIN FITTING, PART NO. 21310 (AWL*)								Service ATA:32
PN:21310-106	MOS	29-Apr-15						LIFE LIMIT	
SN:DCL179	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-29-961-801PROC. REF: AMM 32-11-29-961-801									
32-11-29-102	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO.21112 (AWL*)								Service ATA:32
PN:21112-101	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1309	HRS	4228.4							
	AFL	2192	11271	TAC 2192	11271		6564		
PROC. REF: AMM 32-11-29-961-802PROC. REF: AMM 32-11-29-961-802									
32-11-29-102	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO.21112 (AWL*)								Service ATA:32
PN:21112-102	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC1318	HRS	4228.4							
	AFL	2192	11271	TAC 2192	11271		6564		
PROC. REF: AMM 32-11-29-961-802PROC. REF: AMM 32-11-29-961-802									
32-11-29-103	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN, PART NO. 21116-1 (AWL*)								Service ATA:32
PN:21116-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC0486	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-29-961-803PROC. REF: AMM 32-11-29-961-803									
32-11-29-103	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN, PART NO. 21116-1 (AWL*)								Service ATA:32
PN:21116-1	MOS	29-Apr-15						LIFE LIMIT	
SN:EXC0478	HRS	4228.4							
	AFL	2192	15000	TAC 2192	15000		10293		
PROC. REF: AMM 32-11-29-961-803PROC. REF: AMM 32-11-29-961-803									
32-11-29-900-801-01	NOSE LANDING GEAR MAIN FITTING								Component ATA:32
PN:1286-0109	MOS/MSC	22-May-15	H/T	TSN 0					
SN:L2157	HRS	4228.4		TSN 0					
WC#: 32.390	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-12-00-201		LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOORS							Service ATA:32
	MOS	12-May-26						MRB	
	HRS	8870	250 (+10%/-10%)	Adj 25	9145	9170	226.4 (+25)		
WC#: 32.075	AFL	4687							
PROC. REF: AMM 12-22-00-640-819PROC. REF: AMM 12-22-00-640-819									
32-12-00-202 ^S		LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOOR ACTUATOR							Service ATA:32
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.080	AFL	4582							
PROC. REF: AMM 12-22-00-640-834PROC. REF: AMM 12-22-00-640-834									
32-12-05-900-801-01		LH INBOARD MLG DOOR							Component ATA:32
PN:GS328-0001-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:S019	HRS	0		TSN 0					
WC#: 32.335	AFL	0		TSN 0					
PROC. REF: AMM 32-12-05-000-801, AMM 32-12-05-400-801PROC. REF: AMM 32-12-05-000-801, AMM 32-12-05-400-801									
32-12-05-900-801-02		RH INBOARD MLG DOOR							Component ATA:32
PN:GS328-0001-4	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:C049	HRS	0		TSN 0					
WC#: 32.335	AFL	0		TSN 0					
PROC. REF: AMM 32-12-05-000-801, AMM 32-12-05-400-801PROC. REF: AMM 32-12-05-000-801, AMM 32-12-05-400-801									
32-12-09-900-801-01		LEFT HAND MLG MAIN FITTING							Component ATA:32
PN:21310-105	MOS/MSC	29-Apr-15	H/T						
SN:WHM133	HRS	4228.4							
WC#: 32.340	AFL	2192		TSN 2192					
PROC. REF: AMM 32-12-09-000-801, AMM 32-12-09-400-801PROC. REF: AMM 32-12-09-000-801, AMM 32-12-09-400-801									
32-12-09-900-801-02		RIGHT HAND MLG MAIN FITTING							Component ATA:32
PN:21310-106	MOS/MSC	29-Apr-15	H/T						
SN:DCL179	HRS	4228.4							
WC#: 32.340	AFL	2192		TSN 2192					
PROC. REF: AMM 32-12-09-000-801, AMM 32-12-09-400-801PROC. REF: AMM 32-12-09-000-801, AMM 32-12-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-20-00-201	^S	RESTORATION OF THE NOSE LANDING GEAR						Service	ATA:32
PN:GW318-2000-1	MOS	14-Aug-25	240 (+3m/-3m)					MRB	
SN:DCL279/05	HRS	8645							
WC#: 32.355	AFL	4582							
PROC. REF: AMM 32-21-00-615-801PROC. REF: AMM 32-21-00-615-801									
32-20-00-204	^S	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.085	AFL	4582							
PROC. REF: AMM 32-21-00-220-801PROC. REF: AMM 32-21-00-220-801									
32-20-00-205	^S	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.090	AFL	4582							
PROC. REF: AMM 32-21-00-280-801PROC. REF: AMM 32-21-00-280-801									
32-20-00-206	^S	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.095	AFL	4582							
PROC. REF: AMM 32-21-00-220-802PROC. REF: AMM 32-21-00-220-802									
32-20-00-207	^S	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.100	AFL	4582							
PROC. REF: AMM 32-21-00-280-802PROC. REF: AMM 32-21-00-280-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-20-00-208	^S	DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.105	AFL	4582							
PROC. REF: AMM 32-21-00-220-803PROC. REF: AMM 32-21-00-220-803									
32-20-00-209	^S	SPECIAL DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.110	AFL	4582							
PROC. REF: AMM 32-21-00-280-803PROC. REF: AMM 32-21-00-280-803									
32-20-00-210	^S	DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.115	AFL	4582							
PROC. REF: AMM 32-33-01-220-801PROC. REF: AMM 32-33-01-220-801									
32-20-00-211	^S	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.120	AFL	4582							
PROC. REF: AMM 32-33-01-280-801PROC. REF: AMM 32-33-01-280-801									
32-21-00-201		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND COMPONENTS							Service ATA:32
	MOS	12-May-26						MRB	
	HRS	8870	250 (+10%/-10%)	Adj 25	9145	9170	226.4 (+25)		
WC#: 32.125	AFL	4687							
PROC. REF: AMM 12-22-00-640-801PROC. REF: AMM 12-22-00-640-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-00-900-801-01	NLG PINTLE PIN								Component ATA:32
PN:1285-0006	MOS/MSC	11-May-15	O/C						
SN:1039156/001	HRS	4228.4		TSN 4221.5					
WC#: 32.385	AFL	2192		TSN 2188					
PROC. REF: AMM 32-21-00-000-801, AMM 32-21-00-400-801PROC. REF: AMM 32-21-00-000-801, AMM 32-21-00-400-801									
32-21-00-900-802-01	NLG ASSY GEAR								Component ATA:32
PN:GW318-2000-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL279/05	HRS	0		TSN 0					
WC#: 32.355	AFL	0		TSN 0					
PROC. REF: AMM 32-21-00-000-801, AMM 32-21-00-400-801PROC. REF: AMM 32-21-00-000-801, AMM 32-21-00-400-801									
32-21-01-101	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT AXLE, PART NO. 1286-0201/-0203/-0204 (AWL*)								Service ATA:32
PN:1286-0204	MOS	22-May-15						LIFE LIMIT	
SN:L2231	HRS	4228.4							
	AFL	2192	15000		17192		12485		
PROC. REF: AMM 32-21-17-961-801PROC. REF: AMM 32-21-17-961-801									
32-21-01-102	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT PISTON(SLIDING TUBE), PART NO. 1286-0001 AND 1286-0077 (AWL*)								Service ATA:32
PN:1286-0077	MOS	22-May-15						LIFE LIMIT	
SN:L0723	HRS	4228.4							
	AFL	2192	15000		17192		12485		
PROC. REF: AMM 32-21-01-961-803PROC. REF: AMM 32-21-01-961-803									
32-21-01-103	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT MAIN FITTING, PART NO. 1286-0101/-0109 (AWL*)								Service ATA:32
PN:1286-0109	MOS	22-May-15						LIFE LIMIT	
SN:L2157	HRS	4228.4							
	AFL	2192	11295		13487		8780		
PROC. REF: AMM 32-21-01-961-802PROC. REF: AMM 32-21-01-961-802									
32-21-01-107	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT, PART NO. 1285-0007/-0041 (AWL*)								Service ATA:32
PN:PN	MOS	07-Oct-05		TAC 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TAC 0					
	AFL	0	15000	TAC 0	15000		10293		
PROC. REF: AMM 32-33-01-961-802PROC. REF: AMM 32-33-01-961-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-202625-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT LH STEERING ACTUATOR BOLT, PART NO. 1285-0010 (AWL*)							Service	ATA:32
	MOS	07-Oct-05						LIFE LIMIT	
	HRS	0							
	AFL	0	15000		15000		10293		
PROC. REF: AMM 32-51-21-961-801PROC. REF: AMM 32-51-21-961-801									
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RH STEERING ACTUATOR BOLT, PART NO. 1285-0010 (AWL*)							Service	ATA:32
	MOS	07-Oct-05						LIFE LIMIT	
	HRS	0							
	AFL	0	15000		15000		10293		
PROC. REF: AMM 32-51-21-961-801PROC. REF: AMM 32-51-21-961-801									
32-21-01-201 ^S	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK STRUT EXTENSION							Service	ATA:32
	MOS	01-Jun-24						MRB	
	HRS	8251.3	750 (+50/-50)						
WC#: 32.130	AFL	4407							
PROC. REF: AMM 32-21-01-220-801PROC. REF: AMM 32-21-01-220-801									
PKG:3									
32-21-01-900-801-01	NOSE LANDING GEAR (NLG) SHOCK STRUT (SLIDING TUBE) PISTON							Component	ATA:32
PN:1286-0077	MOS/MSC	22-May-15	H/T	TSN 0					
SN:L0723	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-01-900-804-01	NLG SHOCK STRUT							Component	ATA:32
PN:22175-109	MOS/MSC	18-May-15	O/C	TSN 115, TSR 0					
SN:00323	HRS	4228.4		TSN 4228.4, TSR 0					
WC#: 32.365	AFL	2192		TSN 2192, TSR 0					
PROC. REF: CMM 32-21-01, AMM 32-21-01-000-801, AMM 32-21-01-400-801PROC. REF: CMM 32-21-01, AMM 32-21-01-000-801, AMM 32-21-01-400-801									
32-21-03-900-801-01	NOSE LANDING GEAR STRUT							Component	ATA:32
PN:1286A0000-02	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00323	HRS	0		TSN 0					
WC#: 32.360	AFL	0		TSN 0					
PROC. REF: AMM 32-21-03-000-801, AMM 32-21-03-400-801PROC. REF: AMM 32-21-03-000-801, AMM 32-21-03-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-05-101 DISCARD THE NOSE LANDING GEAR (NLG) UPPER DRAG BRACE,PART NO. 22511 (AWL*)									Service ATA:32
PN:22511-101	MOS	01-May-15		TAC 115				LIFE LIMIT	
SN:DCL187	HRS	4228.4		TAC 4228.4					
	AFL	2192	12540	TAC 2192	12540		7833		
PROC. REF: AMM 32-21-05-961-805PROC. REF: AMM 32-21-05-961-805									
32-21-05-102 DISCARD THE NOSE LANDING GEAR (NLG) LOWER DRAG BRACE,PART NO. 22516 (AWL*)									Service ATA:32
PN:22516-103	MOS	01-May-15		TAC 115				LIFE LIMIT	
SN:HAI0223	HRS	4228.4		TAC 4228.4					
	AFL	2192	11520	TAC 2192	11520		6813		
PROC. REF: AMM 32-21-05-961-802PROC. REF: AMM 32-21-05-961-802									
32-21-05-105 DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE APEXPIN, PART NO. 22530 (AWL*)									Service ATA:32
PN:22530-1	MOS	01-May-15		TAC 115				LIFE LIMIT	
SN:EXC0185	HRS	4228.4		TAC 4228.4					
	AFL	2192	11190	TAC 2192	11190		6483		
PROC. REF: AMM 32-21-05-961-803PROC. REF: AMM 32-21-05-961-803									
32-21-05-106 DISCARD THE LH NOSE LANDING GEAR (NLG) DRAG BRACETRNNION PIN, PART NO. 22534 (AWL*)									Service ATA:32
PN:22534-1	MOS	01-May-15		TAC 115				LIFE LIMIT	
SN:CPS0505	HRS	4228.4		TAC 4228.4					
	AFL	2192	11220	TAC 2192	11220		6513		
PROC. REF: AMM 32-21-05-961-804PROC. REF: AMM 32-21-05-961-804									
32-21-05-106 DISCARD THE RH NOSE LANDING GEAR (NLG) DRAG BRACETRNNION PIN, PART NO. 22534 (AWL*)									Service ATA:32
PN:22534-1	MOS	01-May-15		TAC 115				LIFE LIMIT	
SN:CPS0503	HRS	4228.4		TAC 4228.4					
	AFL	2192	11220	TAC 2192	11220		6513		
PROC. REF: AMM 32-21-05-961-804PROC. REF: AMM 32-21-05-961-804									
32-21-05-107 DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE FORWARD STABILIZER LINK, PART NO. 22580 (AWL*)									Service ATA:32
PN:PN	MOS	07-Oct-05		TAC 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TAC 0					
	AFL	0	11565	TAC 0	11565		6858		
PROC. REF: AMM 32-21-05-961-806PROC. REF: AMM 32-21-05-961-806									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-05-108		DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE AFT STABILIZER LINK, PART NO. 22585 (AWL*)						Service	ATA:32
PN:PN	MOS	07-Oct-05		TAC 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TAC 0					
	AFL	0	11505	TAC 0	11505		6798		
PROC. REF: AMM 32-21-05-961-807PROC. REF: AMM 32-21-05-961-807									
32-21-05-900-801-01		NLG DRAG BRACE						Component	ATA:32
PN:22500-105	MOS/MSC	02-Jun-15	O/C	TSN 116, TSR 0					
SN:DCL284/05	HRS	4228.4		TSN 4228.4, TSR 0					
WC#: 32.350	AFL	2192		TSN 2192, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-05-900-801-03		NLG APEX DRAG BRACE PIN						Component	ATA:32
PN:22530-1	MOS/MSC	01-May-15	H/T	TSN 115					
SN:EXC0185	HRS	4228.4		TSN 4228.4					
WC#: 32.725	AFL	2192		TSN 2192					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-05-900-802-01		NLG UPPER DRAG BRACE						Component	ATA:32
PN:22511-101	MOS/MSC	01-May-15	H/T	TSN 115					
SN:DCL187	HRS	4228.4		TSN 4228.4					
	AFL	2192		TSN 2192					
PROC. REF: CMM 32-70-07, AMM 32-21-05-000-801, AMM 32-21-05-400-801PROC. REF: CMM 32-70-07, AMM 32-21-05-000-801, AMM 32-21-05-400-801									
32-21-05-900-803-01		NLG LOWER DRAG BRACE						Component	ATA:32
PN:22516-103	MOS/MSC	01-May-15	H/T	TSN 115					
SN:HAI0223	HRS	4228.4		TSN 4228.4					
	AFL	2192		TSN 2192					
PROC. REF: CMM 32-70-07PROC. REF: CMM 32-70-07									
32-21-05-900-806-01		DOWNLOCK NLG ACTUATOR						Component	ATA:32
PN:22570-101	MOS/MSC	01-May-15	O/C	TSN 115					
SN:DCL521/05	HRS	4228.4		TSN 4228.4					
WC#: 32.365	AFL	2192		TSN 2192					
PROC. REF: AMM 32-21-05-000-801, AMM 32-21-05-400-801PROC. REF: AMM 32-21-05-000-801, AMM 32-21-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-05-900-807-01		NOSE LANDING GEAR (NLG) DRAG BRACE FORWARD STABILIZER LINK						Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-05-900-807-02		NOSE LANDING GEAR (NLG) DRAG BRACE AFT STABILIZER LINK						Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-07-900-801-01		LH NLG TRUNNION PIN						Component	ATA:32
PN:22534-1	MOS/MSC	01-May-15	H/T	TSN 115					
SN:CPS0505	HRS	4228.4	TSN 4228.4						
WC#: 32.375	AFL	2192	TSN 2192						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-21-07-900-801-02		RH NLG TRUNNION PIN						Component	ATA:32
PN:22534-1	MOS/MSC	01-May-15	H/T	TSN 115					
SN:CPS0503	HRS	4228.4	TSN 4228.4						
WC#: 32.375	AFL	2192	TSN 2192						
PROC. REF: AMM 32-21-07-000-801, AMM 32-21-07-400-801PROC. REF: AMM 32-21-07-000-801, AMM 32-21-07-400-801									
32-21-07-900-801-03		NLG LOWER PIN						Component	ATA:32
PN:1285-0042	MOS/MSC	11-May-15	O/C						
SN:1029672/003	HRS	4228.4	TSN 4221.5						
WC#: 32.380	AFL	2192	TSN 2188						
PROC. REF: AMM 32-21-07-000-801, AMM 32-21-07-400-801PROC. REF: AMM 32-21-07-000-801, AMM 32-21-07-400-801									
32-21-09-900-801-01		LH NLG HARNESS						Component	ATA:32
PN:22800-105	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:196	HRS	0	TSN 0						
WC#: 32.395	AFL	0	TSN 0						
PROC. REF: CMM 32-60-04, AMM 32-21-09-000-801, AMM 32-21-09-400-801PROC. REF: CMM 32-60-04, AMM 32-21-09-000-801, AMM 32-21-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-21-09-900-801-02	RH NLG HARNESS							Component	ATA:32
PN:22801-107	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:193	HRS	0		TSN 0					
WC#: 32.395	AFL	0		TSN 0					
PROC. REF: CMM 32-60-04, AMM 32-21-09-000-801, AMM 32-21-09-400-801PROC. REF: CMM 32-60-04, AMM 32-21-09-000-801, AMM 32-21-09-400-801									
32-21-17-900-801-01	NOSE LANDING GEAR AXLE							Component	ATA:32
PN:1286-0204	MOS/MSC	22-May-15	H/T	TSN 0					
SN:L2231	HRS	4228.4		TSN 0					
WC#: 32.345	AFL	2192		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-22-00-101	SPECIAL DETAILED INSPECTION OF THE NOSE GEAR FORWARD DOORS (AWL*)							Service	ATA:32
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 32.135	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-32-20-001, NDT MT-32-20-001PROC. REF: NDT ET-32-20-001, NDT MT-32-20-001									
32-22-00-201	LUBRICATION OF THE NOSE LANDING GEAR (NLG) DOORS							Service	ATA:32
	MOS	12-May-26						MRB	
	HRS	8870	250 (+10%/-10%)	Adj 25	9145	9170	226.4 (+25)		
WC#: 32.140	AFL	4687							
PROC. REF: AMM 12-22-00-640-803PROC. REF: AMM 12-22-00-640-803									
32-22-00-202 ^S	DETAILED INSPECTION OF THE NOSE-GEAR-DOOR HINGES AND ACTUATOR ATTACHMENT FITTING							Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.145	AFL	4582							
PROC. REF: AMM 32-22-01-220-801PROC. REF: AMM 32-22-01-220-801									
32-22-05-900-801-01	NLG AFT DOOR ASSY							Component	ATA:32
PN:GS328-0005-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B175	HRS	0		TSN 0					
WC#: 32.400	AFL	0		TSN 0					
PROC. REF: AMM 32-22-05-000-801, AMM 32-22-05-400-801PROC. REF: AMM 32-22-05-000-801, AMM 32-22-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-22-17-900-801-01	LH NLG FWD DOOR ASSY							Component	ATA:32
PN:GS328-0003-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B177	HRS	0		TSN 0					
WC#: 32.405	AFL	0		TSN 0					
PROC. REF: AMM 32-22-17-000-801, AMM 32-22-17-400-801PROC. REF: AMM 32-22-17-000-801, AMM 32-22-17-400-801									
32-22-17-900-801-02	RH NLG FWD DOOR ASSY							Component	ATA:32
PN:GS328-0004-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B175	HRS	0		TSN 0					
WC#: 32.405	AFL	0		TSN 0					
PROC. REF: AMM 32-22-17-000-801, AMM 32-22-17-400-801PROC. REF: AMM 32-22-17-000-801, AMM 32-22-17-400-801									
32-31-01-900-801-01	LANDING GEAR CONTROL PANEL							Component	ATA:32
PN:GC549-0017-3/00	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6725122	HRS	0		TSN 0					
WC#: 32.415	AFL	0		TSN 0					
PROC. REF: AMM 32-31-01-000-801, AMM 32-31-01-400-801PROC. REF: AMM 32-31-01-000-801, AMM 32-31-01-400-801									
32-31-05-900-801-01	LANDING GEAR CONTROL HANDLE							Component	ATA:32
PN:GW415-7050-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:203	HRS	0		TSN 0					
WC#: 32.410	AFL	0		TSN 0					
PROC. REF: AMM 32-31-05-000-801, AMM 32-31-05-400-801PROC. REF: AMM 32-31-05-000-801, AMM 32-31-05-400-801									
32-31-09-101	VISUAL CHECK OF THE LANDING-GEAR ELECTRONIC CONTROL UNIT (LG ECU) (CMR**)							Service	ATA:32
	MOS	14-Aug-25						CMR	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 32.150	AFL	4582							
PROC. REF: AMM 32-31-09-210-801PROC. REF: AMM 32-31-09-210-801									
32-31-09-900-801-01	LANDING GEAR ECU							Component	ATA:32
PN:GW415-5100-1	MOS/MSC	08-Oct-12	O/C	TSN 0					
SN:E641	HRS	2886.8		TSN 0					
WC#: 32.420	AFL	1498		TSN 0					
PROC. REF: AMM 32-31-09-000-801, AMM 32-31-09-400-801PROC. REF: AMM 32-31-09-000-801, AMM 32-31-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-31-13-900-801-01	NO. 2 SYSTEM L/G CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NGL/1559/04	HRS	0		TSN 0					
WC#: 32.425	AFL	0		TSN 0					
PROC. REF: AMM 32-31-13-000-801, AMM 32-31-13-400-801PROC. REF: AMM 32-31-13-000-801, AMM 32-31-13-400-801									
32-31-15-900-801-01	NO. 3 SYSTEM L/G CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NGL/1558/04	HRS	0		TSN 0					
WC#: 32.425	AFL	0		TSN 0					
PROC. REF: AMM 32-31-15-000-801, AMM 32-31-15-400-801PROC. REF: AMM 32-31-15-000-801, AMM 32-31-15-400-801									
32-31-17-900-801-01	L/G DOOR CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NGL/1553/04	HRS	0		TSN 0					
WC#: 32.425	AFL	0		TSN 0					
PROC. REF: AMM 32-31-17-000-801, AMM 32-31-17-400-801PROC. REF: AMM 32-31-17-000-801, AMM 32-31-17-400-801									
32-31-21-900-801-01	CHECK, SIDE BRACE CONTROL VALVE								Component ATA:32
PN:GW415-6075-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NGL/1205/04	HRS	0		TSN 0					
WC#: 32.430	AFL	0		TSN 0					
PROC. REF: AMM 32-31-21-000-801, AMM 32-31-21-400-801PROC. REF: AMM 32-31-21-000-801, AMM 32-31-21-400-801									
32-32-01-105	DISCARD THE LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600 (AWL*)								Service ATA:32
PN:GW412-1000-1	MOS	12-Oct-12						LIFE LIMIT	
SN:11MDT0881	HRS	2899.8							
	AFL	1504	25000		26504		21797		
PROC. REF: AMM 32-32-01-961-801PROC. REF: AMM 32-32-01-961-801									
32-32-01-105	DISCARD THE RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600 (AWL*)								Service ATA:32
PN:GW412-1000-2	MOS							LIFE LIMIT	
SN:DCL536/05	HRS	0							
	AFL	0	25000		25000		20293		
PROC. REF: AMM 32-32-01-961-801PROC. REF: AMM 32-32-01-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-01-900-801-01 LH MLG RETRACTION ACTUATOR								Component	ATA:32
PN:GW412-1000-1	MOS/MSC	12-Oct-12	H/T	TSN 1					
SN:11MDT0881	HRS	2899.8		TSN 0					
WC#: 32.435	AFL	1504		TSN 0					
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									
32-32-01-900-801-02 RH MLG RETRACTION ACTUATOR								Component	ATA:32
PN:GW412-1000-2	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:DCL536/05	HRS	0		TSN 0					
WC#: 32.435	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									
32-32-01-900-801-03 LH MLG SIDE STAY (LOWER) PIN								Component	ATA:32
PN:21113-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC1270	HRS	4228.4							
WC#: 32.440	AFL	2192		TSN 2192					
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									
32-32-01-900-801-04 RH MLG SIDE STAY (LOWER) PIN								Component	ATA:32
PN:21113-1	MOS/MSC	29-Apr-15	H/T						
SN:EXC1302	HRS	4228.4							
WC#: 32.440	AFL	2192		TSN 2192					
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									
32-32-01-900-803-01 LH MLG RETRACTION ACTUATOR PIN								Component	ATA:32
PN:21118-3	MOS/MSC	29-Apr-15	O/C						
SN:EXC0421	HRS	4228.4							
WC#: 32.450	AFL	2192							
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									
32-32-01-900-803-02 RH MLG RETRACTION ACTUATOR PIN								Component	ATA:32
PN:21118-3	MOS/MSC	29-Apr-15	O/C						
SN:EXC0423	HRS	4228.4							
WC#: 32.450	AFL	2192							
PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801PROC. REF: AMM 32-32-01-000-801, AMM 32-32-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-01-900-804-01 LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: CMM 32-30-27PROC. REF: CMM 32-30-27									
32-32-01-900-804-02 RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: CMM 32-30-27PROC. REF: CMM 32-30-27									
32-32-01-900-805-01 LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-01-900-805-02 RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-01-900-806-01 LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-01-900-806-02 RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-01-900-807-01 LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-01-900-807-02 RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-107 DISCARD THE LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY,PART NO. 21900 (AWL*)								Service	ATA:32
PN:GW415-0001-3	MOS	08-Oct-12						LIFE LIMIT	
SN:12SM00037	HRS	2886.8							
	AFL	1498	25000		26498		21791		
PROC. REF: AMM 32-32-05-961-801PROC. REF: AMM 32-32-05-961-801									
32-32-05-107 DISCARD THE RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY,PART NO. 21900 (AWL*)								Service	ATA:32
PN:GW415-0001-4	MOS							LIFE LIMIT	
SN:NGL/0176/04	HRS	0							
	AFL	0	25000		25000		20293		
PROC. REF: AMM 32-32-05-961-801PROC. REF: AMM 32-32-05-961-801									
32-32-05-900-801-01 LH MLG UPLOCK								Component	ATA:32
PN:GW415-0001-3	MOS/MSC	08-Oct-12	H/T	TSN 0					
SN:12SM00037	HRS	2886.8		TSN 0					
WC#: 32.455	AFL	1498		TSN 0					
PROC. REF: CMM 32-30-24, AMM 32-32-05-000-801, AMM 32-32-05-400-801PROC. REF: CMM 32-30-24, AMM 32-32-05-000-801, AMM 32-32-05-400-801									
32-32-05-900-801-02 RH MLG UPLOCK								Component	ATA:32
PN:GW415-0001-4	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:NGL/0176/04	HRS	0		TSN 0					
WC#: 32.455	AFL	0		TSN 0					
PROC. REF: CMM 32-30-24, AMM 32-32-05-000-801, AMM 32-32-05-400-801PROC. REF: CMM 32-30-24, AMM 32-32-05-000-801, AMM 32-32-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
32-32-05-900-802-01		LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-32-05-900-802-02		RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-32-05-900-803-01		LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-32-05-900-803-02		RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-32-05-900-804-01		LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-32-05-900-804-02		RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-05-900-805-01 LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-900-805-02 RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-900-806-01 LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-900-806-02 RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-900-807-01 LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-32-05-900-807-02 RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-09-900-801-01	LH MLG DOOR INBOARD ACTUATOR								Component ATA:32
PN:GW412-2000-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL263/05	HRS	0		TSN 0					
WC#: 32.460	AFL	0		TSN 0					
PROC. REF: CMM 32-30-32, AMM 32-32-09-000-801, AMM 32-32-09-400-801PROC. REF: CMM 32-30-32, AMM 32-32-09-000-801, AMM 32-32-09-400-801									
32-32-09-900-801-02	RH MLG DOOR INBOARD ACTUATOR								Component ATA:32
PN:GW412-2000-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL262/05	HRS	0		TSN 0					
WC#: 32.460	AFL	0		TSN 0					
PROC. REF: CMM 32-30-32, AMM 32-32-09-000-801, AMM 32-32-09-400-801PROC. REF: CMM 32-30-32, AMM 32-32-09-000-801, AMM 32-32-09-400-801									
32-32-13-101	DISCARD THE LH MAIN-GEAR DOOR UPLOCK, PART NO. GW415-2200-5/6 (AWL*)								Service ATA:32
PN:GW415-2200-5	MOS							LIFE LIMIT	
SN:NGL/0180/04	HRS	0							
	AFL	0	6250		6250		1543		
PROC. REF: AMM 32-32-13-961-801PROC. REF: AMM 32-32-13-961-801									
32-32-13-101	DISCARD THE RH MAIN-GEAR DOOR UPLOCK, PART NO.GW415-2200-5/6 (AWL*)								Service ATA:32
PN:GW415-2200-6	MOS							LIFE LIMIT	
SN:NGL/0181/04	HRS	0							
	AFL	0	6250		6250		1543		
PROC. REF: AMM 32-32-13-961-801PROC. REF: AMM 32-32-13-961-801									
32-32-13-900-801-01	LH MLG DOOR INBOARD UPLOCK								Component ATA:32
PN:GW415-2200-5	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:NGL/0180/04	HRS	0		TSN 0					
WC#: 32.465	AFL	0		TSN 0					
PROC. REF: CMM 32-30-28, AMM 32-32-13-000-801, AMM 32-32-13-400-801PROC. REF: CMM 32-30-28, AMM 32-32-13-000-801, AMM 32-32-13-400-801									
32-32-13-900-801-02	RH MLG DOOR INBOARD UPLOCK								Component ATA:32
PN:GW415-2200-6	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:NGL/0181/04	HRS	0		TSN 0					
WC#: 32.465	AFL	0		TSN 0					
PROC. REF: CMM 32-30-28, AMM 32-32-13-000-801, AMM 32-32-13-400-801PROC. REF: CMM 32-30-28, AMM 32-32-13-000-801, AMM 32-32-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-33-01-105	DISCARD THE NOSE LANDING GEAR (NLG) RETRACTION ACTUATORASSEMBLY, PART NO. 22400-101/-103 (AWL*)								Service ATA:32
PN:GW412-1050-3	MOS	02-Jun-15		TAC 116				LIFE LIMIT	
SN:DCL117/05	HRS	4228.4		TAC 4228.4					
	AFL	2192	20000	TAC 2192	20000		15293		
PROC. REF: AMM 32-33-01-961-801PROC. REF: AMM 32-33-01-961-801									
32-33-01-111	RESTORATION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-32-035 PART C) (AWL*)								Service ATA:32
	MOS	14-Aug-25	120		14-Aug-35		3337 d	RESTORE	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 32-21-01-610-801PROC. REF: AMM 32-21-01-610-801									
32-33-01-112	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-32-035 PART C) (AWL*)								Service ATA:32
	MOS	26-Jun-23							
	HRS	7882.3	1500		9382.3		463.7		
	AFL	4203							
PROC. REF: AMM 32-21-00-220-804PROC. REF: AMM 32-21-00-220-804									
32-33-01-900-801-01	NLG RETRACTION ACTUATOR								Component ATA:32
PN:GW412-1050-3	MOS/MSC	02-Jun-15	H/T	TSN 116, TSR 0					
SN:DCL117/05	HRS	4228.4		TSN 4228.4, TSR 0					
WC#: 32.480	AFL	2192		TSN 2192, TSR 0					
PROC. REF: AMM 32-33-01-000-801, AMM 32-33-01-400-801PROC. REF: AMM 32-33-01-000-801, AMM 32-33-01-400-801									
32-33-01-900-802-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: CMM 32-30-25PROC. REF: CMM 32-30-25									
32-33-01-900-803-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR PISTON								Component ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-33-01-900-804-01 NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-01-900-805-01 NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-01-900-811-01 NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-05-106 DISCARD THE NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY,PART NO. 22600-101/-103 (AWL*)								Service	ATA:32
PN:GW415-2100-3	MOS							LIFE LIMIT	
SN:NGL/0174/04	HRS	0							
	AFL	0	25000		25000		20293		
PROC. REF: AMM 32-33-05-961-801PROC. REF: AMM 32-33-05-961-801									
32-33-05-900-801-01 NLG UPLOCK								Component	ATA:32
PN:GW415-2100-3	MOS/MSC	07-Oct-05	H/T	TSN 0					
SN:NGL/0174/04	HRS	0		TSN 0					
WC#: 32.485	AFL	0		TSN 0					
PROC. REF: AMM 32-33-05-000-801, AMM 32-33-05-400-801PROC. REF: AMM 32-33-05-000-801, AMM 32-33-05-400-801									
32-33-05-900-803-01 NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY HOOK								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-33-05-900-804-01 NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY LOCK LEVER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-05-900-805-01 NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY STOP PIN								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-09-900-801-01 NLG FWD DOOR ACTUATOR								Component	ATA:32
PN:GW415-2350-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL0117/04	HRS	0		TSN 0					
WC#: 32.490	AFL	0		TSN 0					
PROC. REF: CMM 32-30-30, AMM 32-33-09-000-801, AMM 32-33-09-400-801PROC. REF: CMM 32-30-30, AMM 32-33-09-000-801, AMM 32-33-09-400-801									
32-33-09-900-802-01 NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-09-900-803-01 NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-33-13-101 DISCARD THE NOSE-GEAR FORWARD-DOOR UPLOCK, PART NO. GW415-2300-1 (AWL*)								Service	ATA:32
PN:GW415-2300-3	MOS/MSC		N/A						
SN:DCL284/04	HRS	0							
	AFL	0							
PROC. REF: AMM 32-33-13-961-801PROC. REF: AMM 32-33-13-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-33-13-900-801-01	NLG FORWARD DOOR UNLOCK							Component	ATA:32
PN:GW415-2300-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL284/04	HRS	0		TSN 0					
WC#: 32.495	AFL	0		TSN 0					
PROC. REF: CMM 32-30-31, AMM 32-33-13-000-802, AMM 32-33-13-400-802PROC. REF: CMM 32-30-31, AMM 32-33-13-000-802, AMM 32-33-13-400-802									
32-34-00-101	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY EXTENSION (CMR*)							Service	ATA:32
	MOS	21-May-24						AIRWORTHINESS	
	HRS	8251.1	1500		9751.1		832.5		
	AFL	4407							
PROC. REF: AMM 32-34-00-720-801PROC. REF: AMM 32-34-00-720-801									
32-34-00-202 ^S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE NOSE LANDING-GEAR WHEEL-WELL FS202.75 TO FS280.00							Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.160	AFL	4582	450 (+50/-50)						
PROC. REF: AMM 32-34-00-220-801PROC. REF: AMM 32-34-00-220-801									
32-34-00-203 ^S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE FORWARD AVIONICS COMPARTMENT FS202.75 TO FS280.00							Service	ATA:32
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.165	AFL	4582							
PROC. REF: AMM 32-34-00-220-802PROC. REF: AMM 32-34-00-220-802									
32-34-00-204 ^S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MAIN AVIONICS COMPARTMENT FS280.00 TO FS557.00							Service	ATA:32
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.170	AFL	4582							
PROC. REF: AMM 32-34-00-220-803PROC. REF: AMM 32-34-00-220-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-34-00-205 ^S		DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MID-LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.175	AFL	4582							
PROC. REF: AMM 32-34-00-220-804PROC. REF: AMM 32-34-00-220-804									PKG:38
32-34-00-206 ^S		DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY EXTENSION CONTROL PATH IN THE MAIN LANDING-GEAR WHEEL-WELL, FS719.30 TO FS781.00						Service	ATA:32
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 32.180	AFL	4582							
PROC. REF: AMM 32-34-00-220-805PROC. REF: AMM 32-34-00-220-805									PKG:34
32-34-01-900-801-01		MANUAL RELEASE HANDLE						Component	ATA:32
PN:GW415-7100-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0197	HRS	0		TSN 0					
WC#: 32.515	AFL	0		TSN 0					
PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801									
32-34-03-900-801-01		NLG DOOR QUADRANT						Component	ATA:32
PN:GW413-1000-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL163	HRS	0		TSN 0					
WC#: 32.500	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-34-03-900-801-02		MANUAL RELEASE QUADRANT						Component	ATA:32
PN:GW413-3000-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL175	HRS	0		TSN 0					
WC#: 32.520	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-34-03-900-802-01		NOSE LANDING GEAR QUADRANT						Component	ATA:32
PN:GW413-2000-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL176	HRS	0		TSN 0					
WC#: 32.510	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801									
32-34-03-900-803-01 MLG QUADRANT								Component	ATA:32
PN:GW413-7000-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL-184	HRS	0		TSN 0					
WC#: 32.505	AFL	0		TSN 0					
PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801PROC. REF: AMM 32-34-01-000-801, AMM 32-34-01-400-801									
32-34-05-900-801-01 LH SHUTOFF VALVE								Component	ATA:32
PN:GW415-6175-3	MOS/MSC	21-Feb-24	O/C						
SN:415T	HRS	8168.1							
WC#: 32.620	AFL	4354							
PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801									
32-34-05-900-801-02 RH SHUTOFF VALVE								Component	ATA:32
PN:GW415-6175-3	MOS/MSC	21-Feb-24	O/C						
SN:418T	HRS	8168.1							
WC#: 32.620	AFL	4354							
PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801									
32-34-05-900-802-01 HYD S/O DUMP MANUAL RELEASE VALVE								Component	ATA:32
PN:GW415-6101-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL293/04	HRS	0		TSN 0					
WC#: 32.525	AFL	0		TSN 0					
PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801PROC. REF: AMM 32-34-05-000-801, AMM 32-34-05-400-801									
32-34-05-900-802-02 HYDRAULIC DUMP VALVE								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.530	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-34-09-900-801-01 MAIN LANDING GEAR MRS ALTERNATE POWER VALVE								Component	ATA:32
PN:GW415-6051-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL295/04	HRS	0		TSN 0					
WC#: 32.475	AFL	0		TSN 0					
PROC. REF: AMM 32-34-09-000-801, AMM 32-34-09-400-801PROC. REF: AMM 32-34-09-000-801, AMM 32-34-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-34-09-900-801-02 ALTERNATE POWER VALVE								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.535	AFL	0		TSN 0					
PROC. REF: AMM 32-34-09-000-801, AMM 32-34-09-400-801PROC. REF: AMM 32-34-09-000-801, AMM 32-34-09-400-801									
32-40-00-201 ^S FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS								Service	ATA:32
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500 (+50/-50)						
WC#: 32.185	AFL	4570							
PROC. REF: AMM 32-40-00-720-801PROC. REF: AMM 32-40-00-720-801									
32-41-01-201 SPECIAL DETAILED INSPECTION NO. 1 ASSY MLG WHEEL NO.1 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	T/C					MRB	
SN:0903	HRS	8641.1							
	AFL	4580							
PROC. REF: AMM 32-41-01-280-801PROC. REF: AMM 32-41-01-280-801									
32-41-01-201 SPECIAL DETAILED INSPECTION NO. 2 ASSY MLG WHEEL NO.2 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	T/C					MRB	
SN:1450	HRS	8641.1							
	AFL	4580							
PROC. REF: AMM 32-41-01-280-801PROC. REF: AMM 32-41-01-280-801									
32-41-01-201 SPECIAL DETAILED INSPECTION NO. 3 ASSY MLG WHEEL NO.3 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	14-Apr-26	T/C					MRB	
SN:0889	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-41-01-280-801PROC. REF: AMM 32-41-01-280-801									
32-41-01-201 SPECIAL DETAILED INSPECTION NO. 4 ASSY MLG WHEEL NO.4 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	21-Oct-24	T/C					MRB	
SN:0890	HRS	8560.8							
	AFL	4544							
PROC. REF: AMM 32-41-01-280-801PROC. REF: AMM 32-41-01-280-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-41-01-202	DETAILED INSPECTION NO. 1 ASSY MLG WHEEL NO.1 MLG WHEEL ASSY								Service ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	T/C					MRB	
SN:0903	HRS	8641.1							
	AFL	4580							
PROC. REF: AMM 32-41-01-220-801PROC. REF: AMM 32-41-01-220-801									
32-41-01-202	DETAILED INSPECTION NO. 2 ASSY MLG WHEEL NO.2 MLG WHEEL ASSY								Service ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	T/C					MRB	
SN:1450	HRS	8641.1							
	AFL	4580							
PROC. REF: AMM 32-41-01-220-801PROC. REF: AMM 32-41-01-220-801									
32-41-01-202	DETAILED INSPECTION NO. 3 ASSY MLG WHEEL NO.3 MLG WHEEL ASSY								Service ATA:32
PN:3-1599	MOS/MSC	14-Apr-26	T/C					MRB	
SN:0889	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-41-01-220-801PROC. REF: AMM 32-41-01-220-801									
32-41-01-202	DETAILED INSPECTION NO. 4 ASSY MLG WHEEL NO.4 MLG WHEEL ASSY								Service ATA:32
PN:3-1599	MOS/MSC	21-Oct-24	T/C					MRB	
SN:0890	HRS	8560.8							
	AFL	4544							
PROC. REF: AMM 32-41-01-220-801PROC. REF: AMM 32-41-01-220-801									
32-41-01-900-801-01	NO. 1 ASSY MLG WHEEL								Component ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	O/C	TSO 0					
SN:0903	HRS	8641.1		TSO 0					
WC#: 32.540	AFL	4580		TSO 0					
PROC. REF: CMM 32-48-22, CMM 32-48-30PROC. REF: CMM 32-48-22, CMM 32-48-30									
32-41-01-900-801-02	NO. 2 ASSY MLG WHEEL								Component ATA:32
PN:3-1599	MOS/MSC	26-Feb-25	O/C	TSO 2					
SN:1450	HRS	8641.1		TSO 0					
WC#: 32.545	AFL	4580		TSO 0					
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-41-01-900-801-03		NO. 3 ASSY MLG WHEEL						Component	ATA:32
PN:3-1599	MOS/MSC	14-Apr-26	O/C	TSO 0					
SN:0889	HRS	8842.7	TSO 0						
WC#: 32.550	AFL	4672	TSO 0						
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801									
32-41-01-900-801-04		NO. 4 ASSY MLG WHEEL						Component	ATA:32
PN:3-1599	MOS/MSC	21-Oct-24	O/C	TSO 5					
SN:0890	HRS	8560.8	TSO 0						
WC#: 32.555	AFL	4544	TSO 0						
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32-41-01-000-801, AMM 32-41-01-400-801									
32-41-01-900-802-01		NO. 1 MLG TIRE						Component	ATA:32
PN:382K02-1	MOS/MSC	26-Feb-25	O/C	TSN 12					
SN:40120843	HRS	8641.1	TSN 0						
WC#: 32.540	AFL	4580	TSN 0						
PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801									
32-41-01-900-802-02		NO. 2 MLG TIRE						Component	ATA:32
PN:382K02-1	MOS/MSC	26-Feb-25	O/C	TSN 4					
SN:42770847	HRS	8641.1	TSN 0						
WC#: 32.545	AFL	4580	TSN 0						
PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801									
32-41-01-900-802-03		NO. 3 MLG TIRE						Component	ATA:32
PN:382K02-1	MOS/MSC	26-Feb-25	O/C	TSN 9					
SN:41290852	HRS	8641.1	TSN 0						
WC#: 32.550	AFL	4580	TSN 0						
PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801									
32-41-01-900-802-04		NO. 4 MLG TIRE						Component	ATA:32
PN:382K02-1	MOS/MSC	21-Oct-24	O/C	TSN 8					
SN:40120846	HRS	8560.8	TSN 0						
WC#: 32.555	AFL	4544	TSN 0						
PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801PROC. REF: AMM 32-41-01-000-801, AMM 32-41-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-42-01-201	SPECIAL DETAILED INSPECTION LH ASSY NLG WHEEL LH NLG WHEEL ASSY								Service ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	T/C					MRB	
SN:1159	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-42-01-280-801PROC. REF: AMM 32-42-01-280-801									
32-42-01-201	SPECIAL DETAILED INSPECTION RH ASSY NLG WHEEL RH NLG WHEEL ASSY								Service ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	T/C					MRB	
SN:2253	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-42-01-280-801PROC. REF: AMM 32-42-01-280-801									
32-42-01-202	DETAILED INSPECTION LH ASSY NLG WHEEL LH NLG WHEEL ASSY								Service ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	T/C					MRB	
SN:1159	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-42-01-220-801PROC. REF: AMM 32-42-01-220-801									
32-42-01-202	DETAILED INSPECTION RH ASSY NLG WHEEL RH NLG WHEEL ASSY								Service ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	T/C					MRB	
SN:2253	HRS	8842.7							
	AFL	4672							
PROC. REF: AMM 32-42-01-220-801PROC. REF: AMM 32-42-01-220-801									
32-42-01-900-801-01	LH ASSY NLG WHEEL								Component ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	O/C	TSO 0					
SN:1159	HRS	8842.7		TSO 0					
WC#: 32.560	AFL	4672		TSO 0					
PROC. REF: CMM 32-48-23, AMM 32-42-01-000-801, AMM 32-42-01-400-801PROC. REF: CMM 32-48-23, AMM 32-42-01-000-801, AMM 32-42-01-400-801									
32-42-01-900-801-02	RH ASSY NLG WHEEL								Component ATA:32
PN:3-1560	MOS/MSC	14-Apr-26	O/C	TSO 0					
SN:2253	HRS	8842.7		TSO 0					
WC#: 32.565	AFL	4672		TSO 0					
PROC. REF: CMM 32-48-23, AMM 32-42-01-000-801, AMM 32-42-01-400-801PROC. REF: CMM 32-48-23, AMM 32-42-01-000-801, AMM 32-42-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-42-01-900-802-01	LH NLG TIRE								Component ATA:32
PN:217K22-1	MOS/MSC	25-Mar-24	O/C	TSN 7					
SN:32120682	HRS	8200.3		TSN 0					
WC#: 32.560	AFL	4373		TSN 0					
PROC. REF: AMM 32-42-01-000-801, AMM 32-42-01-400-801PROC. REF: AMM 32-42-01-000-801, AMM 32-42-01-400-801									
32-42-01-900-802-02	RH NLG TIRE								Component ATA:32
PN:217K22-1	MOS/MSC	25-Mar-24	O/C	TSN 7					
SN:32130599	HRS	8200.3		TSN 0					
WC#: 32.565	AFL	4373		TSN 0					
PROC. REF: AMM 32-42-01-000-801, AMM 32-42-01-400-801PROC. REF: AMM 32-42-01-000-801, AMM 32-42-01-400-801									
32-43-00-201	DETAILED INSPECTION OF THE BRAKE WEAR INDICATORS								Service ATA:32
	MOS/MSC	26-May-22	O/C						
	HRS	7483							
WC#: 32.200	AFL	3957							
PROC. REF: AMM 32-43-00-220-801PROC. REF: AMM 32-43-00-220-801									
32-43-00-900-801-01	AUTOBRAKE SWITCH								Component ATA:32
PN:GW415-7350-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:178	HRS	0		TSN 0					
WC#: 32.645	AFL	0		TSN 0					
PROC. REF: AMM 32-43-47-000-801, AMM 32-43-47-400-801PROC. REF: AMM 32-43-47-000-801, AMM 32-43-47-400-801									
32-43-01-900-801-01	BRAKE CONTROL UNIT								Component ATA:32
PN:GW415-7125-5	MOS/MSC	11-Apr-18	O/C	TSR 1					
SN:164	HRS	5904.4		TSR 0					
WC#: 32.570	AFL	3032		TSR 0					
PROC. REF: AMM 32-43-01-000-801, AMM 32-43-01-400-801PROC. REF: AMM 32-43-01-000-801, AMM 32-43-01-400-801									
32-43-05-900-801-01	LEFT NO.1 POSITION BRAKE PEDAL TRANSDUCER								Component ATA:32
PN:GW415-7400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1944	HRS	0		TSN 0					
WC#: 32.575	AFL	0		TSN 0					
PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-05-900-801-02 LEFT NO.2 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:GW415-7400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1942	HRS	0		TSN 0					
WC#: 32.575	AFL	0		TSN 0					
PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801									
32-43-05-900-801-03 RIGHT NO. 1 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:GW415-7400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1962	HRS	0		TSN 0					
WC#: 32.580	AFL	0		TSN 0					
PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801									
32-43-05-900-801-04 RIGHT NO. 2 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:GW415-7400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1963	HRS	0		TSN 0					
WC#: 32.580	AFL	0		TSN 0					
PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801PROC. REF: AMM 32-43-05-000-801, AMM 32-43-05-400-801									
32-43-07-201 ^S VISUAL CHECK OF THE BRAKE-PEDAL RETURN SPRING								Service	ATA:32
	MOS	01-Jun-24						MRB	
	HRS	8251.3	750 (+50/-50)						
WC#: 32.205	AFL	4407							
PROC. REF: AMM 32-43-07-210-801PROC. REF: AMM 32-43-07-210-801									
32-43-09-900-801-01 LEFT FORWARD BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:848	HRS	0		TSN 0					
WC#: 32.585	AFL	0		TSN 0					
PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801									
32-43-09-900-801-02 RIGHT FORWARD BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	10-Sep-24	O/C	TSN 0					
SN:4742	HRS	8487		TSN 0					
WC#: 32.585	AFL	4503		TSN 0					
PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-09-900-801-03		LEFT AFT BRAKE CONTROL VALVE						Component	ATA:32
PN:GW415-6150-1	MOS/MSC	14-Sep-14	O/C	TSO 0					
SN:1844	HRS	3886.1	TSN 1178.1, TSO 0						
WC#: 32.590	AFL	2021	TSN 374, TSO 0						
PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801									
32-43-09-900-801-04		RIGHT AFT BRAKE CONTROL VALVE						Component	ATA:32
PN:GW415-6150-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:865	HRS	0	TSN 0						
WC#: 32.590	AFL	0	TSN 0						
PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801PROC. REF: AMM 32-43-09-000-801, AMM 32-43-09-400-801									
32-43-13-201 ^S		FUNCTIONAL TEST OF THE BRAKE DISK FOR DRIVE SLOT ENLARGEMENT						Service	ATA:32
	MOS	14-Aug-25	30 (+3m/-3m)	MRB					
	HRS	8645							
	AFL	4582							
PKG:32									
PROC. REF: AMM 32-43-13-720-801PROC. REF: AMM 32-43-13-720-801									
32-43-13-301 ^S		RESTORATION (REPLATING) OF THE BRAKE ASSEMBLY - TORQUE TUBE						Service	ATA:32
	MOS	14-Aug-25	60 (+3m/-3m)	OPTIONAL					
	HRS	8645							
	AFL	4582							
PKG:34									
PROC. REF: AMM 32-43-13-840-801PROC. REF: AMM 32-43-13-840-801									
32-43-13-900-801-01		NO. 1 MLG BRAKE						Component	ATA:32
PN:GW313-2001-3	MOS/MSC	28-Aug-18	O/C	TSO 1					
SN:0704	HRS	6128.2	TSO 0						
WC#: 32.595	AFL	3145	TSO 0						
PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801									
32-43-13-900-801-02		NO. 2 MLG BRAKE						Component	ATA:32
PN:GW313-2001-3	MOS/MSC	27-Nov-19	O/C	TSO 1					
SN:2015	HRS	6749.5	TSO 0						
WC#: 32.595	AFL	3486	TSO 0						
PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty						
ATA 32 - LANDING GEAR															
32-43-13-900-801-03		NO. 3 MLG BRAKE						Component	ATA:32						
PN:GW313-2001-3	MOS/MSC	14-Jun-21	O/C	TSO 2											
SN:0290	HRS	7123.8	TSO 0												
WC#: 32.595	AFL	3741	TSO 0												
PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801															
32-43-13-900-801-04		NO. 4 MLG BRAKE						Component	ATA:32						
PN:GW313-2001-3	MOS/MSC	14-Jan-20	O/C	TSO 1											
SN:1784	HRS	6793.6	TSO 0												
WC#: 32.595	AFL	3511	TSO 0												
PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801PROC. REF: CMM 32-48-21, AMM 32-43-13-000-801, AMM 32-43-13-400-801															
32-43-17-900-801-01		LEFT FORWARD BRAKE PRESSURE TRANSDUCER						Component	ATA:32						
PN:GW415-1350-3	MOS/MSC	30-Apr-08	O/C												
SN:6265-10A-185	HRS	658.8													
WC#: 32.600	AFL	394													
PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801															
32-43-17-900-801-02		RIGHT FORWARD BRAKE PRESSURE TRANSDUCER						Component	ATA:32						
PN:GW415-1350-3	MOS/MSC	30-Apr-08	O/C												
SN:6265-10A-187	HRS	658.8													
WC#: 32.600	AFL	394													
PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801															
32-43-17-900-801-03		LEFT AFT BRAKE PRESSURE TRANSDUCER						Component	ATA:32						
PN:GW415-1350-3	MOS/MSC	30-Apr-08	O/C												
SN:6265-10A-183	HRS	658.8													
WC#: 32.605	AFL	394													
PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801															
32-43-17-900-801-04		RIGHT AFT BRAKE PRESSURE TRANSDUCER						Component	ATA:32						
PN:GW415-1350-3	MOS/MSC	30-Apr-08	O/C												
SN:6265-10A-189	HRS	658.8													
WC#: 32.605	AFL	394													
PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801PROC. REF: AMM 32-43-17-000-801, AMM 32-43-17-400-801															

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-21-900-801-01		LOB SHUTTLE VALVE						Component	ATA:32
PN:GW415-6200-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:639	HRS	0		TSN 0					
WC#: 32.610	AFL	0		TSN 0					
PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801									
32-43-21-900-801-02		LIB SHUTTLE VALVE						Component	ATA:32
PN:GW415-6200-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:643	HRS	0		TSN 0					
WC#: 32.610	AFL	0		TSN 0					
PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801									
32-43-21-900-801-03		RIB SHUTTLE VALVE						Component	ATA:32
PN:GW415-6200-1	MOS/MSC	13-Oct-22	O/C	TSO 5					
SN:3063	HRS	7654		TSN 2029.3, TSO 0					
WC#: 32.615	AFL	4057		TSN 837, TSO 0					
PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801									
32-43-21-900-801-04		ROB SHUTTLE VALVE						Component	ATA:32
PN:GW415-6200-1	MOS/MSC	16-May-13	O/C						
SN:119	HRS	3138.2							
WC#: 32.615	AFL	1658							
PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801PROC. REF: AMM 32-43-21-000-801, AMM 32-43-21-400-801									
32-43-25-101		OPERATIONAL TEST OF THE BRAKE SHUTOFF VALVE (CMR*)						Service	ATA:32
	MOS	12-Nov-24						AIRWORTHINESS	
	HRS	8623.4	500		9123.4		204.8		
	AFL	4570							
PROC. REF: AMM 32-43-25-710-801PROC. REF: AMM 32-43-25-710-801									
32-43-29-900-801-01		CHECK, BRAKE CONTROL VALVE						Component	ATA:32
PN:GW415-6250-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0621	HRS	0		TSN 0					
WC#: 32.470	AFL	0		TSN 0					
PROC. REF: AMM 32-43-29-000-801, AMM 32-43-29-400-801PROC. REF: AMM 32-43-29-000-801, AMM 32-43-29-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-29-900-801-02	NO. 2 SYS PRESSURE CHECK, BRAKE CONTROL VALVE							Component	ATA:32
PN:GW415-6250-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0620	HRS	0		TSN 0					
WC#: 32.625	AFL	0		TSN 0					
PROC. REF: AMM 32-43-29-000-801, AMM 32-43-29-400-801PROC. REF: AMM 32-43-29-000-801, AMM 32-43-29-400-801									
32-43-33-900-801-01	NO. 1 HYDRAULIC FUSE VALVE							Component	ATA:32
PN:GW415-1300-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:742	HRS	0		TSN 0					
WC#: 32.630	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-43-33-900-801-02	NO. 2 HYDRAULIC FUSE VALVE							Component	ATA:32
PN:GW415-1300-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:740	HRS	0		TSN 0					
WC#: 32.630	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-43-33-900-801-03	NO. 3 HYDRAULIC FUSE VALVE							Component	ATA:32
PN:GW415-1300-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:741	HRS	0		TSN 0					
WC#: 32.630	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-43-33-900-801-04	NO. 4 HYDRAULIC FUSE VALVE							Component	ATA:32
PN:GW415-1300-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:755	HRS	0		TSN 0					
WC#: 32.630	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-43-37-101	DISCARD THE NO. 2 BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (AWL*)							Service	ATA:32
PN:GW415-1250-1	MOS	11-Nov-21						LIFE LIMIT	
SN:60185-2612NAE	HRS	7277.1							
	AFL	3821	8366	TAC 5897	6290		1583		
PROC. REF: AMM 32-43-37-961-801PROC. REF: AMM 32-43-37-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-37-900-801-05		NO. 2 BRAKE ACCUMULATOR						Component	ATA:32
PN:GW415-1250-1	MOS/MSC	11-Nov-21	H/T						
SN:60185-2612NAE	HRS	7277.1		TSR 575.5					
WC#: 32.635	AFL	3821		TSN 5897, TSR 365					
PROC. REF: AMM 32-43-37-000-801, AMM 32-43-37-400-801PROC. REF: AMM 32-43-37-000-801, AMM 32-43-37-400-801									
32-43-41-900-801-01		PRESSURE GAUGE AND CHARGING VALVE						Component	ATA:32
PN:GW415-1260-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:4L228	HRS	0		TSN 0					
WC#: 32.640	AFL	0		TSN 0					
PROC. REF: AMM 32-43-41-000-801, AMM 32-43-41-400-801PROC. REF: AMM 32-43-41-000-801, AMM 32-43-41-400-801									
32-43-45-900-801-01		GROUND LIFT/AUTO BRAKE CONTROL PANEL						Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.650	AFL	0		TSN 0					
PROC. REF: AMM 32-43-45-000-801, AMM 32-43-45-400-801PROC. REF: AMM 32-43-45-000-801, AMM 32-43-45-400-801									
32-43-49-900-801-01		NO.2 HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:32
PN:GW415-1400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0386	HRS	0		TSN 0					
WC#: 32.655	AFL	0		TSN 0					
PROC. REF: AMM 32-43-49-000-801, AMM 32-43-49-400-801PROC. REF: AMM 32-43-49-000-801, AMM 32-43-49-400-801									
32-43-51-900-801-01		NO.3 HYDRAULIC SYSTEM PRESSURE SWITCH						Component	ATA:32
PN:GW415-1400-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0421	HRS	0		TSN 0					
WC#: 32.655	AFL	0		TSN 0					
PROC. REF: AMM 32-43-51-000-801, AMM 32-43-51-400-801PROC. REF: AMM 32-43-51-000-801, AMM 32-43-51-400-801									
32-43-53-201		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WHEEL SPEED TRANSDUCERS CONNECTORS						Service	ATA:32
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 32-43-53-210-802PROC. REF: AMM 32-43-53-210-802									
									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-43-53-900-801-01		NO. 1 MLG WHEEL SPEED TRANSDUCER						Component	ATA:32
PN:GW415-1050-9	MOS/MSC	06-Feb-15	O/C	TSN 0					
SN:3189	HRS	4132.3		TSN 0					
WC#: 32.660	AFL	2144		TSN 0					
PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801									
32-43-53-900-801-02		NO. 2 MLG WHEEL SPEED TRANSDUCER						Component	ATA:32
PN:GW415-1050-9	MOS/MSC	06-Feb-15	O/C	TSN 0					
SN:3190	HRS	4132.3		TSN 0					
WC#: 32.660	AFL	2144		TSN 0					
PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801									
32-43-53-900-801-03		NO. 3 MLG WHEEL SPEED TRANSDUCER						Component	ATA:32
PN:GW415-1050-9	MOS/MSC	06-Feb-15	O/C	TSN 0					
SN:3195	HRS	4132.3		TSN 0					
WC#: 32.660	AFL	2144		TSN 0					
PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801									
32-43-53-900-801-04		NO. 4 MLG WHEEL SPEED TRANSDUCER						Component	ATA:32
PN:GW415-1050-9	MOS/MSC	14-Aug-25	O/C	TSO 0					
SN:3284	HRS	8645		TSO 0					
WC#: 32.660	AFL	4582		TSO 0					
PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801PROC. REF: AMM 32-43-53-000-801, AMM 32-43-53-400-801									
32-44-01-900-801-01		PARKING BRAKE VALVE						Component	ATA:32
PN:GW415-6225-5	MOS/MSC	16-May-13	O/C	TSN 7					
SN:0604	HRS	3138.2		TSN 0					
WC#: 32.665	AFL	1658		TSN 0					
PROC. REF: AMM 32-44-01-000-801, AMM 32-44-01-400-801PROC. REF: AMM 32-44-01-000-801, AMM 32-44-01-400-801									
32-44-05-101		DISCARD THE NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1/-3 (AWL*)						Service	ATA:32
PN:GW415-1200-3	MOS	11-Nov-21						LIFE LIMIT	
SN:60188-2234NAE	HRS	7277.1							
	AFL	3821	5816	TAC 3085	6552		1845		
PROC. REF: AMM 32-44-05-961-801PROC. REF: AMM 32-44-05-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-44-05-900-801-01 NO. 3 BRAKE ACCUMULATOR								Component	ATA:32
PN:GW415-1200-3	MOS/MSC	11-Nov-21	H/T						
SN:60188-2234NAE	HRS	7277.1							
WC#: 32.670	AFL	3821		TSN 3085					
PROC. REF: AMM 32-44-05-000-801, AMM 32-44-05-400-801PROC. REF: AMM 32-44-05-000-801, AMM 32-44-05-400-801									
32-44-09-900-801-01 PARKING BRAKE HANDLE								Component	ATA:32
PN:GW415-6500-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0199	HRS	0		TSN 0					
WC#: 32.675	AFL	0		TSN 0					
PROC. REF: AMM 32-44-09-000-801, AMM 32-44-09-400-801PROC. REF: AMM 32-44-09-000-801, AMM 32-44-09-400-801									
32-51-01-900-801-01 STEERING CONTROL UNIT								Component	ATA:32
PN:GW415-8100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:04-186	HRS	0		TSN 0					
WC#: 32.680	AFL	0		TSN 0					
PROC. REF: AMM 32-51-01-000-801, AMM 32-51-01-400-801PROC. REF: AMM 32-51-01-000-801, AMM 32-51-01-400-801									
32-51-05-900-801-01 STEERING CONTROL HANDWHEEL								Component	ATA:32
PN:GW415-7200-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DCL290/05	HRS	0		TSN 0					
WC#: 32.690	AFL	0		TSN 0					
PROC. REF: CMM 32-50-18, AMM 32-51-05-000-801, AMM 32-51-05-400-801PROC. REF: CMM 32-50-18, AMM 32-51-05-000-801, AMM 32-51-05-400-801									
32-51-09-900-801-01 LH RUDDER CONTROL RVDT								Component	ATA:32
PN:GW415-7260-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1157	HRS	0		TSN 0					
WC#: 32.695	AFL	0		TSN 0					
PROC. REF: AMM 32-51-09-000-801, AMM 32-51-09-400-801PROC. REF: AMM 32-51-09-000-801, AMM 32-51-09-400-801									
32-51-09-900-801-02 RH RUDDER CONTROL RVDT								Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.695	AFL	0		TSN 0					
PROC. REF: AMM 32-51-09-000-801, AMM 32-51-09-400-801PROC. REF: AMM 32-51-09-000-801, AMM 32-51-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
32-51-13-900-801-01		STEERING SOLENOID VALVE							Component	ATA:32
PN:GW415-6275-3	MOS/MSC	31-Jan-24	O/C	TSR 1						
SN:320	HRS	8150.7	TSR 0							
WC#: 32.700	AFL	4342	TSR 0							
PROC. REF: AMM 32-51-13-000-801, AMM 32-51-13-400-801PROC. REF: AMM 32-51-13-000-801, AMM 32-51-13-400-801										
32-51-17-900-801-01		NOSE STEERING MANIFOLD							Component	ATA:32
PN:1289A0000-01	MOS/MSC	18-Dec-17	O/C	TSR 0						
SN:00198	HRS	5716.4	TSN 3444.1, TSR 0							
WC#: 32.705	AFL	2942	TSN 1144, TSR 0							
PROC. REF: AMM 32-51-17-000-801, AMM 32-51-17-400-801PROC. REF: AMM 32-51-17-000-801, AMM 32-51-17-400-801										
32-51-21-900-801-01		NOSE LANDING GEAR (NLG) SHOCK STRUT STEERING ACTUATOR BOLT							Component	ATA:32
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
32-51-21-900-802-01		LH SWIVEL, STEERING ACTUATOR MANIFOLD							Component	ATA:32
PN:1285A0100-03	MOS/MSC	11-May-15	O/C							
SN:00240	HRS	4228.4	TSN 4221.5							
WC#: 32.710	AFL	2192	TSN 2188							
PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801										
32-51-21-900-802-02		RH SWIVEL, STEERING ACTUATOR MANIFOLD							Component	ATA:32
PN:1285A0300-03	MOS/MSC	11-May-15	O/C							
SN:00212	HRS	4228.4	TSN 4221.5							
WC#: 32.710	AFL	2192	TSN 2188							
PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801										
32-51-21-900-803-01		LH STEERING ACTUATOR							Component	ATA:32
PN:1287A0000-04	MOS/MSC	20-Oct-19	O/C	TSR 1						
SN:1287A00LI002156	HRS	6699.3	TSN 2150.9, TSR 0							
WC#: 32.715	AFL	3452	TSN 954, TSR 0							
PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-51-21-900-803-02	RH STEERING ACTUATOR							Component	ATA:32
PN:1288A000-03	MOS/MSC	11-Jun-19	O/C	TSN 0					
SN:03451	HRS	6506.9		TSN 0					
WC#: 32.715	AFL	3366		TSN 0					
PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801PROC. REF: AMM 32-51-21-000-801, AMM 32-51-21-400-801									
32-51-29-900-801-01	PRESSURE STEERING CONTROL SWITCH							Component	ATA:32
PN:GW415-1500-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:C024020	HRS	0		TSN 0					
WC#: 32.685	AFL	0		TSN 0					
PROC. REF: AMM 32-51-29-000-801, AMM 32-51-29-400-801PROC. REF: AMM 32-51-29-000-801, AMM 32-51-29-400-801									
32-51-33-900-801-01	HYDRAULIC COMPENSATOR							Component	ATA:32
PN:GW415-1450-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:CEP-0019	HRS	0		TSN 0					
WC#: 32.720	AFL	0		TSN 0					
PROC. REF: AMM 32-51-33-000-801, AMM 32-51-33-400-801PROC. REF: AMM 32-51-33-000-801, AMM 32-51-33-400-801									
32-60-00-201 ^S	VISUAL CHECK OF THE LANDING GEAR POSITION AND WARNING SYSTEM							Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 32.215	AFL	4582							
PROC. REF: AMM 32-60-00-210-801PROC. REF: AMM 32-60-00-210-801									
32-ZL-00-201 ^S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY							Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.220	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-801									
32-ZL-00-202 ^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - LH							Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.225	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-10-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-10-00-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-ZL-00-203	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - RH						Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.230	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-10-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-10-00-210-801									PKG:58
32-ZL-00-204	^S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - LH						Service	ATA:32
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC#: 32.235	AFL	4124	900 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802									PKG:60
32-ZL-00-205	^S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - RH						Service	ATA:32
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC#: 32.240	AFL	4124	900 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802									PKG:60
32-ZL-00-206	^S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - AFT						Service	ATA:32
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC#: 32.245	AFL	4124	900 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 32-20-00-210-802									PKG:60
32-ZL-00-207	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - LH						Service	ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.250	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-12-05-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-12-05-210-801									PKG:58

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-ZL-00-208	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - RH							Service ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.255	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-12-05-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-12-05-210-801									
32-ZL-00-209	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - LH							Service ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.260	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-12-01-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-12-01-210-801									
32-ZL-00-210	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - RH							Service ATA:32
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC#: 32.265	AFL	4582	450 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 32-12-01-210-801PROC. REF: SPM 20-70-00-210-801, AMM 32-12-01-210-801									
322107-007-01	^U	NLG PINTLE PIN							Component ATA:32
PN:1285-0006	MOS/MSC	11-May-15	O/C						
SN:1039155/001	HRS	4228.4		TSN 4221.5					
	AFL	2192		TSN 2188					
ATA 33 - LIGHTS									
33-00-00-201		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING TIP LIGHTS AND COMPONENTS CONNECTORS AND GROUND STUDS							Service ATA:33
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 33-00-00-210-801PROC. REF: AMM 33-00-00-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-11-01-900-801-01		LEFT 7.5A CONVERTER						Component	ATA:33
PN:GC531-0001-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0570	HRS	0		TSN 0					
WC#: 33.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
33-11-01-900-801-02		RIGHT FORWARD 7.5A CONVERTER						Component	ATA:33
PN:GC531-0001-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0572	HRS	0		TSN 0					
WC#: 33.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
33-11-01-900-801-03		RIGHT AFT 7.5A CONVERTER						Component	ATA:33
PN:GC531-0001-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0571	HRS	0		TSN 0					
WC#: 33.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
33-11-01-900-802-01		LH 15A DC/DC CONVERTER						Component	ATA:33
PN:GC531-0002-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0364	HRS	0		TSN 0					
WC#: 33.040	AFL	0		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									
33-11-01-900-802-02		RH 15A DC/DC CONVERTER						Component	ATA:33
PN:GC531-0002-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0366	HRS	0		TSN 0					
WC#: 33.040	AFL	0		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									
33-11-01-900-803-01		LH 0.1A DC/AC INVERTER						Component	ATA:33
PN:GC531-0003-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0403	HRS	0		TSN 0					
WC#: 33.045	AFL	0		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-11-01-900-803-02		RH 0.1A DC/AC INVERTER						Component	ATA:33
PN:GC531-0003-3	MOS/MSC	09-May-19	O/C	TSN 0					
SN:2742	HRS	6472.9		TSN 0					
	AFL	3334		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									
33-11-01-900-803-03		LH 0.5A DC/AC INVERTER						Component	ATA:33
PN:GC531-0004-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0383	HRS	0		TSN 0					
WC#: 33.050	AFL	0		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									
33-11-01-900-803-04		RH 0.5A DC/AC INVERTER						Component	ATA:33
PN:GC531-0004-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0379	HRS	0		TSN 0					
WC#: 33.050	AFL	0		TSN 0					
PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802PROC. REF: AMM 33-11-01-000-802, AMM 33-11-01-400-802									
33-13-05-900-801-01		LH MAP READING LIGHT						Component	ATA:33
PN:2LA005163-25	MOS/MSC	27-Jul-20	O/C	TSN 8					
SN:4853313	HRS	6911.6		TSN 0					
WC#: 33.055	AFL	3586		TSN 0					
PROC. REF: AMM 33-13-05-000-801, AMM 33-13-05-400-801PROC. REF: AMM 33-13-05-000-801, AMM 33-13-05-400-801									
33-13-05-900-801-02		RH MAP READING LIGHT						Component	ATA:33
PN:2LA005163-25	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1043162	HRS	0		TSN 0					
WC#: 33.055	AFL	0		TSN 0					
PROC. REF: AMM 33-13-05-000-801, AMM 33-13-05-400-801PROC. REF: AMM 33-13-05-000-801, AMM 33-13-05-400-801									
33-24-50-601 ^{U S}		OPERATIONAL TEST OF THE ORDINANCE SIGNS						Service	ATA:33
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-31-01-900-801-01 NOSE GEAR BAY/TAIL LIGHT								Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.060	AFL	0		TSN 0					
PROC. REF: AMM 33-31-01-000-801, AMM 33-31-01-400-801PROC. REF: AMM 33-31-01-000-801, AMM 33-31-01-400-801									
33-31-09-900-801-01 APU COMPARTMENT LIGHT								Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.065	AFL	0		TSN 0					
PROC. REF: AMM 33-31-09-000-801, AMM 33-31-09-400-801PROC. REF: AMM 33-31-09-000-801, AMM 33-31-09-400-801									
33-31-13-900-801-01 NO. 1 MAIN LIGHT								Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801									
33-31-13-900-801-02 NO. 2 MAIN LIGHT								Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801									
33-31-13-900-801-03 NO. 3 MAIN LIGHT								Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801PROC. REF: AMM 33-31-13-000-801, AMM 33-31-13-400-801									
33-31-17-900-801-01 LH FS381 AUTO SHUT-OFF BOX								Component	ATA:33
PN:GE534-0001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1060426	HRS	0		TSN 0					
WC#: 33.075	AFL	0		TSN 0					
PROC. REF: AMM 33-31-17-000-801, AMM 33-31-17-400-801PROC. REF: AMM 33-31-17-000-801, AMM 33-31-17-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-31-17-900-801-02		LH FS909 AUTO SHUT-OFF BOX						Component	ATA:33
PN:GE534-0001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1050107	HRS	0		TSN 0					
WC#: 33.080	AFL	0		TSN 0					
PROC. REF: AMM 33-31-17-000-801, AMM 33-31-17-400-801PROC. REF: AMM 33-31-17-000-801, AMM 33-31-17-400-801									
33-31-17-900-801-03		RH DVC AUTO SHUT-OFF LIGHT						Component	ATA:33
PN:GE534-0001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1057647	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
33-41-01-201		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING LANDING AND TAXI LIGHTS CONNECTORS						Service	ATA:33
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 33-41-01-210-801PROC. REF: AMM 33-41-01-210-801									
33-41-01-900-801-01		LH LANDING LIGHT LENS						Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.085	AFL	0		TSN 0					
PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801									
33-41-01-900-801-02		RH LANDING LIGHT LENS						Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.085	AFL	0		TSN 0					
PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801									
33-41-01-900-802-01		LH WING LANDING/TAXI LIGHT						Component	ATA:33
PN:GE536-0003-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1066109	HRS	0		TSN 0					
WC#: 33.090	AFL	0		TSN 0					
PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-41-01-900-802-02 RH WING LANDING/TAXI LIGHT								Component	ATA:33
PN:1X4455177-50	MOS/MSC	08-Nov-19	O/C	TSN 11					
SN:4449750	HRS	6716.3		TSN 0					
WC#: 33.090	AFL	3465		TSN 0					
PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801PROC. REF: AMM 33-41-01-000-801, AMM 33-41-01-400-801									
33-41-05-900-801-01 LH NLG LIGHT								Component	ATA:33
PN:2LA409800-05	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:432	HRS	0		TSN 0					
WC#: 33.095	AFL	0		TSN 0					
PROC. REF: AMM 33-41-05-000-801, AMM 33-41-05-400-801PROC. REF: AMM 33-41-05-000-801, AMM 33-41-05-400-801									
33-41-05-900-801-02 RH NLG LIGHT								Component	ATA:33
PN:2LA409800-05	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:455	HRS	0		TSN 0					
WC#: 33.095	AFL	0		TSN 0					
PROC. REF: AMM 33-41-05-000-801, AMM 33-41-05-400-801PROC. REF: AMM 33-41-05-000-801, AMM 33-41-05-400-801									
33-42-01-900-801-01 LH WING NAVIGATION (RED) LIGHT								Component	ATA:33
PN:2LA007181-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1035112	HRS	0		TSN 0					
WC#: 33.105	AFL	0		TSN 0					
PROC. REF: AMM 33-42-01-000-801, AMM 33-42-01-400-801PROC. REF: AMM 33-42-01-000-801, AMM 33-42-01-400-801									
33-42-01-900-801-02 RH WING NAVIGATION (GREEN) LIGHT								Component	ATA:33
PN:2LA007182-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1035083	HRS	0		TSN 0					
WC#: 33.100	AFL	0		TSN 0					
PROC. REF: AMM 33-42-01-000-801, AMM 33-42-01-400-801PROC. REF: AMM 33-42-01-000-801, AMM 33-42-01-400-801									
33-42-09-900-801-01 NOSE GEAR BAY/TAIL LIGHT								Component	ATA:33
PN:2LA006419-22	MOS/MSC	17-Jun-13	O/C						
SN:1696982	HRS	3170.7							
WC#: 33.110	AFL	1678							
PROC. REF: AMM 33-42-09-000-801, AMM 33-42-09-400-801PROC. REF: AMM 33-42-09-000-801, AMM 33-42-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-42-13-900-801-01		FAILURE IND (MID CENTER FUSE) BOX						Component	ATA:33
PN:GE536-0001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1042418	HRS	0		TSN 0					
WC#: 33.115	AFL	0		TSN 0					
PROC. REF: AMM 33-42-13-000-801, AMM 33-42-13-400-801PROC. REF: AMM 33-42-13-000-801, AMM 33-42-13-400-801									
33-43-01-900-801-01		LH STROBE WING LIGHT						Component	ATA:33
PN:2LA006178-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1040028	HRS	0		TSN 0					
WC#: 33.120	AFL	0		TSN 0					
PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801									
33-43-01-900-801-02		RH STROBE WING LIGHT						Component	ATA:33
PN:2LA006178-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1040029	HRS	0		TSN 0					
WC#: 33.120	AFL	0		TSN 0					
PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801									
33-43-01-900-801-03		STROBE WING LIGHT						Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.125	AFL	0		TSN 0					
PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801PROC. REF: AMM 33-43-01-000-801, AMM 33-43-01-400-801									
33-43-05-900-801-01		STROBE (TAIL) LIGHT						Component	ATA:33
PN:2LA006181-22	MOS/MSC	20-May-08	O/C	TSN 3					
SN:1143338	HRS	701.8		TSN 0					
WC#: 33.130	AFL	408		TSN 0					
PROC. REF: AMM 33-43-05-000-801, AMM 33-43-05-400-801PROC. REF: AMM 33-43-05-000-801, AMM 33-43-05-400-801									
33-43-09-201		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE LOWER STROBE/ANTICOLLISION LIGHT CONNECTOR						Service	ATA:33
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 33-43-09-210-801PROC. REF: AMM 33-43-09-210-801									
									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-43-09-900-801-01 UPPER STROBE, ANTICOLLISION FUSELAGE LIGHT								Component	ATA:33
PN:2LA003849-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1043826	HRS	0		TSN 0					
WC#: 33.135	AFL	0		TSN 0					
PROC. REF: AMM 33-43-09-400-801, AMM 33-43-09-000-801PROC. REF: AMM 33-43-09-400-801, AMM 33-43-09-000-801									
33-43-09-900-801-02 LOWER STROBE, ANTICOLLISION FUSELAGE LIGHT								Component	ATA:33
PN:2LA003849-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1053013	HRS	0		TSN 0					
WC#: 33.135	AFL	0		TSN 0					
PROC. REF: AMM 33-43-09-400-801, AMM 33-43-09-000-801PROC. REF: AMM 33-43-09-400-801, AMM 33-43-09-000-801									
33-44-01-900-801-01 LH WING/TAIL STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES456038-03	MOS/MSC	08-Jan-11	O/C	TSN 0					
SN:1726679	HRS	1932		TSN 0					
WC#: 33.140	AFL	1047		TSN 0					
PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801									
33-44-01-900-801-02 RH WING/TAIL STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES007046-22	MOS/MSC	24-Dec-07	O/C	TSR 10					
SN:379	HRS	522.7		TSR 0					
WC#: 33.140	AFL	292		TSR 0					
PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801									
33-44-01-900-801-03 TAIL WING/TAIL STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES007046-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1052215	HRS	0		TSN 0					
WC#: 33.145	AFL	0		TSN 0					
PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801PROC. REF: AMM 33-44-01-000-801, AMM 33-44-01-400-801									
33-44-05-900-801-01 UPPER STROBE/ANTICOLLISION LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES006794-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1048336	HRS	0		TSN 0					
WC#: 33.150	AFL	0		TSN 0					
PROC. REF: AMM 33-44-05-000-801, AMM 33-44-05-400-801PROC. REF: AMM 33-44-05-000-801, AMM 33-44-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10

Serial: 9175

RegNo: N117TP

HRS: 8918.6

AFL: 4707

As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-44-05-900-801-02		LOWER STROBE/ANTICOLLISION LIGHT POWER SUPPLY						Component	ATA:33
PN:8ES006794-22	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1058157	HRS	0		TSN 0					
WC#: 33.150	AFL	0		TSN 0					
PROC. REF: AMM 33-44-05-000-801, AMM 33-44-05-400-801PROC. REF: AMM 33-44-05-000-801, AMM 33-44-05-400-801									
33-45-01-900-801-01		LH SCANLITE WING						Component	ATA:33
PN:2LA455188-00	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:113	HRS	0		TSN 0					
WC#: 33.155	AFL	0		TSN 0					
PROC. REF: AMM 33-45-01-000-801, AMM 33-45-01-400-801PROC. REF: AMM 33-45-01-000-801, AMM 33-45-01-400-801									
33-45-01-900-801-02		RH SCANLITE WING						Component	ATA:33
PN:2LA455189-50	MOS/MSC	13-Nov-18	O/C	TSN 2					
SN:4353919	HRS	6189.3		TSN 0					
WC#: 33.155	AFL	3178		TSN 0					
PROC. REF: AMM 33-45-01-000-801, AMM 33-45-01-400-801PROC. REF: AMM 33-45-01-000-801, AMM 33-45-01-400-801									
33-46-01-900-801-01		LH LOGO LIGHT						Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.160	AFL	0		TSN 0					
PROC. REF: AMM 33-46-01-000-801, AMM 33-46-01-400-801PROC. REF: AMM 33-46-01-000-801, AMM 33-46-01-400-801									
33-46-01-900-801-02		RH LOGO LIGHT						Component	ATA:33
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.160	AFL	0		TSN 0					
PROC. REF: AMM 33-46-01-000-801, AMM 33-46-01-400-801PROC. REF: AMM 33-46-01-000-801, AMM 33-46-01-400-801									
33-50-00-201 ^S		FUNCTIONAL TEST OF THE EMERGENCY LIGHTS POWER-SUPPLIES						Service	ATA:33
	MOS	14-Aug-25	15 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 33.015	AFL	4582							
PROC. REF: AMM 33-51-09-720-801PROC. REF: AMM 33-51-09-720-801									
PKG:31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-50-00-202	OPERATIONAL TEST OF THE EMERGENCY LIGHTS								Service ATA:33
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	9695	9745	776.4 (+50)		
WC#: 33.020	AFL	4582							
PROC. REF: AMM 33-51-00-710-801PROC. REF: AMM 33-51-00-710-801									
33-51-01-900-801-01	LH PASSENGER DOOR EMERGENCY LIGHT								Component ATA:33
PN:GE535-0001-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1040532	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-51-01-000-801, AMM 33-51-01-400-801PROC. REF: AMM 33-51-01-000-801, AMM 33-51-01-400-801									
33-51-05-900-801-01	RH OVER-WING EMERGENCY EXIT LIGHT (FS661)								Component ATA:33
PN:2LA455200-02	MOS/MSC	15-Jun-17	O/C	TSN 6					
SN:3717703	HRS	5428.8		TSN 0					
	AFL	2792		TSN 0					
PROC. REF: AMM 33-51-05-000-801, AMM 33-51-05-400-801PROC. REF: AMM 33-51-05-000-801, AMM 33-51-05-400-801									
33-51-05-900-801-02	RH OVER-WING EMERGENCY EXIT LIGHT (FS805)								Component ATA:33
PN:GE535-0001-5	MOS/MSC	15-Jun-17	O/C	TSN 6					
SN:3706851	HRS	5428.8		TSN 0					
	AFL	2792		TSN 0					
PROC. REF: AMM 33-51-05-000-801, AMM 33-51-05-400-801PROC. REF: AMM 33-51-05-000-801, AMM 33-51-05-400-801									
33-51-09-900-801-01	NO.1 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	14-Aug-25	O/C	TSN 70, TSO 0					
SN:4804802	HRS	8645		TSN 1807.7, TSO 0					
	AFL	4582		TSN 1049, TSO 0					
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801									
33-51-09-900-801-02	NO.2 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	14-Aug-25	O/C	TSN 75, TSO 0					
SN:4623767	HRS	8645		TSN 1807.7, TSO 0					
	AFL	4582		TSN 1049, TSO 0					
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33-51-09-900-801-03	NO.3 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	14-Aug-25	O/C	TSO 0					
SN:4677547	HRS	8645		TSO 0					
	AFL	4582		TSO 0					
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33-51-09-000-801, AMM 33-51-09-400-801									
33-51-09-900-801-04	NO.4 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	14-Aug-25	O/C	TSO 0					
SN:3813	HRS	8645		TSO 0					
	AFL	4582		TSO 0					
PROC. REF: AMM 33-51-09-000-801, AMM 33-51-09-400-801PROC. REF: AMM 33-51-09-000-801, AMM 33-51-09-400-801									
33-51-50-601 ^{U S}	OPERATIONAL TEST OF THE CABIN EMERGENCY LIGHTING SYSTEM								Service ATA:33
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
330011-712 ^U	LH GALLEY OVERHEAD LIGHT ASSY								Component ATA:33
PN:2LA455905-04	MOS/MSC	05-Nov-09	O/C						
SN:1535265	HRS	1347.2							
	AFL	746							
332008-701 ^U	CREW WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	31-Jul-19	O/C	TSN 0					
SN:4432387	HRS	6606.7		TSN 0					
	AFL	3390		TSN 0					
332008-702 ^U	LH FWD WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	04-Nov-09	O/C						
SN:1108629	HRS	1347.2							
	AFL	746							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332008-703 ^U		LIGHTING POWER SUPPLY						Component	ATA:33
PN:8ES455827-00	MOS/MSC	26-Jun-22	O/C	TSN 0					
SN:5281478	HRS	7535.3		TSN 0					
	AFL	3992		TSN 0					
332008-704 ^U		WASH LIGHTNING POWER SUPPLY LEFT AFT PS554						Component	ATA:33
PN:8ES455827-00	MOS/MSC	20-Nov-23	O/C	TSN 21				CUSTOMER CODE	
SN:5390325	HRS	8092.2		TSN 0					
	AFL	4307		TSN 0					
334601-701 ^U		LH LOGO LIGHT						Component	ATA:33
PN:4338327	MOS/MSC	07-Oct-05	O/C						
SN:468	HRS	0							
	AFL	0							
334601-702 ^U		RH LOGO LIGHT						Component	ATA:33
PN:4338327	MOS/MSC	07-Oct-05	O/C						
SN:471	HRS	0							
	AFL	0							
335109-701 ^U		AVIONIC BAY EMERGENCY LIGHT POWER SUPPLY						Component	ATA:33
PN:3400-20	MOS/MSC	20-Jul-09	O/C	TSN 2					
SN:004551	HRS	1216.3		TSN 0					
	AFL	671		TSN 0					
335110-701 ^U		NO. 1 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK						Component	ATA:33
PN:8ES360000-00	MOS/MSC	21-Jan-24	O/C	TSN 13					
SN:21920	HRS			TSN 0					
	AFL			TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
335110-702	U	NO. 2 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK						Component	ATA:33
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
335110-703	U	NO. 3 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK						Component	ATA:33
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
335110-704	U	NO. 4 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK						Component	ATA:33
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
ATA 34 - NAVIGATION									
34-00-00-701	U	RAD ALT BANDPASS FILTER #1						Component	ATA:34
PN:241-1122-020	MOS/MSC	11-Oct-23	O/C					CUSTOMER CODE	
SN:51194	HRS	8051.5							
	AFL	4275							
34-00-00-702	U	RAD ALT BANDPASS FILTER #2						Component	ATA:34
PN:241-1122-020	MOS/MSC	11-Oct-23	O/C					CUSTOMER CODE	
SN:51196	HRS	8051.5							
	AFL	4275							
34-11-00-101		FUNCTIONAL TEST OF THE AIR DATA COMPUTER, (RVSM QUALIFIED A/C) (CMR*)						Service	ATA:34
	MOS	14-Apr-25	24 (+3m/-3m)	Adj 3	14-Jul-27	14-Oct-27	384 d (+92)	CMR	
	HRS								
WC#: 34.005	AFL								
PROC. REF: AMM 34-11-00-720-801PROC. REF: AMM 34-11-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-11-00-202		FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEMS							Service ATA:34
	MOS	14-Apr-25	24 (+3m/-3m)	Adj 3	14-Jul-27	14-Oct-27	384 d (+92)	MRB	
	HRS								
WC#:	34.010	AFL							
PROC. REF: AMM 34-11-00-720-802PROC. REF: AMM 34-11-00-720-802									
34-11-01-201		DETAILED INSPECTION OF THE PITOT-STATIC PROBES							Service ATA:34
	MOS	14-Apr-25	24 (+3m/-3m)	Adj 3	14-Jul-27	14-Oct-27	384 d (+92)	MRB	
	HRS								
WC#:	34.015	AFL							
PROC. REF: AMM 34-11-01-220-801PROC. REF: AMM 34-11-01-220-801									
34-11-01-900-801-01		NO. 1 PITOT STATIC PROBE							Component ATA:34
PN:0856TT1	MOS/MSC	25-Nov-19	H/T	TSN 0					
SN:315421	HRS	6740.2		TSN 0					
WC#:	34.035	AFL	3480	TSN 0					
PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801									
34-11-01-900-801-02		NO. 2 PITOT STATIC PROBE							Component ATA:34
PN:0856TT4	MOS/MSC	30-Mar-23	H/T	TSN 0					
SN:328084	HRS	7780.3		TSN 0					
WC#:	34.035	AFL	4138	TSN 0					
PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801									
34-11-01-900-801-03		NO. 3 PITOT STATIC PROBE							Component ATA:34
PN:0856TT3	MOS/MSC	30-Mar-23	H/T	TSN 0					
SN:328069	HRS	7780.3		TSN 0					
WC#:	34.035	AFL	4138	TSN 0					
PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801									
34-11-01-900-801-04		STANDBY PITOT STATIC PROBE							Component ATA:34
PN:0856TT2	MOS/MSC	14-Aug-25	H/T	TSN 0					
SN:335756	HRS	8645		TSN 0					
WC#:	34.035	AFL	4582	TSN 0					
PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801PROC. REF: CMM 34-10-68, AMM 34-11-01-000-801, AMM 34-11-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-11-03-201	^S	SERVICING OF THE VISUAL DRAINS							Service ATA:34
	MOS	14-Aug-25	15 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 34.020	AFL	4582							
PROC. REF: AMM 34-11-03-616-801PROC. REF: AMM 34-11-03-616-801									
34-11-05-900-801-01		TOTAL TEMPERATURE SENSOR							Component ATA:34
PN:0102AH2AF	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:A57733	HRS	0		TSN 0					
WC#: 34.040	AFL	0		TSN 0					
PROC. REF: AMM 34-11-05-000-801, AMM 34-11-05-400-801PROC. REF: AMM 34-11-05-000-801, AMM 34-11-05-400-801									
34-11-09-900-801-01		NO. 1 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	16-Apr-19	O/C						
SN:06070842	HRS	6418.9							
WC#: 34.045	AFL	3306							
PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801									
34-11-09-900-801-02		NO. 2 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	01-Apr-24	O/C						
SN:05120767	HRS	8207.3							
WC#: 34.045	AFL	4380							
PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801									
34-11-09-900-801-03		NO. 3 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	01-Apr-24	O/C						
SN:05110709	HRS	8207.3							
WC#: 34.045	AFL	4380							
PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801PROC. REF: AMM 34-11-09-000-801, AMM 34-11-09-400-801									
34-11-CA-200		RECERTIFY NO. 1 MICRO AIR DATA COMPUTER PER 14 CFR 91.411							Service ATA:34
PN:7030700-70708	MOS	14-Apr-25	24		14-Apr-27		293 d	FAA	
SN:06070842	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-11-CA-200		RECERTIFY NO. 2 MICRO AIR DATA COMPUTER PER 14 CFR 91.411							Service ATA:34
PN:7030700-70708	MOS	14-Apr-25	24		14-Apr-27		293 d	FAA	
SN:05120767	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-11-CA-200		RECERTIFY NO. 3 MICRO AIR DATA COMPUTER PER 14 CFR 91.411							Service ATA:34
PN:7030700-70708	MOS	14-Apr-25	24		14-Apr-27		293 d	FAA	
SN:05110709	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-12-01-201		FUNCTIONAL TEST OF THE STANDBY AIRSPEED/ALTIMETER INDICATOR (A/C 9002 TO 9157)							Service ATA:34
	MOS/MSC		N/A						
	HRS	0							
WC#: 34.025	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-12-03-900-801-01		INTEGRATED STANDBY INDICATOR							Component ATA:34
PN:C16221RA01	MOS/MSC	10-Jun-13	O/C	TSR 2					
SN:C16221010795	HRS	3168.9		TSR 0					
WC#: 34.050	AFL	1671		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-13-00-101		DISCARD OF THE NO. 1 PITOT-STATIC PROBES, (RVSM QUALIFIEDA/C) (AWL*)							Service ATA:34
PN:0856TT1	MOS	25-Nov-19						LIFE LIMIT	
SN:315421	HRS	6740.2	9600		16340.2		7421.6		
	AFL	3480							
PROC. REF: AMM 34-11-01-961-801PROC. REF: AMM 34-11-01-961-801									
34-13-00-101		DISCARD THE NO. 2 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY) (AWL*)							Service ATA:34
PN:0856TT4	MOS	30-Mar-23						LIFE LIMIT	
SN:328084	HRS	7780.3	9600		17380.3		8461.7		
	AFL	4138							
PROC. REF: AMM 34-11-01-961-801PROC. REF: AMM 34-11-01-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-13-00-101	DISCARD THE NO. 3 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY) (AWL*)								Service ATA:34
PN:0856TT3	MOS	30-Mar-23						LIFE LIMIT	
SN:328069	HRS	7780.3	9600		17380.3		8461.7		
	AFL	4138							
PROC. REF: AMM 34-11-01-961-801PROC. REF: AMM 34-11-01-961-801									
34-13-00-101	DISCARD THE PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY) (AWL*)								Service ATA:34
PN:0856TT2	MOS	14-Aug-25						LIFE LIMIT	
SN:335756	HRS	8645	9600		18245		9326.4		
	AFL	4582							
PROC. REF: AMM 34-11-01-961-801PROC. REF: AMM 34-11-01-961-801									
34-13-00-201	FUNCTIONAL TEST OF THE INTEGRATED ELECTRONIC STANDBY INSTRUMENT (A/C 9158 AND SUBS)								Service ATA:34
	MOS	14-Apr-25	24 (+3m/-3m)	Adj 3	14-Jul-27	14-Oct-27	384 d (+92)	MRB	
	HRS								
	AFL								
PROC. REF: AMM 34-12-03-720-801PROC. REF: AMM 34-12-03-720-801									
34-21-01-900-801-01	STANDBY ATTITUDE HORIZON INDICATOR								Component ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-22-01-900-801-01	STANDBY COMPASS								Component ATA:34
PN:WL1001KCA1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:AT4901104	HRS	0		TSN 0					
WC#: 34.060	AFL	0		TSN 0					
PROC. REF: AMM 34-22-01-000-801, AMM 34-22-01-400-801PROC. REF: AMM 34-22-01-000-801, AMM 34-22-01-400-801									
34-32-00-201 ^S	DETAILED INSPECTION OF THE ELECTRO-OPTICAL UNIT HYGROMETER SENSOR (IF HUDS INSTALLED)								Service ATA:34
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 34.030	AFL	4582							
PROC. REF: AMM 34-32-13-220-801PROC. REF: AMM 34-32-13-220-801									

PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-33-03-900-801-01 EVS SYSTEM - INFRARED (ISU) SENSOR UNIT								Component	ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-33-03-000-801, AMM 34-33-03-400-801PROC. REF: AMM 34-33-03-000-801, AMM 34-33-03-400-801									
34-33-06-900-802-01 EVS SYSTEM - INFRARED WINDOW								Component	ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-33-06-000-802, AMM 34-33-06-400-802PROC. REF: AMM 34-33-06-000-802, AMM 34-33-06-400-802									
34-33-09-900-801-01 EVS SYSTEM - HEATER (EVSHC) CONTROLLER								Component	ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-33-09-000-801, AMM 34-33-09-400-801PROC. REF: AMM 34-33-09-000-801, AMM 34-33-09-400-801									
34-41-01-900-801-01 NOSE RADOME RECEIVER/TRANSMITTER ANTENNA								Component	ATA:34
PN:7021450-801	MOS/MSC	06-May-13	O/C	TSR 2					
SN:00112538	HRS	3138.2		TSR 0					
WC#: 34.065	AFL	1658		TSR 0					
PROC. REF: AMM 34-41-01-000-801, AMM 34-41-01-400-801PROC. REF: AMM 34-41-01-000-801, AMM 34-41-01-400-801									
34-41-05-900-801-01 LH WEATHER RADAR CONTROLLER								Component	ATA:34
PN:7008471-415	MOS/MSC	07-Oct-05	O/C						
SN:05028165	HRS	0							
WC#: 34.070	AFL	0							
PROC. REF: AMM 34-41-05-000-801, AMM 34-41-05-400-801PROC. REF: AMM 34-41-05-000-801, AMM 34-41-05-400-801									
34-41-05-900-801-02 RH WEATHER RADAR CONTROLLER								Component	ATA:34
PN:7008471-417	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05018159	HRS	0		TSN 0					
WC#: 34.070	AFL	0		TSN 0					
PROC. REF: AMM 34-41-05-000-801, AMM 34-41-05-400-801PROC. REF: AMM 34-41-05-000-801, AMM 34-41-05-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-42-01-900-801-01 ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER								Component	ATA:34
PN:965-0976-040-218-218	MOS/MSC	14-Feb-24	O/C	TSR 1					
SN:13695	HRS	8164.7		TSR 0					
WC#: 34.075	AFL	4350		TSR 0					
PROC. REF: AMM 34-42-01-000-801, AMM 34-42-01-400-801PROC. REF: AMM 34-42-01-000-801, AMM 34-42-01-400-801									
34-43-01-900-801-01 TCAS PROCESSOR								Component	ATA:34
PN:7517900-10020	MOS/MSC	02-Jun-26	O/C						
SN:20009135	HRS	8887.7							
WC#: 34.080	AFL	4694							
PROC. REF: AMM 34-43-01-000-801, AMM 34-43-01-400-801PROC. REF: AMM 34-43-01-000-801, AMM 34-43-01-400-801									
34-43-05-900-801-01 TCAS LOWER TCAS ANTENNA								Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5840	HRS	0		TSN 0					
WC#: 34.085	AFL	0		TSN 0					
PROC. REF: AMM 34-43-05-000-801, AMM 34-43-05-400-801PROC. REF: AMM 34-43-05-000-801, AMM 34-43-05-400-801									
34-43-09-900-801-01 UPPER DIRECTIONAL TCAS ANTENNA								Component	ATA:34
PN:7514081-914	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ANE21727	HRS	0		TSN 0					
WC#: 34.090	AFL	0		TSN 0					
PROC. REF: AMM 34-43-09-000-801, AMM 34-43-09-400-801PROC. REF: AMM 34-43-09-000-801, AMM 34-43-09-400-801									
34-44-01-900-801-01 NO. 1 RADIO ALTIMETER RECEIVER								Component	ATA:34
PN:822-0615-207	MOS/MSC	08-Feb-26	O/C	TSO 0					
SN:4LHM3	HRS	8870		TSO 0					
WC#: 34.095	AFL	4687		TSO 0					
PROC. REF: AMM 34-44-01-000-801, AMM 34-44-01-400-801PROC. REF: AMM 34-44-01-000-801, AMM 34-44-01-400-801									
34-44-01-900-801-02 NO. 2 RADIO ALTIMETER RECEIVER								Component	ATA:34
PN:822-0615-207	MOS/MSC	09-Nov-22	O/C	TSO 0					
SN:4FLGH1	HRS	7673.2		TSO 0					
WC#: 34.095	AFL	4072		TSO 0					
PROC. REF: AMM 34-44-01-000-801, AMM 34-44-01-400-801PROC. REF: AMM 34-44-01-000-801, AMM 34-44-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-44-05-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE RADIO ALTIMETER ANTENNAS CONNECTORS								Service ATA:34
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 42d	25-Sep-30	25-Dec-30	1553 d (+91)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 34-44-05-210-801PROC. REF: AMM 34-44-05-210-801									
34-44-05-900-801-01	TRANSCEIVER NO. 1 RADIO ALTIMETER ANTENNA								Component ATA:34
PN:DMPN19-1-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2622A	HRS	0		TSN 0					
WC#: 34.100	AFL	0		TSN 0					
PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801									
34-44-05-900-801-02	TRANSCEIVER NO. 2 RADIO ALTIMETER ANTENNA								Component ATA:34
PN:DMPN19-1-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5245A	HRS	0		TSN 0					
WC#: 34.100	AFL	0		TSN 0					
PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801									
34-44-05-900-801-03	RECEIVER NO. 1 RADIO ALTIMETER ANTENNA								Component ATA:34
PN:DMPN19-1-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5249	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801									
34-44-05-900-801-04	RECEIVER NO. 2 RADIO ALTIMETER ANTENNA								Component ATA:34
PN:DMPN19-1-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5307	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801PROC. REF: AMM 34-44-05-000-801, AMM 34-44-05-400-801									
34-45-01-900-801-01	NO. 1 IRU								Component ATA:34
PN:HG2001GD03	MOS/MSC	08-Jun-15	O/C						
SN:56006317	HRS	4822.9							
WC#: 34.110	AFL	2511							
PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
34-45-01-900-801-02		NO. 2 IRU							Component	ATA:34
PN:HG2001GD03	MOS/MSC	28-Jun-21	O/C	TSR 3						
SN:56019857	HRS	7126.5	TSN 3766, TSR 0							
WC#: 34.110	AFL	3743	TSN 958, TSR 0							
PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801										
34-45-01-900-801-03		NO. 3 IRU							Component	ATA:34
PN:HG2001GD03	MOS/MSC	20-Jul-15	O/C	TSR 1						
SN:01055422	HRS	4308.3	TSR 0							
WC#: 34.110	AFL	2232	TSR 0							
PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801PROC. REF: AMM 34-45-01-000-801, AMM 34-45-01-400-801										
34-45-05-900-801-01		MSU TRIPLEX MODE SELECT CONTROL PANEL							Component	ATA:34
PN:CG2015AC10	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:56004833	HRS	0	TSN 0							
WC#: 34.115	AFL	0	TSN 0							
PROC. REF: AMM 34-45-05-000-801, AMM 34-45-05-400-801PROC. REF: AMM 34-45-05-000-801, AMM 34-45-05-400-801										
34-46-01-900-801-01		CONTROL DISPLAY (IRS) UNIT							Component	ATA:34
PN:CG1230AC11	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:56005613	HRS	0	TSN 0							
WC#: 34.120	AFL	0	TSN 0							
PROC. REF: AMM 34-46-01-000-801, AMM 34-46-01-400-801PROC. REF: AMM 34-46-01-000-801, AMM 34-46-01-400-801										
34-47-01-900-801-01		LIGHTNING SENSOR SYSTEM LP-860 PROCESSOR							Component	ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
WC#: 34.125	AFL	0	TSN 0							
PROC. REF: AMM 34-47-01-000-801, AMM 34-47-01-400-801PROC. REF: AMM 34-47-01-000-801, AMM 34-47-01-400-801										
34-47-05-900-801-01		LIGHTNING SENSOR SYSTEM ANTENNA							Component	ATA:34
PN:7014062-901	MOS/MSC	27-Nov-06	O/C							
SN:03090636	HRS	86.8	TSN 0							
WC#: 34.130	AFL	40	TSN 0							
PROC. REF: AMM 34-47-05-000-801, AMM 34-47-05-400-801PROC. REF: AMM 34-47-05-000-801, AMM 34-47-05-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-47-06-900-801-01	(AT-850) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
34-51-01-900-801-01	NO. 1 RECEIVER NAVIGATION UNIT								Component ATA:34
PN:7510100-631	MOS/MSC	21-May-10	O/C	TSR 1					
SN:05068135	HRS	1597.2		TSR 0					
WC#: 34.140	AFL	886		TSR 0					
PROC. REF: AMM 34-51-01-000-801, AMM 34-51-01-400-801PROC. REF: AMM 34-51-01-000-801, AMM 34-51-01-400-801									
34-51-01-900-801-02	NO. 2 RECEIVER NAVIGATION UNIT								Component ATA:34
PN:7510100-631	MOS/MSC	28-Apr-21	O/C	TSR 132					
SN:98113120	HRS								
WC#: 34.140	AFL								
PROC. REF: AMM 34-51-01-000-801, AMM 34-51-01-400-801PROC. REF: AMM 34-51-01-000-801, AMM 34-51-01-400-801									
34-51-05-900-801-01	LH VOR/ILS (WHITE) ANTENNA								Component ATA:34
PN:S65-247-38	MOS/MSC	29-Jan-24	O/C	TSN 1					
SN:180-17486	HRS			TSN 0					
WC#: 34.145	AFL			TSN 0					
PROC. REF: AMM 34-51-05-000-801, AMM 34-51-05-400-801PROC. REF: AMM 34-51-05-000-801, AMM 34-51-05-400-801									
34-51-05-900-801-02	RH VOR/ILS (WHITE) ANTENNA								Component ATA:34
PN:S65-247-38	MOS/MSC	29-Jan-24	O/C	TSN 1					
SN:180-17485	HRS			TSN 0					
WC#: 34.145	AFL			TSN 0					
PROC. REF: AMM 34-51-05-000-801, AMM 34-51-05-400-801PROC. REF: AMM 34-51-05-000-801, AMM 34-51-05-400-801									
34-51-09-900-801-01	VOR/LOC PHASING COUPLER								Component ATA:34
PN:SSPD113-38	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:666-1101	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-51-17-900-801-01		GLIDE SLOPE ANTENNA						Component	ATA:34
PN:DMN25-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:4035	HRS	0		TSN 0					
WC#: 34.150	AFL	0		TSN 0					
PROC. REF: AMM 34-51-17-000-801, AMM 34-51-17-400-801PROC. REF: AMM 34-51-17-000-801, AMM 34-51-17-400-801									
34-51-21-900-801-01		GLIDESLOPE ANTENNA DIPLEXER						Component	ATA:34
PN:DMH24-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:16696	HRS	0		TSN 0					
WC#: 34.155	AFL	0		TSN 0					
PROC. REF: AMM 34-51-21-000-801, AMM 34-51-21-400-801PROC. REF: AMM 34-51-21-000-801, AMM 34-51-21-400-801									
34-51-25-900-801-01		BOTTOM MARKER BEACON ANTENNA						Component	ATA:34
PN:S35-1000-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:102-5678	HRS	0		TSN 0					
WC#: 34.160	AFL	0		TSN 0					
PROC. REF: AMM 34-51-25-000-801, AMM 34-51-25-400-801PROC. REF: AMM 34-51-25-000-801, AMM 34-51-25-400-801									
34-52-01-900-801-01		NO. 1 ADF (AT-860) ANTENNA						Component	ATA:34
PN:7510300-901	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05029066	HRS	0		TSN 0					
WC#: 34.165	AFL	0		TSN 0					
PROC. REF: AMM 34-52-01-000-801, AMM 34-52-01-400-801PROC. REF: AMM 34-52-01-000-801, AMM 34-52-01-400-801									
34-52-01-900-801-02		NO. 2 ADF (AT-860) ANTENNA						Component	ATA:34
PN:7510300-901	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05029072	HRS	0		TSN 0					
WC#: 34.165	AFL	0		TSN 0					
PROC. REF: AMM 34-52-01-000-801, AMM 34-52-01-400-801PROC. REF: AMM 34-52-01-000-801, AMM 34-52-01-400-801									
34-53-01-900-801-01		NO.1 LOWER DME ANTENNA						Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5828	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-53-01-000-801, AMM 34-53-01-400-801PROC. REF: AMM 34-53-01-000-801, AMM 34-53-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-53-01-900-801-02		NO.2 LOWER DME ANTENNA						Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5837	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-53-01-000-801, AMM 34-53-01-400-801PROC. REF: AMM 34-53-01-000-801, AMM 34-53-01-400-801									
34-54-01-900-801-01		NO.1 UPPER ATC ANTENNA						Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5547	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801									
34-54-01-900-801-02		NO.2 UPPER ATC ANTENNA						Component	ATA:34
PN:S65-5366-101	MOS/MSC	28-Apr-21	O/C	TSN 3					
SN:185-17250	HRS	7053.8		TSN 0					
	AFL	3690		TSN 0					
PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801									
34-54-01-900-801-03		NO.1 LOWER ATC ANTENNA						Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5817	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801									
34-54-01-900-801-04		NO.2 LOWER ATC ANTENNA						Component	ATA:34
PN:S65-5366-10L	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:5823	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801PROC. REF: AMM 34-54-01-000-801, AMM 34-54-01-400-801									
34-55-01-900-801-01		NO. 1 GLOBAL POSITIONING SENSOR UNIT						Component	ATA:34
PN:HG2021GD04	MOS/MSC	30-Nov-21	O/C	TSR 1					
SN:0480	HRS	7298.6		TSR 0					
WC#: 34.170	AFL	3840		TSR 0					
PROC. REF: AMM 34-55-01-000-801, AMM 34-55-01-400-801PROC. REF: AMM 34-55-01-000-801, AMM 34-55-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-55-01-900-801-02 NO. 2 GLOBAL POSITIONING SENSOR UNIT								Component	ATA:34
PN:HG2021GD04	MOS/MSC	27-Nov-20	O/C	TSR 7					
SN:0272	HRS	6989		TSR 0					
WC#: 34.170	AFL	3644		TSR 0					
PROC. REF: AMM 34-55-01-000-801, AMM 34-55-01-400-801PROC. REF: AMM 34-55-01-000-801, AMM 34-55-01-400-801									
34-55-05-900-801-01 LH GPS ANTENNA								Component	ATA:34
PN:S67-1575-137	MOS/MSC	14-May-13	O/C	TSN 35					
SN:773-0428	HRS	3138.2		TSN 0					
WC#: 34.175	AFL	1658		TSN 0					
PROC. REF: AMM 34-55-05-000-801, AMM 34-55-05-400-801PROC. REF: AMM 34-55-05-000-801, AMM 34-55-05-400-801									
34-55-05-900-801-02 RH GPS ANTENNA								Component	ATA:34
PN:S67-1575-137	MOS/MSC	14-May-13	O/C	TSN 34					
SN:773-0468	HRS	3138.2		TSN 0					
WC#: 34.175	AFL	1658		TSN 0					
PROC. REF: AMM 34-55-05-000-801, AMM 34-55-05-400-801PROC. REF: AMM 34-55-05-000-801, AMM 34-55-05-400-801									
34-61-01-900-801-01 NO. 1 FMS CDU UNIT								Component	ATA:34
PN:G7830-03	MOS/MSC	04-Feb-23	O/C	TSN 2					
SN:79120	HRS	7751.1		TSN 0					
WC#: 34.180	AFL	4121		TSN 0					
PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801									
34-61-01-900-801-02 NO. 2 FMS CDU UNIT								Component	ATA:34
PN:G7830-03	MOS/MSC	04-Feb-23	O/C	TSN 2					
SN:79115	HRS	7751.1		TSN 0					
WC#: 34.180	AFL	4121		TSN 0					
PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801									
34-61-01-900-801-03 NO. 3 FMS CDU UNIT								Component	ATA:34
PN:G7830-03	MOS/MSC	04-Feb-23	O/C	TSN 2					
SN:79117	HRS	7751.1		TSN 0					
	AFL	4121		TSN 0					
PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801PROC. REF: AMM 34-61-01-000-801, AMM 34-61-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34-62-01-900-801-01		FMS DATA LOADER						Component	ATA:34
PN:G7228-01	MOS/MSC	20-Mar-26	O/C						
SN:53867	HRS	8870							
WC#: 34.185	AFL	4687							
PROC. REF: AMM 34-62-01-000-801, AMM 34-62-01-400-801PROC. REF: AMM 34-62-01-000-801, AMM 34-62-01-400-801									
341201-001A ^U		FUNCTIONAL TEST OF THE INTEGRATED ELECTRONIC STAND BY INSTRUMENT WITH HEADING DISPLAY						Service	ATA:34
PN:C16221RA01	MOS	14-Apr-25	24		14-Apr-27		293 d		
SN:C16221010795	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
343203-701 ^U		COMPUTER HUD MOUNTING TRAY						Component	ATA:34
PN:GT547-0005-5	MOS/MSC	18-May-10	O/C						
SN:292	HRS	1594.8							
	AFL	882							
343209-701 ^U		COMBINER OPTICAL UNIT						Component	ATA:34
PN:GT546-0004-3	MOS/MSC	07-Oct-05	O/C						
SN:140	HRS	0							
	AFL	0							
343210-701 ^U		HUD COMPUTER						Component	ATA:34
PN:GT546-0001-7	MOS/MSC	11-Dec-17	O/C	TSR 0					
SN:377	HRS	5709.7		TSR 0					
	AFL	2937		TSR 0					
343210-702 ^U		HUD MONITOR CARD						Component	ATA:34
PN:E24739BA04	MOS/MSC	02-May-13	O/C						
SN:1115	HRS	3138.2							
	AFL	1658							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
343213-701	PROJECTOR OPTICAL UNIT								Component ATA:34
PN:GT546-0003-3	MOS/MSC	21-May-15	O/C						
SN:241	HRS	4228.4							
	AFL	2192							
343215-701	EVS INFRARED SENSOR								Component ATA:34
PN:GT546-1000-1	MOS/MSC	26-Feb-20	O/C	TSR 1					
SN:10091163	HRS	6852.3		TSR 0					
	AFL	3544		TSR 0					
343219-701	AIRCRAFT IDENTIFICATION TAG								Component ATA:34
PN:GT546-1003-1	MOS/MSC	07-Oct-05	O/C						
SN:05420295	HRS	0							
	AFL	0							
344701-701	LIGHTNING SENSOR PROCESSOR								Component ATA:34
PN:7011822-904	MOS/MSC	12-Feb-07	O/C	TSR 1					
SN:01091162	HRS	197.3		TSR 0					
	AFL	104		TSR 0					
349910-701	EVS FAIRING WINDOW								Component ATA:34
PN:GT415-1001-1	MOS/MSC	18-Dec-17	O/C	TSN 0					
SN:16470575	HRS	5716		TSN 0					
	AFL	2942		TSN 0					
ATA 35 - OXYGEN									
35-11-01-201	DISCARD OF THE LEFT INBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:806371-130	MOS	01-Feb-15	180		01-Feb-30		1317 d	LIFE LIMIT	
SN:C15050053	HRS	8222.7							
	AFL	4390							
Manufacture Date:: 01-Feb-15 PROC. REF: AMM 35-11-01-960-802PROC. REF: AMM 35-11-01-960-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-11-01-201	DISCARD OF THE LEFT OUTBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:806371-130	MOS	01-Jan-23	180		01-Jan-38		4208 d	LIFE LIMIT	
SN:C09030826-A	HRS	8222.7							
	AFL	4390							
Manufacture Date:: 01-Jan-23									
PROC. REF: AMM 35-11-01-960-802PROC. REF: AMM 35-11-01-960-802									
35-11-01-201	DISCARD OF THE RIGHT INBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:806371-130	MOS	01-Jan-23	180		01-Jan-38		4208 d	LIFE LIMIT	
SN:C09030220-A	HRS	8222.7							
	AFL	4390							
Manufacture Date:: 01-Jan-23									
PROC. REF: AMM 35-11-01-960-802PROC. REF: AMM 35-11-01-960-802									
35-11-01-201	DISCARD OF THE RIGHT OUTBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:806371-130	MOS	01-Jan-23	180		01-Jan-38		4208 d	LIFE LIMIT	
SN:C09030397-A	HRS	8222.7							
	AFL	4390							
Manufacture Date:: 01-Jan-23									
PROC. REF: AMM 35-11-01-960-802PROC. REF: AMM 35-11-01-960-802									
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:806371-130	MOS	01-Aug-23	60		01-Aug-28		768 d	MRB	
SN:C15050053	HRS	8222.7							
WC#: 35.025	AFL	4390							
HydroCheck Date: : 01-Aug-23									
PROC. REF: AMM 35-11-01-720-801PROC. REF: AMM 35-11-01-720-801									
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:806371-130	MOS	01-Jul-23	60		01-Jul-28		737 d	MRB	
SN:C09030826-A	HRS	8222.7							
WC#: 35.015	AFL	4390							
HydroCheck Date: : 01-Jul-23									
PROC. REF: AMM 35-11-01-720-801PROC. REF: AMM 35-11-01-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:806371-130	MOS	01-Jul-23	60		01-Jul-28		737 d	MRB	
SN:C09030220-A	HRS	8222.7							
WC#: 35.030	AFL	4390							
HydroCheck Date: : 01-Jul-23									
PROC. REF: AMM 35-11-01-720-801PROC. REF: AMM 35-11-01-720-801									
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:806371-130	MOS	01-Jul-23	60		01-Jul-28		737 d	MRB	
SN:C09030397-A	HRS	8222.7							
WC#: 35.020	AFL	4390							
HydroCheck Date: : 01-Jul-23									
PROC. REF: AMM 35-11-01-720-801PROC. REF: AMM 35-11-01-720-801									
35-11-01-900-801-01	LEFT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component ATA:35
PN:806371-130	MOS/MSC	24-Apr-24	H/T	TSO 0					
SN:C09030826-A	HRS	8222.7		TSO 0					
WC#: 35.015	AFL	4390		TSO 0					
PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801									
35-11-01-900-801-02	RIGHT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component ATA:35
PN:806371-130	MOS/MSC	24-Apr-24	H/T	TSO 0					
SN:C09030397-A	HRS	8222.7		TSO 0					
WC#: 35.020	AFL	4390		TSO 0					
PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801									
35-11-01-900-801-03	LEFT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component ATA:35
PN:806371-130	MOS/MSC	22-Apr-24	H/T	TSO 0					
SN:C15050053	HRS	8222.7		TSO 0					
WC#: 35.025	AFL	4390		TSO 0					
PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801									
35-11-01-900-801-04	RIGHT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component ATA:35
PN:806371-130	MOS/MSC	24-Apr-24	H/T	TSO 0					
SN:C09030220-A	HRS	8222.7		TSO 0					
WC#: 35.030	AFL	4390		TSO 0					
PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801PROC. REF: AMM 35-11-01-000-801, AMM 35-11-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-11-09-900-801-01	LH STOWAGE BOX							Component	ATA:35
PN:MXP411-3	MOS/MSC	07-Sep-24	O/C	TSN 226, TSO 4	01-May-30 (M)		1406 d		
SN:SE13283	HRS	8479.2		TSO 0					
WC#: 35.045	AFL	4499		TSO 0					
PROC. REF: AMM 35-11-09-000-801, AMM 35-11-09-400-801PROC. REF: AMM 35-11-09-000-801, AMM 35-11-09-400-801									
35-11-09-900-801-02	RH STOWAGE BOX							Component	ATA:35
PN:MXP411-3	MOS/MSC	07-Sep-24	O/C	TSN 234, TSO 4	01-May-30 (M)		1406 d		
SN:SE10480	HRS	8479.2		TSO 0					
WC#: 35.045	AFL	4499		TSO 0					
PROC. REF: AMM 35-11-09-000-801, AMM 35-11-09-400-801PROC. REF: AMM 35-11-09-000-801, AMM 35-11-09-400-801									
35-11-50-601 ^{U S}	OPERATIONAL TEST OF CREW OXYGEN SYSTEM MODIFICATIONS							Service	ATA:35
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
35-11-50-603 ^{U S}	DETAILED INSPECTION OF CREW PROTECTIVE BREATHING EQUIPMENT (PBE)							Service	ATA:35
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
									PKG:31
35-12-00-701 ^U	OXYGEN FILLER VALVE							Component	ATA:35
PN:170080-00	MOS/MSC	24-Oct-23	O/C	TSN 0				CUSTOMER CODE	
SN:N/A	HRS	8069.4		TSN 0					
	AFL	4290		TSN 0					
35-12-09-900-801-01	OXYGEN PRESSURE TRANSDUCER							Component	ATA:35
PN:GC481-0070-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:F5341	HRS	0		TSN 0					
WC#: 35.050	AFL	0		TSN 0					
PROC. REF: AMM 35-12-09-000-801, AMM 35-12-09-400-801PROC. REF: AMM 35-12-09-000-801, AMM 35-12-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
35-20-05-900-801-01	S/O THERAPEUTIC OXYGEN VALVE								Component ATA:35
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.010	AFL	0		TSN 0					
PROC. REF: AMM 35-20-05-000-801, AMM 35-20-05-400-801PROC. REF: AMM 35-20-05-000-801, AMM 35-20-05-400-801									
35-21-01-201	FUNCTIONAL TEST OF THE PASSENGER OXYGEN CONTROL PANEL								Service ATA:35
	MOS	14-Aug-25	30 (+3m/-3m)	Adj -10d	04-Feb-28	04-May-28	589 d (+90)	MRB	
	HRS	8645							
WC#: 35.005	AFL	4582							
PKG:32									
PROC. REF: AMM 35-21-01-720-801PROC. REF: AMM 35-21-01-720-801									
35-21-01-900-801-01	PASSENGER OXYGEN CONTROL PANEL / ALTIMETRIC VALVE								Component ATA:35
PN:GC481-0080-3	MOS/MSC	14-Aug-25	O/C	TSR 0					
SN:273	HRS	8645		TSR 0					
WC#: 35.055	AFL	4582		TSR 0					
PROC. REF: AMM 35-21-01-000-801, AMM 35-21-01-400-801PROC. REF: AMM 35-21-01-000-801, AMM 35-21-01-400-801									
35-21-50-601 ^{U S}	OPERATIONAL TEST OF PASSENGER OXYGEN SYSTEM								Service ATA:35
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
35-21-50-602 ^U	FUNCTIONAL TEST OF PASSENGER OXYGEN SYSTEM								Service ATA:35
	MOS	14-Aug-25	30		14-Feb-28		599 d	STLMC	
	HRS	8645							
	AFL	4582							
PKG:32									
351000-002 ^U	NEBULIZER KIT								Component ATA:35
PN:O2C33K08-1-144	MOS/MSC	20-Jul-23	O/C						
SN:10337-001-01	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351000-002A	U	REPLACE							Service ATA:35
PN:O2C33K08-1-144	MOS	31-Jul-23	120		31-Jul-33		2593 d	VENDOR RECOMMENDATION	
SN:10337-001-01	HRS								
	AFL								
351103-701	U	PILOT HALF MASK							Component ATA:35
PN:MC20-004	MOS/MSC	15-Aug-22	H/T	TSO 1					
SN:141019I	HRS	7609.7		TSO 0					
	AFL	4027		TSO 0					
351103-701A	U	RESTORATION (OVERHAUL) PILOT HALF MASK (35-11-50-602)							Service ATA:35
PN:MC20-004	MOS/MSC	15-Aug-22	DUE		31-Jul-28 (M)		767 d	STLMC	
SN:141019I	HRS	7609.7							
	AFL	4027							
351103-702	U	COPILOT HALF MASK							Component ATA:35
PN:MC20-004	MOS/MSC	21-Feb-24	H/T	TSO 1					
SN:SE19945	HRS	8168		TSO 0					
	AFL	4354		TSO 0					
351103-702A	U	RESTORATION (OVERHAUL) COPILOT HALF MASK (35-11-50-602)							Service ATA:35
PN:MC20-004	MOS/MSC	21-Feb-24	DUE		01-Jan-30 (M)		1286 d	STLMC	
SN:SE19945	HRS	8168							
	AFL	4354							
351103-704	U	JUMP SEAT HALF MASK							Component ATA:35
PN:MC20-004	MOS/MSC	01-Apr-24	O/C	TSO 1					
SN:SE65696I	HRS	8207.3		TSO 0					
	AFL	4380		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351103-704A	U	RESTORATION (OVERHAUL) JUMP SEAT HALF MASK (35-11-50-602)							Service ATA:35
PN:MC20-004	MOS/MSC	01-Apr-24	DUE		18-Mar-30 (M)		1362 d	STLMC	
SN:SE65696I	HRS	8207.3							
	AFL	4380							
351105-703	U	SWEEP ON (JUMPSEAT) MASK							Component ATA:35
PN:MF10-08-01	MOS/MSC	07-Oct-05	O/C						
SN:SE05127	HRS	0							
	AFL	0							
351109-701	U	3RD CREW MASK STOWAGE BOX							Component ATA:35
PN:MXP411-3	MOS/MSC	17-May-12	O/C	TSO 0					
SN:SE122206	HRS	2616.8		TSO 0					
	AFL	1382		TSO 0					
352101-002	U	RH ALTIMETRIC VALVE							Component ATA:35
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
359523-701	U	(AFT END CABINET C/R) PBE							Component ATA:35
PN:DP3113AMR-10037N	MOS/MSC	11-Nov-24	O/C					LIFE LIMIT	
SN:E106824	HRS	8623.4							
	AFL	4570							
359523-701A	U	RESTORE (AFT END CABINET C/R) PBE (35-11-50-604)							Service ATA:35
PN:DP3113AMR-10037N	MOS/MSC	11-Nov-24	DUE		01-Aug-32 (M)		2229 d	STLMC	
SN:E106824	HRS	8623.4							
	AFL	4570							
Expiry Date: : 01-Aug-32									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
359523-702 U	(AFT WARDROBE) PBE								Component ATA:35
PN:DP3113AMR-10037N	MOS/MSC	11-Nov-24	O/C	TSN 156				LIFE LIMIT	
SN:E1102847	HRS	8623.4		TSN 6006.6					
	AFL	4570		TSN 3188					
359523-702A U	RESTORE (AFT WARDROBE) PBE (35-11-50-604)								Service ATA:35
PN:DP3113AMR-10037N	MOS/MSC	11-Nov-24	DUE		01-Nov-34 (M)		3051 d	STLMC	
SN:E1102847	HRS	8623.4							
	AFL	4570							
Expiry Date: : 01-Nov-34									
ATA 36 - PNEUMATIC									
36-11-01-900-801-01	LH HIGH PRESSURE BLEED VALVE								Component ATA:36
PN:GG436-1001-9	MOS/MSC	25-Feb-13	O/C	TSR 4					
SN:00824	HRS	3021.2		TSN 1448.6, TSR 0					
WC#: 36.005	AFL	1590		TSR 0					
PROC. REF: AMM 36-11-01-000-801, AMM 36-11-01-400-801PROC. REF: AMM 36-11-01-000-801, AMM 36-11-01-400-801									
36-11-01-900-801-02	RH HIGH PRESSURE BLEED VALVE								Component ATA:36
PN:GG436-1001-9	MOS/MSC	21-Nov-24	O/C						
SN:00386	HRS	8628.8		TSN 9926					
WC#: 36.005	AFL	4574		TSN 5729					
PROC. REF: AMM 36-11-01-000-801, AMM 36-11-01-400-801PROC. REF: AMM 36-11-01-000-801, AMM 36-11-01-400-801									
36-11-05-900-801-01	LH CHECK INTERMEDIATE PRESSURE VALVE								Component ATA:36
PN:GG436-1002-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00480	HRS	0		TSN 0					
WC#: 36.010	AFL	0		TSN 0					
PROC. REF: AMM 36-11-05-000-801, AMM 36-11-05-400-801PROC. REF: AMM 36-11-05-000-801, AMM 36-11-05-400-801									
36-11-05-900-801-02	RH CHECK INTERMEDIATE PRESSURE VALVE								Component ATA:36
PN:GG436-1002-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00492	HRS	0		TSN 0					
WC#: 36.010	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
PROC. REF: AMM 36-11-05-000-801, AMM 36-11-05-400-801PROC. REF: AMM 36-11-05-000-801, AMM 36-11-05-400-801									
36-11-09-900-801-01		LH BLEED PRESS - REGULATING & S/O VALVE						Component	ATA:36
PN:GG436-1055-1	MOS/MSC	04-Aug-15	O/C	TSR 1					
SN:00452	HRS	4355	TSR 0						
WC#: 36.015	AFL	2247	TSR 0						
PROC. REF: AMM 36-11-09-000-801, AMM 36-11-09-400-801PROC. REF: AMM 36-11-09-000-801, AMM 36-11-09-400-801									
36-11-09-900-801-02		RH BLEED PRESS - REGULATING & S/O VALVE						Component	ATA:36
PN:GG436-1055-1	MOS/MSC	15-Jun-17	O/C	TSR 3					
SN:13360	HRS	5428.8	TSN 3830.1, TSR 0						
WC#: 36.015	AFL	2792	TSN 1132, TSR 0						
PROC. REF: AMM 36-11-09-000-801, AMM 36-11-09-400-801PROC. REF: AMM 36-11-09-000-801, AMM 36-11-09-400-801									
36-11-13-900-801-01		LH PRECOOLER						Component	ATA:36
PN:GG474-1004-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50154	HRS	0	TSN 0						
WC#: 36.020	AFL	0	TSN 0						
PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801									
36-11-13-900-801-02		RH PRECOOLER						Component	ATA:36
PN:GG474-1004-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:50168	HRS	0	TSN 0						
WC#: 36.020	AFL	0	TSN 0						
PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801									
36-11-13-900-802-01		LH PLENUM INLET						Component	ATA:36
PN:GG468-4072-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0176	HRS	0	TSN 0						
WC#: 36.025	AFL	0	TSN 0						
PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801									
36-11-13-900-802-02		RH PLENUM INLET						Component	ATA:36
PN:GG468-4072-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0180	HRS	0	TSN 0						
WC#: 36.025	AFL	0	TSN 0						
PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801PROC. REF: AMM 36-11-13-000-801, AMM 36-11-13-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-17-900-801-01	LH FAN AIR VALVE							Component	ATA:36
PN:GG433-1005-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00478	HRS	0		TSN 0					
WC#: 36.035	AFL	0		TSN 0					
PROC. REF: AMM 36-11-17-000-801, AMM 36-11-17-400-801PROC. REF: AMM 36-11-17-000-801, AMM 36-11-17-400-801									
36-11-17-900-801-02	RH FAN AIR VALVE							Component	ATA:36
PN:GG433-1005-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:00485	HRS	0		TSN 0					
WC#: 36.035	AFL	0		TSN 0					
PROC. REF: AMM 36-11-17-000-801, AMM 36-11-17-400-801PROC. REF: AMM 36-11-17-000-801, AMM 36-11-17-400-801									
36-11-21-201 ^S	DISCARD OF THE LH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER							Service	ATA:36
	MOS	24-Jun-20						MRB	
	HRS	6911.6	2250						
	AFL	3586							
PROC. REF: AMM 36-11-21-961-801PROC. REF: AMM 36-11-21-961-801									
36-11-21-201 ^S	DISCARD OF THE RH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER							Service	ATA:36
	MOS	27-Feb-22						MRB	
	HRS	7287.8	2250						
	AFL	3829							
PROC. REF: AMM 36-11-21-961-801PROC. REF: AMM 36-11-21-961-801									
36-11-21-900-801-01	LH PNEUMATIC TEMP THERMOSTAT							Component	ATA:36
PN:GG436-1006-7	MOS/MSC	06-Oct-20	O/C						
SN:00776	HRS	6972.8							
WC#: 36.040	AFL	3632							
PROC. REF: CMM 36-12-05, AMM 36-11-21-000-801, AMM 36-11-21-400-801PROC. REF: CMM 36-12-05, AMM 36-11-21-000-801, AMM 36-11-21-400-801									
36-11-21-900-801-02	RH PNEUMATIC TEMP THERMOSTAT							Component	ATA:36
PN:GG436-1006-7	MOS/MSC	21-Nov-21	O/C	TSR 32					
SN:00603	HRS	7287.8		TSN 5200.1, TSR 383.1					
WC#: 36.040	AFL	3829		TSN 2376, TSR 248					
PROC. REF: CMM 36-12-05, AMM 36-11-21-000-801, AMM 36-11-21-400-801PROC. REF: CMM 36-12-05, AMM 36-11-21-000-801, AMM 36-11-21-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-25-900-801-01 LH BLEED PRESSURE TRANSDUCER									Component ATA:36
PN:GG436-1007-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1037	HRS	0		TSN 0					
WC#: 36.045	AFL	0		TSN 0					
PROC. REF: AMM 36-11-25-000-801, AMM 36-11-25-400-801PROC. REF: AMM 36-11-25-000-801, AMM 36-11-25-400-801									
36-11-25-900-801-02 RH BLEED PRESSURE TRANSDUCER									Component ATA:36
PN:GG436-1007-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1021	HRS	0		TSN 0					
WC#: 36.045	AFL	0		TSN 0					
PROC. REF: AMM 36-11-25-000-801, AMM 36-11-25-400-801PROC. REF: AMM 36-11-25-000-801, AMM 36-11-25-400-801									
36-11-29-900-801-01 LH BOOT									Component ATA:36
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
36-11-29-900-801-02 RH BOOT									Component ATA:36
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
36-11-29-900-802-01 CROSS BLEED VALVE									Component ATA:36
PN:GG436-1008-7	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:646	HRS	0		TSN 0					
WC#: 36.070	AFL	0		TSN 0					
PROC. REF: AMM 36-11-29-000-801, AMM 36-11-29-400-801PROC. REF: AMM 36-11-29-000-801, AMM 36-11-29-400-801									
36-11-29-900-802-02 COUPLING COVER									Component ATA:36
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.075	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-33-900-801-01	LH BLEED MANAGEMENT (BMC) CONTROLLER								Component ATA:36
PN:GG546-1017-13	MOS/MSC	08-Aug-11	O/C	TSN 0					
SN:01120	HRS	2297.7		TSN 0					
WC#: 36.080	AFL	1197		TSN 0					
PROC. REF: AMM 36-11-33-000-801, AMM 36-11-33-400-801PROC. REF: AMM 36-11-33-000-801, AMM 36-11-33-400-801									
36-11-33-900-801-02	RH BLEED MANAGEMENT (BMC) CONTROLLER								Component ATA:36
PN:GG546-1017-13	MOS/MSC	20-Feb-08	O/C	TSN 1393, TSR 3					
SN:0332	HRS	580.4		TSR 0					
WC#: 36.080	AFL	336		TSN 489, TSR 0					
PROC. REF: AMM 36-11-33-000-801, AMM 36-11-33-400-801PROC. REF: AMM 36-11-33-000-801, AMM 36-11-33-400-801									
36-11-37-900-801-01	LH IP PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1018-1	MOS/MSC	12-Feb-24	O/C	TSN 15					
SN:11195	HRS	8164.7		TSN 0					
WC#: 36.085	AFL	4350		TSN 0					
PROC. REF: AMM 36-11-37-000-801, AMM 36-11-37-400-801PROC. REF: AMM 36-11-37-000-801, AMM 36-11-37-400-801									
36-11-37-900-801-02	RH IP PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1018-1	MOS/MSC	17-Jul-24	O/C	TSN 1					
SN:11324	HRS	8369.2		TSN 0					
WC#: 36.085	AFL	4459		TSN 0					
PROC. REF: AMM 36-11-37-000-801, AMM 36-11-37-400-801PROC. REF: AMM 36-11-37-000-801, AMM 36-11-37-400-801									
36-11-41-900-801-01	HP GROUND CONNECTION								Component ATA:36
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 36.090	AFL	0		TSN 0					
PROC. REF: AMM 36-11-41-000-801, AMM 36-11-41-400-801PROC. REF: AMM 36-11-41-000-801, AMM 36-11-41-400-801									
36-11-41-900-801-02	DUCT								Component ATA:36
PN:GG468-4066-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0184	HRS	0		TSN 0					
WC#: 36.095	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-61-101	DISCARD APU CROSS BLEED VALVE UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-19	MOS	26-May-20						LIFE LIMIT	
SN:6793	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101	DISCARD L/H FLOW CONTROL VALVE UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-15	MOS	04-May-23						LIFE LIMIT	
SN:11782	HRS	7808.8	8000		15808.8		6890.2		
	AFL	4157							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101	DISCARD LEFT BLEED FILTER UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10046	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101	DISCARD LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10350	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101	DISCARD LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-17	MOS	26-May-20						LIFE LIMIT	
SN:4809	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101	DISCARD LH FLOW SENSOR VENTURI UROSEAL CONNECTOR (AWL*)								Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10364	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-61-101 DISCARD R/H FLOW CONTROL VALVE UROSEAL CONNECTOR (AWL*)									Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10509	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101 DISCARD RH FLOW SENSOR VENTURI UROSEAL CONNECTOR (AWL*)									Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10351	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101 DISCARD RIGHT BLEED FILTER UROSEAL CONNECTOR (AWL*)									Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10058	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101 DISCARD RIGHT CROSS BLEED VALVE UROSEAL CONNECTOR (AWL*)									Service ATA:36
PN:GG468-4054-17	MOS	05-Aug-20						LIFE LIMIT	
SN:4744	HRS	6919.2	8000		14919.2		6000.6		
	AFL	3591							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-101 DISCARD RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR (AWL*)									Service ATA:36
PN:GG468-4054-15	MOS	26-May-20						LIFE LIMIT	
SN:10362	HRS	6911.6	8000		14911.6		5993		
	AFL	3586							
PROC. REF: AMM 36-11-61-961-801PROC. REF: AMM 36-11-61-961-801									
36-11-61-900-801-01 LH FLOW SENSOR VENTURI UROSEAL CONNECTOR									Component ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 5					
SN:10364	HRS	6911.6		TSN 0					
WC#: 21.115	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-61-900-801-02 RH FLOW SENSOR VENTURI UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 5					
SN:10351	HRS	6911.6		TSN 0					
WC#: 21.115	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									
36-11-61-900-801-03 LEFT BLEED FILTER UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 12					
SN:10046	HRS	6911.6		TSN 0					
WC#: 21.120	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									
36-11-61-900-801-04 RIGHT BLEED FILTER UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 12					
SN:10058	HRS	6911.6		TSN 0					
WC#: 21.120	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									
36-11-61-900-801-05 L/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	04-May-23	H/T	TSN 7					
SN:11782	HRS	7808.8		TSN 0					
WC#: 21.125	AFL	4157		TSN 0					
PROC. REF: CMM 30-12-06, AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: CMM 30-12-06, AMM 21-51-25-000-801, AMM 21-51-25-400-801									
36-11-61-900-801-06 R/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 1					
SN:10509	HRS	6911.6		TSN 0					
WC#: 21.125	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06, AMM 21-51-25-000-801, AMM 21-51-25-400-801PROC. REF: CMM 30-12-06, AMM 21-51-25-000-801, AMM 21-51-25-400-801									
36-11-61-900-801-07 LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR								Component	ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 5					
SN:10350	HRS	6911.6		TSN 0					
WC#: 36.030	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
36-11-61-900-801-08	RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	26-May-20	H/T	TSN 5					
SN:10362	HRS	6911.6		TSN 0					
WC#: 36.030	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06PROC. REF: CMM 30-12-06									
36-11-61-900-801-09	LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-17	MOS/MSC	26-May-20	H/T	TSN 0					
SN:4809	HRS	6911.6		TSN 0					
WC#: 36.050	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801									
36-11-61-900-801-10	RIGHT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-17	MOS/MSC	05-Aug-20	H/T	TSN 9					
SN:4744	HRS	6919.2		TSN 0					
WC#: 36.050	AFL	3591		TSN 0					
PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801									
36-11-61-900-801-11	APU CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-19	MOS/MSC	26-May-20	H/T	TSN 1					
SN:6793	HRS	6911.6		TSN 0					
WC#: 36.055	AFL	3586		TSN 0					
PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801PROC. REF: CMM 30-12-06, AMM 36-11-29-000-801, AMM 36-11-29-400-801									
ATA 38 - WATER/WASTE									
38-13-50-601 ^U	RESTORE POTABLE WATER TREATMENT UNIT								Service ATA:38
	MOS	14-Aug-25						STLMC	
	HRS	8645	3000		11645		2726.4		
	AFL	4582							
PKG:8									
38-13-52-601 ^{U S}	DISCARD POTABLE WATER TREATMENT UNIT FILTER CARTRIDGE								Service ATA:38
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
38-31-50-601 ^{U S} GENERAL VISUAL INSPECTION OF THE FORWARD TOILET INSTALLATION Service ATA:38									
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
38-32-50-601 ^{U S} GENERAL VISUAL INSPECTION OF THE AFT TOILET INSTALLATION Service ATA:38									
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
380002-702 ^U GALLEY WATER HEATER Component ATA:38									
PN:4E4099-3	MOS/MSC	23-Jul-09	O/C	TSR 5					
SN:N0707202	HRS	1223.6		TSR 0					
	AFL	675		TSR 0					
380002-703 ^U AFT LAVATORY WATER HEATER Component ATA:38									
PN:4E4099-3	MOS/MSC	18-Jul-23	O/C	TSR 2					
SN:N1326006	HRS	7923.9		TSR 0					
	AFL	4211		TSR 0					
380002-704 ^U HEATED DRAIN LINE (SINK) HOSE Component ATA:38									
PN:4E4425-04	MOS/MSC	05-Oct-09	O/C						
SN:N0725702	HRS	1338.1							
	AFL	735							
380006-701 ^U GALLEY WATER STERILIZER Component ATA:38									
PN:09-130021-102	MOS/MSC	08-Jun-20	O/C	TSO 2					
SN:1-0217	HRS	6911.6		TSO 0					
	AFL	3586		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
381002-702	U	WATER TANK (AFT) 28.6 GAL TANK						Component	ATA:38
PN:4E4604-1	MOS/MSC	07-Oct-05	O/C						
SN:XRS-002	HRS	0							
	AFL	0							
381003-701	U	POTABLE WATER PUMP						Component	ATA:38
PN:4E4360-1	MOS/MSC	07-Oct-05	O/C						
SN:C-174	HRS	0							
	AFL	0							
381003-702	U	POTABLE WATER PUMP						Component	ATA:38
PN:4E4360-1	MOS/MSC	07-Oct-05	O/C						
SN:C-175	HRS	0							
	AFL	0							
381008-701	U	POTABLE WATER TRANSDUCER						Component	ATA:38
PN:2E1976-2	MOS/MSC	07-Oct-05	O/C						
SN:6611-3-178	HRS	0							
	AFL	0							
381009-701	U	CONTROL (EIB) PANEL						Component	ATA:38
PN:4E4381-1	MOS/MSC	12-Mar-07	O/C						
SN:U0033	HRS	220.4		TSN 0					
	AFL	117		TSN 0					
381010-701	U	EIB PWS CONTROL						Component	ATA:38
PN:5E2651-20	MOS/MSC	21-Apr-09	O/C	TSR 1					
SN:U030	HRS	1096.2		TSR 0					
	AFL	616		TSR 0					

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
381115-701	MOTORIZED VALVE								Component ATA:38
PN:4E4348-1	MOS/MSC	07-Oct-05	O/C						
SN:N0534703	HRS	0							
	AFL	0							
381115-702	MOTORIZED VALVE								Component ATA:38
PN:4E4348-2	MOS/MSC	07-Oct-05	O/C						
SN:N0513209	HRS	0							
	AFL	0							
381115-703	MOTORIZED VALVE								Component ATA:38
PN:4E4348-5	MOS/MSC	07-Oct-05	O/C						
SN:N0513603	HRS	0							
	AFL	0							
381115-704	MOTORIZED VALVE								Component ATA:38
PN:4E4348-2	MOS/MSC	10-Oct-11	O/C	TSN 0					
SN:N1109706	HRS	2390.7		TSN 0					
	AFL	1249		TSN 0					
381115-705	MOTORIZED VALVE								Component ATA:38
PN:4E4348-2	MOS/MSC	07-Oct-05	O/C						
SN:N0513206	HRS	0							
	AFL	0							
381115-706	MOTORIZED VALVE								Component ATA:38
PN:4E4449-1	MOS/MSC	07-Oct-05	O/C						
SN:0109	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
381150-701 ^U HAND SHOWER HOT WATER VENT VALVE								Component	ATA:38
PN:4E3261-4	MOS/MSC	05-May-15	O/C	TSN 1					
SN:4200	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
381150-702 ^U HAND SHOWER COLD WATER VENT VALVE								Component	ATA:38
PN:4E3261-4	MOS/MSC	08-Sep-07	O/C						
SN:1317	HRS	431.5							
	AFL	233							
381150-703 ^U GALLEY HOT WATER VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	08-Sep-07	O/C						
SN:0069	HRS	431.5							
	AFL	233							
381150-704 ^U GALLEY COLD WATER VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	06-Dec-17	O/C	TSN 0					
SN:2749	HRS	5684.7		TSN 0					
	AFL	2924		TSN 0					
381150-705 ^U AFT LAVATORY HOT WATER VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	05-May-15	O/C	TSN 2					
SN:2240	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					
381150-706 ^U AFT LAVATORY COLD WATER VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	05-May-15	O/C	TSN 2					
SN:2238	HRS	4228.4		TSN 0					
	AFL	2192		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
381150-707 ^U		WATER VENT VALVE						Component	ATA:38
PN:4E3261-4	MOS/MSC	08-Sep-07	O/C						
SN:1326	HRS	431.5							
	AFL	233							
381300-701 ^U		LOGIC MODULE - AFT LAVATORY MODULE						Component	ATA:38
PN:7700721	MOS/MSC	18-Nov-20	O/C	TSN 157, TSR 1					
SN:149	HRS	6986.7		TSR 0					
	AFL	3643		TSR 0					
381306-701 ^U		LAVATORY 2 VACUUM SWITCH						Component	ATA:38
PN:7700750	MOS/MSC	22-Oct-08	O/C	TSN 0					
SN:0150	HRS	927.8		TSN 0					
	AFL	501		TSN 0					
383000-701 ^U		EXTERNAL CONTROL (WASTE DISPOSAL) PANEL						Component	ATA:38
PN:4E3600-1	MOS/MSC	07-Oct-05	O/C						
SN:U0037	HRS	0							
	AFL	0							
383005-701 ^U		FORWARD LAVATORY TOILET ASSEMBLY						Component	ATA:38
PN:7900151	MOS/MSC	11-Jan-08	O/C	TSR 2					
SN:63-389	HRS	538.8		TSR 0					
	AFL	304		TSR 0					
383005-702 ^U		AFT LAVATORY TOILET ASSEMBLY						Component	ATA:38
PN:7900268	MOS/MSC	07-Apr-20	O/C	TSO 7					
SN:63-728	HRS	6879.6		TSO 0					
	AFL	3560		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
383006-701	AFT WASTE TANK ASSY								Component ATA:38
PN:7900330	MOS/MSC	07-Oct-05	O/C						
SN:43-580	HRS	0							
	AFL	0							
383031-701	FWD TOILET RINSE VALVE								Component ATA:38
PN:PN	MOS/MSC	O/C							
SN:UNKNOWN	HRS								
	AFL								
383031-702	AFT TOILET RINSE VALVE								Component ATA:38
PN:15800-470	MOS/MSC	07-Apr-20	O/C						
SN:003	HRS	6879.6							
	AFL	3560							
383106-701	AFT LAV WASTE TANK DIFFERENTIAL PRESSURE (DELTA P LEVEL) SENSOR								Component ATA:38
PN:7700719	MOS/MSC	26-Feb-25	O/C	TSN 9					
SN:2425	HRS	8641.1		TSN 0					
	AFL	4580		TSN 0					
383108-701	FWD DRAIN MAST								Component ATA:38
PN:24E506700G1	MOS/MSC	O/C							
SN:UNKNOWN	HRS								
	AFL								
383108-702	AFT DRAIN MAST								Component ATA:38
PN:24E506700G1	MOS/MSC	26-Feb-20	O/C	TSN 0					
SN:N2001414	HRS	6852.3		TSN 0					
	AFL	3544		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 38 - WATER/WASTE									
384000-701	U	VACUUM	AFT GENERATOR					Component	ATA:38
PN:7800365	MOS/MSC	03-Nov-21	O/C						
SN:10257	HRS	7274.6		TSN 1153					
	AFL	3819		TSN 2272					
ATA 44 - CABIN SYSTEMS									
441000-701	U	MOVING MAP	EQUIPMENT					Component	ATA:44
PN:822-1881-101	MOS/MSC	15-Jun-23	O/C	TSO 1					
SN:412M4P	HRS	7864.7		TSO 0					
	AFL	4198		TSO 0					
441000-702	U	MOVING MAP (AVOD)	MCE #2 EQUIPMENT					Component	ATA:44
PN:822-1915-002	MOS/MSC	07-Oct-05	O/C						
SN:28XFV	HRS	0							
	AFL	0							
441001-701	U	NO. 4 DIGITAL TAPPING	EQUIPMENT					Component	ATA:44
PN:1308524-100	MOS/MSC	26-Feb-25	O/C	TSO 80					
SN:1J0KD	HRS	8641.1		TSO 0					
	AFL	4580		TSO 0					
441001-703	U	DIGITAL TAPPING (HIGH CABINET)	EQUIPMENT					Component	ATA:44
PN:1308524-100	MOS/MSC	20-Oct-20	O/C	TSO 0					
SN:1J0KD	HRS	6972.8		TSO 0					
	AFL	3632		TSO 0					
441004-701	U	NO. 1 MODULAR CABIN (MCE)	EQUIPMENT					Component	ATA:44
PN:822-1877-001	MOS/MSC	03-Nov-06	O/C						
SN:1NLZR	HRS	36.5							
	AFL	14							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 44 - CABIN SYSTEMS									
441004-702	U	NO. 2 MODULAR CABIN (MCE) EQUIPMENT						Component	ATA:44
PN:822-1877-001	MOS/MSC	07-Oct-05	O/C						
SN:246VX	HRS	0							
	AFL	0							
441005-701	U	PROCESSOR/MASS STORAGE (MCE#1) EQUIPMENT						Component	ATA:44
PN:822-1880-001	MOS/MSC	08-Jun-23	O/C						
SN:344DD	HRS	7852.6							
	AFL	4190							
441005-702	U	PROCESSOR/MASS STORAGE (MCE#2) EQUIPMENT						Component	ATA:44
PN:822-1880-001	MOS/MSC	30-Sep-15	O/C	TSO 31					
SN:2NFNR	HRS	4469		TSO 0					
	AFL	2318		TSO 0					
441006-701	U	MCE#1 POWER SUPPLY						Component	ATA:44
PN:822-1879-001	MOS/MSC	09-Nov-16	O/C	TSO 1					
SN:2B1JK	HRS	5103.8		TSO 0					
	AFL	2616		TSO 0					
441006-702	U	MCE#2 POWER SUPPLY						Component	ATA:44
PN:822-1879-001	MOS/MSC	09-Nov-16	O/C	TSO 3					
SN:2RD1W	HRS	5103.8		TSO 0					
	AFL	2616		TSO 0					
441007-701	U	SWITCH ETHERNET (MCE#1) EQUIPMENT						Component	ATA:44
PN:822-1943-002	MOS/MSC	06-May-11	O/C	TSO 22					
SN:22BVT	HRS	2157.3		TSO 0					
	AFL	1140		TSO 0					

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 44 - CABIN SYSTEMS									
441007-702 ^U		SWITCH ETHERNET (MCE#2) EQUIPMENT						Component	ATA:44
PN:822-1943-002	MOS/MSC	06-May-11	O/C	TSO 22					
SN:22BYX	HRS	2157.3		TSO 0					
	AFL	1140		TSO 0					
441008-701 ^U		COOLING FAN (MCU) FS429 FAN						Component	ATA:44
PN:822-1916-001	MOS/MSC	07-Oct-05	O/C						
SN:26KVJ	HRS	0							
	AFL	0							
441008-702 ^U		COOLING FAN (MCU) FS477 FAN						Component	ATA:44
PN:822-1916-001	MOS/MSC	07-Oct-05	O/C						
SN:25VLH	HRS	0							
	AFL	0							
442001-701 ^U		ZONE DISTRIBUTION #1 EQUIPMENT						Component	ATA:44
PN:1308523-101	MOS/MSC	12-May-09	O/C	TSR 5					
SN:2VJGW	HRS	1101.5		TSR 0					
	AFL	627		TSR 0					
442001-702 ^U		ZONE DISTRIBUTION #2 EQUIPMENT						Component	ATA:44
PN:1308523-101	MOS/MSC	30-Sep-15	O/C						
SN:35VJY	HRS	4469							
	AFL	2318							
442001-703 ^U		ZONE DISTRIBUTION #3 EQUIPMENT						Component	ATA:44
PN:1308523-101	MOS/MSC	07-May-10	O/C	TSR 1					
SN:1HYBG	HRS	1594.8		TSR 0					
	AFL	882		TSR 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 44 - CABIN SYSTEMS									
442001-704	ZONE DISTRIBUTION #4 EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	19-Sep-12	O/C	TSR 14					
SN:35RXY	HRS	2863.9		TSR 0					
	AFL	1482		TSR 0					
442001-705	ZONE DISTRIBUTION #5 EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	26-Sep-21	O/C	TSO 1					
SN:1HY1H	HRS	7237.6		TSO 0					
	AFL	3796		TSO 0					
443252-701	KA MOD MAN - MODULE MANAGER								Component ATA:44
PN:90400012-001	MOS/MSC	15-Jun-17	O/C	TSN 0					
SN:000000325	HRS	5428.8		TSN 0					
	AFL	2792		TSN 0					
443252-702	KA KANDU - AIRCRAFT NETWORK DATA UNIT								Component ATA:44
PN:90401566	MOS/MSC	15-Jun-17	O/C	TSN 0					
SN:000000673	HRS	5428.8		TSN 0					
	AFL	2792		TSN 0					
443252-703	KA TMA - TAIL MOUNTED ANTENNA								Component ATA:44
PN:90400013-001	MOS/MSC	17-Apr-21	O/C						
SN:000000393	HRS	7073.8							
	AFL	3705							
443252-704	KA APM - AIRPLANE PERSONALITY MODULE								Component ATA:44
PN:90401121	MOS/MSC	15-Jun-17	O/C	TSN 0					
SN:000000549	HRS	5428.8		TSN 0					
	AFL	2792		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 44 - CABIN SYSTEMS

443252-705	U	KA KFRU - RADIO FREQUENCY UNIT						Component	ATA:44
PN:90406952	MOS/MSC	20-Jul-20	O/C	TSN 0					
SN:000001382	HRS	6911.6		TSN 0					
	AFL	3586		TSN 0					

ATA 45 - CENTRAL MAINT SYSTEM

45-45-00-201	S	VISUAL CHECK OF THE ENGINE MAINTENANCE ALERTS						Service	ATA:45
	MOS	13-Nov-24							
	HRS	8623.4	500 (+50/-50)						
	AFL	4570							

PROC. REF: AMM 71-00-00-210-803PROC. REF: AMM 71-00-00-210-803

PKG:2

454510-701	U	PMAT BATTERY PACK						Component	ATA:45
PN:7037534-400	MOS/MSC	18-Jul-23	O/C	TSN 0					
SN:NSN	HRS	7923.9		TSN 0					
	AFL	4211		TSN 0					

459910-701	U	PMAT UNIT						Component	ATA:45
PN:7023300-801	MOS/MSC	26-Feb-25	O/C	TSR 1					
SN:09100622	HRS	8641.1		TSR 0					
	AFL	4580		TSR 0					

ATA 49 - AIRBORNE AUXILIARY POWER

49-11-00-201	S	VISUAL CHECK OF THE SUPPORT MOUNTINGS						Service	ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.005	AFL	4582							

PROC. REF: AMM 49-11-00-210-801PROC. REF: AMM 49-11-00-210-801

PKG:32

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49-11-01-201	^S	VISUAL CHECK OF THE MOUNTING STRUTS							Service ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.010	AFL	4582							
PROC. REF: AMM 49-11-01-210-801PROC. REF: AMM 49-11-01-210-801									
49-14-05-101		DISCARD THE APU DOOR LINEAR ACTUATOR, PART NO. 8653M9 (AWL*)							Service ATA:49
PN:7082114-2	MOS/MSC	18-Jun-17	N/A						
SN:09020047	HRS	5437							
	AFL	2796							
PROC. REF: AMM 49-14-05-961-801PROC. REF: AMM 49-14-05-961-801									
49-14-05-900-801-01		LINEAR ACTUATOR							Component ATA:49
PN:7082114-2	MOS/MSC	18-Jun-17	O/C	TSR 1					
SN:09020047	HRS	5437		TSR 0					
WC#: 49.040	AFL	2796		TSR 0					
PROC. REF: AMM 49-14-05-000-801, AMM 49-14-05-400-801PROC. REF: AMM 49-14-05-000-801, AMM 49-14-05-400-801									
49-15-00-201	^S	GENERAL VISUAL INSPECTION OF THE OIL-COOLER DUCT AND BOOT ASSEMBLY							Service ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.015	AFL	4582							
PROC. REF: AMM 49-15-00-210-801PROC. REF: AMM 49-15-00-210-801									
49-15-09-201	^S	GENERAL VISUAL INSPECTION OF THE INLET DUCT AND BOOT ASSEMBLY							Service ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.020	AFL	4582							
PROC. REF: AMM 49-15-00-210-802PROC. REF: AMM 49-15-00-210-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49-18-00-201	S	APU - GENERAL VISUAL INSPECTION OF THE APU DRAIN LINES						Service	ATA:49
	MOS	14-Aug-25						MRB	
	HRS	9615	1000 (+50/-50)						
	APUS	8333							
PKG:1000									
PROC. REF: AMM 49 18 00 210 801, AMM 49-18-00, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801PROC. REF: AMM 49 18 00 210 801, AMM 49-18-00, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801, AMM 49-18-00-210-801									
49-21-00-301		APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (PRE SB RE220-49-7813)						Service	ATA:49
	MOS/MS	08-May-10	N/A					OPTIONAL	
	HRS	1920							
	APUS	1658							
PROC. REF: AMM 49 21 00 170 801, AMM 49-21-00, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801PROC. REF: AMM 49 21 00 170 801, AMM 49-21-00, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801									
49-21-00-302		APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (POST SB RE220-49-7813 AND APU S/N P-286 AND SUBS)						Service	ATA:49
	MOS	25-May-23						OPTIONAL	
	HRS	8804	2000 (+50/-50)		10804	10854	1132 (+50)		
	APUS	7582							
PROC. REF: AMM 49 21 00 170 801, AMM 49-21-00, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801PROC. REF: AMM 49 21 00 170 801, AMM 49-21-00, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801, AMM 49-21-00-170-801									
49-30-00-204	S	APU - GENERAL VISUAL INSPECTION OF THE APU FUEL-SYSTEM COMPONENTS						Service	ATA:49
	MOS	14-Aug-25						MRB	
	HRS	9615	1000 (+50/-50)						
	APUS	8333							
PKG:1000									
PROC. REF: AMM 49 30 00 210 804, AMM 49-30-00, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804PROC. REF: AMM 49 30 00 210 804, AMM 49-30-00, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804, AMM 49-30-00-210-804									
49-42-00-301	S	APU - CLEANING OF THE STARTER MOTOR OF BRUSH DUST MATERIAL						Service	ATA:49
	MOS	16-May-24						OPTIONAL	
	HRS	9274	750 (+50/-50)						
	APUS	8001							
PKG:750									
PROC. REF: AMM 49 42 01 110 801, AMM 49-42-01, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801PROC. REF: AMM 49 42 01 110 801, AMM 49-42-01, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801, AMM 49-42-01-110-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49-42-01-201	APU - DETAILED INSPECTION OF THE STARTER MOTOR								Service ATA:49
	MOS	14-Aug-25						MRB	
	HRS	9615	1000 (+50/-50)	Adj 50	10665	10715	993 (+50)		
	APUS	8333							
PROC. REF: AMM 49 42 01 220 801, AMM 49-42-01, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801 AMM 49-42-01, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801, AMM 49-42-01-220-801 PKG:1000									
49-52-00-301	APU - CLEANING OF THE LOAD-CONTROL-VALVE INLET FILTER (LOAD CONTROL VALVE P/N 3291210-3)								Service ATA:49
	MOS/MSC	30-Jun-21	N/A						
	HRS	7850		Adj 50					
	APUS	6826							
PROC. REF: AMM 49 52 05 160 801, AMM 49-52-05, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801 PROC. REF: AMM 49 52 05 160 801, AMM 49-52-05, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801, AMM 49-52-05-160-801									
49-61-01-900-801-01	FADEC CONTROLLER								Component ATA:49
PN:2118990-3	MOS/MSC	24-Jan-11	O/C						
SN:87-K0247	HRS	1975.1							
WC#: 49.045	AFL	1065							
PROC. REF: AMM 49-61-01-000-801, AMM 49-61-01-400-801PROC. REF: AMM 49-61-01-000-801, AMM 49-61-01-400-801									
49-62-00-201	APU - OPERATIONAL TEST OF THE APU EMERGENCY SHUTDOWN (APU SHUTDOWN SWITCH AND AFT SERVICE CONTROL PANEL APU SHUT-OFF SWITCH)								Service ATA:49
	MOS	21-Feb-24						MRB	
	HRS	9165	2250 (+50/-50)	Adj 50	11465	11515	1793 (+50)		
	APUS								
PROC. REF: AMM 49 62 00 710 802, AMM 49-62-00, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802 PROC. REF: AMM 49 62 00 710 802, AMM 49-62-00, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802, AMM 49-62-00-710-802									
49-70-00-201 ^S	VISUAL CHECK OF THE APU INDICATING SYSTEM								Service ATA:49
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 49.025	AFL	4582							
PROC. REF: AMM 49-70-00-210-801PROC. REF: AMM 49-70-00-210-801 PKG:4									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49-80-04-900-801-01	APU EXHAUST DUCT ASSY (LOWER) INSULATION							Component	ATA:49
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
49-80-05-201 ^S	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT							Service	ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.030	AFL	4582							
PROC. REF: AMM 49-80-05-210-801PROC. REF: AMM 49-80-05-210-801									
49-80-05-900-801-01	THERMAL BLANKET							Component	ATA:49
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
49-80-05-900-802-01	EXHAUST TAILPIPE DUCT							Component	ATA:49
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.060	AFL	0		TSN 0					
PROC. REF: AMM 49-80-05-000-801, AMM 49-80-05-400-801PROC. REF: AMM 49-80-05-000-801, AMM 49-80-05-400-801									
49-80-09-201 ^S	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT SEAL							Service	ATA:49
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 49.035	AFL	4582							
PROC. REF: AMM 49-80-09-210-801PROC. REF: AMM 49-80-09-210-801									
49-90-00-204 ^S	APU - GENERAL VISUAL INSPECTION OF THE APU OIL-SYSTEM COMPONENTS							Service	ATA:49
	MOS	14-Aug-25						MRB	
	HRS	9615	1000 (+50/-50)						
	APUS	8333							
PKG:1000									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
PROC. REF: AMM 49 90 00 210 804, AMM 49-90-00, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804PROC. REF: AMM 49 90 00 210 804, AMM 49-90-00, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804, AMM 49-90-00-210-804									
49-90-29-201	S	APU - DISCARD THE APU OIL-FILTER ELEMENT						Service	ATA:49
	MOS	31-May-24						MRB	
	HRS	9293	1500 (+50/-50)						
	APUS	8017							
PKG:1500									
PROC. REF: AMM 49 90 29 961 801, AMM 49-90-29, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801PROC. REF: AMM 49 90 29 961 801, AMM 49-90-29, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801, AMM 49-90-29-961-801									
49-90-29-202	S	APU - DISCARD THE APU-GENERATOR SCAVENGE-OIL FILTER-ELEMENT						Service	ATA:49
	MOS	31-May-24						MRB	
	HRS	9293	1500 (+50/-50)						
	APUS	8017							
PKG:1500									
PROC. REF: AMM 49 90 29 961 802, AMM 49-90-29, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802PROC. REF: AMM 49 90 29 961 802, AMM 49-90-29, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802, AMM 49-90-29-961-802									
490001-701	U	APU EXHAUST DUCT SUPPORT						Component	ATA:49
PN:GA453-0009-1	MOS/MSC	26-Feb-25	O/C	TSR 0					
SN:N/A	HRS	8641.1		TSR 0					
	AFL	4580		TSR 0					
490002-001		APU - WIRING HARNESS						Component	ATA:49
PN:WE3888471-1	MOS/MSC	15-Jun-17	O/C	TSN 0					
SN:16-162599-02031	HRS	5932		TSN 0					
	APUS	5077		TSN 0					
PROC. REF: AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801PROC. REF: AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801, AMM 49-12-01-000-801, AMM 49-12-01-400-801									
492001-001	U	APU - COMPRESSOR IMPELLER						Component	ATA:49
PN:WB3822573-1	MOS			TSN 0				LIFE LIMIT	
SN:050350100287	HRS			TSN 0					
	APUS	0	20000	TSN 0	20000	20000	11606		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
492002-001	APU - FIRST STAGE TURBINE ROTOR ASSEMBLY							Component	ATA:49
PN:WK3840141-3	MOS			TSN 0				LIFE LIMIT	
SN:052241000920	HRS			TSN 0					
	APUS	0	20000	TSN 0	20000	20000	11606		
PROC. REF: AMM 49-10-00, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802PROC. REF: AMM 49-10-00, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802, AMM 49-10-00-961-802									
492003-001	APU - SECOND STAGE TURBINE ROTOR ASSEMBLY							Component	ATA:49
PN:WE897994-3	MOS			TSN 0				LIFE LIMIT	
SN:050134501014	HRS			TSN 0					
	APUS	0	20000	TSN 0	20000	20000	11606		
PROC. REF: AMM 49-10-00, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801PROC. REF: AMM 49-10-00, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801, AMM 49-10-00-961-801									
493001-001	APU - FUEL CONTROL UNIT FCU							Component	ATA:49
PN:441950-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:CUB20314	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801PROC. REF: AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801, AMM 49-30-01-400-801, AMM 49-30-01-000-801, AMM 49-30-01-000-801, AMM 49-30-01-400-801									
493001-001 ^U	FUEL CONTROL UNIT FCU							Component	ATA:49
PN:441950-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:CUB20314	HRS	0		TSN 0					
	AFL	0		TSN 0					
493002-701 ^U	APU - FUEL SOLENOID SHUT-OFF VALVE							Component	ATA:49
PN:WE3883738-2	MOS/MSC	11-Nov-19	O/C	TSO 9					
SN:T#01386	HRS	7241		TSO 0					
	APUS	6302		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 49 - AIRBORNE AUXILIARY POWER										
494001-002		APU - STARTER MOTOR							Component	ATA:49
PN:2704554-3	MOS/MSC	15-May-18	O/C	TSO 13						
SN:3051	HRS	6450		TSO 0						
	APUS	5555		TSO 0						
PROC. REF: AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801 AMM 49-42-01-000-801PROC. REF: AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801, AMM 49-42-01-400-801, AMM 49-42-01-000-801 AMM 49-42-01-400-801, AMM 49-42-01-000-801										
494101-001		APU - IGNITION EXCITER							Component	ATA:49
PN:WE3876295-6	MOS/MSC	21-Mar-23	O/C	TSO 1						
SN:J11380161	HRS	8721		TSO 0						
	APUS	7521		TSO 0						
PROC. REF: AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801 AMM 49-41-01-400-801PROC. REF: AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801, AMM 49-41-01-400-801, AMM 49-41-01-000-801 AMM 49-41-01-000-801, AMM 49-41-01-400-801										
494101-001 ^U		IGNITION EXCITER							Component	ATA:49
PN:WE3876295-5	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:050218053919	HRS	0		TSN 0						
	AFL	0		TSN 0						
495101-001		APU - SURGE VALVE							Component	ATA:49
PN:3291212-4	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:647	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801 AMM 49-51-01-400-801PROC. REF: AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801, AMM 49-51-01-400-801, AMM 49-51-01-000-801 AMM 49-51-01-000-801, AMM 49-51-01-400-801										
495205-001		APU - LOAD CONTROL VALVE							Component	ATA:49
PN:3291210-5	MOS/MSC	10-Jun-19	O/C							
SN:574	HRS	7060								
	APUS	6101								
PROC. REF: AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801 AMM 49-52-05-400-801PROC. REF: AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801, AMM 49-52-05-400-801, AMM 49-52-05-000-801 AMM 49-52-05-000-801, AMM 49-52-05-400-801										

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
496102-001	APU - INLET PRESSURE SENSOR							Component	ATA:49
PN:WE3876283-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801PROC. REF: AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801, AMM 49-61-13-000-801, AMM 49-61-13-400-801									
496103-001	APU - SPEED SENSOR							Component	ATA:49
PN:WE3876281-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801PROC. REF: AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801, AMM 49-61-17-000-801, AMM 49-61-17-400-801									
496105-001	APU - NO. 1 EXHAUST GAS TEMPERATURE SENSOR							Component	ATA:49
PN:WE3876352-2	MOS/MSC	10-Aug-17	O/C	TSN 0					
SN:N/A	HRS	6008		TSN 0					
	APUS	5140		TSN 0					
PROC. REF: AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801PROC. REF: AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801									
496105-002	APU - NO. 2 EXHAUST GAS TEMPERATURE SENSOR							Component	ATA:49
PN:WE3876352-2	MOS/MSC	01-May-12	O/C						
SN:MFR50413-1101229	HRS	3082							
	APUS								
PROC. REF: AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801PROC. REF: AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801, AMM 49-61-05-000-801, AMM 49-61-05-400-801									
499001-001	APU - OIL COOLER							Component	ATA:49
PN:160534-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:976	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801PROC. REF: AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801, AMM 49-90-37-000-801, AMM 49-90-37-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
499002-001	APU - LUBE PUMP							Component	ATA:49
PN:WE3881781-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:VE1835	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
499035-001	APU - DIFFERENTIAL PRESSURE-GENERATOR SWITCH							Component	ATA:49
PN:WE3876294-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	APUS	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
499053-001	APU - APU GEARBOX							Component	ATA:49
PN:WK3805055-6	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:052241000006	HRS	0		TSN 0					
	APUS	0		TSN 0					
499110	APU - SOAP OIL CHECK							Service	ATA:49
	MOS	31-May-24							
	HRS	9293	500 (+20%/-20%)	9793	9893	121 (+100)			
	APUS	8017							
49APU1	APU							Component	ATA:49
PN:WE3800714-1	MOS/MSC		E/C						
SN:P-299	HRS								
WC#: 49.APU1	AFL								
PROC. REF: AMM 49-10-00-000-801, AMM 49-10-00-400-801PROC. REF: AMM 49-10-00-000-801, AMM 49-10-00-400-801									
ATA 52 - DOORS									
52-10-00-207	LUBRICATION OF THE PASSENGER DOOR							Service	ATA:52
	MOS	29-May-24						MRB	
	HRS	8252.8	1500 (+50/-50)	9752.8	9802.8	834.2 (+50)			
	AFL	4411							
PROC. REF: AMM 12-22-00-640-808PROC. REF: AMM 12-22-00-640-808									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-11-00-101	DETAILED INSPECTION OF THE OUTER SKIN OF THE PASSENGER DOOR (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.005	AFL	0	T:5255		5255		548		
PROC. REF: AMM 52-11-00-220-803PROC. REF: AMM 52-11-00-220-803									
52-11-00-102	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE FRAMES (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.010	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-52-10-001PROC. REF: NDT ET-52-10-001									
52-11-00-103	DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE-FRAMES, STOPS, SKIN AND STIFFENERS - INTERNAL (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.015	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 52-11-00-220-806PROC. REF: AMM 52-11-00-220-806									
52-11-00-105 ^S	GENERAL VISUAL INSPECTION OF THE SKIN EXTERNAL SURFACE (AWL*)							Service	ATA:52
	MOS	16-Jun-20						HASC	
	HRS	6911.6							
	AFL	3586	3750						
PROC. REF: AMM 52-11-00-210-808PROC. REF: AMM 52-11-00-210-808									
52-11-00-106	VISUAL CHECK OF THE PASSENGER-DOOR VENT-FLAP MECHANISM (CMR*)							Service	ATA:52
	MOS	13-Nov-24						AIRWORTHINESS	
	HRS	8623.4	500		9123.4		204.8		
	AFL	4570							
PROC. REF: AMM 52-11-00-210-807PROC. REF: AMM 52-11-00-210-807									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-11-00-201	^S	FUNCTIONAL TEST OF THE PASSENGER DOOR MECHANISM							Service ATA:52
	MOS	11-May-24						MRB	
	HRS	8243.1	2250 (+50/-50)						
WC#: 52.025	AFL	4401							
PROC. REF: AMM 52-11-00-720-801PROC. REF: AMM 52-11-00-720-801									
52-11-00-202	^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR							Service ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.030	AFL	4582							
PROC. REF: AMM 52-11-00-220-801PROC. REF: AMM 52-11-00-220-801									
52-11-00-203	^S	DETAILED INSPECTION OF THE STOPS AND ABUTMENTS OF THE PASSENGER DOOR							Service ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.035	AFL	4582							
PROC. REF: AMM 52-11-00-220-802PROC. REF: AMM 52-11-00-220-802									
52-11-00-900-801-01		PASSENGER DOOR ASSY							Component ATA:52
PN:GS328-0010-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:SB/GX/C033	HRS	0		TSN 0					
WC#: 52.170	AFL	0		TSN 0					
PROC. REF: AMM 52-11-00-000-801, AMM 52-11-00-400-801PROC. REF: AMM 52-11-00-000-801, AMM 52-11-00-400-801									
52-11-00-900-802-01		PASSENGER DOOR ACTUATOR MOTOR							Component ATA:52
PN:GS321-0591-9	MOS/MSC	14-Aug-25	O/C	TSR 0					
SN:G0800	HRS	8645		TSR 0					
WC#: 52.175	AFL	4582		TSR 0					
PROC. REF: AMM 52-11-00-000-801, AMM 52-11-00-400-801, AMM 52-11-25-000-801, AMM 52-11-25-400-801PROC. REF: AMM 52-11-00-000-801, AMM 52-11-00-400-801, AMM 52-11-25-000-801, AMM 52-11-25-400-801									
52-11-21-201	^S	DETAILED INSPECTION OF THE HANDRAILS ATTACHMENT TO THE FUSELAGE							Service ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.050	AFL	4582							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 52 - DOORS									
PROC. REF: AMM 52-11-21-220-801PROC. REF: AMM 52-11-21-220-801									

52-11-25-101	RESTORATION OF THE PASSENGER DOOR ACTUATOR MOTOR, PART NO. GS321-0591-9 (GEARHEAD, PART NO. 2H4A321809A) (AWL*)							Service	ATA:52
PN:GS321-0591-9	MOS	14-Aug-25						RESTORE	
SN:G0800	HRS	8645							
	AFL	4582	850		5432		725		
PROC. REF: AMM 52-11-25-610-801PROC. REF: AMM 52-11-25-610-801									

52-11-29-900-801-01	PASSENGER DOOR AIRSTAIR							Component	ATA:52
PN:GS328-0009-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:GBGX11033	HRS	0		TSN 0					
WC#: 52.180	AFL	0		TSN 0					
PROC. REF: AMM 52-11-29-000-801, AMM 52-11-29-400-801PROC. REF: AMM 52-11-29-000-801, AMM 52-11-29-400-801									

52-11-41-101	DISCARD THE NO. 1 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1 (AWL*)							Service	ATA:52
PN:GS321-0580-1	MOS	11-May-24						LIFE LIMIT	
SN:10645	HRS	8243.1							
	AFL	4401	650		5051		344		
PROC. REF: AMM 52-11-41-961-801PROC. REF: AMM 52-11-41-961-801									

52-11-41-101	DISCARD THE NO. 2 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1 (AWL*)							Service	ATA:52
PN:GS321-0580-1	MOS	11-May-24						LIFE LIMIT	
SN:10646	HRS	8243.1							
	AFL	4401	650		5051		344		
PROC. REF: AMM 52-11-41-961-801PROC. REF: AMM 52-11-41-961-801									

52-11-41-101	DISCARD THE NO. 3 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1 (AWL*)							Service	ATA:52
PN:GS321-0580-1	MOS	11-May-24						LIFE LIMIT	
SN:10647	HRS	8243.1							
	AFL	4401	650		5051		344		
PROC. REF: AMM 52-11-41-961-801PROC. REF: AMM 52-11-41-961-801									

52-11-41-101	DISCARD THE NO. 4 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1 (AWL*)							Service	ATA:52
PN:GS321-0580-1	MOS	11-May-24						LIFE LIMIT	
SN:10649	HRS	8243.1							
	AFL	4401	650		5051		344		
PROC. REF: AMM 52-11-41-961-801PROC. REF: AMM 52-11-41-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 52 - DOORS

52-11-41-900-801-01	NO. 1 PASSENGER DOOR TENSATOR SPRING							Component	ATA:52
PN:GS321-0580-1	MOS/MSC	11-May-24	H/T	TSN 9					
SN:10645	HRS	8243.1		TSN 0					
	AFL	4401		TSN 0					
PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801									

52-11-41-900-801-02	NO. 2 PASSENGER DOOR TENSATOR SPRING							Component	ATA:52
PN:GS321-0580-1	MOS/MSC	11-May-24	H/T	TSN 9					
SN:10646	HRS	8243.1		TSN 0					
	AFL	4401		TSN 0					
PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801									

52-11-41-900-801-03	NO. 3 PASSENGER DOOR TENSATOR SPRING							Component	ATA:52
PN:GS321-0580-1	MOS/MSC	11-May-24	H/T	TSN 9					
SN:10647	HRS	8243.1		TSN 0					
	AFL	4401		TSN 0					
PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801									

52-11-41-900-801-04	NO. 4 PASSENGER DOOR TENSATOR SPRING							Component	ATA:52
PN:GS321-0580-1	MOS/MSC	11-May-24	H/T	TSN 9					
SN:10649	HRS	8243.1		TSN 0					
	AFL	4401		TSN 0					
PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801PROC. REF: AMM 52-11-41-000-801, AMM 52-11-41-400-801									

52-21-00-103 ^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE OVERWING EMERGENCY EXIT (AWL*)							Service	ATA:52
	MOS	10-Jun-20						HASC	
	HRS	6911.6							
WC#: 52.085	AFL	3586	3750						
									PKG:75
PROC. REF: AMM 52-21-00-210-803PROC. REF: AMM 52-21-00-210-803									

52-21-00-104	DETAILED INSPECTION OF THE OVER-WING EMERGENCY EXIT DOOR (AWL*)							Service	ATA:52
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500	7500			2793		
									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
PROC. REF: AMM 52-21-00-220-803PROC. REF: AMM 52-21-00-220-803									
52-21-00-201	^S	OPERATIONAL TEST OF THE OVER-WING EMERGENCY-EXIT						Service	ATA:52
	MOS	14-Aug-25	15 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.060	AFL	4582							
									PKG:31
PROC. REF: AMM 52-21-00-710-801PROC. REF: AMM 52-21-00-710-801									
52-21-00-202	^S	FUNCTIONAL TEST OF THE OVER-WING EMERGENCY-EXIT EXIT PULL SIGN						Service	ATA:52
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.065	AFL	4582							
									PKG:32
PROC. REF: AMM 52-21-00-720-802PROC. REF: AMM 52-21-00-720-802									
52-21-00-203	^S	LUBRICATION OF THE OVER-WING EMERGENCY-EXIT DOOR						Service	ATA:52
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.070	AFL	4582							
									PKG:32
PROC. REF: AMM 12-22-00-640-805PROC. REF: AMM 12-22-00-640-805									
52-21-00-204	^S	DETAILED INSPECTION OF THE LATCH FITTINGS AND DOOR STOP FITTINGS OF THE OVER- WING EMERGENCY EXIT						Service	ATA:52
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.075	AFL	4582							
									PKG:34
PROC. REF: AMM 52-21-00-220-801PROC. REF: AMM 52-21-00-220-801									
52-21-00-205	^S	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE OVER-WING EMERGENCY EXIT						Service	ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.080	AFL	4582							
									PKG:38
PROC. REF: AMM 52-21-00-220-802PROC. REF: AMM 52-21-00-220-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-21-00-900-801-01	OVERWING EMERGENCY EXIT DOOR ASSY							Component	ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.185	AFL	0		TSN 0					
PROC. REF: AMM 52-21-00-000-801, AMM 52-21-00-400-801PROC. REF: AMM 52-21-00-000-801, AMM 52-21-00-400-801									
52-30-00-101	DETAILED INSPECTION OF THE BAGGAGE DOOR (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.090	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 52-30-00-220-809PROC. REF: AMM 52-30-00-220-809									
52-30-00-105	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SKIN BETWEEN DOOR UPPER SKIN EDGE AND VENT DOOR (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.110	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-52-31-001PROC. REF: NDT ET-52-31-001									
52-30-00-106	DETAILED INSPECTION OF THE VENT DOOR OF THE BAGGAGE DOOR (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 52.115	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 52-30-00-220-808PROC. REF: AMM 52-30-00-220-808									
52-30-00-107	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR (AWL*)							Service	ATA:52
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-52-30-002PROC. REF: NDT ET-52-30-002									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-30-00-108	^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL SURFACE OF THE BAGGAGE DOOR SKIN INCLUDING DOOR HANDLE RECESS (AWL*)						Service	ATA:52
	MOS	16-Jun-20						HASC	
	HRS	6911.6							
WC#: 52.130	AFL	3586	3750						
PROC. REF: AMM 52-30-00-210-806PROC. REF: AMM 52-30-00-210-806									
52-30-00-201	^S	DETAILED INSPECTION OF THE SURROUND ANGLES AND STOP FITTINGS OF THE BAGGAGE DOOR						Service	ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.120	AFL	4582							
PROC. REF: AMM 52-30-00-220-803PROC. REF: AMM 52-30-00-220-803									
52-30-00-202	^S	DETAILED INSPECTION OF THE INTERNAL SUPPORT STRUCTURE OF THE BAGGAGE DOOR						Service	ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.125	AFL	4582							
PROC. REF: AMM 52-30-00-220-805PROC. REF: AMM 52-30-00-220-805									
52-30-00-301	^S	LUBRICATION OF THE BAGGAGE DOOR						Service	ATA:52
	MOS	14-Aug-25	30 (+3m/-3m)					OPTIONAL	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 12-22-00-640-806PROC. REF: AMM 12-22-00-640-806									
52-31-01-900-801-01		BAGGAGE COMPARTMENT DOOR ASSY						Component	ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.190	AFL	0		TSN 0					
PROC. REF: AMM 52-31-01-000-801, AMM 52-31-01-400-801PROC. REF: AMM 52-31-01-000-801, AMM 52-31-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-31-09-101	DETAILED INSPECTION OF THE BAGGAGE DOOR SEAL (CMR**)								Service ATA:52
	MOS	14-Aug-25	15 (+3m/-3m)	Adj 3	14-Feb-27	14-May-27	234 d (+89)	CMR	
	HRS	8645							
WC#: 52.135	AFL	4582							
PROC. REF: AMM 52-31-09-220-801PROC. REF: AMM 52-31-09-220-801									
52-41-00-201 ^S	DETAILED INSPECTION OF THE AFT EQUIPMENT-COMPARTMENT DOOR SEAL								Service ATA:52
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.140	AFL	4582							
PROC. REF: AMM 52-41-09-220-801PROC. REF: AMM 52-41-09-220-801									
52-41-00-900-801-01	REAR EQUIPMENT BAY DOOR								Component ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.195	AFL	0		TSN 0					
PROC. REF: AMM 52-41-00-000-801, AMM 52-41-00-400-801PROC. REF: AMM 52-41-00-000-801, AMM 52-41-00-400-801									
52-42-01-900-801-01	FORWARD EQUIPMENT COMPARTMENT DOOR								Component ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.215	AFL	0		TSN 0					
PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801									
52-43-01-900-801-01	LH ASSY - ACCESS DOOR								Component ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.200	AFL	0		TSN 0					
PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801									
52-43-01-900-801-02	RH ASSY - ACCESS DOOR								Component ATA:52
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 52.200	AFL	0		TSN 0					
PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801PROC. REF: AMM 52-42-01-000-801, AMM 52-42-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
52-44-25-900-801-01	CASTING DOOR								Component ATA:52
PN:GD236-5060-11	MOS/MSC	26-Feb-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8641.1		TSN 0					
WC#: 52.205	AFL	4580		TSN 0					
PROC. REF: AMM 52-44-25-000-801, AMM 52-44-25-400-801PROC. REF: AMM 52-44-25-000-801, AMM 52-44-25-400-801									
52-44-37-900-801-01	DOOR CASTING								Component ATA:52
PN:GD236-3020-11	MOS/MSC	26-Feb-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8641.1		TSN 0					
WC#: 52.210	AFL	4580		TSN 0					
PROC. REF: AMM 52-44-37-000-801, AMM 52-44-37-400-801PROC. REF: AMM 52-44-37-000-801, AMM 52-44-37-400-801									
52-71-50-601 ^{U S}	OPERATIONAL TEST OF THE CABIN DOOR ANNUNCIATION SYSTEM								Service ATA:52
	MOS	14-Aug-25	15					STLMC	
	HRS	8645							
	AFL	4582							
PKG:31									
52-ZL-00-201 ^S	GENERAL VISUAL INSPECTION OF THE OVER-WING EMERGENCY EXIT - EXTERNAL								Service ATA:52
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.145	AFL	4582							
PKG:34									
PROC. REF: SPM 20-70-00-210-801, AMM 52-21-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 52-21-00-210-804									
52-ZL-00-202 ^S	GENERAL VISUAL INSPECTION OF THE LATCH MECHANISM OF THE OVER-WING EMERGENCY EXIT								Service ATA:52
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.150	AFL	4582							
PKG:34									
PROC. REF: SPM 20-70-00-210-801, AMM 52-21-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 52-21-00-210-802									
52-ZL-00-203 ^S	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - INBOARD SIDE								Service ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.155	AFL	4582							
PKG:38									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 52 - DOORS

PROC. REF: SPM 20-70-00-210-801, AMM 52-30-00-210-807PROC. REF: SPM 20-70-00-210-801, AMM 52-30-00-210-807

52-ZL-00-204	S	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - OUTBOARD SIDE						Service	ATA:52
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 52.160	AFL	4582							
									PKG:38
PROC. REF: SPM 20-70-00-210-801, AMM 52-30-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 52-30-00-210-804									

52-ZL-00-205		GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - EXTERNAL						Service	ATA:52
	MOS	14-Aug-25	24 (+3m/-3m)	Adj 3	14-Nov-27	14-Feb-28	507 d (+92)	MRB	
	HRS	8645							
WC#: 52.165	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 52-11-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 52-11-00-210-801									

521161-701	U	DOOR STEP ACTUATOR						Component	ATA:52
PN:GS321-0988-3	MOS/MSC	07-May-13	O/C						
SN:0121	HRS	3138.2							
	AFL	1658							

ATA 53 - FUSELAGE									
53-10-00-101		DETAILED INSPECTION OF THE FLOOR ATTACHMENT TO THE BULKHEAD FS202.00 (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.005	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-819PROC. REF: AMM 53-10-00-220-819									

53-10-00-102		DETAILED INSPECTION OF THE LANDING GEAR BOX (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.010	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-820PROC. REF: AMM 53-10-00-220-820									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-103	DETAILED INSPECTION OF THE FLOOR ATTACHMENT TO THE BULKHEAD, FS202.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.015	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-821PROC. REF: AMM 53-10-00-220-821									
53-10-00-104	DETAILED INSPECTION OF THE BULKHEAD FS202.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.020	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-822PROC. REF: AMM 53-10-00-220-822									
53-10-00-105	GENERAL VISUAL INSPECTION OF THE FRAME FS251.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.025	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-210-822PROC. REF: AMM 53-10-00-210-822									
53-10-00-106	SPECIAL DETAILED INSPECTION OF THE FRAME FS280.00 - EXTERNAL (AWL*)							Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 53.030	AFL	EFF	T:7500		7500 *		2793		
									PKG:76
PROC. REF: NDT ET-53-10-004, NDT RT-53-10-001PROC. REF: NDT ET-53-10-004, NDT RT-53-10-001									
53-10-00-107	DETAILED INSPECTION OF THE FRAME FS280.00 - INTERNAL (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.035	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-825PROC. REF: AMM 53-10-00-220-825									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10

Serial: 9175

RegNo: N117TP

HRS: 8918.6

AFL: 4707

As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-108	SPECIAL DETAILED INSPECTION OF THE SPLICE AT STRINGERS 16A AND 23 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.040	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-10-005PROC. REF: NDT ET-53-10-005									
53-10-00-109	DETAILED INSPECTION OF THE SHEET METAL FRAME FS210.00, FS220.00, FS235.00, FS265.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.045	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-826PROC. REF: AMM 53-10-00-220-826									
53-10-00-110	DETAILED INSPECTION OF THE STRINGERS 16A AND 23 FROM FS202.00 TO FS280.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.050	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-827PROC. REF: AMM 53-10-00-220-827									
53-10-00-112	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUND STRUCTURE (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.060	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-10-006, NDT ET-53-10-007PROC. REF: NDT ET-53-10-006, NDT ET-53-10-007									
53-10-00-114	DETAILED INSPECTION OF THE COCKPIT SKIN PANELS (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-10-00-220-840PROC. REF: AMM 53-10-00-220-840									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-115		SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW CENTER POST (AWL*)						Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-53-10-001PROC. REF: NDT ET-53-10-001									PKG:76
53-10-00-116		SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW LOWER SILL AT THE CENTER POST ATTACHMENT NEAR BLO (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:6620		6620		1913		
PROC. REF: NDT ET-53-10-002PROC. REF: NDT ET-53-10-002									
53-10-00-117 ^S		DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD FS202.75, ABOVE FLOOR (AWL*)						Service	ATA:53
	MOS	22-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.125	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-836PROC. REF: AMM 53-10-00-220-836									PKG:75
53-10-00-118 ^S		DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD FS202.75 WEB, BELOW FLOOR (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.130	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-811PROC. REF: AMM 53-10-00-220-811									PKG:75
53-10-00-119 ^S		GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN FS169.00 TO FS280.00 (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.135	AFL	3586	3750						
PROC. REF: AMM 53-10-00-210-802PROC. REF: AMM 53-10-00-210-802									PKG:75

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-120	^S	DETAILED INSPECTION OF THE LONGITUDINAL AND CIRCUMFERENTIAL SKIN JOINTS FS202.75 TO FS280.00 (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.140	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-814PROC. REF: AMM 53-10-00-220-814									
53-10-00-121	^S	DETAILED INSPECTION OF THE NLG AND PRESSURIZED PANEL CUTOUT SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.145	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-815PROC. REF: AMM 53-10-00-220-815									
53-10-00-122	^S	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW CUTOUT SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.150	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-816PROC. REF: AMM 53-10-00-220-816									
53-10-00-123	^S	DETAILED INSPECTION OF THE PRESSURIZED SURFACES OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.155	AFL	3586	3750						
PROC. REF: AMM 53-10-00-220-818PROC. REF: AMM 53-10-00-220-818									
53-10-00-124		DETAILED INSPECTION OF THE ACCESS PANEL SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T: 7500		7500		2793		
PROC. REF: AMM 53-10-00-220-839PROC. REF: AMM 53-10-00-220-839									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-125		DETAILED INSPECTION OF THE SKIN SPLICE FS280.00 - EXTERNAL (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-10-00-220-841PROC. REF: AMM 53-10-00-220-841									PKG:76
53-10-00-126		DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUNDSTRUCTURE, GUSSET AND SIDE PLATES (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:6639		6639		1932		
PROC. REF: AMM 53-10-00-220-842PROC. REF: AMM 53-10-00-220-842									
53-10-00-201 ^S		DETAILED INSPECTION OF THE INTERNAL STRUCTURE FS169.00 TO FS202.75, ABOVE FLOOR						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.070	AFL	4582							
PROC. REF: AMM 53-10-00-220-835PROC. REF: AMM 53-10-00-220-835									PKG:34
53-10-00-202 ^S		DETAILED INSPECTION OF THE INTERNAL STRUCTURE FS169.00 TO FS202.75, BELOW FLOOR						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.075	AFL	4582							
PROC. REF: AMM 53-10-00-220-837PROC. REF: AMM 53-10-00-220-837									PKG:34
53-10-00-203 ^S		DETAILED INSPECTION OF THE INTERNAL FORWARD FUSELAGE SKIN/STRUCTURE AND FS280.00 BULKHEAD FORWARD FACE FS202.75 TO FS280.00, ABOVE WL79.50						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.080	AFL	4582							
PROC. REF: AMM 53-10-00-220-833PROC. REF: AMM 53-10-00-220-833									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-205	^S	DETAILED INSPECTION OF THE PILOT AND COPILOT SEAT TRACKS							Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.090	AFL	4582							
PROC. REF: AMM 53-10-00-220-813PROC. REF: AMM 53-10-00-220-813									
53-10-00-207	^S	DETAILED INSPECTION OF THE FLOOR STRUCTURE FS202.75 TO FS280.00							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.100	AFL	4582							
PROC. REF: AMM 53-10-00-220-807PROC. REF: AMM 53-10-00-220-807									
53-10-00-208	^S	DETAILED INSPECTION OF THE FORWARD JACKING POINT FS278.00							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.105	AFL	4582							
PROC. REF: AMM 53-10-00-220-834PROC. REF: AMM 53-10-00-220-834									
53-10-00-209		DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW SURROUND STRUCTURE AND RETAINERS							Service ATA:53
	MOS	23-Jun-20	120 (+3m/-3m)		23-Jun-30	23-Sep-30	1459 d (+92)	MRB	
	HRS	6911.6							
WC#: 53.110	AFL	3586							
PROC. REF: AMM 53-10-00-220-802PROC. REF: AMM 53-10-00-220-802									
53-10-00-210	^S	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE							Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.115	AFL	4582							
PROC. REF: AMM 53-10-00-220-805PROC. REF: AMM 53-10-00-220-805									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-10-00-211	^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE FS202.75 TO FS280.00, BELOW FLOOR							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.120	AFL	4582							
PROC. REF: AMM 53-10-00-220-806PROC. REF: AMM 53-10-00-220-806									PKG:38
53-10-00-212		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE FLIGHT COMPARTMENT CONNECTORS							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 53-10-00-210-824PROC. REF: AMM 53-10-00-210-824									PKG:38
53-10-00-213	^S	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FORWARD FACE OF THE FORWARD PRESSURE BULKHEAD CONNECTORS, FS202.00							Service ATA:53
	MOS	22-Jun-20	180 (+3m/-3m)					MRB	
	HRS	6911.6							
	AFL	3586							
PROC. REF: AMM 53-10-00-210-825PROC. REF: AMM 53-10-00-210-825									PKG:52
53-20-00-101		DETAILED INSPECTION OF THE FUSELAGE UPPER SKIN AND LONGITUDINAL JOINTS FROM FS381.00 TO FS557.00 - EXTERNAL (AWL*)							Service ATA:53
	MOS							AIRWORTHINESS	
	HRS								
WC#: 53.160	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: AMM 53-20-00-220-864PROC. REF: AMM 53-20-00-220-864									PKG:76
53-20-00-104		SPECIAL DETAILED INSPECTION OF THE FUSELAGE KEEL BEAM (AWL*)							Service ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.175	AFL	0	T:6082		6082		1375		
PROC. REF: NDT ET-53-20-001PROC. REF: NDT ET-53-20-001									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-105	SPECIAL DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.180	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-20-006PROC. REF: NDT ET-53-20-006									PKG:76
53-20-00-106	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR AND THE STIFFENERS OF THE PRESSURE BULKHEAD FROM FS557.00 TO FS574.50 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.185	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-20-002PROC. REF: NDT ET-53-20-002									PKG:76
53-20-00-109	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE JOINTS FROM FS281.00 TO FS557.00 - EXTERNAL (AWL*)							Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 53.200	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-53-20-007, NDT UT-53-20-001PROC. REF: NDT ET-53-20-007, NDT UT-53-20-001									PKG:76
53-20-00-110	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM FS281.00 TO FS381.00 - EXTERNAL (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.205	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-20-00-220-863PROC. REF: AMM 53-20-00-220-863									PKG:76
53-20-00-117	DETAILED INSPECTION OF THE PASSENGER DOOR CUTOUT STRUCTURE AND FITTINGS (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.230	AFL	0	T:5848		5848		1141		
PROC. REF: AMM 53-20-00-220-851PROC. REF: AMM 53-20-00-220-851									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-118		SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT FS381.00 (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.235	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: NDT ET-53-20-003PROC. REF: NDT ET-53-20-003									
53-20-00-119		SPECIAL DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BARREL JOINTS FS381.00 AND FS557.00 (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.240	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: NDT ET-53-20-005PROC. REF: NDT ET-53-20-005									
53-20-00-120		SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00 (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.245	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: NDT ET-53-20-004PROC. REF: NDT ET-53-20-004									
53-20-00-122		DETAILED INSPECTION OF THE MACHINED FITTINGS AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.255	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: AMM 53-20-00-220-832PROC. REF: AMM 53-20-00-220-832									
53-20-00-123		DETAILED INSPECTION OF THE AVIONICS BAY DOOR AND SURROUNDING SKIN (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.260	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: AMM 53-20-00-220-862PROC. REF: AMM 53-20-00-220-862									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-124	DETAILED INSPECTION OF THE WING INSPECTION LIGHT INSTALLATION (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.265	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-20-00-220-865PROC. REF: AMM 53-20-00-220-865									PKG:76
53-20-00-125	DETAILED INSPECTION OF THE STRINGERS AND FRAMES FROM FS381.00 TO FS557.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: AMM 53-20-00-220-860PROC. REF: AMM 53-20-00-220-860									PKG:76
53-20-00-126	DETAILED INSPECTION OF THE FUSELAGE STRINGERS AND FRAMES FROM FS281.00 TO FS381.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-20-00-220-861PROC. REF: AMM 53-20-00-220-861									PKG:76
53-20-00-127	GENERAL VISUAL INSPECTION OF THE PRESSURE BULKHEAD FS557.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-20-00-210-817PROC. REF: AMM 53-20-00-210-817									PKG:76
53-20-00-128 ^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE FS381.00 TO FS557.00 AND STR6L TO STR6R (AWL*)							Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.420	AFL	3586	3750						
PROC. REF: AMM 53-20-00-210-801PROC. REF: AMM 53-20-00-210-801									PKG:75

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-129	^S	GENERAL VISUAL INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE FS381.00 TO FS557.00 AND STR6L TO STR6R (AWL*)						Service	ATA:53
	MOS	10-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.425	AFL	3586	3750						
PROC. REF: AMM 53-20-00-210-802PROC. REF: AMM 53-20-00-210-802									
53-20-00-130	^S	DETAILED INSPECTION OF THE EXTERNAL AVIONICS- COMPARTMENT ACCESS SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.430	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-834PROC. REF: AMM 53-20-00-220-834									
53-20-00-131	^S	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00 (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.435	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-809PROC. REF: AMM 53-20-00-220-809									
53-20-00-132	^S	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS557.00 TO FS574.60 AND BL46L TO BL46R (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.440	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-810PROC. REF: AMM 53-20-00-220-810									
53-20-00-133	^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE FS281.00 TO FS381.00 AND STR2L TO STR7R (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.445	AFL	3586	3750						
PROC. REF: AMM 53-20-00-210-804PROC. REF: AMM 53-20-00-210-804									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-134	^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL LEFT SIDE AND LOWER SKIN FS281.00 TO FS381.00 AND STR2L TO STR25L (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.450	AFL	3586	3750						
PROC. REF: AMM 53-20-00-210-805PROC. REF: AMM 53-20-00-210-805									
53-20-00-135	^S	DETAILED INSPECTION OF THE SILLS, FRAME, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.455	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-821PROC. REF: AMM 53-20-00-220-821									
53-20-00-136	^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL RIGHT SIDE AND LOWER SKIN FS281.00 TO FS381.00 AND STR7R TO STR25R (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.460	AFL	3586	3750						
PROC. REF: AMM 53-20-00-210-806PROC. REF: AMM 53-20-00-210-806									
53-20-00-137	^S	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE WINDOW SURROUND CUTOUTS (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.465	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-836PROC. REF: AMM 53-20-00-220-836									
53-20-00-138	^S	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS FS281.00 TO FS381.00, STR2L, STR7R, STR14L, STR19R AND STR25L (AWL*)						Service	ATA:53
	MOS	22-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.470	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-840PROC. REF: AMM 53-20-00-220-840									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-139	^S	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS FS381.00 TO FS557.00, STR6R, STR6L, STR20R AND STR20L (AWL*)						Service	ATA:53
	MOS	22-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.475	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-838PROC. REF: AMM 53-20-00-220-838									
53-20-00-140	^S	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE SERVICE DOOR CUTOUT, FS295.00 TO FS310.00 AND STR22R TO STR24R (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.480	AFL	3586	3750						
PROC. REF: AMM 53-20-00-220-835PROC. REF: AMM 53-20-00-220-835									
53-20-00-201	^S	DETAILED INSPECTION OF THE INTERNAL FUSELAGE SKIN AND STRUCTURE FS281.00 TO FS861.00, ABOVE WL71.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.270	AFL	4582							
PROC. REF: AMM 53-20-00-220-801PROC. REF: AMM 53-20-00-220-801									
53-20-00-202	^S	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE FS381.00 TO FS557.00, BELOW WL71.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.275	AFL	4582							
PROC. REF: AMM 53-20-00-220-802PROC. REF: AMM 53-20-00-220-802									
53-20-00-203	^S	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.280	AFL	4582							
PROC. REF: AMM 53-20-00-220-839PROC. REF: AMM 53-20-00-220-839									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-204	^S	DETAILED INSPECTION OF THE KEEL BEAM, FS501.00 TO FS574.00 AND BL4.6L TO BL4.6R						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.285	AFL	4582							
PROC. REF: AMM 53-20-00-220-803PROC. REF: AMM 53-20-00-220-803									
53-20-00-205	^S	DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 AND STR19L AND STR19R						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.290	AFL	4582							
PROC. REF: AMM 53-20-00-220-805PROC. REF: AMM 53-20-00-220-805									
53-20-00-206	^S	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.295	AFL	4582							
PROC. REF: AMM 53-20-00-220-806PROC. REF: AMM 53-20-00-220-806									
53-20-00-207	^S	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.300	AFL	4582							
PROC. REF: AMM 53-20-00-220-854PROC. REF: AMM 53-20-00-220-854									
53-20-00-208	^S	DETAILED INSPECTION OF THE TOP SIDE OF THE PRESSURE FLOOR, FS557.00 TO FS574.50 AND BL46L TO BL46R						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.305	AFL	4582							
PROC. REF: AMM 53-20-00-220-807PROC. REF: AMM 53-20-00-220-807									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-209	^S	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE FS381.00 TO FS557.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.310	AFL	4582							
PROC. REF: AMM 53-20-00-220-808PROC. REF: AMM 53-20-00-220-808									PKG:38
53-20-00-210	^S	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.315	AFL	4582							
PROC. REF: AMM 53-20-00-220-817PROC. REF: AMM 53-20-00-220-817									PKG:34
53-20-00-212	^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50 FS281.00 TO FS381.00						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.325	AFL	4582							
PROC. REF: AMM 53-20-00-220-812PROC. REF: AMM 53-20-00-220-812									PKG:34
53-20-00-213	^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50 FS281.00 TO FS381.00, AS VISIBLE WITH THE FLOOR PANELS INSTALLED						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.330	AFL	4582							
PROC. REF: AMM 53-20-00-220-813PROC. REF: AMM 53-20-00-220-813									PKG:34
53-20-00-214	^S	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE FS281.00 TO FS381.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.335	AFL	4582							
PROC. REF: AMM 53-20-00-220-818PROC. REF: AMM 53-20-00-220-818									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-215	^S	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE FS281.00 TO FS381.00 AS VISIBLE FROM THE CRAWLWAY						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.340	AFL	4582							
PROC. REF: AMM 53-20-00-220-819PROC. REF: AMM 53-20-00-220-819									PKG:34
53-20-00-216	^S	DETAILED INSPECTION OF THE FLOOR STRUCTURE IN THE WAY OF THE PASSENGER DOOR STEP FS310.00 TO FS347.00						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.345	AFL	4582							
PROC. REF: AMM 53-20-00-220-820PROC. REF: AMM 53-20-00-220-820									PKG:34
53-20-00-217	^S	DETAILED INSPECTION OF THE SILLS, FRAMES, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.350	AFL	4582							
PROC. REF: AMM 53-20-00-220-821PROC. REF: AMM 53-20-00-220-821									PKG:34
53-20-00-218	^S	DETAILED INSPECTION OF THE INTERNAL SKIN AROUND THE PASSENGER DOOR CUTOUT						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.355	AFL	4582							
PROC. REF: AMM 53-20-00-220-837PROC. REF: AMM 53-20-00-220-837									PKG:38
53-20-00-219	^S	DETAILED INSPECTION OF THE FITTINGS AND HINGES ON THE FUSELAGE FOR THE PASSENGER DOOR						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.360	AFL	4582							
PROC. REF: AMM 53-20-00-220-822PROC. REF: AMM 53-20-00-220-822									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-221	^S	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS FS281.00 TO FS381.00, STR19R AND STR25L						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.370	AFL	4582							
									PKG:38
PROC. REF: AMM 53-20-00-220-824PROC. REF: AMM 53-20-00-220-824									
53-20-00-223	^S	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS FS381.00 TO FS557.00 - STR20L AND STR20R						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.380	AFL	4582							
									PKG:38
PROC. REF: AMM 53-20-00-220-826PROC. REF: AMM 53-20-00-220-826									
53-20-00-225	^S	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT FS381.00, BELOW WL71.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.390	AFL	4582							
									PKG:38
PROC. REF: AMM 53-20-00-220-828PROC. REF: AMM 53-20-00-220-828									
53-20-00-227	^S	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00, BELOW WL71.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.400	AFL	4582							
									PKG:38
PROC. REF: AMM 53-20-00-220-830PROC. REF: AMM 53-20-00-220-830									
53-20-00-229	^S	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR FS295.00 TO FS310.00 AND STR22R TO STR24R						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.410	AFL	4582							
									PKG:34
PROC. REF: AMM 53-20-00-220-832PROC. REF: AMM 53-20-00-220-832									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-20-00-230	S	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR FS295.00 TO FS310.00 AND STR22R TO STR24R AS VISIBLE FROM THE CRAWLWAY						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.415	AFL	4582							
PROC. REF: AMM 53-20-00-220-833PROC. REF: AMM 53-20-00-220-833									PKG:38
53-20-00-244	S	DETAILED INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R COVERED BY THE FORWARD FUEL TANK (A/C 9003, 9096, 9159 AND SUBS)						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 53-20-00-220-853PROC. REF: AMM 53-20-00-220-853									PKG:38
53-20-00-246		DETAILED INSPECTION OF THE GROUND STUDS FOR L/HIRF PROTECTION IN THE LOWER FORWARD FUSELAGE BETWEEN FS280.00 AND FS557.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 53-20-00-220-867PROC. REF: AMM 53-20-00-220-867									PKG:38
53-20-04-602	U	DETAILED VISUAL INSPECTION OF SATELLITE RADIO SYSTEM ANTENNA LOCATION - FS500						Service	ATA:53
	MOS							SALI	
	HRS								
	AFL		T:7500		7500		2793		
53-30-00-01	U	DETAILED VISUAL INSPECTION OF THE BULKHEAD FEED THRU INSTALLATION AND DOUBLER – FS 557 AT RBL 14.0 AND WL 59.38						Service	ATA:53
	MOS							CUSTOMER CODE	
	HRS								
	AFL		T:10000		10000		5293		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-102	SPECIAL DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 TO FS781.00, STRINGER 6 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.490	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-002PROC. REF: NDT ET-53-30-002									
53-30-00-103	DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 AND FS797.00, STRINGERS 18L TO 18R (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.495	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-836PROC. REF: AMM 53-30-00-220-836									
53-30-00-104	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE CABIN WINDOW CUTOUTS, FS557.00 TO FS797.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.500	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-833PROC. REF: AMM 53-30-00-220-833									
53-30-00-105	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTER FLANGE, FS574.00 (AWL*)							Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 53.505	AFL	EFF	T:7500		7500 *		2793		
									PKG:76
PROC. REF: NDT UT-53-30-002PROC. REF: NDT UT-53-30-002									
53-30-00-106	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.510	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-004, NDT UT-53-30-001PROC. REF: NDT ET-53-30-004, NDT UT-53-30-001									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-107	DETAILED INSPECTION OF THE INTERMEDIATE FRAMES (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.515	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-839PROC. REF: AMM 53-30-00-220-839									
53-30-00-110	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.530	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-011, NDT ET-53-30-013, NDT UT-53-30-005PROC. REF: NDT ET-53-30-011, NDT ET-53-30-013, NDT UT-53-30-005									
53-30-00-111	DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS AND BEAMS FROM FS719.30 TO FS781.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.535	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-837PROC. REF: AMM 53-30-00-220-837									
53-30-00-113	DETAILED INSPECTION OF THE KEEL BEAM, FS719.30 TO FS781.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.545	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-812PROC. REF: AMM 53-30-00-220-812									
53-30-00-114	SPECIAL DETAILED INSPECTION OF THE REAR SPAR BULKHEAD, FS719.30 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.550	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-014, NDT UT-53-30-008PROC. REF: NDT ET-53-30-014, NDT UT-53-30-008									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-115	DETAILED INSPECTION OF THE FRAME, FS781.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.560	AFL	0	T:6654		6654		1947		
PROC. REF: AMM 53-30-00-220-832PROC. REF: AMM 53-30-00-220-832									
53-30-00-116	DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-30-00-220-834PROC. REF: AMM 53-30-00-220-834									
53-30-00-118	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS FROM FS719.30 TO FS781.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-015, NDT UT-53-30-004PROC. REF: NDT ET-53-30-015, NDT UT-53-30-004									
53-30-00-119	SPECIAL DETAILED INSPECTION OF STRINGER 6 FROM FS574.00 TO FS781.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-30-012PROC. REF: NDT ET-53-30-012									
53-30-00-120	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTBOARD AND INBOARD FLANGES, FS574.00 (AWL*)							Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
									PKG:76
PROC. REF: NDT ET-53-30-003PROC. REF: NDT ET-53-30-003									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-121	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS574.00 (AWL*)							Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-53-30-008PROC. REF: NDT ET-53-30-008									PKG:76
53-30-00-122	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS719.30 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-30-005PROC. REF: NDT ET-53-30-005									PKG:76
53-30-00-123	SPECIAL DETAILED INSPECTION OF THE FRAME SPLICE, STRINGERS 5 AND 15, FS574.50 AND FS719.30 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-30-007PROC. REF: NDT ET-53-30-007									PKG:76
53-30-00-124 ^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE NOT BEHIND THE FAIRING, FS557.00 TO FS797.60 (AWL*)							Service	ATA:53
	MOS	23-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.640	AFL	3586	3750						
PROC. REF: AMM 53-30-00-210-802PROC. REF: AMM 53-30-00-210-802									PKG:75
53-30-00-125 ^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BEHIND THE FAIRING, FS557.00 TO FS797.60 (AWL*)							Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.645	AFL	3586	3750						
PROC. REF: AMM 53-30-00-210-804PROC. REF: AMM 53-30-00-210-804									PKG:75

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-126	^S	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVERWING EMERGENCY EXIT (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.650	AFL	3586	3750						
PROC. REF: AMM 53-30-00-220-803PROC. REF: AMM 53-30-00-220-803									
53-30-00-127	^S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF CABIN WINDOW CUTOUTS, SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.655	AFL	3586	3750						
PROC. REF: AMM 53-30-00-220-830PROC. REF: AMM 53-30-00-220-830									
53-30-00-128	^S	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS719.30 TO FS781.00 AND BL35L TO BL35R (AWL*)						Service	ATA:53
	MOS	15-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.660	AFL	3586	3750						
PROC. REF: AMM 53-30-00-220-808PROC. REF: AMM 53-30-00-220-808									
53-30-00-129	^S	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.665	AFL	3586	3750						
PROC. REF: AMM 53-30-00-220-825PROC. REF: AMM 53-30-00-220-825									
53-30-00-130	^S	DETAILED INSPECTION OF THE CIRCUMFERENTIAL SKIN JOINT AT FS557.00 AND LONGITUDINAL SKIN JOINTS AT STR6 AND STR18, L AND R (AWL*)						Service	ATA:53
	MOS	17-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.670	AFL	3586	3750						
PROC. REF: AMM 53-30-00-220-835PROC. REF: AMM 53-30-00-220-835									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-131	SPECIAL DETAILED INSPECTION OF THE EMERGENCY DOOR CUTOUT AND LATCH FITTING (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T:7500		7500		2793		
PROC. REF: NDT ET-53-30-006PROC. REF: NDT ET-53-30-006									PKG:76
53-30-00-132	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T:7500		7500		2793		
PROC. REF: NDT ET-53-30-010, NDT UT-53-30-007PROC. REF: NDT ET-53-30-010, NDT UT-53-30-007									PKG:76
53-30-00-133	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN SPLICES AT FS737.00 FROM STR15 TO STR19 AND AT STR15 BETWEEN FS737.00 AND FS787.70 (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-30-016, NDT UT-53-30-009PROC. REF: NDT ET-53-30-016, NDT UT-53-30-009									PKG:76
53-30-00-134	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME OUTER-CAP, FS719.30 AT BL47.61 (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT UT-53-30-003PROC. REF: NDT UT-53-30-003									PKG:76
53-30-00-135	DETAILED INSPECTION OF THE FUSELAGE SKIN PANEL AND STRINGER 18 - INTERNAL (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-30-00-220-843PROC. REF: AMM 53-30-00-220-843									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-136		SPECIAL DETAILED INSPECTION OF THE FRAME, FS781.00 (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-30-017, NDT UT-53-30-010PROC. REF: NDT ET-53-30-017, NDT UT-53-30-010									PKG:76
53-30-00-137		DETAILED INSPECTION OF THE CENTER FUSELAGE SKINPANEL-ASSEMBLY FROM FS557.00 TO FS797.60 (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-30-00-220-841PROC. REF: AMM 53-30-00-220-841									PKG:76
53-30-00-138		DETAILED INSPECTION OF THE FRAME SPLICE, FS574.00 TOFS781.00, STR5 AND STR15 (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-30-00-220-842PROC. REF: AMM 53-30-00-220-842									PKG:76
53-30-00-201		DETAILED INSPECTION OF THE FRONT SPAR FRAME ABOVE WL71.50, FS574.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)	Adj -108d	28-Apr-35	28-Jul-35	3229 d (+91)	MRB	
	HRS	8645							
WC#: 53.565	AFL	4582							
PROC. REF: AMM 53-30-00-220-801PROC. REF: AMM 53-30-00-220-801									
53-30-00-202 ^S		DETAILED INSPECTION OF THE FRONT SPAR FRAME BELOW WL71.50, FS574.50						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.570	AFL	4582							
PROC. REF: AMM 53-30-00-220-810PROC. REF: AMM 53-30-00-220-810									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-203	DETAILED INSPECTION OF THE REAR SPAR FRAME ABOVE WL71.50, FS719.30								Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)	Adj -108d	28-Apr-35	28-Jul-35	3229 d (+91)	MRB	
	HRS	8645							
WC#: 53.575	AFL	4582							
PROC. REF: AMM 53-30-00-220-802PROC. REF: AMM 53-30-00-220-802									
53-30-00-204 ^S	DETAILED INSPECTION OF THE REAR SPAR FRAME BELOW WL71.50, FS719.30								Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.580	AFL	4582							
PROC. REF: AMM 53-30-00-220-813PROC. REF: AMM 53-30-00-220-813									
53-30-00-205 ^S	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT -EXTERNAL								Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.585	AFL	4582							
PROC. REF: AMM 53-30-00-220-803PROC. REF: AMM 53-30-00-220-803									
53-30-00-206	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT - INTERNAL								Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)	Adj -24d	21-Jul-35	21-Oct-35	3313 d (+92)	MRB	
	HRS	8645							
WC#: 53.590	AFL	4582							
PROC. REF: AMM 53-30-00-220-827PROC. REF: AMM 53-30-00-220-827									
53-30-00-207 ^S	DETAILED INSPECTION OF THE FITTINGS ON THE FRAME OF THE OVER-WING EMERGENCY EXIT								Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.595	AFL	4582							
PROC. REF: AMM 53-30-00-220-804PROC. REF: AMM 53-30-00-220-804									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-208	^S	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE CABIN WINDOW CUTOUTS							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.600	AFL	4582							
PROC. REF: AMM 53-30-00-220-805PROC. REF: AMM 53-30-00-220-805									
53-30-00-210	^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BELOW WL71.50, FS557.00 TO FS797.60							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.610	AFL	4582							
PROC. REF: AMM 53-30-00-220-815PROC. REF: AMM 53-30-00-220-815									
53-30-00-211	^S	DETAILED INSPECTION OF THE TOP OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.615	AFL	4582							
PROC. REF: AMM 53-30-00-220-807PROC. REF: AMM 53-30-00-220-807									
53-30-00-212	^S	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.620	AFL	4582							
PROC. REF: AMM 53-30-00-220-808PROC. REF: AMM 53-30-00-220-808									
53-30-00-213	^S	DETAILED INSPECTION OF THE PRESSURE FLOOR BEAMS, FS713.10 TO FS781.00, BL0.0, BL9, BL19, BL27 AND BL35							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.625	AFL	4582							
PROC. REF: AMM 53-30-00-220-809PROC. REF: AMM 53-30-00-220-809									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-30-00-214	^S	DETAILED INSPECTION OF THE KEEL BEAM STRUCTURE, FS719.30 TO FS781.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.630	AFL	4582							
PROC. REF: AMM 53-30-00-220-812PROC. REF: AMM 53-30-00-220-812									PKG:38
53-30-00-215	^S	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.635	AFL	4582							
PROC. REF: AMM 53-30-00-220-825PROC. REF: AMM 53-30-00-220-825									PKG:38
53-30-CUS-001	^U	DETAILED INSPECTION OF THE BULKHEAD FEED THROUGH AND DOUBLER - FS 557, RBL14.0 AND WL59.38. INSPECT CUTOUT AND DOUBLER RIVET LINES FOR CRACKS AND CORROSION.						Service	ATA:53
	MOS								
	HRS								
	AFL		T:10000		10000		5293		
53-40-00-101		DETAILED INSPECTION OF THE FUSELAGE SKIN FROM FS781.00 TO FS861.00 - EXTERNAL (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.675	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-40-00-220-846PROC. REF: AMM 53-40-00-220-846									PKG:76
53-40-00-102		SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN LONGITUDINAL JOINTS (AWL*)						Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 53.680	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-53-40-009, NDT ET-53-40-010, NDT ET-53-40-015, NDT UT-53-40-005PROC. REF: NDT ET-53-40-009, NDT ET-53-40-010, NDT ET-53-40-015, NDT UT-53-40-005									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-103	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE AND PRESSURE BULKHEAD (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.685	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-833PROC. REF: AMM 53-40-00-220-833									
53-40-00-104	DETAILED INSPECTION OF THE FRAMES AT FS925.00 AND FS987.00 AND THE REAR FUSELAGE LONGERON PLATFORM (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.690	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-840PROC. REF: AMM 53-40-00-220-840									
53-40-00-105	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD AT FS861.00, AND THE FLOOR BEAMS FS789.00 TO FS861.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.695	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-832PROC. REF: AMM 53-40-00-220-832									
53-40-00-106	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN FROM FS861.00 TO REAR SPAR FRAME - EXTERNAL (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.700	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-210-802PROC. REF: AMM 53-40-00-210-802									
53-40-00-108	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, LOWER SILL (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.710	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-834PROC. REF: AMM 53-40-00-220-834									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-109	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, FRAME AND REINFORCING STRAP (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.715	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-40-00-220-835PROC. REF: AMM 53-40-00-220-835									PKG:76
53-40-00-110	DETAILED INSPECTION OF THE REAR-PRESSURE BULKHEAD UPPER-HORIZONTAL-BEAM (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.720	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-40-00-220-847PROC. REF: AMM 53-40-00-220-847									PKG:76
53-40-00-111	DETAILED INSPECTION OF THE PRESSURE BULKHEAD AT FS861.00 VERTICAL STIFFENERS AND BAGGAGE DOOR SILL FITTING (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.725	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-40-00-220-822PROC. REF: AMM 53-40-00-220-822									PKG:76
53-40-00-113	SPECIAL DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAM JOINTS (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.735	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-40-004PROC. REF: NDT ET-53-40-004									PKG:76
53-40-00-114	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT AT FS813.00 (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.740	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-40-002PROC. REF: NDT ET-53-40-002									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-115		SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT, FORWARD OF FS861.00 (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.745	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: NDT ET-53-40-003PROC. REF: NDT ET-53-40-003									
53-40-00-117		GENERAL VISUAL INSPECTION OF THE REAR FUSELAGE KEEL BEAM (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.755	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-839PROC. REF: AMM 53-40-00-220-839									
53-40-00-119		DETAILED INSPECTION OF THE REAR-FUSELAGE SKIN ENGINE-MOUNT-CUTOUTS (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.765	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-848PROC. REF: AMM 53-40-00-220-848									
53-40-00-120		SPECIAL DETAILED INSPECTION OF THE INNER FLAP TRACK SUPPORT-FITTINGS ON THE REAR FUSELAGE (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.770	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: NDT ET-53-40-005PROC. REF: NDT ET-53-40-005									
53-40-00-121		DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT-SPAR (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	53.775	AFL	0	T:7500	7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-849PROC. REF: AMM 53-40-00-220-849									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-122	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER MID-SPAR (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.780	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-843PROC. REF: AMM 53-40-00-220-843									
53-40-00-123	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER REAR-SPAR (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.785	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-844PROC. REF: AMM 53-40-00-220-844									
53-40-00-124	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SUPPORT FRAMES FOR THE ENGINE BEAMS, INNER FLANGE (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.790	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-40-001PROC. REF: NDT ET-53-40-001									
53-40-00-125	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT SPAR, INBOARD FLANGE (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.795	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-53-40-008PROC. REF: NDT ET-53-40-008									
53-40-00-126	DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAMS (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-40-00-220-831PROC. REF: AMM 53-40-00-220-831									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-127		SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CIRCUMFERENTIAL JOINTS (AWL*)						Service	ATA:53
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-53-40-011, NDT ET-53-40-013, NDT ET-53-40-014, NDT UT-53-40-003, NDT UT-53-40-004PROC. REF: NDT ET-53-40-011, NDT ET-53-40-013, NDT ET-53-40-014, NDT UT-53-40-003, NDT UT-53-40-004									
53-40-00-128		DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE BAGGAGE DOOR (AWL*)						Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7450		7450		2743		
PROC. REF: AMM 53-40-00-220-820PROC. REF: AMM 53-40-00-220-820									
53-40-00-129 ^S		GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE PRESSURIZED FUSELAGE, FS797.00 TO FS861.00 (AWL*)						Service	ATA:53
	MOS	15-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.880	AFL	3586	3750						
PROC. REF: AMM 53-40-00-210-826PROC. REF: AMM 53-40-00-210-826									
53-40-00-130 ^S		DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS OF THE PRESSURE SHELL NOT COVERED BY WING -TO-FUSELAGE FAIRINGS (AWL*)						Service	ATA:53
	MOS	23-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.885	AFL	3586	3750						
PROC. REF: AMM 53-40-00-220-815PROC. REF: AMM 53-40-00-220-815									
53-40-00-131 ^S		DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.890	AFL	3586	3750						
PROC. REF: AMM 53-40-00-220-821PROC. REF: AMM 53-40-00-220-821									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-132	^S	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BENEATH THE WING-TO-FUSELAGE FAIRING IN THE PRESSURIZED ZONE (AWL*)						Service	ATA:53
	MOS	11-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.895	AFL	3586	3750						
PROC. REF: AMM 53-40-00-210-808PROC. REF: AMM 53-40-00-210-808									PKG:75
53-40-00-133	^S	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS BENEATH THE WING-TO-FUSELAGE FAIRING (AWL*)						Service	ATA:53
	MOS	15-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.900	AFL	3586	3750						
PROC. REF: AMM 53-40-00-220-816PROC. REF: AMM 53-40-00-220-816									PKG:75
53-40-00-134	^S	DETAILED INSPECTION OF THE PRESSURE BULKHEAD FORWARD WEB BELOW FLOOR (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.905	AFL	3586	3750						
PROC. REF: AMM 53-40-00-220-817PROC. REF: AMM 53-40-00-220-817									PKG:75
53-40-00-135	^S	DETAILED INSPECTION OF THE PRESSURE BULKHEAD WEB ABOVE FLOOR (AWL*)						Service	ATA:53
	MOS	24-Jun-20						HASC	
	HRS	6911.6							
WC#: 53.910	AFL	3586	3750						
PROC. REF: AMM 53-40-00-220-818PROC. REF: AMM 53-40-00-220-818									PKG:75
53-40-00-137		SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD AT FS861.00 (AWL*)						Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-40-017PROC. REF: NDT ET-53-40-017									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-138	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE - PRESSURE BULKHEAD (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-40-016, NDT UT-53-40-006PROC. REF: NDT ET-53-40-016, NDT UT-53-40-006									
53-40-00-139	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKINCUTOUTS FROM FS781.00 TO FS1066.00 (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-53-40-012, NDT UT-53-40-002PROC. REF: NDT ET-53-40-012, NDT UT-53-40-002									
53-40-00-140	DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CUTOUTS FROM FS781.00 TO FS1066.00 (AWL*)							Service	ATA:53
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 53-40-00-220-851PROC. REF: AMM 53-40-00-220-851									
53-40-00-201 ^S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE VERTICAL STABILIZER, FS945.00 TO THE REAR SPAR OF THE VERTICAL STABILIZER							Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.800	AFL	4582							
PROC. REF: AMM 53-40-00-220-803PROC. REF: AMM 53-40-00-220-803									
53-40-00-202 ^S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE PYLON, FS877.25 TO THE REAR SPAR OF THE VERTICAL STABILIZER							Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.805	AFL	4582							
PROC. REF: AMM 53-40-00-220-804PROC. REF: AMM 53-40-00-220-804									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-203	^S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE WING-TO-FUSELAGE FAIRING, AND THE AFT KEEL BEAM, FS781.00 TO FS945.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.810	AFL	4582							
PROC. REF: AMM 53-40-00-220-805PROC. REF: AMM 53-40-00-220-805									PKG:38
53-40-00-204	^S	DETAILED INSPECTION OF THE STOP FITTINGS OF THE BAGGAGE DOOR ON THE FUSELAGE						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.815	AFL	4582							
PROC. REF: AMM 53-40-00-220-801PROC. REF: AMM 53-40-00-220-801									PKG:34
53-40-00-205	^S	DETAILED INSPECTION OF THE INTERNAL SURROUND STRUCTURE OF THE BAGGAGE DOOR, FORWARD OF THE PRESSURE BULKHEAD						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.820	AFL	4582							
PROC. REF: AMM 53-40-00-220-802PROC. REF: AMM 53-40-00-220-802									PKG:38
53-40-00-206	^S	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.825	AFL	4582							
PROC. REF: AMM 53-40-00-220-821PROC. REF: AMM 53-40-00-220-821									PKG:34
53-40-00-208	^S	DETAILED INSPECTION OF THE INTERNAL FUSELAGE STRUCTURE AND FORWARD FACE OF THE REAR PRESSURE BULKHEAD BELOW THE FLOOR, AND THE FLOOR STRUCTURE OF THE BAGGAGE COMPARTMENT						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.835	AFL	4582							
PROC. REF: AMM 53-40-00-220-807PROC. REF: AMM 53-40-00-220-807									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-209 ^S		DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.840	AFL	4582							
PROC. REF: AMM 53-40-00-220-808PROC. REF: AMM 53-40-00-220-808									PKG:34
53-40-00-210 ^S		DETAILED INSPECTION OF THE STRUCTURE OF THE AFT FACE OF THE REAR PRESSURE BULKHEAD						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.845	AFL	4582							
PROC. REF: AMM 53-40-00-220-809PROC. REF: AMM 53-40-00-220-809									PKG:38
53-40-00-211 ^S		DETAILED INSPECTION OF THE UPPER SILL AND STOP BACKUP STRUCTURE OF THE BAGGAGE DOOR, AFT OF THE PRESSURE BULKHEAD						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.850	AFL	4582							
PROC. REF: AMM 53-40-00-220-810PROC. REF: AMM 53-40-00-220-810									PKG:38
53-40-00-212 ^S		DETAILED INSPECTION OF THE AUXILIARY FUEL TANK FLOOR STRUCTURE						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.855	AFL	4582							
PROC. REF: AMM 53-40-00-220-819PROC. REF: AMM 53-40-00-220-819									PKG:38
53-40-00-213 ^S		DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE, FS861.00, VERTICAL-STABILIZER REAR-SPAR FRAME						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.860	AFL	4582							
PROC. REF: AMM 53-40-00-220-812PROC. REF: AMM 53-40-00-220-812									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-40-00-214	^S	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE ADJACENT TO THE AUXILIARY FUEL TANK, FS861.00 TO FS893.50, WL80.25 TO WL137.00						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.865	AFL	4582							
PROC. REF: AMM 53-40-00-220-813PROC. REF: AMM 53-40-00-220-813									PKG:38
53-40-00-215	^S	DETAILED INSPECTION OF THE FORWARD ENGINE-MOUNT FRAME-ASSEMBLY						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.870	AFL	4582							
PROC. REF: AMM 53-40-00-220-814PROC. REF: AMM 53-40-00-220-814									PKG:34
53-40-00-216	^S	DETAILED INSPECTION OF THE SUPPORT STRUCTURE OF THE INNER FLAP INBOARD TRACK						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.875	AFL	4582							
PROC. REF: AMM 53-40-00-220-811PROC. REF: AMM 53-40-00-220-811									PKG:38
53-40-00-217		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AFT FACE OF THE AFT PRESSURE BULKHEAD CONNECTORS - FS861.00						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 41d	24-Sep-30	24-Dec-30	1552 d (+91)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 53-40-00-210-831PROC. REF: AMM 53-40-00-210-831									PKG:34
53-40-05-602	^U	DETAILED VISUAL INSPECTION OF CAMERA SYSTEM ELECTRICAL RECEPTACLE LOCATION - FS806						Service	ATA:53
	MOS	26-May-20						SALI	
	HRS	6911.6							
	AFL	3586	1875	Adj 50	5511		804		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-50-00-101	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR CAP AND CRUCIFORM FITTING (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.915	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-50-00-220-806PROC. REF: AMM 53-50-00-220-806									
53-50-00-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER ATTACHMENT AT THE FUSELAGE FRAMES (AWL*)							Service	ATA:53
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 53.920	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 53-50-00-220-810PROC. REF: AMM 53-50-00-220-810									
53-50-00-201 ^S	DETAILED INSPECTION OF THE AFT ENGINE-MOUNT FRAME-ASSEMBLY							Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.940	AFL	4582							
									PKG:34
PROC. REF: AMM 53-50-00-220-801PROC. REF: AMM 53-50-00-220-801									
53-50-00-202 ^S	DETAILED INSPECTION OF THE MID SPAR FRAME							Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.945	AFL	4582							
									PKG:38
PROC. REF: AMM 53-50-00-220-802PROC. REF: AMM 53-50-00-220-802									
53-50-00-203 ^S	DETAILED INSPECTION OF THE REAR SPAR FRAME							Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.950	AFL	4582							
									PKG:38
PROC. REF: AMM 53-50-00-220-803PROC. REF: AMM 53-50-00-220-803									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 53 - FUSELAGE									
53-50-00-204	^S	DETAILED INSPECTION OF THE STRUT ATTACH AND BACKUP FITTINGS OF THE APU MOUNT STRUCTURE						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.955	AFL	4582							
PROC. REF: AMM 53-50-00-220-804PROC. REF: AMM 53-50-00-220-804									

PKG:38

53-60-01-900-801-01		RADOME						Component	ATA:53
PN:GC245-0003-1	MOS/MSC	15-Jun-17	O/C						
SN:045	HRS	5428.8							
WC#: 53.1125	AFL	2792							
PROC. REF: AMM 53-60-01-000-801, AMM 53-60-01-400-801PROC. REF: AMM 53-60-01-000-801, AMM 53-60-01-400-801									

53-62-01-900-801-01		EVS SYSTEM - HEATED FAIRING						Component	ATA:53
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-62-01-000-801, AMM 53-62-01-400-801PROC. REF: AMM 53-62-01-000-801, AMM 53-62-01-400-801									

53-ICA-00-00	^U	ADVANCE L5 CABIN WIRING COAX FEED THROUGH RIGHT SIDE JUST FORWARD OF FS 557.0 AND JUST ABOVE STRINGER #20R AND LEFT SIDE FORWARD OF FS 557.0 JUST ABOVE STRINGER 20L. THE WIRING COAX MUST BE REMOVED TO PERFORM THE HIGH FREQUENCY EDDY INSPECTION (HFEC). 1) FATIGUE LIFE 15000 CYCLES DUE @18586 CYCLES (WHEN FATIGUE LIFE REACHED CONTACT DUNCAN AVIATION FOR FURTHER INSTRUCTIONS)						Service	ATA:53
	MOS							ICA	
	HRS								
	AFL	T:15000		18586 (M)			13879		

53-ICA-001	^U	PERFORM HFEC INSPECTION OF CABIN WIRING COAX FEE- THROUGH						Service	ATA:53
	MOS							ICA	
	HRS								
	AFL	T:7500		7500			2793		

53-ICA-001	^U	PERFORM HFEC INSPECTION OF CABIN WIRING COAX FEE- THROUGH						Service	ATA:53
	MOS							ICA	
	HRS								
	AFL	T:7500		7500			2793		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-201	S	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.960	AFL	4582							
									PKG:38
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-803PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-803									
53-ZL-00-202	S	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL LH						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.965	AFL	4582							
									PKG:38
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-806									
53-ZL-00-203	S	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL RH						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.970	AFL	4582							
									PKG:34
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-807PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-807									
53-ZL-00-204	S	GENERAL VISUAL INSPECTION OF THE NOSE WHEEL WELL						Service	ATA:53
	MOS	14-Aug-25						MRB	
	HRS	8645							
WC# : 53.975	AFL	4582	450 (+50/-50)						
									PKG:58
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-818PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-818									
53-ZL-00-205	S	GENERAL VISUAL INSPECTION OF THE MID LOWER FUSELAGE, SLAT DRIVE COMPARTMENT - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.980	AFL	4582							
									PKG:34
PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53-10-00-210-809PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53-10-00-210-809									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-206	^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS781.00 TO FS861.00, BELOW WL71.5 - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.985	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-825PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-825									
53-ZL-00-207	^S	GENERAL VISUAL INSPECTION OF THE AFT WING-TO-FUSELAGE FAIRING - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.990	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-61-09-210-801PROC. REF: SPM 20-70-00-210-801, AMM 53-61-09-210-801									
53-ZL-00-208	^S	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.995	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-806									
53-ZL-00-209	^S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1000	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-807PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-807									
53-ZL-00-210	^S	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1005	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-808PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-808									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-211	^S	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX LOWER SURFACE - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1010	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-811PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-811									PKG:38
53-ZL-00-212	^S	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1015	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-812PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-812									PKG:38
53-ZL-00-213	^S	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE BETWEEN FS280.00 AND FS557.00 - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1020	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-813PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-813									PKG:34
53-ZL-00-214	^S	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR22L AND STR22R - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1025	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-816PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-816									PKG:34
53-ZL-00-215	^S	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR18L AND STR22L, AND STR18R AND STR22R - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1030	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-814PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-814									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-216	^S	GENERAL VISUAL INSPECTION OF THE WING-TO-FUSELAGE FAIRINGS - EXTERNAL						Service	ATA:53
	MOS	15-Jun-20						MRB	
	HRS	6911.6							
WC# : 53.1035	AFL	3586	1800 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-810PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-810									PKG:74
53-ZL-00-217	^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE NOSE SECTION - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC# : 53.1040	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-815PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-815									PKG:8
53-ZL-00-218	^S	GENERAL VISUAL INSPECTION OF THE NOSE SECTION OF THE FORWARD EQUIPMENT COMPARTMENT - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.1045	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-817PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-817									PKG:34
53-ZL-00-219	^S	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT						Service	ATA:53
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.1050	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-819PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-819									PKG:32
53-ZL-00-220	^S	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT, EXCLUDING THE BAGGAGE DOOR - EXTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 53.1055	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-805PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-805									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-221	^S	GENERAL VISUAL INSPECTION OF THE ELECTRICAL POWER CONTROL-CENTER - EXTERNAL							Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1060	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53-40-00-210-827PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53-40-00-210-827									PKG:34
53-ZL-00-222	^S	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT - INTERNAL							Service ATA:53
	MOS	25-Jun-20	180 (+3m/-3m)					MRB	
	HRS	6911.6							
WC#: 53.1065	AFL	3586							
PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-830PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-830									PKG:52
53-ZL-00-223	^S	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE - EXTERNAL							Service ATA:53
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1070	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-805PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-805									PKG:38
53-ZL-00-224		GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT ABOVE THE CABIN FLOOR - INTERNAL							Service ATA:53
	MOS	28-Apr-15	180 (+3m/-3m)		28-Apr-30	28-Jul-30	1403 d (+91)	MRB	
	HRS	4228.4							
WC#: 53.1075	AFL	2192							
PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-809PROC. REF: SPM 20-70-00-210-801, AMM 53-30-00-210-809									PKG:52
53-ZL-00-225	^S	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE BETWEEN FS280.00 AND FS557.00, EXCLUDING THE PASSENGER DOOR - EXTERNAL							Service ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1080	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-811PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-811									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-226	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, ABOVE WL71.50, EXCLUDING THE PASSENGER DOOR - INTERNAL							Service	ATA:53
	MOS	28-Apr-15	180 (+3m/-3m)		28-Apr-30		1403 d (+91)	MRB	
	HRS	4228.4							
WC#: 53.1085	AFL	2192							
PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-812PROC. REF: SPM 20-70-00-210-801, AMM 53-20-00-210-812									PKG:52
53-ZL-00-227 ^S	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - EXTERNAL							Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1090	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-811PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-811									PKG:34
53-ZL-00-228 ^S	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - INTERNAL							Service	ATA:53
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1095	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-812PROC. REF: SPM 20-70-00-210-801, AMM 53-40-00-210-812									PKG:32
53-ZL-00-229 ^S	GENERAL VISUAL INSPECTION OF THE TAILCONE - EXTERNAL							Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1100	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-804									PKG:34
53-ZL-00-230 ^S	GENERAL VISUAL INSPECTION OF THE TAILCONE - INTERNAL							Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1105	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-805PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-805									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
53-ZL-00-231	^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS987.50 TO THE VERTICAL-STABILIZER REAR-SPAR DATUM-LINE - INTERNAL						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1110	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 53-50-00-210-806									PKG:34
53-ZL-00-232	^S	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL LH						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1115	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-820PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-820									PKG:34
53-ZL-00-233	^S	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL RH						Service	ATA:53
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 53.1120	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-820PROC. REF: SPM 20-70-00-210-801, AMM 53-10-00-210-820									PKG:34
ATA 54 - NACELLES/PYLONS									
54-50-00-201	^S	DETAILED INSPECTION OF THE VERTICAL FLANGE OF THE PYLON DRAG ANGLES - PS30.00 TO PS151.00						Service	ATA:54
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 54.005	AFL	4582							
PROC. REF: AMM 54-50-00-220-801PROC. REF: AMM 54-50-00-220-801									PKG:38
54-50-00-202	^S	DETAILED INSPECTION OF THE PYLON CENTER BOX INTERNAL STRUCTURE - PS30.00 TO PS151.00						Service	ATA:54
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 54.010	AFL	4582							
PROC. REF: AMM 54-50-00-220-802PROC. REF: AMM 54-50-00-220-802									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-50-01-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE PYLONS CONNECTORS								Service ATA:54
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 54-50-01-220-801PROC. REF: AMM 54-50-01-220-801									PKG:38
54-51-00-101	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM ATTACHMENT-LUGS (AWL*)								Service ATA:54
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 54.015	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-54-50-002PROC. REF: NDT ET-54-50-002									PKG:76
54-51-00-102	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, UPPER AND LOWER CAPS (AWL*)								Service ATA:54
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 54.020	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-54-50-004PROC. REF: NDT ET-54-50-004									PKG:76
54-51-00-103	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM THRUST-STRUT (AWL*)								Service ATA:54
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 54.025	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-54-50-001PROC. REF: NDT ET-54-50-001									PKG:76
54-51-00-106	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, FUSELAGE JOINT (AWL*)								Service ATA:54
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 54.040	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-54-50-003PROC. REF: NDT ET-54-50-003									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
54-51-00-107	DETAILED INSPECTION OF THE ENGINE PYLON SKINS AND DRAG ANGLES (AWL*)							Service	ATA:54
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 54-51-00-220-804PROC. REF: AMM 54-51-00-220-804									PKG:76

54-52-05-900-801-01	LH PYLON LEADING EDGE							Component	ATA:54
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 54.050	AFL	0		TSN 0					
PROC. REF: AMM 54-52-05-000-801, AMM 54-52-05-400-801PROC. REF: AMM 54-52-05-000-801, AMM 54-52-05-400-801									

54-52-05-900-801-02	RH PYLON LEADING EDGE							Component	ATA:54
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 54.050	AFL	0		TSN 0					
PROC. REF: AMM 54-52-05-000-801, AMM 54-52-05-400-801PROC. REF: AMM 54-52-05-000-801, AMM 54-52-05-400-801									

54-ZL-00-201 ^S	GENERAL VISUAL INSPECTION OF THE PYLON - LH EXTERNAL							Service	ATA:54
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 54.045	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 54-50-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 54-50-00-210-801									PKG:34

54-ZL-00-202 ^S	GENERAL VISUAL INSPECTION OF THE PYLON - RH EXTERNAL							Service	ATA:54
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 54.045	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 54-50-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 54-50-00-210-801									PKG:34

ATA 55 - STABILIZERS

55-10-00-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE-ACTUATOR FITTING-LUGS INCLUDING PINS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
WC#:	55.005	AFL	0	T:7500	7500 (M)		2793		PKG:76
PROC. REF: NDT ET-55-10-003, NDT MT-55-10-003, NDT UT-55-10-001PROC. REF: NDT ET-55-10-003, NDT MT-55-10-003, NDT UT-55-10-001									
55-10-00-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT FITTINGS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	55.010	AFL	0	T:7500	7500 (M)		2793		PKG:76
PROC. REF: NDT ET-55-10-001, NDT MT-55-10-001PROC. REF: NDT ET-55-10-001, NDT MT-55-10-001									
55-10-00-103	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTING LUGS AND PINS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	55.015	AFL	0	T:7500	7500 (M)		2793		PKG:76
PROC. REF: NDT ET-55-10-002, NDT MT-55-10-002PROC. REF: NDT ET-55-10-002, NDT MT-55-10-002									
55-10-00-104	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER REAR SPAR JOINT (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	55.020	AFL	0	T:7500	7500 (M)		2793		PKG:76
PROC. REF: NDT ET-55-10-007PROC. REF: NDT ET-55-10-007									
55-10-00-105	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL-STABILIZER (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	55.025	AFL	0	T:7500	7500		2793		PKG:76
PROC. REF: AMM 55-10-00-220-807PROC. REF: AMM 55-10-00-220-807									
55-10-00-108	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PCU FITTINGS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#:	55.040	AFL	0	T:7500	7500 (M)		2793		PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
PROC. REF: NDT ET-55-10-004, NDT PT-55-10-001PROC. REF: NDT ET-55-10-004, NDT PT-55-10-001									
55-10-00-109	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTINGS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: AMM 55-10-00-220-811PROC. REF: AMM 55-10-00-220-811									
55-10-00-110	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER FRONT SPAR JOINT (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: NDT ET-55-10-008PROC. REF: NDT ET-55-10-008									
55-10-00-201 ^S	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS AND STRAPS OF THE HORIZONTAL STABILIZER							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.045	AFL	4582							
									PKG:38
PROC. REF: AMM 55-10-00-220-802PROC. REF: AMM 55-10-00-220-802									
55-10-00-202 ^S	DETAILED INSPECTION OF THE CENTER BOX RIBS AND FITTINGS OF THE HORIZONTAL STABILIZER							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.050	AFL	4582							
									PKG:38
PROC. REF: AMM 55-10-00-220-804PROC. REF: AMM 55-10-00-220-804									
55-10-00-203 ^S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER HINGE, SUPPORT, AND BACKUP FITTINGS AT RIBS 4, 5, 9 AND 12							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.055	AFL	4582							
									PKG:38
PROC. REF: AMM 55-10-00-220-805PROC. REF: AMM 55-10-00-220-805									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-00-204		DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE HORIZONTAL STABILIZER						Service	ATA:55
	MOS							MRB	
	HRS	0							
WC#: 55.060	AFL	0	T:7500 (+50/-50)		7500	7550	2793 (+50)		
PROC. REF: AMM 55-10-00-220-806PROC. REF: AMM 55-10-00-220-806									
55-10-00-205 ^S		DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL STABILIZER						Service	ATA:55
	MOS	24-Jun-20						MRB	
	HRS	6911.6							
WC#: 55.065	AFL	3586	3750 (+50/-50)						
PROC. REF: AMM 55-10-00-220-807PROC. REF: AMM 55-10-00-220-807									
55-10-00-900-803-01		HORIZONTAL STABILIZER						Component	ATA:55
PN:GS258-0001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B174	HRS	0		TSN 0					
WC#: 55.360	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
55-10-05-900-801-01		BULLET FAIRING ASSY						Component	ATA:55
PN:GS248-0002-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B178	HRS	0		TSN 0					
WC#: 55.375	AFL	0		TSN 0					
PROC. REF: AMM 55-10-05-000-801, AMM 55-10-05-400-801PROC. REF: AMM 55-10-05-000-801, AMM 55-10-05-400-801									
55-10-05-900-813-01		LH TIP FAIRING						Component	ATA:55
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 55.365	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
55-10-05-900-813-02		RH TIP FAIRING						Component	ATA:55
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 55.370	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-10-09-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE BASEPLATE (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.070	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: NDT ET-55-10-006PROC. REF: NDT ET-55-10-006									
55-10-09-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE CENTER-LINE JOINT-STRAPS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.075	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: NDT ET-55-10-005PROC. REF: NDT ET-55-10-005									
55-10-09-103	DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.080	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: AMM 55-10-09-220-803PROC. REF: AMM 55-10-09-220-803									
55-10-09-104	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: AMM 55-10-09-220-801PROC. REF: AMM 55-10-09-220-801									
55-10-09-105	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER YAW RESTRAINT (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: NDT ET-55-10-009PROC. REF: NDT ET-55-10-009									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-20-00-101	SPECIAL DETAILED INSPECTION OF THE ELEVATOR, ACTUATOR AND HINGE FITTING (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.085	AFL	0	T:7500		7500 (M)		2793		
									PKG:76
PROC. REF: NDT ET-55-20-001PROC. REF: NDT ET-55-20-001									
55-20-00-102	DETAILED INSPECTION OF THE ELEVATOR - COMPOSITE PARTS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.090	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-20-00-220-802PROC. REF: AMM 55-20-00-220-802									
55-20-00-201	SPECIAL DETAILED INSPECTION OF THE UPPER AND LOWER SKINS OF THE ELEVATOR							Service	ATA:55
	MOS	18-Jun-20						MRB	
	HRS	6911.6							
WC#: 55.095	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 55-20-00-280-801PROC. REF: AMM 55-20-00-280-801									
55-20-00-202	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE ELEVATOR							Service	ATA:55
	MOS							MRB	
	HRS	0							
WC#: 55.100	AFL	0	T:7500 (+50/-50)		7500	7550	2793 (+50)		
									PKG:76
PROC. REF: AMM 55-20-00-220-801PROC. REF: AMM 55-20-00-220-801									
55-20-05-201 ^S	DETAILED INSPECTION OF THE FITTINGS OF THE ELEVATOR							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.105	AFL	4582							
									PKG:38
PROC. REF: AMM 55-20-05-220-801PROC. REF: AMM 55-20-05-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-102	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.115	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-00-210-810PROC. REF: AMM 55-30-00-210-810									
55-30-00-103	SPECIAL DETAILED INSPECTION OF THE SURROUND STRUCTURE OF THE ACCESS HOLE ON THE VERTICAL STABILIZER (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.120	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-30-003PROC. REF: NDT ET-55-30-003									
55-30-00-104	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER PIVOT AND ACTUATOR FITTINGS FOR THE HORIZONTAL STABILIZER (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.125	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-30-002, NDT ET-55-30-006, NDT ET-55-30-007, NDT ET-55-30-008, NDT UT-55-30-001PROC. REF: NDT ET-55-30-002, NDT ET-55-30-006, NDT ET-55-30-007, NDT ET-55-30-008, NDT UT-55-30-001									
55-30-00-105	DETAILED INSPECTION OF THE BACKUP STRUCTURE OF THE HORIZONTAL-STABILIZER ACTUATOR ATTACHMENT TO THE VERTICAL STABILIZER (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.130	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-00-220-809PROC. REF: AMM 55-30-00-220-809									
55-30-00-106	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR STRAP (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.135	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-00-220-804, AMM 55-30-00-220-810PROC. REF: AMM 55-30-00-220-804, AMM 55-30-00-220-810									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-107	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER RUDDER HINGE FITTINGS AND PINS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.140	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT ET-55-30-001, NDT PT-55-30-001PROC. REF: NDT ET-55-30-001, NDT PT-55-30-001									
55-30-00-111	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR PIN (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.160	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT MT-55-30-001PROC. REF: NDT MT-55-30-001									
55-30-00-112	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.165	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: AMM 55-30-00-210-809PROC. REF: AMM 55-30-00-210-809									
55-30-00-113	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER SIDE-STAYS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.170	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT ET-55-30-005PROC. REF: NDT ET-55-30-005									
55-30-00-114	DETAILED INSPECTION OF THE VERTICAL STABILIZER CLOSING RIB (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.175	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: AMM 55-30-00-220-807PROC. REF: AMM 55-30-00-220-807									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-115	SPECIAL DETAILED INSPECTION OF THE RUDDER WISHBONE (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.180	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-30-004PROC. REF: NDT ET-55-30-004									
55-30-00-116	DETAILED INSPECTION OF THE RUDDER WISHBONE (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-00-220-808PROC. REF: AMM 55-30-00-220-808									
55-30-00-117	DETAILED INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS (AWL*)							Service	ATA:55
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-00-220-806PROC. REF: AMM 55-30-00-220-806									
55-30-00-118	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES (AWL*)							Service	ATA:55
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-30-009PROC. REF: NDT ET-55-30-009									
55-30-00-202 ^S	DETAILED INSPECTION OF THE STABILIZER DRAG ANGLES - FRONT SPAR DATUM TO REAR SPAR DATUM							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.190	AFL	4582							
									PKG:38
PROC. REF: AMM 55-30-00-220-802PROC. REF: AMM 55-30-00-220-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-00-203 ^S		DETAILED INSPECTION OF THE FRONT SPAR, WEB AND STRAPS OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.195	AFL	4582							
PROC. REF: AMM 55-30-00-220-805PROC. REF: AMM 55-30-00-220-805									
55-30-00-205		GENERAL VISUAL INSPECTION OF THEVERTICAL-STABILIZER SKIN OUTER-SURFACESCOVERED BY ACCESS PANELS AND RUDDER SEAL							Service ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)	Adj 3	14-Nov-30	14-Feb-31	1603 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 55-30-00-210-812PROC. REF: AMM 55-30-00-210-812									
55-30-00-206 ^S		GENERAL VISUAL INSPECTION OF THEVERTICAL-STABILIZER SKIN OUTER-SURFACESCOVERED BY THE DORSAL AND BULLET FAIRINGS							Service ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 55-30-00-210-813PROC. REF: AMM 55-30-00-210-813									
55-30-00-900-803-01		VERTICAL STAB BOX ASSY							Component ATA:55
PN:GD248-0100-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:NOT	SERIALIZEDHRS	0		TSN 0					
WC#: 55.385	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
55-30-01-101		GENERAL VISUAL INSPECTION OF THE CAPS OF THE REAR SPAR OF THE VERTICAL STABILIZER (AWL*)							Service ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.200	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 55-30-01-210-801PROC. REF: AMM 55-30-01-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-01-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER MID-SPAR CAP (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.205	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-30-01-220-808PROC. REF: AMM 55-30-01-220-808									
55-30-01-201 ^S	DETAILED INSPECTION OF THE HORIZONTAL LEGS, FRONT-SPAR JOINT LEGS, AND SHEAR ANGLE OF THE VERTICAL-STABILIZER FRONT SPAR-TO-FUSELAGE INTERFACE-FITTINGS							Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.210	AFL	4582							
									PKG:34
PROC. REF: AMM 55-30-01-220-803PROC. REF: AMM 55-30-01-220-803									
55-30-01-203 ^S	DETAILED INSPECTION OF THE FITTINGS AND WISHBONE ATTACHMENTS OF THE RUDDER AND REAR SPAR AFT FACE AND RUDDER HINGE OF THE VERTICAL STABILIZER							Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.215	AFL	4582							
									PKG:38
PROC. REF: AMM 55-30-01-220-806PROC. REF: AMM 55-30-01-220-806									
55-30-01-204 ^S	DETAILED INSPECTION OF THE TIP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER							Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.220	AFL	4582							
									PKG:34
PROC. REF: AMM 55-30-01-220-807PROC. REF: AMM 55-30-01-220-807									
55-30-01-205 ^S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE AND REAR SPAR FORWARD FACE OF THE VERTICAL STABILIZER AND WISHBONE ATTACHMENTS TO THE VERTICAL STABILIZER							Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.225	AFL	4582							
									PKG:34
PROC. REF: AMM 55-30-01-220-809PROC. REF: AMM 55-30-01-220-809									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-30-01-206 ^S		DETAILED INSPECTION OF THE ATTACHMENTS AND FITTINGS OF THE WISHBONE TO THE VERTICAL STABILIZER						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.230	AFL	4582							
PROC. REF: AMM 55-30-01-220-810PROC. REF: AMM 55-30-01-220-810									
55-30-01-207 ^S		DETAILED INSPECTION OF THE LOWER ATTACHMENT PINS OF THE PITCH TRIM ACTUATOR						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.235	AFL	4582							
PROC. REF: AMM 55-30-01-220-811PROC. REF: AMM 55-30-01-220-811									
55-30-01-208 ^S		DETAILED INSPECTION OF THE LOWER ATTACHMENT BOLTS OF THE PITCH TRIM ACTUATOR						Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.240	AFL	4582							
PROC. REF: AMM 55-30-01-220-812PROC. REF: AMM 55-30-01-220-812									
55-30-01-209 ^S		DETAILED INSPECTION OF THE RUDDER HINGE PINS						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.245	AFL	4582							
PROC. REF: AMM 55-30-01-220-813PROC. REF: AMM 55-30-01-220-813									
55-30-09-900-801-01		VERTICAL STABILIZER LEADING EDGE						Component	ATA:55
PN:GS248-0003-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B179	HRS	0		TSN 0					
WC#: 55.380	AFL	0		TSN 0					
PROC. REF: AMM 55-30-09-000-801, AMM 55-30-09-400-801PROC. REF: AMM 55-30-09-000-801, AMM 55-30-09-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-40-00-101	SPECIAL DETAILED INSPECTION OF THE RUDDER ACTUATOR BRACKET LUGS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.250	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-40-001PROC. REF: NDT ET-55-40-001									
55-40-00-102	DETAILED INSPECTION OF THE RUDDER STRUCTURE - COMPOSITE PARTS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.255	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 55-40-00-220-803PROC. REF: AMM 55-40-00-220-803									
55-40-00-103	SPECIAL DETAILED INSPECTION OF THE RUDDER HINGE FITTINGS (AWL*)							Service	ATA:55
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 55.260	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-55-40-002PROC. REF: NDT ET-55-40-002									
55-40-00-201	SPECIAL DETAILED INSPECTION OF THE SKINS OF THE RUDDER, EXTERNAL							Service	ATA:55
	MOS	18-Jun-20						MRB	
	HRS	6911.6							
WC#: 55.265	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 55-40-00-280-801PROC. REF: AMM 55-40-00-280-801									
55-40-00-203	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE RUDDER							Service	ATA:55
	MOS							MRB	
	HRS	0							
WC#: 55.270	AFL	0	T:7500 (+50/-50)		7500	7550	2793 (+50)		
									PKG:76
PROC. REF: AMM 55-40-00-220-801PROC. REF: AMM 55-40-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-40-00-205	^S	DETAILED INSPECTION OF THE BACKUP FITTINGS OF THE RUDDER							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.275	AFL	4582							
PROC. REF: AMM 55-40-00-220-805PROC. REF: AMM 55-40-00-220-805									
55-ZL-00-201	^S	GENERAL VISUAL INSPECTION OF THE RAM AIR INTAKE AND DORSAL FAIRING - INTERNAL							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.280	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-05-210-801PROC. REF: SPM 20-70-00-210-801, AMM 55-30-05-210-801									
55-ZL-00-202	^S	GENERAL VISUAL INSPECTION OF THE RAM AIR DORSAL FAIRING AND THE LEADING EDGE OF THE VERTICAL STABILIZER - EXTERNAL							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.285	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-802									
55-ZL-00-203	^S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL LH							Service ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.290	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-803PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-803									
55-ZL-00-204	^S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL RH							Service ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.295	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-803PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-803									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-ZL-00-205	^S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - INTERNAL						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.300	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 55-30-00-210-804									
55-ZL-00-206	^S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL-STABILIZER BULLET FAIRING - EXTERNAL						Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.305	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-05-210-801PROC. REF: SPM 20-70-00-210-801, AMM 55-10-05-210-801									
55-ZL-00-207	^S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL- STABILIZER BULLET FAIRING - INTERNAL						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.310	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-05-210-802PROC. REF: SPM 20-70-00-210-801, AMM 55-10-05-210-802									
55-ZL-00-208	^S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER LEADING EDGE - INTERNAL						Service	ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.315	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-30-09-210-801PROC. REF: SPM 20-70-00-210-801, AMM 55-30-09-210-801									
55-ZL-00-209	^S	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE RUDDER - INTERNAL						Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 55.320	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-40-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 55-40-00-210-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-ZL-00-210 ^S		GENERAL VISUAL INSPECTION OF THE RUDDER - EXTERNAL							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 55.325	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-40-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 55-40-00-210-801									PKG:38
55-ZL-00-211 ^S		GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL LH							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 55.330	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-803PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-803									PKG:38
55-ZL-00-212 ^S		GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL RH							Service ATA:55
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 55.335	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-803PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-803									PKG:38
55-ZL-00-213 ^S		GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL LH							Service ATA:55
	MOS	24-Jun-20						MRB	
	HRS	6911.6							
WC# : 55.340	AFL	3586	3750 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-806									PKG:75
55-ZL-00-214 ^S		GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL RH							Service ATA:55
	MOS	24-Jun-20						MRB	
	HRS	6911.6							
WC# : 55.345	AFL	3586	3750 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-806									PKG:75

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
55-ZL-00-215 ^S		GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL LH						Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 55.350	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-808PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-808									
PKG:34									
55-ZL-00-216 ^S		GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL RH						Service	ATA:55
	MOS	14-Aug-25	60 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 55.355	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-808PROC. REF: SPM 20-70-00-210-801, AMM 55-10-00-210-808									
PKG:34									
ATA 56 - WINDOWS									
56-10-01-900-801-01		LH WINDSHIELD ASSEMBLY						Component	ATA:56
PN:GC331-0001-13	MOS/MSC	15-May-22	O/C	TSN 0					
SN:6507	HRS	7468.4			TSN 0				
WC#: 56.005	AFL	3949			TSN 0				
PROC. REF: CMM 56-10-01, AMM 56-10-01-000-801, AMM 56-10-01-400-801PROC. REF: CMM 56-10-01, AMM 56-10-01-000-801, AMM 56-10-01-400-801									
56-10-01-900-801-02		RH WINDSHIELD ASSEMBLY						Component	ATA:56
PN:GC331-0001-14	MOS/MSC	17-Jul-24	O/C	TSN 1					
SN:7978	HRS	8369.2			TSN 0				
WC#: 56.005	AFL	4459			TSN 0				
PROC. REF: CMM 56-10-01, AMM 56-10-01-000-801, AMM 56-10-01-400-801PROC. REF: CMM 56-10-01, AMM 56-10-01-000-801, AMM 56-10-01-400-801									
56-10-01-900-802-01		SIDE POST (LH) SPLICE STRAP						Component	ATA:56
PN:GC212-0063-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6971902	HRS	0			TSN 0				
WC#: 56.010	AFL	0			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
56-10-01-900-802-02		SIDE POST (RH) SPLICE STRAP						Component	ATA:56
PN:GC212-0063-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6826656	HRS	0			TSN 0				
WC#: 56.010	AFL	0			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 56 - WINDOWS										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
56-10-05-900-801-01		LH SIDE WINDOW							Component	ATA:56
PN:GC331-0003-7	MOS/MSC	20-Jun-24	O/C	TSN 12						
SN:7293	HRS	8286.1	TSN 0							
WC#: 56.015	AFL	4433	TSN 0							
PROC. REF: CMM 56-10-02, AMM 56-10-05-000-801, AMM 56-10-05-400-801PROC. REF: CMM 56-10-02, AMM 56-10-05-000-801, AMM 56-10-05-400-801										
56-10-05-900-801-02		RH SIDE WINDOW							Component	ATA:56
PN:GC331-0003-8	MOS/MSC	29-Nov-19	O/C	TSN 0						
SN:5394	HRS	6753.8	TSN 0							
WC#: 56.015	AFL	3488	TSN 0							
PROC. REF: CMM 56-10-02, AMM 56-10-05-000-801, AMM 56-10-05-400-801PROC. REF: CMM 56-10-02, AMM 56-10-05-000-801, AMM 56-10-05-400-801										
56-20-01-900-801-01		LEFT NO.1 ASSY CABIN WINDOW							Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:8035	HRS	0	TSN 0							
WC#: 56.020	AFL	0	TSN 0							
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801										
56-20-01-900-801-02		RIGHT NO. 1 ASSY CABIN WINDOW							Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:8025	HRS	0	TSN 0							
WC#: 56.020	AFL	0	TSN 0							
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801										
56-20-01-900-801-03		LEFT NO.2 ASSY CABIN WINDOW							Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:8034	HRS	0	TSN 0							
WC#: 56.025	AFL	0	TSN 0							
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801										
56-20-01-900-801-04		RIGHT NO. 2 ASSY CABIN WINDOW							Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:8036	HRS	0	TSN 0							
WC#: 56.025	AFL	0	TSN 0							
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
56-20-01-900-801-05		LEFT NO.3 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8024	HRS	0		TSN 0					
WC#: 56.030	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-06		RIGHT NO. 3 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8037	HRS	0		TSN 0					
WC#: 56.030	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-07		LEFT NO.4 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8023	HRS	0		TSN 0					
WC#: 56.035	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-08		RIGHT NO. 4 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8038	HRS	0		TSN 0					
WC#: 56.035	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-09		LEFT NO.5 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8022	HRS	0		TSN 0					
WC#: 56.040	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-10		RIGHT NO. 5 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8039	HRS	0		TSN 0					
WC#: 56.040	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
56-20-01-900-801-11	LEFT NO.6 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8021	HRS	0		TSN 0					
WC#: 56.050	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-12	RIGHT NO. 6 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8041	HRS	0		TSN 0					
WC#: 56.050	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-13	LEFT NO.7 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7375	HRS	0		TSN 0					
WC#: 56.055	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-14	RIGHT NO. 7 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:8040	HRS	0		TSN 0					
WC#: 56.055	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-15	LEFT NO.8 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7376	HRS	0		TSN 0					
WC#: 56.060	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-16	RIGHT NO. 8 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7382	HRS	0		TSN 0					
WC#: 56.060	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
56-20-01-900-801-17		LEFT NO.9 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7377	HRS	0		TSN 0					
WC#: 56.065	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-18		RIGHT NO. 9 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7383	HRS	0		TSN 0					
WC#: 56.065	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-19		LEFT NO.10 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7378	HRS	0		TSN 0					
WC#: 56.070	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-20		RIGHT NO. 10 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7374	HRS	0		TSN 0					
WC#: 56.070	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-21		LEFT NO.11 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7379	HRS	0		TSN 0					
WC#: 56.075	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-22		RIGHT NO. 11 ASSY CABIN WINDOW						Component	ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7384	HRS	0		TSN 0					
WC#: 56.075	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
56-20-01-900-801-23	LEFT NO.12 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7380	HRS	0		TSN 0					
WC#: 56.080	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-24	RIGHT NO. 12 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7385	HRS	0		TSN 0					
WC#: 56.080	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-25	LEFT NO.13 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7381	HRS	0		TSN 0					
WC#: 56.085	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
56-20-01-900-801-26	RIGHT NO. 13 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:7386	HRS	0		TSN 0					
WC#: 56.085	AFL	0		TSN 0					
PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801PROC. REF: CMM 56-20-00, AMM 56-20-01-000-801, AMM 56-20-01-400-801									
ATA 57 - WINGS									
57-00-00-900-801-01	LEFT HAND WING ASSEMBLY								Component ATA:57
PN:GM118-1001-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0175	HRS	0		TSN 0					
WC#: 57.695	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-00-00-900-801-02	RIGHT HAND WING ASSEMBLY								Component ATA:57
PN:GM118-1001-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0175	HRS	0		TSN 0					
WC#: 57.695	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-101	SPECIAL DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL ACCESS-HOLES (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.005	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-10-003PROC. REF: NDT ET-57-10-003									
57-10-00-102	DETAILED INSPECTION OF THE AC TRANSFER-PUMP LOWER PANEL (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.010	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-811PROC. REF: AMM 57-10-00-220-811									
57-10-00-103	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE-STAY FITTING (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.015	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-10-008PROC. REF: NDT ET-57-10-008									
57-10-00-104	SPECIAL DETAILED INSPECTION OF THE CENTER WING LOWER PANEL SPLICE, BL47.61 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.020	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-10-004, NDT UT-57-10-001PROC. REF: NDT ET-57-10-004, NDT UT-57-10-001									
57-10-00-106	DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.025	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-813PROC. REF: AMM 57-10-00-220-813									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-107	DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER WING (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.030	AFL	EFF	T:7500		7500 *		2793		PKG:76
PROC. REF: AMM 57-10-00-220-817PROC. REF: AMM 57-10-00-220-817									
57-10-00-108	DETAILED INSPECTION OF THE CENTER-WING UPPER PANEL (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.035	AFL	EFF	T:7500		7500 *		2793		PKG:76
PROC. REF: AMM 57-10-00-220-814PROC. REF: AMM 57-10-00-220-814									
57-10-00-109	DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.040	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: AMM 57-10-00-220-815PROC. REF: AMM 57-10-00-220-815									
57-10-00-110	SPECIAL DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 TRUSS SUPPORT PLATE (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.045	AFL	0	T:7400		7400		2693		
PROC. REF: NDT ET-57-10-005, NDT MT-57-10-002PROC. REF: NDT ET-57-10-005, NDT MT-57-10-002									
57-10-00-111	SPECIAL DETAILED INSPECTION OF THE LOWER-CAP OF THE CENTER-WING FRONT SPAR (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.050	AFL	EFF	T:7500		7500 *		2793		PKG:76
PROC. REF: NDT ET-57-10-012PROC. REF: NDT ET-57-10-012									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10

Serial: 9175

RegNo: N117TP

HRS: 8918.6

AFL: 4707

As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-112	DETAILED INSPECTION OF THE LOWER CAP OF THE CENTER-WING REAR SPAR (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-818PROC. REF: AMM 57-10-00-220-818									
57-10-00-113	DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 CHORD FLANGES (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.060	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-816PROC. REF: AMM 57-10-00-220-816									
57-10-00-114	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-810PROC. REF: AMM 57-10-00-220-810									
57-10-00-115	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL SPLICE, BL47.61 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-10-00-220-812PROC. REF: AMM 57-10-00-220-812									
57-10-00-116	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE LOWER CAP (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-10-006, NDT UT-57-10-003PROC. REF: NDT ET-57-10-006, NDT UT-57-10-003									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-117	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER-WING (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-57-10-014PROC. REF: NDT ET-57-10-014									PKG:76
57-10-00-118	SPECIAL DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75 (AWL*)							Service	ATA:57
	MOS	09-Jun-19						AIRWORTHINESS	
	HRS	6506.5							
	AFL	3365	2273		5638		931		
PROC. REF: NDT ET-57-10-002, NDT MT-57-10-001PROC. REF: NDT ET-57-10-002, NDT MT-57-10-001									
57-10-00-119	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP, BL44.00 TO BL47.60 (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT RT-57-10-003PROC. REF: NDT RT-57-10-003									PKG:76
57-10-00-121	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP AND WING SKIN BETWEEN LBL44.00 AND RBL44.00 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT RT-57-10-005PROC. REF: NDT RT-57-10-005									PKG:76
57-10-00-122	DETAILED INSPECTION OF THE KEEL BEAM RIB TRUSS-BEAM PINS, BL4.75 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-10-00-220-820PROC. REF: AMM 57-10-00-220-820									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-123	SPECIAL DETAILED INSPECTION OF THE WING FRONT-SPAR LOWER-CAP AND WEB AT KEEL BEAM ATTACHMENTS, BL4.75 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT UT-57-10-002PROC. REF: NDT UT-57-10-002									PKG:76
57-10-00-124	DETAILED INSPECTION OF THE FRONT SPAR LOWER CAP OF THE CENTER WING FROM LBL47.60 TO RBL47.60 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-10-00-220-819PROC. REF: AMM 57-10-00-220-819									PKG:76
57-10-00-125	SPECIAL DETAILED INSPECTION OF THE CENTER WING FRONT-SPAR LOWER-CAP AND WEB AT FS574.50 FROM LBL47.60 TO RBL47.60 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT RT-57-10-004PROC. REF: NDT RT-57-10-004									PKG:76
57-10-00-201 ^S	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.065	AFL	4582							
PROC. REF: AMM 57-10-00-220-801PROC. REF: AMM 57-10-00-220-801									PKG:38
57-10-00-202 ^S	DETAILED INSPECTION OF THE CENTER WING FRONT SPAR AFT FACE, AND CENTER WING UPPER PANEL, LOWER PANEL AND RIBS - INTERNAL LBL47.6 TO RBL47.6							Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.070	AFL	4582							
PROC. REF: AMM 57-10-00-220-802PROC. REF: AMM 57-10-00-220-802									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-203	^S	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.075	AFL	4582							
PROC. REF: AMM 57-10-00-220-803PROC. REF: AMM 57-10-00-220-803									PKG:38
57-10-00-204	^S	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.080	AFL	4582							
PROC. REF: AMM 57-10-00-220-804PROC. REF: AMM 57-10-00-220-804									PKG:38
57-10-00-205	^S	DETAILED INSPECTION OF THE UPPER FACE OF THE CENTER WING UPPER PANEL						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.085	AFL	4582							
PROC. REF: AMM 57-10-00-220-805PROC. REF: AMM 57-10-00-220-805									PKG:38
57-10-00-206	^S	DETAILED INSPECTION OF THE LOWER FACE OF THE CENTER WING LOWER PANEL						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.090	AFL	4582							
PROC. REF: AMM 57-10-00-220-806PROC. REF: AMM 57-10-00-220-806									PKG:34
57-10-00-208	^S	DETAILED INSPECTION OF THE OUTER FACE OF THE CENTER WING ROOT RIB						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.095	AFL	4582							
PROC. REF: AMM 57-10-00-220-808PROC. REF: AMM 57-10-00-220-808									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-10-00-209	^S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE STAY FITTING						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.100	AFL	4582							
PROC. REF: AMM 57-10-00-220-809PROC. REF: AMM 57-10-00-220-809									PKG:34
57-20-00-101		DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40 (AWL*)						Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.105	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-826PROC. REF: AMM 57-20-00-220-826									PKG:76
57-20-00-102		DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - EXTERNAL (AWL*)						Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.110	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-827PROC. REF: AMM 57-20-00-220-827									PKG:76
57-20-00-103		DETAILED INSPECTION OF THE WING LOWER-SKIN FUEL-SYSTEM-HOLES (AWL*)						Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.115	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-813PROC. REF: AMM 57-20-00-220-813									PKG:76
57-20-00-104		SPECIAL DETAILED INSPECTION OF THE LOWER WING-PLANK STRINGER-RUNOUT (AWL*)						Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.120	AFL	EFF	T:7500		7500 *		2793		
PROC. REF: NDT ET-57-20-014PROC. REF: NDT ET-57-20-014									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-105	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) LOWER STRAP, WS85.50 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.125	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-013, NDT RT-57-20-005PROC. REF: NDT ET-57-20-013, NDT RT-57-20-005									
57-20-00-106	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) FITTING JOINT (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.130	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-008, NDT RT-57-20-002PROC. REF: NDT ET-57-20-008, NDT RT-57-20-002									
57-20-00-108	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS178.00 (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.140	AFL	EFF	T:7500		7500 *		2793		
									PKG:76
PROC. REF: NDT ET-57-20-002PROC. REF: NDT ET-57-20-002									
57-20-00-109	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS287.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.145	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-009, NDT RT-57-20-007PROC. REF: NDT ET-57-20-009, NDT RT-57-20-007									
57-20-00-110	SPECIAL DETAILED INSPECTION OF THE LOWER SKIN SPLICE AT THE FRONT SPAR, CANTED RIB NO. 2 TO CWS390.90 (AWL*)							Service	ATA:57
	MOS	22-Jun-20						AIRWORTHINESS	
	HRS	6911.6							
WC#: 57.150	AFL	3586	2339		5925		1218		
PROC. REF: NDT ET-57-20-001PROC. REF: NDT ET-57-20-001									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-111	DETAILED INSPECTION OF THE LOWER-SKIN SPANWISE-SPLICE (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.155	AFL	0	T:6232		6232		1525		
PROC. REF: AMM 57-20-00-220-824PROC. REF: AMM 57-20-00-220-824									
57-20-00-112	DETAILED INSPECTION OF THE OUTER WING FRONT AND REAR SPAR CAPS AND SKIN (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.160	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-829PROC. REF: AMM 57-20-00-220-829									
57-20-00-113	GENERAL VISUAL INSPECTION OF THE WING UPPER-SKIN (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.165	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-210-814PROC. REF: AMM 57-20-00-210-814									
57-20-00-114	DETAILED INSPECTION OF THE WING RIBS AT WS66.00, WS178.00, WS287.00 AND CWS464.20 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.170	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-816PROC. REF: AMM 57-20-00-220-816									
57-20-00-115	DETAILED INSPECTION OF THE WING RIB AT WS85.50 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.175	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-817PROC. REF: AMM 57-20-00-220-817									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-116	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS66.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.180	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-003PROC. REF: NDT ET-57-20-003									
57-20-00-119	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION-FITTING (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.195	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-007, NDT RT-57-20-001PROC. REF: NDT ET-57-20-007, NDT RT-57-20-001									
57-20-00-120	SPECIAL DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-20-012PROC. REF: NDT ET-57-20-012									
57-20-00-121	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - INTERNAL (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-20-00-220-830PROC. REF: AMM 57-20-00-220-830									
57-20-00-122	DETAILED INSPECTION OF THE LOWER SKIN AT THE SPANWISE-SPLICE (AWL*)							Service	ATA:57
	MOS	14-Aug-25						AIRWORTHINESS	
	HRS	8645							
	AFL	4582	940		5522		815		
PROC. REF: AMM 57-20-00-220-815PROC. REF: AMM 57-20-00-220-815									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-123	DETAILED INSPECTION OF THE LOWER SKIN AT THE FRONT AND REAR SPAR JOINTS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-831PROC. REF: AMM 57-20-00-220-831									PKG:76
57-20-00-125	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS178.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-20-004PROC. REF: NDT ET-57-20-004									PKG:76
57-20-00-126	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS287.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-20-005PROC. REF: NDT ET-57-20-005									PKG:76
57-20-00-127	SPECIAL DETAILED INSPECTION OF THE WING RIB AT CWS464.20 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-20-006PROC. REF: NDT ET-57-20-006									PKG:76
57-20-00-128	DETAILED INSPECTION OF THE WING RIB AT WS85.50 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T:7500		7500		2793		
PROC. REF: AMM 57-20-00-220-832PROC. REF: AMM 57-20-00-220-832									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-129	SPECIAL DETAILED INSPECTION OF THE LOWER SPLICE OF THE FRONT SPAR, WS275.60 AND WS549.55 (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-20-011, NDT UT-57-20-001PROC. REF: NDT ET-57-20-011, NDT UT-57-20-001									PKG:76
57-20-00-201 ^S	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.200	AFL	4582							
PROC. REF: AMM 57-20-00-220-801PROC. REF: AMM 57-20-00-220-801									PKG:38
57-20-00-202 ^S	DETAILED INSPECTION OF THE AFT FACE OF THE FRONT SPAR OF THE WING - BL47.61 TO CWS537.40							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.205	AFL	4582							
PROC. REF: AMM 57-20-00-220-802PROC. REF: AMM 57-20-00-220-802									PKG:38
57-20-00-203 ^S	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE WING - BL47.61 TO CWS537.40							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.210	AFL	4582							
PROC. REF: AMM 57-20-00-220-803PROC. REF: AMM 57-20-00-220-803									PKG:38
57-20-00-204 ^S	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR AND AUXILIARY SPAR OF THE WING							Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.215	AFL	4582							
PROC. REF: AMM 57-20-00-220-804PROC. REF: AMM 57-20-00-220-804									PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-205	^S	DETAILED INSPECTION OF THE LOWER WING SURFACE COVERED BY THE FUEL ACCESS PANELS						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.220	AFL	4582							
PROC. REF: AMM 57-20-00-220-805PROC. REF: AMM 57-20-00-220-805									
57-20-00-206	^S	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - BL47.61 TO CWS537.40						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.225	AFL	4582							
PROC. REF: AMM 57-20-00-220-806PROC. REF: AMM 57-20-00-220-806									
57-20-00-207	^S	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - CWS537.40 TO WS536.50						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.230	AFL	4582							
PROC. REF: AMM 57-20-00-220-807PROC. REF: AMM 57-20-00-220-807									
57-20-00-210	^S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION FITTING AND BAY						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.245	AFL	4582							
PROC. REF: AMM 57-20-00-220-810PROC. REF: AMM 57-20-00-220-810									
57-20-00-212	^S	DETAILED INSPECTION OF THE AILERON SUPPORT FITTINGS						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.250	AFL	4582							
PROC. REF: AMM 57-20-00-220-812PROC. REF: AMM 57-20-00-220-812									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-20-00-213	^S	DETAILED INSPECTION OF THE INTERNAL WING STRUCTURE BETWEEN THE REAR SPAR AND AUXILIARY SPAR, WS85.00 TO WS178.00						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 57-20-00-220-821PROC. REF: AMM 57-20-00-220-821									PKG:34
57-30-00-101		SPECIAL DETAILED INSPECTION OF THE WINGLET INSTALLATION (AWL*)						Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.255	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-30-001PROC. REF: NDT ET-57-30-001									PKG:76
57-30-00-102		DETAILED INSPECTION OF THE WINGLET - EXTERNAL SURFACES (AWL*)						Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-30-00-220-804PROC. REF: AMM 57-30-00-220-804									PKG:76
57-30-00-202	^S	DETAILED INSPECTION OF THE WINGLET ATTACHMENT FITTINGS						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.265	AFL	4582							
PROC. REF: AMM 57-30-00-220-802PROC. REF: AMM 57-30-00-220-802									PKG:38
57-30-00-900-801-01		LEFT WINGLET						Component	ATA:57
PN:GM178-1000-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0176	HRS	0		TSN 0					
WC#: 57.700	AFL	0		TSN 0					
PROC. REF: AMM 57-30-00-000-801, AMM 57-30-00-400-801PROC. REF: AMM 57-30-00-000-801, AMM 57-30-00-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS									
57-30-00-900-801-02		RIGHT WINGLET						Component	ATA:57
PN:GM178-1000-2		MOS/MSC	07-Oct-05	O/C	TSN 0				
SN:0175		HRS	0	TSN 0					
WC#: 57.700		AFL	0	TSN 0					
PROC. REF: AMM 57-30-00-000-801, AMM 57-30-00-400-801PROC. REF: AMM 57-30-00-000-801, AMM 57-30-00-400-801									

57-30-01-900-801-01		LH WING TIP LENS			Component	ATA:57
PN:9EL409620-25	MOS/MSC	03-Oct-18	O/C	TSN 5		
SN:M21148	HRS	6189.3		TSN 0		
WC#: 57.705	AFL	3178		TSN 0		
PROC. REF: CMM 33-42-22, AMM 57-30-01-000-801, AMM 57-30-01-400-801PROC. REF: CMM 33-42-22, AMM 57-30-01-000-801, AMM 57-30-01-400-801						

57-30-01-900-801-02		RH WING TIP LENS			Component	ATA:57
PN:9EL409610-25	MOS/MSC	03-Oct-18	O/C	TSN 10		
SN:M11089	HRS	6189.3		TSN 0		
WC#: 57.705	AFL	3178		TSN 0		
PROC. REF: CMM 33-42-22, AMM 57-30-01-000-801, AMM 57-30-01-400-801PROC. REF: CMM 33-42-22, AMM 57-30-01-000-801, AMM 57-30-01-400-801						

57-42-00-101		SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TRACKS (AWL*)						Service	ATA:57	
	MOS							AIRWORTHINESS		
	HRS	0								
WC#: 57.270	AFL	0	T:7500	7500			2793			
PROC. REF: NDT MT-57-42-002PROC. REF: NDT MT-57-42-002									PKG:76	

57-42-00-103		SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TRACKS (AWL*)						Service	ATA:57	
	MOS							AIRWORTHINESS		
	HRS	0								
WC#: 57.275	AFL	0	T:7500	7500				2793		
PROC. REF: NDT MT-57-42-003PROC. REF: NDT MT-57-42-003									PKG:76	

57-42-00-104	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TRACKS (AWL*)						Service	ATA:57
	MOS							AIRWORTHINESS
	HRS	0						
WC#: 57.280	AFL	0	T:7500	7500	2793			
								PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: NDT MT-57-42-004PROC. REF: NDT MT-57-42-004									
57-42-00-105	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT TRACKS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.285	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT MT-57-42-005PROC. REF: NDT MT-57-42-005									
57-42-00-107	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TO TRACK ATTACHMENTS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.290	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT ET-57-42-007PROC. REF: NDT ET-57-42-007									
57-42-00-108	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TO TRACK ATTACHMENTS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.295	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: NDT ET-57-42-006PROC. REF: NDT ET-57-42-006									
57-42-00-109	DETAILED INSPECTION OF THE SLAT TRACK ATTACHMENT LUGS, SLAT NO. 3 AND NO. 4 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.300	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: AMM 57-42-02-220-809PROC. REF: AMM 57-42-02-220-809									
57-42-00-111	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TO TRACK ATTACHMENTS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS								
	AFL	EFF	T:7500		7500 *		2793		PKG:76
PROC. REF: NDT ET-57-42-008PROC. REF: NDT ET-57-42-008									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-42-00-201	^S	DETAILED INSPECTION OF THE NO. 1 SLAT SUPPORT FITTINGS							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.310	AFL	4582							
PROC. REF: AMM 57-42-00-220-801PROC. REF: AMM 57-42-00-220-801									PKG:38
57-42-00-202	^S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT SUPPORT FITTINGS							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.315	AFL	4582							
PROC. REF: AMM 57-42-00-220-802PROC. REF: AMM 57-42-00-220-802									PKG:38
57-42-02-101		DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 1 AND NO. 2 (AWL*)							Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.320	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-42-02-220-810PROC. REF: AMM 57-42-02-220-810									PKG:76
57-42-02-103		DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 3 AND NO. 4 (AWL*)							Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.330	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-42-02-220-811PROC. REF: AMM 57-42-02-220-811									PKG:76
57-42-02-104		SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT BODIES INTERCONNECT PIN (AWL*)							Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.335	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-42-004, NDT MT-57-42-006PROC. REF: NDT ET-57-42-004, NDT MT-57-42-006									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-42-02-105	SPECIAL DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 ROLLER PINS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.340	AFL	0	T:7500		7500		2793		
PROC. REF: NDT MT-57-42-001, NDT PT-57-42-001PROC. REF: NDT MT-57-42-001, NDT PT-57-42-001									PKG:76
57-42-02-106	DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 SUPPORT RIBS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 57-42-02-220-812PROC. REF: AMM 57-42-02-220-812									PKG:76
57-42-02-201 ^S	DETAILED INSPECTION OF THE NO. 1 SLAT TRACK RAILS							Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.345	AFL	4582							
PROC. REF: AMM 57-42-02-220-801PROC. REF: AMM 57-42-02-220-801									PKG:34
57-42-02-202 ^S	DETAILED INSPECTION OF THE NO. 1 SLAT RAIL SUPPORT FITTINGS							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.350	AFL	4582							
PROC. REF: AMM 57-42-02-220-802PROC. REF: AMM 57-42-02-220-802									PKG:38
57-42-02-203 ^S	DETAILED INSPECTION OF THE NO. 1 SLAT BODY							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.355	AFL	4582							
PROC. REF: AMM 57-42-02-220-803PROC. REF: AMM 57-42-02-220-803									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-42-02-204	^S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT TRACK RAILS							Service ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.360	AFL	4582							
PROC. REF: AMM 57-42-02-220-804PROC. REF: AMM 57-42-02-220-804									
57-42-02-205	^S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT RAIL SUPPORT FITTINGS							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.365	AFL	4582							
PROC. REF: AMM 57-42-02-220-805PROC. REF: AMM 57-42-02-220-805									
57-42-02-206	^S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT BODIES							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.370	AFL	4582							
PROC. REF: AMM 57-42-02-220-806PROC. REF: AMM 57-42-02-220-806									
57-51-00-101		SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS47.80 (AWL*)							Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.375	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-003, NDT MT-57-51-001PROC. REF: NDT ET-57-51-003, NDT MT-57-51-001									
57-51-00-102		SPECIAL DETAILED INSPECTION OF THE FLAP SUPPORT STRUCTURE, WS178.00 (AWL*)							Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.380	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-004, NDT MT-57-51-002PROC. REF: NDT ET-57-51-004, NDT MT-57-51-002									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-51-00-103	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS287.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.385	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-001, NDT MT-57-51-003PROC. REF: NDT ET-57-51-001, NDT MT-57-51-003									PKG:76
57-51-00-104	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS404.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.390	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-002, NDT MT-57-51-004PROC. REF: NDT ET-57-51-002, NDT MT-57-51-004									PKG:76
57-51-00-105	SPECIAL DETAILED INSPECTION OF THE FLAP CARRIAGE, WS47.80, WS178.00, WS287.00 AND WS404.00. (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.395	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-005PROC. REF: NDT ET-57-51-005									PKG:76
57-51-00-106	SPECIAL DETAILED INSPECTION OF THE FLAP SIDE FITTING, WS47.80 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.400	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-006, NDT MT-57-51-006, NDT PT-57-51-006PROC. REF: NDT ET-57-51-006, NDT MT-57-51-006, NDT PT-57-51-006									PKG:76
57-51-00-107	SPECIAL DETAILED INSPECTION OF THE FLAP RAIL FORWARD FITTING, WS287.00 AND WS404.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.405	AFL	0	T:7500		7500		2793		
PROC. REF: NDT ET-57-51-007, NDT MT-57-51-007PROC. REF: NDT ET-57-51-007, NDT MT-57-51-007									PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-51-00-108	SPECIAL DETAILED INSPECTION OF THE FLAP BODY FITTING (METALLIC), WS178.00, WS287.00 AND WS404.00 (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.410	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-51-008PROC. REF: NDT ET-57-51-008									
57-51-00-109	SPECIAL DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAP (METALLIC) END RIBS (AWL*)							Service	ATA:57
	MOS	EFF						AIRWORTHINESS	
	HRS								
WC#: 57.415	AFL	EFF	T:7500		7500 *		2793		
									PKG:76
PROC. REF: NDT ET-57-51-009PROC. REF: NDT ET-57-51-009									
57-51-00-110	DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAPS (COMPOSITE) (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.420	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-51-00-220-802PROC. REF: AMM 57-51-00-220-802									
57-51-00-201	SPECIAL DETAILED INSPECTION OF THE INBOARD-FLAP INTERNALRIBS AND INBOARD FITTINGS							Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)	Adj -50d	25-Jun-30	25-Sep-30	1461 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
									PKG:34
PROC. REF: AMM 57-51-00-290-801PROC. REF: AMM 57-51-00-290-801									
57-51-00-202 ^S	SPECIAL DETAILED INSPECTION OF THE MID-FLAP INTERNAL RIBS							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)						
	HRS	8645							
	AFL	4582							
									PKG:38
PROC. REF: AMM 57-51-00-290-802PROC. REF: AMM 57-51-00-290-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-51-00-203	^S	SPECIAL DETAILED INSPECTION OF THE OUTBOARD-FLAP INTERNAL RIBS						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)						
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 57-51-00-290-803PROC. REF: AMM 57-51-00-290-803									
57-51-05-201	^S	DETAILED INSPECTION OF THE FLAP TRACK RAILS - WS47.80, WS178.00, WS287.00 AND WS404.00						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.425	AFL	4582							
PROC. REF: AMM 57-51-05-220-801PROC. REF: AMM 57-51-05-220-801									
57-51-05-202	^S	DETAILED INSPECTION OF THE FLAP SUPPORT FITTINGS - WS47.80, WS178.00, WS287.00 AND WS404.00						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.430	AFL	4582							
PROC. REF: AMM 57-51-05-220-817PROC. REF: AMM 57-51-05-220-817									
57-51-05-203	^S	DETAILED INSPECTION OF THE INNER-FLAP INNER-FITTINGS AND END RIBS						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.435	AFL	4582							
PROC. REF: AMM 57-51-05-220-809PROC. REF: AMM 57-51-05-220-809									
57-51-05-204	^S	DETAILED INSPECTION OF THE INNER-FLAP OUTER-FITTINGS AND THE MIDDLE-FLAP INNER-FITTINGS AND END RIBS						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.440	AFL	4582							
PROC. REF: AMM 57-51-05-220-810PROC. REF: AMM 57-51-05-220-810									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-51-05-205	^S	DETAILED INSPECTION OF THE MIDDLE-FLAP OUTER-FITTINGS AND THE OUTER-FLAP INNER-FITTINGS AND END RIBS							Service ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.445	AFL	4582							
PROC. REF: AMM 57-51-05-220-811PROC. REF: AMM 57-51-05-220-811									PKG:34
57-51-05-206	^S	DETAILED INSPECTION OF THE OUTER-FLAP OUTER-FITTINGS AND END RIBS							Service ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.450	AFL	4582							
PROC. REF: AMM 57-51-05-220-812PROC. REF: AMM 57-51-05-220-812									PKG:34
57-51-05-207		DETAILED INSPECTION OF THE INNER FLAPS UPPER AND LOWER SKIN							Service ATA:57
	MOS	23-Jun-20						MRB	
	HRS	6911.6							
WC# : 57.455	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 57-51-05-220-813PROC. REF: AMM 57-51-05-220-813									
57-51-05-208		SPECIAL DETAILED INSPECTION OF THE INNER FLAPS TRAILING EDGE UPPER AND LOWER SKIN AND CORE							Service ATA:57
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC# : 57.460	AFL	4124	950 (+50/-50)	Adj 50	5124	5174	417 (+50)		
PROC. REF: AMM 57-51-05-280-801PROC. REF: AMM 57-51-05-280-801									
57-51-05-209	^S	DETAILED INSPECTION OF THE MIDDLE/OUTBOARD UPPER AND LOWER FLAPS SKIN							Service ATA:57
	MOS	23-Jun-20						MRB	
	HRS	6911.6							
WC# : 57.465	AFL	3586	3750 (+50/-50)						
PROC. REF: AMM 57-51-05-220-815PROC. REF: AMM 57-51-05-220-815									PKG:75
57-51-05-210		SPECIAL DETAILED INSPECTION OF THE MIDDLE/OUTER FLAP PANEL TRAILING EDGE UPPER AND LOWER SKIN AND CORE							Service ATA:57
	MOS	23-Jun-20						MRB	
	HRS	6911.6							
WC# : 57.470	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: AMM 57-51-05-280-802PROC. REF: AMM 57-51-05-280-802									
57-60-00-101	SPECIAL DETAILED INSPECTION OF THE AILERON CENTER-HINGE ASSEMBLY (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.475	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-60-001, NDT PT-57-60-001PROC. REF: NDT ET-57-60-001, NDT PT-57-60-001									
57-60-00-103	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE PINS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.480	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT PT-57-60-002PROC. REF: NDT PT-57-60-002									
57-60-00-104	DETAILED INSPECTION OF THE AILERONS (AWL*)							Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.485	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: AMM 57-60-00-220-805PROC. REF: AMM 57-60-00-220-805									
57-60-00-105	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE FITTING ASSEMBLIES (AWL*)							Service	ATA:57
	MOS	07-Oct-05						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:7500		7500		2793		
									PKG:76
PROC. REF: NDT ET-57-60-002PROC. REF: NDT ET-57-60-002									
57-60-00-201 ^S	DETAILED INSPECTION OF THE AILERON HINGE FITTINGS							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.490	AFL	4582							
									PKG:38
PROC. REF: AMM 57-60-00-220-804PROC. REF: AMM 57-60-00-220-804									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-60-00-202	SPECIAL DETAILED INSPECTION OF THE AILERON SKIN								Service ATA:57
	MOS	23-Jun-20						MRB	
	HRS	6911.6							
WC#: 57.495	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 57-60-00-280-801PROC. REF: AMM 57-60-00-280-801									
57-60-00-203	DETAILED INSPECTION OF THE AILERON SPAR								Service ATA:57
	MOS							MRB	
	HRS	0							
WC#: 57.500	AFL	0	T:7500 (+50/-50)		7500	7550	2793 (+50)		PKG:76
PROC. REF: AMM 57-60-00-220-803PROC. REF: AMM 57-60-00-220-803									
57-60-00-900-802-01	LEFT AILERON								Component ATA:57
PN:GM158-1000-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:178	HRS	0		TSN 0					
WC#: 57.725	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-60-00-900-802-02	RIGHT AILERON								Component ATA:57
PN:GM158-1000-6	MOS/MSC	03-Feb-25	O/C	TSN 232, TSR 1					
SN:0176	HRS	8641.1		TSN 8641.1, TSR 0					
WC#: 57.725	AFL	4580		TSN 4580, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-70-00-101	SPECIAL DETAILED INSPECTION OF THE SPOILERS (NO. 1 TO NO. 6) HINGE FITTINGS (AWL*)								Service ATA:57
	MOS	14-Aug-25						AIRWORTHINESS	
	HRS	8645							
WC#: 57.505	AFL	4582	763		5345		638		
PROC. REF: NDT ET-57-70-001, NDT PT-57-70-001PROC. REF: NDT ET-57-70-001, NDT PT-57-70-001									
57-70-00-102	DETAILED INSPECTION OF THE SPOILERS NO. 1 TO NO. 6 (AWL*)								Service ATA:57
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 57.510	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: AMM 57-70-00-220-801PROC. REF: AMM 57-70-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-71-00-201	^S	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.515	AFL	4582							
PROC. REF: AMM 57-71-00-220-803PROC. REF: AMM 57-71-00-220-803									
57-71-00-202	^S	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS - BL47.61AND WS178.00							Service ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.520	AFL	4582							
PROC. REF: AMM 57-71-00-220-801PROC. REF: AMM 57-71-00-220-801									
57-71-00-203	^S	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER SKIN							Service ATA:57
	MOS	23-Jun-20						MRB	
	HRS	6911.6							
WC#: 57.525	AFL	3586	3750 (+50/-50)						
PROC. REF: AMM 57-71-00-280-801PROC. REF: AMM 57-71-00-280-801									
57-71-00-900-801-01		GROUND OUTBOARD LH SPOILER							Component ATA:57
PN:GM168-1200-13	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0177	HRS	7751.1		TSN 7751.1					
WC#: 57.730	AFL	4121		TSN 4121					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-71-00-900-801-02		GROUND INBOARD LH SPOILER							Component ATA:57
PN:GM168-1100-1	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0176	HRS	7751.1		TSN 7751.1					
WC#: 57.730	AFL	4121		TSN 4121					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-71-00-900-801-03		GROUND INBOARD RH SPOILER							Component ATA:57
PN:GM168-1100-2	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0177	HRS	7751.1		TSN 7751.1					
WC#: 57.735	AFL	4121		TSN 4121					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 57 - WINGS										
57-71-00-900-801-04		GROUND OUTBOARD RH SPOILER							Component	ATA:57
PN:GM168-1200-14	MOS/MSC	03-Feb-23	O/C	TSN 208						
SN:0178	HRS	7751.1		TSN 7751.1						
WC#: 57.735	AFL	4121		TSN 4121						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
57-72-00-201 ^S		DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SUPPORT-FITTINGS							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB		
	HRS	8645								
WC#: 57.530	AFL	4582								
PKG:38										
PROC. REF: AMM 57-72-00-220-801PROC. REF: AMM 57-72-00-220-801										
57-72-00-202 ^S		DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER HINGE FITTINGS - WS178.00 AND WS404.00							Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB		
	HRS	8645								
WC#: 57.535	AFL	4582								
PKG:38										
PROC. REF: AMM 57-72-00-220-803PROC. REF: AMM 57-72-00-220-803										
57-72-00-203 ^S		SPECIAL DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SKIN - WS178.00 AND WS404.00							Service	ATA:57
	MOS	23-Jun-20					MRB			
	HRS	6911.6								
WC#: 57.540	AFL	3586	3750 (+50/-50)							
PKG:75										
PROC. REF: AMM 57-72-00-280-801PROC. REF: AMM 57-72-00-280-801										
57-72-00-900-801-01		OUTBOARD LEFT SPOILERON							Component	ATA:57
PN:GM168-1800-31	MOS/MSC	03-Feb-23	O/C	TSN 208						
SN:0178	HRS	7751.1		TSN 7751.1						
WC#: 57.740	AFL	4121		TSN 4121						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-72-00-900-801-02		INBOARD LEFT SPOILERON						Component	ATA:57
PN:GM168-1700-31	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0176	HRS	7751.1	TSN 7751.1						
WC#: 57.745	AFL	4121	TSN 4121						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-72-00-900-801-03		INBOARD RIGHT SPOILERON						Component	ATA:57
PN:GM168-1700-32	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0175	HRS	7751.1	TSN 7751.1						
WC#: 57.745	AFL	4121	TSN 4121						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-72-00-900-801-04		OUTBOARD RIGHT SPOILERON						Component	ATA:57
PN:GM168-1800-32	MOS/MSC	03-Feb-23	O/C	TSN 208					
SN:0177	HRS	7751.1	TSN 7751.1						
WC#: 57.740	AFL	4121	TSN 4121						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
57-ZL-00-201 ^S		GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.545	AFL	4582							
PKG:32									
PROC. REF: SPM 20-70-00-210-801, AMM 57-40-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-40-00-210-802									
57-ZL-00-202 ^S		GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.550	AFL	4582							
PKG:32									
PROC. REF: SPM 20-70-00-210-801, AMM 57-40-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-40-00-210-802									
57-ZL-00-203 ^S		GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.555	AFL	4582							
PKG:32									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 57 - WINGS

PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57-40-00-210-801, AMM 57-40-00-210-803PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57-40-00-210-801, AMM 57-40-00-210-803

57-ZL-00-204	S	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 57.560	AFL	4582							

PKG:34

PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57-40-00-210-801, AMM 57-40-00-210-803PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57-40-00-210-801, AMM 57-40-00-210-803

57-ZL-00-205	S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	30 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 57.565	AFL	4582							

PKG:32

PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-804

57-ZL-00-206	S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	30 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 57.570	AFL	4582							

PKG:32

PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-804PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-804

57-ZL-00-207	S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 57.575	AFL	4582							

PKG:38

PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-805PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-805

57-ZL-00-208	S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)				MRB		
	HRS	8645							
WC#: 57.580	AFL	4582							

PKG:38

PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-805PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-805

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-ZL-00-209 ^S		GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.585	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, SPM 51-23-00-390-821, AMM 57-20-00-210-815PROC. REF: SPM 20-70-00-210-801, SPM 51-23-00-390-821, AMM 57-20-00-210-815									PKG:38
57-ZL-00-210 ^S		GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.590	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-815PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-815									PKG:38
57-ZL-00-211 ^S		GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.595	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-806									PKG:34
57-ZL-00-212 ^S		GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.600	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-806PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-806									PKG:34
57-ZL-00-213 ^S		GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC# : 57.605	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-807PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-807									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-ZL-00-214	^S	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.610	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-807PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-807									PKG:38
57-ZL-00-215	^S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.615	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-808PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-808									PKG:34
57-ZL-00-216	^S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.620	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-808PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-808									PKG:34
57-ZL-00-217	^S	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.625	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-809PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-809									PKG:38
57-ZL-00-218	^S	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.630	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-809PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-809									PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-ZL-00-219	^S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL LH						Service	ATA:57
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC#: 57.635	AFL	4124	900 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-810PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-810									PKG:60
57-ZL-00-220	^S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL RH						Service	ATA:57
	MOS	14-Feb-23						MRB	
	HRS	7761.3							
WC#: 57.640	AFL	4124	900 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-810PROC. REF: SPM 20-70-00-210-801, AMM 57-20-00-210-810									PKG:60
57-ZL-00-221	^S	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.645	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-30-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-30-00-210-801									PKG:34
57-ZL-00-222	^S	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.650	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-30-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-30-00-210-801									PKG:34
57-ZL-00-223	^S	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL LH						Service	ATA:57
	MOS	27-May-20						MRB	
	HRS	6911.6							
WC#: 57.655	AFL	3586	1800 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-801									PKG:74

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-ZL-00-224	^S	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL RH						Service	ATA:57
	MOS	27-May-20						MRB	
	HRS	6911.6							
WC#: 57.660	AFL	3586	1800 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-801									
57-ZL-00-225	^S	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.665	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-802									
57-ZL-00-226	^S	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.670	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-51-00-210-802									
57-ZL-00-227	^S	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL LH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.675	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-801									
57-ZL-00-228	^S	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL RH						Service	ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.680	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
57-ZL-00-229	^S	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - LH							Service ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.685	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-802									PKG:34
57-ZL-00-230	^S	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - RH							Service ATA:57
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 57.690	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 57-00-00-210-802									PKG:34
ATA 71 - POWER PLANT									
71-00-00-201		DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE COMPONENTS ELECTRICAL CONNECTORS							Service ATA:71
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 71-00-00-220-801PROC. REF: AMM 71-00-00-220-801									PKG:38
71-10-00-201		GENERAL VISUAL INSPECTION OF THE COWLS							Service ATA:71
	MOS	31-May-24						MRB	
	HRS	8252.8	1500 (+50/-50)		9752.8	9802.8	834.2 (+50)		
WC#: 71.005	AFL	4411							
PROC. REF: AMM 71-10-00-210-801PROC. REF: AMM 71-10-00-210-801									PKG:5
71-10-00-202		GENERAL VISUAL INSPECTION OF THE COWL DOOR SEALS							Service ATA:71
	MOS	30-May-24						MRB	
	HRS	8252.8	1500 (+50/-50)		9752.8	9802.8	834.2 (+50)		
WC#: 71.010	AFL	4411							
PROC. REF: AMM 71-10-00-210-802PROC. REF: AMM 71-10-00-210-802									PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-11-01-201		DETAILED INSPECTION OF THE INLET-COWL AERODYNAMIC SURFACES							Service ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#:	AFL	4582							
PROC. REF: AMM 71-11-01-220-802PROC. REF: AMM 71-11-01-220-802									PKG:8
71-11-01-202		DETAILED INSPECTION OF THE INLET-COWL FASTENERS AND ATTACHMENT RING							Service ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#:	AFL	4582							
PROC. REF: AMM 71-11-01-220-803PROC. REF: AMM 71-11-01-220-803									PKG:8
71-11-01-203		GENERAL VISUAL INSPECTION OF THE INLET-COWL REAR-BULKHEAD FIREWALL-MATERIAL (EXTERNAL SURFACES)							Service ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#:	AFL	4582							
PROC. REF: AMM 71-11-01-210-802PROC. REF: AMM 71-11-01-210-802									PKG:8
71-11-02-900-801-01		LH ENGINE NOSE COWL							Component ATA:71
PN:07C0001-005	MOS/MSC	08-Oct-09	O/C	TSR 2					
SN:E166	HRS	1338.1		TSR 0					
WC#:	AFL	735		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-11-02-900-801-02		RH ENGINE NOSE COWL							Component ATA:71
PN:07C0001-006	MOS/MSC	08-Oct-09	O/C	TSR 2					
SN:E166	HRS	1338.1		TSR 0					
WC#:	AFL	735		TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-12-01-101	DETAILED INSPECTION OF THE UPPER FAN-COWL-DOOR (AWL*)								Service ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.030	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 71-12-01-220-801PROC. REF: AMM 71-12-01-220-801									
71-12-01-201 ^S	DETAILED INSPECTION OF THE UPPER COWLS								Service ATA:71
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 71.035	AFL	4582							
PROC. REF: AMM 71-12-01-220-801PROC. REF: AMM 71-12-01-220-801									
71-12-01-202	SPECIAL DETAILED INSPECTION OF THE UPPER COWLS								Service ATA:71
	MOS	11-Jun-20						MRB	
	HRS	6911.6							
WC#: 71.040	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 71-12-01-280-801PROC. REF: AMM 71-12-01-280-801									
71-12-01-900-801-01	LH ENGINE FAN DOOR UPPER COWL								Component ATA:71
PN:07D0001-013	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E179/SB2200	HRS	0		TSN 0					
WC#: 71.110	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01-000-801, AMM 71-12-01-400-801PROC. REF: AMM 71-12-01-000-801, AMM 71-12-01-400-801									
71-12-01-900-801-02	RH ENGINE FAN DOOR UPPER COWL								Component ATA:71
PN:07D0001-014	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E179/SB2201	HRS	0		TSN 0					
WC#: 71.110	AFL	0		TSN 0					
PROC. REF: AMM 71-12-01-000-801, AMM 71-12-01-400-801PROC. REF: AMM 71-12-01-000-801, AMM 71-12-01-400-801									
71-13-01-201 ^S	FUNCTIONAL TEST OF THE LOWER-COWL PRESSURE-RELIEF DOORS								Service ATA:71
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 71.045	AFL	4582							
PKG:32									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
PROC. REF: AMM 71-13-01-720-801PROC. REF: AMM 71-13-01-720-801									
71-13-01-900-801-01		LH ENGINE FAN DOOR LOWER COWL						Component	ATA:71
PN:07D1001-017	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E179/SB2202	HRS	0	TSN 0						
WC#: 71.115	AFL	0	TSN 0						
PROC. REF: AMM 71-13-01-000-801, AMM 71-13-01-400-801PROC. REF: AMM 71-13-01-000-801, AMM 71-13-01-400-801									
71-13-01-900-801-02		RH ENGINE FAN DOOR LOWER COWL						Component	ATA:71
PN:07D1002-017	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E179/SB2203	HRS	0	TSN 0						
WC#: 71.115	AFL	0	TSN 0						
PROC. REF: AMM 71-13-01-000-801, AMM 71-13-01-400-801PROC. REF: AMM 71-13-01-000-801, AMM 71-13-01-400-801									
71-14-01-201		GENERAL VISUAL INSPECTION OF THE FIXED COWL SEALS						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 71.050	AFL	4582							
PKG:8									
PROC. REF: AMM 71-14-01-210-801PROC. REF: AMM 71-14-01-210-801									
71-14-01-202		DETAILED INSPECTION OF THE FIXED COWL						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	11695	11745	2776.4 (+50)		
WC#: 71.055	AFL	4582							
PKG:8									
PROC. REF: AMM 71-14-01-220-801PROC. REF: AMM 71-14-01-220-801									
71-20-00-201 ^S		DETAILED INSPECTION OF THE MOUNTS						Service	ATA:71
	MOS	14-Aug-25	120 (+3m/-3m)						MRB
	HRS	8645							
WC#: 71.060	AFL	4582							
PKG:38									
PROC. REF: AMM 71-20-00-220-801PROC. REF: AMM 71-20-00-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-20-00-202	S	DETAILED INSPECTION OF THE CASING LUGS FOR THE FRONT MOUNTS							Service ATA:71
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 71.065	AFL	4582							
PROC. REF: AMM 71-20-00-220-802PROC. REF: AMM 71-20-00-220-802									
71-21-01-101		SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT BEAM AND LINKS (AWL*)							Service ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.070	AFL	0	T:7500		7500		2793		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-21-01-102		SPECIAL DETAILED INSPECTION OF THE THRUST STRUT (AWL*)							Service ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.075	AFL	0	T:7500		7500		2793		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-21-01-103		SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT LINK PINS, THRUST STRUT PINS, THRUST PIN AND PYLON ATTACHMENT PINS (AWL*)							Service ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.080	AFL	0	T:7500		7500		2793		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-21-02-900-801-01		NO. 1 MOUNT TO BEAM ATTACH PIN							Component ATA:71
PN:BRR15812	MOS/MS	07-Oct-05	O/C	TSN 0					
SN:135402038	HRS	0		TSN 0					
WC#: 71.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-21-02-900-801-02		NO. 2 MOUNT TO BEAM ATTACH PIN						Component	ATA:71
PN:BRR15812	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:140899004	HRS	0		TSN 0					
WC#: 71.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-21-02-900-801-03		NO. 3 MOUNT TO BEAM ATTACH PIN						Component	ATA:71
PN:BRR15812	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:135042041	HRS	0		TSN 0					
WC#: 71.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-21-02-900-801-04		NO. 4 MOUNT TO BEAM ATTACH PIN						Component	ATA:71
PN:BRR15812	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:140899009	HRS	0		TSN 0					
WC#: 71.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-22-01-101		SPECIAL DETAILED INSPECTION OF THE REAR MOUNT BEAM AND LINKS (AWL*)						Service	ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.085	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-22-01-102		SPECIAL DETAILED INSPECTION OF THE REAR MOUNT LINK PINS AND PYLON ATTACHMENT PINS (AWL*)						Service	ATA:71
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 71.090	AFL	0	T:7500		7500		2793		PKG:76
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-22-02-900-801-01		AFT LH LOWER MOUNT BEAM TO LINK PIN						Component	ATA:71
PN:BRR15835	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KWBB778	HRS	0		TSN 0					
WC#: 71.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-22-02-900-801-02 AFT RH LOWER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KWBB780	HRS	0		TSN 0					
WC#: 71.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-22-02-900-801-03 AFT LH UPPER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KWBB779	HRS	0		TSN 0					
WC#: 71.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-22-02-900-801-04 AFT RH UPPER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:KWBB781	HRS	0		TSN 0					
WC#: 71.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-23-01-900-801-01 LEFT UPPER FRONT MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR22405	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
WC#: 71.120	AFL	4582		TSN 0					
PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801									
71-23-01-900-801-02 RIGHT UPPER FRONT MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR22405	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
WC#: 71.120	AFL	4582		TSN 0					
PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801									
71-23-01-900-801-03 LEFT LOWER FRONT MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR22405	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0453	HRS	8645		TSN 0					
WC#: 71.125	AFL	4582		TSN 0					
PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
71-23-01-900-801-04		RIGHT LOWER FRONT MOUNT LINK ASSEMBLY						Component	ATA:71
PN:BRR22405	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0448	HRS	8645		TSN 0					
WC#: 71.125	AFL	4582		TSN 0					
PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801PROC. REF: AMM 71-23-01-000-801, AMM 71-23-01-400-801									
71-24-01-900-801-01		LEFT UPPER REAR MOUNT LINK ASSEMBLY						Component	ATA:71
PN:BRR24413	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0150	HRS	8645		TSN 0					
WC#: 71.135	AFL	4582		TSN 0					
PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801									
71-24-01-900-801-02		RIGHT UPPER REAR MOUNT LINK ASSEMBLY						Component	ATA:71
PN:BRR24413	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0302	HRS	8645		TSN 0					
WC#: 71.135	AFL	4582		TSN 0					
PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801									
71-24-01-900-801-03		LEFT LOWER REAR MOUNT LINK ASSEMBLY						Component	ATA:71
PN:BRR24413	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0160	HRS	8645		TSN 0					
WC#: 71.140	AFL	4582		TSN 0					
PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801									
71-24-01-900-801-04		RIGHT LOWER REAR MOUNT LINK ASSEMBLY						Component	ATA:71
PN:BRR24413	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:228537AB0169	HRS	8645		TSN 0					
WC#: 71.140	AFL	4582		TSN 0					
PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801PROC. REF: AMM 71-24-01-000-801, AMM 71-24-01-400-801									
71-ZL-00-201 ^S		GENERAL VISUAL INSPECTION OF THE NACELLE - RH						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 71.095	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-802									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

71-ZL-00-202	^S	GENERAL VISUAL INSPECTION OF THE NACELLE - LH						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 71.095	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-802PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-802									PKG:8

71-ZL-00-203	^S	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL LH						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 71.100	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-801									PKG:8

71-ZL-00-204	^S	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL RH						Service	ATA:71
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 71.100	AFL	4582							
PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-801PROC. REF: SPM 20-70-00-210-801, AMM 71-00-00-210-801									PKG:8

710005	NO. 1 ENGINE - ENGINE MIDLIFE INSPECTION							Service	ATA:71
	MOS/MSC	07-Oct-05	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

710005	NO. 2 ENGINE - ENGINE MIDLIFE INSPECTION							Service	ATA:71
	MOS/MSC	07-Oct-05	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

710009	NO. 1 ENGINE - ENGINE OVERHAUL							Service	ATA:71
	MOS/MSC	07-Oct-05	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

710009	NO. 2 ENGINE - ENGINE OVERHAUL							Service	ATA:71
	MOS/MSC	07-Oct-05	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

717102-001	NO. 1 ENGINE - DRAINS EJECTOR PUMP							Component	ATA:71
PN:CV41-14-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05-0411217	HRS	0		TSN 0					
WC#: 71.005	ENC	0		TSN 0					
PROC. REF: AMM 73-12-15-210-801PROC. REF: AMM 73-12-15-210-801									

717102-001	NO. 2 ENGINE - DRAINS EJECTOR PUMP							Component	ATA:71
PN:CV41-14-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05-0411215	HRS	0		TSN 0					
WC#: 71.005	ENC	0		TSN 0					
PROC. REF: AMM 73-12-15-210-801PROC. REF: AMM 73-12-15-210-801									

71EN1	NO. 1 ENGINE							Component	ATA:71
PN:BR710	MOS/MSC		E/C						
SN:12471	HRS								
WC#: 71.EN1	AFL								
PROC. REF: AMM 71-00-00-000-801, AMM 71-00-00-400-801PROC. REF: AMM 71-00-00-000-801, AMM 71-00-00-400-801									

71EN2	NO. 2 ENGINE							Component	ATA:71
PN:BR710	MOS/MSC		E/C						
SN:12472	HRS								
WC#: 71.EN2	AFL								
PROC. REF: AMM 71-00-00-000-801, AMM 71-00-00-400-801PROC. REF: AMM 71-00-00-000-801, AMM 71-00-00-400-801									

ATA 72 - ENGINE

72-21-04-900-801-01	LH THRUST STRUT							Component	ATA:72
PN:BRR17672	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:654	HRS	0		TSN 0					
WC#: 72.005	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-21-04-900-801-02		RH THRUST STRUT						Component	ATA:72
PN:BRR15817	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:204756RL2222	HRS	8645		TSN 0					
WC#: 72.005	AFL	4582		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-30-01-201		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS						Service	ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7430.4	2000 (+50/-50)	Adj 50	(9480.4) 9480.4	9530.4	561.8 (+50)		
WC#: 72.005	ENC	3923							
PROC. REF: AMM 72 30 01 210 801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-50-00-220-801, AMM 72-30-01-210-801PROC. REF: AMM 72 30 01 210 801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-50-00-220-801, AMM 72-30-01-210-801									
72-30-01-201		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS						Service	ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7425.2	2000 (+50/-50)	Adj 3.6	(9428.8) 9428.8	9478.8	510.2 (+50)		
WC#: 72.005	ENC	3921							
PROC. REF: AMM 72 30 01 210 801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-50-00-220-801, AMM 72-30-01-210-801PROC. REF: AMM 72 30 01 210 801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-30-01-210-801, AMM 72-50-00-220-801, AMM 72-30-01-210-801									
72-31-02-201		NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES						Service	ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)		
WC#: 72.010	ENC	4582							
PKG:4									
PROC. REF: AMM 72 31 02 220 801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801PROC. REF: AMM 72 31 02 220 801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801									
72-31-02-201		NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES						Service	ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)		
WC#: 72.010	ENC	4582							
PKG:4									
PROC. REF: AMM 72 31 02 220 801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801PROC. REF: AMM 72 31 02 220 801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801, AMM 72-31-02-220-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)		
WC# : 72.015	ENC	4582							
PROC. REF: AMM 72 31 02 220 802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802 PROC. REF: AMM 72 31 02 220 802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802									
72-31-02-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)		
WC# : 72.015	ENC	4582							
PROC. REF: AMM 72 31 02 220 802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802 PROC. REF: AMM 72 31 02 220 802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802, AMM 72-31-02-220-802									
72-31-02-203	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]								Service ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
PROC. REF: AMM 72 31 02 610 801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801 PROC. REF: AMM 72 31 02 610 801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									
72-31-02-203	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]								Service ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
PROC. REF: AMM 72 31 02 610 801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801 PROC. REF: AMM 72 31 02 610 801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C / W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026
25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-203 OPT 1	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1)]								Service ATA:72
	MOS	01-Jun-24							
	HRS	8252.8	4000 (+400/-400)		(12252.8) 12252.8	12652.8	3334.2 (+400)		
	ENC	4411	3000		(7411) 7411		2704		
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									
72-31-02-203 OPT 1	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1)]								Service ATA:72
	MOS	01-Jun-24							
	HRS	8252.8	4000 (+400/-400)		(12252.8) 12252.8	12652.8	3334.2 (+400)		
	ENC	4411	3000		(7411) 7411		2704		
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									
72-31-02-203 OPT 2/1	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)								Service ATA:72
	MOS/MSC		-						
	HRS								
	ENC								
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									
72-31-02-203 OPT 2/1	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)								Service ATA:72
	MOS/MSC		-						
	HRS								
	ENC								
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801									
72-31-02-203 OPT 2/2	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)								Service ATA:72
	MOS/MSC		-						
	HRS								
WC#: 72.525	ENC								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801										
72-31-02-203 OPT 2/2		NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)							Service	ATA:72
MOS/MSC		-								
HRS										
WC#: 72.525		ENC								
PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801PROC. REF: AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801, AMM 72-31-02-610-801										
72-31-02-220-801		NO. 1 ENGINE - EXAMINE THE NO. 1 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION							Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY		
SN:202542RGE116822	HRS	8646.2	1000			(9646.2) 9646.2	727.6			
ENC		4583								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
72-31-02-220-801		NO. 1 ENGINE - EXAMINE THE NO. 10 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION							Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY		
SN:202542RGE113575	HRS	8646.2	1000			(9646.2) 9646.2	727.6			
ENC		4583								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
72-31-02-220-801		NO. 1 ENGINE - EXAMINE THE NO. 11 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION							Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY		
SN:202542RGE113567	HRS	8646.2	1000			(9646.2) 9646.2	727.6			
ENC		4583								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
72-31-02-220-801		NO. 1 ENGINE - EXAMINE THE NO. 12 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION							Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY		
SN:202542RGE113592	HRS	8646.2	1000			(9646.2) 9646.2	727.6			
ENC		4583								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 13 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116922	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 14 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113608	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 15 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116835	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 16 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113604	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 17 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113709	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 18 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116849	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 19 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113605	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 2 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113705	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 20 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116949	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 21 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116818	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 22 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116955	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 23 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113523	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 24 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113615	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 3 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113613	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 4 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116969	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 5 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116867	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 6 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116905	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 7 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116942	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 8 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE113568	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 1 ENGINE - EXAMINE THE NO. 9 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116394	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 1 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117011	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 10 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117001	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 11 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116516	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 12 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116994	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 13 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117000	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 14 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116976	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 15 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117007	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 16 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116996	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 17 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117002	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 18 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117003	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 19 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116887	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 2 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116522	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 20 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116890	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 21 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116982	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 22 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116999	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 23 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117004	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 24 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117012	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 3 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116723	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 4 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116983	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801		NO. 2 ENGINE - EXAMINE THE NO. 5 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION						Service	ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116948	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 6 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE117025	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 7 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116958	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 8 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116973	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-220-801	NO. 2 ENGINE - EXAMINE THE NO. 9 FAN BLADE TRANSITION STRIP TO IDENTIFY STRIP LOSS OR STRIP DETERIORATION								Service ATA:72
PN:FW33513	MOS	17-Aug-25						MANDATORY	
SN:202542RGE116817	HRS	8646.2	1000		(9646.2) 9646.2		727.6		
	ENC	4583							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-31-02-301	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)								Service ATA:72
	MOS/MSC		N/A						
	HRS								
	ENC								
PROC. REF: AMM 72 31 02 280 801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
72-31-02-301	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)								Service	ATA:72
	MOS/MSC	N/A								
	HRS									
	ENC									
PROC. REF: AMM 72 31 02 280 801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801PROC. REF: AMM 72 31 02 280 801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801, AMM 72-31-02-280-801										
72-32-02-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES								Service	ATA:72
	MOS	14-Aug-25	MRB							
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)			
WC#: 72.020	ENC	4582								
PKG:4										
PROC. REF: AMM 72 32 02 220 801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801PROC. REF: AMM 72 32 02 220 801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801										
72-32-02-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES								Service	ATA:72
	MOS	14-Aug-25	MRB							
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)			
WC#: 72.020	ENC	4582								
PKG:4										
PROC. REF: AMM 72 32 02 220 801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801PROC. REF: AMM 72 32 02 220 801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801, AMM 72-32-02-220-801										
72-32-02-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES								Service	ATA:72
	MOS	14-Aug-25	MRB							
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)			
WC#: 72.025	ENC	4582								
PKG:4										
PROC. REF: AMM 72 32 02 220 802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802PROC. REF: AMM 72 32 02 220 802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-32-02-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)	Adj 50	(9695) 9695	9745	776.4 (+50)		
WC#: 72.025	ENC	4582							
PROC. REF: AMM 72 32 02 220 802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802PROC. REF: AMM 72 32 02 220 802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802, AMM 72-32-02-220-802									
72-33-00-301	NO. 1 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)								Service ATA:72
	MOS/MSC		N/A						
	HRS	0							
WC#: 72.030	ENC	0							
PROC. REF: AMM 75 31 01 640 801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801PROC. REF: AMM 75 31 01 640 801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801									
72-33-00-301	NO. 2 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)								Service ATA:72
	MOS/MSC		N/A						
	HRS	0							
WC#: 72.030	ENC	0							
PROC. REF: AMM 75 31 01 640 801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801PROC. REF: AMM 75 31 01 640 801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801, AMM 75-31-01-640-801									
72-34-01-201 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 72.035	ENC	4582							
PROC. REF: AMM 72 34 01 210 802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802PROC. REF: AMM 72 34 01 210 802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802									
72-34-01-201 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 72.035	ENC	4582							
PROC. REF: AMM 72 34 01 210 802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802PROC. REF: AMM 72 34 01 210 802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802, AMM 72-34-01-210-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-38-01-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING								Service ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7430.4	2000 (+50/-50)	Adj 50	(9480.4) 9480.4	9530.4	561.8 (+50)		
WC# : 72.040	ENC	3923							
PROC. REF: AMM 72 38 01 210 801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801PROC. REF: AMM 72 38 01 210 801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801									
72-38-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING								Service ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7425.2	2000 (+50/-50)	Adj 3.6	(9428.8) 9428.8	9478.8	510.2 (+50)		
WC# : 72.040	ENC	3921							
PROC. REF: AMM 72 38 01 210 801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801PROC. REF: AMM 72 38 01 210 801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801, AMM 72-38-01-210-801									
72-40-00-203 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC# : 72.045	ENC	4582							
PKG:4									
PROC. REF: AMM 72 40 00 220 801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801PROC. REF: AMM 72 40 00 220 801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801									
72-40-00-203 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC# : 72.045	ENC	4582							
PKG:4									
PROC. REF: AMM 72 40 00 220 801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801PROC. REF: AMM 72 40 00 220 801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801, AMM 72-40-00-220-801									
72-40-00-204 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES								Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC# : 72.050	ENC	4582							
PKG:4									
PROC. REF: AMM 72 40 00 220 802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802PROC. REF: AMM 72 40 00 220 802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-40-00-204	^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES							Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 72.050	ENC	4582							
PROC. REF: AMM 72 40 00 220 802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802 PROC. REF: AMM 72 40 00 220 802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802, AMM 72-40-00-220-802									
72-40-00-205	^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES							Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 72.055	ENC	4582							
PROC. REF: AMM 72 40 00 220 803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803 PROC. REF: AMM 72 40 00 220 803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803									
72-40-00-205	^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES							Service ATA:72
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 72.055	ENC	4582							
PROC. REF: AMM 72 40 00 220 803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803 PROC. REF: AMM 72 40 00 220 803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803, AMM 72-40-00-220-803									
72-50-00-204		NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM							Service ATA:72
	MOS	29-Aug-16						MRB	
	HRS	4985.4	5000 (+50/-50)	Adj 14.6	(10000) 10000	10050	1081.4 (+50)		
WC#: 72.520	ENC	2563							
PROC. REF: AMM 72 50 00 280 801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801 PROC. REF: AMM 72 50 00 280 801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801									
72-50-00-204		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM							Service ATA:72
	MOS	29-Aug-16						MRB	
	HRS	4985.4	5000 (+50/-50)	Adj 14.6	(10000) 10000	10050	1081.4 (+50)		
WC#: 72.520	ENC	2563							
PROC. REF: AMM 72 50 00 280 801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801 PROC. REF: AMM 72 50 00 280 801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801, AMM 72-50-00-280-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-50-00-205	NO. 1 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM								Service ATA:72
	MOS							MRB	
	HRS	EFF	5000 (+50/-50)		(10000) 10000 * (M)	10050	1081.4 (+50)		
	ENC								
PROC. REF: AMM 72 50 00 220 801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801PROC. REF: AMM 72 50 00 220 801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801									
72-50-00-205	NO. 2 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM								Service ATA:72
	MOS							MRB	
	HRS	EFF	5000 (+50/-50)		(10000) 10000 * (M)	10050	1081.4 (+50)		
	ENC								
PROC. REF: AMM 72 50 00 220 801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801PROC. REF: AMM 72 50 00 220 801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801, AMM 72-50-00-220-801									
72-71-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT								Service ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7430.4	2000 (+50/-50)	Adj 50	(9480.4) 9480.4	9530.4	561.8 (+50)		
WC#: 72.060	ENC	3923							
PROC. REF: AMM 72 71 00 210 801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801PROC. REF: AMM 72 71 00 210 801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801									
72-71-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT								Service ATA:72
	MOS	20-Apr-22						MRB	
	HRS	7425.2	2000 (+50/-50)	Adj 3.6	(9428.8) 9428.8	9478.8	510.2 (+50)		
WC#: 72.060	ENC	3921							
PROC. REF: AMM 72 71 00 210 801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801PROC. REF: AMM 72 71 00 210 801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801, AMM 72-71-00-210-801									
720001-001	NO. 1 ENGINE - 31 LP COMPRESSOR FAN MODULE								Component ATA:72
PN:M31-113	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:31101501	HRS	0		TSN 0					
WC#: 72.065	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720001-001	NO. 2 ENGINE - 31 LP COMPRESSOR FAN MODULE								Component ATA:72
PN:M31-113	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:31101502	HRS	0		TSN 0					
WC#: 72.065	ENC	0		TSN 0					
720002-001	NO. 1 ENGINE - 32 INTERMEDIATE CASE MODULE								Component ATA:72
PN:M32-121	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:32121372	HRS	0		TSN 0					
WC#: 72.070	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720002-001	NO. 2 ENGINE - 32 INTERMEDIATE CASE MODULE								Component ATA:72
PN:M32-121	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:32121373	HRS	0		TSN 0					
WC#: 72.070	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720003-001	NO. 1 ENGINE - 33 HP COMPRESSOR MODULE								Component ATA:72
PN:M33-114	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:33121374	HRS	0		TSN 0					
WC#: 72.075	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720003-001	NO. 2 ENGINE - 33 HP COMPRESSOR MODULE								Component ATA:72
PN:M33-114	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:33121375	HRS	0		TSN 0					
WC#: 72.075	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720004-001	NO. 1 ENGINE - 34 LP COMPRESSOR CASE MODULE								Component ATA:72
PN:M34-110	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:34101489	HRS	0		TSN 0					
WC#: 72.080	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720004-001	NO. 2 ENGINE - 34 LP COMPRESSOR CASE MODULE								Component ATA:72
PN:M34-110	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:34101490	HRS	0		TSN 0					
WC#: 72.080	ENC	0		TSN 0					
720005-001	NO. 1 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE								Component ATA:72
PN:M41-125	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:41121372	HRS	0		TSN 0					
WC#: 72.085	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720005-001	NO. 2 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE								Component ATA:72
PN:M41-125	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:41121373	HRS	0		TSN 0					
WC#: 72.085	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720006-001	NO. 1 ENGINE - 51 LP TURBINE MODULE								Component ATA:72
PN:M51-111	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:51101489	HRS	0		TSN 0					
WC#: 72.090	ENC	0		TSN 0					
720006-001	NO. 2 ENGINE - 51 LP TURBINE MODULE								Component ATA:72
PN:M51-111	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:51101490	HRS	0		TSN 0					
WC#: 72.090	ENC	0		TSN 0					
720007-001	NO. 1 ENGINE - 61 ACCESSORY GEARBOX MODULE								Component ATA:72
PN:M61-185	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:61121372	HRS	0		TSN 0					
WC#: 72.095	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720007-001	NO. 2 ENGINE - 61 ACCESSORY GEARBOX MODULE								Component ATA:72
PN:M61-185	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:61121373	HRS	0		TSN 0					
WC#: 72.095	ENC	0		TSN 0					
720304-015	NO. 1 ENGINE - NO. 2 BOLT, BIHEX, HD								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
720304-015	NO. 2 ENGINE - NO. 2 BOLT, BIHEX, HD								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
723204-001	NO. 1 ENGINE - NO 3 BEARING								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.360	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723204-001	NO. 2 ENGINE - NO 3 BEARING								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.360	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-001	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2345	HRS	0		TSN 0					
WC#: 72.365	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723205-001	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2353	HRS	0		TSN 0					
WC#: 72.365	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-002	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2346	HRS	0		TSN 0					
WC#: 72.370	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-002	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2354	HRS	0		TSN 0					
WC#: 72.370	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-003	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2347	HRS	0		TSN 0					
WC#: 72.375	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-003	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2355	HRS	0		TSN 0					
WC#: 72.375	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723205-004	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2348	HRS	0		TSN 0					
WC#: 72.380	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723205-004 NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component	ATA:72
PN:1022-1-11	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2356	HRS	0		TSN 0					
WC#: 72.380	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723206-001 NO. 1 ENGINE - BEARING OUTER RING								Component	ATA:72
PN:BRR12474	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:821	HRS	0		TSN 0					
WC#: 72.385	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723206-001 NO. 2 ENGINE - BEARING OUTER RING								Component	ATA:72
PN:BRR12474	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:829	HRS	0		TSN 0					
WC#: 72.385	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723206-002 NO. 1 ENGINE - BEARING ASSEMBLY								Component	ATA:72
PN:BRR22056	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:890	HRS	0		TSN 0					
WC#: 72.390	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723206-002 NO. 2 ENGINE - BEARING ASSEMBLY								Component	ATA:72
PN:BRR22056	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:888	HRS	0		TSN 0					
WC#: 72.390	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723207-001 NO. 1 ENGINE - INNER REAR BEARING								Component	ATA:72
PN:BRR23643	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:628	HRS	0		TSN 0					
WC#: 72.395	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723207-001	NO. 2 ENGINE - INNER REAR BEARING								Component ATA:72
PN:BRR23643	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:625	HRS	0		TSN 0					
WC#: 72.395	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723208-001	NO. 1 ENGINE - FRONT LPC BEARING								Component ATA:72
PN:BRR24148	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:660	HRS	0		TSN 0					
WC#: 72.400	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723208-001	NO. 2 ENGINE - FRONT LPC BEARING								Component ATA:72
PN:BRR24148	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:662	HRS	0		TSN 0					
WC#: 72.400	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723303-001	NO. 1 ENGINE - ASSEMBLY OF HPC NOZZLE								Component ATA:72
PN:BRR21927	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1326	HRS	0		TSN 0					
WC#: 72.415	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723303-001	NO. 2 ENGINE - ASSEMBLY OF HPC NOZZLE								Component ATA:72
PN:BRR21927	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1328	HRS	0		TSN 0					
WC#: 72.415	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723802-001	NO. 1 ENGINE - NOSE CONE ASSEMBLY								Component ATA:72
PN:KH96766	MOS/MSC	17-Jun-24	O/C	TSN 3					
SN:NSN	HRS	8280.9		TSN 0					
WC#: 72.425	ENC	4430		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723802-001	NO. 2 ENGINE - NOSE CONE ASSEMBLY								Component ATA:72
PN:BRR24229	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:20833523698527	HRS	6740.2		TSN 0					
WC#: 72.425	ENC	3480		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725123-001	NO. 1 ENGINE - STUB SHAFT ASSEMBLY								Component ATA:72
PN:BRR40703	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:672	HRS	0		TSN 0					
WC#: 72.480	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725123-001	NO. 2 ENGINE - STUB SHAFT ASSEMBLY								Component ATA:72
PN:BRR40703	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:684	HRS	0		TSN 0					
WC#: 72.480	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725613-001	NO. 1 ENGINE - REAR MOUNT RING								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.490	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725613-001	NO. 2 ENGINE - REAR MOUNT RING								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.490	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726100-001	NO. 1 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:39600219	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:558	HRS	0		TSN 0					
WC#: 72.495	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726100-001	NO. 2 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:39600219	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:554	HRS	0		TSN 0					
WC#: 72.495	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726101-001	NO. 1 ENGINE - VALVE								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726101-001	NO. 2 ENGINE - VALVE								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726102-001	NO. 1 ENGINE - GRAVITY OIL FILLER								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726102-001	NO. 2 ENGINE - GRAVITY OIL FILLER								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726103-001	NO. 1 ENGINE - OIL LEVEL SENSOR								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726103-001	NO. 2 ENGINE - OIL LEVEL SENSOR								Component ATA:72
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 73 - ENGINE FUEL AND CONTROL									
73-00-00-201 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS								Service ATA:73
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 73.005	ENC	4582							
PROC. REF: AMM 73 00 00 210 801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801PROC. REF: AMM 73 00 00 210 801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801									
73-00-00-201 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS								Service ATA:73
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 73.005	ENC	4582							
PROC. REF: AMM 73 00 00 210 801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801PROC. REF: AMM 73 00 00 210 801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801, AMM 73-00-00-210-801									
73-12-01-201 ^S	NO. 1 ENGINE - DISCARD THE LP FUEL FILTER								Service ATA:73
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 73.010	ENC	4582							
PROC. REF: AMM 73 12 01 961 801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801PROC. REF: AMM 73 12 01 961 801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801									
73-12-01-201 ^S	NO. 2 ENGINE - DISCARD THE LP FUEL FILTER								Service ATA:73
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 73.010	ENC	4582							
PROC. REF: AMM 73 12 01 961 801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801PROC. REF: AMM 73 12 01 961 801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801, AMM 73-12-01-961-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
Serial: 9175
RegNo: N117TP
HRS: 8918.6
AFL: 4707
As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
73-21-05-201 DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE T20/P20 SENSORS CONNECTORS									Service ATA:73
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 73-21-05-220-801PROC. REF: AMM 73-21-05-220-801									PKG:38

731101-001		NO. 1 ENGINE - FUEL PUMP				Component	ATA:73
PN:828200-3	MOS/MSC	08-Jul-20	O/C	TSO 4			
SN:2396	HRS	6911.6	TSN 7663.3, TSO 0				
WC#: 73.030	ENC	3586	TSN 2786, TSO 0				

731101-001		NO. 2 ENGINE - FUEL PUMP				Component	ATA:73
PN:828200-3	MOS/MSC	08-Jul-20	O/C	TSO 4			
SN:2458	HRS	6911.6	TSN 5841, TSO 0				
WC#: 73.030	ENC	3586	TSN 1732, TSO 0				

731102-001		NO. 1 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR				Component	ATA:73
PN:0154HY	MOS/MSC	14-May-19	O/C				
SN:R6904	HRS	6477.6			TSN 1799		
WC#: 73.185	ENC	3345			TSN 619		

731102-001		NO. 2 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR				Component	ATA:73
PN:0154HY	MOS/MSC	19-Aug-19	O/C	TSN 3			
SN:U7487	HRS	6623.5	TSN 0				
WC#: 73.185	ENC	3408	TSN 0				

731201-001					NO. 1 ENGINE - TUBE ASSY					Component	ATA:73
PN:PN		MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:UNKNOWN		HRS	0		TSN 0						
WC#: 73.035		ENC	0		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731201-001	NO. 2 ENGINE - TUBE ASSY								Component ATA:73
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.035	ENC	0		TSN 0					
731201-711 ^U	NO. 1 ENGINE - FUEL LP ELEMENT FILTER								Component ATA:73
PN:PN-UNKNOWN	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
	ENC	4582		TSN 0					
731201-711 ^U	NO. 2 ENGINE - FUEL LP ELEMENT FILTER								Component ATA:73
PN:PN-UNKNOWN	MOS/MSC	14-Aug-25	O/C	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
	ENC	4582		TSN 0					
731301-001	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42383	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.040	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-001	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16675	HRS	0		TSN 0					
WC#: 73.040	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-002	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	17-Oct-23	O/C	TSO 19					
SN:N5192	HRS	8061.2		TSN 7865.1, TSO 0					
WC#: 73.045	ENC	4284		TSN 2395, TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-002		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16676	HRS	0		TSN 0					
WC#: 73.045	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-003		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42389	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.050	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-003		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16677	HRS	0		TSN 0					
WC#: 73.050	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-004		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16962	HRS	0		TSN 0					
WC#: 73.055	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-004		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16678	HRS	0		TSN 0					
WC#: 73.055	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-005		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42391	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.060	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-005		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16679	HRS	0		TSN 0					
WC#: 73.060	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-006		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16964	HRS	0		TSN 0					
WC#: 73.065	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-006		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16680	HRS	0		TSN 0					
WC#: 73.065	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-007		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16965	HRS	0		TSN 0					
WC#: 73.070	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-007		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16681	HRS	0		TSN 0					
WC#: 73.070	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-008		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16966	HRS	0		TSN 0					
WC#: 73.075	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-008		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16682	HRS	0		TSN 0					
WC#: 73.075	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-009		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42394	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.080	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-009		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16683	HRS	0		TSN 0					
WC#: 73.080	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-010		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16968	HRS	0		TSN 0					
WC#: 73.085	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-010		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16684	HRS	0		TSN 0					
WC#: 73.085	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-011		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42395	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.090	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-011		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16685	HRS	0		TSN 0					
WC#: 73.090	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-012		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16970	HRS	0		TSN 0					
WC#: 73.095	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-012		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	14-Jun-23	O/C	TSO 15					
SN:N5162	HRS	7864.7		TSN 7865.1, TSO 0					
WC#: 73.095	ENC	4198		TSN 2395, TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-013		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	26-Jun-20	O/C						
SN:N42397	HRS	6911.6		TSN 6185, TSR 0					
WC#: 73.100	ENC	3586		TSN 2594, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-013		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16687	HRS	0		TSN 0					
WC#: 73.100	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-014		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16972	HRS	0		TSN 0					
WC#: 73.105	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-014	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16688	HRS	0		TSN 0					
WC#: 73.105	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-015	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16973	HRS	0		TSN 0					
WC#: 73.110	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-015	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16689	HRS	0		TSN 0					
WC#: 73.110	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-016	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16974	HRS	0		TSN 0					
WC#: 73.115	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-016	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16690	HRS	0		TSN 0					
WC#: 73.115	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-017	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16975	HRS	0		TSN 0					
WC#: 73.120	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-017		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16691	HRS	0		TSN 0					
WC#: 73.120	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-018		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16976	HRS	0		TSN 0					
WC#: 73.125	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-018		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16692	HRS	0		TSN 0					
WC#: 73.125	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-019		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16977	HRS	0		TSN 0					
WC#: 73.130	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-019		NO. 2 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	17-Oct-23	O/C	TSO 19					
SN:N5251	HRS	8061.2		TSN 7865.1, TSO 0					
WC#: 73.130	ENC	4284		TSN 2395, TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731301-020		NO. 1 ENGINE - FUEL BURNER						Component	ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16978	HRS	0		TSN 0					
WC#: 73.135	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731301-020	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N16694	HRS	0		TSN 0					
WC#: 73.135	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731302-001	NO. 1 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD								Component ATA:73
PN:8910-214	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14249614	HRS	0		TSN 0					
WC#: 73.140	ENC	0		TSN 0					
731302-001	NO. 2 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD								Component ATA:73
PN:8910-214	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14234317	HRS	0		TSN 0					
WC#: 73.140	ENC	0		TSN 0					
731303-001	NO. 1 ENGINE - FUEL RETURN TANK TRANSFERS VALVE								Component ATA:73
PN:8910-312	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14242505	HRS	0		TSN 0					
WC#: 73.145	ENC	0		TSN 0					
731303-001	NO. 2 ENGINE - FUEL RETURN TANK TRANSFERS VALVE								Component ATA:73
PN:8910-312	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14180389	HRS	0		TSN 0					
WC#: 73.145	ENC	0		TSN 0					
732101-001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC								Component ATA:73
PN:1520KDC07-011	MOS/MSC	08-Jan-24	O/C	TSR 58					
SN:BX660054	HRS	8135.3		TSN 7948.2, TSR 1662.4					
WC#: 73.150	ENC	4329		TSN 3356, TSR 995					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732101-001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC								Component ATA:73
PN:1520KDC05-011	MOS/MSC	08-Jan-24	O/C						
SN:BX80005	HRS	8135.3			TSN 8280.2				
WC#: 73.150	ENC	4329			TSN 3280				
732102-001	NO. 1 ENGINE - FUEL UNIT METER								Component ATA:73
PN:8061-977	MOS/MSC	07-Oct-05	O/C		TSN 0				
SN:14241611	HRS	0			TSN 0				
WC#: 73.155	ENC	0			TSN 0				
732102-001	NO. 2 ENGINE - FUEL UNIT METER								Component ATA:73
PN:8061-977	MOS/MSC	21-Feb-11	O/C		TSR 1				
SN:16477706	HRS	2010.7			TSN 132.9, TSR 0				
WC#: 73.155	ENC	1093			TSN 55, TSR 0				
732103-001	NO. 1 ENGINE - DEDICATED GENERATOR ROTOR								Component ATA:73
PN:83311-430242	MOS/MSC	07-Oct-05	O/C		TSN 0				
SN:2576	HRS	0			TSN 0				
WC#: 73.160	ENC	0			TSN 0				
732103-001	NO. 2 ENGINE - DEDICATED GENERATOR ROTOR								Component ATA:73
PN:83311-430242	MOS/MSC	07-Oct-05	O/C		TSN 0				
SN:2640	HRS	0			TSN 0				
WC#: 73.160	ENC	0			TSN 0				
732104-001	NO. 1 ENGINE - DEDICATED GENERATOR STATOR								Component ATA:73
PN:514842-1	MOS/MSC	23-Feb-15	O/C		TSN 0				
SN:N14490028	HRS	4146.2			TSN 0				
WC#: 73.165	ENC	2162			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732104-001	NO. 2 ENGINE - DEDICATED GENERATOR STATOR								Component ATA:73
PN:514842-1	MOS/MSC	16-Feb-15	O/C	TSN 0					
SN:N14490016	HRS	4143.1		TSN 0					
WC#: 73.165	ENC	2155		TSN 0					
732104-002	NO. 1 ENGINE - DATA ENTRY PLUG								Component ATA:73
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.170	ENC	0		TSN 0					
732104-002	NO. 2 ENGINE - DATA ENTRY PLUG								Component ATA:73
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.170	ENC	0		TSN 0					
732105-001	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RRAD0317	HRS	0		TSN 0					
WC#: 73.175	ENC	0		TSN 0					
732105-001	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RRAD0319	HRS	0		TSN 0					
WC#: 73.175	ENC	0		TSN 0					
732105-002	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RRAD0293	HRS	0		TSN 0					
WC#: 73.180	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732105-002	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RRAD0288	HRS	0		TSN 0					
WC#: 73.180	ENC	0		TSN 0					
733101-001	NO. 1 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:9-217-82	MOS/MSC	05-Nov-15	O/C	TSR 11					
SN:170436-178	HRS	4541.6		TSN 1824, TSR 0					
WC#: 73.190	ENC	2349		TSN 592, TSR 0					
733101-001	NO. 2 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:9-217-49	MOS/MSC	11-Jun-08	O/C						
SN:170436-3	HRS	749.6		TSN 512.3					
WC#: 73.190	ENC	425		TSN 161					
733303-001	NO. 1 ENGINE - FUEL LOW PRESSURE SWITCH								Component ATA:73
PN:21SN04-433	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E064824	HRS	0		TSN 0					
WC#: 73.195	ENC	0		TSN 0					
733303-001	NO. 2 ENGINE - FUEL LOW PRESSURE SWITCH								Component ATA:73
PN:21SN04-433	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:E064825	HRS	0		TSN 0					
WC#: 73.195	ENC	0		TSN 0					
733401-001	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:73
PN:21SN04-430	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:F011198	HRS	0		TSN 0					
WC#: 73.200	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

733401-001	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH							Component	ATA:73
PN:21SN04-430	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:F010627	HRS	0		TSN 0					
WC#: 73.200	ENC	0		TSN 0					

ATA 74 - IGNITION

74-30-01-201	^S	LH ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH						Service	ATA:74
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500 (+50/-50)						
	AFL	4570							
PROC. REF: AMM 74-30-01-710-801PROC. REF: AMM 74-30-01-710-801									

PKG:2

74-30-01-201	^S	RH ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH						Service	ATA:74
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500 (+50/-50)						
	AFL	4570							
PROC. REF: AMM 74-30-01-710-801PROC. REF: AMM 74-30-01-710-801									

PKG:2

741001-001	NO. 1 ENGINE - EXCITER UNIT IGNITION							Component	ATA:74
PN:9060440-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05109521	HRS	0		TSN 0					
WC#: 74.010	ENC	0		TSN 0					

741001-001	NO. 2 ENGINE - EXCITER UNIT IGNITION							Component	ATA:74
PN:9060440-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05099202	HRS	0		TSN 0					
WC#: 74.010	ENC	0		TSN 0					

741001-002	NO. 1 ENGINE - EXCITER UNIT IGNITION							Component	ATA:74
PN:9060440-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05109524	HRS	0		TSN 0					
WC#: 74.015	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
741001-002	NO. 2 ENGINE - EXCITER UNIT IGNITION								Component ATA:74
PN:9060440-2	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:05099203	HRS	0		TSN 0					
WC#: 74.015	ENC	0		TSN 0					
742001-001	NO. 1 ENGINE - LH IGNITOR PLUG								Component ATA:74
PN:CH34760-2	MOS/MSC	14-Jun-23	O/C						
SN:22049876	HRS	7864.7							
WC#: 74.020	ENC	4198							
742001-001	NO. 2 ENGINE - LH IGNITOR PLUG								Component ATA:74
PN:CH34760-2	MOS/MSC	14-Jun-23	O/C						
SN:22049856	HRS	7864.7							
WC#: 74.020	ENC	4198							
742001-002	NO. 1 ENGINE - RH IGNITOR PLUG								Component ATA:74
PN:CH347760-2	MOS/MSC	14-Jun-23	O/C						
SN:2209682	HRS	7864.7							
WC#: 74.025	ENC	4198							
742001-002	NO. 2 ENGINE - RH IGNITOR PLUG								Component ATA:74
PN:CH34760-2	MOS/MSC	14-Jun-23	O/C						
SN:22049661	HRS	7864.7							
WC#: 74.025	ENC	4198							
ATA 75 - AIR									
752201-001	NO. 1 ENGINE - AIR BUFFER VALVE								Component ATA:75
PN:8910-512	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14248051	HRS	0		TSN 0					
WC#: 75.010	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
752201-001	NO. 2 ENGINE - AIR BUFFER VALVE								Component ATA:75
PN:8910-512	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14216204	HRS	0		TSN 0					
WC#: 75.010	ENC	0		TSN 0					
753101-001	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELG037	HRS	0		TSN 0					
WC#: 75.015	ENC	0		TSN 0					
753101-001	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELB368	HRS	0		TSN 0					
WC#: 75.015	ENC	0		TSN 0					
753101-002	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELG038	HRS	0		TSN 0					
WC#: 75.020	ENC	0		TSN 0					
753101-002	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELB369	HRS	0		TSN 0					
WC#: 75.020	ENC	0		TSN 0					
753101-003	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELG039	HRS	0		TSN 0					
WC#: 75.025	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
753101-003	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELB370	HRS	0		TSN 0					
WC#: 75.025	ENC	0		TSN 0					
753101-004	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELG040	HRS	0		TSN 0					
WC#: 75.030	ENC	0		TSN 0					
753101-004	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELA374	HRS	0		TSN 0					
WC#: 75.030	ENC	0		TSN 0					
753102-001	NO. 1 ENGINE - BLEED SOLENOID BLOCK VALVE								Component ATA:75
PN:EA100118G	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELH322	HRS	0		TSN 0					
WC#: 75.035	ENC	0		TSN 0					
753102-001	NO. 2 ENGINE - BLEED SOLENOID BLOCK VALVE								Component ATA:75
PN:EA100118G	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:ELC268	HRS	0		TSN 0					
WC#: 75.035	ENC	0		TSN 0					
753103-001	NO. 1 ENGINE - VANE STATOR VARIABLE ACTUATOR								Component ATA:75
PN:8100-115	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14134903	HRS	0		TSN 0					
WC#: 75.040	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10
 Serial: 9175
 RegNo: N117TP
 HRS: 8918.6
 AFL: 4707
 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
753103-001	NO. 2 ENGINE - VANE STATOR VARIABLE ACTUATOR								Component ATA:75
PN:8100-115	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:14248039	HRS	0		TSN 0					
WC#: 75.040	ENC	0		TSN 0					
ATA 76 - ENGINE CONTROLS									
76-10-01-900-801-01	THROTTLE QUADRANT								Component ATA:76
PN:GH562-3001-5	MOS/MSC	03-Dec-10	O/C						
SN:D0048	HRS	1959.4							
WC#: 76.005	AFL	1014							
PROC. REF: AMM 76-10-01-000-801, AMM 76-10-01-400-801PROC. REF: AMM 76-10-01-000-801, AMM 76-10-01-400-801									
ATA 77 - ENGINE INDICATING									
77-31-04-900-801-01	EVMU ENGINE VIBRATION MONITORING UNIT								Component ATA:77
PN:10609B10B14	MOS/MSC	29-Sep-10	O/C	TSR 5					
SN:B511	HRS	1768.8		TSN 2196.5, TSR 0					
WC#: 77.005	AFL	966		TSN 626, TSR 0					
PROC. REF: AMM 77-31-04-000-801, AMM 77-31-04-400-801PROC. REF: AMM 77-31-04-000-801, AMM 77-31-04-400-801									
771201-001	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6702	HRS	0		TSN 0					
WC#: 77.010	ENC	0		TSN 0					
771201-001	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6719	HRS	0		TSN 0					
WC#: 77.010	ENC	0		TSN 0					
771201-002	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6703	HRS	0		TSN 0					
WC#: 77.015	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771201-002	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6720	HRS	0		TSN 0					
WC#: 77.015	ENC	0		TSN 0					
771201-003	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6704	HRS	0		TSN 0					
WC#: 77.020	ENC	0		TSN 0					
771201-003	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6721	HRS	0		TSN 0					
WC#: 77.020	ENC	0		TSN 0					
771201-004	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6706	HRS	0		TSN 0					
WC#: 77.025	ENC	0		TSN 0					
771201-004	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:6722	HRS	0		TSN 0					
WC#: 77.025	ENC	0		TSN 0					
772101-001	NO. 1 ENGINE - NO. 1 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF001494	HRS	0		TSN 0					
WC#: 77.030	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-001	NO. 2 ENGINE - NO. 1 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF001529	HRS	0		TSN 0					
WC#: 77.030	ENC	0		TSN 0					
772101-002	NO. 1 ENGINE - NO. 2 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF001515	HRS	0		TSN 0					
WC#: 77.035	ENC	0		TSN 0					
772101-002	NO. 2 ENGINE - NO. 2 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002308	HRS	0		TSN 0					
WC#: 77.035	ENC	0		TSN 0					
772101-003	NO. 1 ENGINE - NO. 3 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002016	HRS	0		TSN 0					
WC#: 77.040	ENC	0		TSN 0					
772101-003	NO. 2 ENGINE - NO. 3 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002720	HRS	0		TSN 0					
WC#: 77.040	ENC	0		TSN 0					
772101-004	NO. 1 ENGINE - NO. 4 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002310	HRS	0		TSN 0					
WC#: 77.045	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-004	NO. 2 ENGINE - NO. 4 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002726	HRS	0		TSN 0					
WC#: 77.045	ENC	0		TSN 0					
772101-005	NO. 1 ENGINE - NO. 5 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002307	HRS	0		TSN 0					
WC#: 77.050	ENC	0		TSN 0					
772101-005	NO. 2 ENGINE - NO. 5 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002729	HRS	0		TSN 0					
WC#: 77.050	ENC	0		TSN 0					
772101-006	NO. 1 ENGINE - NO. 6 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002348	HRS	0		TSN 0					
WC#: 77.055	ENC	0		TSN 0					
772101-006	NO. 2 ENGINE - NO. 6 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002744	HRS	0		TSN 0					
WC#: 77.055	ENC	0		TSN 0					
772101-007	NO. 1 ENGINE - NO. 7 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002000	HRS	0		TSN 0					
WC#: 77.060	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
772101-007	NO. 2 ENGINE - NO. 7 THERMOCOUPLE PROBE								Component ATA:77
PN:8TC60AAC1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:MF002745	HRS	0		TSN 0					
WC#: 77.060	ENC	0		TSN 0					
772201-001	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component ATA:77
PN:920-4-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1935	HRS	0		TSN 0					
WC#: 77.065	ENC	0		TSN 0					
772101-001	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component ATA:77
PN:920-4-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1871	HRS	0		TSN 0					
WC#: 77.065	ENC	0		TSN 0					
772201-002	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component ATA:77
PN:920-4-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1938	HRS	0		TSN 0					
WC#: 77.070	ENC	0		TSN 0					
772201-002	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component ATA:77
PN:920-4-14	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:1954	HRS	0		TSN 0					
WC#: 77.070	ENC	0		TSN 0					
773101-001	NO. 1 ENGINE - ENGINE VIBRATION MONITORING CABLE ASSEMBLY								Component ATA:77
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
773101-001	NO. 2 ENGINE - ENGINE VIBRATION MONITORING CABLE ASSEMBLY							Component	ATA:77
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
ATA 78 - EXHAUST									
78-10-01-201	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
	ENC	4582							
PROC. REF: AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801PROC. REF: AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801									
PKG:4									
78-10-01-201	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
	ENC	4582							
PROC. REF: AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801PROC. REF: AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801, AMM 78-10-01-210-801									
PKG:4									
78-10-02-201	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
	ENC	4582							
PROC. REF: AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801PROC. REF: AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801									
PKG:4									
78-10-02-201	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
	ENC	4582							
PROC. REF: AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801PROC. REF: AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801, AMM 78-10-02-210-801									
PKG:4									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-30-00-201	S	GENERAL VISUAL INSPECTION OF THE THRUST-REVERSER THERMAL BLANKET							Service ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 78.015	AFL	4582							
PROC. REF: AMM 78-30-00-210-805PROC. REF: AMM 78-30-00-210-805									
78-30-00-204	S	FUNCTIONAL TEST OF THE THRUST REVERSER							Service ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	4500 (+50/-50)						
WC#: 78.025	AFL	4582							
PROC. REF: AMM 78-30-00-720-802PROC. REF: AMM 78-30-00-720-802									
78-30-00-205	S	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER P-SEALS AND SEAL DEPRESSORS/SUPPORT							Service ATA:78
	MOS	14-Aug-25	30 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 78-30-00-210-808PROC. REF: AMM 78-30-00-210-808									
78-30-00-206		DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE THRUST REVERSERS ELECTRICAL CONNECTORS							Service ATA:78
	MOS	14-Aug-25	120 (+3m/-3m)	Adj 3	14-Nov-35	14-Feb-36	3429 d (+92)	MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 78-30-00-220-801PROC. REF: AMM 78-30-00-220-801									
78-30-00-900-801-01		LEFT THRUST REVERSER							Component ATA:78
PN:07G0001-009	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:369	HRS	0		TSN 0					
WC#: 78.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-30-00-900-801-02		RIGHT THRUST REVERSER						Component	ATA:78
PN:07G0001-015	MOS/MSC	18-Oct-09	O/C						
SN:RH 714	HRS	1344.7		TSN 0					
WC#: 78.070	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-31-01-101		DETAILED INSPECTION OF THE THRUST REVERSER UPPER DOOR (AWL*)						Service	ATA:78
	MOS							AIRWORTHINESS	
	HRS	0							
WC#: 78.030	AFL	0	T:7500		7500		2793		
PROC. REF: AMM 78-31-01-220-803PROC. REF: AMM 78-31-01-220-803									
78-31-01-201 ^S		DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (METALLIC)						Service	ATA:78
	MOS	14-Aug-25	120 (+3m/-3m)					MRB	
	HRS	8645							
WC#: 78.035	AFL	4582							
PROC. REF: AMM 78-31-01-220-802PROC. REF: AMM 78-31-01-220-802									
78-31-01-202		SPECIAL DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (COMPOSITE)						Service	ATA:78
	MOS	12-Jun-20						MRB	
	HRS	6911.6							
WC#: 78.040	AFL	3586	1875 (+50/-50)	Adj 50	5511	5561	804 (+50)		
PROC. REF: AMM 78-31-01-280-801PROC. REF: AMM 78-31-01-280-801									
78-31-01-900-801-01		UPPER LEFT THRUST REVERSER DOOR						Component	ATA:78
PN:04G0037-023	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UL1166	HRS	0		TSN 0					
WC#: 78.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-32-01-900-801-01		UPPER RIGHT THRUST REVERSER DOOR						Component	ATA:78
PN:04G2037-004	MOS/MSC	18-Oct-09	O/C						
SN:UR1545	HRS	1344.7		TSN 0					
WC#: 78.065	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-33-01-900-801-01		LH ISOLATION THRUST REVERSER VALVE						Component	ATA:78
PN:P472A0001-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW414-04	HRS	0		TSN 0					
WC#: 78.070	AFL	0		TSN 0					
PROC. REF: AMM 78-33-01-000-801, AMM 78-33-01-400-801PROC. REF: AMM 78-33-01-000-801, AMM 78-33-01-400-801									
78-33-01-900-801-02		RH ISOLATION THRUST REVERSER VALVE						Component	ATA:78
PN:P472A0001-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW355-02	HRS	0		TSN 0					
WC#: 78.070	AFL	0		TSN 0					
PROC. REF: AMM 78-33-01-000-801, AMM 78-33-01-400-801PROC. REF: AMM 78-33-01-000-801, AMM 78-33-01-400-801									
78-33-02-900-801-01		LH DIRECTIONAL CONTROL UNIT DCU						Component	ATA:78
PN:P473A0001-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW365-04	HRS	0		TSN 0					
WC#: 78.075	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-02-900-801-02		RH DIRECTIONAL CONTROL UNIT DCU						Component	ATA:78
PN:P473A0001-01	MOS/MSC	18-Oct-09	O/C						
SN:A0063078	HRS	1344.7		TSN 0					
WC#: 78.075	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-03-201 ^S		DETAILED INSPECTION OF THE THRUST REVERSER UNIT (TRU) PRIMARY-DOOR ACTUATOR-ROD END						Service	ATA:78
	MOS	14-Aug-25	60 (+3m/-3m)					MRB	
	HRS	8645							
	AFL	4582							
PROC. REF: AMM 78-33-03-220-801PROC. REF: AMM 78-33-03-220-801									
78-33-03-900-801-01		LEFT UPPER THRUST REVERSER DOOR ACTUATOR						Component	ATA:78
PN:P471A0001-01	MOS/MSC	26-Feb-25	O/C	TSR 0					
SN:23244088	HRS	8641.1		TSN 22.2, TSR 0					
WC#: 78.080	AFL	4580		TSN 15, TSR 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-33-03-900-801-02		LEFT LOWER THRUST REVERSER DOOR ACTUATOR						Component	ATA:78
PN:P471A0001-01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW1656-04	HRS	0		TSN 0					
WC#: 78.080	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-03-900-801-03		RIGHT UPPER THRUST REVERSER DOOR ACTUATOR						Component	ATA:78
PN:P471A0001-01	MOS/MSC	18-Oct-09	O/C						
SN:A0062723	HRS	1344.7		TSN 0					
WC#: 78.085	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-03-900-801-04		RIGHT LOWER THRUST REVERSER DOOR ACTUATOR						Component	ATA:78
PN:P471A0001-01	MOS/MSC	18-Oct-09	O/C						
SN:A0061281	HRS	1344.7		TSN 0					
WC#: 78.085	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-04-900-801-01		LOB PRIMARY LOCK ACTUATOR						Component	ATA:78
PN:P466A0001-02	MOS/MSC	07-Sep-07	O/C						
SN:DAW1098-01	HRS	431.5		TSN 1331					
WC#: 78.090	AFL	233		TSN 627					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-04-900-801-02		LIB PRIMARY LOCK ACTUATOR						Component	ATA:78
PN:P466A0001-02	MOS/MSC	07-Sep-07	O/C						
SN:DAW1097-01	HRS	431.5		TSN 1331					
WC#: 78.095	AFL	233		TSN 627					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-04-900-801-03		RIB PRIMARY LOCK ACTUATOR						Component	ATA:78
PN:P466A0001-02	MOS/MSC	18-Oct-09	O/C						
SN:A0061263	HRS	1344.7		TSN 0					
WC#: 78.095	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-33-04-900-801-04		ROB PRIMARY LOCK ACTUATOR						Component	ATA:78
PN:P466A0001-02	MOS/MSC	18-Oct-09	O/C						
SN:DAW3333-08	HRS	1344.7		TSN 0					
WC#: 78.090	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-05-101		OPERATIONAL TEST OF THE TERTIARY LOCK (CMR**)						Service	ATA:78
	MOS	14-Aug-25						CMR	
	HRS	8645	4500 (+50/-50)	Adj 50	13195	13245	4276.4 (+50)		
WC#: 78.045	AFL	4582							
PROC. REF: AMM 78-33-05-710-801PROC. REF: AMM 78-33-05-710-801									
78-33-05-201 ^S		GENERAL VISUAL INSPECTION OF THE TERTIARY LOCK HOOK						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
WC#: 78.050	AFL	4582							
PROC. REF: AMM 78-33-05-210-802PROC. REF: AMM 78-33-05-210-802									
78-33-05-203 ^S		GENERAL VISUAL INSPECTION OF THE PIVOTING DOOR KEEPER BAR						Service	ATA:78
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)						
	AFL	4582							
PROC. REF: AMM 78-33-05-210-803PROC. REF: AMM 78-33-05-210-803									
78-33-05-900-801-01		LEFT UPPER T/R TERTIARY LOCK						Component	ATA:78
PN:P516A0001-00	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW1880-04	HRS	0		TSN 0					
WC#: 78.095	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-05-900-801-02		LEFT LOWER T/R TERTIARY LOCK						Component	ATA:78
PN:P516A0001-00	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:DAW1860-04	HRS	0		TSN 0					
WC#: 78.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-33-05-900-801-03 RIGHT UPPER T/R TERTIARY LOCK									Component ATA:78
PN:P516A0001-00	MOS/MSC	18-Oct-09	O/C						
SN:DAW3362-08	HRS	1344.7			TSN 0				
WC#: 78.095	AFL	741			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-33-05-900-801-04 RIGHT LOWER T/R TERTIARY LOCK									Component ATA:78
PN:P516A0001-00	MOS/MSC	18-Oct-09	O/C						
SN:DAW3245-08	HRS	1344.7			TSN 0				
WC#: 78.100	AFL	741			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-01 LEFT UPPER INBOARD STOW SWITCH									Component ATA:78
PN:T7013-3	MOS/MSC	03-Aug-19	O/C		TSN 13				
SN:1062	HRS	6612.4			TSN 0				
WC#: 78.110	AFL	3393			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-02 LEFT UPPER OUTBOARD STOW SWITCH									Component ATA:78
PN:T7013-2	MOS/MSC	15-Jun-17	O/C		TSN 56				
SN:3692	HRS	5428.8			TSN 0				
WC#: 78.115	AFL	2792			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-03 LEFT LOWER OUTBOARD STOW SWITCH									Component ATA:78
PN:T7013	MOS/MSC	07-Oct-05	O/C		TSN 0				
SN:966	HRS	0			TSN 0				
WC#: 78.120	AFL	0			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-04 LEFT LOWER INBOARD STOW SWITCH									Component ATA:78
PN:T7013	MOS/MSC	07-Oct-05	O/C		TSN 0				
SN:980	HRS	0			TSN 0				
WC#: 78.125	AFL	0			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-34-01-900-801-05		RIGHT UPPER INBOARD STOW SWITCH						Component	ATA:78
PN:T7013	MOS/MSC	05-Feb-13	O/C	TSN 0					
SN:1856	HRS	3009.7		TSN 0					
WC#: 78.110	AFL	1574		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-06		RIGHT UPPER OUTBOARD STOW SWITCH						Component	ATA:78
PN:T7013-2	MOS/MSC	27-May-19	O/C	TSN 23					
SN:0363	HRS	6502.8		TSN 0					
WC#: 78.115	AFL	3361		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-07		RIGHT LOWER OUTBOARD STOW SWITCH						Component	ATA:78
PN:T7013-3	MOS/MSC	04-Sep-24	O/C	TSN 67					
SN:1694	HRS	8469.9		TSN 0					
WC#: 78.120	AFL	4493		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-01-900-801-08		RIGHT LOWER INBOARD STOW SWITCH						Component	ATA:78
PN:T7013-2	MOS/MSC	18-Oct-09	O/C						
SN:0595	HRS	1344.7		TSN 0					
WC#: 78.125	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-02-900-801-01		NO. 1 DOOR POSITION (LDVT) TRANSMITTER						Component	ATA:78
PN:133F025-005	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:A100674	HRS	0		TSN 0					
WC#: 78.105	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-02-900-801-02		NO. 2 DOOR POSITION (LDVT) TRANSMITTER						Component	ATA:78
PN:133F025005	MOS/MSC	18-Oct-09	O/C						
SN:A101688	HRS	1344.7		TSN 0					
WC#: 78.105	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
78-34-02-900-801-03		NO. 3 DOOR POSITION (LDVT) TRANSMITTER						Component	ATA:78
PN:133F025-005	MOS/MSC	17-Jan-24	O/C	TSN 3					
SN:A107113	HRS	8143.1		TSN 0					
WC#: 78.105	AFL	4335		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-02-900-801-04		NO. 4 DOOR POSITION (LDVT) TRANSMITTER						Component	ATA:78
PN:133F025-005	MOS/MSC	18-Oct-09	O/C						
SN:A101686	HRS	1344.7		TSN 0					
WC#: 78.105	AFL	741		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-34-03-900-801-01		THRUST REVERSER BOX						Component	ATA:78
PN:GD517-5000-7/01	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:N/A	HRS	0		TSN 0					
WC#: 78.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
78-ZL-00-201 ^S		GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - LH						Service	ATA:78
	MOS	12-Jun-20						MRB	
	HRS	6911.6							
WC#: 78.055	AFL	3586	1800 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78-30-00-210-801PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78-30-00-210-801									
78-ZL-00-202 ^S		GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - RH						Service	ATA:78
	MOS	12-Jun-20						MRB	
	HRS	6911.6							
WC#: 78.055	AFL	3586	1800 (+50/-50)						
PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78-30-00-210-801PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78-30-00-210-801									
783102-701 ^U		LH FIXED STRUCTURE THRUST REVERSER						Component	ATA:78
PN:PN	MOS/MSC	07-Oct-05	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783102-702	RH FIXED STRUCTURE THRUST REVERSER								Component ATA:78
PN:07G0013-023	MOS/MSC	18-Oct-09	O/C						
SN:RH714	HRS	1344.7		TSN 0					
	AFL	741		TSN 0					
783105-702	RH THRUST REVERSER LOWER DOOR								Component ATA:78
PN:04G2039-002	MOS/MSC	18-Oct-09	O/C						
SN:LR1333	HRS	1344.7		TSN 0					
	AFL	741		TSN 0					
ATA 79 - OIL									
79-11-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK								Service ATA:79
	MOS	20-Apr-22						MRB	
	HRS	7430.4	2000 (+50/-50)	Adj 50	(9480.4) 9480.4	9530.4	561.8 (+50)		
WC#: 79.005	ENC	3923							
PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801									
79-11-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK								Service ATA:79
	MOS	20-Apr-22						MRB	
	HRS	7425.2	2000 (+50/-50)	Adj 3.6	(9428.8) 9428.8	9478.8	510.2 (+50)		
WC#: 79.005	ENC	3921							
PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801									
79-11-00-202	NO. 1 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK								Service ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	(11695) 11695	11745	2776.4 (+50)		
WC#: 79.010	ENC	4582							
PROC. REF: AMM 79 11 00 720 801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801PROC. REF: AMM 79 11 00 720 801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
79-11-00-202	NO. 2 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK								Service ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	3000 (+50/-50)	Adj 50	(11695) 11695	11745	2776.4 (+50)		
WC#: 79.010	ENC	4582							
PROC. REF: AMM 79 11 00 720 801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801 PROC. REF: AMM 79 11 00 720 801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801, AMM 79-11-00-720-801									
79-11-00-204	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)								Service ATA:79
	MOS/MSC	21-Sep-10	N/A					MRB	
	HRS	1768.8							
WC#: 79.015	ENC	966							
PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801 PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801									
79-11-00-204	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)								Service ATA:79
	MOS/MSC	21-Sep-10	N/A					MRB	
	HRS	1768.8							
WC#: 79.015	ENC	966							
PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801 PROC. REF: AMM 79 11 00 210 801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801, AMM 79-11-00-210-801									
79-12-01-900-801-01	OIL REPLENISHMENT TANK ASSY								Component ATA:79
PN:GC639-0011-3	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0174	HRS	0		TSN 0					
WC#: 79.005	AFL	0		TSN 0					
PROC. REF: AMM 79-12-01-000-801, AMM 79-12-01-400-801PROC. REF: AMM 79-12-01-000-801, AMM 79-12-01-400-801									
79-12-02-900-801-01	OIL REPLENISHMENT PUMP								Component ATA:79
PN:GC639-0013-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:10AY20	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-12-02-000-801, AMM 79-12-02-400-801PROC. REF: AMM 79-12-02-000-801, AMM 79-12-02-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
79-12-04-900-801-01		SELECTOR VALVE							Component	ATA:79
PN:GC639-0012-1	MOS/MSC	07-Oct-05	O/C	TSN 0						
SN:188	HRS	0		TSN 0						
WC#: 79.010	AFL	0		TSN 0						
PROC. REF: AMM 79-12-04-000-801, AMM 79-12-04-400-801PROC. REF: AMM 79-12-04-000-801, AMM 79-12-04-400-801										
79-21-02-201 ^S		NO. 1 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT							Service	ATA:79
PN:PN-UNKNOWN	MOS	14-Aug-25						MRB		
SN:UNKNOWN	HRS	8645	1000 (+50/-50)							
WC#: 79.020	ENC	4582								
PKG:4										
PROC. REF: AMM 79 21 02 961 801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801PROC. REF: AMM 79 21 02 961 801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801										
79-21-02-201 ^S		NO. 2 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT							Service	ATA:79
PN:PN-UNKNOWN	MOS	14-Aug-25						MRB		
SN:UNKNOWN	HRS	8645	1000 (+50/-50)							
WC#: 79.020	ENC	4582								
PKG:4										
PROC. REF: AMM 79 21 02 961 801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801PROC. REF: AMM 79 21 02 961 801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801, AMM 79-21-02-961-801										
79-21-04-201 ^S		NO. 1 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service	ATA:79
	MOS	14-Aug-25						MRB		
	HRS	8645	1000 (+50/-50)							
WC#: 79.025	ENC	4582								
PKG:4										
PROC. REF: AMM 79 21 04 220 801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801PROC. REF: AMM 79 21 04 220 801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801										
79-21-04-201 ^S		NO. 2 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service	ATA:79
	MOS	14-Aug-25						MRB		
	HRS	8645	1000 (+50/-50)							
WC#: 79.025	ENC	4582								
PKG:4										
PROC. REF: AMM 79 21 04 220 801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801PROC. REF: AMM 79 21 04 220 801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801, AMM 79-21-04-220-801										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
79-21-04-202 ^S		NO. 1 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR						Service	ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 79.030	ENC	4582							
PROC. REF: AMM 79 21 04 220 802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802PROC. REF: AMM 79 21 04 220 802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802									
79-21-04-202 ^S		NO. 2 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR						Service	ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 79.030	ENC	4582							
PROC. REF: AMM 79 21 04 220 802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802PROC. REF: AMM 79 21 04 220 802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802, AMM 79-21-04-220-802									
79-21-04-203 ^S		NO. 1 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR						Service	ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 79.035	ENC	4582							
PROC. REF: AMM 79 21 04 220 803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803PROC. REF: AMM 79 21 04 220 803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803									
79-21-04-203 ^S		NO. 2 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR						Service	ATA:79
	MOS	14-Aug-25						MRB	
	HRS	8645	1000 (+50/-50)						
WC#: 79.035	ENC	4582							
PROC. REF: AMM 79 21 04 220 803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803PROC. REF: AMM 79 21 04 220 803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803, AMM 79-21-04-220-803									
79-31-02-900-801-01		OIL PROBE						Component	ATA:79
PN:GC639-0014-1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0288	HRS	0		TSN 0					
WC#: 79.015	AFL	0		TSN 0					
PROC. REF: AMM 79-31-02-000-801, AMM 79-31-02-400-801PROC. REF: AMM 79-31-02-000-801, AMM 79-31-02-400-801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792101-001	NO. 1 ENGINE - OIL UNIT PUMP								Component ATA:79
PN:LR47000C	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B1524	HRS	0		TSN 0					
WC#: 79.045	ENC	0		TSN 0					
792101-001	NO. 2 ENGINE - OIL UNIT PUMP								Component ATA:79
PN:LR47000C	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:B1534	HRS	0		TSN 0					
WC#: 79.045	ENC	0		TSN 0					
792102-001	NO. 1 ENGINE - PRESSURE FILTER ELEMENT								Component ATA:79
PN:PN-UNKNOWN	MOS/MSC	14-Aug-25	H/T	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
WC#: 79.050	ENC	4582		TSN 0					
792102-001	NO. 2 ENGINE - PRESSURE FILTER ELEMENT								Component ATA:79
PN:PN-UNKNOWN	MOS/MSC	14-Aug-25	H/T	TSN 0					
SN:UNKNOWN	HRS	8645		TSN 0					
WC#: 79.050	ENC	4582		TSN 0					
792201-001	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4274	HRS	0		TSN 0					
WC#: 79.055	ENC	0		TSN 0					
792201-001	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4270	HRS	0		TSN 0					
WC#: 79.055	ENC	0		TSN 0					

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792201-002	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L3589	HRS	0		TSN 0					
WC#: 79.060	ENC	0		TSN 0					
792201-002	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4286	HRS	0		TSN 0					
WC#: 79.060	ENC	0		TSN 0					
792201-003	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L3628	HRS	0		TSN 0					
WC#: 79.065	ENC	0		TSN 0					
792201-003	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4271	HRS	0		TSN 0					
WC#: 79.065	ENC	0		TSN 0					
792201-004	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4272	HRS	0		TSN 0					
WC#: 79.070	ENC	0		TSN 0					
792201-004	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4289	HRS	0		TSN 0					
WC#: 79.070	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792201-005	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4280	HRS	0		TSN 0					
WC#: 79.075	ENC	0		TSN 0					
792201-005	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:L4273	HRS	0		TSN 0					
WC#: 79.075	ENC	0		TSN 0					
792202-001	NO. 1 ENGINE - OIL, FUEL COOLED COOLER								Component ATA:79
PN:55007001-41	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:55007-1034	HRS	0		TSN 0					
WC#: 79.080	ENC	0		TSN 0					
792202-001	NO. 2 ENGINE - OIL, FUEL COOLED COOLER								Component ATA:79
PN:55007001-41	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:55007-1018	HRS	0		TSN 0					
WC#: 79.080	ENC	0		TSN 0					
793301-001	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001 M1	MOS/MSC	18-Apr-19	O/C	TSN 0					
SN:10779585	HRS	6424.3		TSN 0					
WC#: 79.085	ENC	3309		TSN 0					
793301-001	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001 M1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2119642	HRS	0		TSN 0					
WC#: 79.085	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793301-002	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001 M1	MOS/MSC	18-Apr-19	O/C	TSN 0					
SN:2119671	HRS	6424.3		TSN 0					
WC#: 79.090	ENC	3309		TSN 0					
793301-002	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001 M1	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:2119646	HRS	0		TSN 0					
WC#: 79.090	ENC	0		TSN 0					
793401-001	NO. 1 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:79
PN:21SN04-472	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:F014535	HRS	0		TSN 0					
WC#: 79.095	ENC	0		TSN 0					
793401-001	NO. 2 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:79
PN:21SN04-472	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:F014532	HRS	0		TSN 0					
WC#: 79.095	ENC	0		TSN 0					
793402-001	NO. 1 ENGINE - OIL FILTER POP-UP INDICATOR								Component ATA:79
PN:QA07508	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RP4-5549	HRS	0		TSN 0					
WC#: 79.100	ENC	0		TSN 0					
793402-001	NO. 2 ENGINE - OIL FILTER POP-UP INDICATOR								Component ATA:79
PN:QA07508	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:RP4-1836	HRS	0		TSN 0					
WC#: 79.100	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026 25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 80 - STARTING									
80-11-01-203	S	NO. 1 ENGINE - DISCARD THE AIR TURBINE STARTER OIL						Service	ATA:80
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500	(+50/-50)					
	ENC	4570							
PROC. REF: AMM 80 11 01 961 801, EMM 12-14-13, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801 PROC. REF: AMM 80 11 01 961 801, EMM 12-14-13, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801									
80-11-01-203	S	NO. 2 ENGINE - DISCARD THE AIR TURBINE STARTER OIL						Service	ATA:80
	MOS	13-Nov-24						MRB	
	HRS	8623.4	500	(+50/-50)					
	ENC	4570							
PROC. REF: AMM 80 11 01 961 801, EMM 12-14-13, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801 PROC. REF: AMM 80 11 01 961 801, EMM 12-14-13, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801, AMM 80-11-01-961-801									
801101-001	NO. 1 ENGINE - AIR TURBINE STARTER ASSY							Component	ATA:80
PN:3505934-8	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0405-1506	HRS	0		TSN 0					
WC#: 80.015	ENC	0		TSN 0					
801101-001	NO. 2 ENGINE - AIR TURBINE STARTER ASSY							Component	ATA:80
PN:3505934-13	MOS/MSC	14-Jun-23	O/C	TSR 1					
SN:069-415C	HRS	7864.7		TSN 7964, TSR 0					
WC#: 80.015	ENC	4198		TSN 3196, TSR 0					
801102-001	NO. 1 ENGINE - AIR STARTER VALVE							Component	ATA:80
PN:PN	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 80.020	ENC	0		TSN 0					
801102-001	NO. 2 ENGINE - AIR STARTER VALVE							Component	ATA:80
PN:3291182-5	MOS/MSC	07-Oct-05	O/C	TSN 0					
SN:0305-1709	HRS	0		TSN 0					
WC#: 80.020	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: BD-700-1A10 Serial: 9175 RegNo: N117TP HRS: 8918.6 AFL: 4707 As Of: 19-Jun-2026

25-Jun-2026 12:20 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 80 - STARTING									