



Maintenance Due List

N530BD

Make & Model (Serial)
BOMBARDIER CL 604 (5352)

Operator
Jet Linx Aviation

Reported Date
13-Aug-2026

Hours
8695.10

Landings
4002

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	CF34-3B (872215)	8695.10	4003.00
Engine 2	CF34-3B (872216)	8695.10	4003.00
APU 0	GTCP36-100(E) (P-223C)	10315.00	0.00

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 20-00-205 Airframe INSPECTION PKG 24 Month #830	COCKPIT FUNCTIONAL TEST (WEIGHT CHECK) OF THE PORTABLE FIRE - EXTINGUISHER CONTAINER	31-MAY-2025 H: 8649.70 L: 3986	M: 12	M: 1		31-MAY-2026	M: -2 D: -13
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
100 JLA-PF-0020 (- JLCD) Airframe INSPECTION #3325	PERFORM PREFLIGHT INSPECTION	23-JUN-2026 H: 8695.10 L: 4002	D: 10			03-JUL-2026	M: -1 D: -10
Notes (ZONE: --) (AVG MAN HRS: 3) (UPDATE NOTE: COMPLIED WITH PREFLIGHT CHECKLIST)							
100 JLA-AFM0000 (- JLCD) Airframe INSPECTION #1296	VERIFY CURRENT REVISION STATUS OF ONBOARD FLIGHT MANUALS (I.E. AFM, POH, QRH, ETC.) -or- IF MANUALS ARE ELECTRONIC, CONFIRM ONBOARD IPAD IS PRESENT, CHARGED, OPERABLE.	17-JUN-2026 H: 8695.10 L: 4002	D: 30			17-JUL-2026	M: 0 D: -27
Notes (ZONE: --) (AVG MAN HRS: 1) (UPDATE NOTE: UPDATED AFM ON IPAD)							
00 JLA-Monthly0021(- JLCD) Airframe INSPECTION #1768	MONTHLY MAINTENANCE ITEMS CHECK	23-JUN-2026 H: 8695.10 L: 4002	D: 30	D: 7		23-JUL-2026	M: 0 D: -21
Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH MONTHLY CHECKLIST)							
Max Next Due D(+7): 30-JUL-2026							
Max Remaining D(+7): -14							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2026-14-09 AMD 39-23410 Airframe AD - Open FAA #3748	THIS AD WAS PROMPTED BY A DETERMINATION THAT NEW OR MORE RESTRICTIVE AIRWORTHINESS LIMITATIONS ARE NECESSARY. THE FAA IS ISSUING THIS AD TO ADDRESS NEW OR MORE RESTRICTIVE LIMITATIONS. FAILURE TO COMPLY WITH THESE NEW OR MORE RESTRICTIVE LIMITATIONS ... Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE DETERMINE ANY FURTHER APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS.					18-AUG-2026	M: 0 D: 5
10 00-00 Airframe INSPECTION #3736	Airframe Storage Requirements	13-AUG-2026 H: 8695.10 L: 4002	D: 7			20-AUG-2026 Max Next Due	M: 0 D: 7 Max Remaining
25 60-00-007 Airframe INSPECTION #1531	COPILOT CREW LIFE VEST COPILOT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: REMOVED COPILOT LIFE VEST, P/N P01074-101C S/N 20011360020 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110041, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 0 D: 18
25 60-00-007 Airframe INSPECTION #429	JUMPSEAT CREW LIFE VEST JUMPSEAT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: REMOVED JUMP SEAT LIFE VEST, P/N P01074-101C S/N 20011360109 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110058, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 0 D: 18
25 60-00-007 Airframe INSPECTION #441	PILOT CREW LIFE VEST PILOT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: REMOVED PILOT SEAT LIFE VEST, P/N P01074-101C S/N 20011360203 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110042, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 0 D: 18
34 JLA-NDB34-(-JLCD) Airframe INSPECTION #1044	UPDATE NAV DATABASE (J6 AMERICAS) Notes (AVG MAN HRS: 1)	13-AUG-2026 H: 8695.10 L: 4002				02-SEP-2026	M: 0 D: 20



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
00 JLA-Aircraft Records (-JLCD) Airframe INSPECTION #1083	(NON-GROUNDING, LOG ENTRY/MTR NOT REQUIRED TO COMPLETE THIS TASK) COLLECT/FILE RTS DOCUMENTATION FOR ALL MAINTENANCE PERFORMED IN THE LAST 30 DAYS. REVIEW COMPLIANCE HISTORY IN THE MAINTENANCE TRACKING SYSTEM TO CONFIRM ALL MAINTENANCE THAT WAS PERFORMED DURING THAT TIME.	13-AUG-2026 H: 8695.10 L: 4002	D: 30			12-SEP-2026	M: 0 D: 30
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: VERIFIED LOG ENTRIES AGAINST COMPLIANCE HISTORY.)						
49 00-90-011 APU INSPECTION #5	VERIFY APU HOURS & CYCLES (ADD 6739 HOURS TO HOBBS)	13-AUG-2026 H: 10315.00	D: 30			12-SEP-2026	M: 0 D: 30
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: UPDATED APU HOURS IN COMPLIANCE DATA. CURRENT: 10,289 HRS.)						
72 00-00 Engine 1 INSPECTION #952	Engine Run - Prevent Storage Program Requirements (for each engine)	13-AUG-2026 H: 8695.10 C: 4003	D: 30			12-SEP-2026 Max Next Due	M: 0 D: 30 Max Remaining
72 00-00 Engine 2 INSPECTION #955	Engine Run - Prevent Storage Program Requirements (for each engine)	13-AUG-2026 H: 8695.10 C: 4003	D: 30			12-SEP-2026 Max Next Due	M: 0 D: 30 Max Remaining
72 00-CUS-9020 Airframe INSPECTION #2884	PERFORMANCE CHECK ENGINE TREND MONITORING DATA (NON GROUNDING)	13-AUG-2026 H: 8695.10 L: 4002	M: 1			13-SEP-2026	M: 1 D: 0
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH ECTM DATA DOWNLOAD AND SENT TO CAMP FOR TRACKING.)						
26 JLA- FIREEXTMTLY26-(- JLCD) Airframe INSPECTION #241	CABIN & COCKPIT FIRE EXTINGUISHER VISUAL INSPECTION	13-AUG-2026 H: 8695.10 L: 4002	D: 30			30-SEP-2026	M: 1 D: 17
	Notes (ZONE: --) (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH COCKPIT AND CABIN FIRE EXTINGUISHER VISUAL CHECKS.)						



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 9999.1 Airframe INSPECTION #1263	EGPWS DATABASE UPDATE	29-OCT-2025 H: 8656.00 L: 3990	M: 12			31-OCT-2026	M: 2 D: 18
	Notes (ZONE: --) (UPDATE NOTE: WORK ACCOMPLISHED BY DIRECT MX CRS # FMSR378E DATED 10/29/2025 SEE WORK ORDER # CRS250482.)						
05 M006 Airframe INSPECTION #2648	6 MONTH CHECK	26-MAY-2026 H: 8686.90 L: 3999	M: 6	M: 1		26-NOV-2026	M: 3 D: 13
	Notes (AVG MAN HRS: 16) (TOL. ADJUSTMENT: -17D) (UPDATE NOTE: COMPLIED WITH 6 MONTH CHECK TASKS IAW CL604 MPD REV 35 SECTION 2.4)					Max Next Due M(+1): 26-DEC -2026	Max Remaining M(+1): 4
31 2101-001A Airframe INSPECTION #2334	LEFT REPLACE NO. 1 DIGITAL CLOCK BATTERIES (AA)	17-DEC-2025 H: 8670.40 L: 3995	M: 12			17-DEC-2026	M: 4 D: 4
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF NO.1 DAVTRON DIGITAL CLOCK BATTERY IAW CL604 AMM CH 31-21-01. OPS CHECK GOOD.)						
32 JLA-32Brakes (- JLCD) Airframe INSPECTION #3745	REVIEW BRAKE MEASUREMENTS, PROJECT NEXT BRAKE CHANGES OVER THE NEXT 24 MONTHS, INFORM MX PLANNING TO ADD TO MX PROJECTIONS (NON-GROUNDING)	23-JUN-2026 H: 8695.10 L: 4002	M: 6			23-DEC-2026	M: 4 D: 10
						Max Next Due	Max Remaining
76 0130 Airframe INSPECTION #2590	DOWNLOAD ECTM	13-MAR-2025 H: 8631.50 L: 3977	L: 50			L: 4027	L: 25
	Notes (ZONE: --) (UPDATE NOTE: COMPLIED WITH ENGINE TREND MONITOR DOWNLOAD) (NOTE: SEND AN EMAIL WITH THE .ENG FILE TO GEAEREMOTESERVICES@AE.GE.COM WITH THE SUBJECT LINE CLXXXX. (PLEASE REPLACE THE XS WITH THE AIRCRAFT SERIAL NUMBER))						
25 60-00-007 Airframe INSPECTION #209	NO.2 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 5 D: 18
	Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)						



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-007 Airframe INSPECTION #3143	NO.3 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 5 D: 18
25 60-00-007 Airframe INSPECTION #2841	NO.4 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 5 D: 18
25 60-00-007 Airframe INSPECTION #1512	NO.5 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 5 D: 18
25 60-00-007 Airframe INSPECTION #615	NO.6 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: COMPLIED WITH INSPECTION 25-60-00-007, NO.6 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION, BY INSTALLATION OF NEW LIFE VEST. REMOVED NO. 6 LIFE VEST, P/N P01074-101W S/N 17101310046 AND INSTALLED NEW LIFE VEST, P/N P01074-101W S/N 22010750027 IAW GULFSTREAM INSTRUCTIONS FOR CONTINUED AIRWORTHINESS REPORT NO. CBD4468A002 CHAPTER 25-60-00. DOM 26-JAN-2022, NEXT INSPECTION DUE 31-JAN-2027.)	12-JUL-2022 H: 7626.60 L: 3406	M: 60			31-JAN-2027	M: 5 D: 18
25 60-00-007 Airframe INSPECTION #2191	NO.7 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 5 D: 18
26 2303 Airframe INSPECTION #763	COCKPIT WEIGHT CHECK COCKPIT (HALON) FIRE EXTINGUISHER PORTABLE Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 262303 COCKPIT WEIGHT CHECK COCKPIT (HALON) BOTTLE WEIGHT 3.16 OZ 29-JAN-2025.)	01-FEB-2026 H: 8670.40 L: 3995	M: 12			01-FEB-2027	M: 5 D: 19



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 20-00-207 Engine 1 INSPECTION #660	DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR	09-SEP-2024 H: 8541.00 C: 3921	H: 200.00	H: 20.00		H: 8741.00 Max Next Due H(+20.00): 8761.00	H: 45.90 Max Remaining H(+20.00): 65.90
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 72-20-00-207 DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR. IAW CL604 AMM 72-20-00. NO DEFECTS NOTED.)							
72 20-00-207 Engine 2 INSPECTION #218	DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR	09-SEP-2024 H: 8541.00 C: 3921	H: 200.00	H: 20.00		H: 8741.00 Max Next Due H(+20.00): 8761.00	H: 45.90 Max Remaining H(+20.00): 65.90
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 72-20-00-207 DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR. IAW CL604 AMM 72-20-00. NO DEFECTS NOTED.)							
AD 2025-22-04 Airframe AD - Open FAA #2987	FLIGHT CONTROLS - FLAP SYSTEM ON-BOARD RECORDER (FSOBR) EFFECTS ON FLAP CONTROL UNIT - DISCONNECTION AND INSTALLATION PROHIBITION OF THE FSOBR		M: 14 H: 1000.00			23-FEB-2027 H: 9671.70	M: 6 D: 10 H: 976.60
Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, CERTIFICATED IN ANY CATEGORY. COMPLIANCE: FOR AIRPLANES THAT HAVE INCORPORATED BOMBARDIER SERVICE BULLETIN 604-27-035, BOMBARDIER SERVICE BULLETIN 605-27-006, OR BOMBARDIER SERVICE BULLETIN 650-27-001 AS OF THE EFFECTIVE DATE OF THIS AD: WITHIN 1,000 FLIGHT HOURS OR 14 MONTHS, WHICHEVER OCCURS FIRST, AFTER THE EFFECTIVE DATE OF THIS AD, DISCONNECT THE FSOBR IN ACCORDANCE WITH SECTION 2.B OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE BULLETIN LISTED IN TABLE 1 TO PARAGRAPH (G) OF THIS AD.)							
26 2505-701B Airframe INSPECTION #1341	CABIN WEIGHT CHECK FIRE EXTINGUISHER PORTABLE BOTTLE 26-25-00-9002 - FIRE EXT HALON TYPE	01-FEB-2026 H: 8670.40 L: 3995	M: 12			28-FEB-2027	M: 6 D: 15
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH 262505-701B, WEIGHT CHECK OF CABIN FIRE EXTINGUISHER, IAW PLACARDED INSTRUCTIONS. WEIGHT FOUND WITHIN LIMITS. WEIGHT 5 LBS. 5 OZ. REMOVED CABIN FIRE EXTINGUISHER P/N 30H673 S/N F-68184866 AND INSTALLED NEW PORTABLE FIRE EXTINGUISHER P/N 30H673 S/N I-48489258 IAW BOMBARDIER CL 604 AMM 26-26-01. DOM 20/DEC/2024)							
27 42-01-110 Airframe INSPECTION #3353	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA), PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)	23-MAR-2017 H: 5979.10 L: 2576	M: 120			23-MAR-2027	M: 7 D: 10
Notes (AVG MAN HRS: 31) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 00-KCA-9174 Airframe INSPECTION #2810	NO.2 LIFE RAFT - RECERTIFICATION	10-APR-2024 H: 8348.50 L: 3805	M: 36			29-MAR-2027	M: 7 D: 16
Notes (AVG MAN HRS: 3) (UPDATE NOTE: INSTALLED OVERHAULED NO. 2 LIFE RAFT P/N RAF1210-305T1 S/N 1054KO ON AIRCRAFT AFTER OVERHAUL. LIFE RAFT OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2400108 WORK ORDER WSM2400108 RO-6340-N530BD CRS# WV1R599K DATED 29-MAR-2024)							
26 20-00-208 Airframe INSPECTION PKG 96 Month #1946	COCKPIT DETAILED INSPECTION OF THE PORTABLE FIRE-EXTINGUISHER CONTAINER	20-MAR-2024 H: 8325.70 L: 3788	M: 72	M: 1		13-APR-2027	M: 8 D: 0
Notes (AVG MAN HRS: 0.5)							
27 35-04-101 Airframe INSPECTION #1776	FWD - LEFT FUNCTIONAL TEST OF THE ANGLE OF ATTACK (AOA) TRANSDUCER LINEARITY	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
Notes (AVG MAN HRS: 5.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 35-04-101 Airframe INSPECTION #4	FWD - RIGHT FUNCTIONAL TEST OF THE ANGLE OF ATTACK (AOA) TRANSDUCER LINEARITY	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
Notes (AVG MAN HRS: 5.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
AD 2003-22-12 (Left) AMD Par. (h) Airframe AD - Recurring FAA #237	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - MEASUREMENT, REPETITIVE MEASUREMENT AND CORRECTIVE ACTIONS	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (ISSUING AUTHORITY: FAA).PERFORMED FUNCTIONAL TEST							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-22-12 (Right) AMD Par. (h) Airframe AD - Recurring FAA #2421	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - MEASUREMENT, REPETITIVE MEASUREMENT AND CORRECTIVE ACTIONS Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (ISSUING AUTHORITY: FAA).PERFORMED FUNCTIONAL TEST	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
25 9991 Airframe INSPECTION #720	DEFIBRILLATOR SMART PADS REPLACEMENT Notes (UPDATE NOTE: REMOVED OLD DEFIBRILLATOR PADS P/N 989803139261 S/N 230517-0957 AND INSTALLED NEW DEFIBRILLATOR PADS P/N 989803139261 S/N 241022-0952 EXPIRES 22/APR/2027 IAW BOMBARDIER CL 604 AMM 24-32-01.) (NOTE: EXPIRE DATE ON PADS)	19-SEP-2025 H: 8650.80 L: 3987				22-APR-2027	M: 8 D: 9
AD 2025-0088 Airframe AD - Open EASA #1535	NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT Notes (ISSUING AUTHORITY: EASA) (NOTE: APPLICABILITY: ROCKWELL COLLINS GPS-4000S, GLU-2100, GLUS-2100 AND GLUS-2100A RECEIVERS, HAVING A PART NUMBER (P/N) AS LISTED IN APPENDIX 1 OF THIS AD, ALL SERIAL NUMBERS. AFFECTED PART: ANY ROCKWELL COLLINS (COLLINS) SATELLITE BASED AUGMENTATION SYSTEMS (SBAS) RECEIVER GPS-4000S, GLU-2100, GLUS-2100 AND GLUS-2100A, HAVING HARDWARE AND OPERATIONAL PROGRAM SOFTWARE (OPS) P/N AS IDENTIFIED IN APPENDIX 1 OF THIS AD. COMPLIANCE: FOR AFFECTED AEROPLANES HAVING AIRWORTHINESS APPROVAL FOR LPV-200 OPERATIONS: WITHIN 2 YEARS AFTER THE EFFECTIVE DATE OF THIS AD, OR BEFORE NEXT FLIGHT AFTER HAVING OBTAINED THE AIRWORTHINESS APPROVAL FOR LPV-200 OPERATIONS, WHICHEVER OCC		M: 24			30-APR-2027	M: 8 D: 17
25 00-ICA-9001 Airframe INSPECTION #1821	INSPECT RIGHT HAND GALLEY - 12 MONTH PER GULFSTREAM AEROSPACE ICA DOCUMENT CBB2801A002 Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
25 00-ICA-9001A Airframe INSPECTION #2385	RIGHT HAND GALLEY WATER FILTER - 12 MONTH PER GULFSTREAM AEROSPACE ICA DOCUMENT CBB2801A002 Notes (AVG MAN HRS: 1.5) (APX COST: 210.45) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 00-ICA-9003 Airframe INSPECTION #2277	INSPECT (GENERAL VISUAL) CABIN INTERIOR - 12 MONTH/400 HOUR PER GULFSTREAM DOC. NO. CBD4468A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12 H: 400.00	M: 1 H: 30.00		21-MAY-2027 H: 9086.90	M: 9 D: 8 H: 391.80 Max Next Due M(+1): 21-JUN-2027 H(+30.00): 9116.90 Max Remaining M(+1): 10 H(+30.00): 421.80
Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 00-ICA-9008 Airframe INSPECTION #3226	INSPECTION CABIN INTERIOR - 12 MONTH PER GULFSTREAM DOC. NO. CBD4468A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 29-00-601 Airframe INSPECTION #1588	INSPECT INTERIOR DRAWERS, DOORS, AND CABINETS	21-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		21-MAY-2027	M: 9 D: 8 Max Next Due M(+1): 21-JUN-2027 Max Remaining M(+1): 10
Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 30-00-001 Airframe INSPECTION #2259	GALLEY - VISUALLY INSPECT GENERAL CONDITION AND SECURITY.	21-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		21-MAY-2027	M: 9 D: 8 Max Next Due M(+1): 21-JUN-2027 Max Remaining M(+1): 10
Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 60-00-201 Airframe INSPECTION #331	OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-203 Airframe INSPECTION #2920	DETAILED INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 60-00-603 Airframe INSPECTION #262	INSPECT DETAILED OF LIFE RAFTS EXPIRATION DATE	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 62.00.1 Airframe INSPECTION #2093	EMERGENCY LOCATOR TRANSMITTER (ELT) GENERAL VISUAL INSPECTION. REF. BOMBARDIER DOC. NO. BAS63017002-SM-1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 62-00.2 Airframe INSPECTION #415	EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA GENERAL VISUAL INSPECTION. REF. BOMBARDIER DOC. NO. BAS63017002-SM-1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 6201-001C Airframe INSPECTION #2417	ELT INSPECT	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (AVG MAN HRS: 0.5) (APX COST: 987.69) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 9320 Airframe INSPECTION #737	FIRST AID KIT INSPECTION	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 9990 Airframe INSPECTION #2084	DEFIBRILLATOR VISUAL INSPECTION	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (ZONE: --) (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 FAR 91.207 Airframe INSPECTION FAA #1777	EMERGENCY LOCATOR TRANSMITTER (ELT) INSPECTION AND TEST PER FAR 91.207 (D)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)							
31 2101-002A Airframe INSPECTION #1683	RIGHT REPLACE NO. 2 DIGITAL CLOCK BATTERIES (AA)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
34 9000 Airframe INSPECTION #2883	JLAC AVIONICS INSPECTION #1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (ZONE: --) (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 1 Airframe INSPECTION #1738	OXYGEN SYSTEM OPERATIONAL & MASK DROP TEST. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 2 Airframe INSPECTION #84	OXYGEN SYSTEM MASK INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 T.M5352-0256 Oxygen 3 Airframe INSPECTION #2088	OXYGEN SYSTEM LINES, FITTINGS AND HARDWARE INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 4 Airframe INSPECTION #1542	OXYGEN SYSTEM FLEXIBLE LINE INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 6 Airframe INSPECTION #3285	PORTABLE OXYGEN BOTTLE ANNUAL INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 7 Airframe INSPECTION #2424	PORTABLE OXYGEN BOTTLE MASK ANNUAL INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
38 T.M5352-0256 OVBD SVC Airframe INSPECTION #270	INSPECT OVERBOARD SERVICING FOR LEAKAGE, SPILLAGE, CORROSION. DOOR HINGES & LATCHES FOR WEAR AND SECURITY. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 T.M5352-0256 Toilet 1 Airframe INSPECTION #1461	INSPECT TOILET ENCLOSURE AREA FOR SPILLAGE AND CORROSION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 9 D: 8
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
05 PKG 12 Month Airframe INSPECTION #3714	12 MONTHLY TASKS	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 9 D: 13
Notes (AVG MAN HRS: 48) (APX COST: 3,288.94) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: SDL MX CAPABLE)							
33 51-51-711 Airframe INSPECTION #2308	EMERGENCY LIGHTING SYSTEM - OPERATIONAL TEST	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 9 D: 13
Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
05 PKG 24 Month Airframe INSPECTION #2311	24 MONTHLY TASKS	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		29-MAY-2027	M: 9 D: 16
Notes (AVG MAN HRS: 3.5) (TOL. ADJUSTMENT: -1D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
23 71-00-203 Airframe INSPECTION #1261	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING DEVICE (ULD)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
Notes (MANUAL ADJUSTMENT: 0D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)							



Maintenance Due List

13-Aug-2026 14:31 Z

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 23-00-101 Airframe INSPECTION #841	OPERATIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG)	31-MAY-2025 H: 8649.70 L: 3986	M: 24 H: 1600.00			31-MAY-2027 H: 10249.70	M: 9 D: 18 H: 1554.60
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT.						
25 00-ICA-9002 Airframe INSPECTION #1193	INSPECTION RIGHT HAND GALLEY 24 MONTH PER GULFSTREAM DOC. NO. CBB2801A002	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 2		31-MAY-2027 Max Next Due M(+2): 31-JUL- 2027	M: 9 D: 18 Max Remaining M(+2): 11
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 21-00-602 Airframe INSPECTION #1769	DETAILED INSPECTION PASSENGER SEATS RESTRAINTS	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027 Max Next Due M(+1): 30-JUN- 2027	M: 9 D: 18 Max Remaining M(+1): 10
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
31 31-00-202 Airframe INSPECTION #3443	OPERATIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATING DEVICE (ULD)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (MANUAL ADJUSTMENT: 0D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)						
34 13-00-102 Airframe INSPECTION #2142	NO.1 FUNCTIONAL TEST OF THE AIR DATA COMPUTER (ADC), (POST SB 604-34-012, RVSM QUALIFIED A/C)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 13-00-102 Airframe INSPECTION #2873	NO.2 FUNCTIONAL TEST OF THE AIR DATA COMPUTER (ADC), (POST SB 604-34-012, RVSM QUALIFIED A/C)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
34 9001 Airframe INSPECTION #2160	JLAC AVIONICS INSPECTION #2	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (ZONE: --) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
34 9002 Airframe INSPECTION #466	JLAC AVIONICS INSPECTION #3	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (ZONE: --) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
34 FAR 91.411 Airframe INSPECTION FAA #1808	ALTIMETER STANDBY INDICATOR TESTS AND INSPECTIONS PER FAR 91.411	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.411 Airframe INSPECTION FAA #1028	NO.1 AIR DATA COMPUTER TESTS AND INSPECTIONS PER FAR 91.411 APPENDIX E OF PART 43	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.411 Airframe INSPECTION FAA #1220	NO.2 AIR DATA COMPUTER TESTS AND INSPECTIONS PER FAR 91.411 APPENDIX E OF PART 43	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 FAR 91.413 Airframe INSPECTION FAA #510	LEFT ATC TRANSPONDER TEST AND INSPECTIONS PER FAR 91.413 APPENDIX F OF PART 43. Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
34 FAR 91.413 Airframe INSPECTION FAA #2207	RIGHT ATC TRANSPONDER TEST AND INSPECTIONS PER FAR 91.413 APPENDIX F OF PART 43 Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 9 D: 18
56 LAI-ICA-123.2 Airframe INSPECTION #3741	Left Cockpit PMA Windshield DryView Rain Repellant Coating Inspection. Reference Lee Aerospace Document Number LAI-ICA-123 Reference Number LAI-ICA-123	08-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		31-MAY-2027 Max Next Due M(+1): 30-JUN-2027	M: 9 D: 18 Max Remaining M(+1): 10
SB 604-35-007 R1 Part B Airframe SB - Open #930	SPECIAL CHECK/MODIFICATION - PASSENGER OXYGEN SUPPLY SYSTEM - VALIDATION AND MODIFICATION FOR INCORRECT LANYARD LENGTH OF THE PASSENGER OXYGEN MASK - MODIFICATION - REPLACEMENT OF OXYGEN MASK Notes (AVG MAN HRS: 1) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SB RELEASE (BASIC ISSUE))		M: 60			31-MAY-2027	M: 9 D: 18
102 JLA-Programs-REG-NOAA-Life Raft-1 Airframe INSPECTION #999	#1 LIFE RAFT 406 MHZ ELT-NOAA REGISTRATION RENEWAL (25-NOAA) Notes (UPDATE NOTE: ELT HEX ADCC408DE8001BD)	02-JUL-2025	M: 24			02-JUL-2027	M: 10 D: 19
38 T.M5352-0256 Toilet 2 Airframe INSPECTION #1804	INSPECT TOILET FOR SECURITY OF ATTACHMENT TO FLOOR AND FRAME STRUCTURE. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256 Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)	11-JUL-2023 H: 8075.40 L: 3647	M: 48 H: 1600.00			11-JUL-2027 H: 9675.40	M: 10 D: 28 H: 980.30



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
08 0005 Airframe INSPECTION #1663	36 MONTH AIRCRAFT WEIGH	05-JUL-2024 H: 8455.80 L: 3862	M: 36			31-JUL-2027	M: 11 D: 18
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
25 1897-701A Airframe INSPECTION #2468	NO.1 RECERTIFY LIFE RAFT	28-AUG-2024 H: 8524.50 L: 3908	M: 36			31-JUL-2027	M: 11 D: 18
Notes (UPDATE NOTE: INSTALLED OVERHAULED #1 LIFE RAFT P/N: RAF1210-311T1, S/N: 1121062491H, SAFETECH USA INC. TRACKING #WSM2411359, WORK ORDER #WSM241135924294, CRS #WV1R599K, DATED 29-JUL-2024. HYDRO DATE: 07/2024, NEXT HYDRO DUE: 07/2029. ELT S/N: 24321, ELT BEACON ID: 09082. ELT BATTERY EXP: 03/2029. HEX ID: ADCC408DE8001BD. NEXT LIFE RAFT SERVICE DATE 07/2027.)							
25 00-ICA-9005 Airframe INSPECTION #1625	INSPECTION CABIN INTERIOR 400 HOUR - ICA - PER GULFTREAM DOC. NO. CBD4468A002	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8855.80 Max Next Due H(+40.00): 8895.80	H: 160.70 Max Remaining H(+40.00): 200.70
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
25 T.M5352-0256 Vanity 3 Airframe INSPECTION #2342	VANITY TRASH CONTAINER INSPECT FOR ACCESS, & DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING AND LATCHING. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00			H: 8855.80	H: 160.70
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
25 T.M5352-0256 Vanity 4 Airframe INSPECTION #2913	INSPECT VANITY WATER LINES ABOVE THE FLOOR CONDITION	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00			H: 8855.80	H: 160.70
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 PKG 400 Hour Airframe INSPECTION #2044	400 HOURLY TASKS	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40 Max Next Due H(+40.00): 8915.40	H: 180.30 Max Remaining H(+40.00): 220.30
Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
05 PKG 800 Hour Airframe INSPECTION #2990	800 HOURLY TASKS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40 Max Next Due H(+40.00): 8915.40	H: 180.30 Max Remaining H(+40.00): 220.30
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
25 00-ICA-9006 Airframe INSPECTION #997	INSPECTION CABIN INTERIOR 800 HOUR - ICA - PER GULFSTREAM DOC. NO. CBD4468A002	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40 Max Next Due H(+40.00): 8915.40	H: 180.30 Max Remaining H(+40.00): 220.30
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
25 T.M5352-0256 Vanity 2 Airframe INSPECTION #2742	INSPECT VANITY DOORS, DRAWERS & LATCHES FOR WEAR & OPERATION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
27 13-04-101 Airframe INSPECTION #224	OPERATIONAL TEST OF THE ROLL DISCONNECT SYSTEM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE O							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 14-01-101 Airframe INSPECTION #2595	FUNCTIONAL TEST OF THE AILERON POWER CONTROL UNITS (PCUS)	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)							
27 15-07-101 Airframe INSPECTION #1180	LEFT DETAILED INSPECTION OF THE AILERON FLUTTER DAMPER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS D							
27 15-07-101 Airframe INSPECTION #1909	RIGHT DETAILED INSPECTION OF THE AILERON FLUTTER DAMPER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS D							
27 21-00-101 Airframe INSPECTION #2714	FUNCTIONAL TEST OF THE RUDDER BACKLASH	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 32-00-101 Airframe INSPECTION #1344	OPERATIONAL TEST OF THE ELEVATOR DISCONNECT SYSTEM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR							
27 33-01-101 Airframe INSPECTION #871	FUNCTIONAL TEST OF THE ELEVATOR BACKLASH	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)							
27 34-04-102 Airframe INSPECTION #1766	LEFT INBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS							
27 34-04-102 Airframe INSPECTION #3113	LEFT OUTBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS							



Maintenance Due List

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 34-04-102 Airframe INSPECTION #1187	RIGHT INBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS							
27 34-04-102 Airframe INSPECTION #434	RIGHT OUTBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS							
33 ERO-986602 Airframe INSPECTION #1336	DOMe BOARDING LIGHT DEACTIVATION - TEMP REPAIR	H: 8650.80	H: 300.00			H: 8950.80	H: 255.70
Notes (UPDATE NOTE: AT A PERIOD, NOT TO EXCEED 300 FLIGHT HOURS, THE DISCREPANCY MUST BE REPAIRED BY PART REPLACEMENT OF REPAIRED PER OEM OR ENGINEERING PROCEDURES.)							
32 51-10-101 Airframe INSPECTION #2057	FUNCTIONAL TEST OF THE TRANSFER VALVE OF THE STEERING CONTROL MANIFOLD		H: 4000.00			H: 8957.60	H: 262.50
Notes (SOURCE: MPD, TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3600 HOURS OR MORE, AS OF THE DATE OF SEP 30/2024, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS.)							
56 LAI-ICA-123.1 Airframe INSPECTION #3740	Left Cockpit PMA Windshield Visual Inspection. Reference Lee Aerospace Document Number LAI-ICA-123	08-MAY-2026 H: 8686.90 L: 3999	H: 300.00	H: 40.00		H: 8986.90	H: 291.80
Reference Number LAI-ICA-123						Max Next Due H(+40.00): 9026.90	Max Remaining H(+40.00): 331.80