

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

EMAIL: CAMSREPORTS@HOTMAIL.COM

PHONE: (305) 744-3333 FAX: (888) 575-3499

7/03/2026	REGISTERED OWNER	Air Rodriguez LLC	OPERATOR	Air Rodriguez LLC
	ADDRESS	14546 Brook Hollow #336 San Antonio TX 78232	ADDRESS	14546 Brook Hollow #336 San Antonio, TX 78232
	PHONE	210-340-5500	PHONE	210-340-5500
	CONTACT	Carlton Moy	CONTACT	Carlton Moy
	TITLE		TITLE	
	FAX		FAX	

AIRFRAME

AIRCRAFT MAKE	LEARJET
AIRCRAFT MODEL	31A
AIRCRAFT YEAR	2001
SERIAL NUMBER	31232
AIRCRAFT REGISTRATION NO.	N68VP
TOTAL TIME AIRFRAME	5962.1
TOTAL AIRCRAFT LANDINGS	4521
INSPECTION PROGRAM	FAR 91.409(f,3)
AIRCRAFT HOBBS METER	5964.9

LEFTHAND ENGINE

SERIAL NUMBER	P99591
MAKE	GARRETT
MODEL	TFE731-2-3B
TIME SINCE NEW	5815.0
CYCLES SINCE NEW	4329
TIME SINCE CORE	1745.8
CYCLES SINCE CORE	1237
TIME SINCE MAJOR PERIODIC	258
CYCLES SINCE MAJOR PERIODIC	175
CORE INTERVAL	4200

RIGHTHAND ENGINE

SERIAL NUMBER	P99590
MAKE	GARRETT
MODEL	TFE731-2-3B
TIME SINCE NEW	5866.4
CYCLES SINCE NEW	4532
TIME SINCE CORE	1749.3
CYCLES SINCE CORE	1230
TIME SINCE MAJOR PERIODIC	263
CYCLES SINCE MAJOR PERIODIC	175
CORE INTERVAL	4200

All target dates projected in this report have been calculated using your estimated MONTHLY AVERAGE utilization of **30 HOURS AND 30 CYCLES**.

If your utilization is higher than the one's listed above then **BEWARE THE ITEMS WILL COME DUE EARLIER THAN THE PROJECTED TARGET DATES.**

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

TABLE OF CONTENTS

SUBJECT

PAGE

ATA CODES	1
60 DAY SUMMARY PROJECTION	2
ITEM CHANGE	5
ITEM CHANGE REPORT ADS & SBS	8
AIRFRAME HOURS REPORT	9
CALENDAR REPORT	14
AIRCRAFT LANDINGS REPORT	18
AIRCRAFT UTILIZATION REPORT	20
LH ENGINE HOURS REPORT	27
LH ENGINE CYCLES REPORT	29
RH ENGINE HOURS REPORT	30
RH ENGINE CYCLES REPORT	32
MASTER REPORT (A.T.A. CODES)	33
LONG RANGE PROJECTION REPORT	69
COMPONENT INVENTORY REPORT	79
AIRFRAME AIRWORTHINESS DIRECTIVE REPORT	95
LH ENGINE AIRWORTHINESS DIRECTIVE REPORT	102
RH ENGINE AIRWORTHINESS DIRECTIVE REPORT	105
AIRFRAME SERVICE BULLETIN REPORT	102
LH ENGINE SERVICE BULLETIN REPORT	103
RH ENGINE SERVICE BULLETIN REPORT	118

A.T.A. CODES

CODE	SYSTEM	CODE	SYSTEM
05	INSPECTIONS	54	NACELLES/PYLONS
21	AIR CONDITIONING	55	STABILIZERS
22	AUTOPILOT	56	WINDOWS
23	COMMUNICATIONS	57	WINGS
24	ELECTRICAL POWER	60	STANDARD PRACTICES - PROPELLERS/ROTORS
25	EQUIPMENT & FURNISHINGS	61	PROPELLERS
26	FIRE PROTECTION	65	ROTORS
27	FLIGHT CONTROLS	70	STANDARD PRACTICES - ENGINES
28	FUEL	71	POWER PLANT
29	HYDRAULIC POWER	72	ENGINES
30	ICE & RAIN PROTECTION	73	ENGINE FUEL & CONTROL
31	INDICATOR & RECORDING SYSTEMS	75	IGNITION
32	LANDING GEAR	76	ENGINE CONTROLS
33	LIGHTS	77	ENGINE INDICATING
34	NAVIGATION	78	EXHAUST
35	OXYGEN	79	OIL
36	PNEUMATICS	80	STARTING
37	VACUUM	81	TURBINE
38	WATER/WASTE	82	WATER INJECTION
39	ELECTRICAL/ELECTRONIC PANELS & MULTI PURPOSE COMPONENTS	83	ACCESSORY GEARBOX
49	AIRBORNE AUXILIARY POWER	91	CHARTS
51	STRUCTURES	97	ENGINE SERVICE BULLETINS
52	DOORS	98	AIRFRAME SERVICE BULLETINS
53	FUSELAGE	99	AIRWORTHINESS DIRECTIVES

180 DAY SUMMARY REPORT

LEARJET31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	Tolerance	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER						
99		AD 2026-13-02 RADAR ALT INTERFER 5G			DATE 0 day				7/01/2026
21		EVAPORATOR BLOWERS		AFT	A/C HRS	8/29/2001			7/24/2026
KEITH AIR CONDITION		N/A	N/A	OVERHAUL	2000	0.0	21.0		22.0
25	*	ELT BATTERY			DATE	8/01/2021			8/01/2026
5-11-00		452-0133	391140-018	REPLACE	5 yrs	5342.9		End of Month	
53	*	RAISBECK AFT FUSELAGE STOW LOCKER			AF HRS	3/21/2025			8/07/2026
95-120/96L-120		N/A	N/A	INSPECT	200	5797.2	35.1		5997.2
72	*	INSPECTION, ENGINE 300/400 HR		RH	ENG HRS	3/12/2024		100 Hrs Window	8/09/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590		300	5603.4	37.0		5903.4
72	*	INSPECTION, ENGINE 300/400 HR		LH	ENG HRS	2/29/2024		100 Hrs Window	8/14/2026
72-00-00 TABLE 603		TFE731-2-3B	P99591		300	5557.0	42.0		5857.0
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY		LH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		2406005-22	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY		RH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		2406005-52	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN		LH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		AS157G16311180	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN		RH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		AS157G184H180	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE		LH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		2406005-30	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE		RH	DATE	8/18/2021		25 Hrs Window	8/18/2026
5-11-00		2406005-27	N/A	REPLACE	5 yrs	5393.4		14 Day Window	
1223010F	*	BATTERY, EMERGENCY		PRIMARY	DATE	2/24/2026			8/24/2026
5-10-29		PS835	3211	OPS CHK	6 mos	5887.2		14 Day Window	
1223010F	*	BATTERY, EMERGENCY		SECONDARY	DATE	2/24/2026			8/24/2026
5-10-29		PS835	81952	OPS CHK	6 mos	5887.2		14 Day Window	

180 DAY SUMMARY REPORT

LEARJET31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	FILE I N T E R V A L	LAST A C C O M P L I S H	REMAINING H R / C Y C / L D G	Tolerance	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER						
2432010B	*	BATTERY INSTALLATION		#1	DATE	2/24/2026			8/24/2026
5-10-29		N/A	N/A	INSPECT	6 mos	5887.2		14 Day Window	
2432010B	*	BATTERY INSTALLATION		#2	DATE	2/24/2026			8/24/2026
5-10-29		N/A	N/A	INSPECT	6 mos	5887.2		14 Day Window	
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE		LH	DATE	2/24/2026			8/24/2026
5-10-29		N/A	N/A	INSPECT	6 mos	5887.2		14 Day Window	
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE		RH	DATE	2/24/2026			8/24/2026
5-10-29		N/A	N/A	INSPECT	6 mos	5887.2		14 Day Window	
1223015D	*	BATTERY, EMERGENCY		PRIMARY	DATE	8/29/2025			8/29/2026
5-10-29		501-1712-02	3211	DISCHG	12 mos	5848.7		14 Day Window	
1223015D	*	BATTERY, EMERGENCY		SECONDARY	DATE	8/29/2025			8/29/2026
5-10-29		501-1712-02	81952	DISCHG	12 mos	5848.7		14 Day Window	
53	*	RAISBECK AFT FUSELAGE STOW LOCKER			DATE	8/29/2025			8/29/2026
95-120/96L-120		N/A	N/A	INSPECT	12 mos	5848.7			
26	*	SQUIB,ENGINE FIRE EXTINGUISHER		LH #1	DATE	9/01/2016			9/01/2026
CARTRIDGE LIFE		AE30903823	N/A	REPLACE	10 yrs	4669.7		14 Day Window	
26	*	SQUIB,ENGINE FIRE EXTINGUISHER		LH #2	DATE	9/01/2016			9/01/2026
CARTRIDGE LIFE		AE30903823	N/A	REPLACE	10 yrs	4669.7		14 Day Window	
26	*	SQUIB,ENGINE FIRE EXTINGUISHER		RH #1	DATE	9/01/2016			9/01/2026
CARTRIDGE LIFE		AE30903823	N/A	REPLACE	10 yrs	4669.7		14 Day Window	
26	*	SQUIB,ENGINE FIRE EXTINGUISHER		RH #2	DATE	9/01/2016			9/01/2026
CARTRIDGE LIFE		AE30903823	N/A	REPLACE	10 yrs	4669.7		14 Day Window	
72	*	INSPECTION,ENGINE 150/250 HR		RH	ENG HRS	2/17/2026		100 Hrs Window	9/04/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590		150	5779.4	63.0		5929.4
79	*	INSPECTION,ENGINE SOAP		RH	ENG HRS	2/17/2026		100 Hrs Window	9/04/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590		150	5779.4	63.0		5929.4
72	*	INSPECTION,ENGINE 150/250 HR		LH	ENG HRS	2/17/2026		100 Hrs Window	9/09/2026
72-00-00 TABLE 603		TFE731-2-3B	P99591		150	5733.0	68.0		5883.0

180 DAY SUMMARY REPORT

LEARJET31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	T o l e r a n c e	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						
79	*	INSPECTION, ENGINE SOAP		LH	ENG HRS	2/17/2026	68.0	100 Hrs Window	9/09/2026 5883.0
72-00-00 TABLE 603		TFE731-2-3B	P99591		150	5733.0			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		LH	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		N/A	N/A	CHECK	24 mos	5764.8			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		RH	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		N/A	N/A	CHECK	24 mos	5764.8			
34	*	TRANSPONDER		#1	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		011-01997-00	20S011596 ADS OUT	TEST	24 mos	5764.8			
34	*	TRANSPONDER		#2	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		011-01997-00	20S011342 ADS OUT	TEST	24 mos	5764.8			
34	*	COMPUTER, AIR DATA		#1	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		065-0082-14	X11124	CALIBRATE	24 mos	5764.8			
34	*	COMPUTER, AIR DATA		#2	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		065-0082-14	10948	CALIBRATE	24 mos	5764.8			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		STANDBY	DATE	9/24/2024		End of Month	9/24/2026
FAR 91.411, 413		N/A	N/A	CHECK	24 mos	5764.8			
5313002P	*	PITOT STATIC PROBE ZONE SKIN CONTOR			DATE	9/24/2024		End of Month	9/24/2026
5-10-30 P.2		N/A	N/A	CHECK	24 mos	5764.8			
3411055P	*	PITOT STATIC PROBE PITCH/ROLL ALIGN			DATE	9/24/2024		End of Month	9/24/2026
5-10-30 P.2		N/A	N/A	CHECK	24 mos	5764.8			
3411059K	*	RVSM (AIR DATA SYSTEM)			DATE	9/24/2024		14 Day Window	9/24/2026
5-10-30		N/A	N/A	FUNC TEST	24 mos	5764.8			
34	*	RVSM			DATE	9/24/2024		End of Month	9/24/2026
5-10-30, SB		N/A	N/A		24 mos	5764.8			
3500019R	*	BOTTLE, OXYGEN		TAIL	DATE	9/30/2021		14 Day Window	9/30/2026
5-10-29		176700-40	ALT372-8745	HYDRO	5 yrs	5490.1			
78	*	INSPECTION, THRUST REV 150/200 HR		LH	AF HRS	5/12/2026	111.8	50 Hrs Window	10/22/2026 6073.9
TR4000 78-30-00		N/A	N/A		150	5923.9			

180 DAY SUMMARY REPORT

LEARJET31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	Tolerance	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER						
78	*	INSPECTION, THRUST	REV 150/200 HR	RH	AF HRS	5/12/2026	111.8	50 Hrs Window	10/22/2026
TR4000 78-30-00		N/A	N/A		150	5923.9			
21	*	REFRIGERANT HOSES	CHAFING WEAR	INSPECT	AF HRS	6/14/2019	112.1		10/23/2026
KEITH AIR CONDITION		N/A	N/A		1200	4874.2			
78	*	INSPECTION, THRUST	REV 300/400 HR	LH	AF HRS	3/21/2025	135.1	100 Hrs Window	11/15/2026
TR4000 78-30-00		N/A	N/A		300	5797.2			
78	*	INSPECTION, THRUST	REV 300/400 HR	RH	AF HRS	3/21/2025	135.1	100 Hrs Window	11/15/2026
TR4000 78-30-00		N/A	N/A		300	5797.2			
24	*	BATTERY		#1	DATE	6/22/2026		25 Hrs Window	12/22/2026
GILL BATTERIES		GE381E 90%	G03207744	TEST	6 mos	5962.1		14 Day Window	
24	*	BATTERY		#2	DATE	6/22/2026		25 Hrs Window	12/22/2026
GILL BATTERIES		GE381E 90%	G03207742	TEST	6 mos	5962.1		14 Day Window	

ITEM CHANGE REPORT

LEARJET 31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
24	*	BATTERY		#1		DATE	6/22/2026		PART \$ 0.00	12/22/2026
GILL BATTERIES		GE381E 90%	G03207744	TEST		6 mos	5962.1		LBR \$ 0.00 MHR: 0.0	
24	*	BATTERY		#1		AF HRS	6/22/2026		PART \$ 0.00	12/22/2026
GILL BATTERIES		GE381E 90%	G03207744	TEST		400 hrs	5962.1	400.0	LBR \$ 0.00 MHR: 0.0	6362.1
24	*	BATTERY		#2		DATE	6/22/2026		PART \$ 0.00	12/22/2026
GILL BATTERIES		GE381E 90%	G03207742	TEST		6 mos	5962.1		LBR \$ 0.00 MHR: 0.0	
24	*	BATTERY		#2		AF HRS	6/22/2026		PART \$ 0.00	12/22/2026
GILL BATTERIES		GE381E 90%	G03207742	TEST		400 hrs	5962.1	400.0	LBR \$ 0.00 MHR: 0.0	6362.1
2431011H		STARTER GENERATOR		LH		AF HRS	5/12/2026		PART \$ 0.00	02/18/2029
5-10-29		23080-023A	Y10807	OVERHAUL		1000 hrs	5923.9	961.8	LBR \$ 0.00 MHR: 0.0	6923.9
2431011H		STARTER GENERATOR		RH		AF HRS	5/12/2026		PART \$ 0.00	02/18/2029
5-10-29		23080-023A	Y10294	OVERHAUL		1000 hrs	5923.9	961.8	LBR \$ 0.00 MHR: 0.0	6923.9
2431059U	*	BRUSH, STARTER GENERATOR		LH		AF HRS	5/12/2026		PART \$ 0.00	01/15/2028
5-10-29		23080-023A	Y10807	INSPECT		600 hrs	5923.9	561.8	LBR \$ 0.00 MHR: 0.0	6523.9
2431059U	*	BRUSH, STARTER GENERATOR		RH		AF HRS	5/12/2026		PART \$ 0.00	01/15/2028
5-10-29		23080-023A	Y10294	INSPECT		600 hrs	5923.9	561.8	LBR \$ 0.00 MHR: 0.0	6523.9
2431064U		BEARINGS, STARTER/GENERATOR		LH		AF HRS	5/12/2026		PART \$ 0.00	01/15/2028
5-11-00		23080-023A	Y10807	REPLACE		600 hrs	5923.9	561.8	LBR \$ 0.00 MHR: 0.0	6523.9
2431064U		BEARINGS, STARTER/GENERATOR		RH		AF HRS	5/12/2026		PART \$ 0.00	01/15/2028
5-11-00		23080-023A	Y10294	REPLACE		600 hrs	5923.9	561.8	LBR \$ 0.00 MHR: 0.0	6523.9
24		DISPLAY, ELECTRIC		#1		AF HRS	3/27/2026		PART \$ 0.00	
		066-03137-3300	2980 SVCBLE				4483		LBR \$ 0.00 MHR: 0.0	
24		DISPLAY, ELECTRIC		#1		AF HRS	3/27/2026		PART \$ 0.00	
		066-03137-3300	2980 SVCBLE				5909.1		LBR \$ 0.00 MHR: 0.0	
25	*	LIFE VEST				DATE	6/22/2026		PART \$ 0.00	06/22/2027
		N/A	N/A	VISUAL		12 mos	5962.1		LBR \$ 0.00 MHR: 0.0	
25		RECORDER, COCKPIT VOICE				DATE	6/22/2026		PART \$ 0.00	06/22/2027
		N/A	N/A	FUNC TEST		12 mos	5962.1		LBR \$ 0.00 MHR: 0.0	

ITEM CHANGE REPORT

LEARJET 31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
2565000F	*	BATTERY, UNDERWATER LOCATOR BEACON		CVR		DATE	3/18/2026		PART \$ 0.00	03/18/2028
5-10-29		DK120	NT62067	INSPECT		2 yrs	5898.7		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		COPILOT		DATE	3/27/2026		PART \$ 0.00	03/27/2028
		N/A	N/A	REPLACE		2 yrs	5909.1		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		PILOT		DATE	3/27/2026		PART \$ 0.00	03/27/2028
		N/A	N/A	REPLACE		2 yrs	5909.1		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		COPILOT		DATE	3/27/2026		PART \$ 0.00	
		N/A	N/A	REPLACE			4483		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		COPILOT		DATE	3/27/2026		PART \$ 0.00	
		N/A	N/A	REPLACE			5909.1		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		PILOT		DATE	3/27/2026		PART \$ 0.00	
		N/A	N/A	REPLACE			4483		LBR \$ 0.00 MHR: 0.0	
31		BATTERY, DAVTRON CLOCK		PILOT		DATE	3/27/2026		PART \$ 0.00	
		N/A	N/A	REPLACE			5909.1		LBR \$ 0.00 MHR: 0.0	
32		TIRE		NOSE		DATE	6/22/2026		PART \$ 0.00	
		184F10-2	42200727				4521		LBR \$ 0.00 MHR: 0.0	
32		TIRE		NOSE		DATE	6/22/2026		PART \$ 0.00	
		184F10-2	42200727				5962.1		LBR \$ 0.00 MHR: 0.0	
33	*	LOPRESTI BOOM BEAM		INSPECT		DATE	6/22/2026		PART \$ 0.00	06/22/2027
		STC SA02279AT	600 HRS/1 YR			1 yrs	5962.1		LBR \$ 0.00 MHR: 0.0	
33	*	LOPRESTI BOOM BEAM		INSPECT		AF HRS	6/22/2026		PART \$ 0.00	06/22/2027
		STC SA02279AT	600 HRS/1 YR			600 hrs	5962.1	600.0	LBR \$ 0.00 MHR: 0.0	
34		EGPWS		SELF TEST		DATE	6/22/2026		PART \$ 0.00	06/22/2027
		N/A	N/A			12 mos	5962.1		LBR \$ 0.00 MHR: 0.0	
3411063N	*	RVSM PITOT STATIC PROBES VISUAL		INSPECT		DATE	6/22/2026		PART \$ 0.00	06/22/2028
5-10-30		N/A	N/A			24 mos	5962.1		LBR \$ 0.00 MHR: 0.0	
34		SENSOR, RADAR				DATE	5/12/2026		PART \$ 0.00	
		071-01519-0101	6926				5923.9		LBR \$ 0.00 MHR: 0.0	

ITEM CHANGE REPORT

LEARJET 31232

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
78	*	INSPECTION, THRUST REV 150/200 HR		LH		AF HRS	5/12/2026	111.8	PART \$ 0.00	10/22/2026
TR4000 78-30-00		N/A	N/A			150 hrs	5923.9		LBR \$ 0.00 MHR: 0.0	
78	*	INSPECTION, THRUST REV 150/200 HR		RH		AF HRS	5/12/2026	111.8	PART \$ 0.00	10/22/2026
TR4000 78-30-00		N/A	N/A			150 hrs	5923.9		LBR \$ 0.00 MHR: 0.0	
99		AD 2026-13-02 RADAR ALT INTERFER 5G				DATE			PART \$ 0.00	07/01/2026
						0 day			LBR \$ 0.00 MHR: 0.0	
99	*	AD 74-08-09 LAV FIRE PROTECTION				AF HRS	6/22/2026	1000.0	PART \$ 0.00	03/29/2029
SEE AD						1000 hrs	5962.1		LBR \$ 0.00 MHR: 0.0	

AD & SB ITEM CHANGE REPORT

LEARJET 31232

7/03/2026
N68VP

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	COMPLIANCE	NEXT DUE
AD 2026-03-09		REPLACEMENT OF PBE PORTABLE BREATHING EQUIPMENT P/N 15-40F-11 & 15-40D-80	SAFRAN AEROSYS	DATE:	DATE:
3/12/2026			N/A EQUIPMENT NOT INSTALLED	TIME:	TIME:
				LD/CY:	LD/CY:
AD 2026-13-02		REPLACE OR MODIFY RADAR ALTIMETER TO PREVENT 5G INTERFERENCE	T CAT AIRCRAFT	DATE:	DATE: 7/01/2026
7/01/2026				TIME:	TIME:
				LD/CY:	LD/CY:
AD 74-08-09	R3	INSPECT LAVATORY WASTE RECEPTACLE: TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS DROPPED IN RECEPT	T-CATEGORY	DATE: 6/22/2026	DATE:
3/28/2012			INSPECTED LAV RECEPTICLE & PLACARD	TIME: 5962.1	TIME: 6962.1
				LD/CY: 4521	LD/CY:

AIRFRAME HOURS REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	3/21/2025	5797.2	200 hrs	5997.2	164.9	35.1	08/07/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY	LH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY	RH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN	LH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN	RH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE	LH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE	RH	REPLACE	8/18/2021	5393.4	2400 hrs	7793.4	568.7	1831.3	08/18/2026
78	*	INSPECTION, THRUST REV 150/200 HR	LH		5/12/2026	5923.9	150 hrs	6073.9	38.2	111.8	10/22/2026
78	*	INSPECTION, THRUST REV 150/200 HR	RH		5/12/2026	5923.9	150 hrs	6073.9	38.2	111.8	10/22/2026
21	*	REFRIGERANT HOSES CHAFING WEAR		INSPECT	6/14/2019	4874.2	1200 hrs	6074.2	1087.9	112.1	10/23/2026
78	*	INSPECTION, THRUST REV 300/400 HR	LH		3/21/2025	5797.2	300 hrs	6097.2	164.9	135.1	11/15/2026
78	*	INSPECTION, THRUST REV 300/400 HR	RH		3/21/2025	5797.2	300 hrs	6097.2	164.9	135.1	11/15/2026
24	*	BATTERY	#2	TEST	6/22/2026	5962.1	400 hrs	6362.1	0.0	400.0	12/22/2026
24	*	BATTERY	#1	TEST	6/22/2026	5962.1	400 hrs	6362.1	0.0	400.0	12/22/2026
05	*	INSPECTION, AIRFRAME, PHASE A1 - A6			12/31/2025	5853.4	300 hrs	6153.4	108.7	191.3	12/31/2026
2431017H	*	BATTERY CABLES & RECEPTACLES	#1	INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
2431017H	*	BATTERY CABLES & RECEPTACLES	#2	INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
53		ZR LITE INSPECTION			2/04/2026	5878.4	300 hrs	6178.4	83.7	216.3	02/04/2027
2130007U	*	CABIN PRESSURIZATION LEAK RATE CHK			11/01/2019	4980.4	1200 hrs	6180.4	981.7	218.3	02/06/2027
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	1/10/2023	5610.0	600 hrs	6210.0	352.1	247.9	03/07/2027
33	*	LOPRESTI BOOM BEAM		INSPECT	6/22/2026	5962.1	600 hrs	6562.1	0.0	600.0	06/22/2027
78	*	INSPECTION, THRUST REV 600/800 HR	LH		3/21/2025	5797.2	600 hrs	6397.2	164.9	435.1	09/11/2027
78	*	INSPECTION, THRUST REV 600/800 HR	RH		3/21/2025	5797.2	600 hrs	6397.2	164.9	435.1	09/11/2027
21	*	COMPRESSOR BELT TENSION WEAR		INSPECT	6/13/2025	5818.7	600 hrs	6418.7	143.4	456.6	10/02/2027
21	*	EVAPORATOR & CONDENSER COILS		INSPECT	6/13/2025	5818.7	600 hrs	6418.7	143.4	456.6	10/02/2027
21	*	AIR CONDITIONING SYSTEM COMPONENTS		INSPECT	8/15/2025	5843.8	600 hrs	6443.8	118.3	481.7	10/27/2027
05	*	INSPECTION, AIRFRAME, PHASE B1 - B6			12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
5610023G	*	WINDSHIELD LARASCOPE	RH		12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
2740021Q	*	ACTUATOR, HORIZONTAL STABILIZER		OVERHAUL	12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
2431059U	*	BRUSH, STARTER GENERATOR	LH	INSPECT	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431059U	*	BRUSH, STARTER GENERATOR	RH	INSPECT	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431064U		BEARINGS, STARTER/GENERATOR	LH	REPLACE	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431064U		BEARINGS, STARTER/GENERATOR	RH	REPLACE	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2750002E		BUSHING, FLAP NOSE ROLLER	RH INBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	RH OTBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
5750046H	*	FITTINGS, FLAP TRACK SUPPORT	RH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750044H	*	BEARINGS, FLAP CAM FOLLOWER	LH/RH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
5750046H	*	FITTINGS, FLAP TRACK SUPPORT	LH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	LH INBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	LH OTBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2431011H		STARTER GENERATOR	LH	OVERHAUL	5/12/2026	5923.9	1000 hrs	6923.9	38.2	961.8	02/18/2029
2431011H		STARTER GENERATOR	RH	OVERHAUL	5/12/2026	5923.9	1000 hrs	6923.9	38.2	961.8	02/18/2029
99	*	AD 74-08-09 LAV FIRE PROTECTION			6/22/2026	5962.1	1000 hrs	6962.1	0.0	1000.0	03/29/2029

AIRFRAME HOURS REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
78	*	INSPECTION, THRUST REV 1200/1400 HR	LH		3/21/2025	5797.2	1200 hrs	6997.2	164.9	1035.1	05/03/2029
78	*	INSPECTION, THRUST REV 1200/1400 HR	RH		3/21/2025	5797.2	1200 hrs	6997.2	164.9	1035.1	05/03/2029
05	*	INSPECTION, AIRFRAME, PHASE C1 - C6			12/31/2025	5853.4	1200 hrs	7053.4	108.7	1091.3	06/28/2029
2730036A	*	ELEVATOR BELLCRANKS		EDDY	7/02/2021	5335.9	2400 hrs	7735.9	626.2	1773.8	07/02/2029
2710036F	*	CABLE ASSY, AILERON CONTROL COLUMN	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON CONTROL COLUMN	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
78	*	INSPECTION, THRUST REV 2400 HR	LH		5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON FORWARD	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
78	*	INSPECTION, THRUST REV 2400 HR	RH		5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON FORWARD	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON SECTOR AFT		REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	LH INBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	LH OTBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	RH INBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	RH OTBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	LH AFT	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	LH FWD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	RH AFT	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	RH FWD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2720013F		CABLE ASSY, RUDDER	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2720013F		CABLE ASSY, RUDDER	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
7120067T	*	BOLT, AFT ENGINE ATTACH	RH	FLOUR PEN	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120067T	*	BOLT, AFT ENGINE ATTACH	LH	FLOUR PEN	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3020001U	*	BULKHEAD, ENGINE NACELLE INLET	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3020001U	*	BULKHEAD, ENGINE NACELLE INLET	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120024E	*	CASTING, ENGINE MOUNT	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120024E	*	CASTING, ENGINE MOUNT	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120063Q	*	MOUNT ISOLATOR, ENGINE (FWD/AFT)	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120063Q	*	MOUNT ISOLATOR, ENGINE (FWD/AFT)	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7810005U	*	NOZZLES, ENGINE EXHAUST	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7810005U	*	NOZZLES, ENGINE EXHAUST	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450043J	*	PYLON/ENGINE BEAM STRUCTURE	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450043J	*	PYLON/ENGINE BEAM STRUCTURE	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2710014E	*	BOLT, AILERON CENTER HINGE	LH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710014E	*	BOLT, AILERON CENTER HINGE	RH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710010E	*	BOLT, AILERON DRIVE YOKE	LH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710010E	*	BOLT, AILERON DRIVE YOKE	RH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030

AIRFRAME HOURS REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRACT	LH	REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRACT	RH	REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY, HYD NOSE GEAR RETRACT		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
7110021G		HOSE ASSY, FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
7110021G		HOSE ASSY, FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
7110021G		HOSE ASSY, FUEL SUPPLY	LH	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
7110021G		HOSE ASSY, FUEL SUPPLY	RH	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER	LH OTBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER	LH INBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER	LH INBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER	LH OUTBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER	RH OTBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER	RH INBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER	RH INBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER	RH OUTBD	REPLACE	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	12/31/2030
05	*	INSPECTION, AIRFRAME, PHASE D1 - D6			12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	10/10/2032
2730033A	*	CONTROL COLUMN FLUORESCENT PEN		INSPECT	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	10/10/2032
7120037L		BOND JOINT ISO ASSY, ENG AFT CENTER	LH AFT	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		BOND JOINT ISO ASSY, ENG AFT CENTER	RH AFT	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		ENG AFT ISOLATOR ASSY, HOUSING	LH	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		ENG AFT ISOLATOR ASSY, HOUSING	RH	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT, HOUSING	LH LWR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT, HOUSING	LH UPR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT, HOUSING	RH LWR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT, HOUSING	RH UPR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY	LH LOWER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY	LH UPPER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY	RH LOWER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY	RH UPPER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120064K		ENG FWD SHOCK MOUNT, BOLTS	LH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT, BOLTS	LH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT, BOLTS	RH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT, BOLTS	RH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT, COVER	LH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT, COVER	LH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT, COVER	RH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT, COVER	RH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
05	*	INSPECTION, AIRFRAME, 12000 HOUR			8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	LH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	LT OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	RH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	RH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750010E	*	TRACK, FLAP NOSE ROLLER	LH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043

AIRFRAME HOURS REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
2750011E	*	TRACK, FLAP NOSE ROLLER	LH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750010E	*	TRACK, FLAP NOSE ROLLER	RH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750011E	*	TRACK, FLAP NOSE ROLLER	RH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
3411056J	*	PROBE, PRIMARY PITOT STATIC	LH	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
3411057J	*	PROBE, PRIMARY PITOT STATIC	RH	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750013E	*	HINGE FITTING, FLAP TRACK	LH INBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750014E	*	HINGE FITTING, FLAP TRACK	LH OUTBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750013E	*	HINGE FITTING, FLAP TRACK	RH INBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750014E	*	HINGE FITTING, FLAP TRACK	RH OUTBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2710026E	*	YOKE ASSEMBLY, AILERON ACTUATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120041E	*	BOLT, ENGINE AFT SHOCK MOUNT ATTACH	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120041E	*	BOLT, ENGINE AFT SHOCK MOUNT ATTACH	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT, ENGINE FWD MOUNT ATTACH	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT, ENGINE FWD MOUNT ATTACH	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT, ENGINE FWD MOUNT ATTACH	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT, ENGINE FWD MOUNT ATTACH	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710016G		AILERON ASSEMBLY	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710016G		AILERON ASSEMBLY	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720023E	*	BEARING BLOCK ASSY, RUDDER LOWER		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710028E	*	BEARING SUPPORT ASSEMBLY, AILERON	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710028E	*	BEARING SUPPORT ASSEMBLY, AILERON	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730021E	*	BELLCRANK ASSEMBLY, ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730021E	*	BELLCRANK ASSEMBLY, ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710020E	*	BOLT, AILERON CLEVIS	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710020E	*	BOLT, AILERON CLEVIS	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT, ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT, RUDDER HINGE	CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT, RUDDER HINGE	LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT, RUDDER HINGE	UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS, AILERON HINGE	LH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS, AILERON HINGE	LH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064

AIRFRAME HOURS REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
2710021M	*	BOLTS,AILERON HINGE	RH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS,AILERON HINGE	RH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710024E	*	CLEVIS,AILERON DRIVE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710024E	*	CLEVIS,AILERON DRIVE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730016E	*	ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730016E	*	ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710031E	*	HINGE BRACKET ON WING,AILERON	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710031E	*	HINGE BRACKET ON WING,AILERON	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720025E	*	HINGE INSTALLATION,RUDDER	CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720024E	*	HINGE INSTALLATION,RUDDER	UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2740010E	*	HINGE PIN,HORIZONTAL STABILIZER		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730023E	*	PUSH PULL TUBE ASSEMBLY,ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730023E	*	PUSH PULL TUBE ASSEMBLY,ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720018E	*	RUDDER ASSEMBLY		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710026E	*	YOKE ASSEMBLY,AILERON ACTUATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	LH	REPLACE	8/27/2013	3790.0	20000 hrs	23790.0	2172.1	17827.9	04/24/2075
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	RH	REPLACE	8/27/2013	3790.0	20000 hrs	23790.0	2172.1	17827.9	04/24/2075
25		RECORDER, COCKPIT VOICE		MTBF	8/29/2001	0.0	30000 hrs	30000.0	5962.1	24037.9	04/24/2092

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

CALENDAR REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
99		AD 2026-13-02 RADAR ALT INTERFER 5G				0 day	07/01/2026
25	*	ELT BATTERY		REPLACE	8/01/2021	5 yrs	08/01/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY	LH	REPLACE	8/18/2021	5 yrs	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP SUPPLY	RH	REPLACE	8/18/2021	5 yrs	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN	LH	REPLACE	8/18/2021	5 yrs	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP RETURN	RH	REPLACE	8/18/2021	5 yrs	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE	LH	REPLACE	8/18/2021	5 yrs	08/18/2026
7110022G		HOSE ASSY, HYD ENGINE PUMP PRESSURE	RH	REPLACE	8/18/2021	5 yrs	08/18/2026
1223010F	*	BATTERY, EMERGENCY	PRIMARY	OPS CHK	2/24/2026	6 mos	08/24/2026
1223010F	*	BATTERY, EMERGENCY	SECONDARY	OPS CHK	2/24/2026	6 mos	08/24/2026
2432010B	*	BATTERY INSTALLATION	#1	INSPECT	2/24/2026	6 mos	08/24/2026
2432010B	*	BATTERY INSTALLATION	#2	INSPECT	2/24/2026	6 mos	08/24/2026
2620042P	*	BOTTLE, ENGINE FIRE EXTIN PRESS GAGE	LH	INSPECT	2/24/2026	6 mos	08/24/2026
2620042P	*	BOTTLE, ENGINE FIRE EXTIN PRESS GAGE	RH	INSPECT	2/24/2026	6 mos	08/24/2026
1223015D	*	BATTERY, EMERGENCY	PRIMARY	DISCHG	8/29/2025	12 mos	08/29/2026
1223015D	*	BATTERY, EMERGENCY	SECONDARY	DISCHG	8/29/2025	12 mos	08/29/2026
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	8/29/2025	12 mos	08/29/2026
26	*	SQUIB, ENGINE FIRE EXTINGUISHER	LH #1	REPLACE	9/01/2016	10 yrs	09/01/2026
26	*	SQUIB, ENGINE FIRE EXTINGUISHER	LH #2	REPLACE	9/01/2016	10 yrs	09/01/2026
26	*	SQUIB, ENGINE FIRE EXTINGUISHER	RH #1	REPLACE	9/01/2016	10 yrs	09/01/2026
26	*	SQUIB, ENGINE FIRE EXTINGUISHER	RH #2	REPLACE	9/01/2016	10 yrs	09/01/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	LH	CHECK	9/24/2024	24 mos	09/24/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	RH	CHECK	9/24/2024	24 mos	09/24/2026
34	*	TRANSPONDER	#1	TEST	9/24/2024	24 mos	09/24/2026
34	*	TRANSPONDER	#2	TEST	9/24/2024	24 mos	09/24/2026
34	*	COMPUTER, AIR DATA	#1	CALIBRATE	9/24/2024	24 mos	09/24/2026
34	*	COMPUTER, AIR DATA	#2	CALIBRATE	9/24/2024	24 mos	09/24/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	STANDBY	CHECK	9/24/2024	24 mos	09/24/2026
5313002P	*	PITOT STATIC PROBE ZONE SKIN CONTOR		CHECK	9/24/2024	24 mos	09/24/2026
3411055P	*	PITOT STATIC PROBE PITCH/ROLL ALIGN		CHECK	9/24/2024	24 mos	09/24/2026
3411059K	*	RVSM (AIR DATA SYSTEM)		FUNC TEST	9/24/2024	24 mos	09/24/2026
34	*	RVSM			9/24/2024	24 mos	09/24/2026
3500019R	*	BOTTLE, OXYGEN	TAIL	HYDRO	9/30/2021	5 yrs	09/30/2026
24	*	BATTERY	#1	TEST	6/22/2026	6 mos	12/22/2026
24	*	BATTERY	#2	TEST	6/22/2026	6 mos	12/22/2026
3510021P		MASK, OXYGEN	PILOT	OVERHAUL	12/30/2020	6 yrs	12/30/2026
05	*	INSPECTION, AIRFRAME, PHASE A1 - A6			12/31/2025	12 mos	12/31/2026
2563001J	*	ELT TEST (91.207 D)		INSPECT	12/31/2025	12 mos	12/31/2026
5210025L	*	CABIN DOOR STRUCTURE & HINGE AREA	EXT LWR	INSPECT	4/24/2025	24 mos	04/24/2027
2812020L	*	VALVE, WING FLAPPER	LH INBD	INSPECT	4/24/2025	24 mos	04/24/2027
2812020L	*	VALVE, WING FLAPPER	RH INBD	INSPECT	4/24/2025	24 mos	04/24/2027
5710145P	*	INBD DRY BAY ADJ FUSE/FWD SPAR 2		INSPECT	4/24/2025	24 mos	04/24/2027
2812002L	*	INNER WING STRUCTURE OTBD WS213.602		INSPECT	4/24/2025	24 mos	04/24/2027
2812010L	*	3 ACCESS COVERS BTWN WS53, 92.0 RIB		INSPECT	4/24/2025	24 mos	04/24/2027

CALENDAR REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
341400K	*	ANTENNA,RADIO ALTIMETER		BOND CK	4/24/2025	24 mos	04/24/2027
25	*	ELT RE-REGISTRATION			6/13/2025	2 yrs	06/13/2027
33	*	LOPRESTI BOOM BEAM		INSPECT	6/22/2026	1 yrs	06/22/2027
25	*	LIFE VEST		VISUAL	6/22/2026	12 mos	06/22/2027
25		RECORDER,COCKPIT VOICE		FUNC TEST	6/22/2026	12 mos	06/22/2027
34		EGPWS		SELF TEST	6/22/2026	12 mos	06/22/2027
05	*	INSPECTION,AIRFRAME,PHASE B1 - B6			12/31/2025	24 mos	12/31/2027
05		AIRCRAFT REGISTRATION			1/30/2021	7 yrs	01/30/2028
2565000F	*	BATTERY,UNDERWATER LOCATOR BEACON	CVR	INSPECT	3/18/2026	2 yrs	03/18/2028
31		BATTERY,DAVTRON CLOCK	PILOT	REPLACE	3/27/2026	2 yrs	03/27/2028
31		BATTERY,DAVTRON CLOCK	COPILOT	REPLACE	3/27/2026	2 yrs	03/27/2028
3411063N	*	RVSM PITOT STATIC PROBES VISUAL		INSPECT	6/22/2026	24 mos	06/22/2028
26	*	BOTTLE,PORTABLE FIRE EXT INTERNAL	CABIN	CHECK	1/06/2023	6 yrs	01/06/2029
26	*	BOTTLE,PORTABLE FIRE EXT INTERNAL	COCKPIT	CHECK	1/06/2023	6 yrs	01/06/2029
2620025Q	*	BOTTLE,ENGINE FIRE EXTING (HYDRO)	LH	HYDRO	2/28/2024	5 yrs	02/28/2029
2561005p	*	LIFE VEST	PILOT	RECERTIFY	4/30/2019	10 yrs	04/30/2029
2561005p	*	LIFE VEST	COPILOT	RECERTIFY	4/30/2019	10 yrs	04/30/2029
2730036A	*	ELEVATOR BELLCRANKS		EDDY	7/02/2021	96 mos	07/02/2029
2566000F		BATTERY,UNDERWATER LOCATOR BEACON	CVR	REPLACE	10/30/2023	6 yrs	10/30/2029
3610006R	*	BOTTLE,EMERGENCY AIR		HYDRO/VIS	11/03/2023	6 yrs	11/03/2029
05	*	INSPECTION,AIRFRAME,PHASE C1 - C6			12/31/2025	48 mos	12/31/2029
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	REPLACE	3/23/2024	6 yrs	03/23/2030
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	LH	REPLACE	5/05/2025	5 yrs	05/05/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5 yrs	05/05/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5 yrs	05/05/2030
3210003G		HOSE ASSY,HYD NOSE GEAR RETRACT		REPLACE	5/05/2025	5 yrs	05/05/2030
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	RH	REPLACE	5/05/2025	5 yrs	05/05/2030
2620025Q	*	BOTTLE,ENGINE FIRE EXTING (HYDRO)	RH	HYDRO	9/30/2025	5 yrs	09/30/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH OUTBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH INBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH OTBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH INBD	REPLACE	12/31/2025	5 yrs	12/31/2030
7110021G		HOSE ASSY,FUEL MOTIVE FLOW	LH NACELLE	REPLACE	12/31/2025	5 yrs	12/31/2030
7110021G		HOSE ASSY,FUEL MOTIVE FLOW	RH NACELLE	REPLACE	12/31/2025	5 yrs	12/31/2030
7110021G		HOSE ASSY,FUEL SUPPLY	LH NACELLE	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH OUTBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH INBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH OTBD	REPLACE	12/31/2025	5 yrs	12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH INBD	REPLACE	12/31/2025	5 yrs	12/31/2030
7110021G		HOSE ASSY,FUEL SUPPLY	RH NACELLE	REPLACE	12/31/2025	5 yrs	12/31/2030
3510021P		MASK,OXYGEN	COPILOT	OVERHAUL	10/16/2025	6 yrs	10/16/2031
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER(MFG)	LH #1	REPLACE	9/30/2023	9 yrs	09/30/2032
05	*	INSPECTION,AIRFRAME,PHASE D1 - D6			12/31/2025	96 mos	12/31/2033
3610056R	*	BOTTLE,EMERGENCY AIR		SCRAP	1/01/1994	40 yrs	01/01/2034

7/03/2026

LEARJET 31232

N68VP

ATA CODE	F A A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
2561005p	*	LIFE VEST	#7	RECERTIFY	2/28/2024	10 yrs	02/28/2034
2561005p	*	LIFE VEST	#2	RECERTIFY	2/28/2024	10 yrs	02/28/2034
2561005p	*	LIFE VEST	#5	RECERTIFY	2/28/2024	10 yrs	02/28/2034
2561005p	*	LIFE VEST	#6	RECERTIFY	2/28/2024	10 yrs	02/28/2034
2561005p	*	LIFE VEST	#1	RECERTIFY	5/31/2024	10 yrs	05/31/2034
2561005p	*	LIFE VEST	#3	RECERTIFY	5/31/2024	10 yrs	05/31/2034
2561005p	*	LIFE VEST	#4	RECERTIFY	5/31/2024	10 yrs	05/31/2034
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER	CABIN	HYDRO	1/06/2023	12 yrs	01/06/2035
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER	COCKPIT	HYDRO	1/06/2023	12 yrs	01/06/2035
3500051R	*	BOTTLE,OXYGEN	TAIL	REPLACE	9/30/2021	15 yrs	09/30/2036
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	LH		9/30/2025	12 yrs	09/30/2037
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	RH		9/30/2025	12 yrs	09/30/2037
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	LH	DYE PEN	9/30/2025	12 yrs	09/30/2037
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	RH	DYE PEN	9/30/2025	12 yrs	09/30/2037
2900001G		HOSE ASSY,HYD ENGINE PUMP SUPPLY	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
5331013X	*	SKIN, UPPER FUSELAGE UNDER OXY LINE		INSPECT	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
05	*	INSPECTION,AIRFRAME, 12 YEAR			12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	RT	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUSELAGE FUEL TRANSFER	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,SPOILER EXTEND	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,SPOILER EXTEND	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,FLAP EXTEND	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,FLAP EXTEND	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYDRAULIC SUPPLY	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 2	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2431058E		CIRCUIT BREAKER,DC BUS 2	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2431058E		CIRCUIT BREAKER,DC BUS 3	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL TRANSFER		REPLACE	12/31/2025	12 yrs	12/31/2037
3233003G		HOSE ASSY,EMERGENCY BRAKE		REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL TRANSFER	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	LH	REPLACE	12/31/2025	12 yrs	12/31/2037

CALENDAR REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYDRAULIC SUPPLY	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,SPOILER RETRACT	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,SPOILER RETRACT	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD PRESSURE	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 3	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	LH	EDDY CURR	12/31/2025	12 yrs	12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	RH	EDDY CURR	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD FLAP RETRACT	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD ENGINE PUMP PRESSURE	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD FLAP RETRACT	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL SUPPLY	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL INTERCONNECT		REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL TRANSFER	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD PRESSURE		REPLACE	12/31/2025	12 yrs	12/31/2037
2900001G		HOSE ASSY,HYD HORIZ STAB		REPLACE	12/31/2025	12 yrs	12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
3233003G		HOSE ASSY,EMERG AIR NOSE GEAR ACT		REPLACE	12/31/2025	12 yrs	12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	LOWER	REPLACE	12/31/2025	12 yrs	12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	UPPER	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	12 yrs	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	12 yrs	12/31/2037
5210104U	*	BOLTS,UPPER DOOR TORSION BAR		REPLACE	12/31/2025	12 yrs	12/31/2037
5322000T		BOLTS,KEELBEAM ATTACHMENT			12/31/2025	12 yrs	12/31/2037

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

AIRFRAME LANDINGS REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDINGS		NEXT DUE	CURRENT	REMAINING	
05	*	INSPECTION,AIRFRAME, 3000 LANDING			8/27/2013	2983	3000 1dg	5983	1538	1462	07/04/2030
3211102V		TORQUE LINK,MAIN LANDING GEAR	LH	REPLACE	8/29/2001	0	6000 1dg	6000	4521	1479	07/21/2030
3211102V		TORQUE LINK,MAIN LANDING GEAR	RH	REPLACE	8/29/2001	0	6000 1dg	6000	4521	1479	07/21/2030
05	*	INSPECTION,AIRFRAME,MAJOR LAND GEAR			8/29/2001	0	6000 1dg	6000	4521	1479	07/21/2030
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	LH		9/30/2025	4454	6000 1dg	10454	67	5933	09/30/2037
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	RH		9/30/2025	4454	6000 1dg	10454	67	5933	09/30/2037
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	LH	DYE PEN	9/30/2025	4454	6000 1dg	10454	67	5933	09/30/2037
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	RH	DYE PEN	9/30/2025	4454	6000 1dg	10454	67	5933	09/30/2037
2820002G		HOSE ASSY,FUEL TRANSFER	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
5210104U	*	BOLTS,UPPER DOOR TORSION BAR		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD FLAP RETRACT	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD ENGINE PUMP PRESSURE	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD FLAP RETRACT	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL SUPPLY	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL INTERCONNECT		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL TRANSFER	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD PRESSURE		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD HORIZ STAB		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
3233003G		HOSE ASSY,EMERG AIR NOSE GEAR ACT		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	LOWER	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	UPPER	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
5322000T		BOLTS,KEELBEAM ATTACHMENT			12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD ENGINE PUMP SUPPLY	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	RT	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUSELAGE FUEL TRANSFER	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,SPOILER EXTEND	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,SPOILER EXTEND	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,FLAP EXTEND	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,FLAP EXTEND	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYDRAULIC SUPPLY	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 2	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037

AIRFRAME LANDINGS REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDINGS		NEXT DUE	CURRENT	REMAINING	
2431058E		CIRCUIT BREAKER,DC BUS 2	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2431058E		CIRCUIT BREAKER,DC BUS 3	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
3233003G		HOSE ASSY,EMERGENCY BRAKE		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYDRAULIC SUPPLY	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,SPOILER RETRACT	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,SPOILER RETRACT	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2900001G		HOSE ASSY,HYD PRESSURE	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 3	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
05	*	INSPECTION,AIRFRAME, 12 YEAR			12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	RH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	LH	REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	LH	EDDY CURR	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
2820002G		HOSE ASSY,FUEL TRANSFER		REPLACE	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	RH	EDDY CURR	12/31/2025	4454	6000 1dg	10454	67	5933	12/31/2037
7830090S	*	RING,T/R AFT BODY MATING FLANGE	LH	FLUOR PEN	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
3211075F	*	STRUT ASSEMBLY,MAIN GEAR	LH	REPLACE	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
7830090S	*	RING,T/R AFT BODY MATING FLANGE	RH	FLUOR PEN	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
3211075F	*	STRUT ASSEMBLY,MAIN GEAR	RH	REPLACE	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
3211078E	*	PIN,MAIN GEAR ATTACH	LH	REPLACE	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
3211078E	*	PIN,MAIN GEAR ATTACH	RH	REPLACE	8/29/2001	0	12000 1dg	12000	4521	7479	12/24/2046
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR	LH	REPLACE	8/29/2001	0	18000 1dg	18000	4521	13479	05/29/2063
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR	RH	REPLACE	8/29/2001	0	18000 1dg	18000	4521	13479	05/29/2063
3211087E	*	ACTUATOR ASSEMBLY,MAIN GEAR	LH	REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068
3211087E	*	ACTUATOR ASSEMBLY,MAIN GEAR	RH	REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068
3211082E	*	STRUT ASSEMBLY,NOSE GEAR		REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068
3211083E	*	ACTUATOR ASSEMBLY,NOSE GEAR		REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068
3211084E	*	PIN,MAIN GEAR ACTUATOR ATTACH	LH	REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068
3211084E	*	PIN,MAIN GEAR ACTUATOR ATTACH	RH	REPLACE	8/29/2001	0	20000 1dg	20000	4521	15479	11/18/2068

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
6/19/2007	1543.2	1286	0.0	0	1431.5	1222	1543.2	1285	0.0
7/03/2007	1640.1	1363	96.9	77	1528.4	1299	1640.1	1363	0.0
8/10/2007	1640.1	1363	0.0	0	1528.4	1299	1640.1	1363	0.0
9/10/2007	1640.1	1363	0.0	0	1528.4	1299	1640.1	1363	0.0
10/10/2007	1698.7	1412	58.6	49	1587.0	1348	1698.7	1412	0.0
11/10/2007	1698.7	1412	0.0	0	1587.0	1348	1698.7	1412	0.0
12/05/2007	1777.5	1475	78.8	63	1665.8	1411	1777.5	1475	0.0
1/10/2008	1777.5	1475	0.0	0	1665.8	1411	1777.5	1475	0.0
2/01/2008	1833.1	1518	55.6	43	1721.4	1454	1833.1	1518	0.0
3/01/2008	1845.9	1528	12.8	10	1734.2	1464	1845.9	1528	0.0
3/03/2008	1854.5	1534	8.6	6	1742.8	1470	1854.5	1534	0.0
3/15/2008	1871.0	1548	16.5	14	1759.3	1484	1871.0	1548	0.0
4/01/2008	1883.3	1556	12.3	8	1771.6	1492	1883.3	1556	0.0
5/01/2008	1895.1	1566	11.8	10	1783.4	1502	1895.1	1566	0.0
6/11/2008	1974.4	1622	79.3	56	1862.7	1558	1974.4	1622	0.0
7/09/2008	2001.4	1638	27.0	16	1889.7	1574	2001.4	1638	0.0
8/22/2008	2055.5	1679	54.1	41	1943.6	1615	2055.5	1679	0.0
9/23/2008	2058.2	1681	2.7	2	1946.3	1617	2058.2	1681	0.0
9/27/2008	2103.3	1717	45.1	36	1991.4	1653	2103.3	1717	0.0
10/10/2008	2103.3	1717	0.0	0	1991.4	1653	2103.3	1717	0.0
11/01/2008	2122.1	1736	18.8	19	2010.2	1672	2122.1	1736	0.0
12/18/2008	2144.7	1756	22.6	20	2033.0	1692	2144.7	1756	0.0
1/10/2009	2144.7	1756	0.0	0	2033.0	1692	2144.7	1756	0.0
2/01/2009	2153.5	1763	8.8	7	2041.8	1700	2153.5	1763	0.0
3/01/2009	2176.6	1782	23.1	19	2064.9	1719	2176.6	1782	0.0
3/30/2009	2214.8	1813	38.2	31	2103.1	1750	2214.8	1813	0.0
4/06/2009	2226.1	1819	11.3	6	2114.4	1756	2226.1	1819	0.0
5/08/2009	2239.3	1827	13.2	8	2127.6	1764	2239.3	1827	0.0
5/18/2009	2259.8	1840	20.5	13	2148.1	1777	2259.8	1840	0.0
6/10/2009	2259.8	1840	0.0	0	2148.1	1777	2259.8	1840	0.0
7/10/2009	2259.8	1840	0.0	0	2148.1	1777	2259.8	1840	0.0
8/01/2009	2326.8	1899	67.0	59	2215.1	1836	2326.8	1899	0.0
8/10/2009	2332.1	1905	5.3	6	2220.4	1842	2332.1	1905	0.0
9/10/2009	2332.1	1905	0.0	0	2220.4	1842	2332.1	1905	0.0
9/21/2009	2398.8	1951	66.7	46	2287.1	1888	2398.8	1951	0.0
10/01/2009	2412.2	1961	13.4	10	2300.5	1898	2412.2	1961	0.0
10/07/2009	2416.5	1964	4.3	3	2304.8	1901	2416.5	1964	0.0
10/19/2009	2438.4	1982	21.9	18	2326.7	1919	2438.4	1982	0.0
11/01/2009	2446.7	1987	8.3	5	2335.0	1924	2446.7	1987	0.0
11/12/2009	2446.7	1987	0.0	0	2335.0	1924	2446.7	1987	0.0
12/02/2009	2482.6	2016	35.9	29	2370.9	1953	2482.6	2016	0.0
12/09/2009	2482.6	2016	0.0	0	2370.9	1953	2482.6	2016	0.0
1/10/2010	2482.6	2016	0.0	0	2370.9	1953	2482.6	2016	0.0
2/01/2010	2484.7	2018	2.1	2	2373.0	1955	2484.7	2018	0.0

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
2/08/2010	2540.5	2060	55.8	42	2428.8	1997	2540.5	2060	0.0
2/12/2010	2540.5	2060	0.0	0	2428.8	1997	2540.5	2060	0.0
3/10/2010	2540.5	2060	0.0	0	2428.8	1997	2540.5	2060	0.0
4/07/2010	2598.1	2098	57.6	38	2486.4	2035	2598.1	2098	0.0
5/10/2010	2598.1	2098	0.0	0	2486.4	2035	2598.1	2098	0.0
6/10/2010	2598.1	2098	0.0	0	2486.4	2035	2598.1	2098	0.0
7/07/2010	2676.5	2163	78.4	65	2564.8	2100	2676.5	2163	0.0
8/10/2010	2676.5	2163	0.0	0	2564.8	2100	2676.5	2163	0.0
9/21/2010	2739.5	2218	63.0	55	2627.8	2155	2739.5	2218	0.0
9/28/2010	2739.5	2218	0.0	0	2627.8	2155	2739.5	2218	0.0
10/10/2010	2739.5	2218	0.0	0	2627.8	2155	2739.5	2218	0.0
11/01/2010	2794.5	2256	55.0	38	2682.8	2194	2794.5	2256	0.0
12/10/2010	2794.5	2256	0.0	0	2682.8	2194	2794.5	2256	0.0
1/12/2011	2840.6	2290	46.1	34	2728.9	2228	2840.6	2290	0.0
2/10/2011	2840.6	2290	0.0	0	2728.9	2228	2840.6	2290	0.0
3/07/2011	2915.8	2350	75.2	60	2804.1	2288	2850.9	2299	0.0
4/06/2011	2951.2	2374	35.4	24	2839.5	2312	2886.3	2323	0.0
5/11/2011	2980.4	2401	29.2	27	2868.7	2339	2915.3	2401	0.0
5/27/2011	2995.1	2412	14.7	11	2883.4	2350	2930.0	2361	0.0
6/09/2011	3006.2	2426	11.1	14	2894.5	2364	2941.1	2375	0.0
7/10/2011	3006.2	2426	0.0	0	2894.5	2364	2941.1	2375	0.0
8/15/2011	3065.4	2468	59.2	42	2953.7	2406	3003.3	2417	0.0
9/13/2011	3103.4	2495	38.0	27	2991.7	2433	3038.3	2444	0.0
10/04/2011	3121.6	2508	18.2	13	3009.9	2446	3056.5	2457	0.0
10/12/2011	3125.5	2511	3.9	3	3013.8	2449	3060.5	2460	0.0
11/01/2011	3139.8	2525	14.3	14	3028.1	2463	3074.7	2474	0.0
11/08/2011	3151.3	2531	11.5	6	3039.6	2469	3086.2	2480	0.0
11/09/2011	3169.7	2535	18.4	4	3058.0	2473	3104.6	2484	0.0
11/14/2011	3169.7	2535	0.0	0	3058.0	2473	3104.6	2484	0.0
12/15/2011	3190.3	2557	20.6	22	3078.6	2495	3125.2	2505	0.0
1/20/2012	3206.2	2571	15.9	14	3094.5	2509	3141.1	2519	0.0
2/09/2012	3225.8	2586	19.6	15	3114.1	2524	3160.7	2534	0.0
2/27/2012	3245.6	2608	19.8	22	3133.9	2546	3180.5	2556	0.0
4/04/2012	3270.0	2627	24.4	19	3158.3	2565	3204.9	2575	0.0
4/11/2012	3275.4	2633	5.4	6	3163.7	2571	3210.3	2581	0.0
4/28/2012	3293.9	2643	18.5	10	3182.2	2581	3228.8	2591	0.0
5/10/2012	3293.9	2643	0.0	0	3182.2	2581	3228.8	2591	0.0
6/21/2012	3345.4	2670	51.5	27	3233.7	2617	3280.3	2627	0.0
6/23/2012	3352.3	2677	6.9	7	3240.6	2624	3287.2	2634	0.0
7/20/2012	3352.3	2677	0.0	0	3240.6	2624	3287.2	2634	0.0
8/17/2012	3394.5	2711	42.2	34	3282.8	2658	3329.4	2668	0.0
9/23/2012	3452.2	2747	57.7	36	3340.5	2694	3387.1	2804	0.0
10/03/2012	3462.6	2752	10.4	5	3350.9	2699	3397.5	2809	0.0
12/03/2012	3535.5	2798	72.9	46	3423.8	2745	3470.4	2855	0.0

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026

N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
1/02/2013	3556.8	2810	21.3	12	3445.1	2757	3491.7	2867	0.0
1/16/2013	3563.4	2817	6.6	7	3451.7	2764	3498.3	2874	0.0
1/26/2013	3582.7	2833	19.3	16	3470.0	2780	3510.0	2890	0.0
2/22/2013	3582.7	2833	0.0	0	3470.0	2780	3510.0	2890	0.0
2/26/2013	3615.7	2854	33.0	21	3504.0	2801	3550.6	2911	0.0
3/10/2013	3615.7	2854	0.0	0	3504.0	2801	3550.6	2911	0.0
4/17/2013	3682.0	2899	66.3	45	3570.3	2845	3616.9	2955	0.0
5/20/2013	3712.3	2922	30.3	23	3600.6	2868	3647.2	2978	0.0
5/29/2013	3712.3	2922	0.0	0	3600.6	2868	3647.2	2978	0.0
6/10/2013	3712.3	2922	0.0	0	3600.6	2868	3647.2	2978	0.0
7/11/2013	3761.7	2955	49.4	33	3650.0	2901	3696.6	3011	0.0
8/02/2013	3790.0	2983	28.3	28	3688.3	2929	3734.9	3039	0.0
8/30/2013	3791.2	2984	1.2	1	3689.5	2930	3736.1	3040	0.0
9/09/2013	3805.5	2998	14.3	14	3703.8	2944	3750.4	3054	0.0
9/13/2013	3805.5	2998	0.0	0	3703.8	2944	3750.4	3054	0.0
10/01/2013	3805.5	2998	0.0	0	3703.8	2944	3750.4	3054	0.0
11/08/2013	3876.5	3042	71.0	44	3764.8	2988	3804.4	3098	0.0
12/19/2013	3919.8	3072	43.3	30	3808.1	3018	3854.7	3128	0.0
1/24/2014	3930.2	3079	10.4	7	3818.5	3025	3865.1	3135	0.0
3/10/2014	3984.7	3113	54.5	34	3873.0	3059	3920.1	3169	0.0
5/27/2014	4043.8	3153	59.1	40	3932.1	3099	3979.2	3209	0.0
6/10/2014	4053.4	3162	9.6	9	3941.7	3108	3988.8	3218	0.0
7/10/2014	4053.4	3162	0.0	0	3941.7	3108	3988.8	3218	0.0
8/01/2014	4119.3	3200	65.9	38	4007.6	3046	4054.4	3256	0.0
8/14/2014	4128.6	3205	9.3	5	4016.9	3051	4063.7	3261	0.0
9/10/2014	4128.6	3205	0.0	0	4016.9	3051	4063.7	3261	0.0
10/01/2014	4139.8	3214	11.2	9	4028.1	3060	4074.9	3270	0.0
11/07/2014	4181.7	3246	41.9	32	4070.0	3092	4116.8	3302	0.0
1/07/2015	4217.8	3265	36.1	19	4070.0	3092	4116.8	3302	0.0
2/20/2015	4227.0	3274	9.2	9	4079.2	3101	4126.3	3311	
3/09/2015	4227.0	3274	0.0	0	4079.2	3101	4126.3	3311	
3/12/2015	4236.9	3281	9.9	7	4089.1	3108	4136.2	3318	
3/26/2015	4236.9	3281	0.0	0	4089.1	3108	4136.2	3318	
3/27/2015	4255.0	3288	18.1	7	4107.2	3115	4154.3	3325	
4/24/2015	4261.8	3294	6.8	6	4114.0	3125	4161.1	3335	
5/08/2015	4276.1	3305	14.3	11	4128.3	3136	4175.4	3346	
5/15/2015	4281.2	3307	5.1	2	4133.4	3138	4180.5	3348	
5/26/2015	4285.0	3309	3.8	2	4137.2	3140	4184.3	3350	
6/01/2015	4289.8	3312	4.8	3	4142.0	3143	4189.1	3353	
6/05/2015	4294.3	3314	4.5	2	4146.5	3145	4193.6	3355	
6/17/2015	4300.2	3317	5.9	3	4152.4	3148	4199.5	3358	
7/01/2015	4308.4	3327	8.2	10	4160.6	3158	4207.7	3368	
7/04/2015	4319.3	3333	10.9	6	4171.5	3164	4218.6	3374	
7/18/2015	4329.7	3341	10.4	8	4181.9	3172	4229.0	3382	

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
7/24/2015	4332.6	3343	2.9	2	4184.8	3174	4231.9	3384	
7/29/2015	4332.6	3343	0.0	0	4184.8	3174	4231.9	3384	
8/01/2015	4337.1	3345	4.5	2	4189.3	3176	4236.4	3386	
8/13/2015	4337.1	3345	0.0	0	4189.3	3176	4236.4	3386	
8/31/2015	4363.9	3369	26.8	24	4216.1	3200	4263.2	3410	
9/15/2015	4363.9	3369	0.0	0	4216.1	3200	4263.2	3410	
10/03/2015	4374.1	3375	10.2	6	4226.3	3206	4273.4	3416	0
10/09/2015	4386.3	3384	12.2	9	4238.5	3215	4285.6	3425	
10/22/2015	4386.3	3384	0.0	0	4238.5	3215	4285.6	3425	
11/08/2015	4397.9	3392	11.6	8	4250.1	3223	4297.2	3433	
11/25/2015	4403.3	3395	5.4	3	4255.5	3226	4302.6	3436	
11/30/2015	4405.4	3397	2.1	2	4257.6	3228	4304.7	3438	
12/14/2015	4410.5	3401	5.1	4	4262.7	3232	4309.8	3442	
1/28/2016	4429.8	3415	19.3	14	4282.0	3246	4329.1	3456	
2/05/2016	4435.5	3419	5.7	4	4287.7	3250	4334.8	3460	
2/13/2016	4438.7	3421	3.2	2	4290.9	3252	4338.0	3462	
2/19/2016	4438.7	3421	0.0	0	4290.9	3252	4338.0	3462	
3/04/2016	4438.7	3421	0.0	0	4290.9	3252	4338.0	3462	
3/30/2016	4453.7	3440	15.0	19	4305.9	3263	4353.0	3473	
4/04/2016	4457.1	3442	3.4	2	4309.3	3265	4356.4	3475	
4/07/2016	4460.6	3446	3.5	4	4312.8	3267	4359.9	3477	
4/18/2016	4468.0	3449	7.4	3	4320.2	3270	4367.3	3480	
5/12/2016	4473.7	3455	5.7	6	4325.9	3276	4373.0	3486	
5/21/2016	4478.8	3457	5.1	2	4331.0	3278	4378.1	3488	
6/06/2016	4486.3	3460	7.5	3	4338.5	3281	4385.6	3491	
6/13/2016	4493.3	3467	7.0	7	4345.5	3288	4392.6	3498	
6/18/2016	4503.7	3472	10.4	5	4355.9	3293	4403.0	3503	
6/24/2016	4508.0	3476	4.3	4	4360.2	3297	4407.3	3507	
7/02/2016	4508.0	3476	0.0	0	4360.2	3297	4407.3	3507	
7/11/2016	4531.9	3494	23.9	18	4384.1	3315	4431.2	3525	
7/19/2016	4539.6	3500	7.7	6	4391.8	3321	4438.9	3531	0
7/25/2016	4544.5	3506	4.9	6	4396.7	3327	4443.8	3537	
7/28/2016	4548.4	3511	3.9	5	4400.6	3332	4447.7	3542	
8/10/2016	4549.8	3512	1.4	1	4402.0	3333	4449.1	3543	
8/12/2016	4555.7	3516	5.9	4	4407.9	3337	4455.0	3547	
8/22/2016	4557.1	3517	1.4	1	4409.3	3338	4456.4	3548	0
8/27/2016	4562.6	3521	5.5	4	4414.8	3342	4461.9	3552	
9/11/2016	4562.6	3521	0.0	0	4414.8	3342	4461.9	3552	
9/16/2016	4582.4	3535	19.8	14	4434.6	3356	4481.7	3566	
9/24/2016	4588.1	3538	5.7	3	4440.3	3359	4487.4	3569	
9/29/2016	4591.6	3540	3.5	2	4443.8	3361	4490.9	3571	
10/07/2016	4596.6	3543	5.0	3	4448.8	3364	4495.9	3574	
10/14/2016	4602.6	3549	6.0	6	4454.8	3370	4501.9	3580	
11/08/2016	4607.0	3551	4.4	2	4459.2	3372	4506.3	3582	

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
11/29/2016	4607.0	3551	0.0	0	4459.2	3372	4506.3	3582	
12/06/2016	4612.7	3556	5.7	5	4464.9	3377	4512.0	3587	
12/09/2016	4615.5	3558	2.8	2	4467.7	3379	4514.8	3589	
12/27/2016	4622.0	3566	6.5	8	4474.2	3387	4521.3	3597	
1/27/2017	4635.1	3574	13.1	8	4487.3	3395	4534.4	3605	
2/09/2017	4643.7	3579	8.6	5	4495.9	3400	4543.0	3610	0
2/21/2017	4646.6	3583	2.9	4	4498.8	3404	4545.9	3614	
2/27/2017	4651.2	3586	4.6	3	4503.4	3407	4550.5	3617	0
3/13/2017	4657.3	3591	6.1	5	4509.5	3412	4556.6	3622	
3/18/2017	4664	3597	6.7	6	4516.2	3418	4563.3	3628	0
4/01/2017	4669.7	3601	5.7	4	4521.9	3422	4569	3632	0
5/19/2017	4669.7	3601	0.0	0	4521.9	3422	4569.0	3632	
6/04/2017	4675.0	3606	5.3	5	4527.2	3427	4574.3	3637	
8/08/2017	4682.3	3610	7.3	4	4534.5	3431	4581.6	3641	
8/24/2017	4684.1	3612	1.8	2	4536.3	3433	4583.4	3643	
9/19/2017	4684.1	3612	0.0	0	4536.3	3433	4583.4	3643	0
10/05/2017	4685.9	3612	1.8	0	4538.1	3433	4585.2	3643	
12/19/2017	4685.9	3612	0.0	0	4538.1	3433	4585.2	3643	0
1/25/2018	4685.9	3612	0.0	0	4538.1	3433	4585.2	3643	0
3/29/2018	4685.9	3612	0.0	0	4538.1	3433	4585.2	3643	0
4/30/2018	4685.9	3612	0.0	0	4538.1	3433	4585.2	3643	0
5/16/2018	4685.9	3612	0.0	0	4538.1	3433	4585.2	3643	0
5/17/2018	4732.0	3640	46.1	28	4585.0	3468	4632.0	3678	
7/25/2018	4732.0	3640	0.0	0	4585	3468	4632.0	3678	0
8/31/2018	4732	3640	0.0	0	4585	3468	4632	3678	0
9/25/2018	4800.4	3661	68.4	21	4653.4	3489	4700.4	3699	
11/02/2018	4842.1	3700	41.7	39	4695.0	3529	4742.0	3740	
1/11/2019	4827.4	3686	-14.7	-14	4680.3	3515	4727.3	3726	0
2/26/2019	4840.1	3699	12.7	13	4693.0	3528	4740.0	3738	
4/02/2019	4862.1	3724	22.0	25	4715.1	3552	4762.1	3762	
5/28/2019	4862.1	3724	0.0	0	4715.1	3552	4762.1	3762	0
6/14/2019	4874.2	3736	12.1	12	4727.2	3564	4774.2	3774	0
7/07/2019	4914.8	3776	40.6	40	4767.8	3604	4814.8	3814	0
8/31/2019	4914.8	3776	0.0	0	4767.8	3604	4814.8	3814	0
9/20/2019	4921.4	3782	6.6	6	4774.4	3610	4821.4	3820	0
10/04/2019	4982.0	3844	60.6	62	4835	3670	4882.0	3880	
11/08/2019	4980.4	3813	-1.6	-31	4833.4	3641	4880.4	3851	0
12/12/2019	4997.7	3829	17.3	16	4850.7	3657	4897.7	3867	0
12/13/2019	5002.3	3835	4.6	6	4855.3	3663	4902.3	3873	0
1/03/2020	5014.0	3844	11.7	9	4867.0	3672	4914.0	3882	
2/28/2020	5014	3844	0.0	0	4867	3672	4914	3882	0
3/24/2020	5014.7	3841	0.7	-3	4871.6	3651	4918.6	3861	
4/13/2020	5014.7	3841			4871.6	3651	4918.6	3861	0
5/31/2020	5014.7	3841	0.0	0	4871.6	3651	4918.6	3861	0

AIRCRAFT UTILIZATION REPORT LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
6/18/2020	5038.0	3860	23.3	19	4895.0	3673	4942.0	3883	
7/04/2020	5060.6	3874	22.6	14	4917.6	3687	4964.6	3897	
8/20/2020	5100.1	3899	39.5	25	4953.1	3727	5000.1	3937	5140.0
10/02/2020	5131.0	3925	30.9	26	4984.0	3753	5031.0	3963	5170.9
10/16/2020	5138.1	3930	7.1	5	5038.1	3559	4991.4	3769	5138.1
11/30/2020	5138.1	3930	0.0	0	5038.1	3559	4991.4	3769	5138.1
12/07/2020	5181.6	3964	43.5	34	5034.6	3791	5081.6	4001	5181.6
2/02/2021	5181.6	3964	0.0	0	5034.6	3791	5081.6	4001	5181.6
3/25/2021	5245.4	4010	63.8	46	5098.4	3837	5145.4	4047	5245.4
4/07/2021	5259.0	4081	13.6	71	5112	3908	5159.0	4118	5299.0
4/30/2021	5259	4081	0.0	0	5112	3908	5159	4118	5299
5/14/2021	5281.9	4040	22.9	-41	5134.9	3867	5181.9	4077	5321.9
6/10/2021	5304.8	4058	22.9	18	5157.8	3885	5204.8	4095	5344.8
7/17/2021	5342.9	4088	38.1	30	5195.9	3915	5242.9	4125	5382.9
9/07/2021	5393.4	4131	50.5	43	5246.4	3958	5293.4	4168	5433.4
10/28/2021	5393.4	4131	0.0	0	5246.4	3958	5293.4	4168	5433.4
11/10/2021	5442.7	4169	49.3	38	5295.7	3977	5342.0	4181	5482.7
12/31/2021	5442.7	4169	0.0	0	5295.7	3977	5342	4181	5482.7
1/31/2022	5442.7	4169	0.0	0	5295.7	3977	5342	4181	5482.7
2/24/2022	5490.1	4188	47.4	19	5343.1	3996	5389.4	4200	5530.1
3/31/2022	5490.1	4188	0.0	0	5343.1	3996	5389.4	4200	5530.1
4/30/2022	5490.1	4188	0.0	0	5343.1	3996	5389.4	4200	5530.1
5/26/2022	5502.2	4195	12.1	7	5355.2	4003	5401.5	4207	5542.2
6/22/2022	5523.1	4209	20.9	14	5376.1	4017	5422.4	4221	5563.1
7/11/2022	5530.4	4214	7.3	5	5383.4	4022	5429.7	4226	5570.4
8/02/2022	5539.2	4219	8.8	5	5392.2	4027	5438.5	4231	5579.2
10/01/2022	5546.1	4226	6.9	7	5399.1	4034	5445.4	4238	5586.1
11/02/2022	5581.9	4267	35.8	41	5434.9	4075	5481.2	4279	5621.9
12/27/2022	5590.4	4271	8.5	4	5443.4	4079	5489.7	4283	5630.4
2/10/2023	5616.2	4289	25.8	18	5469.2	4097	5515.5	4301	5656.2
3/29/2023	5622.6	4294	6.4	5	5475.6	4102	5521.9	4306	5662.6
4/30/2023	5622.6	4294	0.0	0	5475.6	4102	5521.9	4306	5662.6
5/31/2023	5622.6	4294	0.0	0	5475.6	4102	5521.9	4306	5662.6
7/21/2023	5660.9	4318	38.3	24	5513.9	4126	5560.2	4330	5700.9
8/24/2023	5696.6	4340	35.7	22	5549.6	4148	5595.9	4352	5736.6
9/30/2023	5696.6	4340	0.0	0	5549.6	4148	5595.9	4352	5736.6
10/31/2023	5696.6	4340	0.0	0	5549.6	4148	5595.9	4352	5736.6
11/30/2023	5696.6	4340	0.0	0	5549.6	4148	5595.9	4352	5736.6
12/31/2023	5696.6	4340	0.0	0	5549.6	4148	5595.9	4352	5736.6
2/01/2024	5704.8	4346	8.2	6	5557.8	4154	5604.1	4358	5744.8
4/02/2024	5705.4	4347	0.6	1	5558.4	4155	5604.7	4359	5745.4
5/21/2024	5706.1	4348	0.7	1	5559.1	4156	5605.4	4360	5746.1
6/11/2024	5736.2	4366	30.1	18	5589.1	4174	5635.5	4377	5776.2
6/19/2024	5737.5	4368	1.3	2	5590.4	4176	5636.8	4379	5777.5

AIRCRAFT UTILIZATION REPORT

LEARJET 31232

7/03/2026
N68VP

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		HOBBS
	TTSN	LDGS	HOURS	LDGS	TTSN	TCSN	TTSN	TCSN	
7/19/2024	5741.0	4370	3.5	2	5593.9	4178	5640.3	4381	5781.0
8/27/2024	5744.4	4372	3.4	2	5597.3	4180	5643.7	4383	5784.4
9/30/2024	5744.4	4372	0.0	0	5597.3	4180	5643.7	4383	5784.4
11/15/2024	5776.3	4392	31.9	20	5629.2	4200	5675.6	4403	5816.3
12/31/2024	5776.3	4392	0.0	0	5629.2	4200	5675.6	4403	5816.3
2/28/2025	5776.3	4392	0.0	0	5629.2	4200	5675.6	4403	5816.3
4/01/2025	5797.2	4411	20.9	19	5650.1	4219	5696.5	4422	5837.2
4/24/2025	5807.6	4422	10.4	11	5660.5	4230	5706.9	4433	5847.6
5/12/2025	5815.4	4427	7.8	5	5668.3	4235	5714.7	4438	5855.4
7/08/2025	5818.7	4429	3.3	2	5671.6	4237	5718	4440	5858.7
9/18/2025	5848.7	4451	30.0	22	5701.6	4259	5748.0	4462	5848.7
10/24/2025	5848.7	4451	0.0	0	5701.6	4259	5748	4462	5848.7
12/01/2025	5848.7	4451	0.0	0	5701.6	4259	5748	4462	5848.7
2/03/2026	5854.3	4455	5.6	4	5707.2	4263	5758.6	4466	5895.3
2/11/2026	5878.4	4466	24.1	11	5731.3	4274	5782.7	4477	5919.4
3/11/2026	5887.2	4475	8.8	9	5740.1	4283	5791.5	4486	5928.2
7/03/2026	5962.1	4521	74.9	46	5815.0	4329	5866.4	4532	5964.9

LEFT ENGINE HOURS REPORT

GARRETT P99591

7/03/2026

N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
72	*	INSPECTION, ENGINE	300/400 HR	LH		ENG HRS	2/29/2024	42.0	PART \$ 0.00	08/14/2026
72-00-00 TABLE 603		TFE731-2-3B	P99591			300 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	5857.0
72	*	INSPECTION, ENGINE	150/250 HR	LH		ENG HRS	2/17/2026	68.0	PART \$ 0.00	09/09/2026
72-00-00 TABLE 603		TFE731-2-3B	P99591			150 eng	5733.0		LBR \$ 0.00	
									MHR: 0.0	5883.0
79	*	INSPECTION, ENGINE	SOAP	LH		ENG HRS	2/17/2026	68.0	PART \$ 0.00	09/09/2026
72-00-00 TABLE 603		TFE731-2-3B	P99591			150 eng	5733.0		LBR \$ 0.00	
									MHR: 0.0	5883.0
73	*	FILTER ELEMENT, FUEL		LH		ENG HRS	2/29/2024	392.0	PART \$ 0.00	07/30/2027
72-00-00 TABLE 603		897830-1	N/A			650 eng	5557.0		LBR \$ 0.00	
				REPLACE					MHR: 0.0	6207.0
72	*	INSPECTION, ENGINE	600/800 HR	LH		ENG HRS	2/29/2024	542.0	PART \$ 0.00	12/27/2027
72-00-00 TABLE 603		TFE731-2-3B	P99591			800 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	6357.0
79	*	OIL CHANGE, ENGINE		LH		ENG HRS	2/29/2024	942.0	PART \$ 0.00	01/30/2029
72-00-00 P311		MOBIL 254	N/A			1200 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	6757.0
72	*	INSPECTION, ENGINE	COMB PLENUM CASE	LH		ENG HRS	2/29/2024	1142.0	PART \$ 0.00	08/18/2029
SB 72-3105		TFE731-2-3B	P99591			1400 eng	5557.0		LBR \$ 0.00	
				INSPECT					MHR: 0.0	6957.0
72	*	INSPECTION, ENGINE	MAJOR PERIODIC	LH		ENG HRS	2/29/2024	1142.0	PART \$ 0.00	08/18/2029
SB 72-3105		TFE731-2-3B	P99591			1400 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	6957.0
97		SB 72-3494 (TURBINE BLADES)		LH		ENG HRS	2/23/2024	1142.0	PART \$ 0.00	08/18/2029
SEE SB						1400 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	6957.0
72	*	INSPECTION, ENG	1000 - 1500 HR	LH		ENG HRS	2/29/2024	1142.0	PART \$ 0.00	08/18/2029
72-00-00 TABLE 603		TFE731-2-3B	P99591			1400 eng	5557.0		LBR \$ 0.00	
									MHR: 0.0	6957.0
72	*	INSPECTION, ENGINE	FAN SUPPORT ASSY	LH		ENG HRS	12/08/2014	2454.2	PART \$ 0.00	03/22/2033
SB 72-3105		TFE731-2-3B	P99591			4200 eng	4069.2		LBR \$ 0.00	
									MHR: 0.0	8269.2
99	*	AD 2000-15-09 (HPC IMPELLER)		LH		ENG HRS	12/08/2014	2454.2	PART \$ 0.00	03/22/2033
SEE AD						4200 eng	4069.2		LBR \$ 0.00	
									MHR: 0.0	8269.2
97		SB A72-3641 (HP IMPELLER)		LH		ENG HRS	12/08/2014	2454.2	PART \$ 0.00	03/22/2033
SEE SB						4200 eng	4069.2		LBR \$ 0.00	
									MHR: 0.0	8269.2
72	*	INSPECTION, ENGINE	ACCESSORY GEARBOX	LH		ENG HRS	12/08/2014	2454.2	PART \$ 0.00	03/22/2033
SB 72-3105		TFE731-2-3B	P99591			4200 eng	4069.2		LBR \$ 0.00	
									MHR: 0.0	8269.2

LEFT ENGINE HOURS REPORT

GARRETT P99591

7/03/2026

N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R								
72	*	INSPECTION, ENGINE COMPRESSOR ZONE		LH		ENG HRS	12/08/2014	2454.2	PART \$	0.00	03/22/2033
SB 72-3105		TFE731-2-3B	P99591			4200 eng	4069.2		LBR \$	0.00	
									MHR:	0.0	8269.2

LEFT ENGINE CYCLES REPORT

GARRETT P99591

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
72	*	DISC, LP 1ST STAGE TURBINE ROTOR		LH		ENG CYC	2/29/2024		PART \$ 0.00	01/26/2038
SB 72-3001 R56		3075828-1	2318244945678	REPLACE		4400 cyc	4154	4225	LBR \$ 0.00 MHR: 0.0	8554
72	*	DISC, LP 2ND STAGE TURBINE ROTOR		LH		ENG CYC	2/29/2024		PART \$ 0.00	05/06/2038
SB 72-3001 R56		3072069-5	2318244945813	REPLACE		4500 cyc	4154	4325	LBR \$ 0.00 MHR: 0.0	8654
72	*	ROTOR, HP TURBINE WHEEL		LH		ENG CYC	2/29/2024		PART \$ 0.00	04/05/2040
SB 72-3001 R56		3072732-2	1718244924109	REPLACE		5200 cyc	4154	5025	LBR \$ 0.00 MHR: 0.0	9354
72	*	DISC, LP 3RD STAGE TURBINE ROTOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	08/29/2040
SB 72-3001 R56		3072068-3	000322901900	REPLACE		9500 cyc	0	5171	LBR \$ 0.00 MHR: 0.0	9500
72	*	DISC, LP 1ST STAGE AXIAL COMPRESSOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3072395-2	000316004371	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 2ND STAGE AXIAL COMPRESSOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3072396-3	010316000167	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 3RD STAGE AXIAL COMPRESSOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3072397-3	000316004579	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 4TH STAGE AXIAL COMPRESSOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3072398-2	000322903774	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000
72	*	IMPELLER, HP COMPRESSOR RADIAL		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3075765-1	000322908135	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC AND HUB, FAN ROTOR		LH		ENG CYC	7/06/2001		PART \$ 0.00	01/11/2042
SB 72-3001 R56		3073563-2	010322900458	REPLACE		10000 ----	0	5671	LBR \$ 0.00 MHR: 0.0	10000

RIGHT ENGINE HOURS REPORT

GARRETT P99590

7/03/2026

N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
72	*	INSPECTION, ENGINE	300/400 HR	RH		ENG HRS	3/12/2024	37.0	PART \$ 0.00	08/09/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590			300 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	150/250 HR	RH		ENG HRS	2/17/2026	63.0	PART \$ 0.00	09/04/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590			150 eng	5779.4		LBR \$ 0.00 MHR: 0.0	
79	*	INSPECTION, ENGINE	SOAP	RH		ENG HRS	2/17/2026	63.0	PART \$ 0.00	09/04/2026
72-00-00 TABLE 603		TFE731-2-3B	P99590			150 eng	5779.4		LBR \$ 0.00 MHR: 0.0	
73	*	FILTER ELEMENT, FUEL		RH		ENG HRS	3/12/2024	387.0	PART \$ 0.00	07/25/2027
72-00-00 TABLE 603		897830-1	N/A			650 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	600/800 HR	RH		ENG HRS	3/12/2024	537.0	PART \$ 0.00	12/22/2027
72-00-00 TABLE 603		TFE731-2-3B	P99590			800 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
79	*	OIL CHANGE, ENGINE		RH		ENG HRS	11/04/2021	675.6	PART \$ 0.00	05/08/2028
72-00-00 P311		MOBIL 254	N/A			1200 eng	5342.0		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENG	1000 - 1500 HR	RH		ENG HRS	3/12/2024	1137.0	PART \$ 0.00	08/13/2029
72-00-00 TABLE 603		TFE731-2-3B	P99590			1400 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	COMB PLENUM CASE	RH		ENG HRS	3/12/2024	1137.0	PART \$ 0.00	08/13/2029
SB 72-3105		TFE731-2-3B	P99590			1400 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	MAJOR PERIODIC	RH		ENG HRS	3/12/2024	1137.0	PART \$ 0.00	08/13/2029
SB 72-3105		TFE731-2-3B	P99590			1400 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
97	*	SB 72-3494 (TURBINE BLADES)		RH		ENG HRS	3/11/2024	1137.0	PART \$ 0.00	08/13/2029
SEE SB						1400 eng	5603.4		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	FAN SUPPORT ASSY	RH		ENG HRS	12/08/2014	2450.7	PART \$ 0.00	03/18/2033
SB 72-3105		N/A	N/A			4200 eng	4117.1		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	ACCESSORY GEARBOX	RH		ENG HRS	12/08/2014	2450.7	PART \$ 0.00	03/18/2033
SB 72-3105		TFE731-2-3B	P99590			4200 eng	4117.1		LBR \$ 0.00 MHR: 0.0	
72	*	INSPECTION, ENGINE	COMPRESSOR ZONE	RH		ENG HRS	12/08/2014	2450.7	PART \$ 0.00	03/18/2033
SB 72-3105		TFE731-2-3B	P99590			4200 eng	4117.1		LBR \$ 0.00 MHR: 0.0	
99	*	AD 2000-15-09 (HPC IMPELLER)		RH		ENG HRS	12/08/2014	2450.7	PART \$ 0.00	03/18/2033
SEE AD						4200 eng	4117.1		LBR \$ 0.00 MHR: 0.0	

RIGHT ENGINE HOURS REPORT

GARRETT P99590

7/03/2026

N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T		N E X T D U E
		PART NUMBER	PART SERIAL NUMBER								
97		SB A72-3641 (HP IMPELLER)		RH		ENG HRS	12/08/2014	2450.7	PART \$	0.00	03/18/2033
SEE SB						4200 eng	4117.1		LBR \$	0.00	

RIGHT ENGINE CYCLES REPORT

GARRETT P99590

7/03/2026
N68VP

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION ACTION	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
72	*	DISC, LP 1ST STAGE TURBINE ROTOR		RH		ENG CYC	12/08/2014		PART \$ 0.00	03/08/2035
SB 72-3001 R56		3075828-1	13-182449-10989	REPLACE		4400 cyc	3302	3170	LBR \$ 0.00 MHR: 0.0	7702
72	*	DISC, LP 2ND STAGE TURBINE ROTOR		RH		ENG CYC	3/12/2024		PART \$ 0.00	05/06/2038
SB 72-3001 R56		3072069-5	2318244945794	REPLACE		4500 cyc	4357	4325	LBR \$ 0.00 MHR: 0.0	8857
72	*	DISC, LP 3RD STAGE TURBINE ROTOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	02/08/2040
SB 72-3001 R56		3072068-3	000322903014	REPLACE		9500 cyc	0	4968	LBR \$ 0.00 MHR: 0.0	9500
72	*	ROTOR, HP TURBINE WHEEL		RH		ENG CYC	3/12/2024		PART \$ 0.00	04/05/2040
SB 72-3001 R56		3072732-2	1718244924111	REPLACE		5200 cyc	4357	5025	LBR \$ 0.00 MHR: 0.0	9557
72	*	DISC, LP 1ST STAGE AXIAL COMPRESSOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3072395-2	000316004380	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 2ND STAGE AXIAL COMPRESSOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3072396-3	000316004469	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 3RD STAGE AXIAL COMPRESSOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3072397-3	000316004588	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC, LP 4TH STAGE AXIAL COMPRESSOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3072398-2	010322900905	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000
72	*	IMPELLER, HP COMPRESSOR RADIAL		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3075765-1	000322908115	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000
72	*	DISC AND HUB, FAN ROTOR		RH		ENG CYC	7/03/2001		PART \$ 0.00	06/22/2041
SB 72-3001 R56		3073563-2	010322900455	REPLACE		10000 ----	0	5468	LBR \$ 0.00 MHR: 0.0	10000

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
05		AIRCRAFT REGISTRATION				DATE 7 yrs	1/30/2021			1/30/2028
			FAR							
05	*	INSPECTION, AIRFRAME, 12 YEAR			N/A	DATE 12 yrs	12/31/2025			12/31/2037
			5-10-27		N/A		5853.4	0.0		
05	*	INSPECTION, AIRFRAME, 12 YEAR			N/A	LANDING 6000 ldg	12/31/2025			12/31/2037
			5-10-27		N/A		4454	0	5933	10454
05	*	INSPECTION, AIRFRAME, 3000 LANDING			N/A	LANDING 3000 ldg	8/27/2013			7/04/2030
			5-10-00		N/A		2983	0	1462	5983
05	*	INSPECTION, AIRFRAME, 12000 HOUR			N/A	AF HRS 12000 hrs	8/29/2001			1/12/2043
			5-10-00		N/A		0.0	0.0	6037.9	12000.0
05	*	INSPECTION, AIRFRAME, MAJOR LAND GEAR			N/A	LANDING 6000 ldg	8/29/2001			7/21/2030
			5-10-00		N/A		0	0	1479	6000
05	*	INSPECTION, AIRFRAME, PHASE A1 - A6			N/A	DATE 12 mos	12/31/2025			12/31/2026
			5-10-00		N/A		5853.4	0.0		
05	*	INSPECTION, AIRFRAME, PHASE A1 - A6			N/A	AF HRS 300 hrs	12/31/2025			12/31/2026
			5-10-00		N/A		5853.4	0.0	191.3	6153.4
05	*	INSPECTION, AIRFRAME, PHASE B1 - B6			N/A	DATE 24 mos	12/31/2025			12/31/2027
			5-10-00		N/A		5853.4	0.0		
05	*	INSPECTION, AIRFRAME, PHASE B1 - B6			N/A	AF HRS 600 hrs	12/31/2025			11/06/2027
			5-10-00		N/A		5853.4	0.0	491.3	6453.4
05	*	INSPECTION, AIRFRAME, PHASE C1 - C6			N/A	DATE 48 mos	12/31/2025			12/31/2029
			5-10-00		N/A		5853.4	0.0		
05	*	INSPECTION, AIRFRAME, PHASE C1 - C6			N/A	AF HRS 1200 hrs	12/31/2025			6/28/2029
			5-10-00		N/A		5853.4	0.0	1091.3	7053.4
05	*	INSPECTION, AIRFRAME, PHASE D1 - D6			N/A	DATE 96 mos	12/31/2025			12/31/2033
			5-10-00		N/A		5853.4	0.0		
05	*	INSPECTION, AIRFRAME, PHASE D1 - D6			N/A	AF HRS 2400 hrs	12/31/2025			10/10/2032
			5-10-00		N/A		5853.4	0.0	2291.3	8253.4

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
1223010F	*	BATTERY, EMERGENCY		OPS CHK	PS835 3211	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		PRIMARY	5-10-29							
1223010F	*	BATTERY, EMERGENCY		OPS CHK	PS835 81952	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		SECONDARY	5-10-29							
1223015D	*	BATTERY, EMERGENCY		DISCHG	501-1712-02 3211	DATE 12 mos	8/29/2025 5848.7	0.0		8/29/2026
		PRIMARY	5-10-29							
1223015D	*	BATTERY, EMERGENCY		DISCHG	501-1712-02 81952	DATE 12 mos	8/29/2025 5848.7	0.0		8/29/2026
		SECONDARY	5-10-29							
21	*	AIR CONDITIONING SYSTEM COMPONENTS		INSPECT	N/A N/A	AF HRS 600 hrs	8/15/2025 5843.8	0.0	481.7	10/27/2027 6443.8
			KEITH AIR -----							
21	*	COMPRESSOR BELT TENSION WEAR		INSPECT	N/A N/A	AF HRS 600 hrs	6/13/2025 5818.7	0.0	456.6	10/02/2027 6418.7
			KEITH AIR -----							
21	*	EVAPORATOR & CONDENSER COILS		INSPECT	N/A N/A	AF HRS 600 hrs	6/13/2025 5818.7	0.0	456.6	10/02/2027 6418.7
			KEITH AIR -----							
21	*	EVAPORATOR BLOWERS		OVERHAUL	N/A N/A	A/C HRS 2000 a/c	8/29/2001 0.0	1978.0	21.0	7/24/2026 22.0
		AFT	KEITH AIR -----							
21	*	REFRIGERANT HOSES CHAFING WEAR		INSPECT	N/A N/A	AF HRS 1200 hrs	6/14/2019 4874.2	0.0	112.1	10/23/2026 6074.2
			KEITH AIR -----							
2130007U	*	CABIN PRESSURIZATION LEAK RATE CHK			N/A N/A	AF HRS 1200 hrs	11/01/2019 4980.4	0.0	218.3	2/06/2027 6180.4
			5-10-29							
2150034K	*	MOTOR, A/C COMPRESSOR BRUSH WEAR		INSPECT	ES61134-3 143	A/C HRS 1200 a/c	6/19/2018 1793.1	1978.0	1014.1	4/12/2029 1015.1
			5-10-29							
2150035K	*	MOTOR, A/C COMPRESSOR DRIVE		OVERHAUL	ES61134-3 143	A/C HRS 2000 a/c	6/19/2018 1793.1	1978.0	1814.1	6/21/2031 1815.1
			5-10-29							
24	*	BATTERY		TEST	GE381E 90% G03207744	DATE 6 mos	6/22/2026 5962.1	0.0		12/22/2026
		#1	GILL BATTERIES							
24	*	BATTERY		TEST	GE381E 90% G03207744	AF HRS 400 hrs	6/22/2026 5962.1	0.0	400.0	12/22/2026 6362.1
		#1	GILL BATTERIES							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
24	*	BATTERY		TEST	GE381E 90%	DATE	6/22/2026	0.0		12/22/2026
		#2	GILL BATTERIES		G03207742	6 mos	5962.1			
24	*	BATTERY		TEST	GE381E 90%	AF HRS	6/22/2026	0.0	400.0	12/22/2026 6362.1
		#2	GILL BATTERIES		G03207742	400 hrs	5962.1			
2431011H		STARTER GENERATOR		OVERHAUL	23080-023A	AF HRS	5/12/2026	0.0	961.8	2/18/2029 6923.9
		LH	5-10-29		Y10807	1000 hrs	5923.9			
2431011H		STARTER GENERATOR		OVERHAUL	23080-023A	AF HRS	5/12/2026	0.0	961.8	2/18/2029 6923.9
		RH	5-10-29		Y10294	1000 hrs	5923.9			
2431017H	*	BATTERY CABLES & RECEPTACLES		INSPECT	N/A	AF HRS	8/29/2025	0.0	186.6	1/05/2027 6148.7
		#1	5-10-29		N/A	300 hrs	5848.7			
2431017H	*	BATTERY CABLES & RECEPTACLES		INSPECT	N/A	AF HRS	8/29/2025	0.0	186.6	1/05/2027 6148.7
		#2	5-10-29		N/A	300 hrs	5848.7			
2431057E		CIRCUIT BREAKER, DC BUS 2		REPLACE	700-070-40	DATE	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A	12 yrs	5853.4			
2431057E		CIRCUIT BREAKER, DC BUS 2		REPLACE	700-070-40	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RH	5-11-00		N/A	6000 ldg	4454			
2431057E		CIRCUIT BREAKER, DC BUS 3		REPLACE	700-070-40	DATE	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A	12 yrs	5853.4			
2431057E		CIRCUIT BREAKER, DC BUS 3		REPLACE	700-070-40	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RH	5-11-00		N/A	6000 ldg	4454			
2431058E		CIRCUIT BREAKER, DC BUS 2		REPLACE	700-070-40	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2431058E		CIRCUIT BREAKER, DC BUS 2		REPLACE	700-070-40	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			
2431058E		CIRCUIT BREAKER, DC BUS 3		REPLACE	700-070-40	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2431058E		CIRCUIT BREAKER, DC BUS 3		REPLACE	700-070-40	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2431059U	*	BRUSH, STARTER GENERATOR		INSPECT	23080-023A Y10807	AF HRS 600 hrs	5/12/2026 5923.9	0.0	561.8	1/15/2028 6523.9
		LH	5-10-29							
2431059U	*	BRUSH, STARTER GENERATOR		INSPECT	23080-023A Y10294	AF HRS 600 hrs	5/12/2026 5923.9	0.0	561.8	1/15/2028 6523.9
		RH	5-10-29							
2431064U		BEARINGS, STARTER/GENERATOR		REPLACE	23080-023A Y10807	AF HRS 600 hrs	5/12/2026 5923.9	0.0	561.8	1/15/2028 6523.9
		LH	5-11-00							
2431064U		BEARINGS, STARTER/GENERATOR		REPLACE	23080-023A Y10294	AF HRS 600 hrs	5/12/2026 5923.9	0.0	561.8	1/15/2028 6523.9
		RH	5-11-00							
2432010B	*	BATTERY INSTALLATION		INSPECT	N/A N/A	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		#1	5-10-29							
2432010B	*	BATTERY INSTALLATION		INSPECT	N/A N/A	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		#2	5-10-29							
25	*	ELT BATTERY		REPLACE	452-0133 391140-018	DATE 5 yrs	8/01/2021 5342.9	0.0		8/01/2026
			5-11-00							
25	*	ELT RE-REGISTRATION				DATE 2 yrs	6/13/2025 5818.7	0.0		6/13/2027
			5-10-29							
25	*	LIFE VEST		VISUAL	N/A N/A	DATE 12 mos	6/22/2026 5962.1	0.0		6/22/2027
25		RECORDER, COCKPIT VOICE		FUNC TEST	N/A N/A	DATE 12 mos	6/22/2026 5962.1	0.0		6/22/2027
25		RECORDER, COCKPIT VOICE		MTBF	UNKNOWN UNKNOWN	AF HRS 30000 hrs	8/29/2001 0.0	0.0	24037.9	4/24/2092 30000.0
			23-70-03							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24040480020	DATE 10 yrs	5/31/2024 5744.4	0.0		5/31/2034
		#1	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24022500004	DATE 10 yrs	2/28/2024 5705.4	0.0		2/28/2034
		#2	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24052280001	DATE 10 yrs	5/31/2024 5744.4	0.0		5/31/2034
		#3	5-10-29							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24052280005	DATE 10 yrs	5/31/2024 5744.4	0.0		5/31/2034
		#4	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24052280006	DATE 10 yrs	2/28/2024 5705.4	0.0		2/28/2034
		#5	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24052280019	DATE 10 yrs	2/28/2024 5705.4	0.0		2/28/2034
		#6	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-201 24052280002	DATE 10 yrs	2/28/2024 5705.4	0.0		2/28/2034
		#7	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-101C 24040480015	DATE 10 yrs	4/30/2019 5744.4	0.0		4/30/2029
		COPILOT	5-10-29							
2561005p	*	LIFE VEST		RECERTIFY	PO1074-101C 28040480019	DATE 10 yrs	4/30/2019 5744.4	0.0		4/30/2029
		PILOT	5-10-29							
2563001J	*	ELT TEST (91.207 D)		INSPECT	453-5000-366 01238	DATE 12 mos	12/31/2025 5853.4	0.0		12/31/2026
			FAR							
2565000F	*	BATTERY, UNDERWATER LOCATOR BEACON		INSPECT	DK120 NT62067	DATE 2 yrs	3/18/2026 5898.7	0.0		3/18/2028
		CVR	5-10-29							
2566000F	*	BATTERY, UNDERWATER LOCATOR BEACON		REPLACE	DK120 NT62067	DATE 6 yrs	10/30/2023 5705.4	0.0		10/30/2029
		CVR	5-11-00							
26	*	BOTTLE, PORTABLE FIRE EXT INTERNAL		CHECK	A344 B-74105163	DATE 6 yrs	1/06/2023 5605.5	0.0		1/06/2029
		CABIN	NFPA/BOTTLE							
26	*	BOTTLE, PORTABLE FIRE EXT INTERNAL		CHECK	A344 B-74105157	DATE 6 yrs	1/06/2023 5605.5	0.0		1/06/2029
		COCKPIT	NFPA/BOTTLE							
26	*	SQUIB, ENGINE FIRE EXTINGUISHER		REPLACE	AE30903823 N/A	DATE 10 yrs	9/01/2016 4669.7	0.0		9/01/2026
		LH #1	CARTRIDGE LIFE							
26	*	SQUIB, ENGINE FIRE EXTINGUISHER		REPLACE	AE30903823 N/A	DATE 10 yrs	9/01/2016 4669.7	0.0		9/01/2026
		LH #2	CARTRIDGE LIFE							
26	*	SQUIB, ENGINE FIRE EXTINGUISHER		REPLACE	AE30903823 N/A	DATE 10 yrs	9/01/2016 4669.7	0.0		9/01/2026
		RH #1	CARTRIDGE LIFE							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
26	*	SQUIB,ENGINE FIRE EXTINGUISHER		REPLACE	AE30903823 N/A	DATE 10 yrs	9/01/2016 4669.7	0.0		9/01/2026
		RH #2	CARTRIDGE LIFE							
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		LH	5-10-29							
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		RH	5-10-29							
2620025Q	*	BOTTLE,ENGINE FIRE EXTING (HYDRO)		HYDRO	30402102-1 B12566	DATE 5 yrs	2/28/2024 5705.4	0.0		2/28/2029
		LH	5-10-29							
2620025Q	*	BOTTLE,ENGINE FIRE EXTING (HYDRO)		HYDRO	30402102-1 B13615	DATE 5 yrs	9/30/2025 5853.4	0.0		9/30/2030
		RH	5-10-29							
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER		HYDRO	A344 B-74105163	DATE 12 yrs	1/06/2023 5605.5	0.0		1/06/2035
		CABIN	5-10-29							
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER		HYDRO	A344 B-74105157	DATE 12 yrs	1/06/2023 5605.5	0.0		1/06/2035
		COCKPIT	5-10-29							
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER		REPLACE	13083-5 ESD23J943-001	DATE 6 yrs	3/23/2024 5705.4	0.0		3/23/2030
		LH #2	5-11-00							
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER (MFG)		REPLACE	13083-5 ESD23J943-001	DATE 9 yrs	9/30/2023 5705.4	0.0		9/30/2032
		LH #1	5-11-00							
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE		INSPECT	N/A N/A	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		LH	5-10-29							
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE		INSPECT	N/A N/A	DATE 6 mos	2/24/2026 5887.2	0.0		8/24/2026
		RH	5-10-29							
2710010E	*	BOLT,AILERON DRIVE YOKE		REPLACE	NAS1104-38D UNKNOWN	AF HRS 3600 hrs	12/28/2012 3556.8	0.0	1194.7	10/09/2029 7156.8
		LH	5-11-00							
2710010E	*	BOLT,AILERON DRIVE YOKE		REPLACE	NAS1104-38D UNKNOWN	AF HRS 3600 hrs	12/28/2012 3556.8	0.0	1194.7	10/09/2029 7156.8
		RH	5-11-00							
2710014E	*	BOLT,AILERON CENTER HINGE		REPLACE	AN4H13A UNKNOWN	AF HRS 3600 hrs	12/28/2012 3556.8	0.0	1194.7	10/09/2029 7156.8
		LH	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2710014E	*	BOLT,AILERON CENTER HINGE		REPLACE	AN4H13A UNKNOWN	AF HRS 3600 hrs	12/28/2012 3556.8	0.0	1194.7	10/09/2029 7156.8
		RH	5-11-00							
2710016G		AILERON ASSEMBLY		REPLACE	2424000-803 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710016G	*	AILERON ASSEMBLY		REPLACE	2424000-802 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710020E	*	BOLT,AILERON CLEVIS		REPLACE	NAS464P4-12 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710020E	*	BOLT,AILERON CLEVIS		REPLACE	NAS464P4-12 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710021M	*	BOLTS,AILERON HINGE		REPLACE	AN4H12A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH INBD	5-11-00							
2710021M	*	BOLTS,AILERON HINGE		REPLACE	AN4H12A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH OTBD	5-11-00							
2710021M	*	BOLTS,AILERON HINGE		REPLACE	AN4H12A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH INBD	5-11-00							
2710021M	*	BOLTS,AILERON HINGE		REPLACE	AN4H12A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH OTBD	5-11-00							
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE		REPLACE	2324513-17 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE		REPLACE	2324513-18 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710024E	*	CLEVIS,AILERON DRIVE		REPLACE	2324517-3 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710024E	*	CLEVIS,AILERON DRIVE		REPLACE	2324517-3 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710026E	*	YOKE ASSEMBLY,AILERON ACTUATOR		REPLACE	2324511-5 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2710026E	*	YOKE ASSEMBLY,AILERON ACTUATOR		REPLACE	2324511-5 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710028E	*	BEARING SUPPORT ASSEMBLY,AILERON		REPLACE	5425016-5 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710028E	*	BEARING SUPPORT ASSEMBLY,AILERON		REPLACE	5425016-5 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710031E	*	HINGE BRACKET ON WING,AILERON		REPLACE	2322530 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2710031E	*	HINGE BRACKET ON WING,AILERON		REPLACE	2322530 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2710036F	*	CABLE ASSY,AILERON CONTROL COLUMN		REPLACE	2300003-231 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH	5-11-00							
2710036F	*	CABLE ASSY,AILERON CONTROL COLUMN		REPLACE	2300003-229 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH	5-11-00							
2710036F	*	CABLE ASSY,AILERON FORWARD		REPLACE	2300003-245 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH	5-11-00							
2710036F	*	CABLE ASSY,AILERON FORWARD		REPLACE	2300003-246 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH	5-11-00							
2710036F	*	CABLE ASSY,AILERON SECTOR AFT		REPLACE	2300003-17 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
			5-11-00							
2710036F	*	CABLE ASSY,AILERON WING		REPLACE	5405015-31 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH INBD	5-11-00							
2710036F	*	CABLE ASSY,AILERON WING		REPLACE	5405015-29 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH OTBD	5-11-00							
2710036F	*	CABLE ASSY,AILERON WING		REPLACE	5405015-31 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH INBD	5-11-00							
2710036F	*	CABLE ASSY,AILERON WING		REPLACE	5405015-29 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH OTBD	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2720013F		CABLE ASSY, RUDDER		REPLACE	2300003-243 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH	5-11-00							
2720013F		CABLE ASSY, RUDDER		REPLACE	2300003-243 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH	5-11-00							
2720018E	*	RUDDER ASSEMBLY		REPLACE	UNKNOWN UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
			5-11-00							
2720021E	*	BOLT, RUDDER HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		CENTER	5-11-00							
2720021E	*	BOLT, RUDDER HINGE		REPLACE	NAS144A23 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LOWER	5-11-00							
2720021E	*	BOLT, RUDDER HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		UPPER	5-11-00							
2720023E	*	BEARING BLOCK ASSY, RUDDER LOWER		REPLACE	2312040 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
			5-11-00							
2720024E	*	HINGE INSTALLATION, RUDDER		REPLACE	2331030 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		UPPER	5-11-00							
2720025E	*	HINGE INSTALLATION, RUDDER		REPLACE	2331031 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		CENTER	5-11-00							
2730016E	*	ELEVATOR		REPLACE	2434000 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730016E	*	ELEVATOR		REPLACE	2434000 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332018 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH CENTER	5-11-00							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332019 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH INBD	5-11-00							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332013 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH OTBD	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332018 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH CENTER	5-11-00							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332019 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH INBD	5-11-00							
2730020E	*	HINGE, ELEVATOR		REPLACE	2332013 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH OTBD	5-11-00							
2730021E	*	BELLCRANK ASSEMBLY, ELEVATOR		REPLACE	2331511 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730021E	*	BELLCRANK ASSEMBLY, ELEVATOR		REPLACE	2331511 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730023E	*	PUSH PULL TUBE ASSEMBLY, ELEVATOR		REPLACE	2331510 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730023E	*	PUSH PULL TUBE ASSEMBLY, ELEVATOR		REPLACE	2331510 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730024E	*	BOLT, ELEVATOR HINGE		REPLACE	AN4H11A UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
2730030F	*	CABLE ASSY, ELEVATOR		REPLACE	2300003-171 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH AFT	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2730030F	*	CABLE ASSY,ELEVATOR		REPLACE	2300003-240 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH FWD	5-11-00							
2730030F	*	CABLE ASSY,ELEVATOR		REPLACE	2300003-172 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH AFT	5-11-00							
2730030F	*	CABLE ASSY,ELEVATOR		REPLACE	2300003-239 UNKNOWN	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH FWD	5-11-00							
2730033A	*	CONTROL COLUMN FLUORESCENT PEN		INSPECT	N/A N/A	AF HRS 2400 hrs	12/31/2025 5853.4	0.0	2291.3	10/10/2032 8253.4
			5-10-29							
2730036A	*	ELEVATOR BELLCRANKS		EDDY	N/A N/A	DATE 96 mos	7/02/2021 5335.9	0.0		7/02/2029
			5-10-29							
2730036A	*	ELEVATOR BELLCRANKS		EDDY	N/A N/A	AF HRS 2400 hrs	7/02/2021 5335.9	0.0	1773.8	7/02/2029 7735.9
			5-10-29							
2740010E	*	HINGE PIN,HORIZONTAL STABILIZER		REPLACE	2331028-5 UNKNOWN	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
			5-11-00							
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH		REPLACE	NAS464P6-23 UNKNOWN	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LOWER	5-11-00							
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH		REPLACE	NAS464P6-23 UNKNOWN	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LOWER	5-11-00							
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH		REPLACE	NAS464P6-17 UNKNOWN	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		UPPER	5-11-00							
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH		REPLACE	NAS464P6-17 UNKNOWN	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		UPPER	5-11-00							
2740021Q	*	ACTUATOR,HORIZONTAL STABILIZER		OVERHAUL	3135540-014 215	AF HRS 600 hrs	12/31/2025 5853.4	0.0	491.3	11/06/2027 6453.4
			5-10-29							
2750002E		BUSHING,FLAP NOSE ROLLER		REPLACE	NAS76A4-018 N/A	AF HRS 1200 hrs	3/29/2023 5622.6	0.0	860.5	11/09/2028 6822.6
		LH INBD	5-11-00							
2750002E		BUSHING,FLAP NOSE ROLLER		REPLACE	NAS76A4-020 N/A	AF HRS 1200 hrs	3/29/2023 5622.6	0.0	860.5	11/09/2028 6822.6
		LH OTBD	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2750002E		BUSHING, FLAP NOSE ROLLER		REPLACE	NAS76A4-018	AF HRS	3/29/2023	0.0	860.5	11/09/2028 6822.6
		RH INBD	5-11-00		N/A	1200 hrs	5622.6			
2750002E		BUSHING, FLAP NOSE ROLLER		REPLACE	NAS76A4-020	AF HRS	3/29/2023	0.0	860.5	11/09/2028 6822.6
		RH OTBD	5-11-00		N/A	1200 hrs	5622.6			
2750010E	*	TRACK, FLAP NOSE ROLLER		REPLACE	2322511-57	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		LH INBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750010E	*	TRACK, FLAP NOSE ROLLER		REPLACE	2322511-57	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		RH INBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750011E	*	TRACK, FLAP NOSE ROLLER		REPLACE	2322512-37	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		LH OUTBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750011E	*	TRACK, FLAP NOSE ROLLER		REPLACE	2322512-37	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		RH OUTBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750012E	*	FLAP TRACK ASSEMBLY		REPLACE	2325022-16	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		LH INBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750012E	*	FLAP TRACK ASSEMBLY		REPLACE	2325022-15	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		LT OUTBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750012E	*	FLAP TRACK ASSEMBLY		REPLACE	2325022-16	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		RH INBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750012E	*	FLAP TRACK ASSEMBLY		REPLACE	2325022-15	AF HRS	8/29/2001	0.0	6037.9	1/12/2043 12000.0
		RH OUTBD	5-11-00		UNKNOWN	12000 hrs	0.0			
2750013E	*	HINGE FITTING, FLAP TRACK		REPLACE	2625023	AF HRS	8/29/2001	0.0	9037.9	3/31/2051 15000.0
		LH INBD	5-11-00		UNKNOWN	15000 hrs	0.0			
2750013E	*	HINGE FITTING, FLAP TRACK		REPLACE	2625023	AF HRS	8/29/2001	0.0	9037.9	3/31/2051 15000.0
		RH INBD	5-11-00		UNKNOWN	15000 hrs	0.0			
2750014E	*	HINGE FITTING, FLAP TRACK		REPLACE	2625024	AF HRS	8/29/2001	0.0	9037.9	3/31/2051 15000.0
		LH OUTBD	5-11-00		UNKNOWN	15000 hrs	0.0			
2750014E	*	HINGE FITTING, FLAP TRACK		REPLACE	2625024	AF HRS	8/29/2001	0.0	9037.9	3/31/2051 15000.0
		RH OUTBD	5-11-00		UNKNOWN	15000 hrs	0.0			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2750034G		BOLT, FLAP SECTOR MOUNTING		REPLACE	NAS6605H44 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							
2750034G		BOLT, FLAP SECTOR MOUNTING		REPLACE	NAS6605H44 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2750034G		BOLT, FLAP SECTOR MOUNTING		REPLACE	NAS6605H44 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2750034G		BOLT, FLAP SECTOR MOUNTING		REPLACE	NAS6605H44 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2750044H	*	BEARINGS, FLAP CAM FOLLOWER		INSPECT	N/A N/A	AF HRS 1200 hrs	3/29/2023 5622.6	0.0	860.5	11/09/2028 6822.6
		LH/RH	5-10-29							
2760080E	*	BOLT, SPOILER ATTACH 5/16"		REPLACE	NAS464P5A14 UNKNOWN	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							
2760080E	*	BOLT, SPOILER ATTACH 5/16"		REPLACE	NAS464P5A14 UNKNOWN	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2760080E	*	BOLT, SPOILER ATTACH 5/16"		REPLACE	NAS464P5A14 UNKNOWN	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2760080E	*	BOLT, SPOILER ATTACH 5/16"		REPLACE	NAS464P5A14 UNKNOWN	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2760081E	*	BOLT, SPOILER PIVOT 5/16"		REPLACE	NAS6205-20D N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							
2760081E	*	BOLT, SPOILER PIVOT 5/16"		REPLACE	NAS6205-20D N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2760081E	*	BOLT, SPOILER PIVOT 5/16"		REPLACE	NAS6205-20D N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2760081E	*	BOLT, SPOILER PIVOT 5/16"		REPLACE	NAS6205-20D N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2760082E	*	BOLT, SPOILER ACTUATOR 1/4"		REPLACE	NAS464P4-13 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2760082E	*	BOLT, SPOILER ACTUATOR 1/4"		REPLACE	NAS464P4-13	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A		4454			
2760082E	*	BOLT, SPOILER ACTUATOR 1/4"		REPLACE	NAS464P4-13	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A		5853.4			
2760082E	*	BOLT, SPOILER ACTUATOR 1/4"		REPLACE	NAS464P4-13	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037 10454
		RH	5-11-00		N/A		4454			
2812002L	*	INNER WING STRUCTURE OTBD WS213.602		INSPECT	N/A	DATE 24 mos	4/24/2025	0.0		4/24/2027
			5-10-29		N/A		5807.6			
2812010L	*	3 ACCESS COVERS BTWN WS53,92.0 RIB		INSPECT	N/A	DATE 24 mos	4/24/2025	0.0		4/24/2027
			5-10-29		N/A		5807.6			
2812020L	*	VALVE, WING FLAPPER		INSPECT	N/A	DATE 24 mos	4/24/2025	0.0		4/24/2027
		LH INBD	5-10-29		N/A		5807.6			
2812020L	*	VALVE, WING FLAPPER		INSPECT	N/A	DATE 24 mos	4/24/2025	0.0		4/24/2027
		RH INBD	5-10-29		N/A		5807.6			
2820002G		HOSE ASSY, FUEL INTERCONNECT		REPLACE	S-161-16-22	DATE 12 yrs	12/31/2025	0.0		12/31/2037
			5-11-00		N/A		5853.4			
2820002G		HOSE ASSY, FUEL INTERCONNECT		REPLACE	S-161-16-22	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037 10454
			5-11-00		N/A		4454			
2820002G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-62	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		LH	5-10-29		N/A		5853.4			
2820002G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-19	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A		5853.4			
2820002G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2307006-95	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A		5853.4			
2820002G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-62	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037 10454
		LH	5-10-29		N/A		4454			
2820002G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-19	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A		4454			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2307006-95 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-62 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-10-29							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-45 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-19 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2307006-95 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-62 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-10-29							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-45 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2406005-19 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL MOTIVE FLOW		REPLACE	2307006-95 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL SUPPLY		REPLACE	2406005-24 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL SUPPLY		REPLACE	2406005-24 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2820002G		HOSE ASSY,FUEL TRANSFER		REPLACE	S-161-16-35 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-11-00							
2820002G		HOSE ASSY,FUEL TRANSFER		REPLACE	S-161-16-35 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
			5-11-00							
2820002G		HOSE ASSY,FUEL TRANSFER		REPLACE	S-161-16-35 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2820002G		HOSE ASSY, FUEL TRANSFER		REPLACE	S-161-16-35 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2820002G		HOSE ASSY, FUEL TRANSFER		REPLACE	S-161-16-35 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2820002G		HOSE ASSY, FUEL TRANSFER		REPLACE	S-161-16-35 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2820002G		HOSE ASSY, FUSELAGE FUEL TRANSFER		REPLACE	S-161-12-35 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-10-29							
2820002G		HOSE ASSY, FUSELAGE FUEL TRANSFER		REPLACE	S-161-12-35 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-10-29							
2820002G		HOSE ASSY, MOTIVE FLOW		REPLACE	2406005-28 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-10-29							
2820002G		HOSE ASSY, MOTIVE FLOW		REPLACE	3106002-6 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-10-29							
2820002G		HOSE ASSY, MOTIVE FLOW		REPLACE	2406005-28 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-10-29							
2820002G		HOSE ASSY, MOTIVE FLOW		REPLACE	3106002-6 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-10-29							
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW		REPLACE	3106003-1 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-10-29							
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW		REPLACE	12031-016-102 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-10-29							
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW		REPLACE	3106003-1 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-10-29							
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW		REPLACE	12031-016-102 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-10-29							
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW		REPLACE	12031-016-102 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-10-29							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW		REPLACE	12031-016-102	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RH	5-10-29		N/A	6000 ldg	4454			
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW		REPLACE	3106003-1	DATE	12/31/2025	0.0		12/31/2037
		RT	5-10-29		N/A	12 yrs	5853.4			
2820002G		HOSE ASSY,WING PUMP MOTIVE FLOW		REPLACE	3106003-1	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RT	5-10-29		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,FLAP EXTEND		REPLACE	A3028-235	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2900001G		HOSE ASSY,FLAP EXTEND		REPLACE	A3028-235	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,FLAP EXTEND		REPLACE	A3028-235	DATE	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A	12 yrs	5853.4			
2900001G		HOSE ASSY,FLAP EXTEND		REPLACE	A3028-235	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RH	5-11-00		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-21	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2900001G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-21	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-22	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2900001G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-22	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,HYD FLAP RETRACT		REPLACE	2307006-52	DATE	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A	12 yrs	5853.4			
2900001G		HOSE ASSY,HYD FLAP RETRACT		REPLACE	2307006-52	LANDING	12/31/2025	0	5933	12/31/2037 10454
		LH	5-11-00		N/A	6000 ldg	4454			
2900001G		HOSE ASSY,HYD FLAP RETRACT		REPLACE	2307006-52	DATE	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A	12 yrs	5853.4			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
2900001G		HOSE ASSY, HYD FLAP RETRACT		REPLACE	2307006-52 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2900001G		HOSE ASSY, HYD HORIZ STAB		REPLACE	2307006-94 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-11-00							
2900001G		HOSE ASSY, HYD HORIZ STAB		REPLACE	2307006-94 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
			5-11-00							
2900001G		HOSE ASSY, HYD PRESSURE		REPLACE	2307006-244 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-11-00							
2900001G		HOSE ASSY, HYD PRESSURE		REPLACE	2307006-244 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
			5-11-00							
2900001G		HOSE ASSY, HYD PRESSURE		REPLACE	2307006-51 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2900001G		HOSE ASSY, HYD PRESSURE		REPLACE	2307006-51 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2900001G		HOSE ASSY, HYDRAULIC SUPPLY		REPLACE	2406005-52 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							
2900001G		HOSE ASSY, HYDRAULIC SUPPLY		REPLACE	2406005-52 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2900001G		HOSE ASSY, HYDRAULIC SUPPLY		REPLACE	2406005-51 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							
2900001G		HOSE ASSY, HYDRAULIC SUPPLY		REPLACE	2406005-51 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		RH	5-11-00							
2900001G		HOSE ASSY, SPOILER EXTEND		REPLACE	A3028-233 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-11-00							
2900001G		HOSE ASSY, SPOILER EXTEND		REPLACE	A3028-233 N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-11-00							
2900001G		HOSE ASSY, SPOILER EXTEND		REPLACE	A3028-233 N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		RH	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
2900001G		HOSE ASSY, SPOILER EXTEND		REPLACE	A3028-233	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037
		RH	5-11-00		N/A		4454			10454
2900001G		HOSE ASSY, SPOILER RETRACT		REPLACE	A3028-237	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		LH	5-11-00		N/A		5853.4			
2900001G		HOSE ASSY, SPOILER RETRACT		REPLACE	A3028-237	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037
		LH	5-11-00		N/A		4454			10454
2900001G		HOSE ASSY, SPOILER RETRACT		REPLACE	A3028-235	DATE 12 yrs	12/31/2025	0.0		12/31/2037
		RH	5-11-00		N/A		5853.4			
2900001G		HOSE ASSY, SPOILER RETRACT		REPLACE	A3028-235	LANDING 6000 ldg	12/31/2025	0	5933	12/31/2037
		RH	5-11-00		N/A		4454			10454
3020001U	*	BULKHEAD, ENGINE NACELLE INLET		INSPECT	N/A	AF HRS 1400 hrs	3/23/2024	0.0	1143.3	8/19/2029
		LH	5-10-29		N/A		5705.4			7105.4
3020001U	*	BULKHEAD, ENGINE NACELLE INLET		INSPECT	N/A	AF HRS 1400 hrs	3/23/2024	0.0	1143.3	8/19/2029
		RH	5-10-29		N/A		5705.4			7105.4
31		BATTERY, DAVTRON CLOCK		REPLACE	N/A	DATE 2 yrs	3/27/2026	0.0		3/27/2028
		COPILOT			N/A		5909.1			
31		BATTERY, DAVTRON CLOCK		REPLACE	N/A	DATE 2 yrs	3/27/2026	0.0		3/27/2028
		PILOT			N/A		5909.1			
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC		REPLACE	111417-4S0134	DATE 5 yrs	5/05/2025	0.0		5/05/2030
		LH	5-11-00		N/A		5815.4			
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC		REPLACE	111417-4S0134	AF HRS 1500 hrs	5/05/2025	0.0	1353.3	3/17/2030
		LH	5-11-00		N/A		5815.4			7315.4
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC		REPLACE	111417-4S0134	DATE 5 yrs	5/05/2025	0.0		5/05/2030
		RH	5-11-00		N/A		5815.4			
3210003G		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC		REPLACE	111417-4S0134	AF HRS 1500 hrs	5/05/2025	0.0	1353.3	3/17/2030
		RH	5-11-00		N/A		5815.4			7315.4
3210003G		HOSE ASSY, HYD NOSE GEAR RETRACT		REPLACE	111504-6S0120	DATE 5 yrs	5/05/2025	0.0		5/05/2030
			5-11-00		N/A		5815.4			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
3210003G		HOSE ASSY, HYD NOSE GEAR RETRACT		REPLACE	111504-6S0120	AF HRS	5/05/2025	0.0	1353.3	3/17/2030
			5-11-00		N/A	1500 hrs	5815.4			
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	111504-6S0081	DATE	5/05/2025	0.0		5/05/2030
			5-11-00		N/A	5 yrs	5815.4			
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	111504-6S0081	DATE	5/05/2025	0.0		5/05/2030
			5-11-00		N/A	5 yrs	5815.4			
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	111504-6S0081	AF HRS	5/05/2025	0.0	1353.3	3/17/2030
			5-11-00		N/A	1500 hrs	5815.4			
3210003G		HOSE ASSY, NOSE GEAR EXTEND		REPLACE	111504-6S0081	AF HRS	5/05/2025	0.0	1353.3	3/17/2030
			5-11-00		N/A	1500 hrs	5815.4			
3211075F	*	STRUT ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	7479	12/24/2046
		LH	5-11-00		UNKNOWN	12000 ldg	0			
3211075F	*	STRUT ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	7479	12/24/2046
		RH	5-11-00		UNKNOWN	12000 ldg	0			
3211078E	*	PIN, MAIN GEAR ATTACH		REPLACE	2341109	LANDING	8/29/2001	0	7479	12/24/2046
		LH	5-11-00		UNKNOWN	12000 ldg	0			
3211078E	*	PIN, MAIN GEAR ATTACH		REPLACE	2341109	LANDING	8/29/2001	0	7479	12/24/2046
		RH	5-11-00		UNKNOWN	12000 ldg	0			
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	13479	5/29/2063
		LH	5-11-00		UNKNOWN	18000 ldg	0			
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	13479	5/29/2063
		RH	5-11-00		UNKNOWN	18000 ldg	0			
3211082E	*	STRUT ASSEMBLY, NOSE GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	15479	11/18/2068
			5-11-00		UNKNOWN	20000 ldg	0			
3211083E	*	ACTUATOR ASSEMBLY, NOSE GEAR		REPLACE	UNKNOWN	LANDING	8/29/2001	0	15479	11/18/2068
			5-11-00		UNKNOWN	20000 ldg	0			
3211084E	*	PIN, MAIN GEAR ACTUATOR ATTACH		REPLACE	UNKNOWN	LANDING	8/29/2001	0	15479	11/18/2068
		LH	5-11-00		UNKNOWN	20000 ldg	0			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
3211084E	*	PIN, MAIN GEAR ACTUATOR ATTACH		REPLACE	UNKNOWN UNKNOWN	LANDING 20000 ldg	8/29/2001 0		0	11/18/2068 20000
		RH	5-11-00							
3211087E	*	ACTUATOR ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN UNKNOWN	LANDING 20000 ldg	8/29/2001 0		0	11/18/2068 20000
		LH	5-11-00							
3211087E	*	ACTUATOR ASSEMBLY, MAIN GEAR		REPLACE	UNKNOWN UNKNOWN	LANDING 20000 ldg	8/29/2001 0		0	11/18/2068 20000
		RH	5-11-00							
3211102V		TORQUE LINK, MAIN LANDING GEAR		REPLACE	2341119	LANDING 6000 ldg	8/29/2001 0		0	7/21/2030 6000
		LH	5-11-00							
3211102V		TORQUE LINK, MAIN LANDING GEAR		REPLACE	2341119	LANDING 6000 ldg	8/29/2001 0		0	7/21/2030 6000
		RH	5-11-00							
3233003G		HOSE ASSY, AIR MAIN GEAR DOOR EXTEND		REPLACE	2307006-19 N/A	DATE 12 yrs	12/31/2025 5853.4		0.0	12/31/2037
		LH	5-11-00							
3233003G		HOSE ASSY, AIR MAIN GEAR DOOR EXTEND		REPLACE	2307006-19 N/A	LANDING 6000 ldg	12/31/2025 4454		0	12/31/2037 10454
		LH	5-11-00							
3233003G		HOSE ASSY, AIR MAIN GEAR DOOR EXTEND		REPLACE	2307006-20 N/A	DATE 12 yrs	12/31/2025 5853.4		0.0	12/31/2037
		RH	5-11-00							
3233003G		HOSE ASSY, AIR MAIN GEAR DOOR EXTEND		REPLACE	2307006-20 N/A	LANDING 6000 ldg	12/31/2025 4454		0	12/31/2037 10454
		RH	5-11-00							
3233003G		HOSE ASSY, EMERG AIR NOSE GEAR ACT		REPLACE	2307006-111 N/A	DATE 12 yrs	12/31/2025 5853.4		0.0	12/31/2037
			5-11-00							
3233003G		HOSE ASSY, EMERG AIR NOSE GEAR ACT		REPLACE	2307006-111 N/A	LANDING 6000 ldg	12/31/2025 4454		0	12/31/2037 10454
			5-11-00							
3233003G		HOSE ASSY, EMERGENCY BRAKE		REPLACE	2307006-242 N/A	DATE 12 yrs	12/31/2025 5853.4		0.0	12/31/2037
			5-11-00							
3233003G		HOSE ASSY, EMERGENCY BRAKE		REPLACE	2307006-242 N/A	LANDING 6000 ldg	12/31/2025 4454		0	12/31/2037 10454
			5-11-00							
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-112 N/A	DATE 5 yrs	12/31/2025 5853.4		0.0	12/31/2030
		LH INBD	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-112	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH INBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-113	DATE	12/31/2025	0.0		12/31/2030
		LH OUTBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-113	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH OUTBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-112	DATE	12/31/2025	0.0		12/31/2030
		RH INBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-112	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		RH INBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-113	DATE	12/31/2025	0.0		12/31/2030
		RH OUTBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE LOWER		REPLACE	2307006-113	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		RH OUTBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-37	DATE	12/31/2025	0.0		12/31/2030
		LH INBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-37	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH INBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-35	DATE	12/31/2025	0.0		12/31/2030
		LH OTBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-35	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH OTBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-37	DATE	12/31/2025	0.0		12/31/2030
		RH INBD	5-11-00		N/A	5 yrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-37	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		RH INBD	5-11-00		N/A	2400 hrs	5853.4			
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-35	DATE	12/31/2025	0.0		12/31/2030
		RH OTBD	5-11-00		N/A	5 yrs	5853.4			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
3243040G		HOSE ASSY, HYD BRAKE PRESSURE UPPER		REPLACE	2307006-35	AF HRS	12/31/2025	0.0	2291.3	12/31/2030
		RH OTBD	5-11-00		N/A	2400 hrs	5853.4			
33	*	LOPRESTI BOOM BEAM		INSPECT	STC SA02279AT	DATE	6/22/2026	0.0		6/22/2027
					600 HRS/1 YR	1 yrs	5962.1			
33	*	LOPRESTI BOOM BEAM		INSPECT	STC SA02279AT	AF HRS	6/22/2026	0.0	600.0	6/22/2027
					600 HRS/1 YR	600 hrs	5962.1			
34	*	COMPUTER, AIR DATA		CALIBRATE	065-0082-14	DATE	9/24/2024	0.0		9/24/2026
		#1	FAR 91.411, 413		X11124	24 mos	5764.8			
34	*	COMPUTER, AIR DATA		CALIBRATE	065-0082-14	DATE	9/24/2024	0.0		9/24/2026
		#2	FAR 91.411, 413		10948	24 mos	5764.8			
34		EGPWS		SELF TEST	N/A	DATE	6/22/2026	0.0		6/22/2027
					N/A	12 mos	5962.1			
34	*	RVSM			N/A	DATE	9/24/2024	0.0		9/24/2026
			5-10-30, SB		N/A	24 mos	5764.8			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		CHECK	N/A	DATE	9/24/2024	0.0		9/24/2026
		LH	FAR 91.411, 413		N/A	24 mos	5764.8			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		CHECK	N/A	DATE	9/24/2024	0.0		9/24/2026
		RH	FAR 91.411, 413		N/A	24 mos	5764.8			
34	*	STATIC SYSTEM LEAK (FAR91.411/413)		CHECK	N/A	DATE	9/24/2024	0.0		9/24/2026
		STANDBY	FAR 91.411, 413		N/A	24 mos	5764.8			
34	*	TRANSPONDER		TEST	011-01997-00	DATE	9/24/2024	0.0		9/24/2026
		#1	FAR 91.411, 413		20S011596 ADS OUT	24 mos	5764.8			
34	*	TRANSPONDER		TEST	011-01997-00	DATE	9/24/2024	0.0		9/24/2026
		#2	FAR 91.411, 413		20S011342 ADS OUT	24 mos	5764.8			
3411055P	*	PITOT STATIC PROBE PITCH/ROLL ALIGN		CHECK	N/A	DATE	9/24/2024	0.0		9/24/2026
			5-10-30 P.2		N/A	24 mos	5764.8			
3411056J	*	PROBE, PRIMARY PITOT STATIC		REPLACE	0856NA1	AF HRS	8/29/2001	0.0	9037.9	3/31/2051
		LH	5-11-00		UNKNOWN	15000 hrs	0.0			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
3411057J	*	PROBE, PRIMARY PITOT STATIC		REPLACE	0856NA2 UNKNOWN	AF HRS 15000 hrs	8/29/2001 0.0	0.0	9037.9	3/31/2051 15000.0
		RH	5-11-00							
3411059K	*	RVSM (AIR DATA SYSTEM)		FUNC TEST	N/A N/A	DATE 24 mos	9/24/2024 5764.8	0.0		9/24/2026
			5-10-30							
3411063N	*	RVSM PITOT STATIC PROBES VISUAL		INSPECT	N/A N/A	DATE 24 mos	6/22/2026 5962.1	0.0		6/22/2028
			5-10-30							
3414000K	*	ANTENNA, RADIO ALTIMETER		BOND CK	N/A N/A	DATE 24 mos	4/24/2025 5807.6	0.0		4/24/2027
			5-10-29							
3500019R	*	BOTTLE, OXYGEN		HYDRO	176700-40 ALT372-8745	DATE 5 yrs	9/30/2021 5490.1	0.0		9/30/2026
		TAIL	5-10-29							
3500051R	*	BOTTLE, OXYGEN		REPLACE	176700-40 ALT372-8745	DATE 15 yrs	9/30/2021 5490.1	0.0		9/30/2036
		TAIL	5-11-00							
3510021P		MASK, OXYGEN		OVERHAUL	MC10-15-151 89599	DATE 6 yrs	10/16/2025 5887.2	0.0		10/16/2031
		COPILOT	5-10-29							
3510021P		MASK, OXYGEN		OVERHAUL	MC10-15-151 38630	DATE 6 yrs	12/30/2020 5854.3	0.0		12/30/2026
		PILOT	5-10-29							
3610006R	*	BOTTLE, EMERGENCY AIR		HYDRO/VIS	6600194-6 231	DATE 6 yrs	11/03/2023 5741.0	0.0		11/03/2029
			5-10-29							
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		LH	5-10-29							
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		RH	5-10-29							
3610056R	*	BOTTLE, EMERGENCY AIR		SCRAP	6600194-6 231	DATE 40 yrs	1/01/1994 5741.0	0.0		1/01/2034
			5-11-00							
5210025L	*	CABIN DOOR STRUCTURE & HINGE AREA		INSPECT	N/A N/A	DATE 24 mos	4/24/2025 5807.6	0.0		4/24/2027
		EXT LWR	5-10-29							
5210104U	*	BOLTS, UPPER DOOR TORSION BAR		REPLACE	NAS1003-12H N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
5210104U	*	BOLTS, UPPER DOOR TORSION BAR		REPLACE	NAS1003-12H	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
			5-11-00		N/A					
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	N/A	DATE 12 mos	8/29/2025 5848.7	0.0		8/29/2026
			95-120/96L-120		N/A					
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	N/A	AF HRS 200 hrs	3/21/2025 5797.2	0.0	35.1	8/07/2026 5997.2
			95-120/96L-120		N/A					
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	N/A	AF HRS 600 hrs	1/10/2023 5610.0	0.0	247.9	3/07/2027 6210.0
			95-120/96L-120		N/A					
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	N/A	AF HRS 300 hrs	8/29/2025 5848.7	0.0	186.6	1/05/2027 6148.7
			95-120/96L-120		N/A					
53		ZR LITE INSPECTION			N/A	AF HRS 300 hrs	2/04/2026 5878.4	0.0	216.3	2/04/2027 6178.4
					N/A					
5313002P	*	PITOT STATIC PROBE ZONE SKIN CONTOR		CHECK	N/A	DATE 24 mos	9/24/2024 5764.8	0.0		9/24/2026
			5-10-30 P.2		N/A					
5322000T		BOLTS, KEELBEAM ATTACHMENT			MS20005-36/-14	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-11-00		UNKNOWN					
5322000T		BOLTS, KEELBEAM ATTACHMENT			MS20005-36/-14	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
			5-11-00		UNKNOWN					
5331013X	*	SKIN, UPPER FUSELAGE UNDER OXY LINE		INSPECT	N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
			5-10-29		N/A					
5450043J	*	PYLON/ENGINE BEAM STRUCTURE		INSPECT	N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		LH	5-10-29		N/A					
5450043J	*	PYLON/ENGINE BEAM STRUCTURE		INSPECT	N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		RH	5-10-29		N/A					
5450044H	*	ENGINE BEAM SUPPORT FITTINGS		EDDY CURR	N/A	DATE 12 yrs	12/31/2025 5853.4	0.0		12/31/2037
		LH	5-10-29		N/A					
5450044H	*	ENGINE BEAM SUPPORT FITTINGS		EDDY CURR	N/A	LANDING 6000 ldg	12/31/2025 4454	0	5933	12/31/2037 10454
		LH	5-10-29		N/A					

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
5450044H	*	ENGINE BEAM SUPPORT FITTINGS		EDDY CURR	N/A	DATE	12/31/2025	0.0		12/31/2037
		RH	5-10-29		N/A	12 yrs	5853.4			
5450044H	*	ENGINE BEAM SUPPORT FITTINGS		EDDY CURR	N/A	LANDING	12/31/2025	0	5933	12/31/2037 10454
		RH	5-10-29		N/A	6000 ldg	4454			
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE		INSPECT	N/A	AF HRS	3/23/2024	0.0	1143.3	8/19/2029 7105.4
		LH	5-10-29		N/A	1400 hrs	5705.4			
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE		INSPECT	N/A	AF HRS	3/23/2024	0.0	1143.3	8/19/2029 7105.4
		RH	5-10-29		N/A	1400 hrs	5705.4			
5610023G	*	WINDSHIELD LARASCOPE			LA6600393-004	AF HRS	12/31/2025	0.0	491.3	11/06/2027 6453.4
		RH	5-10-29		100055	600 hrs	5853.4			
5710145P	*	INBD DRY BAY ADJ FUSE/FWD SPAR 2		INSPECT	N/A	DATE	4/24/2025	0.0		4/24/2027
			5-10-29		N/A	24 mos	5807.6			
5750046H	*	FITTINGS, FLAP TRACK SUPPORT		INSPECT	N/A	AF HRS	3/29/2023	0.0	860.5	11/09/2028 6822.6
		LH	5-10-29		N/A	1200 hrs	5622.6			
5750046H	*	FITTINGS, FLAP TRACK SUPPORT		INSPECT	N/A	AF HRS	3/29/2023	0.0	860.5	11/09/2028 6822.6
		RH	5-10-29		N/A	1200 hrs	5622.6			
7110021G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-25	DATE	12/31/2025	0.0		12/31/2030
		LH NACELLE	5-11-00		N/A	5 yrs	5853.4			
7110021G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-25	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH NACELLE	5-11-00		N/A	2400 hrs	5853.4			
7110021G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-28	DATE	12/31/2025	0.0		12/31/2030
		RH NACELLE	5-11-00		N/A	5 yrs	5853.4			
7110021G		HOSE ASSY, FUEL MOTIVE FLOW		REPLACE	2406005-28	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		RH NACELLE	5-11-00		N/A	2400 hrs	5853.4			
7110021G		HOSE ASSY, FUEL SUPPLY		REPLACE	2406005-26	DATE	12/31/2025	0.0		12/31/2030
		LH NACELLE	5-11-00		N/A	5 yrs	5853.4			
7110021G		HOSE ASSY, FUEL SUPPLY		REPLACE	2406005-26	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		LH NACELLE	5-11-00		N/A	2400 hrs	5853.4			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
7110021G		HOSE ASSY,FUEL SUPPLY		REPLACE	2406005-23	DATE	12/31/2025	0.0		12/31/2030
		RH NACELLE	5-11-00		N/A	5 yrs	5853.4			
7110021G		HOSE ASSY,FUEL SUPPLY		REPLACE	2406005-23	AF HRS	12/31/2025	0.0	2291.3	12/31/2030 8253.4
		RH NACELLE	5-11-00		N/A	2400 hrs	5853.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-30	DATE	8/18/2021	0.0		8/18/2026
		LH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-30	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		LH	5-11-00		N/A	2400 hrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-27	DATE	8/18/2021	0.0		8/18/2026
		RH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE		REPLACE	2406005-27	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		RH	5-11-00		N/A	2400 hrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN		REPLACE	AS157G16311180	DATE	8/18/2021	0.0		8/18/2026
		LH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN		REPLACE	AS157G16311180	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		LH	5-11-00		N/A	2400 hrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN		REPLACE	AS157G184H180	DATE	8/18/2021	0.0		8/18/2026
		RH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN		REPLACE	AS157G184H180	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		RH	5-11-00		N/A	2400 hrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-22	DATE	8/18/2021	0.0		8/18/2026
		LH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-22	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		LH	5-11-00		N/A	2400 hrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-52	DATE	8/18/2021	0.0		8/18/2026
		RH	5-11-00		N/A	5 yrs	5393.4			
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY		REPLACE	2406005-52	AF HRS	8/18/2021	0.0	1831.3	8/18/2026 7793.4
		RH	5-11-00		N/A	2400 hrs	5393.4			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
7120024E	*	CASTING, ENGINE MOUNT		INSPECT	N/A	AF HRS	3/23/2024	0.0	1143.3	8/19/2029
		LH	5-10-29		N/A	1400 hrs	5705.4			
7120024E	*	CASTING, ENGINE MOUNT		INSPECT	N/A	AF HRS	3/23/2024	0.0	1143.3	8/19/2029
		RH	5-10-29		N/A	1400 hrs	5705.4			
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP			N/A	DATE	9/30/2025	0.0		9/30/2037
		LH	5-10-29		N/A	12 yrs	5853.4			
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP			N/A	LANDING	9/30/2025	0	5933	9/30/2037
		LH	5-10-29		N/A	6000 ldg	4454			
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP			N/A	DATE	9/30/2025	0.0		9/30/2037
		RH	5-10-29		N/A	12 yrs	5853.4			
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP			N/A	LANDING	9/30/2025	0	5933	9/30/2037
		RH	5-10-29		N/A	6000 ldg	4454			
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT		DYE PEN	N/A	DATE	9/30/2025	0.0		9/30/2037
		LH	5-10-29		N/A	12 yrs	5853.4			
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT		DYE PEN	N/A	LANDING	9/30/2025	0	5933	9/30/2037
		LH	5-10-29		N/A	6000 ldg	4454			
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT		DYE PEN	N/A	DATE	9/30/2025	0.0		9/30/2037
		RH	5-10-29		N/A	12 yrs	5853.4			
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT		DYE PEN	N/A	LANDING	9/30/2025	0	5933	9/30/2037
		RH	5-10-29		N/A	6000 ldg	4454			
7120036K		ENG FWD SHOCK MOUNT, COVER		REPLACE	LM833-3	AF HRS	1/02/2015	0.0	2455.7	3/23/2033
		LH LOWER	5-11-00		N/A	4200 hrs	4217.8			
7120036K		ENG FWD SHOCK MOUNT, COVER		REPLACE	LM833-3	AF HRS	1/02/2015	0.0	2455.7	3/23/2033
		LH UPPER	5-11-00		N/A	4200 hrs	4217.8			
7120036K		ENG FWD SHOCK MOUNT, COVER		REPLACE	LM833-3	AF HRS	1/02/2015	0.0	2455.7	3/23/2033
		RH LOWER	5-11-00		N/A	4200 hrs	4217.8			
7120036K		ENG FWD SHOCK MOUNT, COVER		REPLACE	LM833-3	AF HRS	1/02/2015	0.0	2455.7	3/23/2033
		RH UPPER	5-11-00		N/A	4200 hrs	4217.8			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
7120037L		BOND JOINT ISO ASSY,ENG AFT CENTER		REPLACE	LM833-16	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH AFT	5-11-00		N/A	8400 hrs	0.0			
7120037L		BOND JOINT ISO ASSY,ENG AFT CENTER		REPLACE	LM833-16	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH AFT	5-11-00		N/A	8400 hrs	0.0			
7120037L		ENG AFT ISOLATOR ASSY,HOUSING		REPLACE	LM833-30	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH	5-11-00		N/A	8400 hrs	0.0			
7120037L		ENG AFT ISOLATOR ASSY,HOUSING		REPLACE	LM833-30	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH	5-11-00		N/A	8400 hrs	0.0			
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH		REPLACE	2651026-1	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		LH LOWER	5-11-00		N/A	20000 hrs	0.0			
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH		REPLACE	2651026-1	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		LH UPPER	5-11-00		N/A	20000 hrs	0.0			
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH		REPLACE	2651026-1	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		RH LOWER	5-11-00		N/A	20000 hrs	0.0			
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH		REPLACE	2651026-1	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		RH UPPER	5-11-00		N/A	20000 hrs	0.0			
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH		REPLACE	2652002	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		LH	5-11-00		UNKNOWN	20000 hrs	0.0			
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH		REPLACE	2651027-1	AF HRS	8/27/2013	0.0	17827.9	4/24/2075
		LH	5-11-00		N/A	20000 hrs	3790.0			
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH		REPLACE	2652002	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		RH	5-11-00		UNKNOWN	20000 hrs	0.0			
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH		REPLACE	2651027-1	AF HRS	8/27/2013	0.0	17827.9	4/24/2075
		RH	5-11-00		N/A	20000 hrs	3790.0			
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT		REPLACE	6600187-4	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		LH LOWER	5-11-00		N/A	20000 hrs	0.0			
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT		REPLACE	6600187-4	AF HRS	8/29/2001	0.0	14037.9	12/07/2064
		LH UPPER	5-11-00		N/A	20000 hrs	0.0			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT		REPLACE	6600187-4 N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH LOWER	5-11-00							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT		REPLACE	6600187-4 N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH UPPER	5-11-00							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT		REPLACE	NAS1307-3H N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH LOWER	5-11-00							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT		REPLACE	NAS1307-3H N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH UPPER	5-11-00							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT		REPLACE	NAS1307-3H N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH LOWER	5-11-00							
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT		REPLACE	NAS1307-3H N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH UPPER	5-11-00							
7120041E	*	BOLT,ENGINE AFT SHOCK MOUNT ATTACH		REPLACE	NAS335CP23 N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		LH	5-11-00							
7120041E	*	BOLT,ENGINE AFT SHOCK MOUNT ATTACH		REPLACE	NAS335CP23 N/A	AF HRS 20000 hrs	8/29/2001 0.0	0.0	14037.9	12/07/2064 20000.0
		RH	5-11-00							
7120063Q	*	MOUNT ISOLATOR,ENGINE (FWD/AFT)		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		LH	5-10-29							
7120063Q	*	MOUNT ISOLATOR,ENGINE (FWD/AFT)		INSPECT	N/A N/A	AF HRS 1400 hrs	3/23/2024 5705.4	0.0	1143.3	8/19/2029 7105.4
		RH	5-10-29							
7120064K		ENG FWD SHOCK MOUNT,BOLTS		REPLACE	NAS6604H1 N/A	AF HRS 4200 hrs	1/02/2015 4217.8	0.0	2455.7	3/23/2033 8417.8
		LH LOWER	5-11-00							
7120064K		ENG FWD SHOCK MOUNT,BOLTS		REPLACE	NAS6604H1 N/A	AF HRS 4200 hrs	1/02/2015 4217.8	0.0	2455.7	3/23/2033 8417.8
		LH UPPER	5-11-00							
7120064K		ENG FWD SHOCK MOUNT,BOLTS		REPLACE	NAS6604H1 N/A	AF HRS 4200 hrs	1/02/2015 4217.8	0.0	2455.7	3/23/2033 8417.8
		RH LOWER	5-11-00							
7120064K		ENG FWD SHOCK MOUNT,BOLTS		REPLACE	NAS6604H1 N/A	AF HRS 4200 hrs	1/02/2015 4217.8	0.0	2455.7	3/23/2033 8417.8
		RH UPPER	5-11-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY		REPLACE	LM833-1	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH LOWER	5-11-00		N/A	8400 hrs	0.0			
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY		REPLACE	LM833-1	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH UPPER	5-11-00		N/A	8400 hrs	0.0			
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY		REPLACE	LM833-1	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH LOWER	5-11-00		N/A	8400 hrs	0.0			
7120065L		ENG FWD SHOCK MOUNT, MOUNT ASSY		REPLACE	LM833-1	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH UPPER	5-11-00		N/A	8400 hrs	0.0			
7120066L		ENG FWD SHOCK MOUNT, HOUSING		REPLACE	LM833-2	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH LWR	5-11-00		N/A	8400 hrs	0.0			
7120066L		ENG FWD SHOCK MOUNT, HOUSING		REPLACE	LM833-2	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		LH UPR	5-11-00		N/A	8400 hrs	0.0			
7120066L		ENG FWD SHOCK MOUNT, HOUSING		REPLACE	LM833-2	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH LWR	5-11-00		N/A	8400 hrs	0.0			
7120066L		ENG FWD SHOCK MOUNT, HOUSING		REPLACE	LM833-2	AF HRS	8/29/2001	0.0	2437.9	3/05/2033
		RH UPR	5-11-00		N/A	8400 hrs	0.0			
7120067T	*	BOLT, AFT ENGINE ATTACH		FLOUR PEN	2652002-801	AF HRS	3/23/2024	0.0	1143.3	8/19/2029
		LH	5-10-29		N/A	1400 hrs	5705.4			
7120067T	*	BOLT, AFT ENGINE ATTACH		FLOUR PEN	2652002-801	AF HRS	3/23/2024	0.0	1143.3	8/19/2029
		RH	5-10-29		N/A	1400 hrs	5705.4			
72	*	DISC AND HUB, FAN ROTOR		REPLACE	3073563-2	ENG CYC	7/06/2001	0	5671	1/11/2042
		LH	SB 72-3001 R56		010322900458	10000 cyc	0			
72	*	DISC AND HUB, FAN ROTOR		REPLACE	3073563-2	ENG CYC	7/03/2001	0	5468	6/22/2041
		RH	SB 72-3001 R56		010322900455	10000 cyc	0			
72	*	DISC, LP 1ST STAGE AXIAL COMPRESSOR		REPLACE	3072395-2	ENG CYC	7/06/2001	0	5671	1/11/2042
		LH	SB 72-3001 R56		000316004371	10000 cyc	0			
72	*	DISC, LP 1ST STAGE AXIAL COMPRESSOR		REPLACE	3072395-2	ENG CYC	7/03/2001	0	5468	6/22/2041
		RH	SB 72-3001 R56		000316004380	10000 cyc	0			

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
72	*	DISC, LP 1ST STAGE TURBINE ROTOR		REPLACE	3075828-1 2318244945678	ENG CYC 4400 cyc	2/29/2024 4154	0	4225	1/26/2038 8554
		LH	SB 72-3001 R56							
72	*	DISC, LP 1ST STAGE TURBINE ROTOR		REPLACE	3075828-1 13-182449-10989	ENG CYC 4400 cyc	12/08/2014 3302	0	3170	3/08/2035 7702
		RH	SB 72-3001 R56							
72	*	DISC, LP 2ND STAGE AXIAL COMPRESSOR		REPLACE	3072396-3 010316000167	ENG CYC 10000 cyc	7/06/2001 0	0	5671	1/11/2042 10000
		LH	SB 72-3001 R56							
72	*	DISC, LP 2ND STAGE AXIAL COMPRESSOR		REPLACE	3072396-3 000316004469	ENG CYC 10000 cyc	7/03/2001 0	0	5468	6/22/2041 10000
		RH	SB 72-3001 R56							
72	*	DISC, LP 2ND STAGE TURBINE ROTOR		REPLACE	3072069-5 2318244945813	ENG CYC 4500 cyc	2/29/2024 4154	0	4325	5/06/2038 8654
		LH	SB 72-3001 R56							
72	*	DISC, LP 2ND STAGE TURBINE ROTOR		REPLACE	3072069-5 2318244945794	ENG CYC 4500 cyc	3/12/2024 4357	0	4325	5/06/2038 8857
		RH	SB 72-3001 R56							
72	*	DISC, LP 3RD STAGE AXIAL COMPRESSOR		REPLACE	3072397-3 000316004579	ENG CYC 10000 cyc	7/06/2001 0	0	5671	1/11/2042 10000
		LH	SB 72-3001 R56							
72	*	DISC, LP 3RD STAGE AXIAL COMPRESSOR		REPLACE	3072397-3 000316004588	ENG CYC 10000 cyc	7/03/2001 0	0	5468	6/22/2041 10000
		RH	SB 72-3001 R56							
72	*	DISC, LP 3RD STAGE TURBINE ROTOR		REPLACE	3072068-3 000322901900	ENG CYC 9500 cyc	7/06/2001 0	0	5171	8/29/2040 9500
		LH	SB 72-3001 R56							
72	*	DISC, LP 3RD STAGE TURBINE ROTOR		REPLACE	3072068-3 000322903014	ENG CYC 9500 cyc	7/03/2001 0	0	4968	2/08/2040 9500
		RH	SB 72-3001 R56							
72	*	DISC, LP 4TH STAGE AXIAL COMPRESSOR		REPLACE	3072398-2 000322903774	ENG CYC 10000 cyc	7/06/2001 0	0	5671	1/11/2042 10000
		LH	SB 72-3001 R56							
72	*	DISC, LP 4TH STAGE AXIAL COMPRESSOR		REPLACE	3072398-2 010322900905	ENG CYC 10000 cyc	7/03/2001 0	0	5468	6/22/2041 10000
		RH	SB 72-3001 R56							
72	*	IMPELLER, HP COMPRESSOR RADIAL		REPLACE	3075765-1 000322908135	ENG CYC 10000 cyc	7/06/2001 0	0	5671	1/11/2042 10000
		LH	SB 72-3001 R56							
72	*	IMPELLER, HP COMPRESSOR RADIAL		REPLACE	3075765-1 000322908115	ENG CYC 10000 cyc	7/03/2001 0	0	5468	6/22/2041 10000
		RH	SB 72-3001 R56							

MASTER REPORT
LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
72	*	INSPECTION,ENG 1000 - 1500 HR			TFE731-2-3B P99591	ENG HRS 1400 eng	2/29/2024 5557.0	0.0	1142.0	8/18/2029 6957.0
		LH	72-00-00 TABLE 603							
72	*	INSPECTION,ENG 1000 - 1500 HR			TFE731-2-3B P99590	ENG HRS 1400 eng	3/12/2024 5603.4	0.0	1137.0	8/13/2029 7003.4
		RH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 150/250 HR			TFE731-2-3B P99591	ENG HRS 150 eng	2/17/2026 5733.0	0.0	68.0	9/09/2026 5883.0
		LH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 150/250 HR			TFE731-2-3B P99590	ENG HRS 150 eng	2/17/2026 5779.4	0.0	63.0	9/04/2026 5929.4
		RH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 300/400 HR			TFE731-2-3B P99591	ENG HRS 300 eng	2/29/2024 5557.0	0.0	42.0	8/14/2026 5857.0
		LH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 300/400 HR			TFE731-2-3B P99590	ENG HRS 300 eng	3/12/2024 5603.4	0.0	37.0	8/09/2026 5903.4
		RH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 600/800 HR			TFE731-2-3B P99591	ENG HRS 800 eng	2/29/2024 5557.0	0.0	542.0	12/27/2027 6357.0
		LH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE 600/800 HR			TFE731-2-3B P99590	ENG HRS 800 eng	3/12/2024 5603.4	0.0	537.0	12/22/2027 6403.4
		RH	72-00-00 TABLE 603							
72	*	INSPECTION,ENGINE ACCESSORY GEARBOX			TFE731-2-3B P99591	ENG HRS 4200 eng	12/08/2014 4069.2	0.0	2454.2	3/22/2033 8269.2
		LH	SB 72-3105							
72	*	INSPECTION,ENGINE ACCESSORY GEARBOX			TFE731-2-3B P99590	ENG HRS 4200 eng	12/08/2014 4117.1	0.0	2450.7	3/18/2033 8317.1
		RH	SB 72-3105							
72	*	INSPECTION,ENGINE COMB PLENUM CASE		INSPECT	TFE731-2-3B P99591	ENG HRS 1400 eng	2/29/2024 5557.0	0.0	1142.0	8/18/2029 6957.0
		LH	SB 72-3105							
72	*	INSPECTION,ENGINE COMB PLENUM CASE		INSPECT	TFE731-2-3B P99590	ENG HRS 1400 eng	3/12/2024 5603.4	0.0	1137.0	8/13/2029 7003.4
		RH	SB 72-3105							
72	*	INSPECTION,ENGINE COMPRESSOR ZONE			TFE731-2-3B P99591	ENG HRS 4200 eng	12/08/2014 4069.2	0.0	2454.2	3/22/2033 8269.2
		LH	SB 72-3105							
72	*	INSPECTION,ENGINE COMPRESSOR ZONE			TFE731-2-3B P99590	ENG HRS 4200 eng	12/08/2014 4117.1	0.0	2450.7	3/18/2033 8317.1
		RH	SB 72-3105							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		A C T I O N	P A R T N U M B E R P A R T S E R I A L N U M B E R	F I L E I N T E R V A L	L A S T A C C O M P L I S H	T S O / C S O	R E M A I N I N G H R / C Y C / L D G	N E X T D U E
		L O C A T I O N	M A I N T E N A C E R E F E R E N C E							
72	*	INSPECTION,ENGINE FAN SUPPORT ASSY			TFE731-2-3B P99591	ENG HRS 4200 eng	12/08/2014 4069.2	0.0	2454.2	3/22/2033 8269.2
		LH	SB 72-3105							
72	*	INSPECTION,ENGINE FAN SUPPORT ASSY			N/A N/A	ENG HRS 4200 eng	12/08/2014 4117.1	0.0	2450.7	3/18/2033 8317.1
		RH	SB 72-3105							
72	*	INSPECTION,ENGINE MAJOR PERIODIC			TFE731-2-3B P99591	ENG HRS 1400 eng	2/29/2024 5557.0	0.0	1142.0	8/18/2029 6957.0
		LH	SB 72-3105							
72	*	INSPECTION,ENGINE MAJOR PERIODIC			TFE731-2-3B P99590	ENG HRS 1400 eng	3/12/2024 5603.4	0.0	1137.0	8/13/2029 7003.4
		RH	SB 72-3105							
72	*	ROTOR,HP TURBINE WHEEL		REPLACE	3072732-2 1718244924109	ENG CYC 5200 cyc	2/29/2024 4154	0	5025	4/05/2040 9354
		LH	SB 72-3001 R56							
72	*	ROTOR,HP TURBINE WHEEL		REPLACE	3072732-2 1718244924111	ENG CYC 5200 cyc	3/12/2024 4357	0	5025	4/05/2040 9557
		RH	SB 72-3001 R56							
73	*	FILTER ELEMENT,FUEL		REPLACE	897830-1 N/A	ENG HRS 650 eng	2/29/2024 5557.0	0.0	392.0	7/30/2027 6207.0
		LH	72-00-00 TABLE 603							
73	*	FILTER ELEMENT,FUEL		REPLACE	897830-1 N/A	ENG HRS 650 eng	3/12/2024 5603.4	0.0	387.0	7/25/2027 6253.4
		RH	72-00-00 TABLE 603							
78	*	INSPECTION,THRUST REV 1200/1400 HR			N/A N/A	AF HRS 1200 hrs	3/21/2025 5797.2	0.0	1035.1	5/03/2029 6997.2
		LH	TR4000 78-30-00							
78	*	INSPECTION,THRUST REV 1200/1400 HR			N/A N/A	AF HRS 1200 hrs	3/21/2025 5797.2	0.0	1035.1	5/03/2029 6997.2
		RH	TR4000 78-30-00							
78	*	INSPECTION,THRUST REV 150/200 HR			N/A N/A	AF HRS 150 hrs	5/12/2026 5923.9	0.0	111.8	10/22/2026 6073.9
		LH	TR4000 78-30-00							
78	*	INSPECTION,THRUST REV 150/200 HR			N/A N/A	AF HRS 150 hrs	5/12/2026 5923.9	0.0	111.8	10/22/2026 6073.9
		RH	TR4000 78-30-00							
78	*	INSPECTION,THRUST REV 2400 HR			N/A N/A	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		LH	TR4000 78-30-00							
78	*	INSPECTION,THRUST REV 2400 HR			N/A N/A	AF HRS 2400 hrs	5/15/2017 4669.7	0.0	1107.6	7/14/2029 7069.7
		RH	TR4000 78-30-00							

MASTER REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
78	*	INSPECTION, THRUST REV 300/400 HR			N/A	AF HRS	3/21/2025			11/15/2026
		LH	TR4000 78-30-00		N/A	300 hrs	5797.2	0.0	135.1	6097.2
78	*	INSPECTION, THRUST REV 300/400 HR			N/A	AF HRS	3/21/2025			11/15/2026
		RH	TR4000 78-30-00		N/A	300 hrs	5797.2	0.0	135.1	6097.2
78	*	INSPECTION, THRUST REV 600/800 HR			N/A	AF HRS	3/21/2025			9/11/2027
		LH	TR4000 78-30-00		N/A	600 hrs	5797.2	0.0	435.1	6397.2
78	*	INSPECTION, THRUST REV 600/800 HR			N/A	AF HRS	3/21/2025			9/11/2027
		RH	TR4000 78-30-00		N/A	600 hrs	5797.2	0.0	435.1	6397.2
7810005U	*	NOZZLES, ENGINE EXHAUST		INSPECT	N/A	AF HRS	3/23/2024			8/19/2029
		LH	5-10-29		N/A	1400 hrs	5705.4	0.0	1143.3	7105.4
7810005U	*	NOZZLES, ENGINE EXHAUST		INSPECT	N/A	AF HRS	3/23/2024			8/19/2029
		RH	5-10-29		N/A	1400 hrs	5705.4	0.0	1143.3	7105.4
7830090S	*	RING, T/R AFT BODY MATING FLANGE		FLUOR PEN	N/A	LANDING	8/29/2001			12/24/2046
		LH	5-10-29		N/A	12000 ldg	0	0	7479	12000
7830090S	*	RING, T/R AFT BODY MATING FLANGE		FLUOR PEN	N/A	LANDING	8/29/2001			12/24/2046
		RH	5-10-29		N/A	12000 ldg	0	0	7479	12000
79	*	INSPECTION, ENGINE SOAP			TFE731-2-3B	ENG HRS	2/17/2026			9/09/2026
		LH	72-00-00 TABLE 603		P99591	150 eng	5733.0	0.0	68.0	5883.0
79	*	INSPECTION, ENGINE SOAP			TFE731-2-3B	ENG HRS	2/17/2026			9/04/2026
		RH	72-00-00 TABLE 603		P99590	150 eng	5779.4	0.0	63.0	5929.4
79	*	OIL CHANGE, ENGINE			MOBIL 254	ENG HRS	2/29/2024			1/30/2029
		LH	72-00-00 P311		N/A	1200 eng	5557.0	0.0	942.0	6757.0
79	*	OIL CHANGE, ENGINE			MOBIL 254	ENG HRS	11/04/2021			5/08/2028
		RH	72-00-00 P311		N/A	1200 eng	5342.0	0.0	675.6	6542.0
97		SB 72-3494 (TURBINE BLADES)				ENG HRS	2/23/2024			8/18/2029
		LH	SEE SB			1400 eng	5557.0		1142.0	6957.0
97		SB 72-3494 (TURBINE BLADES)				ENG HRS	3/11/2024			8/13/2029
		RH	SEE SB			1400 eng	5603.4		1137.0	7003.4

MASTER REPORT
LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
97		SB A72-3641 (HP IMPELLER)				ENG HRS 4200 eng	12/08/2014 4069.2		2454.2	3/22/2033 8269.2
		LH	SEE SB							
97		SB A72-3641 (HP IMPELLER)				ENG HRS 4200 eng	12/08/2014 4117.1		2450.7	3/18/2033 8317.1
		RH	SEE SB							
99	*	AD 2000-15-09 (HPC IMPELLER)				ENG HRS 4200 eng	12/08/2014 4069.2		2454.2	3/22/2033 8269.2
		LH	SEE AD							
99	*	AD 2000-15-09 (HPC IMPELLER)				ENG HRS 4200 eng	12/08/2014 4117.1		2450.7	3/18/2033 8317.1
		RH	SEE AD							
99		AD 2026-13-02 RADAR ALT INTERFER 5G				DATE 0 day				OVERDUE
99	*	AD 74-08-09 LAV FIRE PROTECTION				AF HRS 1000 hrs	6/22/2026 5962.1		1000.0	3/29/2029 6962.1
			SEE AD							

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
99		AD 2026-13-02 RADAR ALT INTERFER 5G					0 day				07/01/2026
21		EVAPORATOR BLOWERS	AFT	OVERHAUL	8/29/2001	0.0	2000 a/c	22.0	1979.0	21.0	07/24/2026
25	*	ELT BATTERY		REPLACE	8/01/2021	5342.9	5 yrs				08/01/2026
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	3/21/2025	5797.2	200 hrs	5997.2	164.9	35.1	08/07/2026
72	*	INSPECTION,ENGINE 300/400 HR	RH		3/12/2024	5603.4	300 eng	5903.4	263.0	37.0	08/09/2026
72	*	INSPECTION,ENGINE 300/400 HR	LH		2/29/2024	5557.0	300 eng	5857.0	258.0	42.0	08/14/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE	RH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP PRESSURE	LH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN	RH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP RETURN	LH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY	RH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
7110022G		HOSE ASSY,HYD ENGINE PUMP SUPPLY	LH	REPLACE	8/18/2021	5393.4	5 yrs				08/18/2026
2432010B	*	BATTERY INSTALLATION	#2	INSPECT	2/24/2026	5887.2	6 mos				08/24/2026
2432010B	*	BATTERY INSTALLATION	#1	INSPECT	2/24/2026	5887.2	6 mos				08/24/2026
1223010F	*	BATTERY,EMERGENCY	SECONDARY	OPS CHK	2/24/2026	5887.2	6 mos				08/24/2026
1223010F	*	BATTERY,EMERGENCY	PRIMARY	OPS CHK	2/24/2026	5887.2	6 mos				08/24/2026
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE	RH	INSPECT	2/24/2026	5887.2	6 mos				08/24/2026
2620042P	*	BOTTLE,ENGINE FIRE EXTIN PRESS GAGE	LH	INSPECT	2/24/2026	5887.2	6 mos				08/24/2026
1223015D	*	BATTERY,EMERGENCY	SECONDARY	DISCHG	8/29/2025	5848.7	12 mos				08/29/2026
1223015D	*	BATTERY,EMERGENCY	PRIMARY	DISCHG	8/29/2025	5848.7	12 mos				08/29/2026
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	8/29/2025	5848.7	12 mos				08/29/2026
26	*	SQUIB,ENGINE FIRE EXTINGUISHER	RH #2	REPLACE	9/01/2016	4669.7	10 yrs				09/01/2026
26	*	SQUIB,ENGINE FIRE EXTINGUISHER	RH #1	REPLACE	9/01/2016	4669.7	10 yrs				09/01/2026
26	*	SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	REPLACE	9/01/2016	4669.7	10 yrs				09/01/2026
26	*	SQUIB,ENGINE FIRE EXTINGUISHER	LH #1	REPLACE	9/01/2016	4669.7	10 yrs				09/01/2026
72	*	INSPECTION,ENGINE 150/250 HR	RH		2/17/2026	5779.4	150 eng	5929.4	87.0	63.0	09/04/2026
79	*	INSPECTION,ENGINE SOAP	RH		2/17/2026	5779.4	150 eng	5929.4	87.0	63.0	09/04/2026
72	*	INSPECTION,ENGINE 150/250 HR	LH		2/17/2026	5733.0	150 eng	5883.0	82.0	68.0	09/09/2026
79	*	INSPECTION,ENGINE SOAP	LH		2/17/2026	5733.0	150 eng	5883.0	82.0	68.0	09/09/2026
34	*	COMPUTER,AIR DATA	#2	CALIBRATE	9/24/2024	5764.8	24 mos				09/24/2026
34	*	COMPUTER,AIR DATA	#1	CALIBRATE	9/24/2024	5764.8	24 mos				09/24/2026
3411055P	*	PITOT STATIC PROBE PITCH/ROLL ALIGN		CHECK	9/24/2024	5764.8	24 mos				09/24/2026
5313002P	*	PITOT STATIC PROBE ZONE SKIN CONTOR		CHECK	9/24/2024	5764.8	24 mos				09/24/2026
34	*	RVSM			9/24/2024	5764.8	24 mos				09/24/2026
3411059K	*	RVSM (AIR DATA SYSTEM)		FUNC TEST	9/24/2024	5764.8	24 mos				09/24/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	STANDBY	CHECK	9/24/2024	5764.8	24 mos				09/24/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	RH	CHECK	9/24/2024	5764.8	24 mos				09/24/2026
34	*	STATIC SYSTEM LEAK (FAR91.411/413)	LH	CHECK	9/24/2024	5764.8	24 mos				09/24/2026
34	*	TRANSPONDER	#2	TEST	9/24/2024	5764.8	24 mos				09/24/2026
34	*	TRANSPONDER	#1	TEST	9/24/2024	5764.8	24 mos				09/24/2026
3500019R	*	BOTTLE,OXYGEN	TAIL	HYDRO	9/30/2021	5490.1	5 yrs				09/30/2026
78	*	INSPECTION,THRUST REV 150/200 HR	RH		5/12/2026	5923.9	150 hrs	6073.9	38.2	111.8	10/22/2026
78	*	INSPECTION,THRUST REV 150/200 HR	LH		5/12/2026	5923.9	150 hrs	6073.9	38.2	111.8	10/22/2026
21	*	REFRIGERANT HOSES CHAFING WEAR		INSPECT	6/14/2019	4874.2	1200 hrs	6074.2	1087.9	112.1	10/23/2026

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
78	*	INSPECTION, THRUST REV 300/400 HR	RH		3/21/2025	5797.2	300 hrs	6097.2	164.9	135.1	11/15/2026
78	*	INSPECTION, THRUST REV 300/400 HR	LH		3/21/2025	5797.2	300 hrs	6097.2	164.9	135.1	11/15/2026
24	*	BATTERY	#2	TEST	6/22/2026	5962.1	6 mos				12/22/2026
24	*	BATTERY	#1	TEST	6/22/2026	5962.1	6 mos				12/22/2026
3510021P		MASK, OXYGEN	PILOT	OVERHAUL	12/30/2020	5854.3	6 yrs				12/30/2026
2563001J	*	ELT TEST (91.207 D)		INSPECT	12/31/2025	5853.4	12 mos				12/31/2026
05	*	INSPECTION, AIRFRAME, PHASE A1 - A6			12/31/2025	5853.4	12 mos				12/31/2026
2431017H	*	BATTERY CABLES & RECEPTACLES	#2	INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
2431017H	*	BATTERY CABLES & RECEPTACLES	#1	INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	8/29/2025	5848.7	300 hrs	6148.7	113.4	186.6	01/05/2027
53		ZR LITE INSPECTION			2/04/2026	5878.4	300 hrs	6178.4	83.7	216.3	02/04/2027
2130007U	*	CABIN PRESSURIZATION LEAK RATE CHK			11/01/2019	4980.4	1200 hrs	6180.4	981.7	218.3	02/06/2027
53	*	RAISBECK AFT FUSELAGE STOW LOCKER		INSPECT	1/10/2023	5610.0	600 hrs	6210.0	352.1	247.9	03/07/2027
2812010L	*	3 ACCESS COVERS BTWN WS53, 92.0 RIB		INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
3414000K	*	ANTENNA, RADIO ALTIMETER		BOND CK	4/24/2025	5807.6	24 mos				04/24/2027
5210025L	*	CABIN DOOR STRUCTURE & HINGE AREA	EXT LWR	INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
5710145P	*	INBD DRY BAY ADJ FUSE/FWD SPAR 2		INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
2812002L	*	INNER WING STRUCTURE OTBD WS213.602		INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
2812020L	*	VALVE, WING FLAPPER	RH INBD	INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
2812020L	*	VALVE, WING FLAPPER	LH INBD	INSPECT	4/24/2025	5807.6	24 mos				04/24/2027
25	*	ELT RE-REGISTRATION			6/13/2025	5818.7	2 yrs				06/13/2027
34		EGPWS		SELF TEST	6/22/2026	5962.1	12 mos				06/22/2027
25	*	LIFE VEST		VISUAL	6/22/2026	5962.1	12 mos				06/22/2027
33	*	LOPRESTI BOOM BEAM		INSPECT	6/22/2026	5962.1	1 yrs				06/22/2027
25		RECORDER, COCKPIT VOICE		FUNC TEST	6/22/2026	5962.1	12 mos				06/22/2027
73	*	FILTER ELEMENT, FUEL	RH	REPLACE	3/12/2024	5603.4	650 eng	6253.4	263.0	387.0	07/25/2027
73	*	FILTER ELEMENT, FUEL	LH	REPLACE	2/29/2024	5557.0	650 eng	6207.0	258.0	392.0	07/30/2027
78	*	INSPECTION, THRUST REV 600/800 HR	RH		3/21/2025	5797.2	600 hrs	6397.2	164.9	435.1	09/11/2027
78	*	INSPECTION, THRUST REV 600/800 HR	LH		3/21/2025	5797.2	600 hrs	6397.2	164.9	435.1	09/11/2027
21	*	COMPRESSOR BELT TENSION WEAR		INSPECT	6/13/2025	5818.7	600 hrs	6418.7	143.4	456.6	10/02/2027
21	*	EVAPORATOR & CONDENSER COILS		INSPECT	6/13/2025	5818.7	600 hrs	6418.7	143.4	456.6	10/02/2027
21	*	AIR CONDITIONING SYSTEM COMPONENTS		INSPECT	8/15/2025	5843.8	600 hrs	6443.8	118.3	481.7	10/27/2027
2740021Q	*	ACTUATOR, HORIZONTAL STABILIZER		OVERHAUL	12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
05	*	INSPECTION, AIRFRAME, PHASE B1 - B6			12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
5610023G	*	WINDSHIELD LARASCOPE	RH		12/31/2025	5853.4	600 hrs	6453.4	108.7	491.3	11/06/2027
72	*	INSPECTION, ENGINE 600/800 HR	RH		3/12/2024	5603.4	800 eng	6403.4	263.0	537.0	12/22/2027
72	*	INSPECTION, ENGINE 600/800 HR	LH		2/29/2024	5557.0	800 eng	6357.0	258.0	542.0	12/27/2027
05	*	INSPECTION, AIRFRAME, PHASE B1 - B6			12/31/2025	5853.4	24 mos				12/31/2027
2431064U		BEARINGS, STARTER/GENERATOR	RH	REPLACE	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431064U		BEARINGS, STARTER/GENERATOR	LH	REPLACE	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431059U	*	BRUSH, STARTER GENERATOR	RH	INSPECT	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
2431059U	*	BRUSH, STARTER GENERATOR	LH	INSPECT	5/12/2026	5923.9	600 hrs	6523.9	38.2	561.8	01/15/2028
05		AIRCRAFT REGISTRATION			1/30/2021		7 yrs				01/30/2028
2565000F	*	BATTERY, UNDERWATER LOCATOR BEACON	CVR	INSPECT	3/18/2026	5898.7	2 yrs				03/18/2028

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
31		BATTERY, DAVTRON CLOCK	COPILOT	REPLACE	3/27/2026	5909.1	2 yrs				03/27/2028
31		BATTERY, DAVTRON CLOCK	PILOT	REPLACE	3/27/2026	5909.1	2 yrs				03/27/2028
79	*	OIL CHANGE, ENGINE	RH		11/04/2021	5342.0	1200 eng	6542.0	524.4	675.6	05/08/2028
3411063N	*	RVSM PITOT STATIC PROBES VISUAL		INSPECT	6/22/2026	5962.1	24 mos				06/22/2028
2750044H	*	BEARINGS, FLAP CAM FOLLOWER	LH/RH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	RH OTBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	RH INBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	LH OTBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
2750002E		BUSHING, FLAP NOSE ROLLER	LH INBD	REPLACE	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
5750046H	*	FITTINGS, FLAP TRACK SUPPORT	RH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
5750046H	*	FITTINGS, FLAP TRACK SUPPORT	LH	INSPECT	3/29/2023	5622.6	1200 hrs	6822.6	339.5	860.5	11/09/2028
26	*	BOTTLE, PORTABLE FIRE EXT INTERNAL	COCKPIT	CHECK	1/06/2023	5605.5	6 yrs				01/06/2029
26	*	BOTTLE, PORTABLE FIRE EXT INTERNAL	CABIN	CHECK	1/06/2023	5605.5	6 yrs				01/06/2029
79	*	OIL CHANGE, ENGINE	LH		2/29/2024	5557.0	1200 eng	6757.0	258.0	942.0	01/30/2029
2431011H		STARTER GENERATOR	RH	OVERHAUL	5/12/2026	5923.9	1000 hrs	6923.9	38.2	961.8	02/18/2029
2431011H		STARTER GENERATOR	LH	OVERHAUL	5/12/2026	5923.9	1000 hrs	6923.9	38.2	961.8	02/18/2029
2620025Q	*	BOTTLE, ENGINE FIRE EXTING (HYDRO)	LH	HYDRO	2/28/2024	5705.4	5 yrs				02/28/2029
99	*	AD 74-08-09 LAV FIRE PROTECTION			6/22/2026	5962.1	1000 hrs	6962.1	0.0	1000.0	03/29/2029
2150034K	*	MOTOR, A/C COMPRESSOR BRUSH WEAR		INSPECT	6/19/2018	1793.1	1200 a/c	1015.1	185.9	1014.1	04/12/2029
2561005p	*	LIFE VEST	COPILOT	RECERTIFY	4/30/2019	5744.4	10 yrs				04/30/2029
2561005p	*	LIFE VEST	PILOT	RECERTIFY	4/30/2019	5744.4	10 yrs				04/30/2029
78	*	INSPECTION, THRUST REV 1200/1400 HR	RH		3/21/2025	5797.2	1200 hrs	6997.2	164.9	1035.1	05/03/2029
78	*	INSPECTION, THRUST REV 1200/1400 HR	LH		3/21/2025	5797.2	1200 hrs	6997.2	164.9	1035.1	05/03/2029
05	*	INSPECTION, AIRFRAME, PHASE C1 - C6			12/31/2025	5853.4	1200 hrs	7053.4	108.7	1091.3	06/28/2029
2730036A	*	ELEVATOR BELLCRANKS		EDDY	7/02/2021	5335.9	96 mos				07/02/2029
2710036F	*	CABLE ASSY, AILERON CONTROL COLUMN	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON CONTROL COLUMN	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON FORWARD	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON FORWARD	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON SECTOR AFT		REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	RH OTBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	RH INBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	LH OTBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2710036F	*	CABLE ASSY, AILERON WING	LH INBD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	RH FWD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	RH AFT	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	LH FWD	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2730030F	*	CABLE ASSY, ELEVATOR	LH AFT	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2720013F		CABLE ASSY, RUDDER	RH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
2720013F		CABLE ASSY, RUDDER	LH	REPLACE	5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
78	*	INSPECTION, THRUST REV 2400 HR	RH		5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
78	*	INSPECTION, THRUST REV 2400 HR	LH		5/15/2017	4669.7	2400 hrs	7069.7	1292.4	1107.6	07/14/2029
72	*	INSPECTION, ENG 1000 - 1500 HR	RH		3/12/2024	5603.4	1400 eng	7003.4	263.0	1137.0	08/13/2029
72	*	INSPECTION, ENGINE COMB PLENUM CASE	RH	INSPECT	3/12/2024	5603.4	1400 eng	7003.4	263.0	1137.0	08/13/2029

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
72	*	INSPECTION,ENGINE MAJOR PERIODIC	RH		3/12/2024	5603.4	1400 eng	7003.4	263.0	1137.0	08/13/2029
97		SB 72-3494 (TURBINE BLADES)	RH		3/11/2024	5603.4	1400 eng	7003.4	263.0	1137.0	08/13/2029
72	*	INSPECTION,ENG 1000 - 1500 HR	LH		2/29/2024	5557.0	1400 eng	6957.0	258.0	1142.0	08/18/2029
72	*	INSPECTION,ENGINE COMB PLENUM CASE	LH	INSPECT	2/29/2024	5557.0	1400 eng	6957.0	258.0	1142.0	08/18/2029
72	*	INSPECTION,ENGINE MAJOR PERIODIC	LH		2/29/2024	5557.0	1400 eng	6957.0	258.0	1142.0	08/18/2029
97		SB 72-3494 (TURBINE BLADES)	LH		2/23/2024	5557.0	1400 eng	6957.0	258.0	1142.0	08/18/2029
7120067T	*	BOLT,AFT ENGINE ATTACH	LH	FLOUR PEN	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120067T	*	BOLT,AFT ENGINE ATTACH	RH	FLOUR PEN	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3020001U	*	BULKHEAD,ENGINE NACELLE INLET	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3020001U	*	BULKHEAD,ENGINE NACELLE INLET	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120024E	*	CASTING,ENGINE MOUNT	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120024E	*	CASTING,ENGINE MOUNT	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
3610045X	*	HIGH PRESS BLEED AIR HOSE/GASKET	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120063Q	*	MOUNT ISOLATOR,ENGINE (FWD/AFT)	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7120063Q	*	MOUNT ISOLATOR,ENGINE (FWD/AFT)	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7810005U	*	NOZZLES,ENGINE EXHAUST	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
7810005U	*	NOZZLES,ENGINE EXHAUST	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450045J	*	PYLON/ENGINE AFT BEAM STRUCTURE	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450043J	*	PYLON/ENGINE BEAM STRUCTURE	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
5450043J	*	PYLON/ENGINE BEAM STRUCTURE	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT	RH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2610020U	*	TAILCONE FIRE DETECTOR ELEMENT	LH	INSPECT	3/23/2024	5705.4	1400 hrs	7105.4	256.7	1143.3	08/19/2029
2710014E	*	BOLT,AILERON CENTER HINGE	RH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710014E	*	BOLT,AILERON CENTER HINGE	LH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710010E	*	BOLT,AILERON DRIVE YOKE	RH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2710010E	*	BOLT,AILERON DRIVE YOKE	LH	REPLACE	12/28/2012	3556.8	3600 hrs	7156.8	2405.3	1194.7	10/09/2029
2566000F		BATTERY,UNDERWATER LOCATOR BEACON	CVR	REPLACE	10/30/2023	5705.4	6 yrs				10/30/2029
3610006R	*	BOTTLE,EMERGENCY AIR		HYDRO/VIS	11/03/2023	5741.0	6 yrs				11/03/2029
05	*	INSPECTION,AIRFRAME,PHASE C1 - C6			12/31/2025	5853.4	48 mos				12/31/2029
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	RH	REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	LH	REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY,HYD NOSE GEAR RETRACT		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	1500 hrs	7315.4	146.7	1353.3	03/17/2030
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	REPLACE	3/23/2024	5705.4	6 yrs				03/23/2030
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	RH	REPLACE	5/05/2025	5815.4	5 yrs				05/05/2030
3210003G		HOSE ASSY,HYD MAIN GEAR DOOR RETRAC	LH	REPLACE	5/05/2025	5815.4	5 yrs				05/05/2030
3210003G		HOSE ASSY,HYD NOSE GEAR RETRACT		REPLACE	5/05/2025	5815.4	5 yrs				05/05/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	5 yrs				05/05/2030
3210003G		HOSE ASSY,NOSE GEAR EXTEND		REPLACE	5/05/2025	5815.4	5 yrs				05/05/2030
05	*	INSPECTION,AIRFRAME, 3000 LANDING			8/27/2013	2983	3000 ldg	5983	1538	1462	07/04/2030
05	*	INSPECTION,AIRFRAME,MAJOR LAND GEAR			8/29/2001	0	6000 ldg	6000	4521	1479	07/21/2030

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
3211102V		TORQUE LINK,MAIN LANDING GEAR	RH	REPLACE	8/29/2001	0	6000 ldg	6000	4521	1479	07/21/2030
3211102V		TORQUE LINK,MAIN LANDING GEAR	LH	REPLACE	8/29/2001	0	6000 ldg	6000	4521	1479	07/21/2030
2620025Q	*	BOTTLE,ENGINE FIRE EXTING (HYDRO)	RH	HYDRO	9/30/2025	5853.4	5 yrs				09/30/2030
7110021G		HOSE ASSY,FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
7110021G		HOSE ASSY,FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
7110021G		HOSE ASSY,FUEL SUPPLY	RH	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
7110021G		HOSE ASSY,FUEL SUPPLY	LH	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH INBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH OTBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH INBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH OUTBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH INBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH OTBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH INBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
3243040G		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH OUTBD	REPLACE	12/31/2025	5853.4	5 yrs				12/31/2030
2150035K	*	MOTOR,A/C COMPRESSOR DRIVE		OVERHAUL	6/19/2018	1793.1	2000 a/c	1815.1	185.9	1814.1	06/21/2031
3510021P		MASK,OXYGEN	COPILOT	OVERHAUL	10/16/2025	5887.2	6 yrs				10/16/2031
2620040V	*	SQUIB,ENGINE FIRE EXTINGUISHER(MFG)	LH #1	REPLACE	9/30/2023	5705.4	9 yrs				09/30/2032
2730033A	*	CONTROL COLUMN FLUORESCENT PEN		INSPECT	12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	10/10/2032
05	*	INSPECTION,AIRFRAME,PHASE D1 - D6			12/31/2025	5853.4	2400 hrs	8253.4	108.7	2291.3	10/10/2032
7120037L		BOND JOINT ISO ASSY,ENG AFT CENTER	RH AFT	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		BOND JOINT ISO ASSY,ENG AFT CENTER	LH AFT	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		ENG AFT ISOLATOR ASSY,HOUSING	RH	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120037L		ENG AFT ISOLATOR ASSY,HOUSING	LH	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT,MOUNT ASSY	RH UPPER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT,MOUNT ASSY	RH LOWER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT,MOUNT ASSY	LH UPPER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120065L		ENG FWD SHOCK MOUNT,MOUNT ASSY	LH LOWER	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT,HOUSING	RH UPR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT,HOUSING	RH LWR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT,HOUSING	LH UPR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
7120066L		ENG FWD SHOCK MOUNT,HOUSING	LH LWR	REPLACE	8/29/2001	0.0	8400 hrs	8400.0	5962.1	2437.9	03/05/2033
99	*	AD 2000-15-09 (HPC IMPELLER)	RH		12/08/2014	4117.1	4200 eng	8317.1	1749.3	2450.7	03/18/2033
72	*	INSPECTION,ENGINE ACCESSORY GEARBOX	RH		12/08/2014	4117.1	4200 eng	8317.1	1749.3	2450.7	03/18/2033
72	*	INSPECTION,ENGINE COMPRESSOR ZONE	RH		12/08/2014	4117.1	4200 eng	8317.1	1749.3	2450.7	03/18/2033
72	*	INSPECTION,ENGINE FAN SUPPORT ASSY	RH		12/08/2014	4117.1	4200 eng	8317.1	1749.3	2450.7	03/18/2033
97		SB A72-3641 (HP IMPELLER)	RH		12/08/2014	4117.1	4200 eng	8317.1	1749.3	2450.7	03/18/2033
99	*	AD 2000-15-09 (HPC IMPELLER)	LH		12/08/2014	4069.2	4200 eng	8269.2	1745.8	2454.2	03/22/2033
72	*	INSPECTION,ENGINE ACCESSORY GEARBOX	LH		12/08/2014	4069.2	4200 eng	8269.2	1745.8	2454.2	03/22/2033
72	*	INSPECTION,ENGINE COMPRESSOR ZONE	LH		12/08/2014	4069.2	4200 eng	8269.2	1745.8	2454.2	03/22/2033
72	*	INSPECTION,ENGINE FAN SUPPORT ASSY	LH		12/08/2014	4069.2	4200 eng	8269.2	1745.8	2454.2	03/22/2033
97		SB A72-3641 (HP IMPELLER)	LH		12/08/2014	4069.2	4200 eng	8269.2	1745.8	2454.2	03/22/2033
7120036K		ENG FWD SHOCK MOUNT,COVER	RH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT,COVER	RH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
7120036K		ENG FWD SHOCK MOUNT,COVER	LH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120036K		ENG FWD SHOCK MOUNT,COVER	LH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT,BOLTS	RH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT,BOLTS	RH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT,BOLTS	LH UPPER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
7120064K		ENG FWD SHOCK MOUNT,BOLTS	LH LOWER	REPLACE	1/02/2015	4217.8	4200 hrs	8417.8	1744.3	2455.7	03/23/2033
05	*	INSPECTION,AIRFRAME,PHASE D1 - D6			12/31/2025	5853.4	96 mos				12/31/2033
3610056R	*	BOTTLE,EMERGENCY AIR		SCRAP	1/01/1994	5741.0	40 yrs				01/01/2034
2561005p	*	LIFE VEST	#7	RECERTIFY	2/28/2024	5705.4	10 yrs				02/28/2034
2561005p	*	LIFE VEST	#6	RECERTIFY	2/28/2024	5705.4	10 yrs				02/28/2034
2561005p	*	LIFE VEST	#5	RECERTIFY	2/28/2024	5705.4	10 yrs				02/28/2034
2561005p	*	LIFE VEST	#2	RECERTIFY	2/28/2024	5705.4	10 yrs				02/28/2034
2561005p	*	LIFE VEST	#4	RECERTIFY	5/31/2024	5744.4	10 yrs				05/31/2034
2561005p	*	LIFE VEST	#3	RECERTIFY	5/31/2024	5744.4	10 yrs				05/31/2034
2561005p	*	LIFE VEST	#1	RECERTIFY	5/31/2024	5744.4	10 yrs				05/31/2034
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER	COCKPIT	HYDRO	1/06/2023	5605.5	12 yrs				01/06/2035
2620030C	*	BOTTLE,PORTABLE FIRE EXTINGUISHER	CABIN	HYDRO	1/06/2023	5605.5	12 yrs				01/06/2035
72	*	DISC,LP 1ST STAGE TURBINE ROTOR	RH	REPLACE	12/08/2014	3302	4400 cyc	7702	1230	3170	03/08/2035
3500051R	*	BOTTLE,OXYGEN	TAIL	REPLACE	9/30/2021	5490.1	15 yrs				09/30/2036
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	RH	DYE PEN	9/30/2025	5853.4	12 yrs				09/30/2037
7120033E	*	ENGINE MOUNT FWD MOUNT CASTING BOLT	LH	DYE PEN	9/30/2025	5853.4	12 yrs				09/30/2037
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	RH		9/30/2025	5853.4	12 yrs				09/30/2037
7120028E	*	ENGINE MOUNT MAGNETIC PARTICLE INSP	LH		9/30/2025	5853.4	12 yrs				09/30/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2750034G		BOLT,FLAP SECTOR MOUNTING	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	UPPER	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2740011G	*	BOLT,HORIZONTAL STAB ACT ATTACH	LOWER	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760082E	*	BOLT,SPOILER ACTUATOR 1/4"	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760080E	*	BOLT,SPOILER ATTACH 5/16"	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2760081E	*	BOLT,SPOILER PIVOT 5/16"	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
5322000T		BOLTS,KEELBEAM ATTACHMENT			12/31/2025	5853.4	12 yrs				12/31/2037
5210104U	*	BOLTS,UPPER DOOR TORSION BAR		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 3	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2431058E		CIRCUIT BREAKER,DC BUS 3	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2431058E		CIRCUIT BREAKER,DC BUS 2	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2431057E		CIRCUIT BREAKER,DC BUS 2	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	RH	EDDY CURR	12/31/2025	5853.4	12 yrs				12/31/2037
5450044H	*	ENGINE BEAM SUPPORT FITTINGS	LH	EDDY CURR	12/31/2025	5853.4	12 yrs				12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
3233003G		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
3233003G		HOSE ASSY,EMERG AIR NOSE GEAR ACT		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
3233003G		HOSE ASSY, EMERGENCY BRAKE		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, FLAP EXTEND	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, FLAP EXTEND	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL INTERCONNECT		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL SUPPLY	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL TRANSFER	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL TRANSFER	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUEL TRANSFER		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, FUSELAGE FUEL TRANSFER	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD ENGINE PUMP SUPPLY	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD ENGINE PUMP PRESSURE	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD FLAP RETRACT	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD FLAP RETRACT	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD HORIZ STAB		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD PRESSURE	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYD PRESSURE		REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYDRAULIC SUPPLY	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, HYDRAULIC SUPPLY	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, SPOILER EXTEND	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, SPOILER EXTEND	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, SPOILER RETRACT	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2900001G		HOSE ASSY, SPOILER RETRACT	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW	RH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW	RT	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
2820002G		HOSE ASSY, WING PUMP MOTIVE FLOW	LH	REPLACE	12/31/2025	5853.4	12 yrs				12/31/2037
05	*	INSPECTION, AIRFRAME, 12 YEAR			12/31/2025	5853.4	12 yrs				12/31/2037
5331013X	*	SKIN, UPPER FUSELAGE UNDER OXY LINE		INSPECT	12/31/2025	5853.4	12 yrs				12/31/2037
72	*	DISC, LP 1ST STAGE TURBINE ROTOR	LH	REPLACE	2/29/2024	4154	4400 cyc	8554	175	4225	01/26/2038
72	*	DISC, LP 2ND STAGE TURBINE ROTOR	RH	REPLACE	3/12/2024	4357	4500 cyc	8857	175	4325	05/06/2038
72	*	DISC, LP 2ND STAGE TURBINE ROTOR	LH	REPLACE	2/29/2024	4154	4500 cyc	8654	175	4325	05/06/2038
72	*	DISC, LP 3RD STAGE TURBINE ROTOR	RH	REPLACE	7/03/2001	0	9500 cyc	9500	4532	4968	02/08/2040
72	*	ROTOR, HP TURBINE WHEEL	RH	REPLACE	3/12/2024	4357	5200 cyc	9557	175	5025	04/05/2040
72	*	ROTOR, HP TURBINE WHEEL	LH	REPLACE	2/29/2024	4154	5200 cyc	9354	175	5025	04/05/2040
72	*	DISC, LP 3RD STAGE TURBINE ROTOR	LH	REPLACE	7/06/2001	0	9500 cyc	9500	4329	5171	08/29/2040

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
72	*	DISC AND HUB,FAN ROTOR	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	DISC,LP 1ST STAGE AXIAL COMPRESSOR	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	DISC,LP 2ND STAGE AXIAL COMPRESSOR	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	DISC,LP 3RD STAGE AXIAL COMPRESSOR	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	DISC,LP 4TH STAGE AXIAL COMPRESSOR	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	IMPELLER,HP COMPRESSOR RADIAL	RH	REPLACE	7/03/2001	0	10000 cyc	10000	4532	5468	06/22/2041
72	*	DISC AND HUB,FAN ROTOR	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
72	*	DISC,LP 1ST STAGE AXIAL COMPRESSOR	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
72	*	DISC,LP 2ND STAGE AXIAL COMPRESSOR	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
72	*	DISC,LP 3RD STAGE AXIAL COMPRESSOR	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
72	*	DISC,LP 4TH STAGE AXIAL COMPRESSOR	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
72	*	IMPELLER,HP COMPRESSOR RADIAL	LH	REPLACE	7/06/2001	0	10000 cyc	10000	4329	5671	01/11/2042
2750012E	*	FLAP TRACK ASSEMBLY	RH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	RH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	LT OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750012E	*	FLAP TRACK ASSEMBLY	LH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
05	*	INSPECTION,AIRFRAME,12000 HOUR			8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750011E	*	TRACK,FLAP NOSE ROLLER	RH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750010E	*	TRACK,FLAP NOSE ROLLER	RH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750011E	*	TRACK,FLAP NOSE ROLLER	LH OUTBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
2750010E	*	TRACK,FLAP NOSE ROLLER	LH INBD	REPLACE	8/29/2001	0.0	12000 hrs	12000.0	5962.1	6037.9	01/12/2043
3211078E	*	PIN,MAIN GEAR ATTACH	RH	REPLACE	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
3211078E	*	PIN,MAIN GEAR ATTACH	LH	REPLACE	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
7830090S	*	RING,T/R AFT BODY MATING FLANGE	RH	FLUOR PEN	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
7830090S	*	RING,T/R AFT BODY MATING FLANGE	LH	FLUOR PEN	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
3211075F	*	STRUT ASSEMBLY,MAIN GEAR	RH	REPLACE	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
3211075F	*	STRUT ASSEMBLY,MAIN GEAR	LH	REPLACE	8/29/2001	0	12000 ldg	12000	4521	7479	12/24/2046
2750014E	*	HINGE FITTING,FLAP TRACK	RH OUTBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750013E	*	HINGE FITTING,FLAP TRACK	RH INBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750014E	*	HINGE FITTING,FLAP TRACK	LH OUTBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
2750013E	*	HINGE FITTING,FLAP TRACK	LH INBD	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
3411057J	*	PROBE,PRIMARY PITOT STATIC	RH	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
3411056J	*	PROBE,PRIMARY PITOT STATIC	LH	REPLACE	8/29/2001	0.0	15000 hrs	15000.0	5962.1	9037.9	03/31/2051
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR	RH	REPLACE	8/29/2001	0	18000 ldg	18000	4521	13479	05/29/2063
3211080E	*	PILLAR ASSEMBLY, MAIN GEAR	LH	REPLACE	8/29/2001	0	18000 ldg	18000	4521	13479	05/29/2063
2710016G	*	AILERON ASSEMBLY	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710016G		AILERON ASSEMBLY	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720023E	*	BEARING BLOCK ASSY,RUDDER LOWER		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710028E	*	BEARING SUPPORT ASSEMBLY,AILERON	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710028E	*	BEARING SUPPORT ASSEMBLY,AILERON	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730021E	*	BELLCRANK ASSEMBLY,ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730021E	*	BELLCRANK ASSEMBLY,ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710020E	*	BOLT,AILERON CLEVIS	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710020E	*	BOLT,AILERON CLEVIS	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026
N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
2730024E	*	BOLT,ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT,ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT,ELEVATOR HINGE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT,ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT,ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730024E	*	BOLT,ELEVATOR HINGE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120041E	*	BOLT,ENGINE AFT SHOCK MOUNT ATTACH	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120041E	*	BOLT,ENGINE AFT SHOCK MOUNT ATTACH	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120038E	*	BOLT,ENGINE FWD MOUNT ATTACH	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT SUPPORT	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT	RH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT	RH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT	LH UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
7120040V	*	BOLT,ENGINE FWD SHOCK MOUNT	LH LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT,RUDDER HINGE	UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT,RUDDER HINGE	LOWER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720021E	*	BOLT,RUDDER HINGE	CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS,AILERON HINGE	RH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS,AILERON HINGE	RH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS,AILERON HINGE	LH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710021M	*	BOLTS,AILERON HINGE	LH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710024E	*	CLEVIS,AILERON DRIVE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710024E	*	CLEVIS,AILERON DRIVE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730016E	*	ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730016E	*	ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710031E	*	HINGE BRACKET ON WING,AILERON	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710031E	*	HINGE BRACKET ON WING,AILERON	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720024E	*	HINGE INSTALLATION,RUDDER	UPPER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720025E	*	HINGE INSTALLATION,RUDDER	CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2740010E	*	HINGE PIN,HORIZONTAL STABILIZER		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	RH CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH OTBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH INBD	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730020E	*	HINGE,ELEVATOR	LH CENTER	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064

LONG RANGE PROJECTION REPORT

LEARJET 31232

7/03/2026

N68VP

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710023E	*	PULLEY ASSEMBLY,AILERON DRIVE	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730023E	*	PUSH PULL TUBE ASSEMBLY,ELEVATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2730023E	*	PUSH PULL TUBE ASSEMBLY,ELEVATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2720018E	*	RUDDER ASSEMBLY		REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710026E	*	YOKE ASSEMBLY,AILERON ACTUATOR	RH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
2710026E	*	YOKE ASSEMBLY,AILERON ACTUATOR	LH	REPLACE	8/29/2001	0.0	20000 hrs	20000.0	5962.1	14037.9	12/07/2064
3211087E	*	ACTUATOR ASSEMBLY,MAIN GEAR	RH	REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
3211087E	*	ACTUATOR ASSEMBLY,MAIN GEAR	LH	REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
3211083E	*	ACTUATOR ASSEMBLY,NOSE GEAR		REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
3211084E	*	PIN,MAIN GEAR ACTUATOR ATTACH	RH	REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
3211084E	*	PIN,MAIN GEAR ACTUATOR ATTACH	LH	REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
3211082E	*	STRUT ASSEMBLY,NOSE GEAR		REPLACE	8/29/2001	0	20000 ldg	20000	4521	15479	11/18/2068
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	RH	REPLACE	8/27/2013	3790.0	20000 hrs	23790.0	2172.1	17827.9	04/24/2075
7120039E	*	BOLT,ENGINE AFT MOUNT ATTACH	LH	REPLACE	8/27/2013	3790.0	20000 hrs	23790.0	2172.1	17827.9	04/24/2075
25		RECORDER,COCKPIT VOICE		MTBF	8/29/2001	0.0	30000 hrs	30000.0	5962.1	24037.9	04/24/2092

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
21		MOTOR, A/C COMPRESSOR DRIVE		ES61134-3	143	6/19/2018	1793.1 a/c	1978.0	185.9
21		COMPRESSOR ASSEMBLY, AIR CONDITIONER		JBS222-1	JBS2221-228	1/23/2003	233.3 hrs	0.0	5728.8
21		COMPRESSOR, FREON		JBS222-1	K51797	3/17/2011	2360 ldg	0	2161
21		COMPRESSOR, FREON		JBS222-1	K51797	3/17/2011	2932.1 hrs	0.0	3030.0
21		GARRETT MODULE ASSEMBLY		2614062-23	11-1173 REPAIR	12/31/2025	4454 ldg	0	67
21		GARRETT MODULE ASSEMBLY		2614062-23	11-1173 REPAIR	12/31/2025	5853.4 hrs	0.0	108.7
21		METER, AIR CONDITIONER HOBBS		102033-D		4/18/2022	0.0 a/c	0.0	1.0
21		MODULE ASSEMBLY, CABIN PRESSURE		2614062-23	11-1173	4/12/2002	61.7 hrs	0.0	5900.4
21		MOTOR, AIR CONDITIONER COMPRESSOR		31-0550-1	3105501-018 REPAIR	4/12/2002	61.7 hrs		5900.4
21		SENSOR, DUCT TEMPERATURE		6600211-37	8561	5/15/2017	3601 ldg	0	920
21		SENSOR, DUCT TEMPERATURE		6600211-37	8561	5/15/2017	4669.7 hrs	0.0	1292.4
21		SENSOR, TEMPERATURE	LH	6600213-3	306534	5/15/2017	3601 ldg	0	920
21		SENSOR, TEMPERATURE	LH	6600213-3	306534	5/15/2017	4669.7 hrs	0.0	1292.4
21		SENSOR, TEMPERATURE	RH	6600213-3	329051	12/31/2025	4454 ldg	0	67
21		SENSOR, TEMPERATURE	RH	6600213-3	329051	12/31/2025	5853.4 hrs	0.0	108.7
21		SWITCH, CABIN UNDER PRESSURE ANEROID	LH	E45C-47	5330	2/12/2010	2060 ldg	0	2461
21		SWITCH, CABIN UNDER PRESSURE ANEROID	LH	E45C-47	5330	2/12/2010	2540.5 hrs	0.0	3421.6
21		SWITCH, CABIN UNDER PRESSURE ANEROID	RH	E45C-47	6428	12/31/2025	4454 ldg	0	67
21		SWITCH, CABIN UNDER PRESSURE ANEROID	RH	E45C-47	6428	12/31/2025	5853.4 hrs	0.0	108.7
21		VALVE, EMERGENCY PRESSURIZATION	RH	2619500-10	11AL18	8/08/2012	2711 ldg	0	1810
21		VALVE, EMERGENCY PRESSURIZATION	RH	2619500-10	11AL18	8/08/2012	3394.5 hrs	0.0	2567.6
22		ADAPTER, TRIM		065-5046-01	1229	1/16/2026	4455 ldg	0	66
22		ADAPTER, TRIM		065-5046-01	1229	1/16/2026	5895.3 hrs	0.0	66.8
22		COMPUTER, AUTOPILOT		065-0069-17	2365	1/21/2004	519.6 hrs	0.0	5442.5
22		COMPUTER, MACH TRIM		501-1132-05	1788	5/13/2022	4195 ldg	0	326
22		COMPUTER, MACH TRIM		501-1132-05	1788	5/13/2022	5502.2 hrs	0.0	459.9
22		CONTROLLER, AUTOPILOT		065-00154-0101	1332	8/28/2013	3791.2 hrs	0.0	2170.9
22		SERVO ASSEMBLY, PITCH (DC TORQUER)		065-0076-12	2662	5/10/2002	73.9 hrs	0.0	5888.2
23		AUDIO HEAD	COPILOTS	11210-2	124	9/01/2015	3369 ldg	0	1152
23		AUDIO HEAD	COPILOTS	11210-2	124	9/01/2015	4363.9 hrs	0.0	1598.2
23		AUDIO HEAD	PILOTS	11209-2	162	2/06/2002	23.0 hrs	0.0	5939.1
23		CONTROL HEAD, VHF	PRIMARY	071-1341-07	5937 TESTED	3/24/2015	3281 ldg	0	1240
23		CONTROL HEAD, VHF	PRIMARY	071-1341-07	5937 TESTED	3/24/2015	4236.9 hrs	0.0	1725.2
23		TRANSCEIVER, VHF	PRIMARY	064-1047-02	20256 LOANER	7/05/2019	4914.8 hrs	0.0	1047.3
24		STARTER GENERATOR	LH	23080-023A	Y10807	5/12/2026	5923.9 hrs	0.0	38.2
24		STARTER GENERATOR	RH	23080-023A	Y10294	5/12/2026	5923.9 hrs	0.0	38.2
24		BEARINGS, STARTER/GENERATOR	LH	23080-023A	Y10807	5/12/2026	5923.9 hrs	0.0	38.2
24		BEARINGS, STARTER/GENERATOR	RH	23080-023A	Y10294	5/12/2026	5923.9 hrs	0.0	38.2
24		BATTERY	#1	GE381E	G03207744	4/04/2024	4348 ldg	0	173
24		BATTERY	#1	GE381E	G03207744	4/04/2024	5706.1 hrs	0.0	256.0
24		BATTERY	#2	GE381E	G03207742	4/04/2024	4348 ldg	0	173
24		BATTERY	#2	GE381E	G03207742	4/04/2024	5706.1 hrs	0.0	256.0
24		BATTERY, EMERGENCY	PRIMARY	501-1712-02	3211	6/30/2023	4318 ldg	0	203
24		BATTERY, EMERGENCY	PRIMARY	501-1712-02	3211	6/30/2023	5660.9 hrs	0.0	301.2

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
24		BATTERY, EMERGENCY	SECONDARY	501-1712-02	81952	6/30/2023	4318 ldg	0	203
24		BATTERY, EMERGENCY	SECONDARY	501-1712-02	81952	6/30/2023	5660.9 hrs	0.0	301.2
24		CIRCUIT BREAKER, DC BUS 2	LH	700-070-40	N/A	12/31/2025	5853.4 hrs	0.0	108.7
24		CIRCUIT BREAKER, DC BUS 2	RH	700-070-40	N/A	12/31/2025	5853.4 hrs	0.0	108.7
24		CIRCUIT BREAKER, DC BUS 3	LH	700-070-40	N/A	12/31/2025	5853.4 hrs	0.0	108.7
24		CIRCUIT BREAKER, DC BUS 3	RH	700-070-40	N/A	12/31/2025	5853.4 hrs	0.0	108.7
24		DISPLAY, ELECTRIC	#1	066-03137-3300	2980 SVCBLE	3/27/2026	4483 ldg	0	38
24		DISPLAY, ELECTRIC	#1	066-03137-3300	2980 SVCBLE	3/27/2026	5909.1 hrs	0.0	53.0
24		INDICATOR, DC VOLTMETER		N5329051	80940	9/26/2007	1698.7 hrs	0.0	4263.4
25		RECORDER, COCKPIT VOICE		UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
25		AIRCRAFT PAINT	#1	MATTERHORN WHITE	IL050	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#2	GAMMA GRAY	I2014	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#3	GLOSS BLACK	B701	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#4	LIGHT PLUM	IM411	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#5	LIGHT VIOLET	IM617	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#6	PANTONE COLOR	215, P215	2/06/2002	23.0 hrs	0.0	5939.1
25		AIRCRAFT PAINT	#7	DARK ROSE GRAY	IM202	2/06/2002	23.0 hrs	0.0	5939.1
25		BATTERY, UNDERWATER LOCATOR BEACON	CVR	DK120	NT62067	10/30/2023	4347 ldg	0	174
25		BATTERY, UNDERWATER LOCATOR BEACON	CVR	DK120	NT62067	10/30/2023	5705.4 hrs	0.0	256.7
25		ELT BATTERY		452-0133	391140-018	8/01/2021	4088 ldg	0	433
25		ELT BATTERY		452-0133	391140-018	8/01/2021	5342.9 hrs	0.0	619.2
25		LIFE VEST	#1	PO1074-201	24040480020	5/31/2024	4372 ldg	0	149
25		LIFE VEST	#1	PO1074-201	24040480020	5/31/2024	5744.4 hrs	0.0	217.7
25		LIFE VEST	#2	PO1074-201	24022500004	2/28/2024	4347 ldg	0	174
25		LIFE VEST	#2	PO1074-201	24022500004	2/28/2024	5705.4 hrs	0.0	256.7
25		LIFE VEST	#3	PO1074-201	24052280001	5/31/2024	4372 ldg	0	149
25		LIFE VEST	#3	PO1074-201	24052280001	5/31/2024	5744.4 hrs	0.0	217.7
25		LIFE VEST	#4	PO1074-201	24052280005	5/31/2024	4372 ldg	0	149
25		LIFE VEST	#4	PO1074-201	24052280005	5/31/2024	5744.4 hrs	0.0	217.7
25		LIFE VEST	#5	PO1074-201	24052280006	2/28/2024	4347 ldg	0	174
25		LIFE VEST	#5	PO1074-201	24052280006	2/28/2024	5705.4 hrs	0.0	256.7
25		LIFE VEST	#6	PO1074-201	24052280019	2/28/2024	4347 ldg	0	174
25		LIFE VEST	#6	PO1074-201	24052280019	2/28/2024	5705.4 hrs	0.0	256.7
25		LIFE VEST	#7	PO1074-201	24052280002	2/28/2024	4347 ldg	0	174
25		LIFE VEST	#7	PO1074-201	24052280002	2/28/2024	5705.4 hrs	0.0	256.7
25		LIFE VEST	COPILOT	PO1074-101C	24040480015	4/30/2019	4372 ldg	0	149
25		LIFE VEST	COPILOT	PO1074-101C	24040480015	4/30/2019	5744.4 hrs	0.0	217.7
25		LIFE VEST	PILOT	PO1074-101C	28040480019	4/30/2019	4372 ldg	0	149
25		LIFE VEST	PILOT	PO1074-101C	28040480019	4/30/2019	5744.4 hrs	0.0	217.7
26		BOTTLE, ENGINE FIRE EXTING (HYDRO)	LH	30402102-1	B12566	2/28/2024	4347 ldg	0	174
26		BOTTLE, ENGINE FIRE EXTING (HYDRO)	LH	30402102-1	B12566	2/28/2024	5705.4 hrs	0.0	256.7
26		BOTTLE, ENGINE FIRE EXTING (HYDRO)	RH	30402102-1	B13615	9/30/2025	4454 ldg	0	67
26		BOTTLE, ENGINE FIRE EXTING (HYDRO)	RH	30402102-1	B13615	9/30/2025	5853.4 hrs	0.0	108.7
26		BOTTLE, ENGINE FIRE EXTING (INSTALL)	LH	30402102-1	B12566	9/23/2015	3369 ldg	0	1152

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
26		BOTTLE,ENGINE FIRE EXTING (INSTALL)	LH	30402102-1	B12566	9/23/2015	4363.9 hrs	0.0	1598.2
26		BOTTLE,ENGINE FIRE EXTING (INSTALL)	RH	30402102-1	B13615	9/23/2015	3369 ldg	0	1152
26		BOTTLE,ENGINE FIRE EXTING (INSTALL)	RH	30402102-1	B13615	9/23/2015	4363.9 hrs	0.0	1598.2
26		BOTTLE,PORTABLE FIRE EXTINGUISHER	CABIN	A344	B-74105163	1/06/2023	4281 ldg	0	240
26		BOTTLE,PORTABLE FIRE EXTINGUISHER	CABIN	A344	B-74105163	1/06/2023	5605.5 hrs	0.0	356.6
26		BOTTLE,PORTABLE FIRE EXTINGUISHER	COCKPIT	A344	B-74105157	1/06/2023	4281 ldg	0	240
26		BOTTLE,PORTABLE FIRE EXTINGUISHER	COCKPIT	A344	B-74105157	1/06/2023	5605.5 hrs	0.0	356.6
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #1	AE30903823	N/A	9/01/2016	3601 ldg	0	920
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #1	AE30903823	N/A	9/01/2016	4669.7 hrs	0.0	1292.4
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	AE30903823	N/A	9/01/2016	3601 ldg	0	920
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	13083-5	ESD23J943-001	3/23/2024	4347 ldg	0	174
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	AE30903823	N/A	9/01/2016	4669.7 hrs	0.0	1292.4
26		SQUIB,ENGINE FIRE EXTINGUISHER	LH #2	13083-5	ESD23J943-001	3/23/2024	5705.4 hrs	0.0	256.7
26		SQUIB,ENGINE FIRE EXTINGUISHER	RH #1	AE30903823	N/A	9/01/2016	3601 ldg	0	920
26		SQUIB,ENGINE FIRE EXTINGUISHER	RH #1	AE30903823	N/A	9/01/2016	4669.7 hrs	0.0	1292.4
26		SQUIB,ENGINE FIRE EXTINGUISHER	RH #2	AE30903823	N/A	9/01/2016	3601 ldg	0	920
26		SQUIB,ENGINE FIRE EXTINGUISHER	RH #2	AE30903823	N/A	9/01/2016	4669.7 hrs	0.0	1292.4
26		SQUIB,ENGINE FIRE EXTINGUISHER (MFG)	LH #1	13083-5	ESD23J943-001	9/30/2023	4347 ldg	0	174
26		SQUIB,ENGINE FIRE EXTINGUISHER (MFG)	LH #1	13083-5	ESD23J943-001	9/30/2023	5705.4 hrs	0.0	256.7
27		BOLT,AILERON DRIVE YOKE	LH	NAS1104-38D	UNKNOWN	12/28/2012	3556.8 hrs	0.0	2405.3
27		BOLT,AILERON DRIVE YOKE	RH	NAS1104-38D	UNKNOWN	12/28/2012	3556.8 hrs	0.0	2405.3
27		BOLT,AILERON CENTER HINGE	LH	AN4H13A	UNKNOWN	12/28/2012	3556.8 hrs	0.0	2405.3
27		BOLT,AILERON CENTER HINGE	RH	AN4H13A	UNKNOWN	12/28/2012	3556.8 hrs	0.0	2405.3
27		AILERON ASSEMBLY	LH	2424000-803	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		AILERON ASSEMBLY	RH	2424000-802	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT,AILERON CLEVIS	LH	NAS464P4-12	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT,AILERON CLEVIS	RH	NAS464P4-12	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLTS,AILERON HINGE	LH INBD	AN4H12A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLTS,AILERON HINGE	LH OTBD	AN4H12A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLTS,AILERON HINGE	RH INBD	AN4H12A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLTS,AILERON HINGE	RH OTBD	AN4H12A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		PULLEY ASSEMBLY,AILERON DRIVE	LH	2324513-17	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		PULLEY ASSEMBLY,AILERON DRIVE	RH	2324513-18	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		CLEVIS,AILERON DRIVE	LH	2324517-3	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		CLEVIS,AILERON DRIVE	RH	2324517-3	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		YOKE ASSEMBLY,AILERON ACTUATOR	LH	2324511-5	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		YOKE ASSEMBLY,AILERON ACTUATOR	RH	2324511-5	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BEARING SUPPORT ASSEMBLY,AILERON	LH	5425016-5	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BEARING SUPPORT ASSEMBLY,AILERON	RH	5425016-5	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE BRACKET ON WING,AILERON	LH	2322530	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE BRACKET ON WING,AILERON	RH	2322530	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		CABLE ASSY,AILERON CONTROL COLUMN	LH	2300003-231	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON CONTROL COLUMN	RH	2300003-229	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON FORWARD	LH	2300003-245	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
27		CABLE ASSY,AILERON FORWARD	RH	2300003-246	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON SECTOR AFT		2300003-17	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON WING	LH INBD	5405015-31	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON WING	LH OTBD	5405015-29	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON WING	RH INBD	5405015-31	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY,AILERON WING	RH OTBD	5405015-29	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY, RUDDER	LH	2300003-243	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY, RUDDER	RH	2300003-243	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		RUDDER ASSEMBLY		UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, RUDDER HINGE	CENTER	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, RUDDER HINGE	LOWER	NAS144A23	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, RUDDER HINGE	UPPER	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BEARING BLOCK ASSY, RUDDER LOWER		2312040	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE INSTALLATION, RUDDER	UPPER	2331030	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE INSTALLATION, RUDDER	CENTER	2331031	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		ELEVATOR	LH	2434000	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		ELEVATOR	RH	2434000	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	LH CENTER	2332018	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	LH INBD	2332019	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	LH OTBD	2332013	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	RH CENTER	2332018	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	RH INBD	2332019	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE, ELEVATOR	RH OTBD	2332013	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BELLCRANK ASSEMBLY, ELEVATOR	LH	2331511	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BELLCRANK ASSEMBLY, ELEVATOR	RH	2331511	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		PUSH PULL TUBE ASSEMBLY, ELEVATOR	LH	2331510	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		PUSH PULL TUBE ASSEMBLY, ELEVATOR	RH	2331510	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	LH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	LH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	LH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	RH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	RH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	RH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		BOLT, ELEVATOR HINGE	RH	AN4H11A	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		CABLE ASSY, ELEVATOR	LH AFT	2300003-171	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY, ELEVATOR	LH FWD	2300003-240	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY, ELEVATOR	RH AFT	2300003-172	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		CABLE ASSY, ELEVATOR	RH FWD	2300003-239	UNKNOWN	5/15/2017	4669.7 hrs	0.0	1292.4
27		HINGE PIN, HORIZONTAL STABILIZER		2331028-5	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		ACTUATOR, HORIZONTAL STABILIZER		3135540-014	215	12/31/2025	5853.4 hrs	0.0	108.7
27		BUSHING, FLAP NOSE ROLLER	LH INBD	NAS76A4-018	N/A	3/29/2023	5622.6 hrs	0.0	339.5
27		BUSHING, FLAP NOSE ROLLER	LH OTBD	NAS76A4-020	N/A	3/29/2023	5622.6 hrs	0.0	339.5
27		BUSHING, FLAP NOSE ROLLER	RH INBD	NAS76A4-018	N/A	3/29/2023	5622.6 hrs	0.0	339.5
27		BUSHING, FLAP NOSE ROLLER	RH OTBD	NAS76A4-020	N/A	3/29/2023	5622.6 hrs	0.0	339.5
27		TRACK, FLAP NOSE ROLLER	LH INBD	2322511-57	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
27		TRACK, FLAP NOSE ROLLER	RH INBD	2322511-57	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		TRACK, FLAP NOSE ROLLER	LH OUTBD	2322512-37	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		TRACK, FLAP NOSE ROLLER	RH OUTBD	2322512-37	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		FLAP TRACK ASSEMBLY	LH INBD	2325022-16	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		FLAP TRACK ASSEMBLY	LT OUTBD	2325022-15	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		FLAP TRACK ASSEMBLY	RH INBD	2325022-16	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		FLAP TRACK ASSEMBLY	RH OUTBD	2325022-15	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE FITTING, FLAP TRACK	LH INBD	2625023	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE FITTING, FLAP TRACK	RH INBD	2625023	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE FITTING, FLAP TRACK	LH OUTBD	2625024	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27		HINGE FITTING, FLAP TRACK	RH OUTBD	2625024	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
27	#	FLAP NOSE ROLLER SUPPORT ARM		N/A BY S/N		8/29/2001	0 ldg	0	4521
27		ACTUATOR, HORIZONTAL STABILIZER		3135540-014	215	12/31/2025	4454 ldg	0	67
27		ACTUATOR, SPEED BRAKE	LH	2417015-5	1852	2/06/2002	23.0 hrs	0.0	5939.1
27		BOLT, FLAP SECTOR MOUNTING	LH	NAS6605H44	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, FLAP SECTOR MOUNTING	RH	NAS6605H44	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, HORIZONTAL STAB ACT ATTACH	LOWER	NAS464P6-23	UNKNOWN	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, HORIZONTAL STAB ACT ATTACH	UPPER	NAS464P6-17	UNKNOWN	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER ACTUATOR 1/4"	LH	NAS464P4-13	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER ACTUATOR 1/4"	RH	NAS464P4-13	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER ATTACH 5/16"	LH	NAS464P5A14	UNKNOWN	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER ATTACH 5/16"	RH	NAS464P5A14	UNKNOWN	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER PIVOT 5/16"	LH	NAS6205-20D	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOLT, SPOILER PIVOT 5/16"	RH	NAS6205-20D	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		BOOST, RUDDER		065-00153-0200	1210	8/26/2016	3521 ldg	0	1000
27		BOOST, RUDDER		065-00153-0200	1210	8/26/2016	4562.6 hrs	0.0	1399.5
27		BUSHING, FLAP NOSE ROLLER	LH INBD	NAS76A4-018	N/A	3/29/2023	4294 ldg	0	227
27		BUSHING, FLAP NOSE ROLLER	LH OTBD	NAS76A4-020	N/A	3/29/2023	4294 ldg	0	227
27		BUSHING, FLAP NOSE ROLLER	RH INBD	NAS76A4-018	N/A	3/29/2023	4294 ldg	0	227
27		BUSHING, FLAP NOSE ROLLER	RH OTBD	NAS76A4-020	N/A	3/29/2023	4294 ldg	0	227
27		CABLE ASSY, AILERON CONTROL COLUMN	LH	2300003-231	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON CONTROL COLUMN	RH	2300003-229	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON FORWARD	LH	2300003-245	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON FORWARD	RH	2300003-246	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON SECTOR AFT		2300003-17	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON WING	LH INBD	5405015-31	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON WING	LH OTBD	5405015-29	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON WING	RH INBD	5405015-31	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, AILERON WING	RH OTBD	5405015-29	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, ELEVATOR	LH AFT	2300003-171	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, ELEVATOR	LH FWD	2300003-240	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, ELEVATOR	RH AFT	2300003-172	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, ELEVATOR	RH FWD	2300003-239	UNKNOWN	5/15/2017	3601 ldg	0	920
27		CABLE ASSY, RUDDER	LH	2300003-243	UNKNOWN	5/15/2017	3601 ldg	0	920

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
27		CABLE ASSY, RUDDER	RH	2300003-243	UNKNOWN	5/15/2017	3601 ldg	0	920
27		COMPUTER, STALL WARNING		6608263-16	GST02653	2/06/2002	23.0 hrs	0.0	5939.1
27		CONTROLLER, STABILIZER TWO SPEED		6608444-11	63	7/01/2004	669.4 hrs	0.0	5292.7
27		DETECTOR, TRIM IN MOTION		6608326-3	601 REPAIR	12/31/2025	4454 ldg	0	67
27		DETECTOR, TRIM IN MOTION		6608326-3	601 REPAIR	12/31/2025	5853.4 hrs	0.0	108.7
27	#	FLAP NOSE ROLLER SUPPORT ARM		N/A BY S/N		8/29/2001	0.0 hrs	0.0	5962.1
27		INDICATOR, ANGLE OF ATTACK	PILOTS	6608208-9	535	2/06/2002	23.0 hrs	0.0	5939.1
27		POTENTIOMETER, AILERON TRIM		RV45AYSD102A	N/A	12/31/2025	4454 ldg	0	67
27		POTENTIOMETER, AILERON TRIM		RV45AYSD102A	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		POTENTIOMETER, RUDDER TRIM		RV45AYSD102A	N/A	12/31/2025	4454 ldg	0	67
27		POTENTIOMETER, RUDDER TRIM		RV45AYSD102A	N/A	12/31/2025	5853.4 hrs	0.0	108.7
27		SHAKER, CONTROL COLUMN	RH	6608289-2	1273 SVCBLE	6/30/2023	4318 ldg	0	203
27		SHAKER, CONTROL COLUMN	RH	6608289-2	1273 SVCBLE	6/30/2023	5660.9 hrs	0.0	301.2
27		SPOILER	RH	2422510-132	W1582	2/06/2002	23.0 hrs	0.0	5939.1
27		SWITCH, TRIM	PILOT	403-4300	N/A	12/31/2010	2290 ldg	0	2231
27		SWITCH, TRIM	PILOT	403-4300	N/A	12/31/2010	2840.6 hrs	0.0	3121.5
27		VALVE, FLAP CONTROL		6600362-1	686	10/13/2015	3384 ldg	0	1137
27		VALVE, FLAP CONTROL		6600362-1	686	10/13/2015	4386.3 hrs	0.0	1575.8
28		FUEL CELL, FUSELAGE	LH AFT	6600316-15	86107	5/17/2018	3640 ldg	0	881
28		FUEL CELL, FUSELAGE	LH AFT	6600316-15	86107	5/17/2018	4732.0 hrs	0.0	1230.1
28		HOSE ASSY, FUEL INTERCONNECT		S-161-16-22	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	LH	2406005-62	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	LH	2406005-19	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	LH	2307006-95	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	RH	2406005-62	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	RH	2406005-45	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	RH	2406005-19	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL MOTIVE FLOW	RH	2307006-95	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL SUPPLY	RH	2406005-24	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL TRANSFER		S-161-16-35	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL TRANSFER	LH	S-161-16-35	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUEL TRANSFER	RH	S-161-16-35	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, FUSELAGE FUEL TRANSFER	LH	S-161-12-35	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, MOTIVE FLOW	RH	2406005-28	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, MOTIVE FLOW	RH	3106002-6	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, WING PUMP MOTIVE FLOW	LH	3106003-1	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, WING PUMP MOTIVE FLOW	LH	12031-016-102	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, WING PUMP MOTIVE FLOW	RH	12031-016-102	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		HOSE ASSY, WING PUMP MOTIVE FLOW	RT	3106003-1	N/A	12/31/2025	5853.4 hrs	0.0	108.7
28		INDICATOR, FUEL QUANTITY		JG911B20	01020341 REPAIR	6/19/2018	3640 ldg	0	881
28		INDICATOR, FUEL QUANTITY		JG911B20	01020341 REPAIR	6/19/2018	4732.0 hrs	0.0	1230.1
29		GAUGE, TAILCONE HYDRAULIC PRESSURE		S218-2	1223	4/10/2003	287.0 hrs	0.0	5675.1
29		HOSE ASSY, FLAP EXTEND	LH	A3028-235	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, FLAP EXTEND	RH	A3028-235	N/A	12/31/2025	5853.4 hrs	0.0	108.7

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
29		HOSE ASSY, HYD ENGINE PUMP PRESSURE	LH	2406005-21	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD ENGINE PUMP SUPPLY	LH	2406005-22	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD FLAP RETRACT	LH	2307006-52	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD FLAP RETRACT	RH	2307006-52	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD HORIZ STAB		2307006-94	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD PRESSURE		2307006-244	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYD PRESSURE	RH	2307006-51	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYDRAULIC SUPPLY	LH	2406005-52	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, HYDRAULIC SUPPLY	RH	2406005-51	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, SPOILER EXTEND	LH	A3028-233	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, SPOILER EXTEND	RH	A3028-233	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, SPOILER RETRACT	LH	A3028-237	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		HOSE ASSY, SPOILER RETRACT	RH	A3028-235	N/A	12/31/2025	5853.4 hrs	0.0	108.7
29		PUMP, AUXILIARY ELECTRIC HYDRAULIC		6600248-1	1764	2/06/2002	23.0 hrs	0.0	5939.1
29		PUMP, ENGINE HYDRAULIC	LH	65078-01	K0355B REPAIR	3/23/2024	4347 ldg	0	174
29		PUMP, ENGINE HYDRAULIC	LH	65078-01	K0355B REPAIR	3/23/2024	5705.4 hrs	0.0	256.7
29		PUMP, ENGINE HYDRAULIC	RH	65078-01	177997B	7/03/2007	1640.1 hrs	0.0	4322.0
30		BLANKET, HORIZ STAB HEAT	LH	4065-3481	24-72416	12/31/2025	4454 ldg	0	67
30		BLANKET, HORIZ STAB HEAT	LH	4065-3481	24-72416	12/31/2025	5853.4 hrs	0.0	108.7
30		BLANKET, HORIZ STAB HEAT	RH	4065-3481	18-66013	6/19/2018	3640 ldg	0	881
30		BLANKET, HORIZ STAB HEAT	RH	4065-3481	18-66013	6/19/2018	4732.0 hrs	0.0	1230.1
30		SENSOR, WINDSHIELD A-I		6600395-1	204/205	11/13/2015	3395 ldg	0	1126
30		SENSOR, WINDSHIELD A-I		6600395-1	204/205	11/13/2015	4403.3 hrs	0.0	1558.8
30		VALVE ASSY, WINDSHIELD AIR SHUTOFF		2619500-2	UNKNOWN	8/29/2001	0 ldg	0	4521
30		VALVE ASSY, WINDSHIELD AIR SHUTOFF		2619500-2	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
30		VALVE, ALCOHOL REGULATOR & SHUTOFF		6608257-1	1616A	12/12/2004	785.7 hrs	0.0	5176.4
31		BATTERY, DAVTRON CLOCK	COPILOT	N/A	N/A	3/27/2026	4483 ldg	0	38
31		BATTERY, DAVTRON CLOCK	COPILOT	N/A	N/A	3/27/2026	5909.1 hrs	0.0	53.0
31		BATTERY, DAVTRON CLOCK	PILOT	N/A	N/A	3/27/2026	4483 ldg	0	38
31		BATTERY, DAVTRON CLOCK	PILOT	N/A	N/A	3/27/2026	5909.1 hrs	0.0	53.0
32		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC	LH	111417-4S0134	N/A	5/05/2025	5815.4 hrs	0.0	146.7
32		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC	RH	111417-4S0134	N/A	5/05/2025	5815.4 hrs	0.0	146.7
32		HOSE ASSY, HYD NOSE GEAR RETRACT		111504-6S0120	N/A	5/05/2025	5815.4 hrs	0.0	146.7
32		HOSE ASSY, NOSE GEAR EXTEND		111504-6S0081	N/A	5/05/2025	5815.4 hrs	0.0	146.7
32		HOSE ASSY, NOSE GEAR EXTEND		111504-6S0081	N/A	5/05/2025	5815.4 hrs	0.0	146.7
32		STRUT ASSEMBLY, MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		STRUT ASSEMBLY, MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		PIN, MAIN GEAR ATTACH	LH	2341109	UNKNOWN	8/29/2001	0 ldg	0	4521
32		PIN, MAIN GEAR ATTACH	RH	2341109	UNKNOWN	8/29/2001	0 ldg	0	4521
32		PILLAR ASSEMBLY, MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		PILLAR ASSEMBLY, MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		STRUT ASSEMBLY, NOSE GEAR		UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		ACTUATOR ASSEMBLY, NOSE GEAR		UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		PIN, MAIN GEAR ACTUATOR ATTACH	LH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32		PIN,MAIN GEAR ACTUATOR ATTACH	RH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		ACTUATOR ASSEMBLY,MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		ACTUATOR ASSEMBLY,MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0 ldg	0	4521
32		TORQUE LINK,MAIN LANDING GEAR	LH	2341119		8/29/2001	0 ldg	0	4521
32		TORQUE LINK,MAIN LANDING GEAR	RH	2341119		8/29/2001	0 ldg	0	4521
32		ACTUATOR ASSEMBLY,MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		ACTUATOR ASSEMBLY,MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		ACTUATOR ASSEMBLY,NOSE GEAR		UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		ACTUATOR,DOOR	LH INBD	6600085-9	0241	10/04/2011	2508 ldg	0	2013
32		ACTUATOR,DOOR	LH INBD	6600085-9	0241	10/04/2011	3121.6 hrs	0.0	2840.5
32		ACTUATOR,DOOR	RH INBD	6600085-9	0882	10/04/2011	2508 ldg	0	2013
32		ACTUATOR,DOOR	RH INBD	6600085-9	0882	10/04/2011	3121.6 hrs	0.0	2840.5
32		ACTUATOR,NOSE GEAR UPLATCH		2417016-1	5316 REPAIR	4/10/2003	287.0 hrs	0.0	5675.1
32		BRAKE ASSEMBLY	LH INBD	5003096-6	JAN91-2955	8/29/2025	4451 ldg	0	70
32		BRAKE ASSEMBLY	LH INBD	5003096-6	JAN91-2955	8/29/2025	5848.7 hrs	0.0	113.4
32		BRAKE ASSEMBLY	LH OTBD	5003096-6	SEP80-2605	8/29/2025	4451 ldg	0	70
32		BRAKE ASSEMBLY	LH OTBD	5003096-6	SEP80-2605	8/29/2025	5848.7 hrs	0.0	113.4
32		BRAKE ASSEMBLY	RH INBD	5003096-6	FEB68-25A	8/29/2025	4451 ldg	0	70
32		BRAKE ASSEMBLY	RH INBD	5003096-6	FEB68-25A	8/29/2025	5848.7 hrs	0.0	113.4
32		BRAKE ASSEMBLY	RH OTBD	5003096-6	JUN00-5474	8/29/2025	4451 ldg	0	70
32		BRAKE ASSEMBLY	RH OTBD	5003096-6	JUN00-5474	8/29/2025	5848.7 hrs	0.0	113.4
32		COMPUTER,NOSE STEERING		6608468-010	1319	2/06/2002	23.0 hrs	0.0	5939.1
32		CYLINDER,MLG	RH	6041101-002	JK21R05	4/18/2022	4188 ldg	0	333
32		CYLINDER,MLG	RH	6041101-002	JK21R05	4/18/2022	5490.1 hrs	0.0	472.0
32		DOOR,NOSE GEAR	LH	2310620-3	UNK SVCBLE	8/15/2025	5843.8 hrs	0.0	118.3
32		FOLLOW UP,NOSE GEAR	LH	6608288-013	5230	10/26/2016	3551 ldg	0	970
32		FOLLOW UP,NOSE GEAR	LH	6608288-013	5230	10/26/2016	4607.0 hrs	0.0	1355.1
32		FOLLOW UP,NOSE GEAR	RH	6608288-013	5413	10/26/2016	3551 ldg	0	970
32		FOLLOW UP,NOSE GEAR	RH	6608288-013	5413	10/26/2016	4607.0 hrs	0.0	1355.1
32		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	LH	2307006-19	N/A	12/31/2025	5853.4 hrs	0.0	108.7
32		HOSE ASSY,AIR MAIN GEAR DOOR EXTEND	RH	2307006-20	N/A	12/31/2025	5853.4 hrs	0.0	108.7
32		HOSE ASSY,EMERG AIR NOSE GEAR ACT		2307006-111	N/A	12/31/2025	5853.4 hrs	0.0	108.7
32		HOSE ASSY,EMERGENCY BRAKE		2307006-242	N/A	12/31/2025	5853.4 hrs	0.0	108.7
32		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH INBD	2307006-112	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE LOWER	LH OUTBD	2307006-113	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH INBD	2307006-112	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE LOWER	RH OUTBD	2307006-113	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH INBD	2307006-37	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE UPPER	LH OTBD	2307006-35	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH INBD	2307006-37	N/A	12/31/2025	4454 ldg	0	67
32		HOSE ASSY,HYD BRAKE PRESSURE UPPER	RH OTBD	2307006-35	N/A	12/31/2025	4454 ldg	0	67
32	#	HOSE ASSY,HYD MAIN GEAR ACT RETRACT	LH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32	#	HOSE ASSY,HYD MAIN GEAR ACT RETRACT	RH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32	#	HOSE ASSY,HYD MAIN GEAR DOOR EXTEND	LH	TEFLON	N/A	6/17/2020	3867 ldg	0	654

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32	#	HOSE ASSY, HYD MAIN GEAR DOOR EXTEND	RH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC	LH	111417-4S0134	N/A	5/05/2025	4427 ldg	0	94
32		HOSE ASSY, HYD MAIN GEAR DOOR RETRAC	RH	111417-4S0134	N/A	5/05/2025	4427 ldg	0	94
32	#	HOSE ASSY, HYD MAIN GEAR DOOR UPLACH	LH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32	#	HOSE ASSY, HYD MAIN GEAR DOOR UPLACH	RH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32	#	HOSE ASSY, HYD MAIN GEAR EXTEND	LH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32	#	HOSE ASSY, HYD MAIN GEAR EXTEND	RH	TEFLON	N/A	6/17/2020	3867 ldg	0	654
32		HOSE ASSY, HYD NOSE GEAR RETRACT		111504-6S0120	N/A	5/05/2025	4427 ldg	0	94
32	#	HOSE ASSY, HYD NOSE GEAR UPLACH		TEFLON	N/A	6/17/2020	3867 ldg	0	654
32		HOSE ASSY, NOSE GEAR EXTEND		111504-6S0081	N/A	5/05/2025	4427 ldg	0	94
32		HOSE ASSY, NOSE GEAR EXTEND		111504-6S0081	N/A	5/05/2025	4427 ldg	0	94
32		PILLAR ASSEMBLY, MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		PILLAR ASSEMBLY, MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		PIN, MAIN GEAR ACTUATOR ATTACH	LH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		PIN, MAIN GEAR ACTUATOR ATTACH	RH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		PIN, MAIN GEAR ATTACH	LH	2341109	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		PIN, MAIN GEAR ATTACH	RH	2341109	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		STRUT ASSEMBLY, MAIN GEAR	LH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		STRUT ASSEMBLY, MAIN GEAR	RH	UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		STRUT ASSEMBLY, NOSE GEAR		UNKNOWN	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
32		TIRE	LH INBD	178K43-1	20550475	4/18/2022	4188 ldg	0	333
32		TIRE	LH INBD	178K43-1	20550475	4/18/2022	5490.1 hrs	0.0	472.0
32		TIRE	LH OTBD	178K43-1	20560447	4/18/2022	4188 ldg	0	333
32		TIRE	LH OTBD	178K43-1	20560447	4/18/2022	5490.1 hrs	0.0	472.0
32		TIRE	NOSE	184F10-2	42200727	6/22/2026	4521 ldg	0	0
32		TIRE	NOSE	184F10-2	42200727	6/22/2026	5962.1 hrs	0.0	0.0
32		TIRE	RH INBD	178K43-1	53150776	1/28/2026	4463 ldg	0	58
32		TIRE	RH INBD	178K43-1	53150776	1/28/2026	5871.3 hrs	0.0	90.8
32		TIRE	RH OTBD	178K43-1	53160769	1/28/2026	4463 ldg	0	58
32		TIRE	RH OTBD	178K43-1	53160769	1/28/2026	5871.3 hrs	0.0	90.8
32		TORQUE LINK, MAIN LANDING GEAR	LH	2341119		8/29/2001	0.0 hrs	0.0	5962.1
32		TORQUE LINK, MAIN LANDING GEAR	RH	2341119		8/29/2001	0.0 hrs	0.0	5962.1
32		VALVE, ANTI-SKID	RH	39-309-1	1861	10/04/2011	2508 ldg	0	2013
32		VALVE, ANTI-SKID	RH	39-309-1	1861	10/04/2011	3121.6 hrs	0.0	2840.5
32		VALVE, GEAR SELECTOR		48C48641	0074T	8/29/2025	4451 ldg	0	70
32		VALVE, GEAR SELECTOR		48C48641	0074T	8/29/2025	5848.7 hrs	0.0	113.4
32		WHEEL ASSEMBLY, MAIN GEAR	LH INBD	5004913-6	JAN01-3714 NDT	4/18/2022	4188 ldg	0	333
32		WHEEL ASSEMBLY, MAIN GEAR	LH INBD	5004913-6	JAN01-3714 NDT	4/18/2022	5490.1 hrs	0.0	472.0
32		WHEEL ASSEMBLY, MAIN GEAR	LH OTBD	5004913-6	FEB01-3728 NDT	4/18/2022	4188 ldg	0	333
32		WHEEL ASSEMBLY, MAIN GEAR	LH OTBD	5004913-6	FEB01-3728 NDT	4/18/2022	5490.1 hrs	0.0	472.0
32		WHEEL ASSEMBLY, MAIN GEAR	RH INBD	5004913-6	JAN01-3715 NDT	1/28/2026	4463 ldg	0	58
32		WHEEL ASSEMBLY, MAIN GEAR	RH INBD	5004913-6	JAN01-3715 NDT	1/28/2026	5871.3 hrs	0.0	90.8
32		WHEEL ASSEMBLY, MAIN GEAR	RH OTBD	5004913-6	JAN01-3704	1/28/2026	4463 ldg	0	58
32		WHEEL ASSEMBLY, MAIN GEAR	RH OTBD	5004913-6	JAN01-3704	1/28/2026	5871.3 hrs	0.0	90.8

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
33		LAMP, NAV TAILCONE	UPPER	1683	N/A	3/28/2014	3124 ldg	0	1397
33		LAMP, NAV TAILCONE	UPPER	1683	N/A	3/28/2014	4002.5 hrs	0.0	1959.6
33		LAMP, RECOGNITION	LH	Q4681	N/A	1/11/2011	2535 ldg	0	1986
33		LAMP, RECOGNITION	LH	Q4681	N/A	1/11/2011	3169.7 hrs	0.0	2792.4
33		LIGHT DIM ASSEMBLY	COPILOT'S	6608096-5	1005	5/13/2022	4195 ldg	0	326
33		LIGHT DIM ASSEMBLY	COPILOT'S	6608096-5	1005	5/13/2022	5502.2 hrs	0.0	459.9
33		LIGHT DIM ASSEMBLY	PILOT'S	6608096-5	1688	5/15/2017	3601 ldg	0	920
33		LIGHT DIM ASSEMBLY	PILOT'S	6608096-5	1688	5/15/2017	4669.7 hrs	0.0	1292.4
33		LIGHT, ANTI-COLLISION	UPPER	01-0790044-01	04470	12/31/2025	4454 ldg	0	67
33		LIGHT, ANTI-COLLISION	UPPER	01-0790044-01	04470	12/31/2025	5853.4 hrs	0.0	108.7
33		LIGHT, LANDING/TAXI	RH	GE 4580	N/A	10/04/2011	2508 ldg	0	2013
33		LIGHT, LANDING/TAXI	RH	GE 4580	N/A	10/04/2011	3121.6 hrs	0.0	2840.5
33		LOPRESTI BOOM BEAM		STC SA02279AT		1/12/2016	3415 ldg	0	1106
33		LOPRESTI BOOM BEAM		STC SA02279AT		1/12/2016	4429.8 hrs	0.0	1532.3
33		POWER SUPPLY, STROBE LIGHT	TAIL	61-2008	11912B	7/02/2020	3874 ldg	0	647
33		POWER SUPPLY, STROBE LIGHT	TAIL	61-2008	11912B	7/02/2020	5060.6 hrs	0.0	901.5
34		PROBE, PRIMARY PITOT STATIC	LH	0856NA1	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
34		PROBE, PRIMARY PITOT STATIC	RH	0856NA2	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
34		ALTIMETER	STANDBY	8047-3077-53	10431	1/27/2017	3574 ldg	0	947
34		ALTIMETER	STANDBY	8047-3077-53	10431	1/27/2017	4635.1 hrs	0.0	1327.0
34		ANTENNA ARRAY		071-01549-0200	7709	3/06/2014	3108 ldg	0	1413
34		ANTENNA ARRAY		071-01549-0200	7709	3/06/2014	3977.0 hrs	0.0	1985.1
34		ANTENNA, GPS		GA-35	161038	3/17/2020	3841 ldg	0	680
34		ANTENNA, GPS		GA-35	161038	3/17/2020	5014.7 hrs	0.0	947.4
34		COMPUTER, AHRS	#1	065-00185-0101	1226	4/12/2002	61.7 hrs	0.0	5900.4
34		COMPUTER, AHRS	#2	142185-3101	9026	1/09/2007	1460.4 hrs	0.0	4501.7
34		COMPUTER, AIR DATA	#1	065-0082-14	X11124	9/05/2022	4226 ldg	0	295
34		COMPUTER, AIR DATA	#1	065-0082-14	X11124	9/05/2022	5546.1 hrs	0.0	416.0
34		COMPUTER, AIR DATA	#2	065-0082-14	10948 INSTL?	12/29/2014	4217.8 hrs	0.0	1744.3
34		COMPUTER, EGPWS		UNKNOWN	UNKNOWN	3/11/2004	592.6 hrs	0.0	5369.5
34		CONFIGURATION MODULE, UNS		1017-41-001	2067 REPAIRED	8/23/2017	3612 ldg	0	909
34		CONFIGURATION MODULE, UNS		1017-41-001	2067 REPAIRED	8/23/2017	4684.1 hrs	0.0	1278.0
34		CONTROL HEAD, TRANSPONDER		071-01542-2901	1238	8/27/2013	2983 ldg	0	1538
34		CONTROL HEAD, TRANSPONDER		071-01542-2901	1238	8/27/2013	3790.0 hrs	0.0	2172.1
34		CONTROL, EFIS	#1	071-01439-3200	2377	9/01/2015	3369 ldg	0	1152
34		CONTROL, EFIS	#1	071-01439-3200	2377	9/01/2015	4363.9 hrs	0.0	1598.2
34		CONTROL, MULTI FUNCTION DISPLAY		071-01511-0201	1412	9/09/2003	401.1 hrs	0.0	5561.0
34		CONTROLLER, FREQUENCY TPR		071-01542-2901	1270	1/23/2003	233.3 hrs	0.0	5728.8
34		FMS		1017-41-001	2067	2/06/2002	23.0 hrs	0.0	5939.1
34		FMS, UNS		2017-42-211	1295 REPAIR	8/15/2025	5843.8 hrs	0.0	118.3
34		GDL-88 ADS-B OUT		011-02370-00	22U001912	3/17/2020	3841 ldg	0	680
34		GDL-88 ADS-B OUT		011-02370-00	22U001912	3/17/2020	5014.7 hrs	0.0	947.4
34		INDICATOR, MACH AIRSPEED	STANDBY	2C131	624	2/06/2002	23.0 hrs	0.0	5939.1
34		INDICATOR, AUXILIARY GYRO (EMERG)	PILOTS	501-1197-05	7655	2/06/2002	23.0 hrs	0.0	5939.1

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
34		INDICATOR, VERTICAL SPEED	CO-PILOTS	066-3077-48	1522	2/06/2002	23.0 hrs	0.0	5939.1
34		INDICATOR, VERTICAL SPEED	PILOTS	066-3077-48	KAV485T-1603	2/08/2023	4289 ldg	0	232
34		INDICATOR, VERTICAL SPEED	PILOTS	066-3077-48	KAV485T-1603	2/08/2023	5616.2 hrs	0.0	345.9
34		MODULE, CONFIGURATION		071-00097-0100	26264	8/28/2013	3791.2 hrs	0.0	2170.9
34		PANEL, NAVIGATION I CONTROL		071-1343-08	5143	2/06/2002	23.0 hrs	0.0	5939.1
34		PANEL, RADAR CONTROL		071-01438-0401	1265	5/10/2002	73.9 hrs	0.0	5888.2
34		PROBE, ROSEMOUNT TEMPERATURE		102AUIAG	20722E	1/16/2026	4455 ldg	0	66
34		PROBE, ROSEMOUNT TEMPERATURE		102AUIAG	20722E	1/16/2026	5895.3 hrs	0.0	66.8
34		R/T RADAR		071-05149-101	6123 SVCBLE	3/06/2014	3108 ldg	0	1413
34		R/T RADAR		071-05149-101	6123 SVCBLE	3/06/2014	3977.0 hrs	0.0	1985.1
34		R/T, ADF	PRIMARY	066-1105-01	11436	6/19/2018	3640 ldg	0	881
34		R/T, ADF	PRIMARY	066-1105-01	11436	6/19/2018	4732.0 hrs	0.0	1230.1
34		SENSOR, RADAR		071-01519-0101	6926	5/12/2026	5923.9 hrs	0.0	38.2
34		TRANSPONDER	#1	011-01997-00	20S011596 ADS OUT	3/17/2020	3841 ldg	0	680
34		TRANSPONDER	#1	011-01997-00	20S011596 ADS OUT	3/17/2020	5014.7 hrs	0.0	947.4
34		TRANSPONDER	#2	011-01997-00	20S011342 ADS OUT	3/17/2020	3841 ldg	0	680
34		TRANSPONDER	#2	011-01997-00	20S011342 ADS OUT	3/17/2020	5014.7 hrs	0.0	947.4
35		BOTTLE, OXYGEN	TAIL	176700-40	ALT372-8745	9/30/2021	4188 ldg	0	333
35		BOTTLE, OXYGEN	TAIL	176700-40	ALT372-8745	9/30/2021	4188 ldg	0	333
35		BOTTLE, OXYGEN	TAIL	176700-40	ALT372-8745	9/30/2021	5490.1 hrs	0.0	472.0
35		BOTTLE, OXYGEN	TAIL	176700-40	ALT372-8745	9/30/2021	5490.1 hrs	0.0	472.0
35		MASK, OXYGEN	COPILOT	MC10-15-151	89599	10/16/2025	5887.2 hrs	0.0	74.9
35		MASK, OXYGEN	PILOT	MC10-15-151	38630	12/30/2020	5854.3 hrs	0.0	107.8
36		BOTTLE, EMERGENCY AIR		6600194-6	231	1/01/1994	4370 ldg	0	151
36		BOTTLE, EMERGENCY AIR		6600194-6	231	1/01/1994	5741.0 hrs	0.0	221.1
39		VALVE, MODULATING	LH	6600202-3	2716	5/15/2017	3601 ldg	0	920
39		VALVE, MODULATING	LH	6600202-3	2716	5/15/2017	4669.7 hrs	0.0	1292.4
39		VALVE, MODULATING	RH	6600202-3	1935C	5/20/2013	3712.3 hrs	0.0	2249.8
51		RADOME, NOSE CONE		UNKNOWN	0583 REPAIR	7/08/2005	902.6 hrs		5059.5
52		CABLE, CABIN ENTRY DOOR	AFT	2411660-29	N/A	3/10/2015	3281 ldg	0	1240
52		CABLE, CABIN ENTRY DOOR	AFT	2411660-29	N/A	3/10/2015	4236.9 hrs	0.0	1725.2
52		CABLE, CABIN ENTRY DOOR	FWD	2411660-001	10262711	10/04/2011	2508 ldg	0	2013
52		CABLE, CABIN ENTRY DOOR	FWD	2411660-001	10262711	10/04/2011	3121.6 hrs	0.0	2840.5
53		BOLTS, KEELBEAM ATTACHMENT		MS20005-36/-14	UNKNOWN	12/31/2025	5853.4 hrs	0.0	108.7
56		SENSOR, WINDSHIELD TEMP	LH	6600395-1	204	11/13/2015	3395 ldg	0	1126
56		SENSOR, WINDSHIELD TEMP	LH	6600395-1	204	11/13/2015	4403.3 hrs	0.0	1558.8
56		SENSOR, WINDSHIELD TEMP	RH	6600395-1	205	11/13/2015	3395 ldg	0	1126
56		SENSOR, WINDSHIELD TEMP	RH	6600395-1	205	11/13/2015	4403.3 hrs	0.0	1558.8
56		WINDOW, CABIN	LH #2	PAS6600115-10	16901	5/21/2015	3307 ldg	0	1214
56		WINDOW, CABIN	LH #2	PAS6600115-10	16901	5/21/2015	4281.2 hrs	0.0	1680.9
56		WINDOW, CABIN	LH #5	PAS6600115-10	21328	5/15/2017	3601 ldg	0	920
56		WINDOW, CABIN	LH #5	PAS6600115-10	21328	5/15/2017	4669.7 hrs	0.0	1292.4
56		WINDOW, CABIN	RH #3	PAS6600115-10	16911	8/27/2013	3790.0 hrs	0.0	2172.1
56		WINDOW, CABIN	RH #5	PAS6600115-10	5660	4/06/2007	1543.2 hrs	0.0	4418.9

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
56		WINDOW, EMERGENCY EXIT CABIN		PAS6600115-10	21329	5/15/2017	3601 ldg	0	920
56		WINDOW, EMERGENCY EXIT CABIN		PAS6600115-10	21329	5/15/2017	4669.7 hrs	0.0	1292.4
56		WINDSHIELD	LH	6600393-003	2213	6/15/2012	2670 ldg	0	1851
56		WINDSHIELD	LH	6600393-003	2213	6/15/2012	3345.4 hrs	0.0	2616.7
56		WINDSHIELD	RH	LA6600393-004	100055	12/31/2025	4454 ldg	0	67
56		WINDSHIELD	RH	LA6600393-004	100055	12/31/2025	5853.4 hrs	0.0	108.7
71		ENG FWD SHOCK MOUNT, COVER	LH LOWER	LM833-3	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, COVER	LH UPPER	LM833-3	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, COVER	RH LOWER	LM833-3	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, COVER	RH UPPER	LM833-3	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		BOND JOINT ISO ASSY, ENG AFT CENTER	LH AFT	LM833-16	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOND JOINT ISO ASSY, ENG AFT CENTER	RH AFT	LM833-16	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG AFT ISOLATOR ASSY, HOUSING	LH	LM833-30	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG AFT ISOLATOR ASSY, HOUSING	RH	LM833-30	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD MOUNT ATTACH	LH LOWER	2651026-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD MOUNT ATTACH	LH UPPER	2651026-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD MOUNT ATTACH	RH LOWER	2651026-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD MOUNT ATTACH	RH UPPER	2651026-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE AFT MOUNT ATTACH	LH	2652002	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE AFT MOUNT ATTACH	LH	2651027-1	N/A	8/27/2013	3790.0 hrs	0.0	2172.1
71		BOLT, ENGINE AFT MOUNT ATTACH	RH	2652002	UNKNOWN	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE AFT MOUNT ATTACH	RH	2651027-1	N/A	8/27/2013	3790.0 hrs	0.0	2172.1
71		BOLT, ENGINE FWD SHOCK MOUNT	LH LOWER	6600187-4	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT	LH UPPER	6600187-4	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT	RH LOWER	6600187-4	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT	RH UPPER	6600187-4	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	LH LOWER	NAS1307-3H	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	LH UPPER	NAS1307-3H	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	RH LOWER	NAS1307-3H	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE FWD SHOCK MOUNT SUPPORT	RH UPPER	NAS1307-3H	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE AFT SHOCK MOUNT ATTACH	LH	NAS335CP23	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		BOLT, ENGINE AFT SHOCK MOUNT ATTACH	RH	NAS335CP23	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, BOLTS	LH LOWER	NAS6604H1	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, BOLTS	LH UPPER	NAS6604H1	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, BOLTS	RH LOWER	NAS6604H1	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, BOLTS	RH UPPER	NAS6604H1	N/A	1/02/2015	4217.8 hrs	0.0	1744.3
71		ENG FWD SHOCK MOUNT, MOUNT ASSY	LH LOWER	LM833-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, MOUNT ASSY	LH UPPER	LM833-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, MOUNT ASSY	RH LOWER	LM833-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, MOUNT ASSY	RH UPPER	LM833-1	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, HOUSING	LH LWR	LM833-2	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, HOUSING	LH UPR	LM833-2	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, HOUSING	RH LWR	LM833-2	N/A	8/29/2001	0.0 hrs	0.0	5962.1
71		ENG FWD SHOCK MOUNT, HOUSING	RH UPR	LM833-2	N/A	8/29/2001	0.0 hrs	0.0	5962.1

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
71		ENG FWD SHOCK MOUNT,BOLTS	LH LOWER	NAS6604H1	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,BOLTS	LH UPPER	NAS6604H1	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,BOLTS	RH LOWER	NAS6604H1	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,BOLTS	RH UPPER	NAS6604H1	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,COVER	LH LOWER	LM833-3	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,COVER	LH UPPER	LM833-3	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,COVER	RH LOWER	LM833-3	N/A	1/02/2015	3265 ldg	0	1256
71		ENG FWD SHOCK MOUNT,COVER	RH UPPER	LM833-3	N/A	1/02/2015	3265 ldg	0	1256
71		HOSE ASSY,FUEL MOTIVE FLOW	LH NACELLE	2406005-25	N/A	12/31/2025	4454 ldg	0	67
71		HOSE ASSY,FUEL MOTIVE FLOW	RH NACELLE	2406005-28	N/A	12/31/2025	4454 ldg	0	67
71		HOSE ASSY,FUEL SUPPLY	LH NACELLE	2406005-26	N/A	12/31/2025	4454 ldg	0	67
71		HOSE ASSY,FUEL SUPPLY	RH NACELLE	2406005-23	N/A	12/31/2025	4454 ldg	0	67
71		HOSE ASSY,HYD ENGINE PUMP PRESSURE	LH	2406005-30	N/A	8/18/2021	4131 ldg	0	390
71		HOSE ASSY,HYD ENGINE PUMP PRESSURE	RH	2406005-27	N/A	8/18/2021	4131 ldg	0	390
71		HOSE ASSY,HYD ENGINE PUMP RETURN	LH	AS157G16311180	N/A	8/18/2021	4131 ldg	0	390
71		HOSE ASSY,HYD ENGINE PUMP RETURN	RH	AS157G184H180	N/A	8/18/2021	4131 ldg	0	390
71		HOSE ASSY,HYD ENGINE PUMP SUPPLY	LH	2406005-22	N/A	8/18/2021	4131 ldg	0	390
71		HOSE ASSY,HYD ENGINE PUMP SUPPLY	RH	2406005-52	N/A	8/18/2021	4131 ldg	0	390
72		DISC AND HUB,FAN ROTOR	LH	3073563-2	010322900458	7/06/2001	0 cyc	0	4329
72		DISC AND HUB,FAN ROTOR	RH	3073563-2	010322900455	7/03/2001	0 cyc	0	4532
72		DISC,LP 1ST STAGE AXIAL COMPRESSOR	LH	3072395-2	000316004371	7/06/2001	0 cyc	0	4329
72		DISC,LP 1ST STAGE AXIAL COMPRESSOR	RH	3072395-2	000316004380	7/03/2001	0 cyc	0	4532
72		DISC,LP 1ST STAGE TURBINE ROTOR	LH	3075828-1	2318244945678	2/29/2024	4154 cyc	0	175
72		DISC,LP 1ST STAGE TURBINE ROTOR	RH	3075828-1	13-182449-10989	12/08/2014	3302 cyc	0	1230
72		DISC,LP 2ND STAGE AXIAL COMPRESSOR	LH	3072396-3	010316000167	7/06/2001	0 cyc	0	4329
72		DISC,LP 2ND STAGE AXIAL COMPRESSOR	RH	3072396-3	000316004469	7/03/2001	0 cyc	0	4532
72		DISC,LP 2ND STAGE TURBINE ROTOR	LH	3072069-5	2318244945813	2/29/2024	4154 cyc	0	175
72		DISC,LP 2ND STAGE TURBINE ROTOR	RH	3072069-5	2318244945794	3/12/2024	4357 cyc	0	175
72		DISC,LP 3RD STAGE AXIAL COMPRESSOR	LH	3072397-3	000316004579	7/06/2001	0 cyc	0	4329
72		DISC,LP 3RD STAGE AXIAL COMPRESSOR	RH	3072397-3	000316004588	7/03/2001	0 cyc	0	4532
72		DISC,LP 3RD STAGE TURBINE ROTOR	LH	3072068-3	000322901900	7/06/2001	0 cyc	0	4329
72		DISC,LP 3RD STAGE TURBINE ROTOR	RH	3072068-3	000322903014	7/03/2001	0 cyc	0	4532
72		DISC,LP 4TH STAGE AXIAL COMPRESSOR	LH	3072398-2	000322903774	7/06/2001	0 cyc	0	4329
72		DISC,LP 4TH STAGE AXIAL COMPRESSOR	RH	3072398-2	010322900905	7/03/2001	0 cyc	0	4532
72		IMPELLER,HP COMPRESSOR RADIAL	LH	3075765-1	000322908135	7/06/2001	0 cyc	0	4329
72		IMPELLER,HP COMPRESSOR RADIAL	RH	3075765-1	000322908115	7/03/2001	0 cyc	0	4532
72		ROTOR,HP TURBINE WHEEL	LH	3072732-2	1718244924109	2/29/2024	4154 cyc	0	175
72		ROTOR,HP TURBINE WHEEL	RH	3072732-2	1718244924111	3/12/2024	4357 cyc	0	175
72		COMBUSTION CHAMBER PLENUM CASE	LH	3072443-3	01P00242	7/06/2001	0 cyc	0	4329
72		COMBUSTION CHAMBER PLENUM CASE	LH	3072443-3	01P00242	7/06/2001	0.0 eng	0.0	5815.0
72		COMBUSTION CHAMBER PLENUM CASE	RH	3072443-3	01P02683	7/03/2001	0 cyc	0	4532
72		COMBUSTION CHAMBER PLENUM CASE	RH	3072443-3	01P02683	7/03/2001	0.0 eng	0.0	5866.4
72		DISC AND HUB,FAN ROTOR	LH	3073563-2	010322900458	7/06/2001	0.0 eng	0.0	5815.0
72		DISC AND HUB,FAN ROTOR	RH	3073563-2	010322900455	7/03/2001	0.0 eng	0.0	5866.4

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
72		DISC, LP 1ST STAGE AXIAL COMPRESSOR	LH	3072395-2	000316004371	7/06/2001	0.0 eng	0.0	5815.0
72		DISC, LP 1ST STAGE AXIAL COMPRESSOR	RH	3072395-2	000316004380	7/03/2001	0.0 eng	0.0	5866.4
72		DISC, LP 1ST STAGE TURBINE ROTOR	LH	3075828-1	2318244945678	2/29/2024	5557.0 eng	0.0	258.0
72		DISC, LP 1ST STAGE TURBINE ROTOR	RH	3075828-1	13-182449-10989	12/08/2014	4117.1 eng	0.0	1749.3
72		DISC, LP 2ND STAGE AXIAL COMPRESSOR	LH	3072396-3	010316000167	7/06/2001	0.0 eng	0.0	5815.0
72		DISC, LP 2ND STAGE AXIAL COMPRESSOR	RH	3072396-3	000316004469	7/03/2001	0.0 eng	0.0	5866.4
72		DISC, LP 2ND STAGE TURBINE ROTOR	LH	3072069-5	2318244945813	2/29/2024	5557.0 eng	0.0	258.0
72		DISC, LP 2ND STAGE TURBINE ROTOR	RH	3072069-5	2318244945794	3/12/2024	5603.4 eng	0.0	263.0
72		DISC, LP 3RD STAGE AXIAL COMPRESSOR	LH	3072397-3	000316004579	7/06/2001	0.0 eng	0.0	5815.0
72		DISC, LP 3RD STAGE AXIAL COMPRESSOR	RH	3072397-3	000316004588	7/03/2001	0.0 eng	0.0	5866.4
72		DISC, LP 3RD STAGE TURBINE ROTOR	LH	3072068-3	000322901900	7/06/2001	0.0 eng	0.0	5815.0
72		DISC, LP 3RD STAGE TURBINE ROTOR	RH	3072068-3	000322903014	7/03/2001	0.0 eng	0.0	5866.4
72		DISC, LP 4TH STAGE AXIAL COMPRESSOR	LH	3072398-2	000322903774	7/06/2001	0.0 eng	0.0	5815.0
72		DISC, LP 4TH STAGE AXIAL COMPRESSOR	RH	3072398-2	010322900905	7/03/2001	0.0 eng	0.0	5866.4
72		DRIVE SHAFT, FAN	LH	3071955-6	01P12321	7/06/2001	0 cyc	0	4329
72		DRIVE SHAFT, FAN	LH	3071955-6	01P12321	7/06/2001	0.0 eng	0.0	5815.0
72		DRIVE SHAFT, FAN	RH	3071955-6	01P12320	7/03/2001	0 cyc	0	4532
72		DRIVE SHAFT, FAN	RH	3071955-6	01P12320	7/03/2001	0.0 eng	0.0	5866.4
72		DUCT, TURBINE INTERSTAGE TRANSITION	LH	3072726-8	010134504588	7/06/2001	0 cyc	0	4329
72		DUCT, TURBINE INTERSTAGE TRANSITION	LH	3072726-8	010134504588	7/06/2001	0.0 eng	0.0	5815.0
72		DUCT, TURBINE INTERSTAGE TRANSITION	RH	3072726-8	010134503717	7/03/2001	0 cyc	0	4532
72		DUCT, TURBINE INTERSTAGE TRANSITION	RH	3072726-8	010134503717	7/03/2001	0.0 eng	0.0	5866.4
72		GEARBOX, ACCESSORY	LH	3070003-26	S1555	7/06/2001	0 cyc	0	4329
72		GEARBOX, ACCESSORY	LH	3070003-26	S1555	7/06/2001	0.0 eng	0.0	5815.0
72		GEARBOX, ACCESSORY	RH	3070003-26	S1557	7/03/2001	0 cyc	0	4532
72		GEARBOX, ACCESSORY	RH	3070003-26	S1557	7/03/2001	0.0 eng	0.0	5866.4
72		GEARBOX, TRANSFER	LH	3070093-12	P10235	7/06/2001	0 cyc	0	4329
72		GEARBOX, TRANSFER	LH	3070093-12	P10235	7/06/2001	0.0 eng	0.0	5815.0
72		GEARBOX, TRANSFER	RH	3070093-12	P10244	7/03/2001	0 cyc	0	4532
72		GEARBOX, TRANSFER	RH	3070093-12	P10244	7/03/2001	0.0 eng	0.0	5866.4
72		HARNESS, ITT	RH	3073595-1	2415027700108	3/12/2024	4357 cyc	0	175
72		HARNESS, ITT	RH	3073595-1	2415027700108	3/12/2024	5603.4 eng	0.0	263.0
72		IGNITOR PLUG - 6 O'CLOCK	LH	3074541-4	NSN	2/29/2024	4154 cyc	0	175
72		IGNITOR PLUG - 6 O'CLOCK	LH	3074541-4	NSN	2/29/2024	5557.0 eng	0.0	258.0
72		IGNITOR PLUG - 6 O'CLOCK	RH	3074541-4	N/A	3/12/2024	4357 cyc	0	175
72		IGNITOR PLUG - 6 O'CLOCK	RH	3074541-4	N/A	3/12/2024	5603.4 eng	0.0	263.0
72		IGNITOR PLUG - 7 O'CLOCK	LH	3074541-4	NSN	2/29/2024	4154 cyc	0	175
72		IGNITOR PLUG - 7 O'CLOCK	LH	3074541-4	NSN	2/29/2024	5557.0 eng	0.0	258.0
72		IGNITOR PLUG - 7 O'CLOCK	RH	3074541-4	N/A	3/12/2024	4357 cyc	0	175
72		IGNITOR PLUG - 7 O'CLOCK	RH	3074541-4	N/A	3/12/2024	5603.4 eng	0.0	263.0
72		IMPELLER, HP COMPRESSOR RADIAL	LH	3075765-1	000322908135	7/06/2001	0.0 eng	0.0	5815.0
72		IMPELLER, HP COMPRESSOR RADIAL	RH	3075765-1	000322908115	7/03/2001	0.0 eng	0.0	5866.4
72		LINER, COMBUSTION	LH	3073774-2	97P24198	12/08/2014	3092 cyc	0	1237
72		LINER, COMBUSTION	LH	3073774-2	97P24198	12/08/2014	4069.2 eng	0.0	1745.8

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
72		MANIFOLD ASSEMBLY,FUEL	LH	3073591-1	93-504	2/29/2024	4154 cyc	0	175
72		MANIFOLD ASSEMBLY,FUEL	LH	3073591-1	93-504	2/29/2024	5557.0 eng	0.0	258.0
72		MANIFOLD ASSEMBLY,FUEL	RH	3073591-1	4-308C	3/12/2024	4357 cyc	0	175
72		MANIFOLD ASSEMBLY,FUEL	RH	3073591-1	4-308C	3/12/2024	5603.4 eng	0.0	263.0
72		PNEUMATIC PACK	LH	109696-4-1	10949	6/06/2003	162 cyc	0	4167
72		PNEUMATIC PACK	LH	109696-4-1	10949	6/06/2003	234.9 eng	0.0	5580.1
72		ROTOR, HP TURBINE WHEEL	LH	3072732-2	1718244924109	2/29/2024	5557.0 eng	0.0	258.0
72		ROTOR, HP TURBINE WHEEL	RH	3072732-2	1718244924111	3/12/2024	5603.4 eng	0.0	263.0
72		SEAL ROTOR (THRUST BALANCE PISTON)	LH	3072979-1	000322900325	7/06/2001	0 cyc	0	4329
72		SEAL ROTOR (THRUST BALANCE PISTON)	LH	3072979-1	000322900325	7/06/2001	0.0 eng	0.0	5815.0
72		SEAL ROTOR (THRUST BALANCE PISTON)	RH	3072979-1	000322900326	7/03/2001	0 cyc	0	4532
72		SEAL ROTOR (THRUST BALANCE PISTON)	RH	3072979-1	000322900326	7/03/2001	0.0 eng	0.0	5866.4
72		SEAL,ROTATING	LH	3072621-1	01P13709	7/06/2001	0 cyc	0	4329
72		SEAL,ROTATING	LH	3072621-1	01P13709	7/06/2001	0.0 eng	0.0	5815.0
72		SEAL,ROTATING	RH	3072621-1	01P13653	7/03/2001	0 cyc	0	4532
72		SEAL,ROTATING	RH	3072621-1	01P13653	7/03/2001	0.0 eng	0.0	5866.4
72		SHAFT, HP SHOULDER	LH	3071441-1	01P12146	7/06/2001	0 cyc	0	4329
72		SHAFT, HP SHOULDER	LH	3071441-1	01P12146	7/06/2001	0.0 eng	0.0	5815.0
72		SHAFT, HP SHOULDER	RH	3071441-1	01P12151	7/03/2001	0 cyc	0	4532
72		SHAFT, HP SHOULDER	RH	3071441-1	01P12151	7/03/2001	0.0 eng	0.0	5866.4
72		TIE ROD	LH	3073049-1	011119500716	7/06/2001	0 cyc	0	4329
72		TIE ROD	LH	3073049-1	011119500716	7/06/2001	0.0 eng	0.0	5815.0
72		TIE ROD	RH	3073049-1	011119500677	7/03/2001	0 cyc	0	4532
72		TIE ROD	RH	3073049-1	011119500677	7/03/2001	0.0 eng	0.0	5866.4
72		VALVE,BLEED SURGE	LH	978812-5-1	P-3284	12/22/2010	2228 cyc	0	2101
72		VALVE,BLEED SURGE	LH	978812-5-1	P-3284	12/22/2010	2728.9 eng	0.0	3086.1
72		VALVE,BREATHERR	RH	3075323-3	1842C	12/19/2003	498.8 eng	0.0	5367.6
73		FILTER ELEMENT,FUEL	LH	897830-1	N/A	2/29/2024	5557.0 eng	0.0	258.0
73		FILTER ELEMENT,FUEL	RH	897830-1	N/A	3/12/2024	5603.4 eng	0.0	263.0
73		COMPUTER,FUEL CONTROL (DEEC)	LH	2119020-3004	11-BC0050	6/06/2003	162 cyc	0	4167
73		COMPUTER,FUEL CONTROL (DEEC)	LH	2119020-3004	11-BC0050	6/06/2003	234.9 eng	0.0	5580.1
73		COMPUTER,FUEL CONTROL (DEEC)	RH	2119010-3004	61AJ0136	7/03/2001	0 cyc	0	4532
73		COMPUTER,FUEL CONTROL (DEEC)	RH	2119010-3004	61AJ0136	7/03/2001	0.0 eng	0.0	5866.4
73		CONTROL UNIT,FUEL	LH	3070800-73	A4158CPT	2/29/2024	4154 cyc	0	175
73		CONTROL UNIT,FUEL	LH	3070800-73	A4158CPT	2/29/2024	5557.0 eng	0.0	258.0
73		CONTROL UNIT,FUEL	RH	3070800-22	A7574C	1/13/2013	2874 cyc	0	1658
73		CONTROL UNIT,FUEL	RH	3070800-22	A7574C	1/13/2013	3498.3 eng	0.0	2368.1
73		FILTER ELEMENT,FUEL	LH	897830-1	N/A	2/29/2024	4154 cyc	0	175
73		FILTER ELEMENT,FUEL	RH	897830-1	N/A	3/12/2024	4357 cyc	0	175
73		PUMP,FUEL	LH	3070850-48	MX488060	5/19/2003	234.9 eng	22.0	5602.1
73		PUMP,FUEL	RH	3070850-48	MX640904	7/03/2001	0 cyc	0	4532
73		PUMP,FUEL	RH	3070850-48	MX640904	7/03/2001	0.0 eng	0.0	5866.4
73		TRANSMITTER,FUEL FLOW	LH	6600097-4	1217	3/17/2011	2360 ldg	0	2161
73		TRANSMITTER,FUEL FLOW	LH	6600097-4	1217	3/17/2011	2932.1 hrs	0.0	3030.0

COMPONENT INVENTORY REPORT

LEARJET 31232

7/03/2026
N68VP

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
73		VALVE, FLOW DIVIDER/DRAIN	LH	394396-2-1	P3406	1/13/2003	231.7 eng	0.0	5583.3
79		OIL CHANGE, ENGINE	LH	MOBIL 254	N/A	2/29/2024	5557.0 eng	0.0	258.0
79		OIL CHANGE, ENGINE	RH	MOBIL 254	N/A	11/04/2021	5342.0 eng	0.0	524.4
79		FILTER, OIL	LH	3070945-1	N/A	6/07/2024	4174 cyc	0	155
79		FILTER, OIL	LH	3070945-1	N/A	6/07/2024	5589.1 eng	0.0	225.9
79		FILTER, OIL	RH	3070945-1	N/A	6/07/2024	4377 cyc	0	155
79		FILTER, OIL	RH	3070945-1	N/A	6/07/2024	5635.5 eng	0.0	230.9
79		OIL CHANGE, ENGINE	LH	MOBIL 254	N/A	2/29/2024	4154 cyc	0	175
79		OIL CHANGE, ENGINE	RH	MOBIL 254	N/A	11/04/2021	4181 cyc	0	351
79		PUMP, OIL	LH	3060785-3	001405700338	4/28/2017	3422 cyc	0	907
79		PUMP, OIL	LH	3060785-3	001405700338	4/28/2017	4521.9 eng	0.0	1293.1
79		PUMP, OIL	RH	3071949-12	91-14057-2408	3/12/2024	4357 cyc	0	175
79		PUMP, OIL	RH	3071949-12	91-14057-2408	3/12/2024	5603.4 eng	0.0	263.0
79		VALVE, ENGINE FILTER BYPASS	RH	3070246-5	UNKNOWN	11/25/2015	4405.4 hrs	0.0	1556.7

NOTE: # INDICATES ITEM HAS BEEN CHANGED TO AN ON CONDITION STATUS.

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232

**7/03/2026
N68VP**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 2000-24-19		PROCEDURES FOR DOWNING THE FLIGHTCREW OXYGEN MASK WHEN THE CABIN ALTITUDE WARNING HORN IF ACTIVATED	LEARJET	DATE:	DATE:
1/04/2001	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 2001-07-11		INSPECTION AND REPLACEMENT OF DEFECTIVE GOODYEAR TIRES P/N 178K23-5	LEARJET	DATE: 8/29/2001	DATE:
5/01/2001	ONE TIME		C/W BY VISUAL INSPECTION	TIME: 5.5	TIME:
				LD/CY:	LD/CY:
AD 2001-15-17		MODIFY THE ALTITUDE ENCODER INPUTS OF THE CTL-92 TRANSPONDER CONTROL PANELS	ROCKWELL COLLINS	DATE: 6/27/2007	DATE:
8/20/2001	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2001-18-05		INSPECTION OF ALL GOODYEAR FLIGHT EAGLE TIRES, 34X9.25-16 210MPH P/N 348F83-2	GOODYEAR	DATE: 7/14/2006	DATE:
9/24/2001	ONE TIME		N/A P/N 178K23-5 INSTALLED	TIME: 1280.7	TIME:
				LD/CY: 1020	LD/CY:
AD 2001-22-14		REPLACEMENT OF FIRE EXTINGUISHER SYSTEM CARTRIDGES	OVERLAND AVIATION	DATE: 6/27/2007	DATE:
12/10/2001	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2001-23-17		MODIFICATION OF GNS 430 UNITS WHICH COULD RESULT IN CDI OR HSI DISPLAYING INACCURATE COURSE DEVIATIONS.	GARMIN	DATE: 6/27/2007	DATE:
12/28/2001	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2002-06-05		TESTING COLLINS TRANSPONDERS MODE C 621A-3 TRANSPONDERS EQUIPPED WITH P/N P/N 522-2703-XXX	ROCKWELL COLLINS	DATE:	DATE:
4/26/2002	ONE TIME		N/A MST-67A INSTALLED	TIME:	TIME:
				LD/CY:	LD/CY:
AD 2002-06-06		TEST AND OR MODIFY COLLINS TDR-94 TRANSPONDERS	ROCKWELL COLLINS	DATE:	DATE:
5/03/2002	ONE TIME		N/A MST-67A INSTALLED	TIME:	TIME:
				LD/CY:	LD/CY:
AD 2002-13-07		TO PREVENT FAILURE OF THE IRU (INERTIAL REFERENCE UNIT) P/N HG1075AB05 WHEN TRANSITIONING TO EMERG POWER	HONEYWELL AVIONICS	DATE: 6/27/2007	DATE:
8/09/2002	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2002-14-19		INSTALL A MODIFIED AIR DATA COMPUTER ADC-85/85A/850C/850D/850E/850F-34-62	ROCKWELL COLLINS	DATE: 6/27/2007	DATE:
8/23/2002	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2002-17-01		DISABLE FOOT WARMER BY INSTALLING A COLLARON ON FOOT WARMER CIRCUIT BREAKER	LEARJET	DATE:	DATE:
9/12/2002	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 2002-20-09		INSPECTION OF THE AFD-3010 ADAPTIVE FLIGHT DISPLAY UNIT TO DETERMINE THE S/N AND DATE CODE	ROCKWELL COLLINS	DATE: 6/27/2007	DATE:
11/12/2002	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2002-22-13		REPLACE OR MODIFY THE FMC-4200,FMS-5000, OR FMC-6000 UNITS	ROCKWELL COLLINS	DATE: 6/27/2007	DATE:
12/20/2002	ONE TIME		N/A	TIME: 1635.0	TIME:
				LD/CY:	LD/CY:
AD 2003-26-14		REPLACEMENT OF HAND HELD FAULTY FIRE EXTINGUISHERS WHICH DO NOT FULLY DISCHARGE	WATER KIDDE	DATE: 7/28/2004	DATE:
2/20/2004	ONE TIME		N/A AMEREX INSTALLED	TIME: 702.2	TIME:
				LD/CY:	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232

**7/03/2026
N68VP**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 2004-03-08 3/15/2004	ONE TIME	TO PREVENT SIGNIFICANT STRUCTUAL DAMAGE TO ENGINE PYLONS	LEARJET N/A PER SB31-54-02	DATE: 5/10/2011 TIME: 2980.4 LD/CY:	DATE: TIME: LD/CY:
AD 2004-08-15 6/07/2004	ONE TIME	INSPECT & MODIFY TAWS8000 TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER SUPERSEDEDS AD 2003-13-08	GOODRICH AVIONICS N/A EQUIPMENT NOT INSTALLED	DATE: 10/23/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 2004-08-16 6/01/2004	ONE TIME	MODIFY NARCO AT150 TRANSPONDERS TO PREVENT NOT RESPONDING & RECOGNIZING S MODE INTERROGRATIONS	NARCO AVIONICS N/A MST-67A INSTALLED	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2004-10-15 7/09/2004	ONE TIME	TO PREVENT INTERROGATING AIRCRAFT FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM GARMIN GTX 330/330D TRANSPONDERS	GARMIN N/A MST-67A INSTALLED	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2004-13-20 8/03/2004	ONE TIME	TO PREVENT THE GPS NAVIGATION UNIT, UNDER CERTAIN CONDITIONS FROM PROVIDING ERRONEOUS CROSS-DEVIATION	GARMIN N/A	DATE: 6/27/2007 TIME: 1635.0 LD/CY:	DATE: TIME: LD/CY:
AD 2004-16-14 9/13/2004	ONE TIME	TO PREVENT THE TR/RA VSI-TCAS INDICATOR FROM DISPLAYING "RA FAIL" MESSAGE DURING MULTI-AIRCRAFT ENCOUNTER	THALES AVIONICS N/A	DATE: 6/27/2007 TIME: 1635.0 LD/CY:	DATE: TIME: LD/CY:
AD 2005-01-19 2/23/2005	ONE TIME	TO PREVENT INTERROGATING AIRCRAFT FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM GARMIN GTX 330/330D TRANSPONDERS	GARMIN N/A MST-67A INSTALLED	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2005-07-27 5/16/2005	ONE TIME	INSPECTION OF SEAT CENTER CROSSMEMBER FOR CRACKS; P/N DM03437-1	AVIOINTERIORS N/A	DATE: 6/27/2007 TIME: 1635.0 LD/CY:	DATE: TIME: LD/CY:
AD 2005-13-36 8/09/2005	ONE TIME	DO A DETAILED INSPECTION OF THE CENTER BALL OF THE AILERON CONTROL CABLE OR CABLES FOR A DEFECTIVE SWAGE	LEARJET C/W SB A31-27-25	DATE: 8/26/2005 TIME: 942.4 LD/CY:	DATE: TIME: LD/CY:
AD 2005-16-09 LHAFT 9/13/2005	ONE TIME	TO PREVENT IMBALANCE OF THE FUEL LOADS IN THE WINGS OF AIRCRAFT: REPLACEMENT OF TIP TANK FLAPPER VALVE	LEARJET N/A BY AIRCRAFT MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2006-16-18 9/25/2006	ONE TIME	PLACARD & REVISE AIRCRAFT FLIGHT MANUAL (AFM) FOR AIRCRAFT EQUIPPED WITH A SANDEL ST3400 TAWS	SANDEL AVIONICS N/A EQUIPMENT NOT INSTALLED	DATE: 10/23/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 2006-19-04 10/17/2006	ONE TIME	REVISE NORMAL PROCEDURES OF AIRPLANE FLIGHT MANUAL (AFM) FOR AIRCRAFT EQUIPPED WITH HONEYWELL TRANSPONDERS	HONEYWELL N/A EQUIPMENT NOT INSTALLED	DATE: 10/23/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 2006-22-05 12/01/2006	ONE TIME	PERFORM AD ONE TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR SUPERSEDED BY AD 2010-07-02	HONEYWELL N/A	DATE: 6/27/2007 TIME: 1635.0 LD/CY:	DATE: TIME: LD/CY:
AD 2007-04-18 3/23/2007	ONE TIME	MODIFY THE LEFT & RIGHT HAND STANDY FUEL PUMP SWITCHES & INSERT AFM REVISION	LEARJET N/A PER SB 31-28-07 R3	DATE: 3/20/2009 TIME: 2201.7 LD/CY:	DATE: TIME: LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232

**7/03/2026
N68VP**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 2007-17-17		INSPECTION TO PREVENT PENETRATION OF FLAMMABLE LIQUIDS THROUGH ENGINE FIREWALL INTO ENGINE PYLON	LEARJET	DATE: 12/10/2008 TIME: 2144.7 LD/CY:	DATE: TIME: LD/CY:
10/02/2007	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
AD 2007-26-11		REMOVAL OF INTERTECHNIQUE ALUMINUM PORTABLE OXYGEN CYLINDERS	INTERTECHNIQUE	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
1/28/2008	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2009-05-08		UPGRADE TRIMBLE FREEFLIGHT SYS TO PREVENT A PILOT FROM MAKING UNSAFE DECISION BASE OF ERRONEOUS INFO	TRIMBLE	DATE: 10/22/2009 TIME: 2444.1 LD/CY: 1985	DATE: TIME: LD/CY:
4/20/2009	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2010-01-03		INSPECT PROTABE HALON FIRE EXTINGUISGER FOR EFFECTIVE P/N AND SERIAL NUMBER SEE SB 26-115	FIRE FIGHT ENT	DATE: 4/06/2010 TIME: 2598.1 LD/CY: 2098	DATE: TIME: LD/CY:
1/20/2010	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2010-04-16		INSPECT PROTABE HALON FIRE EXTINGUISGER FOR EFFECTIVE P/N AND SERIAL NUMBER	SICLI	DATE: 9/24/2010 TIME: 2739.5 LD/CY:	DATE: TIME: LD/CY:
3/08/2010	ONE TIME		N/A NOT INSTALLED		
AD 2010-07-02		PERFORM AD ONE TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR HONEYWELL PRIMUS II NV-850 NAV RECEIVER	HONEYWELL	DATE: 10/02/2012 TIME: 3462.6 LD/CY:	DATE: TIME: LD/CY:
5/03/2010	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2010-11-05		INSPECTION OF OXYGEN CYLINDER FOR EFFECTIVE S/N FOR REPLACEMENT	AVOX	DATE: 9/24/2010 TIME: 2739.5 LD/CY:	DATE: TIME: LD/CY:
7/06/2010	ONE TIME		N/A NOT INSTALLED		
AD 2011-01-09		INSPECT AIRCRAFT RECORDS TO DETERMINE IF PBE PROTECTIVE BREATHING EQUIP P/N 119003-11 & EFFECTED S/N'S ARE INSTALLED	B/E AEROSPACE	DATE: 6/07/2011 TIME: 3006.2 LD/CY:	DATE: TIME: LD/CY:
2/09/2011	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2011-14-08		DO A RECORD CHECK OR VISUAL INSPECTION FOR EFFECTED PASSENGER OXY MASKS LISTED IN BE AEROSPACE SB 174080-35-04	BE AEROSPACE	DATE: 9/04/2014 TIME: 4139.8 LD/CY: 3214	DATE: TIME: LD/CY:
8/09/2011	ONE TIME		N/A EQUIPMENT NOT INSTALLED		
AD 2012-02-08		UPGRADE SOFTWARE FOR AVIATION COMMUNICATION & SURVELLANCE SYSTEMS (ACSS) TCAS	ACSS	DATE: 3/26/2015 TIME: 4255.0 LD/CY: 3288	DATE: TIME: LD/CY:
3/13/2012	ONE TIME		N/A BY PART NUMBER INSTALLED		
AD 2012-26-15		REMOVAL OF FAULTY AIR DATA COMPUTER PRESSURE TRANSDUCERS OR PERFORM A TGHIS AD HAS BEEN RECINDED	HONEYWELL	DATE: 7/22/2013 TIME: 3774.2 LD/CY:	DATE: TIME: LD/CY:
12/03/2014	ONE TIME		N/A NOT INSTALLED		
AD 2015-08-07		INSPECT INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO SEE IF EFFECTIVE P/N INSTALLED	ZODIAC AERO	DATE: 5/15/2017 TIME: 4669.7 LD/CY: 3601	DATE: TIME: LD/CY:
6/16/2015	ONE TIME		N/A		
AD 2015-10-51E		INCORPORATE THE OPERATIONAL LIMITATIONS LISTED IN PARA (G)(1)(I) & (II) OF THIS AD INTO AFM OR AFMS AS APPLICABLE	AVIDYNE AEROSPACE	DATE: 6/17/2015 TIME: 4294.3 LD/CY: 3314	DATE: TIME: LD/CY:
5/20/2015	ONE TIME		N/A BY PART NUMBER INSTALLED		
AD 2016-11-20 (G)		REPLACEMENT OF PBE DUE TO FIRE UPON ACTIVATION BY CREWMEMBER P/N 119003-11 SUPERSEDED BY AD 2017-18-12	B/E AEROPSACE	DATE: 11/16/2016 TIME: 4607.0 LD/CY: 3551	DATE: TIME: LD/CY:
7/15/2016	ONE TIME		N/A EQUIPMENT NOT INSTALLED		

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232					7/03/2026 N68VP
DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
EFFECTIVE DATE	RECURRS		METHOD		
AD 2017-04-06		REPLACE AFFECTED ALTIMETERS 5934 SERIES	UNITED INSTRUMENTS	DATE: 10/11/2018	DATE:
		MANUFACTURED BETWEEN JAN 2015 &		TIME: 4823.4	TIME:
4/07/2017	ONE TIME	FEB 2016	AFFECTED ALTIMETER NOT INSTALLED	LD/CY: 3674	LD/CY:
AD 2017-04-15		DO A DETAIL INSPECTION OF THE CENTER	LEARJET	DATE:	DATE:
		BALL OF THE AILERON CONTROL CABLES		TIME:	TIME:
4/04/2017	ONE TIME	FOR DEFECTIVE SWAGE	N/A BY AIRCRAFT MODEL	LD/CY:	LD/CY:
AD 2017-11-11		REPLACE ,PLACARD & DISABLE OR MODIFY	NAVWORX	DATE: 12/19/2017	DATE:
		MODEL ADS600 ADS-B UNIVERSAL ACCESS		TIME: 4685.9	TIME:
7/11/2017	ONE TIME	TRANSCIVER UNITS	N/A BY PART NUMBER INSTALLED	LD/CY: 3612	LD/CY:
AD 2017-16-01		DO A GENERAL VISUAL INSPECTION OF	AMER-KING	DATE: 10/11/2018	DATE:
		AK-450 OR AK-451 ELT FOR DISCREPANCIES		TIME: 4823.4	TIME:
10/24/2017	ONE TIME		N/A AFFECTED ELT NOT INSTALLED	LD/CY: 3674	LD/CY:
AD 2017-18-12 (G)		REPLACEMENT OF PBE DUE TO FIRE UPON	B/E AEROPSACE	DATE: 11/16/2016	DATE:
		ACTIVATION BY CREWMEMBER		TIME: 4607.0	TIME:
10/16/2017	ONE TIME	P/N 119003-11	N/A EQUIPMENT NOT INSTALLED	LD/CY: 3551	LD/CY:
ad 2018-19-04		REPLACE THE NOSE ROLLER SUPORT BRACKET	LEARJET	DATE: 10/06/2020	DATE:
		& RIB SUPPORT STRUCTURE		TIME: 5137.7	TIME:
10/23/2018	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 2018-21-14		REPLACEMENT OF OXY MASK INFLATABLE	ZODIAC	DATE: 5/13/2022	DATE:
		HARNESS ASSEMBLY P/N MXH20-1 OR MXH21-1		TIME: 5502.2	TIME:
3/27/2019	ONE TIME		FOUND P/C/W	LD/CY: 4195	LD/CY:
AD 2019-07-10		REMOVAL OF AHRS P/N 145130-2000,	NORTHROP GRUMMAN	DATE: 6/14/2019	DATE:
		145130-201,145130-7000,145130-7001 &		TIME: 4874.2	TIME:
5/29/2019	ONE TIME	145130-7100 FROM SERVICE	N/A EQUIPMENT NOT INSTALLED	LD/CY: 3736	LD/CY:
AD 2020-10-05		REVISE AFM AIRCRAFT FLIGHT MANUAL AND	ROCKWELL COLLINS	DATE: 6/09/2021	DATE:
		DISABLE AUTOMATIC TEMP COMPENSATION		TIME: 5304.8	TIME:
6/24/2020	ONE TIME	FEATURE OF FLIGHT MANAGEMENT SYSTEM	N/A EQUIPMENT NOT INSTALLED	LD/CY: 4058	LD/CY:
AD 2020-18-51		REVISION OF AFM AIRCRAFT FLIGHT MANUAL	BENDIX/KING	DATE: 10/06/2020	DATE:
		PROHIBITING IFR OR NIGHT VFR FLIGHT IF		TIME: 5137.7	TIME:
8/28/2020	ONE TIME	WITH ATTITUDE INDICATOR P/N 306171	N/A EQUIPMENT NOT INSTALLED	LD/CY:	LD/CY:
AD 2021-05-17		UPGRADE FDSA-6500 FIELD SOFTWARE	ROCKWELL COLLINS	DATE: 6/09/2021	DATE:
		LIMITATIONS FOR USING TCAS		TIME: 5304.8	TIME:
4/29/2021	ONE TIME		N/A EQUIPMENT NOT INSTALLED	LD/CY: 4058	LD/CY:
AD 2021-05-17		REVISE THE FLIGHT MANUAL (FMS)	ROCKWELL COLLINS	DATE: 6/09/2021	DATE:
		LIMITATIONS FOR USING TCAS & PLACARD		TIME: 5304.8	TIME:
4/29/2021	ONE TIME	TCAS USE	N/A EQUIPMENT NOT INSTALLED	LD/CY: 4058	LD/CY:
AD 2021-07-13		INSPECT THE SEAT BUCKLES FOR CRACKS	PACIFIC SCIENTIFIC	DATE: 11/04/2021	DATE:
				TIME: 5442.7	TIME:
5/11/2021	ONE TIME	SUPERSEDED BY AD 2024-26-02	N/A TO INSTALLED SEATBELT BUCKLES	LD/CY: 4169	LD/CY:
AD 2021-08-07		REPLACE ROCKWELL GPS P/N 822-2189-100	ROCKWELL COLLINS	DATE: 5/17/2023	DATE:
				TIME: 5646.4	TIME:
5/12/2021	ONE TIME		N/A EQUIPMENT NOT INSTALLED	LD/CY: 4309	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE

LEARJET 31232

7/03/2026

N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
EFFECTIVE DATE	RECURRS		METHOD		
ad 2021-08-15	ONE TIME	UPDATE SOFTWARE ON GARMIN GTS 825, GTS 855 OR GTS 8000 TCAS PROCESSOR	GARMIN	DATE: 5/17/2023	DATE:
5/17/2021			N/A EQUIPMENT NOT INSTALLED	TIME: 5646.4 LD/CY: 4309	TIME: LD/CY:
AD 2021-23-12	ONE TIME	REVISE THE AFM TO INCORPORATE THIS AD ABOUT 5G INTERFERENCE WITH RADIO ALTIMETER,SUPERSEDED BY AD 2023-10-02	T CAT AIRCRAFT	DATE: 1/03/2022	DATE:
12/09/2021			C/W AFM REVISION	TIME: 5490.1 LD/CY: 4188	TIME: LD/CY:
AD 2022-05-01	ONE TIME	REPLACEMENT OF DEFECTIVE SPOILER THAT THE LIFE LIMIT WAS EXTENDED USING RESTORE AIRCRAFT SALES EXTENSION LIMIT	LEARJET	DATE:	DATE:
3/09/2022			N/A BY AIRCRAFT MODEL	TIME: LD/CY:	TIME: LD/CY:
AD 2023-10-02	ONE TIME	REVISE THE AFM TO INCORPORATE THIS AD ABOUT 5G INTERFERENCE WITH RADIO ALTIMETER,SUPERSEDES AD 2021-23-12	T CAT AIRCRAFT	DATE: 6/30/2023	DATE:
5/26/2023			C/W AFM REVISION	TIME: 5660.9 LD/CY: 4318	TIME: LD/CY:
AD 2024-26-02	ONE TIME	INSPECT THE SEAT BUCKLES FOR CRACKS SUPERSEDES AD 2021-07-13	PACIFIC SCIENTIFIC	DATE: 12/31/2025	DATE:
3/07/2025			N/A BY PART NUMBER INSTALLED	TIME: 5853.4 LD/CY: 4454	TIME: LD/CY:
AD 2025-16-09	ONE TIME	INSPECT BUCKLE P/N 1111475 SCREWS FOR CRACKED OR LOOSE AND MISSING SCREW HEADS	PACIFIC SCIENTIFIC	DATE: 12/31/2025	DATE:
9/22/2025			N/A BY PART NUMBER INSTALLED	TIME: 5853.4 LD/CY: 4454	TIME: LD/CY:
AD 2025-25-02	ONE TIME	INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT BBS SUPERSEDED BY AD 2025-26-06	SAFRAN AEROSYS	DATE:	DATE:
12/24/2025			N/A EQUIPMENT NOT INSTALLED	TIME: LD/CY:	TIME: LD/CY:
AD 2026-03-09	ONE TIME	REPLACEMENT OF PBE PORTABLE BREATHING EQUIPMENT P/N 15-40F-11 & 15-40D-80	SAFRAN AEROSYS	DATE:	DATE:
3/12/2026			N/A EQUIPMENT NOT INSTALLED	TIME: LD/CY:	TIME: LD/CY:
AD 2026-13-02	ONE TIME	REPLACE OR MODIFY RADAR ALTIMETER TO PREVENT 5G INTERFERENCE	T CAT AIRCRAFT	DATE:	DATE: 7/01/2026
7/01/2026				TIME: LD/CY:	TIME: LD/CY:
AD 74-08-09	R3	INSPECT LAVATORY WASTE RECEPTACLE: TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS DROPPED IN RECEPT	T-CATEGORY	DATE: 6/22/2026	DATE:
3/28/2012	RECURRS		INSPECTED LAV RECEPTICLE & PLACARD	TIME: 5962.1 LD/CY: 4521	TIME: 6962.1 LD/CY:
AD 76-18-07	ONE TIME	TO DETERMINE THAT EACH INVERTER IS CONNECTED TO THE CORRECT POWER BUS	LEARJET	DATE:	DATE:
9/10/1976			N/A BY AIRCRAFT MODEL	TIME: LD/CY:	TIME: LD/CY:
AD 78-16-03	ONE TIME	TO PRECLUDE A FAILURE OF THE REFRIGERATION CONDENSER FAN P/N 6608059-3	LEARJET	DATE:	DATE:
8/17/1978			N/A BY AIRCRAFT MODEL	TIME: LD/CY:	TIME: LD/CY:
AD 78-25-02 A	ONE TIME	TO ASSURE PROPER LOCKING OF THE CABIN UPPER DOOR WHEN THE INSIDE HANDLE IS IN THE LOCKED POSITION: BOLT INSP/REPLACE	LEARJET	DATE:	DATE:
12/14/1978			N/A BY AIRCRAFT MODEL	TIME: LD/CY:	TIME: LD/CY:
AD 79-08-01	ONE TIME	TO PRECLUDE INADVERTENT THRUST REVERSER DEPLOYMENT AND POSSIBLE LOSS OF AIRCRAFT CONTROL	LEARJET	DATE:	DATE:
4/19/1982			N/A BY AIRCRAFT MODEL	TIME: LD/CY:	TIME: LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232

7/03/2026
N68VP

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 80-06-02		TO PRECLUDE TAKEOFF, OR CONTINUED FLITE AFTER A STARTER ASSIST AIR START, WITH AN UNANNUNCIATED FAILURE IN THE ELEC SYSTEM	LEARJET	DATE:	DATE:
3/24/1980	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 80-07-09		TO ASSURE THAT THE CABIN MAIN ENTRANCE UPPER DOOR WILL OPEN, IN THE EVENT OF AN EMERGENCY	LEARJET	DATE:	DATE:
5/01/1980	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 80-17-11		OVERLOAD FLIGHT CONDITION THAT COULD FAIL THE FORWARD ENGINE MOUNT	LEARJET	DATE:	DATE:
8/28/1980	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 80-19-09		POSSIBILITY OF FUEL CONTAMINATION, PRESENCE OF IGNITION SOURCES IN THE TAIL CONE SERVICE AREA: SUPERCEDES AD 80-09-06	LEARJET	DATE:	DATE:
12/11/1980	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 80-19-11		TO ASSURE THAT THE CREW IS PROVIDED ADDITIONAL INSTRUCTIONS FOR THE SAFE OPERATION OF ACFT: SUPERCEDES AD 80-16-06	LEARJET	DATE:	DATE:
10/09/1980	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 81-13-07		TO ENSURE OPERATION WITHOUT FUEL STARVATION	LEARJET	DATE:	DATE:
6/25/1981	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 82-01-05		PROPER OPERATION OF THE STALL WARNING ACCELEROMETER UNIT	LEARJET	DATE:	DATE:
4/10/1986	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 83-08-03		TO ASSURE THAT NO INTERFERENCE EXISTS BETWEEN RIGHT HAND ENGINE HYDRAULIC PRESSURE LINE AND WIRE BUNDLE	LEARJET	DATE:	DATE:
5/03/1983	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 84-19-06		TO PREVENT AILERON/TRIM TAB FLUTTER DUE TO A FAILURE OR DISCONNECT OF THE TAB CONTROL SYSTEM	LEARJET	DATE:	DATE:
10/22/1984	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 85-16-04		TO PREVENT DETERIORATE OF THE AIRPLANE LATERAL CONTROL CHARACTERISTICS	LEARJET	DATE:	DATE:
9/06/1985	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 86-05-05		RELOCATE THE BATTERY INLET VENT	LEARJET	DATE:	DATE:
1/19/1988	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 86-22-05 A LH/RH		INSPECTION OF UPPER FLAP SECTOR MOUNTING BRACKETS FOR CRACKS	LEARJET	DATE:	DATE:
11/10/1986	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 87-04-06		TO PREVENT THE POTENTIAL FOR OPERATIONS WITH UNSAFE FLIGHT DIRECTOR STEERING COMMANDS	LEARJET	DATE:	DATE:
3/09/1987	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
AD 89-12-01		TO PREVENT FAILURE OF DRAG CHUTE UPON DEPLOYMENT	LEARJET	DATE:	DATE:
7/03/1989	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE LEARJET 31232					7/03/2026
					N68VP
DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 91-03-08		TO PREVENT ELECTROMAGNETIC INTERFERENCE	LEARJET	DATE:	DATE:
		INVERTER P/N 18.95(); 25-415-3-OL;		TIME:	TIME:
2/12/1991	ONE TIME	250001-240G; 6900092; 6900054-54	N/A BY AIRCRAFT MODEL	LD/CY:	LD/CY:
AD 92-19-12		PREVENT ELECTRICAL ARCING & AN IN-FLIGHT	LEARJET	DATE:	DATE:
		FIRE		TIME:	TIME:
11/17/1992	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 94-26-01		PREVENT RAPID DECOMPRESSION OF THE	LEARJET	DATE:	DATE:
		AIRPLANE DUE TO CRACKING & FAILURE OF		TIME:	TIME:
12/09/1994	ONE TIME	OF CERTAIN OUTFLOW/SAFETY VALVES	N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 95-20-03 (b)		PREVENT RAPID DECOMPRESSION OF THE	LEARJET	DATE:	DATE:
		AIRPLANE DUE TO CRACKING & FAILURE OF		TIME:	TIME:
11/02/1995	ONE TIME	OF CERTAIN OUTFLOW/SAFETY VALVES	N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 95-21-03		TO PREVENT ELECTRICAL FAILURE OF THE	LEARJET	DATE:	DATE:
		MICROSWITCHES IN THE ENGINE FIRE PULL		TIME:	TIME:
10/26/1995	ONE TIME	SWITCH ASSEMBLY	N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 96-19-13		TO PREVENT DETERIORATION OF THE LATERAL	LEARJET	DATE:	DATE:
		CONTROL CHARACTERISTICS AS A RESULT OF		TIME:	TIME:
9/10/1996	ONE TIME	AILERON BUFFET OR BUZZ	N/A BY AIRCRAFT MODEL	LD/CY:	LD/CY:
AD 98-06-28		TO PREVENT ELECTRICAL ARCING &	LEARJET INC.	DATE:	DATE:
		SUBSEQUENT FIRE HAZARD		TIME:	TIME:
4/24/1998	ONE TIME	SUPERSEDES AD 96-11-07	N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 99-16-03		TO PREVENT UNDETECTED ACCRETION OF	LEARJET	DATE:	DATE:
		ICE ON THE LEADING EDGE OF THE		TIME:	TIME:
9/07/1999	ONE TIME	HORIZONTAL STABILIZER	N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
AD 99-23-19		TO PREVENT FAILURE OF THE SPOILER	LEARJET	DATE:	DATE:
		ACTUATOR		TIME:	TIME:
12/21/1999	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:

LH ENGINE AIRWORTHINESS DIRECTIVE GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
AD 2000-15-09		TO PREVENT FAILURE OF THE HPC IMPELLER P/N 3073393-1,3073394-1,3073433-1, 3073434-1,3073398-ALL,3073435-ALL	GARRETT	DATE: 12/08/2014	DATE:
LH				TIME: 4069.2	TIME: 8269.2
10/10/2000	RECURRS		SB A72-3641 R1	LD/CY: 3092	LD/CY:
AD 2001-23-09		TO PREVENT FAILURE OF THE FAN ROTOR DISK DUE TO FATIGUE CRACKING; SUPERSEDS AD 86-11-05 & AD 96-18-13	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
12/21/2001	ONE TIME		N/A PER DISC P/N	LD/CY: 1068	LD/CY:
AD 2005-05-15		INSPECTION OR REPLACEMENT OF DEFECTIVE LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS	GARRETT	DATE: 12/08/2014	DATE:
LH				TIME: 4069.2	TIME:
4/18/2005	ONE TIME		C/W SB72-3369	LD/CY: 3092	LD/CY:
AD 2005-13-07		REMOVAL FROM SERVICE OF LP 1ST & 2ND STAGE TURBINE ROTOR DISCS	GARRETT	DATE: 12/22/2010	DATE:
LH				TIME: 2728.9	TIME:
7/27/2005	ONE TIME		N/A PER SB 72-3682	LD/CY: 2228	LD/CY:
AD 2008-02-19		REMOVE AFFECTED HP TURBINE ROTOR DISCS P/N 3075772-1 WITH LISTED S/N FROM SB72-3720	GARRETT	DATE: 12/22/2010	DATE:
LH				TIME: 2728.9	TIME:
3/06/2008	ONE TIME		N/A P/N 3072732-2 INSTALLED	LD/CY: 2228	LD/CY:
AD 2008-19-12		TO PREVENT LPT BLADE SEPARATION	GARRETT	DATE: 12/22/2010	DATE:
LH				TIME: 2728.9	TIME:
10/27/2008	ONE TIME		N/A BY ENGINE MODEL	LD/CY: 2228	LD/CY:
AD 2010-06-11		TO PREVENT UNCONTAINED FAILURE OF THE 2ND & 3RD LPCR DISCS, 3072396-1 OR 3075190-1 OR 3072397-1 OR 3075192-1	GARRETT	DATE: 12/22/2010	DATE:
LH				TIME: 2728.9	TIME:
4/21/2010	ONE TIME		N/A BY P/N	LD/CY: 2228	LD/CY:
AD 2014-12-52		REVIEW ENGINE LOGS TO SEE IF THERE ARE LP2 BLADES P/N 3075424-1,-2 OR -3 INSTALLED WITH LESS THAN 250 HRS TSN	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
6/10/2014	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 2016-07-02		REPLACEMENT OF INTERSTAGE TURBINE DUCT (ITT) SEE AFFECTED S/N'S LISTED IN SB 731-72-3789	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
5/05/2016	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-11-06		TO PREVENT IMPROPER OPERATION OF FUEL CONTROL COMPUTER DUE TO VOLTAGE TRANSIENTS IN THE ELECTRICAL SYSTEM	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
9/23/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-13-09		TO DETECT THE IMPROPER CONFIGURATION OF THE FUEL PUMP	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
7/31/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-18-12		INSTALLATION OF REPLACEMENT FUEL CONTROL ASSEMBLIES, REPLACE THE HYDROMECHANICAL FUEL CONTROL ORIFICE ASSEMBLY	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
8/05/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-18-16		INTERNALLY INSPECT THE FUEL CONTROL COMPUTER	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
8/07/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-23-05		SERVICE LIFE FOR FUEL PUMPS	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
6/04/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:

LH ENGINE AIRWORTHINESS DIRECTIVE GARRETT P99591

7/03/2026

N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
AD 75-07-10		TO DETECT, PREVENT & CORRECT WEAR OF THE TRANSFER GEARBOX VERTICAL BEVEL GEAR BEARING SUPPORT	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
5/01/1975	ONE TIME		N/A GEARBOX SERIES	LD/CY: 1068	LD/CY:
AD 78-22-10		TO PREVENT FAILURE OF THE LOW PRESSURE ROTOR THRUST BALL BEARING WHICH COULD RESULT IN AN IMMEDIATE INFLITE SHUTDOWN	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
11/13/1978	ONE TIME		N/A BY ENGINE S/N	LD/CY:	LD/CY:
AD 80-16-04		TO PREVENT SEPARATION OF TIE ROD AND POTENTIAL MASSIVE ENGINE FAILURE P/N 3070065-1	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
8/07/1980	ONE TIME		N/A BY DATE OF MFG	LD/CY:	LD/CY:
AD 81-24-08 e(1)		TO PREVENT SEPARATION OF THE ENGINE REAR MOUNT FROM THE DUCT	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
1/06/1982	ONE TIME		N/A	LD/CY: 1068	LD/CY:
AD 82-23-03 A	R1	TO PREVENT FAILURE OF HIGH PRESSURE COMPRESSOR IMPELLERS DUE TO CRACKS IMPELLER P/N 3070274-1 OR 3072639-1	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
12/09/1983	ONE TIME		N/A PER P/N	LD/CY: 1068	LD/CY:
AD 86-03-01		INTERSTAGE TRANSITION DUCTS - INSPECTION TO PREVENT SEPARATION OF ENGINE REAR MOUNT FROM THE DUCT	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
2/24/1986	ONE TIME		N/A	LD/CY: 1068	LD/CY:
AD 86-11-05		FAILURE OF FAN ROTOR DISCS; PART NUMBER 3073436 AND 3072162 SUPERSEDED BY AD 2001-23-09	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
6/16/1986	ONE TIME		N/A PER DISC P/N	LD/CY: 1068	LD/CY:
AD 88-18-03		TO PREVENT UNCONTAINED ENGINE FAILURES APPLIES TO HP TURBINE ROTOR DISC P/N 3072316-2, -3 OR 3073110-1, -2	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
8/30/1988	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 89-22-16		TO PREVENT THE UNCOMMANDED ENGINE ACCELERATION OR DECELERATION: REPLACE AFFECTED DEEC,S	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
10/26/1989	ONE TIME		N/A PER P/N	LD/CY: 1068	LD/CY:
AD 90-03-04		REMOVAL AND REPLACEMENT OF HIGH PRESSURE TURBINE ROTOR DISCS P/N 3072316-2 ,-3 AND 3073110-1 ,-2	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
2/22/1990	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 90-24-06		INSPECTION TO DETECT DEFECTIVE THERMOCOUPLE LEAD ASSY P/N 3073950-1,-2, -7,-15, 3074175-1,RWK 3077031-1,-2	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
11/13/1990	ONE TIME		N/A	LD/CY: 1068	LD/CY:
AD 92-12-09		TO PREVENT FAILURE OF THE FIRST STAGE TURBINE ROTOR DISK SUPERSEDED BY AD 94-07-03	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
6/08/1992	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 92-21-06		TO PREVENT AN UNCONTAINED ENGINE FAILURE P/N 3072068-X, 3072544-X,3073015-X, OR 3073115-X LP TURBINE ROTOR DISKS	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
11/27/1992	ONE TIME		N/A	LD/CY: 1068	LD/CY:
AD 94-07-03		PREVENT UNCONTAINED FAILURE OF THE FIRST STAGE LP TURBINE DISK; LP TURBINE NOZZLE P/N 3072842-1 OR 3072319-1 THRU -8	GARRETT	DATE:	DATE:
LH				TIME:	TIME:
6/06/1994	ONE TIME		N/A BY DATE OF MFG	LD/CY:	LD/CY:

**LH ENGINE AIRWORTHINESS DIRECTIVE
GARRETT P99591**

**7/03/2026
N68VP**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 94-23-05 a		REMOVE FROM SERVICE FIRST & SECOND STAGE	GARRETT	DATE:	DATE:
LH		LPT DISKS WITH P/N 3072351-(),3072542-		TIME:	TIME:
12/01/1994	ONE TIME	()),3074103-1,3074105-1	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 95-07-02		TO PREVENT A LOW PRESSURE TURBINE DISK	GARRETT	DATE:	DATE:
LH		WEB SEPARATION		TIME:	TIME:
6/19/1995	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 96-04-01		UNCONTAIN FAN DISK FAILURE	GARRETT	DATE: 10/18/2006	DATE:
LH		P/N 3072162,3073436,3073539,3074529		TIME: 1270.2	TIME:
3/15/1996	ONE TIME	SUPERSEDES AD 93-25-16,AD 92-26-09	N/A PER DISC P/N	LD/CY: 1068	LD/CY:
AD 96-05-03		EDDY-CURRENT INSPECTION OF FAN ROTOR	GARRETT	DATE: 10/18/2006	DATE:
LH		DISC P/N 3072162-1 THRU -4, 3073436-1		TIME: 1270.2	TIME:
4/02/1996	ONE TIME	THRU -4;SUPERSEDES AD 91-08-13	N/A PER DISC P/N	LD/CY: 1068	LD/CY:
AD 96-18-13		TO PREVENT FAILURE OF THE FAN ROTOR DISK	GARRETT	DATE: 10/18/2006	DATE:
LH		DUE TO FATIGUE CRACKING; P/N 3072162-5,		TIME: 1270.2	TIME:
11/12/1996	ONE TIME	SUPERSEDED BY AD 2001-23-09	N/A PER DISC P/N	LD/CY: 1068	LD/CY:
AD 97-04-03		FAILURE OF FIRST STAGE LPT SEAL	GARRETT	DATE:	DATE:
LH		PLATE PART NO. 3073552-2 &		TIME:	TIME:
5/05/1997	ONE TIME	3074053-1	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 98-10-15		TO PREVENT FUEL SPRAYING ON AND	GARRETT	DATE:	DATE:
LH		AROUND ELECTRICAL COMPONENTS		TIME:	TIME:
5/19/1998	ONE TIME	DUE TO CRACKED FUEL LINE	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 98-17-01	R1	TO PREVENT CRACKED FUEL TUBES	GARRETT	DATE: 10/18/2006	DATE:
LH		SUPERSEDES AD 93-10-10		TIME: 1270.2	TIME:
11/29/1999	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:

RH ENGINE AIRWORTHINESS DIRECTIVE GARRETT P99590

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
AD 2000-15-09		TO PREVENT FAILURE OF THE HPC IMPELLER P/N 3073393-1,3073394-1,3073433-1, 3073434-1,3073398-ALL,3073435-ALL	GARRETT	DATE: 12/08/2014	DATE:
RH				TIME: 4117.1	TIME: 8317.1
10/10/2000	RECURRS		C/W SB A72-3641	LD/CY: 3302	LD/CY:
AD 2001-23-09		TO PREVENT FAILURE OF THE FAN ROTOR DISK DUE TO FATIGUE CRACKING; SUPERSEDS AD 86-11-05 & AD 96-18-13	GARRETT	DATE: 10/18/2006	DATE:
RH				TIME: 1381.9	TIME:
12/21/2001	ONE TIME		N/A BY P/N	LD/CY:	LD/CY:
AD 2005-05-15		INSPECTION OR REPLACEMENT OF DEFECTIVE LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS	GARRETT	DATE: 12/08/2014	DATE:
RH				TIME: 4117.1	TIME:
4/18/2005	ONE TIME		C/W SB 72-3369	LD/CY: 3302	LD/CY:
AD 2005-13-07		REMOVAL FROM SERVICE OF LP 1ST & 2ND STAGE TURBINE ROTOR DISCS	GARRETT	DATE: 10/18/2006	DATE:
RH				TIME: 1381.9	TIME:
7/27/2005	ONE TIME		N/A PER SB 72-3682	LD/CY:	LD/CY:
AD 2008-02-19		REMOVE AFFECTED HP TURBINE ROTOR DISCS P/N 3075772-1 WITH LISTED S/N FROM SB72-3720	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
3/06/2008	ONE TIME		N/A P/N 3072732-2 INSTALLED	LD/CY:	LD/CY:
AD 2008-19-12		TO PREVENT LPT BLADE SEPARATION	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
10/27/2008	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 2010-06-11		TO PREVENT UNCONTAINED FAILURE OF THE 2ND & 3RD LPCR DISCS, 3072396-1 OR 3075190-1 OR 3072397-1 OR 3075192-1	GARRETT	DATE: 9/24/2010	DATE:
RH				TIME: 2739.5	TIME:
4/21/2010	ONE TIME		N/A BY P/N	LD/CY:	LD/CY:
AD 2014-12-52		REVIEW ENGINE LOGS TO SEE IF THERE ARE LP2 BLADES P/N 3075424-1,-2 OR -3 INSTALLED WITH LESS THAN 250 HRS TSN	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
6/10/2014	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 2016-07-02		REPLACEMENT OF INTERSTAGE TURBINE DUCT (ITT) SEE AFFECTED S/N'S LISTED IN SB 731-72-3789	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
5/05/2016	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-11-06		TO PREVENT IMPROPER OPERATION OF FUEL CONTROL COMPUTER DUE TO VOLTAGE TRANSIENTS IN THE ELECTRICAL SYSTEM	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
9/23/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-13-09		TO DETECT THE IMPROPER CONFIGURATION OF THE FUEL PUMP	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
7/31/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-18-12		INSTALLATION OF REPLACEMENT FUEL CONTROL ASSEMBLIES, REPLACE THE HYDROMECHANICAL FUEL CONTROL ORIFICE ASSEMBLY	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
8/05/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-18-16		INTERNALLY INSPECT THE FUEL CONTROL COMPUTER	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
8/07/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 74-23-05		SERVICE LIFE FOR FUEL PUMPS	GARRETT	DATE:	DATE:
RH				TIME:	TIME:
6/04/1974	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:

RH ENGINE AIRWORTHINESS DIRECTIVE GARRETT P99590

7/03/2026
N68VP

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 75-07-10 RH 5/01/1975	ONE TIME	TO DETECT, PREVENT & CORRECT WEAR OF THE TRANSFER GEARBOX VERTICAL BEVEL GEAR BEARING SUPPORT	GARRETT N/A BY GEARBOX SERIES NO.	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 78-22-10 RH 11/13/1978	ONE TIME	TO PREVENT FAILURE OF THE LOW PRESSURE ROTOR THRUST BALL BEARING WHICH COULD RESULT IN AN IMMEDIATE INFLITE SHUTDOWN	GARRETT N/A BY ENGINE S/N	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 80-16-04 RH 8/07/1980	ONE TIME	TO PREVENT SEPARATION OF TIE ROD AND POTENTIAL MASSIVE ENGINE FAILURE P/N 3070065-1	GARRETT N/A BY DATE OF MFG	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 81-24-08 e(1) RH 1/06/1982	ONE TIME	TO PREVENT SEPARATION OF THE ENGINE REAR MOUNT FROM THE DUCT	GARRETT N/A PER SB 72-3159/72-3170	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 82-23-03 A RH 12/09/1983	ONE TIME	TO PREVENT FAILURE OF HIGH PRESSURE COMPRESSOR IMPELLERS DUE TO CRACKS IMPELLER P/N 3070274-1 OR 3072639-1	GARRETT N/A BY P/N	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 86-03-01 RH 2/24/1986	ONE TIME	INTERSTAGE TRANSITION DUCTS - INSPECTION TO PREVENT SEPARATION OF ENGINE REAR MOUNT FROM THE DUCT	GARRETT N/A PER SB 72-3309	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 86-11-05 RH 6/16/1986	ONE TIME	FAILURE OF FAN ROTOR DISCS PART NUMBER 3073436 AND 3072162 SUPERSEDED BY AD 2001-23-09	GARRETT N/A BY P/N	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 88-18-03 RH 8/30/1988	ONE TIME	TO PREVENT UNCONTAINED ENGINE FAILURES APPLIES TO HP TURBINE ROTOR DISC P/N 3072316-2, -3 OR 3073110-1, -2	GARRETT N/A BY ENGINE MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 89-22-16 RH 10/26/1989	ONE TIME	TO PREVENT THE UNCOMMANDED ENGINE ACCELERATION OR DECELERATION: REPLACE AFFECTED DEEC,S	GARRETT N/A BY P/N	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 90-03-04 RH 2/22/1990	ONE TIME	REMOVAL AND REPLACEMENT OF HIGH PRESSURE TURBINE ROTOR DISCS P/N 3072316-2 ,-3 AND 3073110-1 ,-2	GARRETT N/A BY ENGINE MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 90-24-06 RH 11/13/1990	ONE TIME	INSPECTION TO DETECT DEFECTIVE THERMOCOUPLE LEAD ASSY P/N 3073950-1,-2, -7,-15, 3074175-1,RWK 3077031-1,-2	GARRETT N/A PER SB 77-3020	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 91-08-13 RH 8/16/1993	ONE TIME	EDDY-CURRENT OR FLUORESCENT INSPECTION OF FAN ROTOR DISC P/N 3072162, 3073436 SUPERSEDED BY AD 96-05-03	GARRETT N/A PER SB A72-3432	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
AD 92-12-09 RH 6/08/1992	ONE TIME	TO PREVENT FAILURE OF THE FIRST STAGE TURBINE ROTOR DISK SUPERSEDED BY AD 94-07-03	GARRETT N/A BY ENGINE MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 92-21-06 RH 11/27/1992	ONE TIME	TO PREVENT AN UNCONTAINED ENGINE FAILURE P/N 3072068-X, 3072544-X,3073015-X, OR 3073115-X LP TURBINE ROTOR DISKS	GARRETT N/A PER SB 72-3474	DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:

RH ENGINE AIRWORTHINESS DIRECTIVE GARRETT P99590

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
AD 93-25-16 (B)		UNCONTAIN FAN DISK FAILURE	GARRETT	DATE: 10/18/2006	DATE:
RH		P/N 3073539-2 OR 3072162-2		TIME: 1381.9	TIME:
1/18/1994	ONE TIME	SUPERSEDED BY AD 96-04-01	N/A PER SB 72-3504	LD/CY:	LD/CY:
AD 94-07-03		PREVENT UNCONTAINED FAILURE OF THE FIRST	GARRETT	DATE:	DATE:
RH		STAGE LP TURBINE DISK; LP TURBINE NOZZLE		TIME:	TIME:
6/06/1994	ONE TIME	P/N 3072842-1 OR 3072319-1 THRU -8	N/A BY DATE OF MFG	LD/CY:	LD/CY:
AD 94-23-05 a		REMOVE FROM SERVICE FIRST & SECOND STAGE	GARRETT	DATE:	DATE:
RH		LPT DISKS WITH P/N 3072351-(),3072542-		TIME:	TIME:
12/01/1994	ONE TIME	()),3074103-1,3074105-1	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 95-07-02		TO PREVENT A LOW PRESSURE TURBINE DISK	GARRETT	DATE:	DATE:
RH		WEB SEPARATION		TIME:	TIME:
6/19/1995	ONE TIME		N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 96-04-01		UNCONTAIN FAN DISK FAILURE	GARRETT	DATE: 10/18/2006	DATE:
RH		P/N 3072162,3073436,3073539,3074529		TIME: 1381.9	TIME:
3/15/1996	ONE TIME	SUPERSEDES AD 93-25-16,AD 92-26-09	N/A BY P/N	LD/CY:	LD/CY:
AD 96-05-03		EDDY-CURRENT INSPECTION OF FAN ROTOR	GARRETT	DATE: 10/18/2006	DATE:
RH		DISC P/N 3072162-1 THRU -4, 3073436-1		TIME: 1381.9	TIME:
4/02/1996	ONE TIME	THRU -4;SUPERSEDES AD 91-08-13	N/A BY P/N	LD/CY:	LD/CY:
AD 96-18-13		TO PREVENT FAILURE OF THE FAN ROTOR DISK	GARRETT	DATE: 10/18/2006	DATE:
RH		DUE TO FATIGUE CRACKING;		TIME: 1381.9	TIME:
11/12/1996	ONE TIME	SUPERSEDED BY AD 2001-23-09	N/A BY P/N	LD/CY:	LD/CY:
AD 97-04-03		FAILURE OF FIRST STAGE LPT SEAL	GARRETT	DATE:	DATE:
RH		PLATE PART NO. 3073552-2 &		TIME:	TIME:
5/05/1997	ONE TIME	3074053-1	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 98-10-15		TO PREVENT FUEL SPRAYING ON AND	GARRETT	DATE:	DATE:
RH		AROUND ELECTRICAL COMPONENTS		TIME:	TIME:
5/19/1998	ONE TIME	DUE TO CRACKED FUEL LINE	N/A BY ENGINE MODEL	LD/CY:	LD/CY:
AD 98-17-01		TO PREVENT CRACKED FUEL TUBES	GARRETT	DATE: 10/18/2006	DATE:
RH		SUPERSEDES AD 93-10-10		TIME: 1381.9	TIME:
11/29/1999	ONE TIME		P/C/W SB A73-3132, SB A73-3128	LD/CY:	LD/CY:

AIRFRAME & APPLIANCE SB REPORT

LEARJET 31232

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
AAK 89-16		REINFORCEMENT OF LOWER CABIN DOOR	LEARJET	DATE: 8/06/2009	DATE:
		JAMB (36 INCH DOOR)		TIME: 2332.1	TIME:
2/10/2004	ONE TIME		C/W	LD/CY:	LD/CY:
SB31-27-25A		INSPECTION / REPLACEMENT OF AILERON	LEARJET Recommended	DATE: 8/26/2005	DATE:
		CONTROL CABLES		TIME: 942.4	TIME:
12/23/2002	ONE TIME		C/W	LD/CY:	LD/CY:
SB31-28-07		FUEL - INSTALLATION OF STANDBY FUEL PUMP	LEARJET Recommended	DATE: 3/20/2009	DATE:
		ANNUNCIATORS		TIME: 2201.7	TIME:
10/26/2015	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
SB31-28-10		FUEL - INSTALLATION OF SINGLE POINT	LEARJET Optional	DATE: 7/09/2008	DATE:
		PRESSURE REFUELING EXTENSION FLANGE		TIME: 2001.4	TIME:
8/13/1997	ONE TIME		C/W	LD/CY:	LD/CY:
SB31-32-17		REPLACEMENT OF ANTI-SKID AND PARKING	BOMBARDIER Recommended	DATE: 2/05/2002	DATE:
		BRAKE INDICATOR LIGHTS		TIME:	TIME:
4/18/2002	ONE TIME		C/W	LD/CY:	LD/CY:
SB31-32-17		LANDING GEAR-REPLACEMENT OF ANTI	BOMBARDIER Recommended	DATE: 2/05/2002	DATE:
		SKID & PARKING BRAKE INDICATOR		TIME:	TIME:
4/18/2002	ONE TIME	LIGHTS	C/W	LD/CY:	LD/CY:
SB31-54-02		NACELLES/PYLONS - INSPECTION/FIREWALL	BOMBARDIER Recommended	DATE: 5/10/2011	DATE:
		SEALING MODIFICATION		TIME: 2980.4	TIME:
8/21/2006	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	LD/CY:	LD/CY:
SBA31-32-25		AFT TRUNNION PIN INSTALLATION	LEARJET Recommended	DATE: 12/31/2025	DATE:
		INSPECTION		TIME: 5853.4	TIME:
3/07/2025	ONE TIME		FOUND P/C/W	LD/CY: 4454	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3001	R56	ENGINE - SERVICE LIFE - SERVICE LIFE	GARRETT	Mandatory	DATE: 2/23/2024
LH		LIMITS OF CRITICAL LIFE LIMITED			TIME: 5557.0
6/29/2011	ONE TIME	COMPONENTS	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3019		ENGINE - ACCESSORY DRIVE - INSPECTION	GARRETT	Recommended	DATE: 10/18/2006
LH		OF TRANSFER GEARBOX BEARING SUPPORT			TIME: 1270.2
4/09/1975	ONE TIME		N/A GEARBOX SERIES	LD/CY: 1068	DATE:
SB 72-3020		ENGINE - ACCESSORY DRIVE - REMOVE &	GARRETT	Mandatory	DATE: 10/18/2006
LH		REPLACE TRANSFER GEARBOX BEARING			TIME: 1270.2
5/26/1976	ONE TIME	SUPPORT CONTROLS WEAR IF RACE ROTATES	N/A GEARBOX SERIES	LD/CY: 1068	DATE:
SB 72-3042	R7	REPLACE COMBUSTION LINER P/N 3072448-4	GARRETT	Optional	DATE: 7/06/2001
LH		WITH IMPROVED COMBUSTION LINER			TIME: 0.0
12/12/2001	ONE TIME	INACTIVE	C/W	LD/CY:	DATE:
SB 72-3099	R2	ENGINE - HP TURBINE ROTOR ASSEMBLY -	GARRETT	Optional	DATE: 2/23/2024
LH		INSTALL HP TURBINE BLADE P/N 3072712-1			TIME: 5557.0
2/10/1989	ONE TIME	FOR FIELD EVALUATION	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3105	R14	ENGINE - INSPECTION INTERVALS -	GARRETT	Mandatory	DATE: 2/23/2024
LH		ESTABLISHING PERIODIC INSPECTION			TIME: 5557.0
10/26/2012	ONE TIME	INTERVALS	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3126	R13	ENGINE - PLANET GEAR INSTALLATION-REPLACE	GARRETT	Recommended	DATE: 2/23/2024
LH		/REWORK PLANET GEARSHAFT ASSY: USES			TIME: 5557.0
9/22/1989	ONE TIME	OPTIMIZED DIAMETER & BALANCE CLAMP NUTS	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3128	R9	ACCESSORY DRIVES - MODIFY ALTERNATOR	GARRETT	Recommended	DATE: 2/23/2024
LH		DRIVE SPUR GEARSHAFT			TIME: 5557.0
2/18/2003	ONE TIME		COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3154	R7	ENGINE - COMPRESS INSTALLATION - INCORP.	GARRETT	Optional	DATE: 2/23/2024
LH		ROTATING HP ROTATING GROUP THRUST BAL			TIME: 5557.0
9/10/2002	ONE TIME	SEAL ROTOR & COMPRESSOR DIFFUSER	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3159		ENGINE - INSPECT AND/OR REPLACE TURBINE	GARRETT	Recommended	DATE: 10/18/2006
LH		INTERSTAGE TRANSITION DUCT: WILL REVEAL			TIME: 1270.2
1/08/1988	ONE TIME	INADEQUATE WELD PENETRATION	N/A	LD/CY: 1068	DATE:
SB 72-3170		ENGINE - TURBINE INTERSTAGE TRANSITION	GARRETT	Optional	DATE: 10/18/2006
LH		DUCT - INSTALL AFT MOUNT AUXILIARY			TIME: 1270.2
3/07/1985	ONE TIME	BRACKET	N/A	LD/CY: 1068	DATE:
SB 72-3208	R1	ENGINE - COMPRESSOR INLET STATOR -	GARRETT	Optional	DATE: 2/23/2024
LH		REPLACE OR REWORK COMPRESSOR INLET			TIME: 5557.0
5/01/1989	ONE TIME	STATOR, P/N 3072429-1 TO P/N 3072429-2	COMPLIED WITH	LD/CY: 4154	DATE:
SB 72-3237	R3	ENGINE - COMPRESSOR SECTION - INSTALL HP	GARRETT	Mandatory	DATE: 2/23/2024
LH		COMPRESSOR IMPELLER, P/N 3073393-1,			TIME: 5557.0
12/15/1989	ONE TIME	3073394-1 AND 3073398-1	NOT APPLICABLE	LD/CY: 4154	DATE:
SB 72-3304		ENGINE - BYPASS SECTION - REPLACE/REWORK	GARRETT	Recommended	DATE: 10/18/2006
LH		FAN DISC NUT, P/N 3071981-1: WILL			TIME: 1270.2
5/24/1985	ONE TIME	PROVIDE COMMONALITY OF PARTS	N/A	LD/CY: 1068	DATE:

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3309	R5	ENGINE - TURBINE SECTION - INSPECT AND/	GARRETT	Recommended	DATE: 2/23/2024	DATE:
LH	ONE TIME	OR REPAIR/REPLACE SPECIFIC IDENTIFIED	COMPLIED WITH		TIME: 5557.0	TIME:
10/20/2004		TURBINE INTERSTAGE TRANSITION DUCTS			LD/CY: 4154	LD/CY:
SB 72-3345	R3	ENGINE - REWORK/REPLACE THERMOCOUPLE	GARRETT	Optional	DATE: 2/23/2024	DATE:
LH	ONE TIME	HARNESS OR THERMOCOUPLE LEAD ASSEMBLY	NOT APPLICABLE		TIME: 5557.0	TIME:
11/30/1990					LD/CY: 4154	LD/CY:
SB 72-3346		WELD TITANIUM STRIPS TO ENDS OF ALL	GARRETT	Optional	DATE: 12/08/2014	DATE:
LH	ONE TIME	VANES AT INNER & OUTER SHROUD LOCATIONS	C/W		TIME: 4069.2	TIME:
1/12/2007		ON FAN BY-PASS STATORS P/N3071965-1,			LD/CY: 3092	LD/CY:
SB 72-3358	R5	ENGINE - COMPRESSOR SECTION - INSTALL	GARRETT	Recommended	DATE: 2/23/2024	DATE:
LH	ONE TIME	OUTER TRANSITION LINER P/N 3073526-3	NOT APPLICABLE		TIME: 5557.0	TIME:
9/09/1994		WITH SPEC. P/N HP COMPRESSOR DIFFUSERS			LD/CY: 4154	LD/CY:
SB 72-3364RWK	R2	RWK HP DIFF TO 3071253-16 OR 3077032-6,	GARRETT		DATE: 2/23/2024	DATE:
LH	ONE TIME	-8,-9,-10	COMPLIED WITH		TIME: 5557.0	TIME:
					LD/CY: 4154	LD/CY:
SB 72-3367	R3	ENGINE - TURBINE SECTION - PERFORM ONE	GARRETT	Recommended	DATE: 7/06/2001	DATE:
LH	ONE TIME	TIME INSPECTION OF NOZZLE THROAT (A5)	C/W		TIME: 0.0	TIME:
9/02/1994		OPENING FOR PROPER DIMENSION			LD/CY:	LD/CY:
SB 72-3369	R6	ENGINE - TURBINE SECTION - ADJUST NOZZLE	GARRETT		DATE: 2/23/2024	DATE:
LH	ONE TIME	THROAT (A5) OPENING(S) EFFECTIVE (AE)	COMPLIED WITH		TIME: 5557.0	TIME:
6/26/2002		FLOW AREA			LD/CY: 4154	LD/CY:
SB 72-3370	R1	ENGINE - TURBINE SECTION - INSPECT AND	GARRETT	Recommended	DATE: 2/23/2024	DATE:
LH	ONE TIME	REWORK TURBINE INTERSTAGE TRANSITION	NOT APPLICABLE		TIME: 5557.0	TIME:
6/15/1990		DUCTS P/N 3071486-X,3072318-X,3072726-X			LD/CY: 4154	LD/CY:
SB 72-3377	R4	ENGINE - INSTALL REDESIGNED COMBUSTION	GARRETT	Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME	SYSTEM (LOW SMOKE)	C/W		TIME: 0.0	TIME:
1/24/2002		INACTIVE FOR FURTHER ACCOMPLISHMENT			LD/CY:	LD/CY:
SB 72-3384	R2	ENGINE - BY-PASS SECTION - REPLACE OIL	GARRETT	Optional	DATE: 2/23/2024	DATE:
LH	ONE TIME	DEFLECTOR OR REWORK EXISTING OIL	COMPLIED WITH		TIME: 5557.0	TIME:
3/06/2001		DEFLECTOR			LD/CY: 4154	LD/CY:
SB 72-3393		ENGINE - BY-PASS SECTION - REPLACE/	GARRETT	Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME	REWORK FAN SUPPORT SHAFT & HOUSING	C/W		TIME: 0.0	TIME:
12/17/2001		INACTIVE FOR FURTHER ACCOMPLISHMENT			LD/CY:	LD/CY:
SB 72-3396		ENGINE - CONVERT ENGINE, PART NO.	GARRETT	Optional	DATE: 10/18/2006	DATE:
LH	ONE TIME	3073610-3 TO PART NO. 3073610-1	N/A		TIME: 1270.2	TIME:
9/22/1989					LD/CY: 1068	LD/CY:
SB 72-3397	R4	ENGINE - INITIATE COMPONENT MAINTENANCE/	GARRETT	Mandatory	DATE: 2/23/2024	DATE:
LH	ONE TIME	MODIFICATION RECORD CARD (CARD-LOG BOOK)	COMPLIED WITH		TIME: 5557.0	TIME:
11/14/2012		(CMMC)			LD/CY: 4154	LD/CY:
SB 72-3405	R2	REPLACE SHROUD RETAINING SLEEVE, P/N	GARRETT	Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME	3070023-1 WITH P/N 3070023-3	C/W		TIME: 0.0	TIME:
11/26/2002		OR 3070023-4			LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3408		COMPRESSOR SECTION - REPLACE SPRING	GARRETT	DATE: 7/06/2001	DATE:
LH		TENSION WASHER, P/N 3000005-2/-56		TIME: 0.0	TIME:
2/19/1990	ONE TIME	WITH P/N 3000005-64	C/W	LD/CY:	LD/CY:
SB 72-3409	R1	COMPRESSOR SECTION - INSTALL FIRST STAGE	GARRETT	DATE: 7/06/2001	DATE:
LH		COMPRESSOR WHEEL ASSEMBLY BLADE		TIME: 0.0	TIME:
8/10/1990	ONE TIME	P/N 3075358-1	C/W	LD/CY:	LD/CY:
SB 72-3410	R1	COMPRESSOR SECTION - INSTALL SECOND	GARRETT	DATE: 10/18/2006	DATE:
LH		STAGE COMPRESSOR ROTOR ASSEMBLY BLADE		TIME: 1270.2	TIME:
8/10/1990	ONE TIME	RETAINER, P/N 3075357-2	FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3411	R1	COMPRESSOR SECTION - INSTALL THIRD	GARRETT	DATE: 10/18/2006	DATE:
LH		STAGE COMPRESSOR ROTOR ASSEMBLY BLADE		TIME: 1270.2	TIME:
8/10/1990	ONE TIME	RETAINER, P/N 3075357-3	FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3413		COMPRESSOR SECTION-INSTALL DRAIN VALVES,	GARRETT	DATE: 7/06/2001	DATE:
LH		P/N 868889-3, & TEE PLATE, P/N 3071835-2		TIME: 0.0	TIME:
7/19/2006	ONE TIME	THAT INCORPORATE LOCKWIRE HOLES	C/W	LD/CY:	LD/CY:
SB 72-3416	R5	HP IMPELLER SHROUD WITH IMPROVED COATING	GARRETT	DATE: 7/06/2001	DATE:
LH				TIME: 0.0	TIME:
1/22/2001	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3419		TURBINE SECTION - PERMANENTLY SEAL NON-	GARRETT	DATE: 7/06/2001	DATE:
LH		FUNCTIONAL BOSS ON THRUST AND EXHAUST		TIME: 0.0	TIME:
11/30/1990	ONE TIME	NOZZLE P/N 3071431-1/-2/-3	C/W	LD/CY:	LD/CY:
SB 72-3421		ENGINE - COMPRESSOR SECTINO - INSTALL LP	GARRETT	DATE: 7/06/2001	DATE:
LH		COMPRESSOR BEARING HOUSING, P/N		TIME: 0.0	TIME:
5/24/1991	ONE TIME	3071691-7 OR 3077043-3	C/W	LD/CY:	LD/CY:
SB 72-3422		INSPECTION OF THE PINION GEAR RETAINER	GARRETT	DATE: 7/06/2001	DATE:
LH		PLATE ASSEMBLY		TIME: 0.0	TIME:
1/03/1991	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3424		BY-PASS SECTION - REPLACEMENT OF FAN	GARRETT	DATE: 7/06/2001	DATE:
LH		ROTOR ASSY WITH SPECIFIC S/N DISC & HUB		TIME: 0.0	TIME:
12/20/1990	ONE TIME	MADE FROM THE SAME MATERIAL HEAT CODE	C/W	LD/CY:	LD/CY:
SB 72-3426		ENG.-TURBINE SECTION-REPLACE/REWORK 3RD	GARRETT	DATE: 7/06/2001	DATE:
LH		STAGE LP TURBINE NOZZLE, P/N 3072342-2		TIME: 0.0	TIME:
5/08/1996	ONE TIME	TO 3072342-4 OR 3070014-3 TO 3070014-5	C/W	LD/CY:	LD/CY:
SB 72-3429		COMPRESSOR SECTION - REPLACE TIE BOLT,	GARRETT	DATE: 7/06/2001	DATE:
LH		P/N 3070065-1/-4 WITH P/N 3070065-3 OR		TIME: 0.0	TIME:
4/03/1992	ONE TIME	3073049-1	C/W	LD/CY:	LD/CY:
SB 72-3434	R3	ENGINE - TURBINE SECTION-INSTALLATION OF	GARRETT	DATE: 7/06/2001	DATE:
LH		HIGH PRESSURE TURBINE NOZZLE ASSEMBLY		TIME: 0.0	TIME:
4/01/1992	ONE TIME	WITH RELOCATED A4 NOZZEL SEGMENTS	C/W	LD/CY:	LD/CY:
SB 72-3441	R2	BY-PASS SECTION - INSTALL RECTANGULAR	GARRETT	DATE: 7/06/2001	DATE:
LH		DAMPER RING, P/N 3073524-6, ON PINION		TIME: 0.0	TIME:
6/04/1993	ONE TIME	(SUN) GEAR ASSEMBLY	C/W	LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3443		COMPRESSOR SECTION - REPLACEMENT OF LP	GARRETT	DATE: 7/06/2001	DATE:
LH		COMPRESSOR SECOND STAGE (STATIC) SHROUD,		TIME: 0.0	TIME:
9/06/1991	ONE TIME	P/N 3070289-2	C/W	LD/CY:	LD/CY:
SB 72-3449		ENGINE-COMPRESSOR SECTION-INSTALL WASHER	GARRETT	DATE: 7/06/2001	DATE:
LH		P/N S8154-2P025, ON BOLTS THAT SECURE HP		TIME: 0.0	TIME:
2/07/1992	ONE TIME	SHROUD TO HP COMPRESSOR DIFFUSER	C/W	LD/CY:	LD/CY:
SB 72-3453	R2	REPLACE #4, #5 CARBON SEALS AND ROTORS	GARRETT	DATE: 7/06/2001	DATE:
LH				TIME: 0.0	TIME:
9/17/1993	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3455	R3	INSTALL PACKINGS, P/N S9413-036 AND SEAL	GARRETT	DATE: 7/06/2001	DATE:
LH		P/N S815506-2, ON TOWER SHAFT OIL		TIME: 0.0	TIME:
9/24/1996	ONE TIME	TRANSFER TUBE	C/W	LD/CY:	LD/CY:
SB 72-3458	R12	ENGINE-BYPASS SECTION-PROVIDE	GARRETT	DATE: 2/23/2024	DATE:
LH		EDDY CURRENT INSPECTION		TIME: 5557.0	TIME:
6/23/2008	ONE TIME	INSTRUCTIONS FOR FAN ROTOR ASSY DISC	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3458	R12	ENGINE-BYPASS SECTION-PROVIDE	GARRETT	DATE: 12/08/2014	DATE:
LH		EDDY CURRENT INSPECTION		TIME: 4069.2	TIME:
6/23/2008	ONE TIME	INSTRUCTIONS FOR FAN ROTOR ASSY DISC	C/W	LD/CY: 3092	LD/CY:
SB 72-3469	R2	ENGINE - COMPRESSOR SECTION - REPLACE	GARRETT	DATE: 7/06/2001	DATE:
LH		NO. 3 CARBON FACE SEAL AND SEAL ROTOR		TIME: 0.0	TIME:
9/14/2001	ONE TIME	INACTIVE	C/W	LD/CY:	LD/CY:
SB 72-3473		ENGINE BY-PASS SECTION - ADDITIONAL SOAP	GARRETT	DATE: 7/06/2001	DATE:
LH		SAMPLING REQUIREMENT		TIME: 0.0	TIME:
4/03/1992	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3475		ENGINE - BY-PASS SECTION - REPLACE NO. 1	GARRETT	DATE: 7/06/2001	DATE:
LH		CARBON FACE SEAL AND SEAL ROTOR.		TIME: 0.0	TIME:
9/14/2001	ONE TIME	INACTIVE	C/W	LD/CY:	LD/CY:
SB 72-3476	R1	TURBINE SECTION - INSTALL HP TURBINE	GARRETT	DATE: 7/06/2001	DATE:
LH		PISTON RING SEAL, P/N 3000002-10		TIME: 0.0	TIME:
10/16/1992	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3477		ACCESSORY DRIVES - REPLACE ACCESSORY	GARRETT	DATE: 7/06/2001	DATE:
LH		DRIVE GEARBOX GASKET		TIME: 0.0	TIME:
4/08/1992	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3480		INCORPORATION OF NEW ENGINE LOG BOOK	GARRETT	DATE: 7/06/2001	DATE:
LH				TIME: 0.0	TIME:
5/29/1992	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3483	R2	COMPRESSOR SECTION - INSTALL LP	GARRETT	DATE: 7/06/2001	DATE:
LH		COMPRESSOR FOURTH STAGE STATOR		TIME: 0.0	TIME:
11/08/1996	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3486	R2	TURBINE SECTION - REPLACE SPECIFIC	GARRETT	DATE: 7/06/2001	DATE:
LH		IDENTIFIED HP TURBINE ROTOR ASSEMBLY		TIME: 0.0	TIME:
6/19/1998	ONE TIME	DISCS	C/W	LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3487	R3	ENGINE-BYPASS SECTION-INSPECT/REWORK	GARRETT	Recommended	DATE: 2/23/2024	DATE:
LH	ONE TIME	FAN BLADE MIDSPAN DAMPER	COMPLIED WITH		TIME: 5557.0	TIME:
6/20/2003					LD/CY: 4154	LD/CY:
SB 72-3488	R3	TURBINE SECTION - PROVIDE AUTHORITY	GARRETT	Recommended	DATE: 12/08/2014	DATE:
LH	ONE TIME	FOR INSTALLATION OF ALTERNATE PART	C/W		TIME: 4069.2	TIME:
10/02/1998		NUMBERED HP TURBINE SHROUD SEGMENTS			LD/CY: 3092	LD/CY:
SB 72-3492		BYPASS SECTION - INSTALL O'RING PACKING,	GARRETT	Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME	P/N S9873-001, BETWEEN SPINNER SUPPORT	C/W		TIME: 0.0	TIME:
7/30/1993		AND FAN BLADES			LD/CY:	LD/CY:
SB 72-3494	R13	TURBINE SECTION-HIGH PRESSURE & LOW	GARRETT	Recommended	DATE: 2/23/2024	DATE:
LH	RECURRS	PRESSURE TURBINE BLADE HOUR TRACKING	COMPLIED WITH		TIME: 5557.0	TIME:
8/06/2015					LD/CY: 4154	LD/CY:
SB 72-3498	R1	BYPASS SECTION - INSTALL FAN SHAFT &	GARRETT	Recommended	DATE: 7/06/2001	DATE:
LH	ONE TIME	RING GEAR WITH NEW RETAINING RING	C/W		TIME: 0.0	TIME:
5/07/1993					LD/CY:	LD/CY:
SB 72-3499	R6	ENGINE - BY-PASS SECTION - INSTALL	GARRETT	Recommended	DATE: 7/06/2001	DATE:
LH	ONE TIME	COMPONENT PARTS TO PREVENT OIL LEAKAGE	N/A		TIME: 0.0	TIME:
12/14/2001		IN #1 OIL SEAL REGION. INACTIVE			LD/CY:	LD/CY:
SB 72-3507	R1	REWORK FAN SHAFT HOUSING	GARRETT		DATE: 10/18/2006	DATE:
LH	ONE TIME	3072160-1/-2 TO 3077082-1/-2	FOUND P/C/W		TIME: 1270.2	TIME:
					LD/CY: 1068	LD/CY:
SB 72-3520	R3	TURBINE SECTION - INSTALL LP THIRD STAGE	GARRETT	Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME	TURBINE ROTOR ASSEMBLY INCORPORATING A	C/W		TIME: 0.0	TIME:
10/15/1999		NEWLY DESIGNED SEAL ROTOR			LD/CY:	LD/CY:
SB 72-3523	R1	INSTALL LP 4TH STAGE COMPRESSOR ROTOR	GARRETT	Optional	DATE: 12/08/2014	DATE:
LH	ONE TIME	ASSY INCORPORATING A SHOULDERED SHAFT	FOUND P/C/W		TIME: 4069.2	TIME:
6/17/2003		WITH AN INTERFERENCE FIT			LD/CY: 3092	LD/CY:
SB 72-3524		BYPASS SECTION - INSTALL RETAINING	GARRETT	Recommended	DATE: 7/06/2001	DATE:
LH	ONE TIME	(DAMPER) RING, P/N 3072463-2	C/W		TIME: 0.0	TIME:
6/04/1993					LD/CY:	LD/CY:
SB 72-3529	R2	BYPASS SECTION - REDESIGNED FAN DISC	GARRETT	Optional	DATE: 10/18/2006	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 1270.2	TIME:
10/25/2000					LD/CY: 1068	LD/CY:
SB 72-3530	R1	TURBINE SECTION - INSTALL AN LP SECOND	GARRETT	Recommended	DATE: 7/06/2001	DATE:
LH	ONE TIME	STAGE TURBINE NOZZLE THAT INCORPORATES	C/W		TIME: 0.0	TIME:
10/08/1993		A HONEYCOMB AIR SEAL			LD/CY:	LD/CY:
SB 72-3531	R4	BYPASS SECTION-INSTALLATION OF FAN	GARRETT	Recommended	DATE: 10/18/2006	DATE:
LH	ONE TIME	BLADES & IDENTIFICATION OF FAN ROTOR	FOUND P/C/W		TIME: 1270.2	TIME:
1/28/2003		ASSEMBLIES			LD/CY: 1068	LD/CY:
SB 72-3532		REWORK COMPRESSOR INTERSTAGE	GARRETT		DATE: 10/18/2006	DATE:
LH	ONE TIME	DIFFUSER	N/A		TIME: 1270.2	TIME:
					LD/CY: 1068	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3535		LOW PRESSURE TURBINE ASSY-INSTALL LP	GARRETT	DATE: 7/06/2001	DATE:
LH		SHAFT & SEAL ASSY THAT INCORPORATES A		TIME: 0.0	TIME:
9/10/1993	ONE TIME	HONEYCOMB SEAL	C/W	LD/CY:	LD/CY:
SB 72-3536	R2	COMBUSTION SECTION - INSTALL COMBUSTION	GARRETT	DATE: 7/06/2001	DATE:
LH		CHAMBER & INNER TRANSITION LINER		TIME: 0.0	TIME:
1/24/2002	ONE TIME	(CONTROLLED FIT/LOW SMOKE)	C/W	LD/CY:	LD/CY:
SB 72-3537		COMPRESSOR SECTION-INSTALL LP 1ST STAGE	GARRETT	DATE: 12/08/2014	DATE:
LH		COMPRESSOR ROTOR ASSY, INCORPORATING A		TIME: 4069.2	TIME:
10/18/1993	ONE TIME	SHOULDERED SHAFT WITH INTERFERENCE FIT	FOUND P/C/W	LD/CY: 3092	LD/CY:
SB 72-3538		COMPRESSOR SECTION - REPLACEMENT OF	GARRETT	DATE: 7/06/2001	DATE:
LH		NO.3 COMPRESSOR BEARING RETAINER NUT		TIME: 0.0	TIME:
9/13/1993	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3540		COMPRESSOR SECTION - IMPROVED NO.4 & 5	GARRETT	DATE: 7/06/2001	DATE:
LH		BEARING SUMP SCAVENGE		TIME: 0.0	TIME:
9/14/2001	ONE TIME	INACTIVE	C/W	LD/CY:	LD/CY:
SB 72-3542	R3	COMPRESSOR SECTION - INSTALL LP SECOND	GARRETT	DATE: 2/23/2024	DATE:
LH		STAGE COMPRESSOR ROTOR ASSY WITH		TIME: 5557.0	TIME:
3/28/2007	ONE TIME	FREQUENCY INSPECTED ROTOR BLADES	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3550	R1	TURBINE SECTION-INSTALL A HONEYCOMB AIR	GARRETT	DATE: 7/06/2001	DATE:
LH		SEAL IN THE TURBINE INTERSTAGE		TIME: 0.0	TIME:
5/18/1995	ONE TIME	TRANSITION DUCT	C/W	LD/CY:	LD/CY:
SB 72-3555	R1	COMPRESSOR SECTION-INSTALL HP	GARRETT	DATE: 2/23/2024	DATE:
LH		DIFFUSER INCORPORATING HONEYCOMB SEAL,		TIME: 5557.0	TIME:
8/30/2002	ONE TIME	HARDOAT, & IMPROVED SURFACE FINISH	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3560	R1	COMPRESSOR SECTION-LP FIRST STAGE	GARRETT	DATE: 10/18/2006	DATE:
LH		COMPRESSOR ROTOR ASSEMBLY BLADES		TIME: 1270.2	TIME:
3/26/1996	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3561	R2	COMPRESSOR SECTION-LP SECOND STAGE	GARRETT	DATE: 10/18/2006	DATE:
LH		COMPRESSOR ROTOR ASSEMBLY BLADES		TIME: 1270.2	TIME:
5/05/2005	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3562	R1	COMPRESSOR SECTION-LP THIRD STAGE	GARRETT	DATE: 10/18/2006	DATE:
LH		COMPRESSOR ROTOR ASSEMBLY BLADES		TIME: 1270.2	TIME:
3/26/1996	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3563	R1	COMPRESSOR SECTION-LP FOURTH STAGE	GARRETT	DATE: 10/18/2006	DATE:
LH		COMPRESSOR ROTOR ASSEMBLY BLADES		TIME: 1270.2	TIME:
3/26/1996	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 72-3564	R7	ENGINE - BANK/SPARE ENGINE CONVERSIONS-	GARRETT	DATE: 10/18/2006	DATE:
LH				TIME: 1270.2	TIME:
1/07/2003	ONE TIME		N/A	LD/CY: 1068	LD/CY:
SB 72-3565		TURBINE SECTION-REMOVAL OF A4 NOZZLE	GARRETT	DATE: 10/18/2006	DATE:
LH		SEGMENTS FROM SPECIFICALLY		TIME: 1270.2	TIME:
6/30/1994	ONE TIME	IDENTIFIED ENGINES	N/A	LD/CY: 1068	LD/CY:

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3566	R4	ENGINE-INSTALL ALTERNATE FITTINGS WITH A RING SEAL	GARRETT	DATE: 2/23/2024	DATE:
LH	ONE TIME		COMPLIED WITH	TIME: 5557.0	TIME:
10/29/2002					LD/CY: 4154
SB 72-3577		TURBINE SECTION-REPLACE HONEYCOMB AIR SEAL, PART NUMBER 3073354-3, IN THE TURBINE INTERSTAGE TRANSITION DUCT	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 4069.2	TIME:
7/19/1995					LD/CY: 3092
SB 72-3584		OIL-DISTRIBUTION-REPLACE ELBOW ADAPTER FOR BUFFER AIR TRANSFER TUBE ON THE LP COMPRESSOR CASE	GARRETT	DATE: 2/23/2024	DATE:
LH	ONE TIME		COMPLIED WITH	TIME: 5557.0	TIME:
11/03/1995					LD/CY: 4154
SB 72-3592	R1	ENGINE - TURBINE SECTION - LP TURBINE THIRD STAGE ROTOR ASSY (DISC) LIFE LIMITED PART LOG CARD	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH	ONE TIME		N/A	TIME: 1270.2	TIME:
4/30/1998					LD/CY: 1068
SB 72-3596	R7	ENGINE - REPLACE MAINSHAFT CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS INACTIVE	GARRETT Optional	DATE: 7/06/2001	DATE:
LH	ONE TIME		C/W	TIME: 0.0	TIME:
9/14/2001					LD/CY:
SB 72-3600		ENGINE-COMPRESSOR SECTION-INSTALL LP COMPRESSOR STATOR SHIM, P/N 3060360-1 THRU -11	GARRETT	DATE: 2/23/2024	DATE:
LH	ONE TIME		COMPLIED WITH	TIME: 5557.0	TIME:
1/13/1997					LD/CY: 4154
SB 72-3603RWK	R1	REWORK COMPRESSOR INTERSTAGE DIFFUSER TO INCORPORATE/ENLARGE OIL SCAVENGE SLOTS	GARRETT	DATE: 10/18/2006	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 1270.2	TIME:
5/22/1996					LD/CY: 1068
SB 72-3604	R4	ENGINE-ACCESSORY DRIVES-REWORK TRANSFER GEARBOX ASSEMBLY,P/N 3070093-X TO P/N 3070093-12	GARRETT	DATE: 10/10/2006	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 1270.2	TIME:
3/20/2015					LD/CY: 1068
SB 72-3605	R4	INSTALL/REWORK ACCESSORY DRIVE GEARBOX ASSY W/ AN IMPROVED AIR OIL SEPARATOR & A NEW AIR BREATHER VALVE ASSY	GARRETT	DATE: 12/08/2014	DATE:
LH	ONE TIME		C/W	TIME: 4069.2	TIME:
6/16/2004					LD/CY: 3092
SB 72-3613	R8	ENGINE-REPLACE NO.1 & NO.3 CARBON RING SEALS & ASSOCIATED VENT/OIL SYSTEM COMPONENTS	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH	ONE TIME		C/W	TIME: 4069.2	TIME:
1/23/2009					LD/CY: 3092
SB 72-3614RWK		BYPASS SECTION-REWORK NO.1 SEAL & SEAL HOUSING TO PART NO. 3071966-5 OR 3077122-1/-2/-3	GARRETT	DATE: 2/23/2024	DATE:
LH	ONE TIME		COMPLIED WITH	TIME: 5557.0	TIME:
2/06/1997					LD/CY: 4154
SB 72-3615		REWORK AIR BREATHER VALVE, P/N 3071564-7 /-8 TO P/N 3071564-9,USED IN AIR BREATHR VALVE P/N 3075323-3	GARRETT	DATE: 2/23/2024	DATE:
LH	ONE TIME		COMPLIED WITH	TIME: 5557.0	TIME:
2/06/1997					LD/CY: 4154
SB 72-3634		2ND STAGE LPC BLADE INSPECTION & P/N REID	GARRETT	DATE: 10/18/2006	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 1270.2	TIME:
					LD/CY: 1068
SB 72-3635		INSPECT/REWORK/INSTALL OIL FILTER COVER P/N 3072231-1 TO P/N 3072231-4	GARRETT	DATE: 10/18/2006	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 1270.2	TIME:
11/16/1998					LD/CY: 1068

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3638	R1	INSTALLATION OF TRANSFER GEARBOX	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		HOUSING ASSEMBLY P/N 3070429-8		TIME: 5557.0	TIME:
4/02/2007	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3643		BYPASS SECTION- INSTALL FAN BLADE	GARRETT Optional	DATE: 2/23/2024	DATE:
LH		RETAINING RING, P/N 3073789-1		TIME: 5557.0	TIME:
3/03/1999	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3644	R2	INSTALL HP IMPELLER SHROUD	GARRETT Optional	DATE: 12/08/2014	DATE:
LH		P/N 3074567-1/-2		TIME: 4069.2	TIME:
1/10/2001	ONE TIME		C/W	LD/CY: 3092	LD/CY:
SB 72-3650		ACCESSORY DRIVES SECTION-NEW NAMEPLATE	GARRETT	DATE: 2/23/2024	DATE:
LH		P/N S20048-1, FOR TRANSFER GEARBOX ASSY		TIME: 5557.0	TIME:
8/10/1999	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3658		AIR INLET SECTION-REPLACE FAN INLET	GARRETT	DATE: 7/06/2001	DATE:
LH		HOUSING		TIME: 0.0	TIME:
9/21/2001	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3662	R8	REPLACE NO. 4 AND NO. 5 CARBON RING	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		SEALS AND ASSOCIATED VENT/OIL SYSTEM		TIME: 4069.2	TIME:
4/12/2012	ONE TIME	COMPONENTS	C/W	LD/CY: 3092	LD/CY:
SB 72-3664		INSPECTION/REPLACEMENT OF THREADED ENDS	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		TIE ROD, (LP TIE ROD), P/N 3073049-1 &		TIME: 5557.0	TIME:
5/05/2000	ONE TIME	3074744-1	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3674	R2	INSPECTION OF SPECIFIC IDENTIFIED	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		MAIN SUPPORT FRAME ASSEMBLIES		TIME: 1270.2	TIME:
9/16/2003	ONE TIME		N/A	LD/CY: 1068	LD/CY:
SB 72-3675	R1	INSPECT FAN BLADES FOR UNAUTHORIZED	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		MARKINGS ON THE FAN BLADE DOVETAIL AFT		TIME: 1270.2	TIME:
1/13/2010	ONE TIME	REGION	C/W	LD/CY: 1068	LD/CY:
SB 72-3676		REPLACE THE HOISTING BRACKET ON THE	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		FAN DUCT SET, P/N 3072420-7(UPPER HALF)		TIME: 1270.2	TIME:
7/12/2001	ONE TIME	ON SPECIFIC IDENTIFIED ENGINES	N/A	LD/CY: 1068	LD/CY:
SB 72-3682		REMOVE SPECIFIC IDENTIFIED LP	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		COMPRESSOR 2ND STAGE (LPC2)		TIME: 1270.2	TIME:
11/26/2002	ONE TIME	DISCS	N/A	LD/CY: 1068	LD/CY:
SB 72-3685		REPLACE SPECIFIC IDENTIFIED LP SECOND	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		STAGE TURBINE BLADES, P/N 3072012-2 AND		TIME: 5557.0	TIME:
3/08/2002	ONE TIME	P/N 3074099-1	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3685		REPLACE SPECIFIC IDENTIFIED LP SECOND	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		STAGE TURBINE BLADES, P/N 3072012-2 AND		TIME: 1270.2	TIME:
3/08/2002	ONE TIME	P/N 3074099-1	C/W	LD/CY: 1068	LD/CY:
SB 72-3687		REMOVE SPECIFIC IDENTIFIED LP	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		COMPRESSOR 2ND STAGE (LPC2)		TIME: 5557.0	TIME:
11/11/2002	ONE TIME	DISCS	NOT APPLICABLE	LD/CY: 4154	LD/CY:

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3696		ACCESSORY DRIVES SECTOR- INSTALL	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		AIR-OIL SEPARATOR P/N 3075781-1		TIME: 4069.2	TIME:
6/16/2004	ONE TIME		C/W	LD/CY: 3092	LD/CY:
SB 72-3704		INSTALL A LOW PRESSURE FIRST STAGE	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		TURBINE (LPT1) ROTOR ASSEMBLY WITH		TIME: 5557.0	TIME:
9/15/2004	ONE TIME	AN IMPROVED LPT1 ROTOR DISC	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3739		INSTALL IMPROVED NO. 1 SEG CARBON SEAL,	GARRETT	DATE: 12/08/2014	DATE:
LH		P/N 3060457-1 OR -2 (AS APPLICABLE)		TIME: 4069.2	TIME:
4/21/2008	ONE TIME	AND/OR NO. 3 SEG CARBON SEAL 3060458-1	C/W	LD/CY: 3092	LD/CY:
SB 72-3759 I	R1	INSTALL IMPROVED PLAIN ENCASED SEAL,	GARRETT	DATE: 2/23/2024	DATE:
LH		P/N 3020052-26		TIME: 5557.0	TIME:
10/28/2011	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 72-3761		INSTALL IMPROVED DIFFUSER VANE DESWIRL	GARRETT	DATE: 12/08/2014	DATE:
LH		PN 3071346-5, TO PREVENT FRET ON		TIME: 4069.2	TIME:
3/03/2010	ONE TIME	OUTER TRANSITION DESWIRL LINER	C/W	LD/CY: 3092	LD/CY:
SB 72-3771		INTRODUCTION OF ALTERNATE LOW PRESSURE	GARRETT Optional	DATE: 2/23/2024	DATE:
LH		SECOND STAGE AXIAL COMPRESSOR (LPC2)		TIME: 5557.0	TIME:
1/28/2011	ONE TIME	ROTOR ASSEMBLY, PN 3075841-2	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 72-3773		INTRODUCTION OF IMPROVED STAGE 4 CASE	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		AND VANE ASSEMBLIES, PN 3074555-10, -11		TIME: 4069.2	TIME:
7/08/2011	ONE TIME		C/W	LD/CY: 3092	LD/CY:
SB 72-3777	R2	INSTALL IMPROVED LOW PRESSURE	GARRETT	DATE: 12/08/2014	DATE:
LH		SECOND STAGE (LPC2) SHROUD, PN 3072403-6		TIME: 4069.2	TIME:
8/17/2012	ONE TIME		C/W	LD/CY: 3092	LD/CY:
SB 72-A3748		REPLACE SPECIFIC IDENTIFIED 2ND STG LOW	GARRETT	DATE: 2/23/2024	DATE:
LH		PRESS COMPRESSOR & 3RD LOW PRESS		TIME: 5557.0	TIME:
8/21/2008	ONE TIME	COMPRESSOR ROTOR DISCS	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 73-3067	R3	REWORK FUEL CONTROL P/N 3070800-8 TO	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		P/N 3070800-11 OR P/N 3070800-11 TO		TIME: 1270.2	TIME:
2/24/1995	ONE TIME	P/N 3070800-8	N/A	LD/CY: 1068	LD/CY:
SB 73-3083	R1	ENGINE - FUEL AND CONTROL - REPLACE FUEL	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		PUMP ANTI-ICING VALVE WITH UNIT		TIME: 1270.2	TIME:
10/20/1989	ONE TIME	CONTAINING AN IMPROVED THERMOSTAT	FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 73-3097		ENGINE FUEL AND CONTROL -CONTROLLING -	GARRETT Optional	DATE: 2/23/2024	DATE:
LH		INSTALL IMPROVED METERING VALVE ASSEMBLY		TIME: 5557.0	TIME:
3/08/1989	ONE TIME	PART NO 3074320-1 IN FUEL CONTROL	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 73-3106	R2	DISTRIBUTION - REPLACEMENT OF BALL AND	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		SPRING ASSY IN FUEL HEATER CHECK VALVE		TIME: 1270.2	TIME:
9/18/1992	ONE TIME	WHEN UNIT FAILS INTERNAL LEAKAGE CHECK	C/W	LD/CY: 1068	LD/CY:
SB 73-3107	R4	INSTALL SUPPORT CLAMP, P/N 211-501-9114,	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		ON FUEL LINE, P/N 3071051-1		TIME: 0.0	TIME:
4/20/1994	ONE TIME		C/W	LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 73-3108	R1	ENGINE FUEL AND CONTROL - DISTRIBUTION	GARRETT	Recommended	DATE: 7/06/2001
LH		INSTALL FUEL CONTROL P3 SENSE LINE,			TIME: 0.0
10/09/1995	ONE TIME	GASKET, P/N 3075481-1	C/W		LD/CY:
SB 73-3109	R1	ENGINE FUEL & CONTROL-DISTRIBUTION-MAIN-	GARRETT		DATE: 7/06/2001
LH		TENANCE OF ENGINES WITH SERVICE TUBE			TIME: 0.0
3/12/1993	ONE TIME	CLAMPS P/N 3073542-1 & 3073543-91 INSTLD	C/W		LD/CY:
SB 73-3110	R1	ENG FUEL & CONTROL - DIST.-REPLACE SEC-	GARRETT	Recommended	DATE: 7/06/2001
LH		ONDARY FLEXIBLE HOSE ASSY (AS REQUIRED)			TIME: 0.0
4/03/1992	ONE TIME	ON SPEC IDENTIFIED FUEL MANIFOLD ASSYS	C/W		LD/CY:
SB 73-3112		ENG FUEL & CONT-CONTROLLING-INSP & REPL	GARRETT	Recommended	DATE: 10/18/2006
LH		IDENT FUEL CONT VAR RESIS (PWR LEV POT)			TIME: 1270.2
2/14/1992	ONE TIME	AS REQ AT COMPONENT OVHL/REPAIR FACILITY	FOUND P/C/W		LD/CY: 1068
SB 73-3114		FUEL AND CONTROL-CONTROLLING-REPLACE	GARRETT	Recommended	DATE: 10/18/2006
LH		METERING VALVE ADJUSTMENT SHAFT AND			TIME: 1270.2
5/29/1992	ONE TIME	THREADED RESTRICTOR AT COMPONENT O/H	FOUND P/C/W		LD/CY: 1068
SB 73-3115	R1	INSTALL AN IMPROVED FUEL CONTROL	GARRETT	Recommended	DATE: 7/06/2001
LH		INCORPORATING A MINIMUM MOD			TIME: 0.0
3/18/1994	ONE TIME	CONFIGURATION STANDARD	C/W		LD/CY:
SB 73-3117		FUEL AND CONTROL-DISTRIBUTION-REPLACE	GARRETT	Recommended	DATE: 7/06/2001
LH		SPECIFIC IDENTIFIED FUEL MANIFOLD			TIME: 0.0
7/07/1992	ONE TIME	ASSEMBLIES.	C/W		LD/CY:
SB 73-3119		CONTROLLING - REPLACE/REWORK GOVERNOR	GARRETT	Recommended	DATE: 10/18/2006
LH		FLYWEIGHT ASSEMBLY AT COMPONENT			TIME: 1270.2
5/07/1993	ONE TIME	REPAIR FACILITY	FOUND P/C/W		LD/CY: 1068
SB 73-3121		DISTRIBUTION -REPLACE SECONDARY FLEXIBLE	GARRETT	Recommended	DATE: 7/06/2001
LH		HOSE ASSY (AS REQUIRED) ON SPECIFIC			TIME: 0.0
11/03/1993	ONE TIME	IDENTIFIED FUEL MANIFOLD ASSEMBLIES	C/W		LD/CY:
SB 73-3123		CONTROLLING-PROVIDE FOR INSTALLATION	GARRETT	Recommended	DATE: 12/08/2014
LH		OF AN ALTERNATE FUEL PUMP ELECTRICAL			TIME: 4069.2
1/30/1996	ONE TIME	DIFFERENTIAL PRESSURE INDICATOR	FOUND P/C/W		LD/CY: 3092
SB 73-3131	R2	ONE TIME INSPECTION FOR SPECIFIC ID	GARRETT	Recommended	DATE: 10/18/2006
LH		FUEL CONTROL COMPRESSOR DISCHARGE			TIME: 1270.2
6/16/2004	ONE TIME	SENSOR BELLOWES P/N 3074139-2	N/A		LD/CY: 1068
SB 73-3134	R2	REPLACE SPECIFIC IDENTIFIED FUEL CONTROL	GARRETT		DATE: 12/22/2010
LH		ASSEMBLIES HAVING SUSPECT TORQUE MOTORS			TIME: 2728.9
4/30/1999	ONE TIME		N/A		LD/CY: 2228
SB 73-3135		DISTRIBUTION-INSPECT/REPLACE FLEX	GARRETT		DATE: 2/23/2024
LH		TUBE ASSY, P/N 3074376-1 (399-5500-0003)			TIME: 5557.0
8/17/2000	ONE TIME	OR 3074376-2 (AS APPLICABLE)	NOT APPLICABLE		LD/CY: 4154
SB 73-3136	R3	DISTRIBUTION-INCORP. IMPROVED PRIMARY &	GARRETT	Optional	DATE: 12/08/2014
LH		SECONDARY MANIFOLD FUEL FEEDER TUBE			TIME: 4069.2
9/10/2002	ONE TIME	ASSEMBLIES	C/W		LD/CY: 3092

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 73-3137		REPLACE THE FUEL HEATER CHECK VALVE, P/N	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		3073932-5 WITH P/N 3073932-6 AND		TIME: 5557.0	TIME:
11/03/2000	ONE TIME	CONNECTING METAL TUBE ASSEMBLIES	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 73-3138		DISTRIBUTION-REPLACE FUEL NOZZLE GASKETS	GARRETT Optional	DATE: 2/23/2024	DATE:
LH				TIME: 5557.0	TIME:
10/20/2000	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 73-3141		REWORK & RE-ID FUEL MANIFOLD ASSEMBLY	GARRETT	DATE: 2/23/2024	DATE:
LH		(MATCHED SET)		TIME: 5557.0	TIME:
	ONE TIME		FOUND P/C/W	LD/CY: 4154	LD/CY:
SB 73-3142		REPLACE SPECIFIC IDENTIFIED FUEL CONTROL	GARRETT Recommended	DATE: 12/22/2010	DATE:
LH		ASSYS HAVING A SUSPECT OVERSPEED AND/OR		TIME: 2728.9	TIME:
10/07/2002	ONE TIME	MANUAL MODE SOLENOID VALVE INSTALLED	N/A	LD/CY: 2228	LD/CY:
SB 73-3147		REPLACE SPECIFIC IDENTIFIED MAIN TURBINE	GARRETT	DATE: 12/22/2010	DATE:
LH		ENGINE FUEL CONTROLS WITH A SUSPECT OVER		TIME: 2728.9	TIME:
3/29/2005	ONE TIME	SPEED GOVERNOR ASSEMBLY INSTALLED	N/A	LD/CY: 2228	LD/CY:
SB 73-3149		CONTROLLING - REPLACE MAIN TURBINE	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		ENGINE FUEL PUMP FUEL FILTER ELEMENT		TIME: 4069.2	TIME:
9/12/2005	ONE TIME	WITH FUEL FILTER ELEMENT, P/N 897830-1	C/W	LD/CY: 3092	LD/CY:
SB 73-3155	R1	INSTALL IMPROVED MAIN TURBINE ENGINE	GARRETT	DATE: 2/23/2024	DATE:
LH		FUEL CONTROL ASSEMBLY, PN 3070800-42		TIME: 5557.0	TIME:
3/28/2012	ONE TIME	THRU -46	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 73-3157	R1	INSTALL IMPROVED FUEL CONTROL ASSEMBLY	GARRETT	DATE: 2/23/2024	DATE:
LH		WITH IMPROVED SOLENOID ATTACHMENT		TIME: 5557.0	TIME:
1/24/2018	ONE TIME	SCREWS	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 74-3003	R5	ENGINE - INSTALL IGNITION UNIT WITH	GARRETT Optional	DATE: 2/23/2024	DATE:
LH		REDUNDANT FIRING CIRCUITS: ALLOWS EACH		TIME: 5557.0	TIME:
9/21/2001	ONE TIME	IGNITOR PLUG TO FIRE ASYNCHRONOUSLY	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 74-3005	R1	REWORK/REPLACE P/N 3073914-2 IGNITION	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		UNIT TO/WITH 3073914-4		TIME: 0.0	TIME:
1/27/1995	ONE TIME	INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W	LD/CY:	LD/CY:
SB 74-3006	R1	IGNITION - GENERAL - INSTALL IGNITION	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		IGNITOR PLUG P/N 3074541-1		TIME: 0.0	TIME:
4/20/1990	ONE TIME		C/W	LD/CY:	LD/CY:
SB 74-3007	R1	GENERAL - INSPECT IRIIDIUM IGNITER PLUGS,	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		P/N 3074541-1 (CHAMPION CH31815) FOR		TIME: 0.0	TIME:
11/11/1993	ONE TIME	LOOSE CENTER FIRING TIP ELECTRODE	C/W	LD/CY:	LD/CY:
SB 76-3049		ENGINE CONTROLS - POWER CONTROL -	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		REPLACE SPECIFIC IDENTIFIED DIGITAL		TIME: 0.0	TIME:
10/06/1989	ONE TIME	ELECTRONIC ENGINE CONTROL P/N 2118002-X	C/W	LD/CY:	LD/CY:
SB 76-3051		ENGINE CONTROL - POWER CONTROL - INSTALL	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		ANTI-ICE AND SURGE SYSTEMS AIR LINE		TIME: 0.0	TIME:
5/18/1990	ONE TIME	MANIFOLD, P/N 3071778-2	C/W	LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 76-3054	R1	ENGINE CONTROLS - POWER CONTROL	GARRETT	DATE: 7/06/2001	DATE:
LH		INSTALL SURGE CONTROL GASKET, P/N	Recommended	TIME: 0.0	TIME:
10/06/1995	ONE TIME	3075481-1/-3.	C/W	LD/CY:	LD/CY:
SB 76-3064		ENGINE-CONTROLS-INSTALL DIGITAL	GARRETT	DATE: 7/06/2001	DATE:
LH		ELECTRONIC ENGINE CONTROL (DEEC),	Optional	TIME: 0.0	TIME:
5/13/1994	ONE TIME	P/N 2118002-204	C/W	LD/CY:	LD/CY:
SB 76-3066		INSTALL DIGITAL ELECTRONIC ENGINE	GARRETT	DATE: 10/18/2006	DATE:
LH		CONTROL (N1 DEEC), P/N 2119010-1		TIME: 1270.2	TIME:
11/06/1997	ONE TIME		N/A	LD/CY: 1068	LD/CY:
SB 76-3067	R19	POWER CONTROL - INSTALL DIGITAL	GARRETT	DATE: 10/18/2006	DATE:
LH		ELECTRONIC ENGINE CONTROL (N1 DEEC)	Optional	TIME: 1270.2	TIME:
12/05/2005	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 76-3068	R2	REWORK N1 DEEC P/N 2119010-3/-3002 TO	GARRETT	DATE: 10/18/2006	DATE:
LH		P/N 2119010-3003 AND P/N 2119020-4/-4002	Recommended	TIME: 1270.2	TIME:
8/07/2015	ONE TIME	TO P/N 2119020-4003	FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 76-3072	R1	INSTALL IMPROVED SURGE BLEED VALVE	GARRETT	DATE: 10/18/2006	DATE:
LH		PART NUMBER 978812-7-1	Optional	TIME: 1270.2	TIME:
2/24/2003	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 76-3076	R1	REWORK N1 DIGITAL ELECTRONIC ENGINE	GARRETT	DATE: 2/23/2024	DATE:
LH		CONTROL TO P/N 2119010-3004, OR P/N	Recommended	TIME: 5557.0	TIME:
7/01/2005	ONE TIME	2119020-4004, TO ADDRESS LEAN BLOWOUT	FOUND P/C/W	LD/CY: 4154	LD/CY:
SB 76-3082		REPLACE SPECIFIC IDENTIFIED N1 DIGITAL	GARRETT	DATE: 2/23/2024	DATE:
LH		ELECTRONIC ENGINE CONTROLS (DEEC)	Recommended	TIME: 5557.0	TIME:
7/02/2007	ONE TIME	P/N 2119010-3004 & 2119020-4004	FOUND P/C/W	LD/CY: 4154	LD/CY:
SB 77-3010	R2	ENGINE - N1 MOTIONAL PICKUP TRANSDUCER -	GARRETT	DATE: 7/06/2001	DATE:
LH		INSTALL AND/OR CLAMP IMPROVED MOTIONAL	Optional	TIME: 0.0	TIME:
2/07/1992	ONE TIME	PICKUP TRANSDUCER, P/N 3073827-1	C/W	LD/CY:	LD/CY:
SB 77-3019	R2	ENGINE INDICATING - TEMPERATURE -	GARRETT	DATE: 7/06/2001	DATE:
LH		INSTALL THERMOCLOUPLE HARNESS, P/N	Recommended	TIME: 0.0	TIME:
6/19/1990	ONE TIME	3073595-1	C/W	LD/CY:	LD/CY:
SB 77-3021	R1	ENGINE INDICATING-POWER - REPLACE	GARRETT	DATE: 2/23/2024	DATE:
LH		N1 MOTIONAL PICKUP TRANSDUCER	Recommended	TIME: 5557.0	TIME:
1/16/2006	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 79-3017	R3	DISTRIBUTION - REPLACE AIR/OIL COOLER &	GARRETT	DATE: 2/23/2024	DATE:
LH		BYPASS VALVE TO PREVENT OIL LEAKGE	Optional	TIME: 5557.0	TIME:
7/31/2006	ONE TIME	BY REDUCING FRETTING AT FLOW CONNECTION	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 79-3023	R1	ENGINE OIL - DISTRIBUTION - INSTALLATION	GARRETT	DATE: 2/23/2024	DATE:
LH		OF REDESIGNED OIL COOLER OIL TRANSFER	Recommended	TIME: 5557.0	TIME:
11/30/2006	ONE TIME	TUBE: TO REDUCE FATIGUE CRACKING	NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 79-3025	R4	ENGINE - REPLACE OR REWORK OIL LUBRICATE	GARRETT	DATE: 12/22/2010	DATE:
LH		NOZZLE: PROVIDES FOR INSTALLATION OF	Recommended	TIME: 2728.9	TIME:
11/11/2002	ONE TIME	LOCKING WASHERS TO PREVENT BOLTS LOOSEN	C/W	LD/CY: 2228	LD/CY:

LEFT ENGINE SERVICE BULLETINS GARRETT P99591

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 79-3032	R2	OIL - REWORK/REPLACE #6 BEARING LUBRICAT	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		TUBE ASSY P/N 3073418-1 TO 3073418-2		TIME: 0.0	TIME:
12/22/1989	ONE TIME	ELIMINATES SOURCE OF TUBE CORROSION	C/W	LD/CY:	LD/CY:
SB 79-3034	R3	OIL - REPLACEMENT/REWORK OF PLUG (CHIP	GARRETT Recommended	DATE: 2/23/2024	DATE:
LH		DETECTOR): VALVE HOUSING MADE OF STEEL		TIME: 5557.0	TIME:
1/28/2000	ONE TIME	TO REDUCE POSSIBILITY OF CRACKING	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 79-3038	R4	REPLACE SEAL, P/N 3020052-5 OR 3020052-16	GARRETT Recommended	DATE: 7/06/2001	DATE:
LH		WITH 3020052-21 IN BREATHER VALVE		TIME: 0.0	TIME:
7/08/1994	ONE TIME	INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W	LD/CY:	LD/CY:
SB 79-3041	R1	OIL - REPLACEMENT/INSPECT/REWORK OF CHIP	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		DETECTOR: FALSE DETECTOR LIGHTS RESULTED		TIME: 0.0	TIME:
1/28/2000	ONE TIME	IN NEED OF RIGID CONTROL OF MAGNETIC GAP	C/W	LD/CY:	LD/CY:
SB 79-3050	R1	INSTALL TRANSFER GEARBOX OIL SCAVENGE	GARRETT	DATE: 7/06/2001	DATE:
LH		TRANSFER & #6 BEARING OIL SCAVENGE		TIME: 0.0	TIME:
2/24/1995	ONE TIME	TUBES WITH FILTER/GEARBOX SCREENS	C/W	LD/CY:	LD/CY:
SB 79-3051		OIL-DISTRIBUTION-INSTALL METAL GASKET,	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		P/N 3075481-2		TIME: 0.0	TIME:
2/18/1994	ONE TIME		C/W	LD/CY:	LD/CY:
SB 79-3053		OIL-DISTRIBUTION-REPLACE REAR TURBINE	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		BEARING OIL-OUT TUBE AND GASKET		TIME: 0.0	TIME:
4/01/1994	ONE TIME		C/W	LD/CY:	LD/CY:
SB 79-3054	R1	OIL-DISTRIBUTION-INSTALL/REWORK OIL LUBE	GARRETT Optional	DATE: 7/06/2001	DATE:
LH		& SCAVENGE PUMP (OIL PUMP) THAT INCORP.		TIME: 0.0	TIME:
7/29/1997	ONE TIME	AN IMPROVED REGULATOR SECTION	C/W	LD/CY:	LD/CY:
SB 79-3055	R2	REPLACE SEAL P/N 3020052-5/-16/-21 WITH	GARRETT Optional	DATE: 10/18/2006	DATE:
LH		P/N 3020052-24, IN AIR BREATHER VALVE		TIME: 1270.2	TIME:
3/30/1995	ONE TIME	ASSY P/N 3072119-1	FOUND P/C/W	LD/CY: 1068	LD/CY:
SB 79-3057	R3	OIL-STORAGE-INSTALL OIL TANK LIQUID	GARRETT Optional	DATE: 2/23/2024	DATE:
LH		LEVEL GAGE, P/N 3075532-1/-2		TIME: 5557.0	TIME:
3/25/1997	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB 79-3058		OIL - DISTRIBUTION - INSTALL OIL JET	GARRETT	DATE: 10/18/2006	DATE:
LH		STRAINER, P/N 891764-11		TIME: 1270.2	TIME:
12/12/2001	ONE TIME	INACTIVE	N/A	LD/CY: 1068	LD/CY:
SB 79-3061	R1	AIR/OIL COOLER INSTALLATION-	GARRETT	DATE: 7/06/2001	DATE:
LH		INSTALL BOTTOM PANEL P/N 3071860-10,		TIME: 0.0	TIME:
2/22/1999	ONE TIME	& ASSOCIATED SCREWS & WASHERS	C/W	LD/CY:	LD/CY:
SB 79-3062		OIL-DISTRIBUTION-REPLACE DE-OIL VALVE	GARRETT	DATE: 7/06/2001	DATE:
LH		(CHECK VALVE), P/N 3074372-1 WITH P/N		TIME: 0.0	TIME:
6/19/1998	ONE TIME	3074372-2	C/W	LD/CY:	LD/CY:
SB 79-3063		INSTALL #6 BEARING LUBE TUBE ASSY P/N	GARRETT	DATE: 7/06/2001	DATE:
LH		3073736-1 & ASSOCIATED BRACKET, P/N		TIME: 0.0	TIME:
7/16/1999	ONE TIME	3073788-1/3075507-1 (AS APPLICABLE)	C/W	LD/CY:	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026

N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 79-3064	R3	INSTALL OIL LUBE & SCAVENGE PUMP P/N	GARRETT	DATE: 12/08/2014	DATE:
LH		3071949-12 TO INCORP. AN IMPROVED	Optional	TIME: 4069.2	TIME:
8/19/2005	ONE TIME	PRESSURE REGULATOR SECTION	C/W	LD/CY: 3092	LD/CY:
SB 79-3066	R2	INSTALL LUBE WITH REGULATOR AND SCAVENGE	GARRETT	DATE: 2/23/2024	DATE:
LH		PUMP (OIL LUBE PUMP), P/N 3060785-2	Recommended	TIME: 5557.0	TIME:
4/12/2012	ONE TIME		NOT APPLICABLE	LD/CY: 4154	LD/CY:
SB 79-3072		INSTALL IMPROVED PACKINGS IN OIL LUBE	GARRETT	DATE: 12/08/2014	DATE:
LH		AND SCAVENGE PUMPS, PN 3060785-2		TIME: 4069.2	TIME:
7/09/2010	ONE TIME	AND PN 3071949-3 THRU -12	C/W	LD/CY: 3092	LD/CY:
SB 79-3075		REPLACE OIL PUMP P/N 3060785-2 WITH	GARRETT	DATE: 2/23/2024	DATE:
LH		3060785-3		TIME: 5557.0	TIME:
	ONE TIME		FOUND P/C/W	LD/CY: 4154	LD/CY:
SB 79-3077		INSTALL IMPROVED OIL TANK INSTRUCTION	GARRETT	DATE: 2/23/2024	DATE:
LH		PLATE TO PREVENT OIL TANK OVERSERVICING		TIME: 5557.0	TIME:
5/09/2018	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB A72-3328		REPLACEMENT OF FAN ROTOR DISC, P/N	GARRETT	DATE: 10/18/2006	DATE:
LH		3072162-ALL, OR 3073436-ALL WITH MORE	Recommended	TIME: 1270.2	TIME:
5/31/1995	ONE TIME	THAN 4000 OPERATING CYCLES	N/A	LD/CY: 1068	LD/CY:
SB A72-3432	R5	INSPECTION OF FAN ROTOR ASSY P/N	GARRETT	DATE: 10/18/2006	DATE:
LH		3072162-ALL/3073436-ALL/3073539-ALL	Recommended	TIME: 1270.2	TIME:
5/31/1995	ONE TIME	OR 3074529-ALL	N/A	LD/CY: 1068	LD/CY:
SB A72-3472	R2	REPL HPT NOZZLE SUPPORT ON SPECIFIED	GARRETT	DATE: 7/06/2001	DATE:
LH		ENGINES	Recommended	TIME: 0.0	TIME:
2/27/1992	ONE TIME		C/W	LD/CY:	LD/CY:
SB A72-3474		ENGINE-BY-PASS SECTION - REPLACEMENT OF	GARRETT	DATE: 10/18/2006	DATE:
LH		SPECIFIC S/N LP TURBINE 3RD STAGE ROTOR	Recommended	TIME: 1270.2	TIME:
4/03/1992	ONE TIME	DISC MFG FROM THE SAME MATL HEAT CODE	N/A	LD/CY: 1068	LD/CY:
SB A72-3504		INSP OF FAN ROTOR ASSY CONT DISC & HUB	GARRETT	DATE: 10/18/2006	DATE:
LH		P/N3072162-1 THRU -4,3073436-1 THRU -4,	Recommended	TIME: 1270.2	TIME:
5/23/2007	ONE TIME	3073539-2 OR 3074529-2 (INACTIVE)	N/A PER DISC P/N	LD/CY: 1068	LD/CY:
SB A72-3544		REPLACEMENT OF SPECIFIC SERIAL NO. FIRST	GARRETT	DATE: 10/18/2006	DATE:
LH		& SECOND STAGE LP TURBINE DISKS MANUFACT	Recommended	TIME: 1270.2	TIME:
10/08/1993	ONE TIME	FROM THE SAME HEAT TREAT LOC	N/A	LD/CY: 1068	LD/CY:
SB A72-3569		ENGINE-BYPASS SECTION-FAN ROTOR DISC	GARRETT	DATE: 10/18/2006	DATE:
LH		CYCLE SERVICE LIFE REDUCTION	Mandatory	TIME: 1270.2	TIME:
5/23/2007	ONE TIME		N/A PER DISC P/N	LD/CY: 1068	LD/CY:
SB A72-3570		ENGINE-BYPASS SECTION-FAN ROTOR DISC	GARRETT	DATE: 10/18/2006	DATE:
LH		CYCLE SERVICE LIFE REDUCTION (INACTIVE	Mandatory	TIME: 1270.2	TIME:
5/23/2007	ONE TIME	FOR FURTHER ACCOMPLISHMENT)	N/A PER DISC P/N	LD/CY: 1068	LD/CY:
SB A72-3578		ENGINE-BYPASS SECTION-INSPECT	GARRETT	DATE: 10/18/2006	DATE:
LH		SPECIFIC S/N FAN ROTOR DISCS		TIME: 1270.2	TIME:
5/23/2007	ONE TIME	INACTIVE FOR FURTHER ACCOMPLISHMENT	N/A	LD/CY: 1068	LD/CY:

LEFT ENGINE SERVICE BULLETINS **GARRETT P99591**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB A72-3619		TURBINE SECTION-REPLACE HP TURBINE NOZZL	GARRETT	DATE: 10/18/2006	DATE:
LH		SUPPORT,P/N 3077050-3, IDENTIFIED WITH		TIME: 1270.2	TIME:
10/07/1997	ONE TIME	SPECIFIC JOB & LOG NUMBERS	N/A	LD/CY: 1068	LD/CY:
SB A72-3623	R7	ENGINE-TURBINE SECTION-HP TURBINE	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		ROTOR DISC BORE INSPECTION		TIME: 4069.2	TIME:
7/20/2010	ONE TIME	P/N 3072732-ALL,3072112-ALL,3073010-ALL	C/W	LD/CY: 3092	LD/CY:
SB A72-3624		ENGINE-ONE TIME OIL FILTER	GARRETT	DATE: 10/18/2006	DATE:
LH		RESAMPLE		TIME: 1270.2	TIME:
1/21/1998	ONE TIME		N/A	LD/CY: 1068	LD/CY:
SB A72-3641	R1	PERFORM EDDY CURRENT INSPECTION OF HP	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		IMPELLER P/N 3073393-1,3073394-1,		TIME: 4069.2	TIME: 8269.2
7/06/2010	RECURRS	3073433-1,3073434-1,3073398-ALL	C/W	LD/CY: 3092	LD/CY:
SB A72-3668		REPLACEMENT OF FAN ROTOR DISC	GARRETT	DATE: 2/23/2024	DATE:
LH		P/N 3072162-ALL,3073539-ALL,		TIME: 5557.0	TIME:
10/25/2000	ONE TIME	30728-16-ALL	COMPLIED WITH	LD/CY: 4154	LD/CY:
SB A72-3700		INSPECTION OF SPECIFIC LOW PRESSURE	GARRETT Recommended	DATE: 12/08/2014	DATE:
LH		FIRST STAGE (A5) TURBINE (LPT1) NOZZLES/		TIME: 4069.2	TIME:
4/22/2004	ONE TIME	TURBINE INTERSTAGE TRANSITION DUCTS	C/W	LD/CY: 3092	LD/CY:
SB A72-3700		INSPECTION OF SPECIFIC LOW PRESSURE	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		FIRST STAGE (A5) TURBINE (LPT1) NOZZLES/		TIME: 1270.2	TIME:
4/22/2004	ONE TIME	TURBINE INTERSTAGE TRANSITION DUCTS	C/W	LD/CY: 1068	LD/CY:
SB A73-3128	R1	DISTRIBUTION-INSTALL FLEX TUBE ASSY	GARRETT	DATE: 2/23/2024	DATE:
LH		P/N 399-5500-0003 OR 3074376-1		TIME: 5557.0	TIME:
8/17/2000	ONE TIME		COMPLIED WITH	LD/CY: 4154	LD/CY:
SB A73-3132	R1	DISTRIBUTION-INSTALL FLEX TUBE	GARRETT Mandatory	DATE: 10/18/2006	DATE:
LH		ASSY, P/N 3074376-2		TIME: 1270.2	TIME:
8/17/2000	ONE TIME		FOUND P/C/W	LD/CY: 1068	LD/CY:
SB A76-3079		POWER CONTROL - REPLACE SPECIFIC	GARRETT Mandatory	DATE: 2/23/2024	DATE:
LH		IDENTIFIED N1 DIGITAL ELECTRONIC ENGINE		TIME: 5557.0	TIME:
12/21/2006	ONE TIME	CONTROLS (DEEC) P/N 2119010 & 2119020	FOUND P/C/W	LD/CY: 4154	LD/CY:
SB A77-3020		TEMPERATURE - REMOVE & REPLACE SPECIFIC	GARRETT Recommended	DATE: 10/18/2006	DATE:
LH		NUMBERED THERMOCOUPLE LEAD ASSEMBLIES		TIME: 1270.2	TIME:
4/27/1990	ONE TIME	LISTED IN TABLE 1	N/A	LD/CY: 1068	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3001	R56	ENGINE - SERVICE LIFE - SERVICE LIFE	GARRETT	Mandatory	DATE: 3/11/2024
RH		LIMITS OF CRITICAL LIFE LIMITED			TIME: 5603.4
6/29/2011	ONE TIME	COMPONENTS	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3019		ENGINE - ACCESSORY DRIVE - INSPECTION	GARRETT	Recommended	DATE: 10/18/2006
RH		OF TRANSFER GEARBOX BEARING SUPPORT			TIME: 1381.9
4/09/1975	ONE TIME		N/A BY GEARBOX SERIES NO.	LD/CY:	DATE:
SB 72-3020		ENGINE - ACCESSORY DRIVE - REMOVE &	GARRETT	Mandatory	DATE: 10/18/2006
RH		REPLACE TRANSFER GEARBOX BEARING			TIME: 1381.9
5/26/1976	ONE TIME	SUPPORT CONTROLS WEAR IF RACE ROTATES	N/A BY GEARBOX SERIES NO.	LD/CY:	DATE:
SB 72-3042	R7	REPLACE COMBUSTION LINER P/N 3072448-4	GARRETT	Optional	DATE: 7/03/2001
RH		WITH IMPROVED COMBUSTION LINER			TIME: 0.0
12/12/2001	ONE TIME	INACTIVE	C/W	LD/CY:	DATE:
SB 72-3099	R2	ENGINE - HP TURBINE ROTOR ASSEMBLY -	GARRETT	Optional	DATE: 3/11/2024
RH		INSTALL HP TURBINE BLADE P/N 3072712-1			TIME: 5603.4
2/10/1989	ONE TIME	FOR FIELD EVALUATION	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3105	R14	ENGINE - INSPECTION INTERVALS -	GARRETT	Mandatory	DATE: 3/11/2024
RH		ESTABLISHING PERIODIC INSPECTION			TIME: 5603.4
10/26/2012	ONE TIME	INTERVALS	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3126	R13	ENGINE - PLANET GEAR INSTALLATION-REPLACE	GARRETT	Recommended	DATE: 3/11/2024
RH		/REWORK PLANET GEARSHAFT ASSY: USES			TIME: 5603.4
9/22/1989	ONE TIME	OPTIMIZED DIAMETER & BALANCE CLAMP NUTS	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3128	R9	ACCESSORY DRIVES - MODIFY ALTERNATOR	GARRETT	Recommended	DATE: 3/11/2024
RH		DRIVE SPUR GEARSHAFT			TIME: 5603.4
2/18/2003	ONE TIME		COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3154	R7	ENGINE - COMPRESS INSTALLATION - INCORP.	GARRETT	Optional	DATE: 3/11/2024
RH		ROTATING HP ROTATING GROUP THRUST BAL			TIME: 5603.4
9/10/2002	ONE TIME	SEAL ROTOR & COMPRESSOR DIFFUSER	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3159		ENGINE - INSPECT AND/OR REPLACE TURBINE	GARRETT	Recommended	DATE: 10/18/2006
RH		INTERSTAGE TRANSITION DUCT: WILL REVEAL			TIME: 1381.9
1/08/1988	ONE TIME	INADEQUATE WELD PENETRATION	N/A	LD/CY:	DATE:
SB 72-3170		ENGINE - TURBINE INTERSTAGE TRANSITION	GARRETT	Optional	DATE: 10/18/2006
RH		DUCT - INSTALL AFT MOUNT AUXILIARY			TIME: 1381.9
3/07/1985	ONE TIME	BRACKET	N/A	LD/CY:	DATE:
SB 72-3208	R1	ENGINE - COMPRESSOR INLET STATOR -	GARRETT	Optional	DATE: 3/11/2024
RH		REPLACE OR REWORK COMPRESSOR INLET			TIME: 5603.4
5/01/1989	ONE TIME	STATOR, P/N 3072429-1 TO P/N 3072429-2	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3237	R3	ENGINE - COMPRESSOR SECTION - INSTALL HP	GARRETT	Mandatory	DATE: 3/11/2024
RH		COMPRESSOR IMPELLER, P/N 3073393-1,			TIME: 5603.4
12/15/1989	ONE TIME	3073394-1 AND 3073398-1	COMPLIED WITH	LD/CY: 4357	DATE:
SB 72-3304		ENGINE - BYPASS SECTION - REPLACE/REWORK	GARRETT	Recommended	DATE: 10/10/2006
RH		FAN DISC NUT, P/N 3071981-1: WILL			TIME: 1381.9
5/24/1985	ONE TIME	PROVIDE COMMONALITY OF PARTS	FOUND P/C/W	LD/CY:	DATE:

RIGHT ENGINE SERVICE BULLETINS GARRETT P99590

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3309	R5	ENGINE - TURBINE SECTION - INSPECT AND/	GARRETT	Recommended	DATE: 3/11/2024	DATE:
RH	ONE TIME	OR REPAIR/REPLACE SPECIFIC IDENTIFIED			TIME: 5603.4	TIME:
10/20/2004		TURBINE INTERSTAGE TRANSITION DUCTS	COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3309		ENGINE - TURBINE SECTION - INSPECT AND/	GARRETT	Recommended	DATE: 10/18/2006	DATE:
RH	ONE TIME	OR REPAIR/REPLACE SPECIFIC IDENTIFIED			TIME: 1381.9	TIME:
10/20/2004		TURBINE INTERSTAGE TRANSITION DUCTS	N/A		LD/CY:	LD/CY:
SB 72-3345	R3	ENGINE - REWORK/REPLACE THERMOCOUPLE	GARRETT	Optional	DATE: 3/11/2024	DATE:
RH	ONE TIME	HARNESS OR THERMOCOUPLE LEAD ASSEMBLY			TIME: 5603.4	TIME:
11/30/1990			COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3346		WELD TITANIUM STRIPS TO ENDS OF ALL	GARRETT	Optional	DATE: 12/08/2014	DATE:
RH	ONE TIME	VANES AT INNER & OUTER SHROUD LOCATIONS			TIME: 4117.1	TIME:
1/12/2007		ON FAN BY-PASS STATORS P/N3071965-1,	C/W		LD/CY: 3302	LD/CY:
SB 72-3358	R5	ENGINE - COMPRESSOR SECTION - INSTALL	GARRETT	Recommended	DATE: 3/11/2024	DATE:
RH	ONE TIME	OUTER TRANSITION LINER P/N 3073526-3			TIME: 5603.4	TIME:
9/09/1994		WITH SPEC. P/N HP COMPRESSOR DIFFUSERS	COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3364RWK		RWK HP DIFF TO 3071253-16 OR 3077032-6,	GARRETT		DATE: 3/11/2024	DATE:
RH	ONE TIME	-8,-9,-10			TIME: 5603.4	TIME:
			NOT APPLICABLE		LD/CY: 4357	LD/CY:
SB 72-3367	R3	ENGINE - TURBINE SECTION - PERFORM ONE	GARRETT	Recommended	DATE: 7/03/2001	DATE:
RH	ONE TIME	TIME INSPECTION OF NOZZLE THROAT (A5)			TIME: 0.0	TIME:
9/02/1994		OPENING FOR PROPER DIMENSION	C/W		LD/CY:	LD/CY:
SB 72-3369	R6	ENGINE - TURBINE SECTION - ADJUST NOZZLE	GARRETT		DATE: 3/11/2024	DATE:
RH	ONE TIME	THROAT (A5) OPENING(S) EFFECTIVE (AE)			TIME: 5603.4	TIME:
6/26/2002		FLOW AREA	COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3370	R1	ENGINE - TURBINE SECTION - INSPECT AND	GARRETT	Recommended	DATE: 3/11/2024	DATE:
RH	ONE TIME	REWORK TURBINE INTERSTAGE TRANSITION			TIME: 5603.4	TIME:
6/15/1990		DUCTS P/N 3071486-X,3072318-X,3072726-X	COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3377	R4	ENGINE - INSTALL REDESIGNED COMBUSTION	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	SYSTEM (LOW SMOKE)			TIME: 0.0	TIME:
1/24/2002		INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W		LD/CY:	LD/CY:
SB 72-3384	R2	ENGINE - BY-PASS SECTION - REPLACE OIL	GARRETT	Optional	DATE: 3/11/2024	DATE:
RH	ONE TIME	DEFLECTOR OR REWORK EXISTING OIL			TIME: 5603.4	TIME:
3/06/2001		DEFLECTOR	COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 72-3393		ENGINE - BY-PASS SECTION - REPLACE/	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	REWORK FAN SUPPORT SHAFT & HOUSING			TIME: 0.0	TIME:
12/17/2001		INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W		LD/CY:	LD/CY:
SB 72-3396		ENGINE - CONVERT ENGINE, PART NO.	GARRETT	Optional	DATE: 10/10/2006	DATE:
RH	ONE TIME	3073610-3 TO PART NO. 3073610-1			TIME: 1381.9	TIME:
9/22/1989			N/A		LD/CY:	LD/CY:
SB 72-3397	R4	ENGINE - INITIATE COMPONENT MAINTENANCE/	GARRETT	Mandatory	DATE: 3/11/2024	DATE:
RH	ONE TIME	MODIFICATION RECORD CARD (CARD-LOG BOOK)			TIME: 5603.4	TIME:
11/14/2012		(CMMC)	COMPLIED WITH		LD/CY: 4357	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3405	R2	REPLACE SHROUD RETAINING SLEEVE, P/N	GARRETT	DATE: 7/03/2001	DATE:
RH		3070023-1 WITH P/N 3070023-3	Optional	TIME: 0.0	TIME:
11/26/2002	ONE TIME	OR 3070023-4	C/W	LD/CY:	LD/CY:
SB 72-3408		COMPRESSOR SECTION - REPLACE SPRING	GARRETT	DATE: 7/03/2001	DATE:
RH		TENSION WASHER, P/N 3000005-2/-56	Recommended	TIME: 0.0	TIME:
2/19/1990	ONE TIME	WITH P/N 3000005-64	C/W	LD/CY:	LD/CY:
SB 72-3409	R1	COMPRESSOR SECTION - INSTALL FIRST STAGE	GARRETT	DATE: 7/03/2001	DATE:
RH		COMPRESSOR WHEEL ASSEMBLY BLADE	Recommended	TIME: 0.0	TIME:
8/10/1990	ONE TIME	P/N 3075358-1	C/W	LD/CY:	LD/CY:
SB 72-3410	R1	COMPRESSOR SECTION - INSTALL SECOND	GARRETT	DATE: 10/10/2006	DATE:
RH		STAGE COMPRESSOR ROTOR ASSEMBLY BLADE	Recommended	TIME: 1381.9	TIME:
8/10/1990	ONE TIME	RETAINER, P/N 3075357-2	FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3411	R1	COMPRESSOR SECTION - INSTALL THIRD	GARRETT	DATE: 10/10/2006	DATE:
RH		STAGE COMPRESSOR ROTOR ASSEMBLY BLADE	Recommended	TIME: 1381.9	TIME:
8/10/1990	ONE TIME	RETAINER, P/N 3075357-3	FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3413		COMPRESSOR SECTION-INSTALL DRAIN VALVES,	GARRETT	DATE: 7/03/2001	DATE:
RH		P/N 868889-3, & TEE PLATE, P/N 3071835-2	Optional	TIME: 0.0	TIME:
7/19/2006	ONE TIME	THAT INCORPORATE LOCKWIRE HOLES	C/W	LD/CY:	LD/CY:
SB 72-3416	R5	HP IMPELLER SHROUD WITH IMPROVED COATING	GARRETT	DATE: 7/03/2001	DATE:
RH			Recommended	TIME: 0.0	TIME:
1/22/2001	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3419		TURBINE SECTION - PERMANENTLY SEAL NON-	GARRETT	DATE: 7/03/2001	DATE:
RH		FUNCTIONAL BOSS ON THRUST AND EXHAUST	Optional	TIME: 0.0	TIME:
11/30/1990	ONE TIME	NOZZLE P/N 3071431-1/-2/-3	C/W	LD/CY:	LD/CY:
SB 72-3421		ENGINE - COMPRESSOR SECTINO - INSTALL LP	GARRETT	DATE: 7/03/2001	DATE:
RH		COMPRESSOR BEARING HOUSING, P/N	Recommended	TIME: 0.0	TIME:
5/24/1991	ONE TIME	3071691-7 OR 3077043-3	C/W	LD/CY:	LD/CY:
SB 72-3422		INSPECTION OF THE PINION GEAR RETAINER	GARRETT	DATE: 7/03/2001	DATE:
RH		PLATE ASSEMBLY	Recommended	TIME: 0.0	TIME:
1/03/1991	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3424		BY-PASS SECTION - REPLACEMENT OF FAN	GARRETT	DATE: 7/03/2001	DATE:
RH		ROTOR ASSY WITH SPECIFIC S/N DISC & HUB	Recommended	TIME: 0.0	TIME:
12/20/1990	ONE TIME	MADE FROM THE SAME MATERIAL HEAT CODE	C/W	LD/CY:	LD/CY:
SB 72-3426	R2	ENG.-TURBINE SECTION-REPLACE/REWORK 3RD	GARRETT	DATE: 7/03/2001	DATE:
RH		STAGE LP TURBINE NOZZLE, P/N 3072342-2	Recommended	TIME: 0.0	TIME:
5/08/1996	ONE TIME	TO 3072342-4 OR 3070014-3 TO 3070014-5	C/W	LD/CY:	LD/CY:
SB 72-3429	R1	COMPRESSOR SECTION - REPLACE TIE BOLT,	GARRETT	DATE: 7/03/2001	DATE:
RH		P/N 3070065-1/-4 WITH P/N 3070065-3 OR	Recommended	TIME: 0.0	TIME:
4/03/1992	ONE TIME	3073049-1	C/W	LD/CY:	LD/CY:
SB 72-3434	R3	ENGINE - TURBINE SECTION-INSTALLATION OF	GARRETT	DATE: 7/03/2001	DATE:
RH		HIGH PRESSURE TURBINE NOZZLE ASSEMBLY	Recommended	TIME: 0.0	TIME:
4/01/1992	ONE TIME	WITH RELOCATED A4 NOZZEL SEGMENTS	C/W	LD/CY:	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3441	R2	BY-PASS SECTION - INSTALL RECTANGULAR DAMPER RING, P/N 3073524-6, ON PINION (SUN) GEAR ASSEMBLY	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
6/04/1993					LD/CY:
SB 72-3443		COMPRESSOR SECTION - REPLACEMENT OF LP COMPRESSOR SECOND STAGE (STATIC) SHROUD, P/N 3070289-2	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/06/1991					LD/CY:
SB 72-3449		ENGINE-COMPRESSOR SECTION-INSTALL WASHER P/N S8154-2P025, ON BOLTS THAT SECURE HP SHROUD TO HP COMPRESSOR DIFFUSER	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
2/07/1992					LD/CY:
SB 72-3453	R2	REPLACE #4, #5 CARBON SEALS AND ROTORS	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/17/1993					LD/CY:
SB 72-3455	R3	INSTALL PACKINGS, P/N S9413-036 AND SEAL P/N 3075506-2, ON TOWER SHAFT OIL TRANSFER TUBE	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/24/1996					LD/CY:
SB 72-3458	R12	ENGINE-BYPASS SECTION-PROVIDE EDDY CURRENT INSPECTION INSTRUCTIONS FOR FAN ROTOR ASSY DISC	GARRETT		DATE: 3/11/2024
RH	ONE TIME		COMPLIED WITH		TIME: 5603.4
6/23/2008					LD/CY: 4357
SB 72-3469	R2	ENGINE - COMPRESSOR SECTION - REPLACE NO. 3 CARBON FACE SEAL AND SEAL ROTOR INACTIVE	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/14/2001					LD/CY:
SB 72-3473		ENGINE BY-PASS SECTION - ADDITIONAL SOAP SAMPLING REQUIREMENT	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
4/03/1992					LD/CY:
SB 72-3475		ENGINE - BY-PASS SECTION - REPLACE NO. 1 CARBON FACE SEAL AND SEAL ROTOR. INACTIVE	GARRETT	Optional	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/14/2001					LD/CY:
SB 72-3476	R1	TURBINE SECTION - INSTALL HP TURBINE PISTON RING SEAL, P/N 3000002-10	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
10/16/1992					LD/CY:
SB 72-3477		ACCESSORY DRIVES - REPLACE ACCESSORY DRIVE GEARBOX GASKET	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
4/08/1992					LD/CY:
SB 72-3480		INCORPORATION OF NEW ENGINE LOG BOOK	GARRETT		DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
5/29/1992					LD/CY:
SB 72-3483	R2	COMPRESSOR SECTION - INSTALL LP COMPRESSOR FOURTH STAGE STATOR	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
11/08/1996					LD/CY:
SB 72-3486	R2	TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED HP TURBINE ROTOR ASSEMBLY DISCS	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
6/19/1998					LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3487 RH 6/20/2003	R3 ONE TIME	ENGINE-BYPASS SECTION-INSPECT/REWORK FAN BLADE MIDSPAN DAMPER	GARRETT Recommended COMPLIED WITH	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 72-3488 RH 10/02/1998	R3 ONE TIME	TURBINE SECTION - PROVIDE AUTHORITY FOR INSTALLATION OF ALTERNATE PART NUMBERED HP TURBINE SHROUD SEGMENTS	GARRETT Recommended C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-3492 RH 7/30/1993	ONE TIME	BYPASS SECTION - INSTALL O-RING PACKING, P/N S9873-001, BETWEEN SPINNER SUPPORT AND FAN BLADES	GARRETT Optional C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3494 RH 8/06/2015	R13 RECURRS	TURBINE SECTION-HIGH PRESSURE & LOW PRESSURE TURBINE BLADE HOUR TRACKING	GARRETT Recommended COMPLIED WITH	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: 7003.4 LD/CY:
SB 72-3498 RH 5/07/1993	R1 ONE TIME	BYPASS SECTION - INSTALL FAN SHAFT & RING GEAR WITH NEW RETAINING RING	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3499 RH 12/14/2001	R6 ONE TIME	ENGINE - BY-PASS SECTION - INSTALL COMPONENT PARTS TO PREVENT OIL LEAKAGE IN #1 OIL SEAL REGION. INACTIVE	GARRETT Recommended N/A	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 72-3507 RH	R1 ONE TIME	REWORK FAN SHAFT HOUSING 3072160-1/-2 TO 3077082-1/-2	GARRETT FOUND P/C/W	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 72-3520 RH 10/15/1999	ONE TIME	TURBINE SECTION - INSTALL LP THIRD STAGE TURBINE ROTOR ASSEMBLY INCORPORATING A NEWLY DESIGNED SEAL ROTOR	GARRETT Optional C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3524 RH 6/04/1993	ONE TIME	BYPASS SECTION - INSTALL RETAINING (DAMPER) RING, P/N 3072463-2	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3529 RH 10/25/2000	ONE TIME	BYPASS SECTION - REDESIGNED FAN DISC	GARRETT Optional C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3530 RH 10/08/1993	R1 ONE TIME	TURBINE SECTION - INSTALL AN LP SECOND STAGE TURBINE NOZZLE THAT INCORPORATES A HONEYCOMB AIR SEAL	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 72-3531 RH 1/28/2003	R4 ONE TIME	BYPASS SECTION-INSTALLATION OF FAN BLADES & IDENTIFICATION OF FAN ROTOR ASSEMBLIES	GARRETT Recommended C/W	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 72-3532 RH	ONE TIME	REWORK COMPRESSOR INTERSTAGE DIFFUSER	GARRETT N/A	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 72-3535 RH 9/10/1993	ONE TIME	LOW PRESSURE TURBINE ASSY-INSTALL LP SHAFT & SEAL ASSY THAT INCORPORATES A HONEYCOMB SEAL	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3536	R2	COMBUSTION SECTION - INSTALL COMBUSTION CHAMBER & INNER TRANSITION LINER (CONTROLLED FIT/LOW SMOKE)	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME		C/W		TIME: 0.0	TIME:
1/24/2002			LD/CY:		LD/CY:	
SB 72-3537		COMPRESSOR SECTION-INSTALL LP 1ST STAGE COMPRESSOR ROTOR ASSY, INCORPORATING A SHOULDERED SHAFT WITH INTERFERENCE FIT	GARRETT	Optional	DATE: 3/11/2024	DATE:
RH	ONE TIME		COMPLIED WITH		TIME: 5603.4	TIME:
10/18/1993			LD/CY: 4357		LD/CY:	
SB 72-3538		COMPRESSOR SECTION - REPLACEMENT OF NO.3 COMPRESSOR BEARING RETAINER NUT	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME		C/W		TIME: 0.0	TIME:
9/13/1993			LD/CY:		LD/CY:	
SB 72-3540	R2	COMPRESSOR SECTION - IMPROVED NO.4 & 5 BEARING SUMP SCAVENGE INACTIVE	GARRETT	Recommended	DATE: 7/03/2001	DATE:
RH	ONE TIME		C/W		TIME: 0.0	TIME:
9/14/2001			LD/CY:		LD/CY:	
SB 72-3550	R1	TURBINE SECTION-INSTALL A HONEYCOMB AIR SEAL IN THE TURBINE INTERSTAGE TRANSITION DUCT	GARRETT	Optional	DATE: 10/10/2006	DATE:
RH	ONE TIME		FOUND P/C/W		TIME: 1381.9	TIME:
5/18/1995			LD/CY:		LD/CY:	
SB 72-3555	R1	COMPRESSOR SECTION-INSTALL HP DIFFUSER INCORPORATING HONEYCOMB SEAL, HARDOAT, & IMPROVED SURFACE FINISH	GARRETT		DATE: 3/11/2024	DATE:
RH	ONE TIME		COMPLIED WITH		TIME: 5603.4	TIME:
8/30/2002			LD/CY: 4357		LD/CY:	
SB 72-3560	R1	COMPRESSOR SECTION-LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT		DATE: 10/10/2006	DATE:
RH	ONE TIME		FOUND P/C/W		TIME: 1381.9	TIME:
3/26/1996			LD/CY:		LD/CY:	
SB 72-3561	R2	COMPRESSOR SECTION-LP SECOND STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT		DATE: 10/10/2006	DATE:
RH	ONE TIME		C/W		TIME: 1381.9	TIME:
5/05/2005			LD/CY:		LD/CY:	
SB 72-3562	R1	COMPRESSOR SECTION-LP THIRD STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT		DATE: 10/10/2006	DATE:
RH	ONE TIME		FOUND P/C/W		TIME: 1381.9	TIME:
3/26/1996			LD/CY:		LD/CY:	
SB 72-3563	R1	COMPRESSOR SECTION-LP FOURTH STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT		DATE: 10/10/2006	DATE:
RH	ONE TIME		FOUND P/C/W		TIME: 1381.9	TIME:
3/26/1996			LD/CY:		LD/CY:	
SB 72-3564	R7	ENGINE - BANK/SPARE ENGINE CONVERSIONS-	GARRETT		DATE: 10/10/2006	DATE:
RH	ONE TIME		N/A		TIME: 1381.9	TIME:
1/07/2003			LD/CY:		LD/CY:	
SB 72-3565		TURBINE SECTION-REMOVAL OF A4 NOZZLE SEGMENTS FROM SPECIFICALLY IDENTIFIED ENGINES	GARRETT	Recommended	DATE: 10/10/2006	DATE:
RH	ONE TIME		N/A		TIME: 1381.9	TIME:
6/30/1994			LD/CY:		LD/CY:	
SB 72-3566	R4	ENGINE-INSTALL ALTERNATE FITTINGS WITH A RING SEAL	GARRETT		DATE: 3/11/2024	DATE:
RH	ONE TIME		COMPLIED WITH		TIME: 5603.4	TIME:
10/29/2002			LD/CY: 4357		LD/CY:	
SB 72-3577		TURBINE SECTION-REPLACE HONEYCOMB AIR SEAL, PART NUMBER 3073354-3, IN THE TURBINE INTERSTAGE TRANSITION DUCT	GARRETT	Recommended	DATE: 12/08/2014	DATE:
RH	ONE TIME		FOUND P/C/W		TIME: 4117.1	TIME:
7/19/1995			LD/CY: 3302		LD/CY:	

RIGHT ENGINE SERVICE BULLETINS GARRETT P99590

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3584		OIL-DISTRIBUTION-REPLACE ELBOW	GARRETT	DATE: 3/11/2024	DATE:
RH		ADAPTER FOR BUFFER AIR TRANSFER TUBE		TIME: 5603.4	TIME:
11/03/1995	ONE TIME	ON THE LP COMPRESSOR CASE	COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3592	R1	ENGINE - TURBINE SECTION - LP TURBINE	GARRETT Recommended	DATE: 10/10/2006	DATE:
RH		THIRD STAGE ROTOR ASSY (DISC) LIFE		TIME: 1381.9	TIME:
4/30/1998	ONE TIME	LIMITED PART LOG CARD	N/A	LD/CY:	LD/CY:
SB 72-3596	R7	ENGINE - REPLACE MAINSHAFT CARBON RING	GARRETT Optional	DATE: 7/03/2001	DATE:
RH		SEALS AND ASSOCIATED VENT/OIL SYSTEM		TIME: 0.0	TIME:
9/14/2001	ONE TIME	COMPONENTS INACTIVE	C/W	LD/CY:	LD/CY:
SB 72-3600		ENGINE-COMPRESSOR SECTION-INSTALL	GARRETT	DATE: 3/11/2024	DATE:
RH		LP COMPRESSOR STATOR SHIM,		TIME: 5603.4	TIME:
1/13/1997	ONE TIME	P/N 3060360-1 THRU -11	COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3603RWK	R1	REWORK COMPRESSOR INTERSTAGE DIFFUSER	GARRETT	DATE: 10/10/2006	DATE:
RH		TO INCORPORATE/ENLARGE OIL SCAVENGE		TIME: 1381.9	TIME:
5/22/1996	ONE TIME	SLOTS	FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3604	R4	ENGINE-ACCESSORY DRIVES-REWORK TRANSFER	GARRETT	DATE: 10/10/2006	DATE:
RH		GEARBOX ASSEMBLY,P/N 3070093-X TO P/N		TIME: 1381.9	TIME:
3/20/2015	ONE TIME	3070093-12	FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3605	R4	INSTALL/REWORK ACCESSORY DRIVE GEARBOX	GARRETT	DATE: 12/08/2014	DATE:
RH		ASSY W/ AN IMPROVED AIR OIL SEPARATOR		TIME: 4117.1	TIME:
6/16/2004	ONE TIME	& A NEW AIR BREATHER VALVE ASSY	C/W	LD/CY: 3302	LD/CY:
SB 72-3613	R8	ENGINE-REPLACE NO.1 & NO.3 CARBON RING	GARRETT Recommended	DATE: 12/08/2014	DATE:
RH		SEALS & ASSOCIATED VENT/OIL SYSTEM		TIME: 4117.1	TIME:
1/23/2009	ONE TIME	COMPONENTS	C/W	LD/CY: 3302	LD/CY:
SB 72-3614RWK		BYPASS SECTION-REWORK NO.1 SEAL &	GARRETT	DATE: 3/11/2024	DATE:
RH		SEAL HOUSING TO PART NO.		TIME: 5603.4	TIME:
2/06/1997	ONE TIME	3071966-5 OR 3077122-1/-2/-3	COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3615		REWORK AIR BREATHER VALVE, P/N 3071564-7	GARRETT	DATE: 3/11/2024	DATE:
RH		-8 TO P/N 3071564-9,USED IN AIR BREATHR		TIME: 5603.4	TIME:
2/06/1997	ONE TIME	VALVE P/N 3075323-3	COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3634		2ND STAGE LPC BLADE INSPECTION	GARRETT	DATE: 10/10/2006	DATE:
RH		& P/N REID		TIME: 1381.9	TIME:
	ONE TIME		FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3635		INSPECT/REWORK/INSTALL OIL FILTER COVER	GARRETT	DATE: 10/10/2006	DATE:
RH		P/N 3072231-1 TO P/N 3072231-4		TIME: 1381.9	TIME:
11/16/1998	ONE TIME		FOUND P/C/W	LD/CY:	LD/CY:
SB 72-3638	R1	INSTALLATION OF TRANSFER GEARBOX	GARRETT Recommended	DATE: 3/11/2024	DATE:
RH		HOUSING ASSEMBLY P/N 3070429-8		TIME: 5603.4	TIME:
4/02/2007	ONE TIME		COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3643		BYPASS SECTION- INSTALL FAN BLADE	GARRETT Optional	DATE: 3/11/2024	DATE:
RH		RETAINING RING, P/N 3073789-1		TIME: 5603.4	TIME:
3/03/1999	ONE TIME		COMPLIED WITH	LD/CY: 4357	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 72-3644	R2	INSTALL HP IMPELLER SHROUD	GARRETT	DATE: 12/08/2014	DATE:
RH		P/N 3074567-1/-2	Optional	TIME: 4117.1	TIME:
1/10/2001	ONE TIME		C/W	LD/CY: 3302	LD/CY:
SB 72-3650		ACCESSORY DRIVES SECTION-NEW NAMEPLATE	GARRETT	DATE: 3/11/2024	DATE:
RH		P/N S20048-1, FOR TRANSFER GEARBOX ASSY		TIME: 5603.4	TIME:
8/10/1999	ONE TIME		COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 72-3658		AIR INLET SECTION-REPLACE FAN INLET	GARRETT	DATE: 7/03/2001	DATE:
RH		HOUSING		TIME: 0.0	TIME:
9/21/2001	ONE TIME		C/W	LD/CY:	LD/CY:
SB 72-3662	R8	REPLACE NO. 4 AND NO. 5 CARBON RING	GARRETT	DATE: 12/08/2014	DATE:
RH		SEALS AND ASSOCIATED VENT/OIL SYSTEM	Recommended	TIME: 4117.1	TIME:
4/12/2012	ONE TIME	COMPONENTS	C/W	LD/CY: 3302	LD/CY:
SB 72-3664		INSPECTION/REPLACEMENT OF THREADED ENDS	GARRETT	DATE: 10/10/2006	DATE:
RH		TIE ROD, (LP TIE ROD), P/N 3073049-1 &	Recommended	TIME: 1381.9	TIME:
5/05/2000	ONE TIME	3074744-1	N/A	LD/CY:	LD/CY:
SB 72-3671	R2	INSTALL REDESIGNED COMBUSTOR	GARRETT	DATE: 3/11/2024	DATE:
RH		CHAMBER PLENUM CASE		TIME: 5603.4	TIME:
7/28/2009	ONE TIME		NOT APPLICABLE	LD/CY: 4357	LD/CY:
SB 72-3674	R2	INSPECTION OF SPECIFIC IDENTIFIED	GARRETT	DATE: 10/10/2006	DATE:
RH		MAIN SUPPORT FRAME ASSEMBLIES	Recommended	TIME: 1381.9	TIME:
9/16/2003	ONE TIME		N/A	LD/CY:	LD/CY:
SB 72-3675		INSPECT FAN BLADES FOR UNAUTHORIZED	GARRETT	DATE: 10/10/2006	DATE:
RH		MARKINGS ON THE FAN BLADE DOVETAIL AFT	Recommended	TIME: 1381.9	TIME:
1/13/2010	ONE TIME	REGION	C/W	LD/CY:	LD/CY:
SB 72-3676		REPLACE THE HOISTING BRACKET ON THE	GARRETT	DATE: 10/10/2006	DATE:
RH		FAN DUCT SET, P/N 3072420-7(UPPER HALF)	Recommended	TIME: 1381.9	TIME:
7/12/2001	ONE TIME	ON SPECIFIC IDENTIFIED ENGINES	N/A	LD/CY:	LD/CY:
SB 72-3682		REMOVE SPECIFIC IDENTIFIED LP	GARRETT	DATE: 10/10/2006	DATE:
RH		COMPRESSOR 2ND STAGE (LPC2)	Recommended	TIME: 1381.9	TIME:
11/26/2002	ONE TIME	DISCS	N/A	LD/CY:	LD/CY:
SB 72-3685		REPLACE SPECIFIC IDENTIFIED LP SECOND	GARRETT	DATE: 10/10/2006	DATE:
RH		STAGE TURBINE BLADES, P/N 3072012-2 AND	Recommended	TIME: 1381.9	TIME:
3/08/2002	ONE TIME	P/N 3074099-1	C/W	LD/CY:	LD/CY:
SB 72-3687		REMOVE SPECIFIC IDENTIFIED LP	GARRETT	DATE: 10/10/2006	DATE:
RH		COMPRESSOR 2ND STAGE (LPC2)	Recommended	TIME: 1381.9	TIME:
11/11/2002	ONE TIME	DISCS	N/A	LD/CY:	LD/CY:
SB 72-3696		ACCESSORY DRIVES SECTOR- INSTALL	GARRETT	DATE: 12/08/2014	DATE:
RH		AIR-OIL SEPARATOR P/N 3075781-1	Recommended	TIME: 4117.1	TIME:
6/16/2004	ONE TIME		C/W	LD/CY: 3302	LD/CY:
SB 72-3704		INSTALL A LOW PRESSURE FIRST STAGE	GARRETT	DATE: 12/08/2014	DATE:
RH		TURBINE (LPT1) ROTOR ASSEMBLY WITH	Recommended	TIME: 4117.1	TIME:
9/15/2004	ONE TIME	AN IMPROVED LPT1 ROTOR DISC	C/W	LD/CY: 3302	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3739 RH 4/21/2008	ONE TIME	INSTALL IMPROVED NO. 1 SEG CARBON SEAL, P/N 3060457-1 OR -2 (AS APPLICABLE) AND/OR NO. 3 SEG CARBON SEAL 3060458-1	GARRETT C/W	DATE: 1/26/2011 TIME: 2840.6 LD/CY: 2290	DATE: TIME: LD/CY:
SB 72-3741 RH 4/21/2008	ONE TIME	INSTALL IMPROVED NO. 4 SEG CARBON SEAL, P/N 3060437-1 AND NO. 5 SEG CARBON SEAL P/N 3060436-1	GARRETT C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-3752 RH 11/05/2008	ONE TIME	INSTALL IMPROVED HPT NOZZLE SEGMENTS, P/N 3074003-3, -4 AND 3074004-2, -4	GARRETT C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-3759 I RH 10/28/2011	R1 ONE TIME	INSTALL IMPROVED PLAIN ENCASED SEAL, P/N 3020052-26	GARRETT C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-3761 RH 3/03/2010	ONE TIME	INSTALL IMPROVED DIFFUSER VANE DESWIRL PN 3071346-5, TO PREVENT FRET ON OUTER TRANSITION DESWIRL LINER	GARRETT C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-3777 RH 8/17/2012	R2 ONE TIME	INSTALL IMPROVED LOW PRESSURE SECOND STAGE (LPC2) SHROUD, PN 3072403-6	GARRETT C/W	DATE: 12/08/2014 TIME: 4117.1 LD/CY: 3302	DATE: TIME: LD/CY:
SB 72-A3748 RH 8/21/2008	ONE TIME	REPLACE SPECIFIC IDENTIFIED 2ND STG LOW PRESS COMPRESSOR & 3RD LOW PRESS COMPRESSOR ROTOR DISCS	GARRETT N/A	DATE: 1/26/2011 TIME: 2840.6 LD/CY: 2290	DATE: TIME: LD/CY:
SB 73-3067 RH 2/24/1995	R3 ONE TIME	REWORK FUEL CONTROL P/N 3070800-8 TO P/N 3070800-11 OR P/N 3070800-11 TO P/N 3070800-8	GARRETT Recommended NOT APPLICABLE	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 73-3083 RH 10/20/1989	R1 ONE TIME	ENGINE - FUEL AND CONTROL - REPLACE FUEL PUMP ANTI-ICING VALVE WITH UNIT CONTAINING AN IMPROVED THERMOSTAT	GARRETT Recommended N/A	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 73-3097 RH 3/08/1989	ONE TIME	ENGINE FUEL AND CONTROL -CONTROLLING - INSTALL IMPROVED METERING VALVE ASSEMBLY PART NO 3074320-1 IN FUEL CONTROL	GARRETT Optional NOT APPLICABLE	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 73-3106 RH 9/18/1992	R2 ONE TIME	DISTRIBUTION - REPLACEMENT OF BALL AND SPRING ASSY IN FUEL HEATER CHECK VALVE WHEN UNIT FAILS INTERNAL LEAKAGE CHECK	GARRETT Recommended C/W	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 73-3107 RH 4/20/1994	R4 ONE TIME	INSTALL SUPPORT CLAMP, P/N 211-501-9114, ON FUEL LINE, P/N 3071051-1	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 73-3108 RH 10/09/1995	ONE TIME	ENGINE FUEL AND CONTROL - DISTRIBUTION INSTALL FUEL CONTROL P3 SENSE LINE, GASKET, P/N 3075481-1	GARRETT Recommended C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 73-3109 RH 3/12/1993	R1 ONE TIME	ENGINE FUEL & CONTROL-DISTRIBUTION-MAIN- TENANCE OF ENGINES WITH SERVICE TUBE CLAMPS P/N 3073542-1 & 3073543-91 INSTLD	GARRETT C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 73-3110	R1	ENG FUEL & CONTROL - DIST.-REPLACE SECONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPEC IDENTIFIED FUEL MANIFOLD ASSOYS	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
4/03/1992					LD/CY:
SB 73-3112		ENG FUEL & CONT-CONTROLLING-INSP & REPL IDENT FUEL CONT VAR RESIS (PWR LEV POT) AS REQ AT COMPONENT OVHL/REPAIR FACILITY	GARRETT	Recommended	DATE: 10/10/2006
RH	ONE TIME		N/A		TIME: 1381.9
2/14/1992					LD/CY:
SB 73-3114		FUEL AND CONTROL-CONTROLLING-REPLACE METERING VALVE ADJUSTMENT SHAFT AND THREADED RESTRICTOR AT COMPONENT O/H	GARRETT	Recommended	DATE: 10/10/2006
RH	ONE TIME		N/A		TIME: 1381.9
5/29/1992					LD/CY:
SB 73-3115	R1	INSTALL AN IMPROVED FUEL CONTROL INCORPORATING A MINIMUM MOD CONFIGURATION STANDARD	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
3/18/1994					LD/CY:
SB 73-3117		FUEL AND CONTROL-DISTRIBUTION-REPLACE SPECIFIC IDENTIFIED FUEL MANIFOLD ASSEMBLIES.	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
7/07/1992					LD/CY:
SB 73-3119		CONTROLLING - REPLACE/REWORK GOVERNOR FLYWEIGHT ASSEMBLY AT COMPONENT REPAIR FACILITY	GARRETT	Recommended	DATE: 10/10/2006
RH	ONE TIME		N/A		TIME: 1381.9
5/07/1993					LD/CY:
SB 73-3121		DISTRIBUTION - REPLACE SECONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPECIFIC IDENTIFIED FUEL MANIFOLD ASSEMBLIES	GARRETT	Recommended	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
11/03/1993					LD/CY:
SB 73-3131	R2	ONE TIME INSPECTION FOR SPECIFIC ID FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOWS P/N 3074139-2	GARRETT	Recommended	DATE: 10/10/2006
RH	ONE TIME		N/A		TIME: 1381.9
6/16/2004					LD/CY:
SB 73-3134	R2	REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSEMBLIES HAVING SUSPECT TORQUE MOTORS	GARRETT		DATE: 10/10/2006
RH	ONE TIME		N/A		TIME: 1381.9
4/30/1999					LD/CY:
SB 73-3135		DISTRIBUTION-INSPECT/REPLACE FLEX TUBE ASSY, P/N 3074376-1 (399-5500-0003) OR 3074376-2 (AS APPLICABLE)	GARRETT		DATE: 3/11/2024
RH	ONE TIME		NOT APPLICABLE		TIME: 5603.4
8/17/2000					LD/CY: 4357
SB 73-3136	R1	DISTRIBUTION-INCORP. IMPROVED PRIMARY & SECONDARY MANIFOLD FUEL FEEDER TUBE ASSEMBLIES	GARRETT	Optional	DATE: 7/03/2001
RH	ONE TIME		C/W		TIME: 0.0
9/10/2002					LD/CY:
SB 73-3137		REPLACE THE FUEL HEATER CHECK VALVE, P/N 3073932-5 WITH P/N 3073932-6 AND CONNECTING METAL TUBE ASSEMBLIES	GARRETT	Recommended	DATE: 3/11/2024
RH	ONE TIME		NOT APPLICABLE		TIME: 5603.4
11/03/2000					LD/CY: 4357
SB 73-3138		DISTRIBUTION-REPLACE FUEL NOZZLE GASKETS	GARRETT	Optional	DATE: 3/11/2024
RH	ONE TIME		COMPLIED WITH		TIME: 5603.4
10/20/2000					LD/CY: 4357
SB 73-3141		REWORK & RE-ID FUEL MANIFOLD ASSEMBLY (MATCHED SET)	GARRETT		DATE: 3/11/2024
RH	ONE TIME		FOUND P/C/W		TIME: 5603.4
					LD/CY: 4357

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 73-3142	ONE TIME	REPLACE SPECIFIC IDENTIFIED FUEL CONTROL	GARRETT	Recommended	DATE: 10/10/2006	DATE:
RH		ASSYS HAVING A SUSPECT OVERSPEED AND/OR			TIME: 1381.9	TIME:
10/07/2002		MANUAL MODE SOLENOID VALVE INSTALLED	N/A		LD/CY:	LD/CY:
SB 73-3147	ONE TIME	REPLACE SPECIFIC IDENTIFIED MAIN TURBINE	GARRETT		DATE: 10/10/2006	DATE:
RH		ENGINE FUEL CONTROLS WITH A SUSPECT OVER			TIME: 1381.9	TIME:
3/29/2005		SPEED GOVERNOR ASSEMBLY INSTALLED	N/A		LD/CY:	LD/CY:
SB 73-3149	ONE TIME	CONTROLLING - REPLACE MAIN TURBINE	GARRETT	Recommended	DATE: 10/10/2006	DATE:
RH		ENGINE FUEL PUMP FUEL FILTER ELEMENT			TIME: 1381.9	TIME:
9/12/2005		WITH FUEL FILTER ELEMENT,P/N 897830-1	C/W		LD/CY:	LD/CY:
SB 74-3003	R4	ENGINE - INSTALL IGNITION UNIT WITH	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	REDUNDANT FIRING CIRCUITS: ALLOWS EACH			TIME: 0.0	TIME:
9/21/2001		IGNITOR PLUG TO FIRE ASYNCHRONOUSLY	C/W		LD/CY:	LD/CY:
SB 74-3005	R1	REWORK/REPLACE P/N 3073914-2 IGNITION	GARRETT	Recommended	DATE: 7/03/2001	DATE:
RH	ONE TIME	UNIT TO/WITH 3073914-4			TIME: 0.0	TIME:
1/27/1995		INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W		LD/CY:	LD/CY:
SB 74-3006		IGNITION - GENERAL - INSTALL IGNITION	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	IGNITOR PLUG P/N 3074541-1			TIME: 0.0	TIME:
4/20/1990			C/W		LD/CY:	LD/CY:
SB 74-3007	R1	GENERAL - INSPECT IRIIDIUM IGNITER PLUGS,	GARRETT	Recommended	DATE: 7/03/2001	DATE:
RH	ONE TIME	P/N 3074541-1 (CHAMPION CH31815) FOR			TIME: 0.0	TIME:
11/11/1993		LOOSE CENTER FIRING TIP ELECTRODE	C/W		LD/CY:	LD/CY:
SB 76-3049		ENGINE CONTROLS - POWER CONTROL -	GARRETT	Recommended	DATE: 10/10/2006	DATE:
RH	ONE TIME	REPLACE SPECIFIC IDENTIFIED DIGITAL			TIME: 1381.9	TIME:
10/06/1989		ELECTRONIC ENGINE CONTROL P/N 2118002-X	N/A		LD/CY:	LD/CY:
SB 76-3051		ENGINE CONTROL - POWER CONTROL - INSTALL	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	ANTI-ICE AND SURGE SYSTEMS AIR LINE			TIME: 0.0	TIME:
5/18/1990		MANIFOLD, P/N 3071778-2	C/W		LD/CY:	LD/CY:
SB 76-3054		ENGINE CONTROLS - POWER CONTROL	GARRETT	Recommended	DATE: 7/03/2001	DATE:
RH	ONE TIME	INSTALL SURGE CONTROL GASKET, P/N			TIME: 0.0	TIME:
10/06/1995		3075481-1/-3.	C/W		LD/CY:	LD/CY:
SB 76-3064		ENGINE-CONTROLS-INSTALL DIGITAL	GARRETT	Optional	DATE: 7/03/2001	DATE:
RH	ONE TIME	ELECTRONIC ENGINE CONTROL (DEEC),			TIME: 0.0	TIME:
5/13/1994		P/N 2118002-204	C/W		LD/CY:	LD/CY:
SB 76-3066	R1	INSTALL DIGITAL ELECTRONIC ENGINE	GARRETT		DATE: 3/11/2024	DATE:
RH	ONE TIME	CONTROL (N1 DEEC), P/N 2119010-1			TIME: 5603.4	TIME:
11/06/1997			COMPLIED WITH		LD/CY: 4357	LD/CY:
SB 76-3067	R19	POWER CONTROL - INSTALL DIGITAL	GARRETT	Optional	DATE: 10/10/2006	DATE:
RH	ONE TIME	ELECTRONIC ENGINE CONTROL (N1 DEEC)			TIME: 1381.9	TIME:
12/05/2005			FOUND P/C/W		LD/CY:	LD/CY:
SB 76-3068	R2	REWORK N1 DEEC P/N 2119010-3/-3002 TO	GARRETT	Recommended	DATE: 5/08/2002	DATE:
RH	ONE TIME	P/N 2119010-3003 AND P/N 2119020-4/-4002			TIME:	TIME:
8/07/2015		TO P/N 2119020-4003	C/W		LD/CY:	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB 76-3076		REWORK N1 DIGITAL ELECTRONIC ENGINE	GARRETT	DATE: 12/22/2005	DATE:
RH		CONTROL TO P/N 2119010-3004, OR P/N		TIME: 1072.0	TIME:
7/01/2005	ONE TIME	2119020-4004, TO ADDRESS LEAN BLOWOUT	C/W	LD/CY:	LD/CY:
SB 76-3082		REPLACE SPECIFIC IDENTIFIED N1 DIGITAL	GARRETT	DATE: 3/11/2024	DATE:
RH		ELECTRONIC ENGINE CONTROLS (DEEC)		TIME: 5603.4	TIME:
7/02/2007	ONE TIME	P/N 2119010-3004 & 2119020-4004	FOUND P/C/W	LD/CY: 4357	LD/CY:
SB 77-3010	R2	ENGINE - N1 MOTIONAL PICKUP TRANSDUCER -	GARRETT	DATE: 7/03/2001	DATE:
RH		INSTALL AND/OR CLAMP IMPROVED MOTIONAL		TIME: 0.0	TIME:
2/07/1992	ONE TIME	PICKUP TRANSDUCER, P/N 3073827-1	C/W	LD/CY:	LD/CY:
SB 77-3019	R2	ENGINE INDICATING - TEMPERATURE -	GARRETT	DATE: 7/03/2001	DATE:
RH		INSTALL THERMOCLOUPLE HARNESS, P/N		TIME: 0.0	TIME:
6/19/1990	ONE TIME	3073595-1	C/W	LD/CY:	LD/CY:
SB 77-3021		ENGINE INDICATING-POWER - REPLACE	GARRETT	DATE: 7/03/2001	DATE:
RH		N1 MOTIONAL PICKUP TRANSDUCER		TIME: 0.0	TIME:
1/16/2006	ONE TIME		C/W	LD/CY:	LD/CY:
SB 79-3017	R3	DISTRIBUTION - REPLACE AIR/OIL COOLER &	GARRETT	DATE: 3/11/2024	DATE:
RH		BYPASS VALVE TO PREVENT OIL LEAKGE		TIME: 5603.4	TIME:
7/31/2006	ONE TIME	BY REDUCING FRETTING AT FLOW CONNECTION	NOT APPLICABLE	LD/CY: 4357	LD/CY:
SB 79-3025	R4	ENGINE - REPLACE OR REWORK OIL LUBRICATE	GARRETT	DATE: 1/26/2011	DATE:
RH		NOZZLE: PROVIDES FOR INSTALLATION OF		TIME: 2840.6	TIME:
11/11/2002	ONE TIME	LOCKING WASHERS TO PREVENT BOLTS LOOSEN	C/W	LD/CY: 2290	LD/CY:
SB 79-3032	R2	OIL - REWORK/REPLACE #6 BEARING LUBRICAT	GARRETT	DATE: 7/03/2001	DATE:
RH		TUBE ASSY P/N 3073418-1 TO 3073418-2		TIME: 0.0	TIME:
12/22/1989	ONE TIME	ELIMINATES SOURCE OF TUBE CORROSION	C/W	LD/CY:	LD/CY:
SB 79-3034	R3	OIL - REPLACEMENT/REWORK OF PLUG (CHIP	GARRETT	DATE: 3/11/2024	DATE:
RH		DETECTOR): VALVE HOUSING MADE OF STEEL		TIME: 5603.4	TIME:
1/28/2000	ONE TIME	TO REDUCE POSSIBILITY OF CRACKING	COMPLIED WITH	LD/CY: 4357	LD/CY:
SB 79-3038	R4	REPLACE SEAL,P/N 3020052-5 OR 3020052-16	GARRETT	DATE: 7/03/2001	DATE:
RH		WITH 3020052-21 IN BREATHER VALVE		TIME: 0.0	TIME:
7/08/1994	ONE TIME	INACTIVE FOR FURTHER ACCOMPLISHMENT	C/W	LD/CY:	LD/CY:
SB 79-3041	R1	OIL - REPLACEMENT/INSPECT/REWORK OF CHIP	GARRETT	DATE: 7/03/2001	DATE:
RH		DETECTOR: FALSE DETECTOR LIGHTS RESULTED		TIME: 0.0	TIME:
1/28/2000	ONE TIME	IN NEED OF RIGID CONTROL OF MAGNETIC GAP	C/W	LD/CY:	LD/CY:
SB 79-3050	R1	INSTALL TRANSFER GEARBOX OIL SCAVENGE	GARRETT	DATE: 7/03/2001	DATE:
RH		TRANSFER & #6 BEARING OIL SCAVENGE		TIME: 0.0	TIME:
2/24/1995	ONE TIME	TUBES WITH FILTER/GEARBOX SCREENS	C/W	LD/CY:	LD/CY:
SB 79-3051		OIL-DISTRIBUTION-INSTALL METAL GASKET,	GARRETT	DATE: 7/03/2001	DATE:
RH		P/N 3075481-2		TIME: 0.0	TIME:
2/18/1994	ONE TIME		C/W	LD/CY:	LD/CY:
SB 79-3053		OIL-DISTRIBUTION-REPLACE REAR TURBINE	GARRETT	DATE: 7/03/2001	DATE:
RH		BEARING OIL-OUT TUBE AND GASKET		TIME: 0.0	TIME:
4/01/1994	ONE TIME		C/W	LD/CY:	LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 79-3054 RH 7/29/1997	R1 ONE TIME	OIL-DISTRIBUTION-INSTALL/REWORK OIL LUBE & SCAVENGE PUMP (OIL PUMP) THAT INCORP. AN IMPROVED REGULATOR SECTION	GARRETT C/W	Optional DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 79-3055 RH 3/30/1995	 ONE TIME	REPLACE SEAL P/N 3020052-5/-16/-21 WITH P/N 3020052-24, IN AIR BREATHER VALVE ASSY P/N 3072119-1	GARRETT FOUND P/C/W	Optional DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 79-3057 RH 3/25/1997	R3 ONE TIME	OIL-STORAGE-INSTALL OIL TANK LIQUID LEVEL GAGE, P/N 3075532-1/-2	GARRETT COMPLIED WITH	Optional DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 79-3058 RH 12/12/2001	 ONE TIME	OIL - DISTRIBUTION - INSTALL OIL JET STRAINER, P/N 891764-11 INACTIVE	GARRETT N/A	DATE: 10/10/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB 79-3059 RH 11/01/1996	R1 ONE TIME	OIL - DISTRIBUTION - INSTALL/REWORK OIL LUBE AND SCAVENGE PUMP WITH IMPROVED SCAVENGE CAPABILITIES	GARRETT C/W	Recommended DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 79-3061 RH 2/22/1999	R1 ONE TIME	AIR/OIL COOLER INSTALLATION- INSTALL BOTTOM PANEL P/N 3071860-10, & ASSOCIATED SCREWS & WASHERS	GARRETT C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 79-3062 RH 6/19/1998	 ONE TIME	OIL-DISTRIBUTION-REPLACE DE-OIL VALVE (CHECK VALVE), P/N 3074372-1 WITH P/N 3074372-2	GARRETT C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 79-3063 RH 7/16/1999	 ONE TIME	INSTALL #6 BEARING LUBE TUBE ASSY P/N 3073736-1 & ASSOCIATED BRACKET, P/N 3073788-1/3075507-1 (AS APPLICABLE)	GARRETT C/W	DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:
SB 79-3064 RH 8/19/2005	R3 ONE TIME	INSTALL OIL LUBE & SCAVENGE PUMP P/N 3071949-12 TO INCORP. AN IMPROVED PRESSURE REGULATOR SECTION	GARRETT FOUND P/C/W	Optional DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 79-3068 RH 3/11/2005	 ONE TIME	INSTALL FUEL OIL COOLER ORIFICE, P/N 3075838-1	GARRETT COMPLIED WITH	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB 79-3077 RH 5/09/2018	 ONE TIME	INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING	GARRETT COMPLIED WITH	DATE: 3/11/2024 TIME: 5603.4 LD/CY: 4357	DATE: TIME: LD/CY:
SB A72-3328 RH 5/31/1995	 ONE TIME	REPLACEMENT OF FAN ROTOR DISC, P/N 3072162-ALL, OR 3073436-ALL WITH MORE THAN 4000 OPERATING CYCLES	GARRETT N/A BY P/N	Recommended DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB A72-3432 RH 5/31/1995	 ONE TIME	INSPECTION OF FAN ROTOR ASSY P/N 3072162-ALL/3073436-ALL/3073539-ALL OR 3074529-ALL	GARRETT N/A	Recommended DATE: 10/18/2006 TIME: 1381.9 LD/CY:	DATE: TIME: LD/CY:
SB A72-3472 RH 2/27/1992	R2 ONE TIME	REPL HPT NOZZLE SUPPORT ON SPECIFIED ENGINES	GARRETT C/W	Recommended DATE: 7/03/2001 TIME: 0.0 LD/CY:	DATE: TIME: LD/CY:

RIGHT ENGINE SERVICE BULLETINS **GARRETT P99590**

7/03/2026
N68VP

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB A72-3474		ENGINE-BY-PASS SECTION - REPLACEMENT OF SPECIFIC S/N LP TURBINE 3RD STAGE ROTOR DISC MFG FROM THE SAME MATL HEAT CODE	GARRETT	Recommended	DATE: 10/18/2006
RH					TIME: 1381.9
4/03/1992	ONE TIME		N/A		LD/CY:
SB A72-3504	R2	INSP OF FAN ROTOR ASSY CONT DISC & HUB P/N3072162-1 THRU -4,3073436-1 THRU -4, 3073539-2 OR 3074529-2 (INACTIVE)	GARRETT	Recommended	DATE: 10/10/2006
RH					TIME: 1381.9
5/23/2007	ONE TIME		N/A		LD/CY:
SB A72-3544		REPLACEMENT OF SPECIFIC SERIAL NO. FIRST & SECOND STAGE LP TURBINE DISKS MANUFACT FROM THE SAME HEAT TREAT LOC	GARRETT	Recommended	DATE: 10/10/2006
RH					TIME: 1381.9
10/08/1993	ONE TIME		N/A		LD/CY:
SB A72-3569		ENGINE-BYPASS SECTION-FAN ROTOR DISC CYCLE SERVICE LIFE REDUCTION	GARRETT	Mandatory	DATE: 10/18/2006
RH					TIME: 1381.9
5/23/2007	ONE TIME		N/A BY P/N		LD/CY:
SB A72-3570		ENGINE-BYPASS SECTION-FAN ROTOR DISC CYCLE SERVICE LIFE REDUCTION (INACTIVE FOR FURTHER ACCOMPLISHMENT)	GARRETT	Mandatory	DATE: 10/18/2006
RH					TIME: 1381.9
5/23/2007	ONE TIME		N/A BY P/N		LD/CY:
SB A72-3578		ENGINE-BYPASS SECTION-INSPECT SPECIFIC S/N FAN ROTOR DISCS INACTIVE FOR FURTHER ACCOMPLISHMENT	GARRETT		DATE: 10/18/2006
RH					TIME: 1381.9
5/23/2007	ONE TIME		N/A BY P/N		LD/CY:
SB A72-3619		TURBINE SECTION-REPLACE HP TURBINE NOZZL SUPPORT,P/N 3077050-3, IDENTIFIED WITH SPECIFIC JOB & LOG NUMBERS	GARRETT		DATE: 10/10/2006
RH					TIME: 1381.9
10/07/1997	ONE TIME		N/A		LD/CY:
SB A72-3623	R7	ENGINE-TURBINE SECTION-HP TURBINE ROTOR DISC BORE INSPECTION P/N 3072732-ALL,3072112-ALL,3073010-ALL	GARRETT	Recommended	DATE: 12/08/2014
RH					TIME: 4117.1
7/20/2010	ONE TIME		C/W		LD/CY: 3302
SB A72-3624		ENGINE-ONE TIME OIL FILTER RESAMPLE	GARRETT		DATE: 10/10/2006
RH					TIME: 1381.9
1/21/1998	ONE TIME		N/A		LD/CY:
SB A72-3641		PERFORM EDDY CURRENT INSPECTION OF HP IMPELLER P/N 3073393-1,3073394-1, 3073433-1,3073434-1,3073398-ALL	GARRETT	Recommended	DATE: 12/08/2014
RH					TIME: 4117.1
7/06/2010	RECURRS		C/W		LD/CY: 3302
SB A72-3668		REPLACEMENT OF FAN ROTOR DISC P/N 3072162-ALL,3073539-ALL, 30728-16-ALL	GARRETT		DATE: 3/11/2024
RH					TIME: 5603.4
10/25/2000	ONE TIME		COMPLIED WITH		LD/CY: 4357
SB A72-3700		INSPECTION OF SPECIFIC LOW PRESSURE FIRST STAGE (A5) TURBINE (LPT1) NOZZLES/ TURBINE INTERSTAGE TRANSITION DUCTS	GARRETT	Recommended	DATE: 12/08/2014
RH					TIME: 4117.1
4/22/2004	ONE TIME		C/W		LD/CY: 3302
SB A72-3700		INSPECTION OF SPECIFIC LOW PRESSURE FIRST STAGE (A5) TURBINE (LPT1) NOZZLES/ TURBINE INTERSTAGE TRANSITION DUCTS	GARRETT	Recommended	DATE: 10/10/2006
RH					TIME: 1381.9
4/22/2004	ONE TIME		C/W		LD/CY:
SB A73-3128		DISTRIBUTION-INSTALL FLEX TUBE ASSY P/N 399-5500-0003 OR 3074376-1	GARRETT		DATE: 10/18/2006
RH					TIME: 1381.9
8/17/2000	ONE TIME		FOUND P/C/W		LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P99590**

**7/03/2026
N68VP**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB A73-3132		DISTRIBUTION-INSTALL FLEX TUBE	GARRETT	DATE: 10/18/2006	DATE:
RH		ASSY, P/N 3074376-2	Mandatory	TIME: 1381.9	TIME:
8/17/2000	ONE TIME		FOUND P/C/W	LD/CY:	LD/CY:
SB A76-3079		POWER CONTROL - REPLACE SPECIFIC	GARRETT	DATE: 3/11/2024	DATE:
RH		IDENTIFIED N1 DIGITAL ELECTRONIC ENGINE	Mandatory	TIME: 5603.4	TIME:
12/21/2006	ONE TIME	CONTROLS (DEEC) P/N 2119010 & 2119020	FOUND P/C/W	LD/CY: 4357	LD/CY:
SB A77-3020		TEMPERATURE - REMOVE & REPLACE SPECIFIC	GARRETT	DATE: 10/18/2006	DATE:
RH		NUMBERED THERMOCOUPLE LEAD ASSEMBLIES	Recommended	TIME: 1381.9	TIME:
4/27/1990	ONE TIME	LISTED IN TABLE 1	N/A	LD/CY:	LD/CY: