




Work Order - Operation Complete
PA MES - Portal
Not secure pa-mfgscpt-prd1:8090/apps/portal/
Verify it's you
Update
Chat
PA MES - Portal
INFINERA\yunchen
Application Launcher
Applications
EWO
PartMaster/EWO Update
Material Request
SF Document Training
SF Training Documents Report
Packing List
Transceiver FMA
G6 Module Test Development Tool
XR Module Test Development Tool
CHM7 Test Development Tool
Product Dev FMA
ICE6 DCO Line Module FMA
ICE6 Module FMA
XR FMA
Test Viewer
Test HW FMA
Line Module Utility (LMU)
MFG Heart Beat
FBN SN Update Tool
Shop Flow Applications
SAPi Module 780 Conversion
SAPi PON Conversion
SAPi Production Order Release
SAPi GI Repost
SAPi Interface Tool
MRSI Part Traceability
Module Welding Gen1/Gen2 Upload
Module Welding Gen3 Upload
Namiki Data Upload
nLM Phase1D Data Upload
BOM and Route Maintenance
Inventory Reconcile
Inventory Receive
Module FMA and Returns
PLC Start
Rx Tx Start
nLM Start
nLM Shipping Serial Number Validation
Work Order Route Change
nLM Ship To CA FGI Start
Part Assembly Maintenance
Work Order Parametrics
Pedigree
RTV Serialized Inventory
User Administration
Work Order Operation Complete
Work Order Operation Complete - Parallel Run
Work Order Operation FMA Tool
Repair Start
Fabrinet Return FA Start
Splice Calculator
Manufacturing Database
Login/Logout
Part Label Print
Part Master
Work Order Operation
Work Order Operation Complete
Vendor
Waffle Pack Update
WIP
Line Module Label Print
Seam Seal Lid Label Print (pick from list)
Seam Seal Lid Label Print (wand list)
Clamshell Label Test Print (wand list)
Module Label Print
Gen 3 Label Print
Gen 6 Seamseal Label Print
Scrap PA Inventory
Ship IOC's to CA
Ship Modules
Ship 780 Modules
Ship TROSA to FBN
Ship Tracking
Shipped Modules Report
Shipped nLM Report
Module/Wafer ID
EWO Module List w/Operations
nLM Update Splice
Modules in Storage Location(1040)
Reports
Gen4 LM Bin Viewer
TestSet Dashboard
Build Plans
PA 2017 Reports Menu
PA (Infinera-D71477) Reports Menu
CA (TestServer) Reports Menu
Systems View of RF Report Archive
Misc. Forms & Documents
Module Dept Spend Matrix
Windsor Drive Master Evacuation List
2025 Holiday Schedule
Other Links
Workday
ADP Employee Benefits Solution
CONCUR Expense
Performance Manager
IT Help Request
Timesheets
Agile
Email
Office 365 Email
Junk Email (Postini)
MyInfinera
\\Allentown\Company
SDS - Safety Data Sheets(MSDS)
eFit Center
Hardware Change Control Board (HWCCB)
Weekly Module PI Meetings
ESD Foot Check Log
GEHS
Archived Content
http://pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete



Apply a document ID (if applicable).



PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
XXM-00145922
XXM-00145923
XXM-00145924
XXM-00145925
XXM-00145926
XXM-00145927
DUT Barcode 7
Wildcard Search
Search Barcodes
Reset
! Serial Numbers Out of WIP
Serial numbers in FMA
Close
Work Order Number | Part Number | Route Id | Operation Number | Operation Id | Start Date | Complete Date | EWO | FMA Id | Pass/Fail | Part Status | Employee Id | Last Update Date
XXM-00145927RWK1 | 810-0447-201 | TROSA_ICEXR4_PROD2 | 4000 | Active PIC Lens Align | 07/04/26 11:27:33 AM | 07/08/26 6:55:34 PM | | 44963 | Fail | FMA | jgervacio | 2026-07-08T18:55:34.337
Assign Part and Parametric
Serial numbers in WIP
ReBin
Assign Part
Assign Parametrics
Pass
Fail
Work Order Number | Part Number | Route Id | Operation Id | EWO | Part Id, Qty, Part Number, Lot | Parametrics | Pass/Fail
XXM-00145922RWK1 | 810-0447-201 Rev 001 Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band) | TROSA_ICEXR4_PROD2 | Wire Bond Control Board OperationNumber: 5075 StartDate: 07/13/26 4:35:46 AM Queue Time: 0.2 Day(s) | | | Machine: 1 |
XXM-00145923RWK1 | 810-0447-201 Rev 001 Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band) | TROSA_ICEXR4_PROD2 | Fiber Lens and PD Lens Align OperationNumber: 4300 StartDate: 07/13/26 5:51:21 AM Queue Time: 0.2 Day(s) | 3373 | N/A,2,799-0579-003,N/A N/A,1,799-0582-002,N/A | Machine: |
XXM-00145924RWK1 | 810-0447-201 Rev 001 Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band) | TROSA_ICEXR4_PROD2 | Wire Bond Control Board OperationNumber: 5075 StartDate: 07/13/26 9:27:53 AM Queue Time: 0.0 Day(s) | | | Machine: |
XXM-00145925RWK1 | 810-0447-201 Rev 001 Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band) | TROSA_ICEXR4_PROD2 | Fiber Lens and PD Lens Align OperationNumber: 4300 StartDate: 07/13/26 5:51:21 AM Queue Time: 0.2 Day(s) | 3373 | N/A,2,799-0579-003,N/A N/A,1,799-0582-002,N/A | Machine: |
XXM-00145926RWK1 | 810-0447-201 Rev 001 | TROSA_ICEXR4_PROD2 | Wire Bond Control Board OperationNumber: 5075 | | | |
Serial number can be entered by:
• Type in serial number
• Scan barcode on traveler
• Scan QR code on package
Note: scrapped parts will not show up in FMA or WIP





Serial number can also be entered by:


- Typing partial serial number in the Wildcard Search
- Click Search Barcodes
- This returns all SNs with the common partial serial number entered


Note: scrapped parts will not show up in FMA or WIP


PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
Wildcard Search
XXM-0014592
Search Barcodes
Reset
! Serial Numbers Out of WIP
Close
Work Order Number
Part Number
Route Id
Operation Number
Operation Id
Start Date
Last Update Date
XXM-00145927RWK1
810-0447-201
TROSA_ICEXR4_PROD2
4000
Active PIC Lens Align
07/04/26 11:27:33 AM
2026-07-08T18:55:34.337
XXM-00145929RWK1
810-0447-201
TROSA_ICEXR4_PROD2
4300
Fiber Lens and PD Lens Align
07/09/26 6:00:24 AM
2026-07-10T09:11:06.433
Assign Part:
Equivalent to Attach Part in legacy wooc tool
To attach part to multiple serial numbers, the selected serial numbers need to have the same part number, route Id and Operation Id
Assign Part and Parametric
ReBin
Assign Part
Assign Parametrics
Pass
Fail
Work Order Number
Part Number
Route Id
Operation Id
EWO
Part Id, Qty, Part Number, Lot
Parametrics
Pass/Fail
XXM-00145920RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Wire Bond Control Board
OperationNumber: 5075
StartDate: 07/13/26 9:24:27 AM
Queue Time: 0.0 Day(s)
XXM-00145921RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Wire Bond Control Board
OperationNumber: 5075
StartDate: 07/13/26 4:34:41 AM
Queue Time: 0.2 Day(s)
XXM-00145922RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Wire Bond Control Board
OperationNumber: 5075
StartDate: 07/13/26 4:35:46 AM
Queue Time: 0.2 Day(s)
XXM-00145923RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT
TROSA_ICEXR4_PROD2
Fiber Lens and PD Lens Align
OperationNumber: 4300
StartDate: 07/13/26 5:51:21 AM
Queue Time: 0.2 Day(s)
3373
Machine:
Warning
Selected work orders must have the same Part Number, Route Id, and Operation Id.
OK


PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
XXM-00145923
XXM-00145925
DUT Barcode 3
Wildcard Search
Search Barcodes
Reset
Assign Part and Pa
ReBin
Work Order Number
XXM-00145923RWK1
XXM-00145925RWK1
Assign Parametrics
Pass
Fail
Parametrics
Pass/Fail
Machine:
Assign Part
Part Number
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
Operation Id
Fiber Lens and PD Lens Align
Work Order Number
XXM-00145923RWK1
XXM-00145925RWK1
Orders. If a Part ID is not entered for a work order, it will retain its original Part ID after the update.
Step 1: List BOM Part Number
Part Number
Description
Lot Qty
799-0579-003
Rev 001
ICE-XR4 V1.1, Internal Focusing Lens, (C+L)-Band
2
799-0582-002
Rev 001
ICE-XR4 800G, Glass PD FOCUSING LENS
1
Step 2: Scan or Enter one or more Part Ids
Part Id
Lot Qty
Qty
Scan/Enter part id
0
Enter Qty
Step 3: Define Parametric
Machine
Enter Machine
Step 4: Set Status
Pass
Fail
Confirm
Cancel
The part number, operation Id, and serial numbers are displayed here
The component PartId can be scanned or typed here
The parametrics can be entered here or on the home screen


PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
XXM-00145923
XXM-00145925
XXM-00145926
DUT Barcode 4
Wildcard Search
Search Barcodes
Reset
Assign Part and Parametric
ReBin
Assign Part
Assign Parametrics
Pass
Fail
Work Order Number
Part Number
Route Id
Operation Id
EWO
Part Id, Qty, Part Number, Lot
XXM-00145923RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Fiber Lens and PD Lens Align
OperationNumber: 4300
StartDate: 07/13/26 5:51:21 AM
Queue Time: 0.2 Day(s)
3373
N/A,2,799-0579-003,N/A
N/A,1,799-0582-002,N/A
XXM-00145925RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Fiber Lens and PD Lens Align
OperationNumber: 4300
StartDate: 07/13/26 5:51:21 AM
Queue Time: 0.2 Day(s)
3373
N/A,2,799-0579-003,N/A
N/A,1,799-0582-002,N/A
XXM-00145926RWK1
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
TROSA_ICEXR4_PROD2
Wire Bond Control Board
OperationNumber: 5075
StartDate: 07/13/26 9:23:24 AM
Queue Time: 0.0 Day(s)
Machine:
Assign Parametrics:
• Equivalent to Parametrics in legacy wooc tool
• To Assign parametrics to multiple serial numbers, the selected serial numbers need to have the same part number, route Id and Operation Id
Warning
Selected work orders must have the same Part Number, Route Id, and Operation Id.
OK



PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
XXM-00145923
XXM-00145925
DUT Barcode 3
Wildcard Search
Search Barcodes
Reset
Assign Part and Pa
ReBin
Work Order Number
XXM-00145923RWK1
XXM-00145925RWK1
Assign Parametrics
Pass
Fail
Parametrics
Pass/Fail
Machine:
Assign Parametrics
Part Number
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
Operation Id
Fiber Lens and PD Lens Align
Work Order Number
XXM-00145923RWK1
XXM-00145925RWK1
Step 1: Define Parametric
Machine
Enter Machine
Step 2: Set Status
Pass
Fail
Note: Defining the Parametrics or Status fields applies updates to all selected work orders. If a Parametric value is not changed for a work order, it will retain its original value for that Parametric after the update.
Confirm
Cancel
The part number, operation Id, and serial numbers are displayed here
The parametrics can be entered here or on the home screen



Pass/Fail parts:

- Equivalent to Pass/Fail in legacy wooc tool

- To pass multiple serial numbers, confirm the correct serial number box is checked
- Only fail multiple serial numbers if they have the same FMA summary and description
- For serial numbers with different FMA summary, only fail one serial number each time to include accurate FMA summary!!!


PA MES Work Order Operation Co
Not secure pa-mfgscpt-prd1:8090/apps/workorder/operationcomplete
Verify it's you
Chat
NOKIA
PA MES - Work Order
INFINERA\yunchen
Operation Complete
Scan/Enter Barcode
XXM-00145923
XXM-00145925
XXM-00145926
DUT Barcode 4
Wildcard Search
Search Barcodes
Reset
Assign Part and Pa
ReBin
Assign Parametrics
Pass
Fail
Work Order Number
Parametrics
Pass/Fail
XXM-00145923RWK1
XXM-00145925RWK1
XXM-00145926RWK1
Machine:
Set Status
Part Number
810-0447-201
Rev 001
Sub-Assy,ICE-XR4,TROSA,OB V1.3 HT w/ Skew Fix,CB V4.5 HT LOW Bin (C-Band)
Operation Id
Wire Bond Control Board
Work Order Number
XXM-00145926RWK1
XXM-00145925RWK1
Note: Setting the status applies the change to all selected work orders.
Step 1: Set Status
Pass
Fail
Re Tune (FMA ticket will not be created if Re Tune is checked.)
FMA Description
Enter description
FMA Summary
Enter summary
Confirm
Cancel
• Enter FMA description and summary here for failing parts