
## Speed Gravit

Pin 3 Input on Auduins

Spannaxvalue variable

when High - high speed

when Lor - Lor speed



S1 am OH, Pin3 High, Led on,
Speed high

S1 off, Pin3 Low, Led off
Speed Low